

## PUBLIC UTILITIES COMMISSION

505 VAN NESS AVENUE  
SAN FRANCISCO, CA 94102-3298



October 28, 2025

EA2025-1327

Jonathan Moulton  
Director of Asset Management  
PacifiCorp  
825 NE Multnomah Street, Suite 1700  
Portland, OR 97232

**SUBJECT:** Electric Distribution Audit of PacifiCorp – Crescent City Division

Mr. Moulton:

On behalf of the Electric Safety and Reliability Branch (ESRB) of the California Public Utilities Commission (CPUC), Monica Hoskins and Rafael Herranz conducted an electric distribution audit of PacifiCorp's Crescent City Division from August 11 through 15, 2025. During the audit, ESRB staff conducted field inspections of PacifiCorp's distribution facilities and equipment and reviewed pertinent documents and records.

As a result of the audit, ESRB staff identified violations of General Order (GO) 95, GO 128, and GO 165. A copy of the audit findings itemizing the violations and observations is enclosed. Please provide a response no later than December 1, 2025, via electronic copy of all corrective actions and preventive measures taken by PacifiCorp to correct the identified violations and prevent the recurrence of such violations. Please note that ESRB will be posting the audit report and your response to our audit on the CPUC website. If there is any information in your response that you would like us to consider as confidential, we request that in addition to your confidential response, you provide us with a public version (a redacted version of your confidential response) to be posted on our website.

If you have any questions concerning this audit, please contact Monica Hoskins at [monica.hoskins@cpuc.ca.gov](mailto:monica.hoskins@cpuc.ca.gov) or (415) 652-1847.

Sincerely,

A handwritten signature in blue ink, appearing to read 'Rickey Tse'.

Rickey Tse, P.E.  
Program and Project Supervisor  
Electric Safety and Reliability Branch  
Safety and Enforcement Division  
California Public Utilities Commission

Enclosure: CPUC Electric Distribution Audit Report for PacifiCorp Crescent City Division

Cc: Lee Palmer, Deputy Executive Director, Safety Enforcement, Safety Policy, Water, CPUC  
Chih sien "Eric" Wu, Program Manager, ESRB, SED, CPUC  
Fadi Daye, Program and Project Supervisor, ESRB, SED, CPUC  
Stephen Lee, Senior Utilities Engineer (Supervisor), ESRB, SED, CPUC  
Yi (Rocky) Yang, Senior Utilities Engineer (Supervisor), ESRB, SED, CPUC  
Monica Hoskins, Utilities Engineer, ESRB, SED, CPUC  
Rafael Herranz, Utilities Engineer, ESRB, SED, CPUC  
Yongling Sun, Public Utility Resource Analyst, ESRB, SED, CPUC  
Brian Pagel, Asset Planning Manager, PacifiCorp  
Travis Rocha, Director of Line Inspection, PacifiCorp

**PACIFICORP CRESCENT CITY DIVISION  
ELECTRIC DISTRIBUTION AUDIT FINDINGS  
AUGUST 11 – 15, 2025**

**I. Records Review**

Electric Safety and Reliability Branch (ESRB) staff reviewed the following standards, documents, procedures, and records for PacifiCorp's Crescent City Division:

- PacifiCorp's Inspection and Maintenance Procedures
- Open and late work orders from June 2020 to May 2025
- Completed work orders and cancelled work orders from June 2024 to May 2025
- Intrusive inspection records from June 2020 to May 2025
- Patrols and detailed inspections completed June 2020 to May 2025
- Reliability metrics and sustained outages for June 2020 to May 2025
- Statistics on overhead and underground facilities
- Division maps showing approximate locations of the plat maps administered by the division
- New Construction Projects list, June 2024 to June 2025
- Pole Loading Calculations list, June 2024 to June 2025
- Outgoing Third-Party Safety Hazard notifications sent June 2020 to May 2025
- List of inspectors and patrolmen active from June 2020 May 2025
- Records of all equipment tests completed May 2022 to April 2025

## II. Records Violations

ESRB observed the following violations during the record review portion of the audit:

### 1. General Order (GO) 95, Rule 18-B, Maintenance Programs states in part:

*“Each company (including electric utilities and communications companies) shall establish and implement an auditable maintenance program for its facilities and lines for the purpose of ensuring that they are in good condition so as to conform to these rules. Each company must describe in its auditable maintenance program the required qualifications for the company representatives who perform inspections and/or who schedule corrective actions. Companies that are subject to GO 165 may maintain procedures for conducting inspections and maintenance activities in compliance with this rule and with GO 165.*

*The auditable maintenance program must include, at a minimum, records that show the date of the inspection, type of equipment/facility inspected, findings, and a timeline for corrective actions to be taken following the identification of a potential violation of GO 95 or a Safety Hazard on the company’s facilities.*

*Companies shall undertake corrective actions within the time periods stated for each of the priority levels set forth below.*

*Scheduling of corrective actions within the time periods below may be based on additional factors, including the following factors, as appropriate:*

- *Type of facility or equipment;*
- *Location, including whether the Safety Hazard or potential violation is located in the High Fire-Threat District;*
- *Accessibility;*
- *Climate;*
- *Direct or potential impact on operations, customers, electrical company workers, communications workers, and the general public.*

*The maximum time periods for corrective actions associated with potential violation of GO 95 or a Safety Hazard are based on the following priority levels:*

- (i) *Level 1 -- An immediate risk of high potential impact to safety or reliability:*
  - *Take corrective action immediately, either by fully repairing or by temporarily repairing and reclassifying to a lower priority.*
- (ii) *Level 2 -- Any other risk of at least moderate potential impact to safety or reliability:*
  - *Take corrective action within specified time period (either by fully repair or by temporarily repairing and reclassifying to Level 3 priority). Time period for corrective action to be determined at the time of identification by a qualified company representative, but not to exceed: (1) six months for*

potential violations that create a fire risk located in Tier 3 of the High Fire-Threat District; (2) 12 months for potential violations that create a fire risk located in Tier 2 of the High Fire-Threat District; (3) 12 months for potential violations that compromise worker safety; and (4) 36 months for all other Level 2 potential violations.

(iii) Level 3 -- Any risk of low potential impact to safety or reliability:

- Take corrective action within 60 months subject to the exception specified below.”

PacifiCorp’s Transmission and Distribution System Condition Priorities and Correction Timeframes: Asset Management Policy No. 292 (Revision 4) published on January 22, 2025, defines the priority codes and associated time frames for repair actions as follows:

| GO 95 Priority | Company Priority | Energy Release Risk <sup>1</sup> | CA Suggested Correction Period |             |             | GO 95 Compliance Requirements <sup>2</sup> |             |             |
|----------------|------------------|----------------------------------|--------------------------------|-------------|-------------|--|-------------|-------------|
|                |                  |                                  | Non-Tier                       | Tier 2      | Tier 3      | Non-Tier                                   | Tier 2      | Tier 3      |
| Level 1        | I <sup>2</sup>   | All                              | Immediately                    | Immediately | Immediately | Immediately                                | Immediately | Immediately |
| Level 2        | A                | Y                                | 30 days                        | 30 days     | 30 days     | 12 months                                  | 12 months   | 6 months    |
|                | A                | N                                | 30 days                        | 30 days     | 30 days     | 12 months                                  | 12 months   | 12 months   |
| Level 2        | B                | Y                                | 36 months                      | 6 months    | 6 months    | 36 months                                  | 12 months   | 6 months    |
|                | B                | N                                | 36 months                      | 36 months   | 36 months   | 36 months                                  | 36 months   | 36 months   |
| Level 3        | C                | N                                | 36 months                      | 36 months   | 36 months   | 60 months                                  | 60 months   | 60 months   |

<sup>1</sup>Energy Release Risks are determined and distinguished in Procedure 069. These conditions may pose a fire risk.

<sup>2</sup>Compliance period in accordance with GO 95. “A” priority may compromise worker safety and correction period is shown as 12 months instead of 36 months. Before June 30, 2019, when the correction time periods were modified to account for the High Fire Threat District, correction time period was immediately for Level 1 and 59 months for Level 2. No time period was established for Level 3 priorities.

<sup>2</sup>Imminent Threat conditions were created May 2024 to differentiate conditions that require immediate repair.

ESRB’s review of PacifiCorp’s Crescent City Division work orders from June 2020 to May 2025 found that PacifiCorp had 149 out of a total of 1,637 (9.1%) late-pending work orders, 173 out of a total of 1,451 (11.9%) late-closed work orders, and 360 out of a total of 657 (54.8%) late-removed work orders. Late-pending work orders are work orders that have not been completed by their assigned due date based on their hazard level. Late-closed work orders are work orders that were completed past their assigned due date based on their hazard level. Late-removed work orders are work orders that were not corrected or cancelled in PacifiCorp’s system prior to their assigned due date. Table 1 below breaks down all the 682 late work orders in PacifiCorp’s Crescent City Division by hazard level and late work order type.

**Table 1: Crescent City Division Late Work Orders**

| Priority Level | Late-Pending Work Orders <sup>1</sup> | Late-Closed Work Orders | Late-Removed Work Orders | Total Late Work Orders |
|----------------|---------------------------------------|-------------------------|--------------------------|------------------------|
| Level 1        | –                                     | –                       | –                        | 0                      |
| Level 2        | 119                                   | 19                      | 321                      | 459                    |
| Level 3        | 30                                    | 154                     | 39                       | 223                    |
| <b>Total</b>   | <b>149</b>                            | <b>173</b>              | <b>360</b>               | <b>682</b>             |

<sup>1</sup>As of May 31, 2025

The work order for facility point `07113001.0158001 for a climbable riser into the primary and open wire secondary has the longest Priority Level 2-A past due date of 1,099 days. The work order had a suggested correction date of March 11, 2022 and was completed on March 14, 2025.

The work order for facility point `07216001.0299808 for missing bolt covers has the longest Priority Level 3-C past due date of 4,330 days. The work order had a suggested correction date of June 13, 2013 and was completed on April 21, 2025.

**2. GO 95, Rule 37, Minimum Clearances of Wires above Railroads, Thoroughfares, Buildings, Etc.** states in part:

*“Clearances between overhead conductors, guys, messengers or trolley span wires and tops of rails, surfaces of thoroughfares or other generally accessible areas across, along or above which any of the former pass; also the clearances between conductors, guys, messengers or trolley span wires and buildings, poles, structures, or other objects, shall not be less than those set forth in Table 1, at a temperature of 60° F. and no wind.”*

- a. PacifiCorp’s *Clearance Table Condition Codes* NO 25: CLRBLDG designates the allowable clearance for power conductors from a building/sign. PacifiCorp references GO 95, Rule 86.6(f), which is not a rule in GO 95. PacifiCorp must adjust their clearance codes to reference GO 95, Rule 37, Table 1.
- b. PacifiCorp’s *Clearance Table Condition Codes* NO 198: SVCDECK designates the allowable clearance for power service conductors from decks. PacifiCorp references GO 95, Rule 84.8-C(4)(b), which is only applicable to communication facilities. PacifiCorp must adjust their clearance codes to reference GO 95, Rule 37, Table 1.

**3. GO 95, Rule 31.2, Inspection of Lines** states in part:

*“Lines shall be inspected frequently and thoroughly for the purpose of ensuring that they are in good condition so as to conform with these rules. Lines temporarily out of service shall be inspected and maintained in such condition as not to create a hazard.”*

**GO 128, Rule 17.2, Inspection** states in part:

*“Systems shall be inspected by the operator frequently and thoroughly for the purpose of insuring that they are in good condition and in conformance with all applicable requirements these rules.”*

**GO 165, Rule III-B, Standards for Inspections** states:

*“Each utility subject to this General Order shall conduct inspections of its distribution facilities, as necessary, to ensure reliable, high quality, and safe operation, but in no case may the period between inspections (measured in years) exceed the time specified in Table 1.”*

Table 1: Distribution Inspection Cycles (Maximum Intervals in Years)

|  | Patrol |                | Detailed |       | Intrusive |       |
|--|--------|----------------|----------|-------|-----------|-------|
|  | Urban  | Rural          | Urban    | Rural | Urban     | Rural |
| <b>Transformers</b>  |        |                |          |       |           |       |
| Overhead   | 1      | 2 <sup>1</sup> | 5        | 5     | ---       | ---   |
| Underground  | 1      | 2              | 3        | 3     | ---       | ---   |
| Padmounted   | 1      | 2              | 5        | 5     | ---       | ---   |
| <b>Switching/Protective Devices</b>  |        |                |          |       |           |       |
| Overhead   | 1      | 2 <sup>1</sup> | 5        | 5     | ---       | ---   |
| Underground  | 1      | 2              | 3        | 3     | ---       | ---   |
| Padmounted   | 1      | 2              | 5        | 5     | ---       | ---   |
| <b>Regulators/Capacitors</b>   |        |                |          |       |           |       |
| Overhead   | 1      | 2 <sup>1</sup> | 5        | 5     | ---       | ---   |
| Underground  | 1      | 2              | 3        | 3     | ---       | ---   |
| Padmount   | 1      | 2              | 5        | 5     | ---       | ---   |
| <b>Overhead Conductor and Cables</b>   |        |                |          |       |           |       |
| Overhead Conductor and Cables  | 1      | 2 <sup>1</sup> | 5        | 5     | ---       | ---   |
| Streetlighting   | 1      | 2              | x        | x     | ---       | ---   |
| Wood Poles under 15 years  | 1      | 2              | x        | x     | ---       | ---   |
| Wood Poles over 15 years which have not been subject to intrusive inspection | 1      | 2              | x        | x     | 10        | 10    |
| Wood poles which passed intrusive inspection                                 | ---    | ---            | ---      | ---   | 20        | 20    |

(1) Patrol inspections in rural areas shall be increased to once per year in Tier 2 and Tier 3 of the High Fire-Threat District. (See GO 95, Rule 21.2-D)

Note: For the purpose of implementing the patrol and detailed inspection intervals in Table 1 above, the term “year” is defined as 12 consecutive calendar months starting the first full calendar month after an inspection is performed, plus three full calendar months, not to exceed the end of the calendar year in which the next inspection is due. A required inspection may be completed any time before the expiration of the associated inspection interval using this definition of “year,” but not after. The completion of an inspection starts a new inspection interval that must be completed within the prescribed timeframe using this definition of “year.” However, inspection intervals may be extended by up to six months in areas where the Governor of California or the President of the United States has declared an emergency or a disaster following a major earthquake or other catastrophe using the procedure set forth in Decision 13-06-011 issued in Rulemaking 08-11-005. The extension shall not exceed six months from the date that an emergency is declared or the date that a disaster is declared, whichever is earlier.

Note: For wood pole intrusive inspections, the term “year” is defined as a calendar year

- a. ESRB’s review of PacifiCorp’s overhead patrols and inspections for the Crescent City Division identified a total of 6 late overhead patrols and inspections out of a total of 34,505 (0.02%) from June 2020 to May 2025. PacifiCorp completed 1 overhead patrol inspection late and 5 overhead detailed inspections late.
- b. ESRB’s review of PacifiCorp’s overhead patrols and inspections for the Crescent City Division identified a total of 132 late underground patrols and inspections out of a total of 5,708 (2.3%) from June 2020 to May 2025. PacifiCorp completed 70 underground patrols late and 62 underground detailed inspections late.
- c. ESRB’s review of PacifiCorp’s intrusive inspections for the Crescent City Division identified a total of 228 late intrusive inspections from June 2020 to May 2025. PacifiCorp completed the 228 Pole Test and Treat (PTT) inspections more than 20 years after the previous inspection.

**4. GO 165, Rule III-C, Record Keeping states in part:**

*“For all inspections records shall specify the circuit, area, facility or equipment inspected, the inspector, the date of the inspection, and any problems (or items requiring corrective action) identified during each inspection, as well as the scheduled date of corrective action.”*

PacifiCorp uses their suggested correction dates as due dates in their records to ensure that work orders are completed within the required timeframes. ESRB identified 7 open Priority B and 3 Priority C work orders that have no suggested correction date or assigned due date, as required by GO 165, Rule III-C. Table 2 below details the overhead open work orders with no suggested correction dates.

**Table 2: Work Orders with No Suggested Correction Date**

| Facility Point Name | Inspection Date | Priority |
|---------------------|-----------------|----------|
| `07113001.0056503   | 3/21/2023       | B        |
| `07113001.0055500   | 3/21/2023       | B        |
| `07113001.0056500   | 3/21/2023       | B        |
| `07113001.0057503   | 3/21/2023       | B        |
| `07117002.0200304   | 3/2/2023        | B        |
| `07114001.0338500   | 3/15/2023       | B        |
| `07117002.0205208   | 3/9/2023        | B        |
| `07113001.0056501   | 3/21/2023       | C        |
| `07114001.0338501   | 3/22/2023       | C        |
| `07114001.0341600   | 3/15/2023       | C        |

### III. Field Inspection

During the field inspection, ESRB inspected the following distribution facilities:

| Location | Asset Type                       | Facility Point Number | GPS Coordinates          |
|----------|----------------------------------|-----------------------|--------------------------|
| 1        | Pole                             | `07218001.0041600     | 41.982500, -124.195278   |
| 2        | Pole                             | `07218001.0041601     | 41.9824232, -124.1941108 |
| 3        | Pole                             | `07219001.0041601     | 41.9825548, -124.1929588 |
| 4        | Pole                             | `07218001.0176502     | 41.9520538, -124.2022084 |
| 5        | Pole                             | `07218001.0176503     | 41.9524368, -124.2014959 |
| 6        | Pole                             | `07218001.0176500     | 41.9521869, -124.2010490 |
| 7        | Pole                             | `07218001.0176504     | 41.9517832, -124.2026912 |
| 8        | Pole                             | `07218001.0266740     | 41.9270180, -124.1423840 |
| 9        | Pole                             | `07218001.0267762     | 41.9272058, -124.1418905 |
| 10       | Pole                             | `07218001.0266800     | 41.9277987, -124.1424343 |
| 11       | Pole                             | `07217001.0137160     | 41.8596757, -124.1223607 |
| 12       | Underground Switch Gap           | `07217001.0137180     | 41.8596757, -124.1223607 |
| 13       | Pole                             | `07217001.0137161     | 41.8605824, -124.1222490 |
| 14       | Pole                             | `07217001.0137100     | 41.8609210, -124.1222296 |
| 15       | Pole                             | `07217001.0137260     | 41.8615305, -124.1222692 |
| 16       | Pole                             | `07217001.0137261     | 41.8622014, -124.1223245 |
| 17       | Underground Padmount Transformer | `07217001.0137080     | 41.8594477, -124.1223298 |
| 18       | Underground Padmount Transformer | `07217001.0136080     | 41.8588776, -124.1245822 |
| 19       | Underground Splice Cabinet       | `07217001.0136082     | 41.8592644, -124.1245054 |
| 20       | Underground Padmount Transformer | `07217001.0136081     | 41.8592619, -124.1242657 |
| 21       | Pole                             | `07217001.0276803     | 41.8418835, -124.1632389 |
| 22       | Pole                             | `07217001.0276804     | 41.8421603, -124.1630770 |
| 23       | Pole                             | `07217001.0276805     | 41.8427737, -124.1627423 |
| 24       | Pole                             | `07217001.0276900     | 41.8429970, -124.1624121 |
| 25       | Pole                             | `07217001.0275400     | 41.8363093, -124.1664290 |
| 26       | Pole                             | `07217001.0275441     | 41.8362031, -124.1660747 |
| 27       | Pole                             | `07216001.0032103     | 41.8043536, -124.1709385 |
| 28       | Pole                             | `07216001.0032102     | 41.8042288, -124.1712704 |
| 29       | Pole                             | `07216001.0031204     | 41.8047559, -124.1720516 |
| 30       | Pole                             | `07216001.0031203     | 41.8052065, -124.1727614 |
| 31       | Pole                             | `07216001.0030302     | 41.8061217, -124.1741367 |
| 32       | Pole                             | `07216001.0030301     | 41.8063814, -124.1743791 |
| 33       | Pole                             | `07216001.0101502     | 41.7946311, -124.1732516 |
| 34       | Pole                             | `07216001.0101440     | 41.7944478, -124.1727805 |

| Location | Asset Type                           | Facility Point Number     | GPS Coordinates          |
|----------|--------------------------------------|---------------------------|--------------------------|
| 35       | Pole                                 | `07216001.0101402         | 41.7944256, -124.1723879 |
| 36       | Pole                                 | `07216001.0187403         | 41.7800374, -124.2197903 |
| 37       | Pole                                 | `07216001.0187402         | 41.7800462, -124.2191824 |
| 38       | Pole                                 | `07216001.0187400         | 41.7795304, -124.2192381 |
| 39       | Pole                                 | `07216001.0214902         | 41.7718880, -124.1861946 |
| 40       | Pole                                 | `07216001.0214904         | 41.7716387, -124.1859518 |
| 41       | Pole                                 | `07216001.0215903         | 41.7720561, -124.1852491 |
| 42       | Pole                                 | `07216001.0215920         | 41.7720561, -124.1852491 |
| 43       | Pole                                 | `07216001.0214903         | 41.7716610, -124.1852105 |
| 44       | Pole                                 | `07113002.0183704         | 41.5211111, -123.987778  |
| 45       | Pole                                 | `07113002.0183601         | 41.520556, -123.988889   |
| 46       | Pole                                 | `07113002.0182600         | 41.520278, -123.989167   |
| 47       | Pole                                 | `07113002.0182601         | 41.520556, -123.989722   |
| 48       | Pole                                 | `07113002.0182700         | 41.521389, -123.989444   |
| 49       | Pole                                 | `07113002.0183705         | 41.521667, -123.988889   |
| 50       | Pole                                 | `07113001.0159800         | 41.522500, -124.032778   |
| 51       | Pole                                 | `07113001.0140801         | 41.522500, -124.032222   |
| 52       | Pole                                 | `07113001.0140800         | 41.521944, -124.031944   |
| 53       | Pole                                 | `07113001.0030000         | 41.540000, -124.050000   |
| 54       | Pole                                 | `07113001.0030001         | 41.540278, -124.049444   |
| 55       | Pole                                 | `07113001.0031001         | 41.539444, -124.049167   |
| 56       | Pole                                 | `07114001.0205001         | 41.583611, -124.085833   |
| 57       | Pole                                 | `07114001.0206004         | 41.583611, -124.085833   |
| 58       | Pole                                 | `07114001.0205003         | 41.583611, -124.086667   |
| 59       | Pole                                 | `07216001.0270760         | 41.7547153, -124.1748441 |
| 60       | Pole                                 | `07216001.0270660         | 41.7542661, -124.1748284 |
| 61       | Pole                                 | `07216001.0270661         | 41.7537714, -124.1747489 |
| 62       | Pole                                 | `07216001.0270601         | 41.7536891, -124.1744130 |
| 63       | Padmount Switch Cabinet/Fuse Cabinet | Abandoned UG fuse cabinet | 41.7536891, -124.1744130 |
| 64       | Pole                                 | `07216001.0270602         | 41.7534997, -124.1741186 |
| 65       | Pole                                 | `07216001.0209603         | 41.7673930, -124.1955236 |
| 66       | Pole                                 | `07216001.0209600         | 41.7673020, -124.1951079 |
| 67       | Pole                                 | `07216001.0209604         | 41.7674210, -124.1961060 |
| 68       | Pole                                 | `07216001.0209607         | 41.7679982, -124.1960782 |
| 69       | Pole                                 | `07216001.0201111         | 41.7598508, -124.2120668 |
| 70       | Pole                                 | `07216001.0200109         | 41.7598478, -124.2127287 |
| 71       | Pole                                 | `07216001.0200100         | 41.7604152, -124.2126009 |
| 72       | Pole                                 | `07216001.0200101         | 41.7606736, -124.2126210 |
| 73       | Pole                                 | `07216001.0200104         | 41.7611923, -124.2126026 |
| 74       | Pole                                 | `07216001.0200202         | 41.7615424, -124.2126619 |

| Location | Asset Type                       | Facility Point Number | GPS Coordinates          |
|----------|----------------------------------|-----------------------|--------------------------|
| 75       | Underground Padmount Transformer | `07216001.0290988     | 41.7581556, -124.2119937 |
| 76       | Underground Switch Cabinet       | `07216001.0290992     | 41.7579803, -124.2127531 |
| 77       | Underground Padmount Transformer | `07216001.0290989     | 41.7579803, -124.2127531 |
| 78       | Underground Padmount Transformer | `07216001.0291985     | 41.7575728, -124.2123451 |
| 79       | Underground Padmount Transformer | `07216001.0193382     | 41.7626198, -124.2265434 |
| 80       | Underground Junction Box         | `07216001.0193383     | 41.7629271, -124.2274389 |
| 81       | Underground Padmount Transformer | `07216001.0194380     | 41.7628001, -124.2256093 |
| 82       | Underground Padmount Transformer | `07216001.0194280     | 41.7622919, -124.2244348 |
| 83       | Underground Junction Box         | `07216001.0194282     | 41.7620493, -124.2253894 |
| 84       | Underground Padmount Transformer | `07216001.0194281     | 41.7620493, -124.2253894 |
| 85       | Pole                             | `07216001.0198311     | 41.7636921, -124.2169458 |
| 86       | Pole                             | `07216001.0198312     | 41.7638532, -124.2168579 |
| 87       | Pole                             | `07216001.0198309     | 41.7641260, -124.2171389 |
| 88       | Pole                             | `07216001.0198300     | 41.7641118, -124.2175466 |
| 89       | Pole                             | `07216001.0198308     | 41.7641350, -124.2180746 |
| 90       | Pole                             | `07216001.0198400     | 41.7644864, -124.2180713 |
| 91       | Pole                             | `07216001.0198401     | 41.7649538, -124.2180693 |
| 92       | Pole                             | `07117003.0082460     | 41.881275, -123.864441   |
| 93       | Pole                             | `07117003.0082400     | 41.881111, -123.864167   |
| 94       | Pole                             | `07117003.0083301     | 41.880556, -123.863333   |
| 95       | Pole                             | `07117003.0083300     | 41.879722, -123.862500   |
| 96       | Pole                             | `07117002.0207501     | 41.8513774, -123.9680465 |
| 97       | Pole                             | `07117002.0207603     | 41.8518336, -123.9684431 |
| 98       | Pole                             | `07117002.0207602     | 41.8524562, -123.9685638 |
| 99       | Pole                             | `07117002.0207702     | 41.8533268, -123.9682309 |
| 100      | Pole                             | `07117002.0207703     | 41.8538457, -123.9682356 |
| 101      | Pole                             | `07117002.0205208     | 41.8457320, -123.9712933 |
| 102      | Pole                             | `07117002.0205209     | 41.8455422, -123.9718495 |
| 103      | Pole                             | `07117002.0205210     | 41.8455799, -123.9723994 |
| 104      | Pole                             | `07117002.0205102     | 41.8455169, -123.9731464 |
| 105      | Pole                             | `07116001.0168903     | 41.7880737, -124.0636062 |
| 106      | Pole                             | `07116001.0167904     | 41.7873270, -124.0637584 |
| 107      | Pole                             | `07116001.0167903     | 41.7872893, -124.0645524 |

| <b>Location</b> | <b>Asset Type</b>                   | <b>Facility Point Number</b> | <b>GPS Coordinates</b>   |
|-----------------|-------------------------------------|------------------------------|--------------------------|
| <b>108</b>      | Pole                                | `07116001.0167902            | 41.7871195, -124.0650221 |
| <b>109</b>      | Pole                                | `07116001.0167901            | 41.7872270, -124.0653550 |
| <b>110</b>      | Pole                                | `07116001.0093301            | 41.7934990, -124.0716984 |
| <b>111</b>      | Pole                                | `07116001.0093300            | 41.7933215, -124.0716549 |
| <b>112</b>      | Pole                                | `07116001.0093202            | 41.7923886, -124.0723311 |
| <b>113</b>      | Pole                                | `07116001.0093201            | 41.7917612, -124.0724666 |
| <b>114</b>      | Pole                                | `07116001.0090901            | 41.8025931, -124.0779084 |
| <b>115</b>      | Pole                                | `07116001.0059800            | 41.8123384, -124.0802788 |
| <b>116</b>      | Pole                                | `07116001.0040702            | 41.8117041, -124.0796790 |
| <b>117</b>      | Pole                                | `07116001.0040701            | 41.8110307, -124.0791161 |
| <b>118</b>      | Underground<br>Padmount Transformer | `07116001.0040280            | 41.8060568, -124.0783037 |
| <b>119</b>      | Underground<br>Padmount Transformer | `07116001.0041180            | 41.8051533, -124.0786403 |
| <b>120</b>      | Underground<br>Padmount Transformer | `07116001.0098381            | 41.7932443, -124.0627382 |
| <b>121</b>      | Underground<br>Padmount Transformer | `07116001.0098281            | 41.7929373, -124.0627949 |
| <b>122</b>      | Underground<br>Padmount Transformer | `07116001.0099380            | 41.7929388, -124.0608097 |
| <b>123</b>      | Underground<br>Padmount Transformer | `07116001.0099381            | 41.7932048, -124.0604348 |
| <b>124</b>      | Underground<br>Padmount Transformer | `07116001.0098380            | 41.7937254, -124.0628505 |
| <b>125</b>      | Pole                                | `07117001.0304400            | 41.836389, -124.110556   |
| <b>126</b>      | Pole                                | `07117001.0304700            | 41.8399645, -124.1092182 |

#### IV. Field Inspection Violations

ESRB identified the following violations during the field inspection:

**1. GO 95, Rule 31.1, Design, Construction and Maintenance** states in part:

*“Electrical supply and communication systems shall be designed, constructed, and maintained for their intended use, regard being given to the conditions under which they are to be operated, to enable the furnishing of safe, proper, and adequate service.”*

ESRB’s findings related to the above rule are listed in Table 3:

**Table 3: GO 95, Rule 31.1 Findings**

| <b>Location</b> | <b>Finding</b>   |
|-----------------|--|
| <b>1</b>        | The pole has an incorrect identification number that differs from the number listed on PacifiCorp’s map. |
| <b>2</b>        | The pole has dirty insulators that need washing.   |
| <b>3</b>        | The pole has dirty insulators that need washing.   |
| <b>15</b>       | The pole is missing the distribution identification and pole number plate.                               |
| <b>33</b>       | The pole has dirty insulators that need washing. PacifiCorp has an existing tag to replace the pole.     |
| <b>38</b>       | The pole is missing the distribution identification and pole number plate.                               |
| <b>45</b>       | The pole is missing visibility strips. <sup>1</sup>  |
| <b>46</b>       | The pole is missing visibility strips.   |
| <b>49</b>       | The pole is missing visibility strips.   |
| <b>54</b>       | The pole is missing the distribution identification and pole number plate.                               |
| <b>56</b>       | The pole has an incorrect identification number that differs from the number listed on PacifiCorp’s map. |
| <b>58</b>       | The pole is missing the distribution identification and pole number plate.                               |
| <b>70</b>       | The pole is missing visibility strips.   |
| <b>71</b>       | The pole is missing visibility strips.   |
| <b>73</b>       | The pole is missing visibility strips.<br>The pole has dirty insulators that need washing.               |

<sup>1</sup> PacifiCorp Procedure 069 – Condition Codes, Code 176 requires any structure that is less than 4 feet of the curb or road edge to have visibility striping or protective-type barrier installed.

| <b>Location</b> | <b>Finding</b>   |
|-----------------|--|
| <b>74</b>       | The pole is missing visibility strips.                                     |
| <b>86</b>       | The pole is missing visibility strips.                                     |
| <b>91</b>       | The pole has dirty insulators that need washing.                           |
| <b>96</b>       | The pole is missing the distribution identification and pole number plate. |
| <b>99</b>       | The pole has loose insulator bolt plates that are not flush with the pole. |
| <b>107</b>      | The pole has dirty insulators that need washing.                           |

**2. GO 95, Rule 34, Foreign Attachments** states in part:

*“Nothing in these rules shall be construed as permitting the unauthorized attachment, to supply, streetlight or communication poles or structures, of antennas, signs, posters, banners, decorations, wires, lighting fixtures, guys, ropes and any other such equipment foreign to the purposes of overhead electric line construction.*

*Nothing herein contained shall be construed as requiring utilities to grant permission for such use of their overhead facilities; or permitting any use of joint poles or facilities for such permanent or temporary construction without the consent of all parties having any ownership whatever in the poles or structures to which attachments may be made; or granting authority for the use of any poles, structures or facilities without the owner’s or owners’ consent.)”*

ESRB’s findings related to the above rule are listed in Table 4:

**Table 4: GO 95, Rule 34 Finding**

| <b>Location</b> | <b>Finding</b>   |
|-----------------|--|
| <b>64</b>       | The pole has an unauthorized third-party attachment.                           |
| <b>66</b>       | The pole has an unauthorized third-party attachment obscuring the pole number. |

**3. GO 95, Rule 35, Vegetation Management** states in part:

*“Where overhead conductors traverse trees and vegetation, safety and reliability of service demand that certain vegetation management activities be performed in order to establish necessary and reasonable clearances, the minimum clearances set forth*

*in Table 1, Cases 13 and 14, measured between line conductors and vegetation under normal conditions shall be maintained. (Also see Appendix E for tree trimming guidelines.) These requirements apply to all overhead electrical supply and communication facilities that are covered by this General Order, including facilities on lands owned and maintained by California state and local agencies.*

*Communication and electric supply circuits, energized at 750 volts or less, including their service drops, should be kept clear of vegetation in new construction and when circuits are reconstructed or repaired, whenever practicable. When a supply or communication company has actual knowledge, obtained either through normal operating practices or notification to the company, that its circuit energized at 750 volts or less shows strain or evidences abrasion from vegetation contact, the condition shall be corrected by reducing conductor tension, rearranging or replacing the conductor, pruning the vegetation, or placing mechanical protection on the conductor(s).”*

ESRB’s finding related to the above rule is listed in Table 5:

**Table 5: GO 95, Rule 35 Findings**

| Location | Finding  |
|----------|--|
| 69       | Excessive vegetation is surrounding the pole and impeding the climbing space. PacifiCorp has an existing tag for this issue. |

**4. GO 95, Rule 38, Minimum Clearance of Wires from Other Wires** states in part:

*“The minimum vertical, horizontal or radial clearances of wires from other wires shall not be less than the values given in Table 2 and are based on a temperature of 60° F. and no wind. Conductors may be deadended at the crossarm or have reduced clearances at points of transposition, and shall not be held in violation of Table 2, Cases 8–15, inclusive.*

*Table 2, Case 19C: The radial separation between guys and span wires passing communication conductors (including open wire, cables, and service drops) supported on the same poles must be at least 3 inches.”*

ESRB’s finding related to the above rule is listed in Table 6:

**Table 6: GO 95, Rule 38 Finding**

| Location | Finding  |
|----------|--|
| 39       | The primary anchor down guy is in contact with the communication (Frontier) conductor. |

**5. GO 95, Rule 51.6-A, High Voltage Marking** states in part:

*“Poles which support line conductors of more than 750 volts shall be marked with high voltage signs. This marking shall consist of a single sign showing the words “HIGH VOLTAGE”, or pair of signs showing the words “HIGH” and “VOLTAGE”, not more than six (6) inches in height with letters not less than 3 inches in height. Such signs shall be of weather and corrosion–resisting material, solid or with letters cut out therefrom and clearly legible.*

*The top of such sign(s) shall be located between the level of the lowest line conductor, energized in excess of 750 volts, on the pole to no more than 40 inches below that conductor level (see Figure 51–1).”*

ESRB’s findings related to the above rule are listed in Table 7:

**Table 7: GO 95, Rule 51.6-A Findings**

| <b>Location</b> | <b>Finding</b>                            |
|-----------------|---|
| <b>4</b>        | The pole has a missing high voltage sign. |
| <b>13</b>       | The pole has a missing high voltage sign. |
| <b>15</b>       | The pole has a missing high voltage sign. |
| <b>49</b>       | The pole has a missing high voltage sign. |
| <b>64</b>       | The pole has a damaged high voltage sign. |
| <b>67</b>       | The pole has a missing high voltage sign. |
| <b>70</b>       | The pole has a damaged high voltage sign. |
| <b>88</b>       | The pole has a damaged high voltage sign. |
| <b>94</b>       | The pole has a damaged high voltage sign. |

**6. GO 95, Rule 54.6-B, Ground Wires** states in part:

*“That portion of the ground wire attached on the face or back of wood crossarms or on the surface of wood poles and structures shall be covered by a suitable protective covering (see Rule 22.8).”*

ESRB’s findings related to the above rule are listed in Table 8:

**Table 8: GO 95, Rule 54.6-B Finding**

| <b>Location</b> | <b>Finding</b>   |
|-----------------|--|
| 33              | The pole has an exposed ground wire. PacifiCorp has an existing tag to replace the pole. |
| 42              | The pole has an exposed ground wire.   |
| 43              | The pole has an exposed transformer ground wire.   |
| 45              | The pole has an exposed transformer ground wire.   |
| 46              | The pole has an exposed secondary ground wire.   |
| 51              | The pole has an exposed secondary ground wire.   |
| 58              | The pole has an exposed transformer ground wire.   |
| 61              | The pole has an exposed transformer ground wire.   |
| 72              | The pole has an exposed transformer ground wire.   |
| 73              | The pole has an exposed transformer ground wire.   |
| 90              | The pole has an exposed transformer ground wire.   |
| 97              | The pole has an exposed transformer ground wire.   |
| 102             | The pole has an exposed transformer ground wire.   |
| 114             | The pole has an exposed transformer ground wire.   |

**7. GO 95, Rule 54.7-A(3)(j), Climbing and Working Space, Allowable Climbing Space Obstructions** states in part:

*“Bolts and their washers. However, bolts bonded to or used for the attachment of deadend hardware of circuits above 750 volts in wood crossarm configuration that project into the climbing space shall be covered with a non-conductive material as specified in Rule 22.8-C. If such bolts are bonded, a positive electrical contact shall be made.”*

ESRB’s findings related to the above rule are listed in Table 9:

**Table 9: GO 95, Rule 54.7-A(3)(j) Findings**

| <b>Location</b> | <b>Finding</b>   |
|-----------------|--|
| 96              | The pole has missing transformer bolt covers. PacifiCorp has an existing tag for this issue. |

| Location | Finding                                       |
|----------|---|
| 98       | The pole has loose transformer bolt covers.   |
| 116      | The pole has missing transformer bolt covers. |

**8. GO 95, Rule 56.2, Overhead Guys, Anchor Guys and Span Wires, Use** states in part:

*“Guys shall be attached to structures, as nearly as practicable, at the center of load. They shall be maintained taut and of such strength as to meet the safety factors of Rule 44.”*

ESRB’s findings related to the above rule are listed in Table 10:

**Table 10: GO 95, Rule 56.2 Findings**

| Location | Finding                                 |
|----------|---|
| 41       | The secondary anchor down guy is slack. |
| 42       | The anchor down guy is slack.           |
| 107      | The secondary anchor down guy is slack. |

**9. GO 95, Rule 56.7-B, Location of Sectionalizing Insulators, Anchor Guys** states in part:

*“In order to prevent trees, buildings, messengers, metal–sheathed cables or other similar objects from grounding portions of guys above guy insulators, it is suggested that anchor guys be sectionalized, where practicable, near the highest level permitted by this Rule.”*

ESRB’s findings related to the above rule are listed in Table 11:

**Table 11: GO 95, Rule 56.7-B Findings**

| Location | Finding  |
|----------|--|
| 40       | The pole has vegetation above the guy insulator that is contacting and grounding the primary and secondary anchor down guys. |
| 70       | The pole has vegetation above the guy insulator that is contacting and grounding the anchor down guy.                        |

**10. GO 95, Rule 56.9, Guy Marker (Guy Guard) states:**

*“A substantial marker of suitable material, including but not limited to metal or plastic, not less than 8 feet in length, shall be securely attached to all anchor guys. Where more than one guy is attached to an anchor rod, only the outermost guy is required to have a marker.”*

ESRB’s finding related to the above rule is listed in Table 12:

**Table 12: GO 95, Rule 56.9 Finding**

| <b>Location</b> | <b>Finding</b>                              |
|-----------------|---|
| <b>48</b>       | The anchor down guy is missing a guy guard. |

**11. GO 95, Rule 59.4-A(2)(c) Grounding, Material and Size, Ground Rods (Ground Electrodes) states in part:**

*“Ground rods shall be driven into the ground so that one end of the ground rod is at a minimum depth of 8 feet below the surface of the ground.”*

ESRB’s finding related to the above rule is listed in Table 13:

**Table 13: GO 95, 59.4-A(2)(c) Finding**

| <b>Location</b> | <b>Finding</b>   |
|-----------------|--|
| <b>33</b>       | The pole has an exposed grounding rod. PacifiCorp has an existing tag to replace the pole. |

**12. GO 95, Rule 91.3-C, Stepping states:**

*“Where installed, the lowest step shall not be less than 8 feet from the ground line, or any easily climbable foreign structure from which one could reach or step. Above this point steps shall be placed, with spacing between steps on the same side of the pole not exceeding 36 inches, at least to that conductor level above which only circuits operated and maintained by one party remain. Steps or fixtures for temporary steps shall be installed as part of a pole restoration process. Steps shall be so placed that runs or risers do not interfere with the free use of the steps.”*

ESRB’s finding related to the above rule is listed in Table 14:

**Table 14: GO 95, Rule 91.3-C Finding**

| <b>Location</b> | <b>Finding</b>                |
|-----------------|-------------------------------|
| 72              | The pole has a low pole step. |

**13. GO 128, Rule 17.8, Identification of Manholes, Handholes, Subsurface and Self-contained Surface-mounted Equipment Enclosures** states:

*“Manholes, handholes, subsurface and self-contained surface-mounted equipment enclosures shall be marked as to ownership to facilitate identification by persons authorized to work therein and by other persons performing work in their vicinity.”*

ESRB’s findings related to the above rule are listed in Table 15:

**Table 15: GO 128, Rule 17.8 Findings**

| <b>Location</b> | <b>Finding</b>  |
|-----------------|---|
| 18              | The padmount transformer is missing an ownership marking. |
| 63              | The padmount switch is missing an ownership marking.      |
| 78              | The padmount transformer is missing an ownership marking. |
| 118             | The padmount transformer is missing an ownership marking. |

**14. GO 128, Rule 35.3, Warning Signs** states:

*“Warning signs indicating high voltage shall be installed on an interior surface, or barrier if present, inside the entrance of vaults, manholes, handholes, pad mounted transformer compartments, and other above ground enclosures containing exposed live parts above 750 volts. Such warning signs shall also be installed on an exterior surface of all such pad mounted transformer compartments and other above ground enclosures. Such signs shall be clearly visible to a person in position to open any such access door, other opening, or barrier.”*

ESRB’s finding related to the above rule is listed in Table 16:

**Table 16: GO 128, Rule 35.3 Finding**

| <b>Location</b> | <b>Finding</b>  |
|-----------------|---|
| 118             | The padmount transformer has a faded high voltage sign. |

**V. Observations**

**1. GO 95, Rule 18, Reporting and Resolution of Safety Hazards Discovered by Utilities** states in part:

*“For purposes of this rule, “Safety Hazard” means a condition that poses a significant threat to human life or property...”*

**GO 95, Rule 18-A, Resolution of Potential Violations of General Order 95 and Safety Hazards** states in part:

*“(3) If a company, while performing inspections of its facilities, discovers a Safety Hazard(s) on or near a communications facility or electric facility involving another company, the inspecting company shall notify the other entity of such Safety Hazard(s) no later than ten (10) business days after the discovery.*

*(4) To the extent a company that has a notification requirement under (2) or (3) above cannot determine the facility owner/operator, it shall contact the pole owner(s) within ten (10) business days if the subject of the notification is a Safety Hazard, or otherwise within a reasonable amount of time not to exceed 180 days after discovery. The notified pole owner(s) shall be responsible for promptly (normally not to exceed five business days) notifying the company owning/operating the facility if the subject of the notification is a Safety Hazard, or otherwise within a reasonable amount of time not to exceed 180 days, after being notified of the potential violation of GO 95.”*

During the field inspection, ESRB observed the third-party safety concerns listed in Table 17:

**Table 17: Third-Party Observations**

| Location | Observation  |
|----------|--|
| 1        | The pole has a slack Spectrum anchor down guy.   |
| 3        | Frontier has an incomplete pole transfer.<br>The pole has a low Spectrum line with insufficient clearance.                               |
| 5        | Frontier has an incomplete pole transfer.<br>The pole has Spectrum equipment in contact with an anchor down guy above the insulator bob. |
| 6        | The pole has an abandoned underground communications conductor.  |
| 8        | The pole has an abandoned Frontier drop.   |
| 14       | The pole has an exposed Spectrum ground wire.  |

| <b>Location</b> | <b>Observation</b>  |
|-----------------|---|
| <b>15</b>       | The pole has an unsecured Spectrum drop.  |
| <b>16</b>       | The pole has an abandoned communications ground wire.   |
| <b>21</b>       | Frontier has an incomplete pole transfer.   |
| <b>25</b>       | Frontier and Charter have incomplete pole transfers.  |
| <b>26</b>       | The communications pole has obstructed climbing space. PacifiCorp has an existing tag for this issue.   |
| <b>27</b>       | The pole has an unsecured Spectrum drop.  |
| <b>28</b>       | Communications has an incomplete pole transfer.   |
| <b>32</b>       | The pole has an abandoned communications drops.<br>The pole has communication anchor down guys in contact above the insulator bobs.                                       |
| <b>39</b>       | The pole has a slack Spectrum anchor down guy.  |
| <b>40</b>       | The pole has a slack Spectrum anchor down guy.  |
| <b>43</b>       | The pole has an abandoned Frontier drop.  |
| <b>46</b>       | The pole has an unsecured communications drop.  |
| <b>48</b>       | The communications pole between Location 47 and Location 48 is leaning.   |
| <b>49</b>       | The Frontier conductor between the pole at Location 49 and the next pole is low and only supported by a stick.  |
| <b>50</b>       | The pole has a slack communications anchor down guy.  |
| <b>53</b>       | The pole has an abandoned communications drop.  |
| <b>56</b>       | The pole has an abandoned communications drop.<br>The pole has communication conductors in contact.<br>The pole has an unattached communications down guy with no anchor. |
| <b>65</b>       | The pole has a slack communications anchor down guy.  |
| <b>69</b>       | Frontier has vegetation causing excessive strain and abrasion on drops between Location 69 and Location 70.   |
| <b>70</b>       | Frontier has an incomplete pole transfer.<br>The pole has vegetation above the Spectrum anchor down guy insulator bob.  |
| <b>72</b>       | The pole has an exposed communications ground wire.   |
| <b>74</b>       | The pole has Frontier drops in contact with Spectrum facilities.  |
| <b>85</b>       | The pole has an abandoned communications drop.  |

| <b>Location</b> | <b>Observation</b>  |
|-----------------|---|
| <b>87</b>       | The pole has an unattached communications down guy with no anchor.  |
| <b>88</b>       | The pole has unsecured Frontier drops hanging from the Frontier equipment box.                                      |
| <b>89</b>       | The pole has an unattached Spectrum down guy with no anchor.  |
| <b>90</b>       | The pole has abandoned communications drops.  |
| <b>92</b>       | Spectrum has a low line unsupported by poles along Old Gasquet Toll Road, Gasquet.                                  |
| <b>96</b>       | The pole has an abandoned Spectrum drop.  |
| <b>97</b>       | The pole has vegetation causing excessive strain on a Spectrum drop.  |
| <b>100</b>      | The pole has a slack Spectrum down guy.   |
| <b>102</b>      | The pole has an abandoned Spectrum drop.  |
| <b>105</b>      | The pole has abandoned Frontier and Spectrum drops.   |
| <b>106</b>      | The pole has an abandoned Frontier drop.  |
| <b>108</b>      | The pole has an abandoned Frontier drop.  |
| <b>110</b>      | The pole has an unsecured Spectrum drop.<br>The pole has a cut exposed Frontier ground wire.                        |
| <b>111</b>      | The pole has a slack Spectrum down guy.   |
| <b>114</b>      | The pole has an abandoned Frontier drop.  |
| <b>116</b>      | The pole has Spectrum equipment in contact with Frontier facilities.  |
| <b>117</b>      | The pole has an unsecured Frontier riser.<br>Communications drops in contact between Location 116 and Location 117. |
| <b>123</b>      | Spectrum has underground equipment with no riser.   |
| <b>124</b>      | Spectrum has an uncovered underground enclosure.<br>Frontier has underground equipment with no enclosure.           |