RESPONSE TO THE CPUC AUDIT FINDINGS

GATEWAY ENERGY STORAGE FACILITY JUNE 2 – JUNE 5, 2025 (AUDIT NUMBER ESS2025-01GW)

Table of Contents

1)	Introduction
2)	Response to Findings
3)	Appendix A – Corrective Action Plan21
4)	Attachment Finding 222
5)	Attachment Finding 425
6)	Attachment Finding 5
7)	Attachment Finding 6a
8)	Attachment Finding 6b29
9)	Attachment Finding 730
10)	Attachment Finding 831
11)	Attachment Finding 9a32
12)	Attachment Finding 9b33
13)	Attachment Finding 1034
14)	Attachment Finding 1135
15)	Attachment Finding 12a36
16)	Attachment Finding 12b45
17)	Attachment Finding 1346
18)	Attachment Finding 15a47
19)	Attachment Finding 15b49
20)	Attachment Finding 1650

1) Introduction¹

Gateway Energy Storage, LLC ("Gateway")¹ appreciates the opportunity to respond to the California Public Utilities Commission ("CPUC") Audit Findings of Gateway Energy Storage Facility June 2–June 5, 2025 ("Audit Report"). The Audit Report addresses Gateway's compliance with General Order 167-C ("GO-167-C"), including related Operation, Maintenance, and Logging Standards. The Audit Report presents "Findings" from the audit conducted by the Commission's Electric Safety and Reliability Branch ("ESRB") on June 2 through June 5, 2025 ("Audit"). Gateway responded to numerous information and data requests from ESRB and provided documentation and on-site support during the audit.

The Audit Report contains 16 Findings, which allege potential violations of GO-167-C requiring corrective action. Gateway notes that GO-167-C was only recently approved by the CPUC and Gateway was not required to certify compliance with GO-167-C at the time of the audit. Gateway completed full compliance with GO-167-C and notified the CPUC of compliance with the Logging Standard, Operations Standard, and Maintenance Standard effective September 9, 2025.

Gateway has taken appropriate action to address the issues identified in the Audit Report. Gateway has closed 14 of the 16 Findings and is tracking to close the remaining two Findings by the end of October. None of the purported issues identified in the Findings pose a significant risk to safety or reliability.

¹ Gateway's participation in this GO 167 audit is purely voluntary and Gateway expressly reserves all rights to assert any privilege or objection to additional requests for information. Gateway also expressly reserves all rights to challenge the legality and applicability of California Public Utilities Code Section 761.3 and the implementation of such statue by the Commission or any other agency or instrumentality of the State of California

2) Response to Findings

a) Finding 1:

- i) Gateway Energy Storage (Gateway) has not conducted an Arc Flash analysis for Gateway 1 and substation equipment since 2020.
- ii) Gateway response to Finding 1:
 - (1) Gateway has contracted with _______ to perform the five-year review of the Arc Flash analysis at Gateway 1 and the Gateway substation. A purchase order was issued for this work scope to ______. The revised report is expected to be received before December 31, 2025.
 - (2) Gateway has created a work order in the site CMMS that will generate and provide a reminder to have the incident energy analysis reviewed for accuracy at intervals of 5 years.
 - (3) Upon completion of the Arc Flash review:
 - (a) Gateway will submit the updated Arc Flash analysis to Electric Safety, and Reliability Branch (ESRB).
 - (b) Gateway will update all Arc Flash equipment labels at Gateway 1 and substation.
- iii) Status: Open tracking to close by 12/31/2025

b) Finding 2:

- i) Gateway must ensure that all agreed-upon updates from the evacuation drill critique are incorporated into the Emergency Response Plan (ERP).
- ii) Gateway response to Finding 2:
 - (1) In September 2024 Emergency Response Plan drill critique a suggestion was made by a local agency to include the square footage of the battery storage buildings in the emergency response plan.
 - (2) Gateway had a discussion on this matter with local Fire Department officials to determine if the recommendation made during the critique was still applicable. The Fire Department confirmed the request was still valid and requested the building square footage be added to Appendix 2 "Quick Reference Guide" of the site Emergency Response Plan.
 - (3) The building square footage was included within revision 5 of the Gateway Emergency Response Plan quick reference guide.
- iii) Attachment Finding 2 find The Quick Reference Guide (Appendix 2) from the Gateway Emergency Response Plan.
- iv) Status: Closed 09/04/2025

c) **Finding 3**:

- i) Lack of documented plan to address insurance recommendation for roof vent fusible link replacement.
- ii) Gateway response to Finding 3:
 - (1) Insurance 2022 Property Inspection report recommendation advised replacing fused links in rooftop mounted vents with rated links.
 - (2) The purpose of the fuse link is to ensure that the smoke and heat removal vent does not open before the activation of the fire sprinkler system. If the vent opened before a sufficient number of sprinklers activate, then a delay in sprinkler activation may occur.
 - (3) Gateway contracted to review the insurance recommendation.
 - (a) Building code used for permitting Gateway first five buildings:
 - (i) 2016 Edition of the California Building Code (CBC)
 - (ii) 2016 Edition of the California Fire Code (CFC)
 - (b) Gateway met both CBC and CFC at time of construction.
 - (c) 2016 edition of CBC Section 910 or NFPA 13 Section 12.1.1.1 only note that the roof vents are required to have a higher temperature rating than the automatic sprinklers.
 - (d) NFPA 204 appendix Section A11.1 notes that where smoke and heat vents with automatic activation are provided in a building protected by an automatic sprinkler system the activation temperature should be a minimum of 70F greater than the sprinkler activation temperature.
 - (i) Gateway installed fuse link rating:
 - (ii) Gateway sprinkler head rating:
 - (iii) Fuse link rating is higher than sprinkler head rating.
 - (e) The 2022 edition of CBC Section 910.3.5 does provide a rating of 360F for the fusible link. Gateway1 was not subject to 2022 edition of CBC
 - (f) Gateway 1 fully meets the requirements at the time of construction.
 - (g) Gateway does not intend to implement the recommendation and considers this item to be closed.
- iii) Status: Closed 9/22/2025

d) **Finding 4**:

- i) Gateway must align the fire response procedures across its emergency response documents to ensure consistency.
- ii) Gateway response to Finding 4:
 - (1) Gateway Plant Operating Procedure "Operational Emergency Response" provides guidance on operator action that should be taken for plant operational issues, such as HVAC trip, Inverter trip, Telemetry issues, black plant, etc.
 - (2) At the time of the audit contained a section that provided immediate action should an operator discover any type of fire at the plant site. These actions corresponded with the actions as outlined in the Site Emergency Response Plan
 - (3) While did not contradict it's clear to Gateway that this caused some confusion with the ESRB auditors.
 - (4) To remove any confusion, Gateway updated removing the immediate fire response actions and now just references to refer to the Emergency Response Plan
- iii) Attachment Finding 4 contains the applicable revised section of
- iv) Status: Closed 7/29/2025

e) Finding 5:

- i) Work orders for completed tasks have not been closed out.
- ii) Gateway response to Finding 5:
 - (1) At the time of the audit Gateway did have several open work orders for work that had been completed.
 - (2) Gateway Technicians received training on the importance of timely closing of work orders.
 - (3) Gateway added work order backlog review to the weekly maintenance planning meeting.
 - (4) Gateway created a recurring monthly PM to review all work orders and close as needed.
- iii) Attachment Finding 5 contains the monthly PM to review and close work order backlog.
- iv) Status: Closed 6/19/2025

f) Finding 6:

- i) Leaking backflow preventer valve at facility entrance requires repair.
- ii) Gateway response to Finding 6:
 - (1) Gateway created work order to track finding.
 - (2) Gateway contracted to perform annual backflow inspection and to repair the leaking relief valve that was identified during the audit.
 - (3) On August 18, 2025 completed the annual inspection and repaired the leaking relief valve.
- iii) Attachment Finding 6a find the repair August 18, 2025, inspection and repair reports.
- iv) Attachment Finding 6b find the photo following repair.
- v) Status: Closed 08/18/2025

g) **Finding 7**:

- i) Gateway must investigate and resolve the active motor alarm on the overcurrent protection relay panel.
- ii) Gateway response to Finding 7:
 - (1) Gateway created work order to track finding.
 - (2) Gateway contracted with _____ on June 16, 2025 to diagnose the alarm on the ____ relay for ____.
 - (3) On June 20,2025 the Technician completed his diagnoses of the alarm. His findings:
 - (a) The charging motor and charging motor thermal relay are working as intended.
 - (b) It was determined that the alarm contact was wired to a normally closed contact and should be wired to the normally open contact.
 - (4) A site substation outage is required to move the wire to a normal open contact and verify proper operation.
 - (5) Gateway has a planned outage scheduled from October 20th to October 24th.
 - (6) Gateway will complete wiring change and verification during the October outage.
- iii) Attachment Finding 7 contains screenshot of work order.
- iv) Status Open tracking to close by 10/24/2025

h) **Finding 8**:

- i) Gateway did not generate a work order for a fan failure alarm, delaying proper tracking of the issue.
- ii) Gateway response to Finding 8:
 - (1) During the audit, the ESRB auditors reviewed the alarm log in OEM local operating system.
 - (2) Gateway is remotely operated by who utilizes who utilizes to operate and monitor alarms for Gateway.
 - (3) As a remote operated site, the local OS is not continuously monitored.
 - (4) Gateway did not have a process in place to review alarms that come into the OS at the time of the audit, as Gateway relied on alarm response.
 - (5) Gateway implemented a weekly review of the alarm log within
- iii) Attachment Finding 8 contains the weekly alarm inspection.
- iv) Status Closed 6/26/2025

i) Finding 9:

- i) Broken and outdated hot sticks were observed in the control house and must be removed or replaced.
- ii) Gateway response to Finding 9:
 - (1) ESRB auditors found two broken hot sticks which had been left in the corner of the substation control house.
 - (2) Gateway immediately disposed of the two broken hot sticks.
- iii) Attachment Finding 9a photographic evidence of broken hot sticks removal
- iv) Attachment Finding 9b current hot stick inventory list with inspection dates.
- v) Status Closed 6/6/2025

j) Finding 10:

- i) ESRB inspectors observed a flammable material storage cabinet without a selfclosing mechanism.
- ii) Gateway response to Finding 10:
 - (1) The self-closing mechanism on the small flammable cabinet at Gateway had failed.
 - (2) Gateway purchased a new flammable storage cabinet and disposed of the old cabinet.
- iii) Attachment Finding 10 photographic evidence of new flammable storage cabinet.
- iv) Status Closed 6/26/2025

k) Finding 11:

- i) The hazardous waste collection drum must be clearly labeled.
- ii) Gateway response to Finding 11:
 - (1) Gateway does not store hazardous waste at site. If any hazardous waste is generated it is transported to a proper handing facility.
 - (2) Gateway does maintain a hazardous waste storage area with empty drums in case they are needed.
 - (3) At the time of the inspection Gateway had an empty drum in the hazardous was storage area. The "Empty" label had fallen off the drum.
 - (4) Gateway re-installed "Empty" labels on the drums stored in the hazardous materials area.
 - (5) Inspection of hazardous materials storage area to ensure all drums are properly labeled is part of the quarterly site safety inspection.
- iii) Attachment Finding 11 photographic evidence of properly labeled drums in hazardous waste storage area.
- iv) Status Closed 6/26/2025

l) Finding 12:

- i) Gateway lacks records of required quarterly site safety inspections.
- ii) Gateway response to Finding 12:
 - (1) Gateway created a quarterly site safety inspection PM to comply with this requirement.
 - (2) The quarterly site safety inspection is divided into different areas of the plant property.
 - (3) Any findings from the inspection are captured in the work order system and tracked on a site safety inspection tracking document.
- iii) Attachment Finding 12a quarterly site safety inspection document.
- iv) Attachment Finding 12b sample of quarterly site safety inspection action tracking document.
- v) Status Closed 9/05/2025

m) Finding 13:

- i) The physical Lockout/Tagout (LOTO) procedure in the LOTO binder is outdated and must be updated.
- ii) Gateway response to Finding 13:
 - (1) Gateway removed and destroyed the outdated printed version, replacing it with the current version of the LOTO procedure.
- iii) Attachment Finding 13 photographic evidence of updated procedure in site safety binder.
- iv) Status Closed 7/26/2025

n) Finding 14:

- i) Equipment inspection tags are missing or outdated.
- ii) Gateway response to Finding 14:
 - (1) During the audit closing meeting, the ESRB auditors notified Gateway of three different items associated with tags at Gateway.
 - (2) Gateway investigated both items:
 - (a) Eyewash Station tags
 - (i) At Gateway monthly eyewash station inspections are tracked on a tracking sheet stored in the CMMS. Inspections are not tracked on a tag.
 - (ii) Gateway ensured no eyewash station had a miscellaneous tag installed.
 - (iii) While Gateway does not agree with the findings as it relates to the eyewash station tags the site implemented the following improvements:
 - Ensured no eyewash station had a manufacture installed inspection tag.
 - 2. Installed sticker on each eyewash station that directs people to CMMS for inspection documentation.
 - 3. Verified in CMMS that all eyewash station inspections had been correctly completed and documented.
 - (b) Fire Extinguisher tags
 - (i) Gateway performs monthly inspections of all fire extinguishers at site.
 - (ii) The Technician initials and dates the tag monthly upon completing the inspection.
 - (iii) An outside vendor performs an annual inspection of all Gateway fire extinguishers. Upon completion of the annual inspection the vendor installs a new tag on the extinguisher. The tag identifies the date of the annual inspection.
 - 1. The last annual inspection for extinguishers installed around the plant was performed on .
 - 2. The last annual inspection on the spare fire extinguishers was performed on .
 - (iv) During the April 2025 monthly inspection, the Technician found one extinguisher that was missing the inspection tag.
 - The Technician replaced the extinguisher with a spare extinguisher and signed the tag.

- 2. The Technician noted in the CMMS work order that he had found the tag missing and had replaced the extinguisher with a spare.
- (v) While Gateway does not agree with the findings as it relates to the fire extinguishers the site did implement the following improvements:
 - 1. Site Manager provided refresher training for all Technicians on steps to take when they find a missing inspection tag.
 - 2. Added a policy to document the inspection tag when the tag was replaced.
- iii) Status Closed 09/04/2025

o) Finding 15:

- i) The hazardous materials list in the hazardous materials physical folder must be updated to include Gateway 2.
- ii) Gateway response to Finding 15:
 - (1) Gateway reviewed and updated the hazardous materials list to include all hazardous substances present within building 6 and building 7.
 - (2) Gateway reviewed the SDS electronic database to ensure all listed items on the hazardous materials list are included within the database.
 - (3) Gateway implemented an annual PM to review the hazardous materials list for accuracy.
- iii) Attachment Finding 15a find the Hazardous materials list.
- iv) Attachment Finding 15b find the annual PM to review the hazardous materials list.
- v) Status Closed 6/26/2025

p) Finding 16:

- i) Gateway must replace deteriorated signage.
- ii) Gateway response to Finding 16:
 - (1) Gateway completed a site wide inspection of all signage.
 - (2) Gateway updated the quarterly site safety inspection to include a check of the condition of all signage. A work order is created for all items found deficient during a quarterly site inspection and are tracked on the quarterly site safety inspection action-item list.
- iii) Attachment Finding 16 find photographic evidence of replaced faded signage.
- iv) Status Closed 6/26/2025


3) Appendix A – Corrective Action Plan


Findings #	CPUC Audit Findings	Action Taken to Close Finding	Assigned to	Status	Date Closed
	An updated arc flash analysis is needed for equipment last studied				
	in 2020.				
1				In-Progress	
1	The facility should ensure that all agreed-upon items from the		-	III-Progress	
	Evacuation Drill Report and Critique live document are incorporated				
2	into the ERP.			Completed	9/4/2025
	Lack of documented plan to address insurance recommendation for				
3	roof vent fusible link replacement			Completed	9/22/2025
	Fire procedures in the ERP and the operational emergency response				
4	plan should be reviewed and aligned for consistency.			Completed	7/29/2025
	Old work orders for completed tasks remain open. The facility				
	should close out all completed work orders to maintain accurate				
5	records.			Completed	6/19/2025
	The backflow preventer valve at the front of the facility is leaking and				
	should be repaired.				
6				Completed	8/18/2025
- 0	A GCB1 motor alarm was active on the 351 overcurrent protection		+	Completed	6/16/2023
	relay panel in the substation control house and needs to be				
	addressed.				
7				In-Progress	
	A fan failure alarm occurred on and				
	was acknowledged on however no work order was				
	written up for the war all the time of the audit. Ensure alarms				
	are promptly acknowledged and, if necessary, followed by work				0/00/0005
8	order entry in the management system. Broken and outdated hot sticks were observed in the control house		-	Completed	6/26/2025
9	and should be removed or replaced.			Completed	6/6/2025
	The site flammable storage cabinet must be self-closing and self-			Completed	0/0/2023
10	latching to meet safety requirements.			Completed	6/26/2025
	The hazardous waste collection drum must be clearly labeled.				
	, , , , , , , , , , , , , , , , , , , ,				
11				Completed	6/26/2025
	Quarterly site safety inspections are required; however, no				
	documentation was provided. The facility should ensure these				
12	inspections are being conducted and properly documented.			Completed	9/5/2025
10	The physical Lockout/Tagout (LOTO) procedure in the LOTO binder is			0	7/00/0005
13	outdated by one revision and should be updated Eyewash stations and fire extinguishers must have			Completed	7/26/2025
	current inspection tags properly signed off monthly or as required.				
	Several items showed missed inspections over multiple months.				
	The should incode inspections over matapie months.				
14				Completed	9/4/2025
	The hazardous materials list in the hazardous materials physical				
15	folder must be updated to include Gateway 2.			Completed	6/26/2025
	Faded stickers and labels were observed throughout the facility and				
	should be replaced to ensure visibility and compliance				
16				Completed	6/26/2025


4) Attachment Finding 2



Emergency Response Plan







Public Version

5) Attachment Finding 4



OPERATIONAL EMERGENCY RESPONSE



1.0 PURPOSE

This procedure provides a list of possible operational emergencies and the correct response actions should they occur.

ENERGY STORAGE

2.0 GENERAL


The following situations and responsive actions are not to be considered all inclusive, as it is not feasible to list every possible plant operational emergency which may arise. Operational experience, actual plant conditions at the time, good engineering practices and common sense must be considered in any emergency condition, but the listed responses should be considered as sound and decisive corrective actions. These emergency procedures are more definitive by their nature; therefore, these responses should generally be followed unless a good reason exists not to do so.

3.0 GUIDELINES

- 3.1 Fire onsite
 - 3.1.1 Reference Site Emergency Response Plan

GATEWAY

6) Attachment Finding 5




7) Attachment Finding 6a

ACCOUN	NT INFORMATION						
Location Na					Meter Numbe	r	
	Y ENERGY STORAG		Control Front		Dhara		
Contact Nan	ne	,	Contact Email		Phone		
Service Add	ress:				Account Nun	nber	\neg
Destantian T		Hanned Torre			Herend I ame		
Protection T	ainment Isolation	Hazard Type			Hazard Level	Lov	.
							•
Device Type	BLY INFORMATION Make	Model	Size	Serial Number	New I	nstall Date	
Location	•	·		•	•		
TESTING	& MAINTENANC	E	-				
	Check Valve #1	Check Valve #2	Relief Valve	PVB/SVB	Shut (Off Valve	s
				Air Inlet Opened at		#1	#2
				PSID			
Initial				Opened Fully	Closed Tigl	ht 🗌	
Test				Check Held at	Leaked		
				PSID			
				Leaked			
				Cleaned		+	\vdash
				Replaced:			
R				Air Inlet Disc			
E				Air Inlet Spring			
P				Check Disc			
A				Check Spring			
l R				Float Diaphragm			
ı "				Rubber Kit			
				Other			
Final	-			Air Inlet PSID	Closed Tig	ht 🗆	Ш
Test				CK Valve PSID			
	re at Time of Test	Test Date		System Test Result			\vdash
2025-08-18							
Remarks Leak repo	rted- Passed after cl	ean and Flush					
TESTER	ATTESTATION, T	EST KIT INFORMA	TION & TEST RE	SULTS			
The a	above report is certifie	ed to be true.					
Gauge Make	<u>. </u>	Model	Gauge I	lo. Cal	Ibration Date		$\neg \neg$
Total ::					4.11		
Tester Name		Testing Company		Cel	t No.		

ACCOUI	NT INFORMATION					Meter	Number		
	Y ENERGY STORAG	3E							
Contact Na	me	C	Contact Email			Phon	0		
Service Add	fraco.					Acco	unt Number		
Service Aut	11000.					A000	unt Number		
Protection 1	Гуре	Hazard Type				Hazai	d Level		
Cont	ainment Isolatio	n					High	Lov	v
ASSEME	BLY INFORMATION	N							
Device Type	Make	Model		Size	Serial Numbe	г	New Insta	II Date	
Location									
Location									
TESTING	S & MAINTENANC		Ι		I				
	Check Valve #1	Check Valve #2	Relief	Valve	PVB/SVB		Shut Off	Valves	
					Air Inlet Opened at			#1	#2
					PSID				
Initial					Opened Fully	Clos	ed Tight		$ \Box $
Test					Check Held at	Leak	ed		
					PSID				
					Leaked			<u> </u>	Щ
					Cleaned				
_					Replaced:				
R					Air Inlet Disc				
E					Air Inlet Spring				
P					Check Disc				
ı					Check Spring				
Ŕ					Diaphragm				
"					Rubber Kit				
					Other				
Final					Air Inlet PSII	Clos	ed Tight	\vdash	П
Test							eu rigiit	╵┖	ᅵᅵᅵ
	re at Time of Test	Test Date				<u>' </u>			\Box
Line Pressure at Time of Test Test Date 2025-08-18				System Test Result					
Remarks									
Leak repo	orted- passed after cl	ean and flush							
		EST KIT INFORMA	ATION & T	EST RE	SULTS				
Gauge Make	above report is certific	Model		Gauge N	0 1	Calibration	Date		
Gauge mak		model .		Gauge N	o.	JampiauON	Date		
Tester Nam	9	Testing Company			_	Cert No.			

8) Attachment Finding 6b




Backflow preventer post leak repair – photo taken 9/23/2025


9) Attachment Finding 7

9/2/25, 2:02 PM Work Orders (No Grouping) RFV Renewables Work Order Gateway Energy Storage Printed 9/2/2025 - 2:01 PM (Duplicate Copy) Maintenance Details Requested By: Target: Priority/Type: Phone: Supervisor: Email: Taken By: Problem: Alarm (ALARM) Model: Last PM: Serial: Manufacturer: Reason: Relay In Control House: Loss of Motor Power in Substation. Alarm Vicinity: indication on relay indicates loss of motor function on in the substation. Likely hood of not being able to close in breaker after being opened. Shutdown Attach Tasks Description Rating Initials Failed N/A Complete Meas. T/S Loss of Motor Power on relay in control house. (Alarm indicates that there is not adequate power to close the 10 Report findings and repair. Comments: This task requires followup steps to complete the repair. 20 Field Inspection scheduled for 06/20/25 Comments: completed a field inspection. I have attached their findings to this work order. 30 Follow-up task after the field inspection. will be completing a review of the system design, the wiring schematics, the relay configuration, and comparing those to industry best practices to make sure the relay is configured to alarm when it needs to and displays no alarms when operating in a non-alarm state. This will require an outage where we can perform point to point testing and breaker trip testing to confirm every point is setup correctlt. Comments: This task was completed. performed an additional analysis and confirmed their recommendations are the best course corrective action. To complete this will perform their corrective actions during the outage in October, then this will be confirmed by manually tripping and re-closing each breaker for a point to point verification. Partially completed because Completed as requested. Completed as requested. Completed as requested. This task is to be completed during the October 2025 outage. The wiring can be corrected and the breaker positions cwill be

10) Attachment Finding 8



11) Attachment Finding 9a




12) Attachment Finding 9b

Model #	Description	Mfg. Date	Last Recert Date	Next Recert Date

13) Attachment Finding 10



14) Attachment Finding 11



Labeled empty drums in Hazardous Waste Collection area


15) Attachment Finding 12a




Gateway Quarterly Site Safety Inspection










































16) Attachment Finding 12b




17) Attachment Finding 13



18) Attachment Finding 15a





19) Attachment Finding 15b

/23/25, 9:16 AM	Work Orders (No Grouping)					
REV Renewables						Work Order
┌ Maintenance Details						Gateway Energy Storage Closed Printed 9/23/2025 - 9:16 AM
Requested: 8/1/2025 9:12:00 AM Phone: Email: Problem: Preventive Maintenance (PM) Last PM: 9/10/2025	Target: Priority/Type:	9/25/2025 2 - Norma l / Pro	eventive		⊟ Gateway	
Reason: Hazardous material List Annual Review						
Labor						
Labor			Work Date 8/1/2025	Start	End	Reg Hrs OT Hrs Other Hrs
Labor Report						
Completed: 8/1/2025 9:14:00 AM Failure:				Meter(s): _		
Signature / Name	Date			Signatur	o / Name	Date

20) Attachment Finding 16

