PUBLIC UTILITIES COMMISSION

505 VAN NESS AVENUE SAN FRANCISCO, CA 94102-3298

October 20, 2022



GI-2022-05-SCG-65-02ABC

Mr. Rodger Schwecke Senior Vice President and Chief Infrastructure Officer Southern California Gas Company 555 West 5th Street, GT21C3 Los Angeles, CA 90013

Dear Mr. Schwecke:

The Safety and Enforcement Division (SED) of the California Public Utilities Commission (CPUC) reviewed Southern California Gas Company's (SoCalGas) response letter, dated September 28, 2022, that addressed four (4) out of nine (9) areas of concern identified during the General Order (G.O.) 112-F Comprehensive Operation and Maintenance Inspection of Southern California Gas Company (SoCalGas)'s NW San Joaquin Valley Distribution Area (Inspection Unit) conducted on May 2 through May 6, 2022. SED had closed the other five (5) areas of concerns in the inspection letter, dated August 29, 2022, based on SoCalGas' responses reviewed by SED at the time.

Attached is a summary of all SED's inspection findings, SoCalGas' responses to SED's findings, and SED's evaluation of SoCalGas' responses to the findings.

This letter serves as an official closure of the 2022 Comprehensive Inspections of SoCalGas' San Joaquin Valley Distribution Area. Any matters that are being considered for enforcement will be processed through the Commission's Citation Program or a formal proceeding.

Thank you for your cooperation in this inspection. If you have any questions, please contact Gordon Kuo, Utilities Engineer, at (213) 618-5263 or by email at gk2@cpuc.ca.gov.

Sincerely,

Hormon Stol

Mahmoud (Steve) Intably, P.E. Program and Project Supervisor Gas Safety and Reliability Branch Safety and Enforcement Division

cc: Alex Hughes, SoCalGas Gwen Marelli, SoCalGas Terence Eng, SED/GSRB Kan-Wai Tong, SED/GSRB Gordon Kuo, SED/GSRB Claudia Almengor, SED/GSRB

Post-Inspection Written Preliminary Findings

Date of Transmittal: 08/23/2022

Dates of Inspection: May 2-6, 2022

Operator: SOUTHERN CALIFORNIA GAS CO

Operator ID: 18484 (primary)

Inspection Systems: Bakersfield, Hanford, Porterville, and Visalia Distribution Districts

Assets (Unit IDs) with results in this report: Northwest - San Joaquin Valley (87048)

System Type: GD

Inspection Name: SoCalGas NW Distribution - San Joaquin Valley

Lead Inspector: Gordon Kuo

Operator Representative: Austin Walker, Miguel Gamboa, Francisco Santa Cruz, Miguel Gamboa

Unsatisfactory Results

No Findings.

Concerns

Records: Operations And Maintenance (PRR.OM)

Question Title, ID Normal Operations and Maintenance Procedures - History, MO.GO.OMHISTORY.R

Question 2. Are construction records, maps and operating history available to appropriate operating personnel? References 192.605(a) (192.605(b)(3))

Assets Covered Northwest - San Joaquin Valley (87048 (65))

Issue Summary Records for vault work order 520002773599 indicated that the sizes of the two vaults of Reg Station DRS 6677N were 200 cubic feet. During field visit on 5/5/2022, SoCalGas measured the vaults and confirmed that they were 6 feet x 6 feet x 5 feet (180 cubic feet). SED requests that SoCalGas updates the vaults' size on their records. On 5/20/22, SoCalGas updated SED that it had removed the vaults from the 200 cubic feet category. SED believes that SoCalGas has adequately addressed the discrepancy of the size description and accepts this correction taken by SoCalGas, but may review and reassess this item in future inspections.

Question Title, ID Maintenance of Equipment Used in Joining of Plastic Pipe by Heat Fusion, MO.GM.EQUIPPLASTICJOINT.R

Question 36. Do records indicate equipment used in joining plastic pipe by heat fusion was maintained in accordance with the manufacturer's recommended practices or with written procedures that have been proven by test and experience to produce acceptable joints?

References 192.603(b) (192.756)

Assets Covered Northwest - San Joaquin Valley (87048 (65))

Issue Summary Per SoCalGas, there are no requirements for taking pictures or other methods of capturing and maintaining records of equipment used in joining plastic pipe by heat fusion. While SoCalGas and SED acknowledge that GS 184.0130 requires employees to use approved and calibrated IR thermometers, there is no method outlined in the written procedures to keep track of which IR thermometer was used for a given project. Without the ability to track IR thermometers used in a given construction project, the IR thermometers' calibration records cannot be provided for review. Accordingly, IR thermometer calibration records were not provided for review during the inspection for projects such as Notification# 2040914037.

SED recommends SoCalGas to develop and implement record keeping requirements to identify and record specific information (e.g. Capital Tool number, calibration date) for calibrated equipment used in any given plastic pipe joining such as an additional form for plastic pipe joining records or another set of work records.

SoCalGas' Response and Remedial Action:

SoCalGas is exploring both interim and longer-term solutions to capture information related to plastic joiners and type of joints, and is evaluating what types of data to capture, such as capital tools used. Identifying and selecting a viable solution includes many considerations. Some of which include: technology reviews, training requirements, changes/impacts to current workforce procedures, overall risk analysis, deployment options and system sustainability with increased data entry/storage. Another key discussion topic revolves around data security/accuracy because non SoCalGas employees (contractors) who perform these tasks will also be involved with this new solution. SoCalGas will continue the analysis and planning efforts and report back with a status update to SED by end of year (2022).

SED's Conclusion:

SED has reviewed SoCalGas' response and accepts the proposed plans that it will explore and implement. However, SED would like to know the final plans and the course of implementation as soon as possible.

Pipeline Field Inspection: Pipeline Inspection (Field) (FR.FIELDPIPE)

Question Title, ID Customer Meters and Regulator Location, DC.METERREGSVC.CUSTMETERREGLOC.O

Question 4. Are meters and service regulators being located consistent with the requirements of 192.353?

References 192.351 (192.353(a), 192.353(b), 192.353(c), 192.353(d))

Assets Covered Northwest - San Joaquin Valley (87048 (65))

Issue Summary On 5/5/2022, SED observed SoCalGas personnel perform a leak survey on map 3-57. At the address of Visalia, SED observed tire tracks and a parked motorcycle near a meter set assembly (MSA). Although the path leading to the MSA was not paved, SED believed that vehicular activity did occur near the MSA and could pose a risk of damage to the MSA. SED suggested SoCalGas consider placing protective bollards at this location to prevent any vehicular access and damage to its meter. On 5/20/22, SoCalGas responded to and adequately addressed this concern by installing protection railings and bollards around the MSA. SED accepts the remedial action taken by SoCalGas, but may review and reassess this item in future inspections.

Question Title, ID Rectifier or other Impressed Current Sources, TD.CPMONITOR.CURRENTTEST.O

Question 17. Do field observations confirm impressed current sources are properly maintained and are functioning properly?

References 192.465(b)

Assets Covered Northwest - San Joaquin Valley (87048 (65))

Issue Summary On 5/5/2022, SED observed a field inspection of SoCalGas' cathodic protection systems. SED found that read point M00 of cathodic protection area (CPA) SL563-003 was -0.544 V, which was less negative than the -0.850 V requirement listed in Appendix D to 49 CFR Part 192. SoCalGas was able to raise the read to -0.719 V after adjusting its rectifier settings. After further diagnosis of the rectifier anodes by SoCalGas on 5/11/2022, SoCalGas planned to install a new deep well anode pit to bolster the cathodic protection current for the CPA. SED requests a copy of the work plan and/or work progress from SoCalGas regarding its permanent remediation of this cathodic protection deficiency for future reference.

SoCalGas' Response and Remedial Action:

Please note that the name of the cathodic protection area visited on 05/05/2022 was SL563-006, and the measurement taken at Read Point M00 was -0.507 V. M00 is a 100mV polarization read point, and the read tolerance limit is -0.544 V.

This area was brought into tolerance on 05/12/2022, after a technician adjusted the rectifier settings, and the measurement taken at Read Point M00 was -0.719V. In addition to adjusting the existing rectifier settings, SoCalGas is also planning a new deep well as a long-term solution. Planning is in progress, and the notification number for the project is 2042158856.

SED's Conclusion:

SED has reviewed SoCalGas' response and accepts the corrective actions that it has articulated and implemented. However, SED may review the records of the corrective action during future inspections.

Question Title, ID Interference Currents, TD.CPMONITOR.INTFRCURRENT.O

Question 22. Are areas of potential stray current identified, and if found, the detrimental effects of stray currents minimized?

References 192.473(a)

Assets Covered Northwest - San Joaquin Valley (87048 (65))

Issue Summary On 5/4/2022, SED observed that SoCalGas CPA SL 151-2 in the Bakersfield district, which contains a critical interference bond, was found to be down. SED requests SoCalGas to promptly take remedial actions for this CPA.

SoCalGas' Response and Remedial Action:

Cathodic Protection Area SL151-2 was brought into tolerance on 06/24/2022, after installing an anode for supplemental current.

SED's Conclusion:

SED has reviewed SoCalGas' response and accepts the corrective actions that it has articulated and implemented. However, SED may review the records of the corrective action during future inspections.

Question Title, ID Atmospheric Corrosion Monitoring, TD.ATM.ATMCORRODEINSP.O

Question 27. Do field observations indicate that pipe exposed to atmospheric corrosion is properly coated?

References 192.481(b) (192.481(c), 192.479(a), 192.479(b), 192.479(c))

Assets Covered Northwest - San Joaquin Valley (87048 (65))

Issue Summary #1: During leak surveys, SED observed signs of atmospheric corrosion at several MSAs. SED requested SoCalGas to assess the aboveground pipelines coating and remediates any atmospheric corrosion issues at the following locations:



On 5/20/22022, SoCalGas responded to and adequately addressed this concern by remediating the coating and atmospheric corrosion issues. SED accepts the remedial action taken by SoCalGas but may review and reassess this item in future inspections.

#2: During vault inspections on 5/5/2022, SED observed signs of atmospheric corrosion inside a vault structure, SAP ID: GD.NOR.VSL.CM.C0000012547, Visalia. SED requested SoCalGas to assess and remediate any atmospheric corrosion issues.

On 5/20/2022, SoCalGas responded to and adequately addressed this concern by remediating the observed issue on 5/12/22 (WO#520003043810). SoCalGas dewatered and cleaned the vault. SoCalGas

also cleaned and recoated the MSA within the vault. SED accepts the remedial action taken by SoCalGas, but may review and reassess this item in future inspections.

Question Title, ID Valve Maintenance Distribution Lines, MO.GM.DISTVALVEINSPECT.O

Question 37. Is proper inspection being performed for each distribution system valve that might be required in an emergency, and prompt remedial action to correct any valves found inoperable?

References 192.747(a) (192.747(b))

Assets Covered Northwest - San Joaquin Valley (87048 (65))

Issue Summary On 5/5/2022, SED observed the field inspection of Plug Valve 38000160. During this inspection, SED found that SoCalGas was not able to operate the plug valve, even with 3 employees. Subsequently, this inspection was marked as incomplete because the employees did not have enough time to lube the valve and confirm whether it was inoperable or hard to operate. SED requested SoCalGas to complete the inspection and provide the final work order detailing the results of this valve inspection, along with any other remedial actions taken if the valve was found to be inoperable.

On 5/20/22, SoCalGas responded to and adequately addressed this concern by flushing and operating the valve on 5/12/22. SoCalGas was able to return the valve to normal operating condition. SED accepts the remedial action taken by SoCalGas, but may review and reassess this item in future inspections.

Question Title, ID Prevention of Accidental Ignition, AR.RMP.IGNITION.O

Question 39. Perform observations of selected locations to verify that adequate steps have been taken by the operator to minimize the potential for accidental ignition.

References 192.751(a) (192.751(b), 192.751(c))

Assets Covered Northwest - San Joaquin Valley (87048 (65))

Issue Summary 1. On 5/4 – 5/2022, SED observed regulator station inspections and found no deployment of Barricades and cautionary signage near SoCalGas' Regulator Stations, RS 6297 and RS 667N, where their operations might create a gaseous atmosphere leading to the potential for accidental ignition during purging and bleeding of the gas from their pipelines.

On 5/20/22, SoCalGas stated that their crew would follow the SoCalGas Gas Standards SCG GS 185.0275 to implement signage in line with SCG GS 166.0025. In addition, SoCalGas' M&R workgroup would work with the policy holder of SCG GS 185.0275 on procedural changes. SED accepts the remedial action taken by SoCalGas, but may review and reassess this item in future inspections.

2. On 5/5/2022, during a vault inspection of Mt Whitney LCVM, a pre-entry inspection for natural gas indications was done via CGI. However, the Altair 5X multi-gas indicator was not activated and placed for sampling until a few minutes after the M&R personnel had entered the vault and begun their work. Per SoCalGas' Gas Standard 223.0210 - Vault Maintenance and Inspection 4.2, subsequent tests are to be conducted to insure a safe atmosphere. On 5/20/22022, SoCalGas responded to and adequately addressed this concern by reviewing the SoCalGas' Gas Standard on 5/13/22022 and documented the understanding of the Gas Standard between the employee and Visalia M&R work group on an Enterprise Training Form 5300. SED accepts the remedial action taken by SoCalGas, but may review and reassess this item in future inspections.

Generic Questions: Generic Questions (GENERIC.GENERIC)

Question Title, ID Generic Question, GENERIC.GENERIC.GENOBSERVE.O

Question 1. Generic question - please provide context in result notes.

References N/A

Assets Covered Northwest - San Joaquin Valley (87048 (65))

Issue Summary 1. During several leak surveys, SED observed the discovery of several leaks at the following addresses. Please provide the follow-up work orders for these leaks.





2. On 5/4/22, M&R field personnel were unable to fault two GMI units used at DRS ID 6297 and field tested at EPM ID 44003 in the Bakersfield district. On 5/6/22, SoCalGas stated both GMI Gasurveyors used by SoCalGas employees 63912 and 57526 (Tag 117970) were unable to show fault while conducting glove test and sent to Pico for further examination. SED would like to request a brief update on SoCalGas' findings and whether the condition encountered were caused by an isolated or systemic cause.

SoCalGas' Response and Remedial Action:

1. All of the leaks identified have been repaired. Below are the leak repair dates and order numbers:



2. GMI units were sent to the instrument shop for inspection. One of the units (117967) was cleaned, had the pump resealed, and was calibrated on 05/25/2022. The other unit (117970) had a new pump installed and was calibrated on 05/25/2022. Both units have been working properly since.

SED's Conclusion:

SED has reviewed SoCalGas' response and accepts the corrective actions that it has articulated and implemented. However, SED may review the records of the corrective action during future inspections.