STATE OF CALIFORNIA

EDMUND G. BROWN JR., Governor

PUBLIC UTILITIES COMMISSION 505 VAN NESS AVENUE SAN FRANCISCO, CA 94102-3298

December 10, 2012

Robert F. LeMoine Manager, Maintenance & Inspection Southern California Edison (SCE) 3 Innovation Way Pomona, CA 91768

SUBJECT: Electric Audit of SCE's Whittier District

Dear Mr. LeMoine:

On behalf of the Electric Safety and Reliability Branch of the California Public Utilities Commission, Derek Fong and Richard Kyo of my staff conducted an audit of SCE's Whittier District from October 22, 2012 to October 26, 2012. The audit included a review of SCE's records and field inspections of SCE's facilities.

During the audit, my staff identified violations of one or more General Orders. A copy of the audit summary itemizing the violations is enclosed. Please advise me no later than January 18, 2013 by electronic or hard copy, of all corrective measures taken by SCE to remedy and prevent such violations.

If you have any questions, you can contact Derek Fong at (213) 576-6850 or derek.fong@cpuc.ca.gov.

Sincerely,

Raffy Stepanian, P.E. Program Manager Electric Safety and Reliability Branch Consumer Protection and Safety Division

Enclosure: Audit Summary

CC: Raymond Fugere, Program and Project Supervisor, CPUC



EA2012-033

AUDIT SUMMARY

1.	Location:	Whittier District
	Date of CPUC Inspection:	10/22/2012
	Explanation of Violation(s):	
	Late Work Orders	
	GO 165, Section IV, Standards for Inspection, Record-keeping, and Reporting, States in part:	
	For all inspections, within a reasonable period, company records shall specify the circuit, area, or equipment inspected, the name of the inspector, the date of the inspection, and any problems identified during each inspection, as well as the scheduled date of corrective action.	
	SCE records indicated that from 2009 to 2012, 267 work orders were completed late. Additionally, in 2012, there were 131 open/past due work orders.	

2.	Location:	Pole No. 1582546E
	Previous SCE Visit Details:	07/05/2012
	Date of CPUC Inspection:	10/22/2012
	Explanation of Violation(s):	
	Reduced Ground Clearance	
	GO 95, Rule 37, Minimum Clearances of Wires above Railroads, Thoroughfares, Buildings, Etc., States in part:	
	The clearances between conductors, guys, messengers or trolley span wires and buildings, poles, structures, or other objects, shall not be less than those set forth in Table 1, at a temperature of 60 F and no wind.	
	An SCE service drop in an area accessible to vehicles had inadequate ground clearance. This violation was not documented when SCE last inspected the pole.	

3.	Location:	Pole No. 1581944E
	Previous SCE Visit Details:	07/02/2012
	Date of CPUC Inspection:	10/22/2012
	Explanation of Violation(s):	
	Reduced Clearance Between Wires	
	GO 95, Rule 38, Minimum Clearances of Wires from Other Wires, states in part:	
	The minimum vertical, horizontal or radial clearances of wires from other wires shall not be less than the values given in Table 2 and are based on a temperature of 60° F. and no wind.	
	The pole had a SCE guy wire touching a CIP cable. This violation was not documented when SCE last inspected the pole.	

4.	Location:	Pole No. 252234E
	Previous SCE Visit Details:	06/27/2012
	Date of CPUC Inspection:	10/23/2012
	Explanation of Violation(s):	
	Missing High Voltage Sign	
	GO 95, Rule 56.1-A, High Voltage Marking, states in part:	
	Poles which support line conductors of more than 750 volts shall be marked with high voltage signs.	
	The High Voltage sign on the crossarm was damaged. This violation was not documented when SCE last inspected the pole.	

5.	Location:	Pole No. 1154650E
	Previous SCE Visit Details:	06/27/2012
	Date of CPUC Inspection:	10/23/2012
	Explanation of Violation(s):	
	Reduced Clearance Between Wires	
	GO 95, Rule 38, Minimum Clearances of Wires from Other Wires, states in part:	
	The minimum vertical, horizontal or radial clearances of wires from other wires shall not be less than the values given in Table 2 and are based on a temperatur of 60° F. and no wind.	

The pole supported a SCE drop with less than 24 inches of radial clearance from a CIP drop beyond 15 feet from the point of attachment. This violation was not documented when SCE last inspected the pole.

6.	Location:	Pole No. M9860Y
	Previous SCE Visit Details:	06/27/2012
	Date of CPUC Inspection:	10/23/2012
	Explanation of Violation(s):	
	Reduced Clearance Between Wires	
	GO 95, Rule 38, Minimum Clearances of Wires from Other Wires, states in part:	
	The minimum vertical, horizontal or radial clearances of wires from other wires shall not be less than the values given in Table 2 and are based on a temperature of 60° F. and no wind.	
	The pole supported a SCE drop with less than 12 inches of radial clearance from a CIP drop at the point of attachment. This violation was not documented when SCE last inspected the pole.	

7.	Location:	Pole No. 650056E
	Previous SCE Visit Details:	06/20/2012
	Date of CPUC Inspection:	10/23/2012
	Explanation of Violation(s):	
	Reduced Clearance Between Wires	
	GO 95, Rule 38, Minimum Clearances of Wires from Other Wires, states in part:	
	The minimum vertical, horizontal or radial clearances of wires from other wires shall not be less than the values given in Table 2 and are based on a temperature of 60° F. and no wind.	
	The pole supported a SCE drop touching an SCE guy wire. This violation was not documented when SCE last inspected the pole.	