

## PUBLIC UTILITIES COMMISSION

505 VAN NESS AVENUE  
SAN FRANCISCO, CA 94102-3298



January 29, 2013

Robert F. LeMoine  
Manager, Maintenance & Inspection  
Southern California Edison (SCE)  
3 Innovation Way  
Pomona, CA 91768

EA2012-036

**SUBJECT:** Audit of SCE's Long Beach District

Dear Mr. LeMoine:

On behalf of the Electric Safety and Reliability Branch of the California Public Utilities Commission, Derek Fong and Richard Kyo of my staff conducted an audit of SCE's Long Beach District from November 26, 2012 to November 30, 2012. The audit included a review of SCE's records and field inspections of SCE's facilities.

During the audit, my staff identified violations of one or more General Orders. A copy of the audit summary itemizing the violations is enclosed. Please advise me no later than March 8, 2013 by electronic or hard copy, of all corrective measures taken by SCE to remedy and prevent such violations.

If you have any questions, you can contact Derek Fong at (213) 576-6850 or [derek.fong@cpuc.ca.gov](mailto:derek.fong@cpuc.ca.gov).

Sincerely,

A handwritten signature in black ink, appearing to read "R. Stepanian", with a long horizontal flourish extending to the right.

Raffy Stepanian, P.E.  
Program Manager  
Electric Safety and Reliability Branch  
Safety and Enforcement Division

Enclosure: Audit Summary

CC: Raymond Fugere, Program and Project Supervisor, CPUC

## AUDIT SUMMARY

The following violations that ESRB engineers discovered during the field audit and were not documented and addressed by SCE during its last detailed inspection as required by General Order 165:

<b>1.</b>	<b>Location:</b>	Pole No. 2276309E
	<b>Previous SCE Visit Details:</b>	08/29/2012
	<b>Date of CPUC Inspection:</b>	11/26/2012
<b>Explanation of Violation(s):</b>		
<b><u>Inadequate Clearance between SCE Triplex and Communication Service Drop</u></b>		
<p>GO 95, Rule 54.8-C4, From Communication Service Drops, states in parts:</p> <p style="text-align: center;"><i>The radial clearance between communication service drop conductors and supply service drop conductors may be less than 48 inches as specified in Table 2, Column C, Cases 4 and 9; Column D, Cases 3 and 8, but shall be not less than 24 inches. Where within 15 feet of the point of attachment of either service drop on a building, this clearance may be further reduced but shall be not less than 12 inches.</i></p> <p>An SCE triplex and a communication service drop had less than a 12 inches radial clearance within 15 feet from their point of attachment.</p>		

<b>2.</b>	<b>Location:</b>	Pole No. 4366742E
	<b>Previous SCE Visit Details:</b>	08/29/2012
	<b>Date of CPUC Inspection:</b>	11/26/2012
<b>Explanation of Violation(s):</b>		
<b><u>Loose V-Brace</u></b>		
<p>GO 95, Rule 31.1, Design, Construction and Maintenance, states in parts:</p> <p style="text-align: center;"><i>Electrical supply and communication systems shall be designed, constructed, and maintained for their intended use, regard being given to the conditions under which they are to be operated, to enable the furnishing of safe, proper, and adequate service.</i></p> <p>The pole had a loose V-brace at the primary crossarm.</p>		

<b>3.</b>	<b>Location:</b>	Pole No. 4336755E
	<b>Previous SCE Visit Details:</b>	04/01/2012
	<b>Date of CPUC Inspection:</b>	11/27/2012
<b>Explanation of Violation(s):</b>		
<b><u>Damaged/Missing High Voltage Sign</u></b>		
<p>GO 95, Rule 51.6-A, High Voltage Marking, states in parts:</p> <p style="text-align: center;"><i>Poles which support line conductors of more than 750 volts shall be marked with high voltage signs.</i></p> <p>The high voltage sign on the crossarm was damaged.</p>		

<b>4.</b>	<b>Location:</b>	Pole No. 1402327E
	<b>Previous SCE Visit Details:</b>	04/01/2012
	<b>Date of CPUC Inspection:</b>	11/27/2012
<b>Explanation of Violation(s):</b>		
<b><u>Damaged Riser Coupling</u></b>		
<p>GO 95, Rule 31.1, Design, Construction and Maintenance, states in parts:</p> <p style="text-align: center;"><i>Electrical supply and communication systems shall be designed, constructed, and maintained for their intended use, regard being given to the conditions under which they are to be operated, to enable the furnishing of safe, proper, and adequate service.</i></p> <p>The pole had a riser with a broken coupling.</p>		

<b>5.</b>	<b>Location:</b>	Pole No. 4454745E
	<b>Previous SCE Visit Details:</b>	04/01/2012
	<b>Date of CPUC Inspection:</b>	11/27/2012
<b>Explanation of Violation(s):</b>		
<b><u>Damaged Ground Wire Cover</u></b>		
<p>GO 95, Rule 31.1, Design, Construction and Maintenance, states in parts:</p> <p style="text-align: center;"><i>Electrical supply and communication systems shall be designed, constructed, and maintained for their intended use, regard being given to the conditions under which they are to be operated, to enable the furnishing of safe, proper, and adequate service.</i></p> <p>The pole had ground wire with a damaged moulding.</p>		

6.	<b>Location:</b>	Structure No. P5200918
	<b>Previous SCE Visit Details:</b>	07/02/2012
	<b>Date of CPUC Inspection:</b>	11/29/2012
<b>Explanation of Violation(s):</b>		
<p data-bbox="191 562 483 596"><b><u>Padmount Opening</u></b></p> <p data-bbox="191 638 1013 672">GO 128, Rule 34.3-B, Guarding Live Parts, states in parts:</p> <p data-bbox="321 709 1318 856"><i>Compartments and enclosures which will, during normal operation, contain exposed live parts shall be designed and installed to prevent a person from passing a wire or other conducting material into such compartment from the outside when it is closed.</i></p> <p data-bbox="191 894 1318 961">The padmount had an opening that would allow a person to pass a wire or other conducting material into the padmount.</p>		