



JOB# J-045679

SCN RESOLUTION & PHOTO

July 21, 2014

Version No: 3.2

Pole Number (Old Pole and New Pole, If Available)	Latitude/Longitude or Address	Noticing Company	Date Completed	Completed By
644931E	34.41174977 -119.86379973	HHS	11/14/2023	HAYDEN PRUDHOMME

What is the issue/correction required?

Crown Castle communications conductor had less than 12 inches of vertical separation from a third-party communications conductor.

PASADO RD N/S 352' W/O CAMINO DEL SUR

Were corrections made per Crown Castle's request? Yes ☒ No ☐ (If 'No' please provide a detailed response below)

Description of work performed.



Raised 1 Cable 6"

Placed Guard Arm and Fiber Tag

Trimmed Tree 65'

Before Photo #1	After Photo #1

SCN RESOLUTION & PHOTO

Before Photo #2 (If Necessary)	After Photo #2 (If Necessary)
 <p>A photograph of a tree with a red arrow pointing to its canopy and the text "Trim Needed". The coordinates 34.411743° N 119.863756° W are visible at the bottom.</p>	 <p>A photograph of a tree with a red arrow pointing to its canopy and the text "Trimmed Tree 45". The coordinates 34.411798° N 119.863600° W are visible at the bottom.</p>
Before Photo #3 (If Necessary)	After Photo #3 (If Necessary)
 <p>A photograph of a tree with a red arrow pointing to its canopy and the text "Trim Needed". The coordinates 34.411702° N 119.863612° W are visible at the bottom.</p>	 <p>A photograph of a tree with a red arrow pointing to its canopy and the text "Trimmed Tree 45". The coordinates 34.411798° N 119.863600° W are visible at the bottom.</p>

Pole Number (Old Pole and New Pole, If Available)	Latitude/Longitude or Address	Noticing Company	Date Completed	Completed By
644939E	34.413818 -119.862661	HHS	11/14/2023	HAYDEN PRUDHOMME

What is the issue/correction required?

Crown Castle needs to transfer its facilities from the buddy pole to the new pole.
CAMINO DEL SUR W/S 1271' S/O COLEGIO RD





Were corrections made per Crown Castle's request? Yes ☒ No ☐ (If 'No' please provide a detailed response below)

Description of work performed.

Removed Guard Arm and Replaced with F-Arm
Placed Fiber Tag
Trimmed Tree 65'



SCN RESOLUTION & PHOTO

Before Photo #2 (If Necessary)	After Photo #2 (If Necessary)
	
Before Photo #3 (If Necessary)	After Photo #3 (If Necessary)
	

Pole Number (Old Pole and New Pole, If Available)	Latitude/Longitude or Address	Noticing Company	Date Completed	Completed By
1081714E	34.451635 -119.758051	HHS	11/15/2023	HAYDEN PRUDHOMME


What is the issue/correction required?

Crown Castle communications conductor supported on Pole number 1081714E was touching a third-party communication down guy wire
1061 Foothill Rd Santa Barbara, Ca 93110





Were corrections made per Crown Castle's request? Yes ☒ No ☐ (If 'No' please provide a detailed response below)

Description of work performed.

Placed Box Guard
Trimmed Tree 100'

Before Photo #1		After Photo #1
		

SCN RESOLUTION & PHOTO

Before Photo #2 (If Necessary)	After Photo #2 (If Necessary)
	
Before Photo #3 (If Necessary)	After Photo #3 (If Necessary)
	



JOB# J-045679

SCN RESOLUTION & PHOTO

July 21, 2014

Version No: 3.2

Pole Number (Old Pole and New Pole, If Available)	Latitude/Longitude or Address	Noticing Company	Date Completed	Completed By
1188582E	34.41373973 -119.85824458	HHS	11/14/2023	HAYDEN PRUDHOMME

What is the issue/correction required?

The ground moulding attached to each of the following poles was damaged
EMBARCADERO DEL MAR P/P 330 W 920 N/O TRIGO RD


Were corrections made per Crown Castle's request? Yes ☒ No ☐ (If 'No' please provide a detailed response below)

Description of work performed.

Placed Molding Stick, Fiber Tag and Guy Guard on Down Guy



SCN RESOLUTION & PHOTO

Before Photo #2 (If Necessary)	After Photo #2 (If Necessary)
 <p>34.413747° N 119.858335° W</p>	 <p>34.413809° N 119.858305° W</p>
Before Photo #3 (If Necessary)	After Photo #3 (If Necessary)
 <p>34.413753° N 119.858401° W</p>	 <p>34.413753° N 119.858428° W</p>

Pole Number (Old Pole and New Pole, If Available)	Latitude/Longitude or Address	Noticing Company	Date Completed	Completed By
1188675E	34.41174661 -119.864222	HHS	11/14/2023	HAYDEN PRUDHOMME


What is the issue/correction required?

Crown Castle communications conductor was touching a third-party communications service drop.
PASADA RD N/S 470' W/O CAMINO DEL SUR


Were corrections made per Crown Castle's request? Yes ☒ No ☐ (If 'No' please provide a detailed response below)

Description of work performed.

Fixed Box Guard and Spec Hardware
Re-tension span
Removed Drops from Lead and Placed Fiber Tag



SCN RESOLUTION & PHOTO

Before Photo #2 (If Necessary)	After Photo #2 (If Necessary)
	
Before Photo #3 (If Necessary)	After Photo #3 (If Necessary)
	

Pole Number (Old Pole and New Pole, If Available)	Latitude/Longitude or Address	Noticing Company	Date Completed	Completed By
1256015E	34.43058512 -119.80239819	HHS	11/20/2023	HAYDEN PRUDHOMME

What is the issue/correction required?

The ground moulding attached to each of the following poles was damaged
WALNUT LN W/S 1528' S/O HOLLISTER AV

Were corrections made per Crown Castle's request? Yes ☒ No ☐ (If 'No' please provide a detailed response below)

Description of work performed.

Replaced Molding Stick
Placed Guy Guard on Down Guy

Before Photo #1		After Photo #1
		

SCN RESOLUTION & PHOTO

Before Photo #2 (If Necessary)	After Photo #2 (If Necessary)
 <p>34.430636° N 119.802407° W</p>	 <p>Molding been replaced</p> <p>Nov 20, 2023 at 10:49:20 AM 34.430732° N 119.802392° W</p>
Before Photo #3 (If Necessary)	After Photo #3 (If Necessary)
 <p>34.430608° N 119.802368° W</p>	 <p>Nov 20, 2023 at 11:14:18 AM 34.430556° N 119.802434° W</p>



JOB# J-045679

SCN RESOLUTION & PHOTO

July 21, 2014

Version No: 3.2

Pole Number (Old Pole and New Pole, If Available)	Latitude/Longitude or Address	Noticing Company	Date Completed	Completed By
1256346E	34.41259 -119.857787	HHS	11/14/2023	HAYDEN PRUDHOMME



What is the issue/correction required?

The Crown Castle down guy wire supporting Pole 1256346E was not taut
CAMINO PESCADERO P/P 260' E 1' S/O SL/O SUENO RD EXTD



Were corrections made per Crown Castle's request? Yes ☐ No ☒ (If 'No' please provide a detailed response below)

No Work Needed

Description of work performed.

Before Photo #1		After Photo #1
		

SCN RESOLUTION & PHOTO

Before Photo #2 (If Necessary)	After Photo #2 (If Necessary)
	
Before Photo #3 (If Necessary)	After Photo #3 (If Necessary)
	



JOB# J-045679

SCN RESOLUTION & PHOTO

July 21, 2014

Version No: 3.2

Pole Number (Old Pole and New Pole, If Available)	Latitude/Longitude or Address	Noticing Company	Date Completed	Completed By
1345769E	34.413757 -119.857144	HHS	11/14/2023	HAYDEN PRUDHOMME

What is the issue/correction required?

Crown Castle communications conductor was touching a third-party communications conductor.
EMBARCADERO DEL MAR W/S 910' N/O TRIGO RD

Were corrections made per Crown Castle's request? Yes ☒ No ☐ (If 'No' please provide a detailed response below)

Description of work performed.





Placed Spreader Bolt



The Foundation for a Wireless World.

CrownCastle.com

SCN RESOLUTION & PHOTO

Before Photo #2 (If Necessary)	After Photo #2 (If Necessary)
<div><p>34.413757° N 119.857109° W</p></div>	<div><p>34.413779° N 119.857088° W</p></div>
Before Photo #3 (If Necessary)	After Photo #3 (If Necessary)
<div><p>34.413764° N 119.857086° W</p></div>	<div><p>34.413757° N 119.857084° W</p></div>

Pole Number (Old Pole and New Pole, If Available)	Latitude/Longitude or Address	Noticing Company	Date Completed	Completed By
1372458E	34.444922 -119.83882	HHS	11/14/2023	HAYDEN PRUDHOMME

What is the issue/correction required?

The outer most down guy wire supporting Pole number 1372458E did not have a guy marker.
COVINGTON WAY P/P 1' S 120' W/O CARLO DR

Were corrections made per Crown Castle's request? Yes ☒ No ☐ (If 'No' please provide a detailed response below)

Description of work performed.

Placed Double F-arm
Swapped Hardware
Placed new 1/4 Down Guy with Guy Guard
Re-tensioned Lead

Before Photo #1	After Photo #1
	

SCN RESOLUTION & PHOTO

Before Photo #2 (If Necessary)	After Photo #2 (If Necessary)
	
Before Photo #3 (If Necessary)	After Photo #3 (If Necessary)



JOB# J-045679

SCN RESOLUTION & PHOTO

July 21, 2014

Version No: 3.2

Pole Number (Old Pole and New Pole, If Available)	Latitude/Longitude or Address	Noticing Company	Date Completed	Completed By
1413703E	34.43501909 -119.80309472	HHS	11/14/2023	HAYDEN PRUDHOMME


What is the issue/correction required?

Crown Castle lashing wire was broken





Were corrections made per Crown Castle's request? Yes ☒ No ☐ (If 'No' please provide a detailed response below)

Description of work performed.

Placed Fiber Tag
Repaired Lashing Wire



SCN RESOLUTION & PHOTO

Before Photo #2 (If Necessary)	After Photo #2 (If Necessary)
	
Before Photo #3 (If Necessary)	After Photo #3 (If Necessary)
	

Pole Number (Old Pole and New Pole, If Available)	Latitude/Longitude or Address	Noticing Company	Date Completed	Completed By
1481587E	34.45157818, -119.75858318	HHS	11/13/2023	HAYDEN PRUDHOMME

What is the issue/correction required?

Crown Castle communications conductor had less than 12 inches of vertical separation from a third-party communications conductor.

FOOTHILL RD N/S 335' E/O CIENEGUITAS RD

Were corrections made per Crown Castle's request? Yes ☒ No ☐ (If 'No' please provide a detailed response below)

Description of work performed.

Removed Guard Arm and Placed F-Arm

Spec Hardware and Placed Fiber Tag

Trimmed Tree 45'

Before Photo #1		After Photo #1
		

SCN RESOLUTION & PHOTO

Before Photo #2 (If Necessary)	After Photo #2 (If Necessary)
	
Before Photo #3 (If Necessary)	After Photo #3 (If Necessary)
	



JOB# J-045679

SCN RESOLUTION & PHOTO

July 21, 2014

Version No: 3.2

Pole Number (Old Pole and New Pole, If Available)	Latitude/Longitude or Address	Noticing Company	Date Completed	Completed By
1665049E	34.45176182 -119.7573553	HHS	11/13/2023	HAYDEN PRUDHOMME

What is the issue/correction required?

Crown Castle communications conductor splice box was touching a third-party communications conductor.
FOOTHILL RD N/S 140' W/O COCOPAH DR Santa Barbara, CA 93110

Were corrections made per Crown Castle's request? Yes ☒ No ☐ (If 'No' please provide a detailed response below)

Description of work performed.





Placed Fiber Tag
Untangled Lines
Placed 2 Spreader Bolts to Prevent 3rd Party Communication Line from Touching Splice Case
Cleaned up Splice Case



The Foundation for a Wireless World.

CrownCastle.com

SCN RESOLUTION & PHOTO

Before Photo #2 (If Necessary)	After Photo #2 (If Necessary)
	
Before Photo #3 (If Necessary)	After Photo #3 (If Necessary)
	

Pole Number (Old Pole and New Pole, If Available)	Latitude/Longitude or Address	Noticing Company	Date Completed	Completed By
2108977E	34.451767 -119.756874	HHS	11/13/2023	HAYDEN PRUDHOMME

What is the issue/correction required?



The "eye" of the Crown Castle down guy anchor supporting the pole was buried.
FOOTHILL RD S/S 730' E/O CIENIGITAS RD

Were corrections made per Crown Castle's request? Yes ☒ No ☐ (If 'No' please provide a detailed response below)





Molding Completed Upon Arrival

Description of work performed.

Dug up to Reveal Anchor

Before Photo #1	After Photo #1
	

SCN RESOLUTION & PHOTO

Before Photo #2 (If Necessary)	After Photo #2 (If Necessary)
	
Before Photo #3 (If Necessary)	After Photo #3 (If Necessary)
	



JOB# J-045679

SCN RESOLUTION & PHOTO

July 21, 2014

Version No: 3.2

Pole Number (Old Pole and New Pole, If Available)	Latitude/Longitude or Address	Noticing Company	Date Completed	Completed By
4371458E	34.43151671 -119.8023725	HHS	11/15/2023	HAYDEN PRUDHOMME

What is the issue/correction required?

Crown Castle communication conductor supported on each of the following poles was strained by vegetation.
S WALNUT LN W/S 1200' S/O HOLLISTER AV

Were corrections made per Crown Castle's request? Yes ☒ No ☐ (If 'No' please provide a detailed response below)

Description of work performed.

Placed 2 Box Guards
Swap Hardware
Tree Trimming 140'



The Foundation for a Wireless World.

CrownCastle.com

SCN RESOLUTION & PHOTO

Before Photo #2 (If Necessary)	After Photo #2 (If Necessary)
	
Before Photo #3 (If Necessary)	After Photo #3 (If Necessary)
	

Pole Number (Old Pole and New Pole, If Available)	Latitude/Longitude or Address	Noticing Company	Date Completed	Completed By
4495632E	34.26617 -119.482128	HHS	11/15/2023	HAYDEN PRUDHOMME

What is the issue/correction required?


Crown Castle communications conductor had less than 12 inches of vertical separation from a third-party communications conductor.

HOLLISTER AV N/S 10' E/O LASSEN DR





Were corrections made per Crown Castle's request? Yes ☒ No ☐ (If 'No' please provide a detailed response below)

Description of work performed.

Moved Frame 6"
Placed Fiber Tab
Spec Hardware



SCN RESOLUTION & PHOTO

Before Photo #2 (If Necessary)	After Photo #2 (If Necessary)
 <p>34.435052° N 119.805914° W</p>	 <p>34.435049° N 119.805902° W</p>
Before Photo #3 (If Necessary)	After Photo #3 (If Necessary)
 <p>34.435034° N 119.805954° W</p>	 <p>34.435049° N 119.805902° W</p>



JOB# J-045679

SCN RESOLUTION & PHOTO

July 21, 2014

Version No: 3.2

Pole Number (Old Pole and New Pole, If Available)	Latitude/Longitude or Address	Noticing Company	Date Completed	Completed By
4797579E	34.4515417 -119.759043	HHS	11/13/2023	HAYDEN PRUDHOMME

What is the issue/correction required?

Crown Castle communications conductor had less than 12 inches of vertical separation from a third-party communications conductor.

FOOTHILL RD N/S 214' E/O CIENEGUITAS RD

Were corrections made per Crown Castle's request? Yes ☒ No ☐ (If 'No' please provide a detailed response below)

Description of work performed.

Placed Snow Show
Trimmed Tree Approx 20'
Placed Fiber Tag

Before Photo #1



After Photo #1





SCN RESOLUTION & PHOTO


Before Photo #2 (If Necessary)	After Photo #2 (If Necessary)
 <p>34.451636° N 119.758852° W</p>	 <p>34.451622° N 119.759438° W</p>
Before Photo #3 (If Necessary)	After Photo #3 (If Necessary)
 <p>34.451636° N 119.758852° W</p>	 <p>34.451635° N 119.759450° W</p>

SCN RESOLUTION & PHOTO

July 21, 2014

Version No: 3.2

Before Photo #4 (If Necessary)	After Photo #4 (If Necessary)
 <p>34.451554° N 119.759066° W</p>	 <p>34.451519° N 119.759278° W</p>
Before Photo #5 (If Necessary)	After Photo #5 (If Necessary)

Pole Number (Old Pole and New Pole, If Available)	Latitude/Longitude or Address	Noticing Company	Date Completed	Completed By
4863759E	34.4123336 -119.86260943 	HHS	11/14/2023	HAYDEN PRUDHOMME


What is the issue/correction required?

A Crown Castle communication conductor supported on each of the following poles was strained by vegetation
CAMINO DEL SUR W/S 200' N/O PASADO RD

Were corrections made per Crown Castle's request? Yes ☒ No ☐ (If 'No' please provide a detailed response below)

Description of work performed.

Trimmed Tree 20'
Spec Hardware
Placed Fiber Tag

Before Photo #1		After Photo #1
		

SCN RESOLUTION & PHOTO

Before Photo #2 (If Necessary)	After Photo #2 (If Necessary)
 <p>34.412371° N 119.862644° W</p>	 <p>Trimmed Tree 20'</p> <p>34.412320° N 119.862626° W</p>
Before Photo #3 (If Necessary)	After Photo #3 (If Necessary)
 <p>34.412338° N 119.862613° W</p>	 <p>Trimmed Tree 20'</p> <p>34.412330° N 119.862601° W</p>

Pole Number (Old Pole and New Pole, If Available)	Latitude/Longitude or Address	Noticing Company	Date Completed	Completed By
S18921Y	34.41184304 -119.8626306	HHS	11/14/2023	HAYDEN PRUDHOMME

What is the issue/correction required?

A Crown Castle splice box was loose and not secured to the pole.
CAMINO DEL SUR N/W COR/O PASADO RD

Were corrections made per Crown Castle's request? Yes ☒ No ☐ (If 'No' please provide a detailed response below)

Description of work performed.

Re-Secure Splice Case
Placed Snow Shoe



SCN RESOLUTION & PHOTO

Before Photo #2 (If Necessary)




After Photo #2 (If Necessary)



Before Photo #3 (If Necessary)



After Photo #3 (If Necessary)



Pole Number (Old Pole and New Pole, If Available)	Latitude/Longitude or Address	Noticing Company	Date Completed	Completed By
S29049Y	34.41339167 -119.86261666	HHS	11/14/2023	HAYDEN PRUDHOMME

What is the issue/correction required?

a Crown Castle communications conductor was touching a third-party communications conductor.
CAMINO DEL SUR W/S 266' S/O ABREGO RD

Were corrections made per Crown Castle's request? Yes ☒ No ☐ (If 'No' please provide a detailed response below)


Description of work performed.

Spec Hardware
Placed Fiber Tag
Re tensioned Span

Before Photo #1	After Photo #1
 	

SCN RESOLUTION & PHOTO

Before Photo #2 (If Necessary)



After Photo #2 (If Necessary)



Before Photo #3 (If Necessary)



After Photo #3 (If Necessary)

