PUBLIC UTILITIES COMMISSION 505 VAN NESS AVENUE SAN FRANCISCO, CA 94102-3298

June 30, 2020



Rodger Schwecke, Senior Vice President Gas Operations and System Integrity Southern California Gas Company 555 West 5<sup>th</sup> Street, GT21C3 Los Angeles, CA 90013

Dear Mr. Schwecke,

The Safety and Enforcement Division (SED) of the California Public Utilities Commission (Commission) reviewed San Diego Gas and Electric Company's (SDG&E) response letter dated May 13, 2020, addressing one violation identified by SED during its investigation of Department of Transportation (DOT) #1268754 reportable incident that occurred on August 22, 2019

Attached is a summary of SED's investigation findings, SDG&E's response to SED's findings, and SED's evaluation of SDG&E's response to the finding.

Within 30 days of your receipt of this letter, please provide a written response indicating the measures taken by SDG&E to address the outstanding probable violation noted in the Findings.

If you have any questions, please contact Desmond Lew, Senior Utilities Engineer (Specialist), at (213) 576-7020 or by email at dl4@cpuc.ca.gov.

Sincerely,

forencet

Terence Eng, P.E. Program Manager Gas Safety and Reliability Branch Safety and Enforcement Division

Attachment

cc: See next page

Troy Bauer, Manager Pipeline Safety and Compliance Southern California Gas Company

Daniel Rendler, Senior Director Safety Management Systems Southern California Gas Company

Mahmoud Intably Program and Project Supervisor Safety and Enforcement Division

Kan-Wai Tong Senior Utilities Engineer (Supervisor) Safety and Enforcement Division

Desmond Lew Senior Utilities Engineer (Specialist) Safety and Enforcement Division

Claudia Almengor Associate Governmental Program Analyst Safety and Enforcement Division

## DOT #1268754 Reportable Incident G20190822-2888 August 22, 2019

### **Identified Probable Violation**

## 1. <u>General Order (GO) 112-F, Reference Title 49 of Code of Federal Regulation</u> (CFR), Part 192, Section 192.605(a) states in part:

General. Each operator shall prepare and follow for each pipeline a manual of written procedures for conducting operations and maintenance activities and for emergency response. For transmission lines, the manual must also include procedures for handling abnormal operations. This manual must be reviewed and updated by the operator at intervals not exceeding 15 months, but at least once each calendar year. The manual must be prepared before operations of a pipeline system commence. Appropriate parts of the manual must be kept at locations where operations and maintenance activities are conducted.

1.1 SDG&E's Gas Standard G8123 Underground Service Alert and Temporary Markings, Section 6.3 states in part:

"If there is any confusion with the USA ticket information or delineation has not been provided at the ticket location, then the locator will contact the excavator to accomplish the following: 6.3.2. Obtain from the excavator a clear description of where the marks are needed."

During an SED interview with SDG&E on September 10, 2019, an SDG&E employee stated he found no delineation marks in the proposed excavation area. Based on his understanding of the description of the location provided on the USA ticket, he located and marked some of SDG&E's facilities but failed to locate and mark the 1 ¼-inch steel gas service line. In addition, he stated that he did not contact the excavator to obtain a clear description of where the marks were needed. SED found SDG&E failed to follow its Gas Standard G8123, Section 6.3 which required the operator to contact the excavator to determine the extent and location of the excavation and to obtain a clear description of where the marks were needed. Therefore, SED finds SDG&E in violation of 192.605(a) for failure to follow its own Gas Standard.

SED found one (1) instance in which the SDG&E employee failed to follow and comply with the requirement stated in SDG&E Gas Standard and thus 192.605(a). Therefore, SED found SDG&E committed a total of one (1) violation of General Order 112-F, which incorporates Title 49 CFR, Part 192 by reference.

#### SDG&E Response:

SDG&E disagrees with SED's assessment that SDG&E failed to follow its Gas Standard G8123, Underground Service Alert and Temporary Markings, Section 6.3 based on the following investigation and facts. On August 22, 2019 a Naton Engineering excavation crew damaged an SDG&E service line causing a gas leak. Investigation of the damage site showed no visible delineation. The site did have utility mark outs provided by Cable, Pipe & Leak, a private marking company, based on flags with their company name (See Image 9 below). No SDG&E or Utiliquest employee marked this location. During the damage investigation it was found that Naton Engineering indicated their work was covered under USA Ticket #A1912341234 (Images 1 and 2 below). This claim by Naton Engineering was determined to be incorrect. Instead, the ticket that covered the area of the damage was actually USA Ticket #A191060668 (Images 5 and 6 below). The USA Ticket #A191060668 was not Naton Engineering's ticket and had expired on July 4, 2019 well before Naton Engineering damaged the service.

In SDG&E's post incident investigation Naton Engineering provided USA Ticket #A1912341234 and claimed their excavation was authorized under the USA Ticket #A1912341234. Delineations for USA Ticket #A191341234 were provided under the initials "PBG" for Naton Engineering's general contractor, Pacific Building Group. (Please see Images 1, 2, 7, 8 and 9 below for pictures showing USA Ticket #A1912341234 detail report and "PBG" delineations). Thus, the Utiliquest employee did not need to communicate with the excavator as he marked according to "PBG" delineations and USA Ticket #A191341234 information. Naton Engineering damaged the gas service line more than 300 feet from the work location as described on USA Ticket #A191341234 and the delineations under "PBG" (See Images 3 and 4 below).

In preparation to respond to SED's Notice of Probable Violation, SDG&E investigated USA tickets in the general area of **Section 1** requested by the general contractor, Pacific Building Group (PBG). It was discovered that Pacific Building Group had requested USA Ticket #A191060668 applicable to the area where the damage occurred. USA Ticket #A191060668 was requested on April 16, 2019, then was renewed twice, and finally expired on July 4, 2019. This ticket was not valid on the day of the subject damage incident occurring on August 22, 2019. Naton Engineering themselves did not have a valid USA ticket for the area where they were excavating, and where the incident occurred. As the post incident interview indicates Naton Engineering construction plans did not show a 1 ¼-inch steel gas service. Please note that the information related to the gas and electric facilities in those plans were neither requested from nor provided by SDG&E. SDG&E did not, nor were they requested to, review those plans for accuracy.

USA Ticket #A191060668 states the following as work location:

X/ST1: ZOO PL W/SIDE OF ZOO DR AT APPROX 257FT S/E OF ZOO PL WITHIN THE SAN DIEGO ZOO \*\*ALT CONTACT IS A AT A AT A AN AN ARKS NEEDED \*\* [emphasis added] \*\*PLEASE CALL AT AT A UPON ARRIVAL OR IF YOU HAVE ANY QUESTIONS\*\* \*\*DELINEATED WITH PBG/USA\*\*

with no answer".

On April 19, 2019, Utiliquest's notes show "Called and spoke with site contact Site phone who confirmed that work was only being done inside the San Diego Zoo. No sdge, gas, sdge electric, cox or att-d within zoo."

Therefore, the Utiliquest employee did adhere to the request made on the USA Ticket #A191060668 by calling and did follow company procedures. The location where the incident occurred was not covered by USA Tickets #A191341234 (300' from excavation site) and USA Ticket #A191060668 was expired and no longer valid on the date of the incident caused by Naton Engineering.

Tislast Datall D

	Ticket D	etail Repo	rt
KORTER	Ticket Number A191341:	234	
Locate Request	For SDG01		
Ticket Number	Message Type	Previous Ticket	Sequence
A191341234	RNEW NORM POLY	N/A	124
Work Informatior	1		
Work Address	OLD GLOBE WAY	Intersection	VILLAGE PL
	SAN DIEGO, CA SAN DIEGO	Duration	N/A
Work Date	8/6/2019 10:07:00 AM	Expiration Date	9/3/2019 11:59:00 PM
Nature of Work	DEMO OF BLDGS & CLEAR/GRUB OF VEGETATION	Explosives	No
White Paint	Yes	Right of Way	No
Mapsco	N/A	Boring	No
Done For	PACIFIC BUILDING GROUP	Legal Given	No
Meet Date	N/A	Mobile ID	CMU01
Project	No	Map No	N/A
Status	COMPLETED	Zone ID	CM01
Depth	N/A	Map Ref	N/A
Transmit Date	8/6/2019 10:07:38 AM	Due Date	8/6/2019 10:07:00 AM
Original Call Date	8/6/2019 10:07:00 AM	Assigned Date	8/6/2019 11:11:58 AM
Send Date	N/A	Work to Begin	Date 8/6/2019 10:07:00 AM

Image 1: USA Ticket #A191341234 was done for Pacific Building Group (PBG).

Company Information				
NATON ENGINEERING		Contact		Contact Phone
4935 2ND ST RAINBOW, CA 92028		Contact Ema	ail	
Company Phone	Company Fax	N/A		
760-731-9000	N/A	Callback		
Alt Contact	Alt Phone	N/A		
N/A	N/A			
Location Points				
LATLONG	32.73307500000	-117.14972200000	DIG BOX	
LATLONG	32.73364400000	-117.14718500000	DIG BOX	
LATLONG	32.73259300000	-117.14694900000	DIG BOX	
LATLONG	32.73202500000	-117.14948700000	DIG BOX	
Additional Members	1 NEXTGLAVE N S	DG01 SND01		

**Image 2:** USA Ticket #A191341234 Detail Report that shows Naton Engineering as a requestor and work to be completed for Pacific Building Group.



**Image 3:** Picture taken on Old Globe Way facing North at intersection of Village Place on May 17, 2019 during mark out. PGB USA mark stenciled to left of light post. This picture is for Naton Engineering's USA Ticket #A1912341234, which is approximately 300 feet from incident area.



**Image 4:** Depicts area covered by Naton Engineering's USA Ticket #A1912341234 which notes work location: Old Globe Way Intersection: Village Pl. (the boxed area) The Red Star is the approximate damage location, about 300 feet north from boxed area.

# Ticket Detail Report

Ticket Number A191060668



Ticket Number	Message Type	Previous Ticket	Sequence
A191060668	RNEW NORM POLY	/ N/A	125
Work Information	D.		
Work Address	ZOO DR	Intersection	ZOO PL
	SAN DIEGO, CA SAN DIEGO	Duration	N/A
Work Date	6/6/2019 10:31:00 AM	Expiration Date	7/4/2019 11:59:00 PM
Nature of Work	NEW CONST	Explosives	No
White Paint	Yes	Right of Way	No
Mapsco	N/A	Boring	No
Done For	SAN DIEGO ZOO	Legal Given	No
Meet Date	N/A	Mobile ID	CMU01
Project	No	Map No	N/A
Status	COMPLETED	Zone ID	CM01
Depth	N/A	Map Ref	N/A
Transmit Date	6/6/2019 10:33:55 A	M Due Date	6/6/2019 10:31:00 AM
Original Call Date	6/6/2019 10:31:00 A	M Assigned Date	6/6/2019 10:35:20 AM
Send Date	N/A	Work to Begin [	Date 6/6/2019 10:31:00 AM


		oca	

X/ST1: ZOO PL	
W/SIDE OF ZOO DR AT APPROX 257FT S/E OF ZOO PL WITHIN	THE SAN DIEGO
ZOO **ALT CONTACT IS AT AT	**NO MARKS
NEEDED** **PLEASE CALL	VAL OR IF YOU
HAVE ANY QUESTIONS** **DELINEATED WITH PBG/USA**	
1 YEAR: N BORING: N STREET/SIDEWALK: Y VACUUM: N EXPL	OSIVES: N

PACIFIC BUILDING G	ROUP	Contact		Contact Phone
9752 ASPEN CREEK CT SUITE 150				
SAN DIEGO, CA 9212	6	Contact Em	ail	
Company Phone	Company Fax	N/A		
	N/A	Callback		
Alt Contact	Alt Phone	N/A		
N/A	N/A			
Location Points				
LATLONG	32.7350310000	0 -117.14899600000	DIG BOX	
LATLONG	32.7348730000	-117.14804700000	DIG BOX	
LATLONG	32.7340700000	-117.14818000000	DIG BOX	
LATLONG	32.7342280000	-117.14913000000	DIG BOX	

**Image 5:** USA Ticket #A191060668 Detail Report that shows Pacific Building Group as a requestor, work to be completed for San Diego Zoo, the note "NO MARKS NEEDED" and direction to contact


upon arrival.



**Image 6:** Depicts area covered by PBG's expired USA Ticket #A191060668. Damage occurred in this area.



**Image 7:** Marks in area described on expired USA Ticket #A191060668 believed to be provided by Cable, Pipe and Leak locating employees.



**Image 8:** Flags in area described on expired USA Ticket #A191060668 labeled Cable, Pipe and Leak.




Image 9: Close up of Cable, Pipe and Leak Flag.

# SED's Conclusion:

SED reviewed SDG&E's response and concluded that SDG&E's locator was dispatched to locate and field mark SDG&E's facilities in the excavation area location as described in USA Ticket #191341234:

"N/SIDE OF OLD GLOBE WAY FRM VILLAGE PL W/FOR APPROX 395FT; N/W SIDE OF VILLAGE PL FRM OLD GLOBE WAY N/E FOR APPROX 180FT TO ZOO DR. LOCS AREA WITHIN THE SAN DIEGO ZOO AT \* ZOO DR HAS BEEN EXTENDED FURTHER S/FRM INTER OF ZOO PL TO INTER WITH VILLAGE PL ON SITE\*\*"



Village Place is highlighted in light purple, Old Globe Way is highlighted in light black, Zoo Place is highlighted in light yellow, Zoo Drive is highlighted in orange. The Location Description is traced by the line in light black (boundaries) and in blue (roads) and links together at named locations per the Location Description. The accident location is indicated by the red point and red triangle. This information can be found on the legend on the left, indicating the excavation area as described in the narrative of USA Ticket #191341234.

According to the Locator's Supervisor (Brad Renfrow), the Locator located and field marked SDG&E's facilities in the vicinity of Old Globe Way and Village Place, but he did not locate and field mark SDG&E's facilities located within the San Diego Zoo at a described in the USA Ticket #191341234. In addition, the supervisor stated that the Locator did not contact the excavator for any additional information. Furthermore, SDG&E's investigation stated that the incident site was "not delineated" by the excavator.

SDG&E's Gas Standard G8123 Underground Service Alert and Temporary Markings, Section 6.3 states in part:

"If there is any confusion with the USA ticket information and/or delineation has not been provided at the ticket location, then the locator shall contact the excavator to accomplish the following:

- 6.3.1. Verify the accuracy of information on the USA ticket to determine the extent and location of the excavation and the starting time.
- 6.3.2. Obtain from the excavator a clear description of where the marks are needed."

SED investigation found that the Locator failed to locate and field mark all SDG&E's facilities within the San Diego Zoo at **Contract Contract**. In addition, SED investigation found that the Locator failed to follow SDG&E's Gas Standard G8123 to contact the excavator to verify and to obtain a clear description of the excavation area location.

Therefore, SED is reiterating its finding that SDG&E is in violation of Title 49 CFR, Part 192.605(a).