

July 1, 2022

VIA ELECTRONIC FILING

Fadi Daye
California Public Utilities Commission
Safety Enforcement Division
505 Van Ness Avenue
San Francisco, CA 94102-3298
fadi.daye@cpuc.ca.gov
ESRB_ComplianceFilings@cpuc.ca.gov

Re: PacifiCorp's (U 901-E) 2021 Annual Report of Inspection Activities Filed Pursuant to General Order No. 165

Per General Order No. 165, PacifiCorp provides the attached 2021 annual report of inspection activities for electric distribution and transmission facilities.


It is respectfully requested that all formal correspondence and Staff requests regarding this matter be addressed to:

By email (preferred): datarequest@pacificorp.com

By regular mail: Data Request Response Center
PacifiCorp
825 NE Multnomah, Suite 2000
Portland, OR 97232

Informal inquiries may be directed to Jonathan Connelly, Director, Asset Management/Wildfire Safety and Asset Management, at (503) 813-6152 or Pooja Kishore, Regulatory Affairs Manager, at (503) 813-7314.

Sincerely,



Shelley McCoy
Director, Regulation

**ANNUAL REPORT OF INSPECTION ACTIVITIES FILED PURSUANT
TO GENERAL ORDER 165
FOR THE CALENDAR YEAR 2021**

2021 GENERAL ORDER 165 ANNUAL REPORT
Reporting Period: 01/01/21 - 12/31/21
PacifiCorp

Distribution										
District	Overhead Patrol		Overhead Detail		Underground Patrol		Underground Detail		Intrusive	
	Due	Outstanding	Due	Outstanding	Due	Outstanding	Due	Outstanding	Due	Outstanding
Alturas	2,769	0	691	0	63	0	24	0	0	0
Crescent City	6,722	0	1,291	0	1,351	0	685	0	398	0
Tulelake	7,566	0	1,854	0	88	0	27	0	648	0
Yreka	33,610	0	5,381	0	4,443	0	1,358	0	1,619	2 ¹
Total	50,667	0	9,217	0	5,945	0	2,094	0	2,665	2

Transmission						
District	Overhead Patrol		Overhead Detail		Intrusive	
	Due	Outstanding	Due	Outstanding	Due	Outstanding
Alturas	738	0	1	0	0	0
Crescent City	1,534	0	664	0	0	0
Tulelake	2,200	0	344	0	620	0
Yreka	7,936	0	430	0	1,397	4 ²
Total	12,418	0	1,439	0	2,027	4

The units listed in the table are defined as "facility points" within PacifiCorp's inspection system. For overhead facilities, a facility point is a pole including all equipment installed on the pole. The span of wire between poles or service drops spanning from poles to customer's facilities are associated to the nearest facility point for inspection purposes. For underground facilities a facility point is the location associated with ground mounted equipment, including all equipment at that individual location such as a padmount transformer or switch cabinet.

Status of Outstanding Inspections

Note 1: Records indicate poles 06238004.0011340 and 06238004.0011341 were not be inspected due to Customer Refusal/Dangerous Access. These poles are scheduled for reinspection 7/29/2022


Note 2: Records indicate structures 1/001, 2/001, 8/062, and 8/062 on line 668014/00 could not be inspected due to no access from locked gate and vegetation. These poles are scheduled for reinspection 7/29/2022

VERIFICATION

I am Vice President of Transmission & Distribution Operations, and am authorized to make this verification on PacifiCorp's behalf. I am informed and believe that the matters stated in the foregoing document are true.

I declare under penalty of perjury that the foregoing is true and correct.

Executed 1st day of July, 2022 at Portland, Oregon.



Allen Berreth
Vice President, Transmission & Distribution Operations