Item	Ticket ID	Status	Priority	Target Finish Date	Pole	Type	Violation Description
1	TK3339768	NEW	2C	2/9/2027	2139796S	Pole	Frontier communications conductors were in contact with third-party communications conductors
3	TK3339769	NEW	2C	2/9/2027	213978S	Pole	Frontier communications conductors were in contact with third-party communications conductors
4	TK3339770	NEW	2C	2/9/2027	4524024E	Pole	Frontier communications conductors were in contact with third-party communications conductors
5	TK3339771	NEW	2C	2/9/2027	GT60807	Pole	Frontier communications conductors were in contact with third-party communications conductors
7	TK3339772	NEW	2C	2/9/2027	4791515E	Pole	Abandoned service drops
8	TK3339778	NEW	2C	2/9/2027	4771120E	Pole	Unauthorized foreign attachments “Free Junk Car Removal” sign.
10	TK3339780	NEW	2C	2/9/2027	4317657E	Pole	The cover to the terminal on Pole No. 4317657E was not properly secured to the termina
12	TK3339781	NEW	2C	2/9/2027	4607462E	Pole	Damaged visibility strips
14	TK3339782	NEW	2C	2/9/2027	216743S	Pole	The pole-mounted terminal on Pole No. 216743S was damaged
15	TK3339783	NEW	2C	2/9/2027	4799724E	Pole	Unauthorized foreign attachments sign advertising a yard sale
16	TK3339243	NEW	2C	2/9/2027	4299391E	Pole	Unauthorized foreign attachment fence post that had been nailed to the pole, Frontier communications conductors were in contact with third-party communications conductors
17	TK3339784	NEW	2C	2/9/2027	216745S	Pole	Frontier communications conductors were in contact with third-party communications conductors
18	TK3339767	NEW	2C	2/9/2027	4151042E	Pole	Unauthorized foreign attachments “Free Junk Car Removal” sign.
19	TK3356148	NEW	2B	2/9/2025	GT140480	Pole	The P-clamp on a service drop from Pole No. GT140480 had become detached
20	TK3339801	NEW	2B	2/9/2025	4060489E	Pole	Frontier communications conductors on or near the following poles passed over private yards at a height of less than 8 feet 6 inches
22	TK3339802	NEW	2B	2/9/2025	17343CWT	Pole	Frontier communications conductors were in contact with third-party communications conductors , conductors on or near the following poles passed over private yards at a height of less than 8 feet 6 inches
23	TK3339803	NEW	2B	2/9/2025	17347CWT	Pole	Abandoned service drops
24	TK3339813	NEW	2B	2/9/2025	4958110E	Pole	Unauthorized foreign attachment “Missing Dog” sign, damaged lashing to the south, Frontier communications conductors were in contact with third-party communications conductors
26	TK3339814	NEW	2B	2/9/2025	4524476E	Pole	Frontier communications conductors were in contact with third-party communications conductors
29	TK3339815	NEW	2B	2/9/2025	19805CWT	Pole	Frontier communications conductors were in contact with third-party communications conductors
30	TK3339816	NEW	2B	2/9/2025	2014492E	Pole	Abandoned service drops
31	TK3339804	NEW	2B	2/9/2025	19808CWT	Pole	Frontier communications conductors were in contact with third-party communications conductors
32	TK3339805	NEW	2B	2/9/2025	2245447E	Pole	Unauthorized foreign attachment speed limit sign, The riser conductor detached from the pole
35	TK3339817	NEW	2B	2/9/2025	4715458E	Pole	Frontier communications conductors were in contact with third-party communications conductors
38	TK3339806	NEW	2B	2/9/2025	1971052E	Pole	Frontier communications conductors were in contact with third-party communications conductors
39	TK3339807	NEW	2B	2/9/2025	4710897E	Pole	The splice case missing its cover, The copper splice not properly secured to the span wire and was dangling from one end.
42	TK3339837	NEW	2C	2/9/2027	4938481E	Pole	Frontier communications conductors were in contact with third-party communications conductors
43	TK3339833	NEW	2C	2/9/2027	4938480E	Pole	Frontier communications conductors were in contact with third-party communications conductors
45	TK3339834	NEW	2C	2/9/2027	4871208E	Pole	The housing of the pole-mounted terminal on Pole No. 4871208E was slightly open
46	TK3339835	NEW	2C	2/9/2027	4938476E	Pole	Frontier communications conductors were in contact with third-party communications conductors
47	TK3339836	NEW	2C	2/9/2027	250002	Pole	Unauthorized foreign attachment thermometer.
50	TK3339838	NEW	2B	2/9/2025	4869669E	Pole	Frontier communications conductors were in contact with third-party communications conductors
51	TK3339839	NEW	2B	2/9/2025	2012060E	Pole	Frontier communications conductors were in contact with third-party communications conductors
56	TK3339840	NEW	2B	2/9/2025	311796	Pole	Abandoned service drops
57	TK3339841	NEW	2B	2/9/2025	4819427E	Pole	The terminal box attached to Pole No. 4819427E was not properly secured to the pole, Frontier communications conductors were in contact with third-party communications conductors
59	TK3339842	NEW	2B	2/9/2025	250012	Pole	Unauthorized foreign attachment street sign, Damaged visibility strips
62	TK3339843	NEW	2B	2/9/2025	4632116E	Pole	Frontier communications conductors were in contact with third-party communications conductors
63	TK3339844	NEW	2C	2/9/2027	13818CWT	Pole	Frontier communications conductors were in contact with third-party communications conductors
65	TK3339845	NEW	2C	2/9/2027	13817CWT	Pole	The pole-mounted fiber terminal attached to Pole No. 13817CWT was not properly secured to the pole, Frontier communications conductors were in contact with third-party communications conductors
66	TK3339846	NEW	2C	2/9/2027	4059453E	Pole	Damaged visibility strips
76	TK3339848	NEW	2C	2/9/2027	T2626290	Hand-hole	Hand-hole T2626290 was full of earth and debris
81	TK3339849	NEW	2C	2/9/2027		Pedestal	The following above-ground enclosure was not secured against entry by unauthorized persons by means of locks or other suitable means
82	TK3339850	NEW	2C	2/9/2027		Pedestal	The base of the pedestal was damaged.
86	TK3339851	NEW	2C	2/9/2027		Flower Pot	The lid to the “flower pot” was unsecured.
90	TK3339852	NEW	2C	2/9/2027	T116668	Combination Structure	The following above-ground enclosure was not secured against entry by unauthorized persons by means of locks or other suitable means
91	TK3339853	NEW	2C	2/9/2027	6234B	Combination Structure	The lid of Combination Structure 6234B was damaged, The following above-ground enclosures were not secured against entry by unauthorized persons by means of locks or other suitable means
94	TK3339854	NEW	2C	2/9/2027	T116662	Combination Structure	The locking mechanism and lid of Combination Structure T116662 were damaged and/or broken, The following above-ground enclosures were not secured against entry by unauthorized persons by means of locks or other suitable means

Item	Ticket ID	Status	Priority	Target Finish Date	Pole	Type	Violation Description
106	TK3339855	NEW	2C	2/9/2027	2328276E	Pole	The down guy wire on each of the following poles was not taut and Unauthorized foreign attachment sign advertising a trust and will service. A frontier communications conductor was in contact with a third-party span guy wire west of Pole No. 2328276E.
112	TK3339847	NEW	2C	2/9/2027	4784303E	Pole	The down guy wire on each of the following poles was not taut: