Ross Johnson
Director

AT&T Services, Inc.
430 Bush Street, 5th Floor
San Francisco, CA 94108

att-regulatory-ca@att.com
www.att.com
415.417.5033

February 7, 2025

Dear Mr. Tse,

Subject: Communication Infrastructure Provider (CIP) Audit of AT&T Plumas, Sierra, and Nevada County Region

The following is AT&T California's ("AT&T's") response to your letter dated December 9, 2024 ("December Letter") regarding the Communication Infrastructure Provider audit of AT&T's Plumas, Sierra, and Nevada County Region from September 9 to September 13, 2024.

The December Letter requested that AT&T advise you of actions taken to address alleged conditions identified during the Safety and Enforcement Division's audit of AT&T Plumas, Sierra, and Nevada County Region. AT&T's response to your December Letter was originally due by January 13, 2025; however, you provided AT&T with two extensions via email ultimately extending AT&T's response due date to February 7, 2025. AT&T timely submits its response.

Enclosed is AT&T's response.

Regards,

Ross Johnson
Director
AT&T Regulatory
415-417-5028
rj2397@att.com

Enclosure:

AT&T's Response to Plumas, Sierra, and Nevada County Region Audit

Cc: Lee Palmer, Director, Safety and Enforcement Division (SED), CPUC
Fadi Daye, Program and Project Supervisor, ESRB, SED, CPUC
Yi "Rocky" Yang, Senior Utilities Engineer (Supervisor), ESRB, SED, CPUC
Stephen Lee, Senior Utilities Engineer (Supervisor), ESRB, SED, CPUC
Emiliano Solorio, Utilities Engineer, ESRB, SED, CPUC
Nora Nguyen, Utilities Engineer, ESRB, SED, CPUC
Madonna Ebrahimof, Staff Services Analyst, ESRB, SED, CPUC
Saira Pasha, Regulatory & Legislative Affairs, AT&T

CPUC AUDIT FINDINGS OF AT&T

PLUMAS, SIERRA & NEVADA COUNTY

SEPTEMBER 9 – 13, 2024

Alleged Records violation 1:

GO 95, Rule 18-B1(a), Maintenance Programs states in part:

> *"The maximum time periods for corrective actions associated with potential violation of GO 95 or a Safety Hazard are based on the following priority levels:*
>
> *(i) Level 1 -- An immediate risk of high potential impact to safety or reliability:*
> - *Take corrective action immediately, either by fully repairing or by temporarily repairing and reclassifying to a lower priority.*
>
> *(ii) Level 2 -- Any other risk of at least moderate potential impact to safety or reliability:*
> - *Take corrective action within specified time period (either by fully repair or by temporarily repairing and reclassifying to Level 3 priority). Time period for corrective action to be determined at the time of identification by a qualified company representative, but not to exceed: (1) six months for potential violations that create a fire risk located in Tier 3 of the High Fire-Threat District; (2) 12 months for potential violations that create a fire risk located in Tier 2 of the High Fire-Threat District; (3) 12 months for potential violations that compromise worker safety; and (4) 36 months for all other Level 2 potential violations.*
>
> *(iii) Level 3 -- Any risk of low potential impact to safety or reliability:*
> - *Take corrective action within 60 months subject to the exception specified below."*

ESRB's review of AT&T's work orders from July 2019 through June 2024 found that AT&T had 2,106 out of 14,177 pending work orders are overdue and 406 out of 2,513 closed work orders were completed late. Late-pending work orders are pending work orders that have not been completed by their assigned due date based on their hazard level, and late-closed work orders are work orders that were completed past their assigned due date based on their hazard level. Table 1 below breaks down the 2,512 late work orders by hazard level.

Table 1: Late Work Orders

Hazard Level	Late-Pending Work Orders[1]	Late-Closed Work Orders	Total Late Work Orders
1	-	96	96
2	97	4	101
2a	1,281	68	1,349
2b	292	203	495

[1] As of June 1, 2021

2c	95	35	130
3	341	-	341
Total	2,106	406	2,512

AT&T must provide ESRB with its corrective action plan to complete the 2,106 late pending work orders and its preventive measures to prevent any work orders from being addressed late in the future.

AT&T Response: Without admitting that AT&T violated GO 95, Rule 18, the information AT&T produced in response to the pre-audit data request appears to indicate that 2106 tickets are pending and 406 were closed; however, that does not necessarily mean that any related corrective action had not been completed by the assigned due date. Closing repair tickets is a time-consuming manual process.

That said, the local team has been engaged and will commit to completing any past due work orders and current work each month until all the work is caught up. They are determining a number they can complete, based on the work now and will have the plan enacted by the end of February.

Alleged Records violation 2:

Table 2 below identifies the most overdue non-exempt work orders for each priority

Table 2: Most Overdue Work Orders

Priority Code	Most Overdue Work Orders (WO#s)	Number of Days Past Assigned Due Date
1	1022416	84
2	493933	757
2a	445022	1,419
2b	504565	1,565
2c	493413	1,493
3	493565	32

AT&T identified work order #1022416 on January 14, 2022, to repair a riser cover with a required end date of January 17, 2022. AT&T did not complete the work until April 11, 2022.

AT&T Response: Without admitting that AT&T violated GO 95, Rule 18, the ticket was closed beyond the assigned due date. The immediate risk was resolved with a temporary solution on January 14, 2022, but the ticket was closed when a permanent solution was implemented.

AT&T identified work order #493933 on October 26, 2019, for a pole safety inspection with a required end date of May 6, 2022. AT&T has not yet completed the work.

AT&T Response: The inspection will be completed by February 28, 2025.

AT&T identified work order #445022 on May 21, 2019, to pole load calculate a leaning pole with a required end date of July 13, 2020. AT&T has not yet completed the work.

AT&T Response: The pole was replaced in February 2021, and the ticket is closed.

AT&T identified work order #504565 on November 9, 2019, to repair a down guy with a required end date of February 18, 2020. AT&T has not yet completed the work.

AT&T Response: The work was completed, and the ticket closed on January 22, 2025.

AT&T identified work order #493413 on October 26, 2019, for a pole transfer with impairments with a required end date of April 30, 2020. AT&T has not yet completed the work.

AT&T Response: The pole transfer was completed and the buddy pole removed on the joint pole project. The ticket is closed.

AT&T identified work order #493565 on October 26, 2019, to transfer facilities to a new pole with a required end date of April 30, 2024. AT&T has not yet completed the work.

AT&T Response: The pole transfer was completed and the buddy pole removed on the joint pole project. This ticket is closed.

Alleged Records violation 2:

GO 95, Rule 80.1.A.(4) – Record Keeping states:

> *"Each company shall maintain records for at least ten (10) years that provide the following information for each facility subject to this rule: The location of the facility, the date of each inspection of the facility, the results of each inspection, the personnel who performed each inspection, the date and description of each corrective action, and the personnel who performed each correction action. Commission staff shall be permitted to inspect records consistent with Public Utilities Code Section 314 (a)."*

AT&T's inspection spreadsheets are missing the personnel who performed each inspection, and the personnel who performed each corrective action.

AT&T Response: AT&T pole inspection work is contracted to Osmose Utilities Services, Inc. and has been since 2019. For the corrective actions, a revised spreadsheet has been provided with the AT&T personnel ID that identifies the AT&T employee who was involved in resolving the issue or oversaw the corrective action along with the closure notes for the workorders.

I. Field Inspection

During the field inspection from September 9 – September 13, 2024, ESRB staff inspected AT&T's communication facilities in the locations listed in Table 3.

Table 3: Field Inspection Locations

Location #	Address/GPS Location	Structure Type	Structure #
1	550 Ivy St. Grass Valley, CA	Pole	200095

2	536 Ivy St. Grass Valley, CA	Pole	299
3	11082 Rough and Ready Hwy. Grass Valley, CA	Pole	120182185
4	1043 Westhill Rd. Grass Valley, CA	Pole	121415472
5	1043 Westhill Rd. Grass Valley, CA	Pole	74118
6	13003 Park View Dr. Grass Valley, CA	Pole	120182350
7	13038 Park View Dr. Grass Valley, CA	Pole	N/A
8	13023 Park View Dr. Grass Valley, CA	Pole	121302398
9	115 Joerschke Dr. Grass Valley, CA	Pole	121777995
10	115 Joerschke Dr. Grass Valley, CA	Pole	121777997
11	131 Joerschke Dr. Grass Valley, CA	Pole	121778000
12	10409 Banner Lava Cap Dr. Grass Valley, CA	Pole	120763462
13	10409 Banner Lava Cap Dr. Grass Valley, CA	Pole	120759701
14	10085 Banner Lava Cap Dr. Grass Valley, CA	Pole	N/A
15	10085 Banner Lava Cap Dr. Grass Valley, CA	Pole	120758661
16	76687 Parkside Ln. Portola, CA	Pole	250093
17	(39.8165010, -120.4520524)	Pole	15
18	76690 Parkside Ln. Portola, CA	Pole	250092
19	678 Sagebrush St. Portola, CA	Pole	160298

Location #	**Address/GPS Location**	**Structure Type**	**Structure #**
20	640 Sagebrush St. Portola, CA	Pole	160297
21	715 Sagebrush St. Portola, CA	Pole	G497
22	(39.8201477, -120.4607266)	Pole	160295
23	510 E. Magnolia Ave. Portola, CA	Pole	66239

24	509 E. Magnolia Ave. Portola, CA	Pole	66238
25	448 E. Magnolia Ave. Portola, CA	Pole	66237
26	355 Joy Way Portola, CA	Pole	P130
27	97 East Sierra Ave. Portola, CA	Pole	225790
28	(39.8112802, -120.4687920)	Pole	186112
29	(39.8112170, -120.4691383)	Pole	193574
30	7735 CA-89 Graeagle, CA	Tree Attachment	N/A
31	(39.7713871, -120.6197990)	Pole	007139
32	7701 CA-89 Graeagle, CA	Pole	007140
33	7701 CA-89 Graeagle, CA	Pole	007141
34	12 Chinook Trail Graeagle, CA	Pole	007103
35	16 Chinook Trail Graeagle, CA	Pole	007104
36	20 Chinook Trail Graeagle, CA	Pole	007105
37	13 Korominu Trail Graeagle, CA	Pole	009981
38	11 Korominu Trail Graeagle, CA	Pole	009980
39	10420 Regency Cir. Truckee, CA	Pole	151390
40	10433 Regency Cir. Truckee, CA	Pole	151391
41	10363 Regency Cir. Truckee, CA	Pole	151389
42	10399 Becket Pl. Truckee, CA	Pole	188345

Location #	**Address/GPS Location**	**Structure Type**	**Structure #**
43	10419 Becket Pl. Truckee, CA	Pole	189344
44	16075 Canterbury Ln. Truckee, CA	Pole	167860
45	16135 Canterbury Ln. Truckee, CA	Pole	167861

46	10144 Wiltshire Ln. Truckee, CA	Pole	180746
47	10260 Laburnham Cir. Truckee, CA	Pole	176739
48	10228 Laburnham Cir. Truckee, CA	Pole	176738
49	10196 Laburnham Cir. Truckee, CA	Pole	178737
50	11901 Stallion Way Truckee, CA	Pole	201347
51	12134 Stallion Way Truckee, CA	Pole	201348
52	(39.3782433, -120.0797866)	Pole	281517
53	11692 Highland Ave. Truckee, CA	Pole	34033715
54	11662 Highland Ave. Truckee, CA	Pole	32403705
55	10309 Columbine Rd. Truckee, CA	Pole	09136997
56	10328 Columbine Rd. Truckee, CA	Pole	07826942
57	10346 Columbine Rd. Truckee, CA	Pole	07236878
58	10037 S. River St. Truckee, CA	Pole	5499606
59	10050 S. River St. Truckee, CA	Pole	53509727
60	10091 S. River St. Truckee, CA	Pole	51959649
61	14323 Glacier View Dr. Truckee, CA	Pole	84450313
62	14352 Glacier View Dr. Truckee, CA	Pole	83070354
63	11789 Bennett Flat Rd. Truckee, CA	Pole	72447431
64	11761 Bennett Flat Rd. Truckee, CA	Pole	73747482

Location #	Address/GPS Location	Structure Type	Structure #
65	12179 Bernese Ln Truckee, CA	Pole	65264749
66	12155 Bernese Ln. Truckee, CA	Pole	64084735

67	12127 Bernese Ln. Truckee, CA	Pole	62834694
68	104 Berriman Loop Grass Valley, CA	Pedestal	N/A
69	126 Berriman Loop Grass Valley, CA	Pedestal	N/A
70	134 Berriman Loop Grass Valley, CA	Pedestal	N/A
71	158 Berriman Loop Grass Valley, CA	Pedestal	N/A
72	166 Berriman Loop Grass Valley, CA	Pedestal	N/A
73	182 Berriman Loop Grass Valley, CA	Pedestal	N/A
74	815 S. Auburn St. Grass Valley, CA	UG Splice Box	N/A
75	815 S. Auburn St. Grass Valley, CA	Pole	T40598611
76	(39.2012998, -121.0591576)	Pole	B25/561
77	808 S. Auburn St. Grass Valley, CA	Pole	N/A
78	13072 Somerset Dr. Grass Valley, CA	Pedestal	N/A
79	13068 Somerset Dr. Grass Valley, CA	Pedestal	N/A
80	13044 Somerset Dr. Grass Valley, CA	Pedestal	N/A
81	142 W. Towle Rd. Alta, CA	Pole	121704811
82	(39.2067939, -120.8078752)	Pole	063014
83	34004 Alta School St. Alta, CA	Pole	120859718
84	167 W. Towle Rd. Alta, CA	Pole	120859754
85	(39.2168592, -120.8205336)	Pole	121458986
86	(39.2167514, -120.8211920)	Pole	120824221
87	(39.1468378, -120.9023537)	Pole	121369786
88	215 Alpine Dr.	Pole	121369784

Location #	**Address/GPS Location**	**Structure Type**	**Structure #**
	Colfax, CA		
89	210 Alpine Dr. Colfax, CA	Pole	121313782

90	18938 Saint Paul Rd. Grass Valley, CA	Pole	120801034
91	(39.1469015, -120.9657641)	Pole	N/A
92	(39.1469095, -120.9664789)	Pole	N/A
93	16176 Colfax Hwy. Grass Valley, CA	Pole	121166180
94	16176 Colfax Hwy. Grass Valley, CA	Pole	122094722
95	14521 Dalmatian Dr. Grass Valley, CA	Pole	8
96	14656 Dalmatian Dr. Grass Valley, CA	Pole	N/A
97	14655 Dalmatian Dr. Grass Valley, CA	Pole	121698605
98	14703 Dalmatian Dr. Grass Valley, CA	Pole	121698604
99	12388 McCourtney Rd. Grass Valley, CA	Pole	120241395
100	(39.2004326, -121.0920291)	Pole	N/A
101	13334 La Barr Meadows Rd. Grass Valley, CA	Pole	110525966
102	13360 La Barr Meadows Rd. Grass Valley, CA	Pole	7913
103	13320 La Barr Meadows Rd. Grass Valley, CA	Pole	78
104	11589 Myna Dr. Grass Valley, CA	Pole	120181916
105	11613 Myrna Dr. Grass Valley, CA	Pole	N/A
106	11352 Michael Way Grass Valley, CA	Pole	120180566
107	11314 Michael Way Grass Valley, CA	Pole	121833346
108	16183 Langley Pl. Grass Valley, CA	Pole	120859939
109	16141 Langley Pl. Alta Sierra, CA	Pole	121613991
110	17962 Norlene Way Grass Valley, CA	Pole	121416472

Location #	**Address/GPS Location**	**Structure Type**	**Structure #**
111	17940 Norlene Way Grass Valley, CA	Pole	121416471

Alleged Field Inspection violation 1:

GO 95, Rule 31.1, Design, Construction and Maintenance states in part:

"Electrical supply and communication systems shall be designed, constructed, and maintained for their intended use, regard being given to the conditions under which they are to be operated, to enable the furnishing of safe, proper, and adequate service.

For all particulars not specified in these rules, design, construction, and maintenance should be done in accordance with accepted good practice for the given local conditions known at the time by those responsible for the design, construction, or maintenance of communication or supply lines and equipment.

A supply or communications company is in compliance with this rule if it designs, constructs, and maintains a facility in accordance with the particulars specified in General Order 95, except that if an intended use or known local conditions require a higher standard than the particulars specified in General Order 95 to enable the furnishing of safe, proper, and adequate service, the company shall follow the higher standard…"

ESRB's findings related to the above rule are listed in Table 4:

Table 4: GO 95, Rule 31.1 Findings

Location #	Findings
4	Terminal box was open.
12	Facilities need to be transferred to new pole.
25	The guy anchor was buried below grade.
26	Facilities need to be transferred to new pole.
27	Riser is separated from pole.
38	There was an abandoned buddy pole.
39	Facilities need to be transferred to new pole.

Location #	Findings
42	The guy anchor was buried below grade.
43	Cable was not securely attached to pole.
52	Facilities need to be transferred to new pole.
58	Cable was not securely attached to pole.
59	Cable was not securely attached to pole.
63	There was a damaged terminal.
65	Cable was not securely attached to pole.
76	Cable was not securely attached to pole.
83	Facilities need to be transferred to new pole.
86	Facilities need to be transferred to new pole.
92	Terminal box was open. Cable was not securely attached to pole.
93	Facilities need to be transferred to new pole.
97	Cable was not securely attached to pole.
104	Facilities need to be transferred to new pole.
106	Facilities need to be transferred to new pole.
110	Cable was not securely attached to pole.

AT&T Response:

The following tickets have been opened and will be worked prior to the due dates. All Past due Items

will be prioritized to be worked as soon as possible.

- 1614207 due on 01/22/2030
- 509252 due on 08/10/2024
- 1614208 due on 01/22/2030
- 1614206 due on 01/22/2030
- 997875 due on 09/24/2024
- 911336 due on 07/20/2024
- 948182 due on 07/08/2026
- 1614188 due on 01/22/2030
- 1614190 due on 01/22/2028
- 1614191 due on 01/22/2030
- 1614189 due on 01/22/2028
- 1379002 due on 01/22/2028
- 1614230 due on 01/22/2030
- 1614232 due on 1/22/2028
- 1492756 due on 04/15/2029
- 782333 due on 10/27/2025
- 1614324 due on 01/22/2030
- 1614325 due on 01/22/2030
- 987466 due on 06/16/2024
- 1499611 due on 04/05/2027
- 782609 due on 10/26/2025
- 986590 due on 6/15/2026
- 1614231 due on 01/22/2028

Alleged Field Inspection violation 2:

GO 95, Rule 31.6, Abandoned Lines states:

> *"Lines or portions of lines permanently abandoned shall be removed by their owners so that such lines shall not become a public nuisance or a hazard to life or property. For the purposes of this rule, lines that are permanently abandoned shall be defined as those lines that are determined by their owner to have no foreseeable future use."*

ESRB's finding related to the above rule is listed in Table 5:

Table 5: GO 95, Rule 31.6
Finding

Location #	Finding
61	There was an abandoned AT&T service drop.

AT&T Response:
Ticket 1614335 was opened for this issue and is due 1/22/2028.

Alleged Field Inspection violation 3:

GO 95, Rule 35, Vegetation Management states in part:

> *"Communication and electric supply circuits, energized at 750 volts or less, including their service drops, should be kept clear of vegetation in new construction and when circuits are reconstructed or repaired, whenever practicable. When a supply or communication company has actual knowledge, obtained either through normal operating practices or notification to the company, that its circuit energized at 750 volts or less shows strain or evidences abrasion from vegetation contact, the condition shall be corrected by reducing conductor tension, rearranging or replacing the conductor, pruning the vegetation, or placing mechanical protection on the conductor(s). For the purpose of this rule, abrasion is defined as damage to the insulation resulting from the friction between the vegetation and conductor. Scuffing or polishing of the insulation or covering is not considered abrasion. Strain on a conductor is present when vegetation contact significantly compromises the structural integrity of supply or communication facilities. Contact between vegetation and conductors, in and of itself, does not constitute a nonconformance with the rule."*

ESRB's finding related to the above rule is listed in Table 6:

Table 6: GO 95, Rule 35 Finding

Location #	Finding
6	There was tree strain on the cable.

AT&T Response:
Ticket 986455 was already opened in the system for this issue and is due 6/16/2026.

Alleged Field Inspection violation 4:

GO 95, Rule 84.8D(4) – Above or below Supply Service Drops states:

"The radial clearance between communication service drop conductors and supply service drop conductors may be less than 48 inches as specified in Table 2, Column C, Cases 4 and 9: Column D, Cases 3 and 8, but shall be not less than 24 inches. Where within 15 feet of the point of attachment of either service drop on a building, this clearance may be further reduced but shall be not less than 12 inches."

ESRB's finding related to above rule is listed in Table 7:

Table 7: GO 95, Rule 84.8D(4) Finding

Location #	Finding
104	AT&T service drop was in contact with electrical service drop.

AT&T Response:
Ticket 1614323 was opened in the system and is due 1/22/2028.

Alleged Field Inspection violation 5:

GO 95, Rule 87.7-D(1), Risers, Covered from Ground Level to 8 Feet Above the Ground states:

"Risers shall be protected from the ground level to a level not less than 8 feet above the ground by:

a) Securely or effectively grounded iron or steel pipe (or other covering at least of equal strength). When metallic sheathed cable rising from underground non- metallic conduit is protected by metallic pipe or moulding, such pipe or moulding shall be effectively grounded as specified in Rule 21.4-A, or

b) Non-metallic conduit or rigid U-shaped moulding. Such conduit or moulding shall be of material as specified in Rule 22.8"

ESRB's findings related to the above rule are listed in Table 8:

Table 8: GO 95, Rule 87.7-D(1)
Findings

Location #	Findings
1	Riser was below 8 feet.
10	Riser was missing for cable along pole.
17	Unsecured cable along pole. Riser was missing for cable along pole.

Location #	Findings
34	Riser was below 8 feet.
35	Riser was missing for cable along pole.
40	Riser was below 8 feet.
51	Riser was below 8 feet.
57	Riser was below 8 feet.
58	Riser was broken.
60	Riser was below 8 feet.
81	Riser was missing for cable along pole.
85	Riser was missing for cable along pole.
95	Riser was uncovered at base of pole.
98	Riser was missing for cable along pole.
107	Riser was missing for cable along pole.
110	Riser was below 8 feet.

The following tickets have been opened and will be worked prior to the due dates. All Past due Items will be prioritized to be worked as soon as possible.

- 1614332 due on 01/22/2028
- 1614333 due on 01/22/2028
- 1614331 due on 01/22/2028
- 1614330 due on 01/22/2028
- 1614329 due on 01/22/2028
- 1614189 due on 01/22/2028
- 1614328 due on 01/22/2028
- 962228 due on 09/14/2026
- 1492800 due on 4/12/2027

- 783255 due on 10/30/2023
- 782665 due on 10/30/2023
- 1376189 due on 9/14/2026
- 1614231due on 01/22/2028

Alleged Field Inspection violation 6:

GO 128, Rule 17.1, Design, Construction and Maintenance states:

"Electrical supply and communication systems shall be designed, constructed, and maintained for their intended use, regard being given to the conditions under which they are to be operated, to enable the furnishing of safe, proper, and adequate service."

ESRB's finding related to above rule is listed in Table 9:

Table 9: GO 128, Rule 17.1 Finding

Location #	Finding
74	Vault lid was broken.

AT&T Response:
Ticket 1614228 was opened in the system to work this item.

Alleged Field Inspection violation 7:

GO 128, Rule 17.8, Identification of Manholes, Handholes, Subsurface and Self- contained Surface-mounted Equipment Enclosures states:

"*Manholes, handholes, subsurface and self-contained surface-mounted equipment enclosures shall be marked as to ownership to facilitate identification by persons authorized to work therein and by other persons performing work in their vicinity."*

ESRB's findings related to the above rule are listed in Table 10:

Table 10: GO 128, Rule 17.8 Findings

Location #	Findings

74	No mark of ownership on vault lid.
80	No mark of ownership on pedestal.

AT&T Response:
Ticket 1614228 was opened in the system to work this item.
Ticket 1614227 was opened in the system to work this item.

Observations

1. **GO 95, Rule 18-A, Resolution of Potential Violations of General Order 95 and Safety Hazards** states in part:

   "(3) If a company, while performing inspections of its facilities, discovers a Safety Hazard(s) on or near a communications facility or electric facility involving another company, the inspecting company shall notify the other entity of such Safety Hazard(s) no later than ten (10) business days after the discovery."

   "(4) To the extent a company that has a notification requirement under (2) or (3) above cannot determine the facility owner/operator, it shall contact the pole owner(s) within ten (10) business days if the subject of the notification is a Safety Hazard, or otherwise within a reasonable amount of time not to exceed 180 days after discovery. The notified pole owner(s) shall be responsible for promptly (normally not to exceed five business days) notifying the company owning/operating the facility if the subject of the notification is a Safety Hazard, or otherwise within a reasonable amount of time not to exceed 180 days, after being notified of the potential violation of GO 95."

ESRB's findings related to the above Rule are listed in Table 11:

Table 11: GO 95, Rule 18-A Findings

Location #	Findings
19	Electrical ground wire was exposed. Electrical ground rod was exposed.
19	Cable TV conductor not securely attached to pole.
22	Cable TV conductor not securely attached to pole. Riser was missing.
25	Electrical guy guard was missing on guy wire.
27	Pole does not meet clearance from building.
28	Cable TV service drop was low.

31	Communications guy guard was missing on guy wire. Electrical guy guard was missing on guy wire.
34	There was an abandoned communications service drop.

34	Electrical ground wire was exposed. Electrical ground rod was exposed.
35	Electrical ground wire was exposed.
36	Electrical ground rod was exposed.
37	Electrical ground wire was exposed.
40	Cable TV drop was not securely attached to pole. Cable TV riser was below 8 feet.
50	Electrical ground wire was exposed. Electrical ground rod was exposed.
56	There was an abandoned cable TV service drop.
57	Cable TV riser was below 8 feet.
60	Cable TV riser was below 8 feet.
88	Electrical secondary does not meet clearance with communications cable.
105	Communications service drop was in contact with guy wire.
106	Electrical high voltage sign was missing.

AT&T Response:

Third Party Notifications will be sent to the appropriate utilities.

PACKAGE_ID	MARKIT_ID	SYS_REGION	STATE	DISTRICT	WC_ID	CLLI
348606		West	California	Auburn	530459	GRVYCA01
443248		West	California	Auburn	530535	GRVYCA12
443877		West	California	Auburn	530459	GRVYCA01
444558		West	California	Auburn	530459	GRVYCA01
445509	100058258	West	CA	Auburn	530459	GRVYCA01
457605	100063555	West	CA	Auburn	530475	NVCYCA11
463700	100066201	West	CA	Auburn	530475	NVCYCA11
463701	100066194	West	CA	Auburn	530475	NVCYCA11
463702	100066190	West	CA	Auburn	530475	NVCYCA11
463705	100065964	West	CA	Chico	530433	BLRSCA12
463707	100065956	West	CA	Chico	530433	BLRSCA12
463708	100065950	West	CA	Chico	530433	BLRSCA12
463724	100065975	West	CA	Chico	530433	BLRSCA12
463725	100065968	West	CA	Chico	530433	BLRSCA12
463726	100066176	West	CA	Auburn	530475	NVCYCA11
463730	100065945	West	CA	Chico	530433	BLRSCA12
463731	100065944	West	CA	Chico	530433	BLRSCA12
463732	100065941	West	CA	Chico	530433	BLRSCA12
463733	100065938	West	CA	Chico	530433	BLRSCA12
463744	100066163	West	CA	Auburn	530475	NVCYCA11
463745	100066160	West	CA	Auburn	530475	NVCYCA11
463762	100065965	West	CA	Chico	530433	BLRSCA12
463795	100066181	West	CA	Auburn	530475	NVCYCA11
463801	100065946	West	CA	Chico	530433	BLRSCA12
463812	100066193	West	CA	Auburn	530475	NVCYCA11
463819	100065979	West	CA	Chico	530433	BLRSCA12
463820	100065967	West	CA	Chico	530433	BLRSCA12
464244	100066173	West	CA	Auburn	530475	NVCYCA11
464248	100066169	West	CA	Auburn	530475	NVCYCA11
464251	100066166	West	CA	Auburn	530475	NVCYCA11
464351	100066189	West	CA	Auburn	530475	NVCYCA11
464353	100066161	West	CA	Auburn	530475	NVCYCA11
464354	100066159	West	CA	Auburn	530475	NVCYCA11
464371	100065958	West	CA	Chico	530433	BLRSCA12
464415	100065978	West	CA	Chico	530433	BLRSCA12
471504	100072182	West	CA	Auburn	530515	TRUCCA11
471505	100072156	West	CA	Auburn	530515	TRUCCA11
471506	100072146	West	CA	Auburn	530515	TRUCCA11
471507	100072137	West	CA	Auburn	530515	TRUCCA11
471508	100072111	West	CA	Auburn	530515	TRUCCA11
471509	100072093	West	CA	Auburn	530515	TRUCCA11

471510	100072087	West	CA	Auburn	530515	TRUCCA11
471835	100072219	West	CA	Auburn	530515	TRUCCA11
471837	100072217	West	CA	Auburn	530515	TRUCCA11
471838	100072216	West	CA	Auburn	530515	TRUCCA11
471840	100072214	West	CA	Auburn	530515	TRUCCA11
471841	100072210	West	CA	Auburn	530515	TRUCCA11
471842	100072208	West	CA	Auburn	530515	TRUCCA11
471843	100072207	West	CA	Auburn	530515	TRUCCA11
471846	100072203	West	CA	Auburn	530515	TRUCCA11
471852	100072193	West	CA	Auburn	530515	TRUCCA11
471854	100072191	West	CA	Auburn	530515	TRUCCA11
471855	100072190	West	CA	Auburn	530515	TRUCCA11
471857	100072187	West	CA	Auburn	530515	TRUCCA11
471859	100072185	West	CA	Auburn	530515	TRUCCA11
471860	100072184	West	CA	Auburn	530515	TRUCCA11
471861	100072183	West	CA	Auburn	530515	TRUCCA11
471862	100072181	West	CA	Auburn	530515	TRUCCA11
471864	100072174	West	CA	Auburn	530515	TRUCCA11
471865	100072173	West	CA	Auburn	530515	TRUCCA11
471867	100072167	West	CA	Auburn	530515	TRUCCA11
471868	100072165	West	CA	Auburn	530515	TRUCCA11
471869	100072164	West	CA	Auburn	530515	TRUCCA11
471870	100072162	West	CA	Auburn	530515	TRUCCA11
471871	100072155	West	CA	Auburn	530515	TRUCCA11
471874	100072149	West	CA	Auburn	530515	TRUCCA11
471875	100072148	West	CA	Auburn	530515	TRUCCA11
471876	100072147	West	CA	Auburn	530515	TRUCCA11
471877	100072145	West	CA	Auburn	530515	TRUCCA11
471880	100072141	West	CA	Auburn	530515	TRUCCA11
471881	100072079	West	CA	Auburn	530515	TRUCCA11
471883	100072077	West	CA	Auburn	530515	TRUCCA11
471884	100072075	West	CA	Auburn	530515	TRUCCA11
471885	100072074	West	CA	Auburn	530515	TRUCCA11
471888	100072063	West	CA	Auburn	530515	TRUCCA11
471890	100072054	West	CA	Auburn	530515	TRUCCA11
471893	100072140	West	CA	Auburn	530515	TRUCCA11
471899	100072129	West	CA	Auburn	530515	TRUCCA11
471900	100072128	West	CA	Auburn	530515	TRUCCA11
471902	100072125	West	CA	Auburn	530515	TRUCCA11
471903	100072053	West	CA	Auburn	530515	TRUCCA11
471904	100072052	West	CA	Auburn	530515	TRUCCA11
471906	100072050	West	CA	Auburn	530515	TRUCCA11
471908	100072045	West	CA	Auburn	530515	TRUCCA11

471910	100072039	West	CA	Auburn	530515	TRUCCA11
471911	100072038	West	CA	Auburn	530515	TRUCCA11
471912	100072037	West	CA	Auburn	530515	TRUCCA11
471914	100072123	West	CA	Auburn	530515	TRUCCA11
471915	100072122	West	CA	Auburn	530515	TRUCCA11
471918	100072116	West	CA	Auburn	530515	TRUCCA11
471920	100072114	West	CA	Auburn	530515	TRUCCA11
471927	100072022	West	CA	Auburn	530515	TRUCCA11
471933	100072103	West	CA	Auburn	530515	TRUCCA11
471937	100072099	West	CA	Auburn	530515	TRUCCA11
471938	100072098	West	CA	Auburn	530515	TRUCCA11
471940	100072091	West	CA	Auburn	530515	TRUCCA11
471941	100072088	West	CA	Auburn	530515	TRUCCA11
471942	100072014	West	CA	Auburn	530515	TRUCCA11
471943	100072013	West	CA	Auburn	530515	TRUCCA11
471956	100072086	West	CA	Auburn	530515	TRUCCA11
471957	100072083	West	CA	Auburn	530515	TRUCCA11
471958	100072081	West	CA	Auburn	530515	TRUCCA11
471959	100072080	West	CA	Auburn	530515	TRUCCA11
472086	100072213	West	CA	Auburn	530515	TRUCCA11
472087	100072212	West	CA	Auburn	530515	TRUCCA11
472088	100072211	West	CA	Auburn	530515	TRUCCA11
472089	100072209	West	CA	Auburn	530515	TRUCCA11
472090	100072205	West	CA	Auburn	530515	TRUCCA11
472091	100072200	West	CA	Auburn	530515	TRUCCA11
472092	100072198	West	CA	Auburn	530515	TRUCCA11
472093	100072195	West	CA	Auburn	530515	TRUCCA11
472094	100072194	West	CA	Auburn	530515	TRUCCA11
472095	100072189	West	CA	Auburn	530515	TRUCCA11
472096	100072178	West	CA	Auburn	530515	TRUCCA11
472097	100072177	West	CA	Auburn	530515	TRUCCA11
472098	100072176	West	CA	Auburn	530515	TRUCCA11
472099	100072175	West	CA	Auburn	530515	TRUCCA11
472100	100072171	West	CA	Auburn	530515	TRUCCA11
472101	100072169	West	CA	Auburn	530515	TRUCCA11
472102	100072168	West	CA	Auburn	530515	TRUCCA11
472103	100072166	West	CA	Auburn	530515	TRUCCA11
472104	100072163	West	CA	Auburn	530515	TRUCCA11
472105	100072161	West	CA	Auburn	530515	TRUCCA11
472106	100072160	West	CA	Auburn	530515	TRUCCA11
472107	100072159	West	CA	Auburn	530515	TRUCCA11
472108	100072158	West	CA	Auburn	530515	TRUCCA11
472109	100072153	West	CA	Auburn	530515	TRUCCA11
472110	100072152	West	CA	Auburn	530515	TRUCCA11

472111	100072151	West	CA	Auburn	530515	TRUCCA11
472112	100072142	West	CA	Auburn	530515	TRUCCA11
472113	100072076	West	CA	Auburn	530515	TRUCCA11
472114	100072070	West	CA	Auburn	530515	TRUCCA11
472115	100072069	West	CA	Auburn	530515	TRUCCA11
472116	100072067	West	CA	Auburn	530515	TRUCCA11
472117	100072066	West	CA	Auburn	530515	TRUCCA11
472118	100072065	West	CA	Auburn	530515	TRUCCA11
472119	100072064	West	CA	Auburn	530515	TRUCCA11
472120	100072062	West	CA	Auburn	530515	TRUCCA11
472121	100072061	West	CA	Auburn	530515	TRUCCA11
472122	100072060	West	CA	Auburn	530515	TRUCCA11
472123	100072059	West	CA	Auburn	530515	TRUCCA11
472124	100072057	West	CA	Auburn	530515	TRUCCA11
472125	100072056	West	CA	Auburn	530515	TRUCCA11
472127	100072138	West	CA	Auburn	530515	TRUCCA11
472128	100072136	West	CA	Auburn	530515	TRUCCA11
472129	100072135	West	CA	Auburn	530515	TRUCCA11
472130	100072126	West	CA	Auburn	530515	TRUCCA11
472131	100072049	West	CA	Auburn	530515	TRUCCA11
472132	100072046	West	CA	Auburn	530515	TRUCCA11
472133	100072044	West	CA	Auburn	530515	TRUCCA11
472134	100072042	West	CA	Auburn	530515	TRUCCA11
472135	100072041	West	CA	Auburn	530515	TRUCCA11
472136	100072036	West	CA	Auburn	530515	TRUCCA11
472137	100072035	West	CA	Auburn	530515	TRUCCA11
472138	100072119	West	CA	Auburn	530515	TRUCCA11
472139	100072113	West	CA	Auburn	530515	TRUCCA11
472141	100072106	West	CA	Auburn	530515	TRUCCA11
472142	100072034	West	CA	Auburn	530515	TRUCCA11
472143	100072031	West	CA	Auburn	530515	TRUCCA11
472144	100072030	West	CA	Auburn	530515	TRUCCA11
472145	100072029	West	CA	Auburn	530515	TRUCCA11
472146	100072026	West	CA	Auburn	530515	TRUCCA11
472148	100072021	West	CA	Auburn	530515	TRUCCA11
472149	100072105	West	CA	Auburn	530515	TRUCCA11
472150	100072104	West	CA	Auburn	530515	TRUCCA11
472151	100072097	West	CA	Auburn	530515	TRUCCA11
472152	100072096	West	CA	Auburn	530515	TRUCCA11
472153	100072095	West	CA	Auburn	530515	TRUCCA11
472154	100072094	West	CA	Auburn	530515	TRUCCA11
472155	100072090	West	CA	Auburn	530515	TRUCCA11
472156	100072089	West	CA	Auburn	530515	TRUCCA11
472159	100072085	West	CA	Auburn	530515	TRUCCA11

472160	100072084	West	CA	Auburn	530515	TRUCCA11
472161	100072082	West	CA	Auburn	530515	TRUCCA11
472414	100072326	West	CA	Auburn	530515	TRUCCA11
472422	100072254	West	CA	Auburn	530515	TRUCCA11
472428	100072285	West	CA	Auburn	530515	TRUCCA11
472434	100072368	West	CA	Auburn	530515	TRUCCA11
472436	100072342	West	CA	Auburn	530515	TRUCCA11
472458	100072305	West	CA	Auburn	530515	TRUCCA11
472462	100072260	West	CA	Auburn	530515	TRUCCA11
472465	100072299	West	CA	Auburn	530515	TRUCCA11
472472	100072374	West	CA	Auburn	530515	TRUCCA11
472479	100072274	West	CA	Auburn	530515	TRUCCA11
472519	100072235	West	CA	Auburn	530515	TRUCCA11
472529	100072316	West	CA	Auburn	530515	TRUCCA11
472561	100072336	West	CA	Auburn	530515	TRUCCA11
472563	100072311	West	CA	Auburn	530515	TRUCCA11
472597	100072349	West	CA	Auburn	530515	TRUCCA11
472608	100072365	West	CA	Auburn	530515	TRUCCA11
472610	100072266	West	CA	Auburn	530515	TRUCCA11
472622	100072286	West	CA	Auburn	530515	TRUCCA11
472637	100072355	West	CA	Auburn	530515	TRUCCA11
472649	100072334	West	CA	Auburn	530515	TRUCCA11
472664	100072279	West	CA	Auburn	530515	TRUCCA11
472672	100072346	West	CA	Auburn	530515	TRUCCA11
472675	100072338	West	CA	Auburn	530515	TRUCCA11
472686	100072323	West	CA	Auburn	530515	TRUCCA11
472690	100072324	West	CA	Auburn	530515	TRUCCA11
472697	100072381	West	CA	Auburn	530515	TRUCCA11
472707	100072224	West	CA	Auburn	530515	TRUCCA11
472727	100072269	West	CA	Auburn	530515	TRUCCA11
472729	100072301	West	CA	Auburn	530515	TRUCCA11
472739	100072354	West	CA	Auburn	530515	TRUCCA11
472742	100072315	West	CA	Auburn	530515	TRUCCA11
472756	100072380	West	CA	Auburn	530515	TRUCCA11
472772	100072276	West	CA	Auburn	530515	TRUCCA11
472773	100072366	West	CA	Auburn	530515	TRUCCA11
472775	100072239	West	CA	Auburn	530515	TRUCCA11
472797	100072236	West	CA	Auburn	530515	TRUCCA11
472800	100072320	West	CA	Auburn	530515	TRUCCA11

472813	100072348	West	CA	Auburn	530515	TRUCCA11
472819	100072363	West	CA	Auburn	530515	TRUCCA11
472827	100072373	West	CA	Auburn	530515	TRUCCA11
472828	100072378	West	CA	Auburn	530515	TRUCCA11
472850	100072246	West	CA	Auburn	530515	TRUCCA11
472872	100072300	West	CA	Auburn	530515	TRUCCA11
472909	100072347	West	CA	Auburn	530515	TRUCCA11
472919	100072319	West	CA	Auburn	530515	TRUCCA11
472928	100072318	West	CA	Auburn	530515	TRUCCA11
472940	100072232	West	CA	Auburn	530515	TRUCCA11
472969	100072372	West	CA	Auburn	530515	TRUCCA11
473031	100072333	West	CA	Auburn	530515	TRUCCA11
473062	100072297	West	CA	Auburn	530515	TRUCCA11
473064	100072340	West	CA	Auburn	530515	TRUCCA11
473076	100072344	West	CA	Auburn	530515	TRUCCA11
473111	100072328	West	CA	Auburn	530515	TRUCCA11
473125	100072314	West	CA	Auburn	530515	TRUCCA11
473127	100072248	West	CA	Auburn	530515	TRUCCA11
473132	100072360	West	CA	Auburn	530515	TRUCCA11
473136	100072237	West	CA	Auburn	530515	TRUCCA11
473137	100072275	West	CA	Auburn	530515	TRUCCA11
473139	100072231	West	CA	Auburn	530515	TRUCCA11
473143	100072362	West	CA	Auburn	530515	TRUCCA11
473145	100072261	West	CA	Auburn	530515	TRUCCA11
473146	100072234	West	CA	Auburn	530515	TRUCCA11
473152	100072306	West	CA	Auburn	530515	TRUCCA11
473160	100072291	West	CA	Auburn	530515	TRUCCA11
473165	100072277	West	CA	Auburn	530515	TRUCCA11
473167	100072294	West	CA	Auburn	530515	TRUCCA11
473169	100072255	West	CA	Auburn	530515	TRUCCA11
473178	100072268	West	CA	Auburn	530515	TRUCCA11
473182	100072335	West	CA	Auburn	530515	TRUCCA11
473184	100072304	West	CA	Auburn	530515	TRUCCA11
473185	100072250	West	CA	Auburn	530515	TRUCCA11
473186	100072345	West	CA	Auburn	530515	TRUCCA11
473194	100072357	West	CA	Auburn	530515	TRUCCA11
473197	100072367	West	CA	Auburn	530515	TRUCCA11
473200	100072227	West	CA	Auburn	530515	TRUCCA11
473201	100072321	West	CA	Auburn	530515	TRUCCA11
473202	100072293	West	CA	Auburn	530515	TRUCCA11
473204	100072317	West	CA	Auburn	530515	TRUCCA11
473213	100072288	West	CA	Auburn	530515	TRUCCA11
473214	100072339	West	CA	Auburn	530515	TRUCCA11
473219	100072382	West	CA	Auburn	530515	TRUCCA11

473221	100072251	West	CA	Auburn	530515	TRUCCA11
473224	100072296	West	CA	Auburn	530515	TRUCCA11
473228	100072258	West	CA	Auburn	530515	TRUCCA11
473229	100072229	West	CA	Auburn	530515	TRUCCA11
473231	100072223	West	CA	Auburn	530515	TRUCCA11
473232	100072241	West	CA	Auburn	530515	TRUCCA11
473233	100072242	West	CA	Auburn	530515	TRUCCA11
473241	100072303	West	CA	Auburn	530515	TRUCCA11
473243	100072263	West	CA	Auburn	530515	TRUCCA11
473245	100072282	West	CA	Auburn	530515	TRUCCA11
473251	100072278	West	CA	Auburn	530515	TRUCCA11
473256	100072332	West	CA	Auburn	530515	TRUCCA11
473258	100072225	West	CA	Auburn	530515	TRUCCA11
473259	100072351	West	CA	Auburn	530515	TRUCCA11
473265	100072356	West	CA	Auburn	530515	TRUCCA11
473268	100072257	West	CA	Auburn	530515	TRUCCA11
473269	100072230	West	CA	Auburn	530515	TRUCCA11
473276	100072252	West	CA	Auburn	530515	TRUCCA11
473277	100072290	West	CA	Auburn	530515	TRUCCA11
473282	100072272	West	CA	Auburn	530515	TRUCCA11
473289	100072307	West	CA	Auburn	530515	TRUCCA11
473296	100072247	West	CA	Auburn	530515	TRUCCA11
473298	100072265	West	CA	Auburn	530515	TRUCCA11
474774	100074339	West	CA	Chico	530493	QNCYCA12
478953		West	California	Auburn	530447	DTFLCA11
482978	100078860	West	CA	Auburn	530459	GRVYCA01
488686	100083356	West	CA	Chico	530493	QNCYCA12
488698	100083322	West	CA	Chico	530493	QNCYCA12
488700	100083332	West	CA	Chico	530493	QNCYCA12
488705	100082793	West	CA	Auburn	530447	DTFLCA11
488716	100083337	West	CA	Chico	530493	QNCYCA12
488801	100083362	West	CA	Chico	530493	QNCYCA12
488814	100083315	West	CA	Chico	530493	QNCYCA12
488822	100083338	West	CA	Chico	530493	QNCYCA12
488832	100083333	West	CA	Chico	530493	QNCYCA12
488856	100083370	West	CA	Chico	530493	QNCYCA12
488857	100083367	West	CA	Chico	530493	QNCYCA12
488860	100083364	West	CA	Chico	530493	QNCYCA12
488894	100083345	West	CA	Chico	530493	QNCYCA12
488896	100083330	West	CA	Chico	530493	QNCYCA12
488906	100082800	West	CA	Auburn	530447	DTFLCA11
489028	100083319	West	CA	Chico	530493	QNCYCA12
489033	100083359	West	CA	Chico	530493	QNCYCA12
489059	100083347	West	CA	Chico	530493	QNCYCA12

489103	100083360	West	CA	Chico	530493	QNCYCA12
489113	100083342	West	CA	Chico	530493	QNCYCA12
489143	100083346	West	CA	Chico	530493	QNCYCA12
489146	100083351	West	CA	Chico	530493	QNCYCA12
489303	100083369	West	CA	Chico	530493	QNCYCA12
489310	100082801	West	CA	Auburn	530447	DTFLCA11
489312	100082803	West	CA	Auburn	530447	DTFLCA11
489317	100082802	West	CA	Auburn	530447	DTFLCA11
489328	100083350	West	CA	Chico	530493	QNCYCA12
489374	100083340	West	CA	Chico	530493	QNCYCA12
491582	100084881	West	CA	Chico	530493	QNCYCA12
493012		West	California	Auburn	530475	NVCYCA11
493348	100087308	West	CA	Auburn	530459	GRVYCA01
493356	100087239	West	CA	Auburn	530459	GRVYCA01
493357	100087238	West	CA	Auburn	530459	GRVYCA01
493368	100087393	West	CA	Auburn	530459	GRVYCA01
493369	100087255	West	CA	Auburn	530459	GRVYCA01
493370	100087252	West	CA	Auburn	530459	GRVYCA01
493382	100087274	West	CA	Auburn	530459	GRVYCA01
493399	100087242	West	CA	Auburn	530459	GRVYCA01
493407	100087429	West	CA	Auburn	530459	GRVYCA01
493408	100087246	West	CA	Auburn	530459	GRVYCA01
493412	100087291	West	CA	Auburn	530459	GRVYCA01
493885	100087341	West	CA	Auburn	530459	GRVYCA01
493934	100087293	West	CA	Auburn	530459	GRVYCA01
493935	100087292	West	CA	Auburn	530459	GRVYCA01
493936	100087284	West	CA	Auburn	530459	GRVYCA01
493937	100087279	West	CA	Auburn	530459	GRVYCA01
493938	100087309	West	CA	Auburn	530459	GRVYCA01
493940	100087304	West	CA	Auburn	530459	GRVYCA01
493942	100087298	West	CA	Auburn	530459	GRVYCA01
493967	100087427	West	CA	Auburn	530459	GRVYCA01
493968	100087423	West	CA	Auburn	530459	GRVYCA01
493969	100087417	West	CA	Auburn	530459	GRVYCA01
493970	100087413	West	CA	Auburn	530459	GRVYCA01
493971	100087405	West	CA	Auburn	530459	GRVYCA01
493973	100087375	West	CA	Auburn	530459	GRVYCA01
493975	100087366	West	CA	Auburn	530459	GRVYCA01
493977	100087337	West	CA	Auburn	530459	GRVYCA01
493978	100087335	West	CA	Auburn	530459	GRVYCA01
493980	100087331	West	CA	Auburn	530459	GRVYCA01
493981	100087321	West	CA	Auburn	530459	GRVYCA01
494090	100087485	West	CA	Auburn	530459	GRVYCA01

494091	100087452	West	CA	Auburn	530459	GRVYCA01
494092	100087444	West	CA	Auburn	530459	GRVYCA01
494093	100087548	West	CA	Auburn	530459	GRVYCA01
494094	100087542	West	CA	Auburn	530459	GRVYCA01
494095	100087519	West	CA	Auburn	530459	GRVYCA01
494096	100087514	West	CA	Auburn	530459	GRVYCA01
494097	100087499	West	CA	Auburn	530459	GRVYCA01
494098	100087533	West	CA	Auburn	530459	GRVYCA01
494099	100087532	West	CA	Auburn	530459	GRVYCA01
494100	100087531	West	CA	Auburn	530459	GRVYCA01
494102	100087537	West	CA	Auburn	530459	GRVYCA01
494200	100087437	West	CA	Auburn	530459	GRVYCA01
494201	100087434	West	CA	Auburn	530459	GRVYCA01
494202	100087545	West	CA	Auburn	530459	GRVYCA01
494203	100087539	West	CA	Auburn	530459	GRVYCA01
494207	100087510	West	CA	Auburn	530459	GRVYCA01
494208	100087506	West	CA	Auburn	530459	GRVYCA01
494209	100087502	West	CA	Auburn	530459	GRVYCA01
494210	100087487	West	CA	Auburn	530459	GRVYCA01
502498	100093734	West	CA	Auburn	530459	GRVYCA01
504552	100095386	West	CA		530437	CHLNCA11
504553	100095483	West	CA	Auburn	530459	GRVYCA01
504554	100095471	West	CA	Auburn	530444	DWNVCA11
504566	100095394	West	CA		530437	CHLNCA11
504569	100095434	West	CA		530437	CHLNCA11
504570	100095520	West	CA	Auburn	530459	GRVYCA01
504573	100095295	West	CA	Auburn	530425	ALGHCA11
504574	100095325	West	CA		530437	CHLNCA11
504575	100095473	West	CA	Auburn	530444	DWNVCA11
504579	100095406	West	CA		530437	CHLNCA11
504585	100095540	West	CA	Auburn	530459	GRVYCA01
504586	100095372	West	CA		530437	CHLNCA11
504587	100095462	West	CA	Auburn	530444	DWNVCA11
504591	100095332	West	CA		530437	CHLNCA11
504593	100095370	West	CA		530437	CHLNCA11
504595	100095383	West	CA		530437	CHLNCA11
504600	100095390	West	CA		530437	CHLNCA11
504602	100095427	West	CA		530437	CHLNCA11
504604	100095382	West	CA		530437	CHLNCA11
504610	100095408	West	CA		530437	CHLNCA11
504611	100095426	West	CA		530437	CHLNCA11
504612	100095343	West	CA		530437	CHLNCA11
504613	100095430	West	CA		530437	CHLNCA11
504615	100095342	West	CA		530437	CHLNCA11

504616	100095490	West	CA	Auburn	530459	GRVYCA01
504617	100095512	West	CA	Auburn	530459	GRVYCA01
504618	100095322	West	CA		530437	CHLNCA11
504619	100095313	West	CA	Auburn	530436	CMPVCA11
504620	100095400	West	CA		530437	CHLNCA11
504621	100095354	West	CA		530437	CHLNCA11
504622	100095389	West	CA		530437	CHLNCA11
504623	100095337	West	CA		530437	CHLNCA11
504625	100095498	West	CA	Auburn	530459	GRVYCA01
504629	100095420	West	CA		530437	CHLNCA11
504634	100095365	West	CA		530437	CHLNCA11
504638	100095312	West	CA	Auburn	530425	ALGHCA11
504640	100095475	West	CA	Auburn	530444	DWNVCA11
504642	100095292	West	CA	Auburn	530425	ALGHCA11
504644	100095457	West	CA	Auburn	530444	DWNVCA11
504645	100095293	West	CA	Auburn	530425	ALGHCA11
504661	100095307	West	CA	Auburn	530425	ALGHCA11
504674	100095346	West	CA		530437	CHLNCA11
504754	100095438	West	CA		530437	CHLNCA11
504755	100095385	West	CA		530437	CHLNCA11
504793	100095364	West	CA		530437	CHLNCA11
504828	100095296	West	CA	Auburn	530425	ALGHCA11
504842	100095403	West	CA		530437	CHLNCA11
504893	100095460	West	CA	Auburn	530444	DWNVCA11
504918	100095294	West	CA	Auburn	530425	ALGHCA11
505016	100095384	West	CA		530437	CHLNCA11
505028	100095311	West	CA	Auburn	530425	ALGHCA11
505030	100095298	West	CA	Auburn	530425	ALGHCA11
505038	100095478	West	CA	Auburn	530444	DWNVCA11
505056	100095306	West	CA	Auburn	530425	ALGHCA11
505070	100095304	West	CA	Auburn	530425	ALGHCA11
505104	100095439	West	CA		530437	CHLNCA11
505111	100095309	West	CA	Auburn	530425	ALGHCA11
505177	100095514	West	CA	Auburn	530459	GRVYCA01
505178	100095300	West	CA	Auburn	530425	ALGHCA11
505198	100095495	West	CA	Auburn	530459	GRVYCA01
505201	100095345	West	CA		530437	CHLNCA11
505202	100095465	West	CA	Auburn	530444	DWNVCA11
505205	100095327	West	CA		530437	CHLNCA11
505210	100095414	West	CA		530437	CHLNCA11
505214	100095378	West	CA		530437	CHLNCA11
505221	100095334	West	CA		530437	CHLNCA11
505229	100095501	West	CA	Auburn	530459	GRVYCA01
505232	100095425	West	CA		530437	CHLNCA11

505241	100095399	West	CA		530437	CHLNCA11
505251	100095497	West	CA	Auburn	530459	GRVYCA01
505252	100095455	West	CA	Auburn	530444	DWNVCA11
505256	100095482	West	CA	Auburn	530459	GRVYCA01
505258	100095299	West	CA	Auburn	530425	ALGHCA11
505269	100095472	West	CA	Auburn	530444	DWNVCA11
505274	100095379	West	CA		530437	CHLNCA11
505275	100095308	West	CA	Auburn	530425	ALGHCA11
505279	100095468	West	CA	Auburn	530444	DWNVCA11
505281	100095393	West	CA		530437	CHLNCA11
505288	100095459	West	CA	Auburn	530444	DWNVCA11
505292	100095487	West	CA	Auburn	530459	GRVYCA01
506414	100097249	West	CA	Auburn	530480	NSJNCA11
506415	100097246	West	CA	Auburn	530480	NSJNCA11
506419	100097241	West	CA	Auburn	530480	NSJNCA11
506460	100097226	West	CA	Auburn	530480	NSJNCA11
506501	100097262	West	CA	Auburn	530480	NSJNCA11
506502	100097260	West	CA	Auburn	530480	NSJNCA11
507124	100097233	West	CA	Auburn	530480	NSJNCA11
507125	100097228	West	CA	Auburn	530480	NSJNCA11
507147	100096780	West	CA	Chico	530433	BLRSCA12
508969	100099234	West	CA	Auburn	530475	NVCYCA11
508971	100099177	West	CA	Auburn	530475	NVCYCA11
508973	100099168	West	CA	Auburn	530475	NVCYCA11
508974	100099253	West	CA	Auburn	530475	NVCYCA11
508976	100099147	West	CA	Auburn	530475	NVCYCA11
508977	100099097	West	CA	Auburn	530475	NVCYCA11
508978	100099011	West	CA	Auburn	530459	GRVYCA01
508979	100099009	West	CA	Auburn	530459	GRVYCA01
508981	100099225	West	CA	Auburn	530475	NVCYCA11
508982	100099224	West	CA	Auburn	530475	NVCYCA11
508983	100099222	West	CA	Auburn	530475	NVCYCA11
508984	100099197	West	CA	Auburn	530475	NVCYCA11
508985	100099189	West	CA	Auburn	530475	NVCYCA11
508986	100099157	West	CA	Auburn	530475	NVCYCA11
508987	100099156	West	CA	Auburn	530475	NVCYCA11
508988	100099266	West	CA	Auburn	530475	NVCYCA11
508989	100099260	West	CA	Auburn	530475	NVCYCA11
508990	100099091	West	CA	Auburn	530475	NVCYCA11
508991	100099065	West	CA	Auburn	530475	NVCYCA11
508992	100099064	West	CA	Auburn	530475	NVCYCA11
508993	100099061	West	CA	Auburn	530475	NVCYCA11
508994	100099053	West	CA	Auburn	530475	NVCYCA11
508995	100099028	West	CA	Auburn	530459	GRVYCA01

508996	100099144	West	CA	Auburn	530475	NVCYCA11
508997	100099138	West	CA	Auburn	530475	NVCYCA11
508998	100099134	West	CA	Auburn	530475	NVCYCA11
508999	100099130	West	CA	Auburn	530475	NVCYCA11
509000	100099123	West	CA	Auburn	530475	NVCYCA11
509001	100099122	West	CA	Auburn	530475	NVCYCA11
509002	100099110	West	CA	Auburn	530475	NVCYCA11
509003	100099248	West	CA	Auburn	530475	NVCYCA11
509005	100099008	West	CA	Auburn	530459	GRVYCA01
509006	100098818	West	CA	Auburn	530459	GRVYCA01
509007	100099095	West	CA	Auburn	530475	NVCYCA11
509008	100099226	West	CA	Auburn	530475	NVCYCA11
509009	100099262	West	CA	Auburn	530475	NVCYCA11
509010	100099081	West	CA	Auburn	530475	NVCYCA11
509011	100099098	West	CA	Auburn	530475	NVCYCA11
509012	100098920	West	CA	Auburn	530459	GRVYCA01
509025	100099219	West	CA	Auburn	530475	NVCYCA11
509218	100098932	West	CA	Auburn	530459	GRVYCA01
509260	100098887	West	CA	Auburn	530459	GRVYCA01
509318	100098964	West	CA	Auburn	530459	GRVYCA01
509364	100098850	West	CA	Auburn	530459	GRVYCA01
509423	100099251	West	CA	Auburn	530475	NVCYCA11
509424	100098972	West	CA	Auburn	530459	GRVYCA01
509427	100099195	West	CA	Auburn	530475	NVCYCA11
509429	100099162	West	CA	Auburn	530475	NVCYCA11
509430	100099263	West	CA	Auburn	530475	NVCYCA11
509431	100099057	West	CA	Auburn	530475	NVCYCA11
509432	100099044	West	CA	Auburn	530459	GRVYCA01
509433	100099040	West	CA	Auburn	530459	GRVYCA01
509434	100099031	West	CA	Auburn	530459	GRVYCA01
509436	100099113	West	CA	Auburn	530475	NVCYCA11
509437	100099106	West	CA	Auburn	530475	NVCYCA11
509439	100099246	West	CA	Auburn	530475	NVCYCA11
509440	100098912	West	CA	Auburn	530459	GRVYCA01
509441	100099014	West	CA	Auburn	530459	GRVYCA01
509447	100098872	West	CA	Auburn	530459	GRVYCA01
509450	100098950	West	CA	Auburn	530459	GRVYCA01
509576	100099617	West	CA	Auburn	530515	TRUCCA11
509577	100099575	West	CA	Auburn	530515	TRUCCA11
509578	100099561	West	CA	Auburn	530515	TRUCCA11
509656	100099630	West	CA	Auburn	530515	TRUCCA11
509657	100099629	West	CA	Auburn	530515	TRUCCA11
509668	100099613	West	CA	Auburn	530515	TRUCCA11

509683	100099590	West	CA	Auburn	530515	TRUCCA11
509686	100099587	West	CA	Auburn	530515	TRUCCA11
509881	100099632	West	CA	Auburn	530515	TRUCCA11
509882	100099631	West	CA	Auburn	530515	TRUCCA11
509883	100099627	West	CA	Auburn	530515	TRUCCA11
509884	100099623	West	CA	Auburn	530515	TRUCCA11
509885	100099621	West	CA	Auburn	530515	TRUCCA11
509886	100099618	West	CA	Auburn	530515	TRUCCA11
509887	100099612	West	CA	Auburn	530515	TRUCCA11
509888	100099609	West	CA	Auburn	530515	TRUCCA11
509889	100099607	West	CA	Auburn	530515	TRUCCA11
509892	100099603	West	CA	Auburn	530515	TRUCCA11
509894	100099592	West	CA	Auburn	530515	TRUCCA11
509895	100099584	West	CA	Auburn	530515	TRUCCA11
509897	100099581	West	CA	Auburn	530515	TRUCCA11
509898	100099580	West	CA	Auburn	530515	TRUCCA11
509899	100099579	West	CA	Auburn	530515	TRUCCA11
509901	100099571	West	CA	Auburn	530515	TRUCCA11
509902	100099570	West	CA	Auburn	530515	TRUCCA11
509903	100099569	West	CA	Auburn	530515	TRUCCA11
509904	100099567	West	CA	Auburn	530515	TRUCCA11
509905	100099565	West	CA	Auburn	530515	TRUCCA11
509906	100099564	West	CA	Auburn	530515	TRUCCA11
509908	100099557	West	CA	Auburn	530515	TRUCCA11
509909	100099652	West	CA	Auburn	530515	TRUCCA11
509910	100099650	West	CA	Auburn	530515	TRUCCA11
509913	100099647	West	CA	Auburn	530515	TRUCCA11
509914	100099645	West	CA	Auburn	530515	TRUCCA11
509916	100099635	West	CA	Auburn	530515	TRUCCA11
509928	100099281	West	CA	Auburn	530475	NVCYCA11
510850	100100742	West	CA	Auburn	530447	DTFLCA11
510851	100100739	West	CA	Auburn	530447	DTFLCA11
510852	100100738	West	CA	Auburn	530447	DTFLCA11
510853	100100737	West	CA	Auburn	530447	DTFLCA11
510854	100100732	West	CA	Auburn	530447	DTFLCA11
510855	100100728	West	CA	Auburn	530447	DTFLCA11
510862	100100748	West	CA	Auburn	530447	DTFLCA11
510863	100100747	West	CA	Auburn	530447	DTFLCA11
510864	100100746	West	CA	Auburn	530447	DTFLCA11
510865	100100745	West	CA	Auburn	530447	DTFLCA11
510873	100100726	West	CA	Auburn	530447	DTFLCA11
510883	100100736	West	CA	Auburn	530447	DTFLCA11
511066	100100752	West	CA	Auburn	530447	DTFLCA11

511101	100100731	West	CA	Auburn	530447	DTFLCA11
511114	100100744	West	CA	Auburn	530447	DTFLCA11
511115	100100743	West	CA	Auburn	530447	DTFLCA11
511116	100100741	West	CA	Auburn	530447	DTFLCA11
511117	100100735	West	CA	Auburn	530447	DTFLCA11
511118	100100733	West	CA	Auburn	530447	DTFLCA11
511119	100100727	West	CA	Auburn	530447	DTFLCA11
511135	100100713	West	CA	Auburn	530447	DTFLCA11
516191	100104567	West	CA	Chico	530493	QNCYCA12
516192	100104561	West	CA	Chico	530493	QNCYCA12
516193	100104558	West	CA	Chico	530493	QNCYCA12
516194	100104556	West	CA	Chico	530493	QNCYCA12
516195	100104554	West	CA	Chico	530493	QNCYCA12
516196	100104552	West	CA	Chico	530493	QNCYCA12
516200	100104551	West	CA	Chico	530493	QNCYCA12
516201	100104549	West	CA	Chico	530493	QNCYCA12
526658	100112928	West	CA	Chico	530433	BLRSCA12
527261	100113777	West	CA	Auburn	530515	TRUCCA11
528294	100113795	West	CA	Auburn	530515	TRUCCA11
528298	100113789	West	CA	Auburn	530515	TRUCCA11
561522	100136794	West	CA	Auburn	530459	GRVYCA01
565202	100139847	West	CA	Chico	530493	QNCYCA12
574470	100147187	West	CA	Chico	530492	PTOLCA01
582457	100152442	West	CA	Chico	530493	QNCYCA12
593350	100161107	West	CA	Chico	530493	QNCYCA12
596188		West	California	Auburn	530444	DWNVCA11
599310	100166587	West	CA	Auburn	530475	NVCYCA11
599311	100166576	West	CA	Auburn	530475	NVCYCA11
632314	100186732	West	CA	Chico	530493	QNCYCA12
643757	100196182	West	CA	Chico	530493	QNCYCA12
649058	100198187	West	CA	Chico	530433	BLRSCA12
652998	100201404	West	CA	Auburn	530459	GRVYCA01
669546	100212554	West	CA	Chico	530471	LLTNCA11
669977	100212904	West	CA	Chico	530492	PTOLCA01
669978	100212897	West	CA	Chico	530506	SRVLCA11
669979	100212894	West	CA	Chico	530492	PTOLCA01
669980	100212891	West	CA	Chico	530492	PTOLCA01
669981	100212890	West	CA	Chico	530471	LLTNCA11
672121	100214507	West	CA	Chico	530471	LLTNCA11
675964	100214650	West	CA	Chico	530433	BLRSCA12
677612	100216304	West	CA	Chico	530492	PTOLCA01
677932	100216573	West	CA	Chico	530471	LLTNCA11
677933	100216572	West	CA	Chico	530471	LLTNCA11
680958	100218309	West	CA	Chico	530493	QNCYCA12

680959	100218307	West	CA	Chico	530433	BLRSCA12
680960	100218304	West	CA	Chico	530492	PTOLCA01
681661	100218749	West	CA	Chico	530493	QNCYCA12
685522	100222160	West	CA	Chico	530493	QNCYCA12
696439	100228184	West	CA	Chico	530492	PTOLCA01
699007	100230215	West	CA	Chico	530471	LLTNCA11
701151	100232199	West	CA	Chico	530492	PTOLCA01
701152	100232198	West	CA	Chico	530492	PTOLCA01
708870	100237764	West	CA	Chico	530471	LLTNCA11
712860	100241178	West	CA	Chico	530433	BLRSCA12
759757	100269558	West	CA	Chico	530493	QNCYCA12
759758	100269697	West	CA	Chico	530492	PTOLCA01
780524	100286851	West	CA	Chico	530493	QNCYCA12
782169	100288606	West	CA	Auburn	530447	DTFLCA11
782170	100288598	West	CA	Auburn	530447	DTFLCA11
782171	100288592	West	CA	Auburn	530447	DTFLCA11
782172	100288589	West	CA	Auburn	530447	DTFLCA11
782173	100288587	West	CA	Auburn	530447	DTFLCA11
782174	100288402	West	CA	Auburn	530436	CMPVCA11
782175	100288401	West	CA	Auburn	530436	CMPVCA11
782176	100288397	West	CA	Auburn	530436	CMPVCA11
782177	100288395	West	CA	Auburn	530436	CMPVCA11
782178	100288393	West	CA	Auburn	530436	CMPVCA11
782179	100288391	West	CA	Auburn	530436	CMPVCA11
782180	100288390	West	CA	Auburn	530436	CMPVCA11
782181	100288389	West	CA	Auburn	530436	CMPVCA11
782182	100288388	West	CA	Auburn	530436	CMPVCA11
782183	100288387	West	CA	Auburn	530436	CMPVCA11
782185	100288458	West	CA		530437	CHLNCA11
782186	100288448	West	CA		530437	CHLNCA11
782187	100288445	West	CA		530437	CHLNCA11
782188	100288536	West	CA	Auburn	530444	DWNVCA11
782196	100288578	West	CA	Auburn	530447	DTFLCA11
782197	100288565	West	CA	Auburn	530447	DTFLCA11
782198	100288558	West	CA	Auburn	530447	DTFLCA11

782199	100288552	West	CA	Auburn	530447	DTFLCA11
782200	100288550	West	CA	Auburn	530447	DTFLCA11
782201	100288547	West	CA	Auburn	530447	DTFLCA11
782202	100288409	West	CA	Auburn	530436	CMPVCA11
782203	100288670	West	CA	Auburn	530459	GRVYCA01
782204	100288712	West	CA	Auburn	530459	GRVYCA01
782205	100288709	West	CA	Auburn	530459	GRVYCA01
782206	100288706	West	CA	Auburn	530459	GRVYCA01
782207	100288386	West	CA	Auburn	530436	CMPVCA11
782208	100288385	West	CA	Auburn	530436	CMPVCA11
782209	100288384	West	CA	Auburn	530436	CMPVCA11
782210	100288379	West	CA	Auburn	530436	CMPVCA11
782212	100288616	West	CA	Auburn	530459	GRVYCA01
782213	100288330	West	CA	Auburn	530425	ALGHCA11
782214	100288328	West	CA	Auburn	530425	ALGHCA11
782215	100288830	West	CA	Auburn	530459	GRVYCA01
782216	100288788	West	CA	Auburn	530459	GRVYCA01
782217	100288770	West	CA	Auburn	530459	GRVYCA01
782218	100288840	West	CA	Auburn	530459	GRVYCA01
782611	100288602	West	CA	Auburn	530447	DTFLCA11
782612	100288590	West	CA	Auburn	530447	DTFLCA11
782613	100288588	West	CA	Auburn	530447	DTFLCA11
782614	100288399	West	CA	Auburn	530436	CMPVCA11
782627	100288577	West	CA	Auburn	530447	DTFLCA11
782628	100288572	West	CA	Auburn	530447	DTFLCA11
782629	100288568	West	CA	Auburn	530447	DTFLCA11
782630	100288566	West	CA	Auburn	530447	DTFLCA11
782631	100288564	West	CA	Auburn	530447	DTFLCA11
782632	100288562	West	CA	Auburn	530447	DTFLCA11
782633	100288436	West	CA		530437	CHLNCA11
782635	100288556	West	CA	Auburn	530447	DTFLCA11
782636	100288548	West	CA	Auburn	530447	DTFLCA11
782637	100288422	West	CA		530437	CHLNCA11
782638	100288421	West	CA		530437	CHLNCA11
782639	100288420	West	CA		530437	CHLNCA11
782640	100288679	West	CA	Auburn	530459	GRVYCA01
782641	100288734	West	CA	Auburn	530459	GRVYCA01
782642	100288724	West	CA	Auburn	530459	GRVYCA01
782643	100288714	West	CA	Auburn	530459	GRVYCA01

782644	100288581	West	CA	Auburn	530447	DTFLCA11
782647	100288661	West	CA	Auburn	530459	GRVYCA01
782648	100288659	West	CA	Auburn	530459	GRVYCA01
782651	100288630	West	CA	Auburn	530459	GRVYCA01
782652	100288629	West	CA	Auburn	530459	GRVYCA01
782655	100288626	West	CA	Auburn	530459	GRVYCA01
782656	100288622	West	CA	Auburn	530459	GRVYCA01
782657	100288615	West	CA	Auburn	530459	GRVYCA01
782658	100288329	West	CA	Auburn	530425	ALGHCA11
782659	100288325	West	CA	Auburn	530425	ALGHCA11
782660	100288689	West	CA	Auburn	530459	GRVYCA01
782661	100288685	West	CA	Auburn	530459	GRVYCA01
782663	100288744	West	CA	Auburn	530459	GRVYCA01
782664	100288743	West	CA	Auburn	530459	GRVYCA01
782666	100288828	West	CA	Auburn	530459	GRVYCA01
782668	100288823	West	CA	Auburn	530459	GRVYCA01
782669	100288810	West	CA	Auburn	530459	GRVYCA01
782670	100288804	West	CA	Auburn	530459	GRVYCA01
782673	100288789	West	CA	Auburn	530459	GRVYCA01
782674	100288775	West	CA	Auburn	530459	GRVYCA01
782675	100288736	West	CA	Auburn	530459	GRVYCA01
782676	100288697	West	CA	Auburn	530459	GRVYCA01

782889	100288901	West	CA	Auburn	530459	GRVYCA01
782892	100288882	West	CA	Auburn	530459	GRVYCA01
783242	100288932	West	CA	Auburn	530459	GRVYCA01
783243	100288924	West	CA	Auburn	530459	GRVYCA01
783244	100288921	West	CA	Auburn	530459	GRVYCA01
783246	100288916	West	CA	Auburn	530459	GRVYCA01
783247	100288902	West	CA	Auburn	530459	GRVYCA01
783252	100288875	West	CA	Auburn	530459	GRVYCA01
783256	100288864	West	CA	Auburn	530459	GRVYCA01
783257	100288974	West	CA	Auburn	530459	GRVYCA01
783259	100288963	West	CA	Auburn	530459	GRVYCA01
783264	100288950	West	CA	Auburn	530459	GRVYCA01
783389	100289939	West	CA	Auburn	530515	TRUCCA11
783405	100289591	West	CA	Auburn	530505	SRCYCA11
783406	100289589	West	CA	Auburn	530505	SRCYCA11
783407	100289588	West	CA	Auburn	530505	SRCYCA11
783408	100289585	West	CA	Auburn	530505	SRCYCA11
783409	100289583	West	CA	Auburn	530505	SRCYCA11
783410	100289581	West	CA	Auburn	530505	SRCYCA11

783411	100289957	West	CA	Auburn	530515	TRUCCA11
783414	100289577	West	CA	Auburn	530505	SRCYCA11
783742	100290000	West	CA	Auburn	530515	TRUCCA11
783743	100289998	West	CA	Auburn	530515	TRUCCA11
783744	100289992	West	CA	Auburn	530515	TRUCCA11
783745	100289990	West	CA	Auburn	530515	TRUCCA11
783746	100289986	West	CA	Auburn	530515	TRUCCA11
783747	100289984	West	CA	Auburn	530515	TRUCCA11
783748	100289944	West	CA	Auburn	530515	TRUCCA11
783749	100289942	West	CA	Auburn	530515	TRUCCA11
783750	100289877	West	CA	Auburn	530515	TRUCCA11
783751	100289876	West	CA	Auburn	530515	TRUCCA11
783752	100289871	West	CA	Auburn	530515	TRUCCA11
783753	100289869	West	CA	Auburn	530515	TRUCCA11
783754	100289809	West	CA	Auburn	530515	TRUCCA11
783756	100289800	West	CA	Auburn	530515	TRUCCA11
783757	100289799	West	CA	Auburn	530515	TRUCCA11
783767	100289833	West	CA	Auburn	530515	TRUCCA11
783768	100289831	West	CA	Auburn	530515	TRUCCA11
783769	100289830	West	CA	Auburn	530515	TRUCCA11
783771	100289826	West	CA	Auburn	530515	TRUCCA11
783772	100289823	West	CA	Auburn	530515	TRUCCA11
783773	100289822	West	CA	Auburn	530515	TRUCCA11
783774	100289819	West	CA	Auburn	530515	TRUCCA11
783775	100289865	West	CA	Auburn	530515	TRUCCA11
783776	100289864	West	CA	Auburn	530515	TRUCCA11
783777	100289863	West	CA	Auburn	530515	TRUCCA11
783778	100289861	West	CA	Auburn	530515	TRUCCA11
783779	100289860	West	CA	Auburn	530515	TRUCCA11
783780	100289859	West	CA	Auburn	530515	TRUCCA11
783781	100289858	West	CA	Auburn	530515	TRUCCA11
783782	100289857	West	CA	Auburn	530515	TRUCCA11
783783	100289854	West	CA	Auburn	530515	TRUCCA11
783784	100289852	West	CA	Auburn	530515	TRUCCA11
783785	100289851	West	CA	Auburn	530515	TRUCCA11
783786	100289794	West	CA	Auburn	530515	TRUCCA11
783787	100289793	West	CA	Auburn	530515	TRUCCA11
783788	100289790	West	CA	Auburn	530515	TRUCCA11
783789	100289789	West	CA	Auburn	530515	TRUCCA11
783790	100289778	West	CA	Auburn	530515	TRUCCA11
783791	100289777	West	CA	Auburn	530515	TRUCCA11
783795	100289814	West	CA	Auburn	530515	TRUCCA11
783796	100289936	West	CA	Auburn	530515	TRUCCA11
783797	100289933	West	CA	Auburn	530515	TRUCCA11

783798	100289932	West	CA	Auburn	530515	TRUCCA11
783799	100289931	West	CA	Auburn	530515	TRUCCA11
783800	100289929	West	CA	Auburn	530515	TRUCCA11
783801	100289928	West	CA	Auburn	530515	TRUCCA11
783803	100289925	West	CA	Auburn	530515	TRUCCA11
783804	100289847	West	CA	Auburn	530515	TRUCCA11
783805	100289846	West	CA	Auburn	530515	TRUCCA11
783806	100289845	West	CA	Auburn	530515	TRUCCA11
783807	100289843	West	CA	Auburn	530515	TRUCCA11
783808	100289838	West	CA	Auburn	530515	TRUCCA11
783809	100289837	West	CA	Auburn	530515	TRUCCA11
783820	100289922	West	CA	Auburn	530515	TRUCCA11
783821	100289921	West	CA	Auburn	530515	TRUCCA11
783822	100289918	West	CA	Auburn	530515	TRUCCA11
783823	100289917	West	CA	Auburn	530515	TRUCCA11
783824	100289916	West	CA	Auburn	530515	TRUCCA11
783826	100289913	West	CA	Auburn	530515	TRUCCA11
783827	100289909	West	CA	Auburn	530515	TRUCCA11
783828	100289908	West	CA	Auburn	530515	TRUCCA11
783829	100289906	West	CA	Auburn	530515	TRUCCA11
783846	100289904	West	CA	Auburn	530515	TRUCCA11
783847	100289902	West	CA	Auburn	530515	TRUCCA11
783848	100289901	West	CA	Auburn	530515	TRUCCA11
783849	100289899	West	CA	Auburn	530515	TRUCCA11
783850	100289893	West	CA	Auburn	530515	TRUCCA11
783851	100289892	West	CA	Auburn	530515	TRUCCA11
783852	100289891	West	CA	Auburn	530515	TRUCCA11
783853	100289889	West	CA	Auburn	530515	TRUCCA11
783854	100289885	West	CA	Auburn	530515	TRUCCA11
783859	100289883	West	CA	Auburn	530515	TRUCCA11
783860	100289881	West	CA	Auburn	530515	TRUCCA11
783861	100289982	West	CA	Auburn	530515	TRUCCA11
783864	100289975	West	CA	Auburn	530515	TRUCCA11
783865	100289974	West	CA	Auburn	530515	TRUCCA11
783866	100289972	West	CA	Auburn	530515	TRUCCA11
783872	100289971	West	CA	Auburn	530515	TRUCCA11
783873	100289970	West	CA	Auburn	530515	TRUCCA11
783874	100289969	West	CA	Auburn	530515	TRUCCA11
783875	100289967	West	CA	Auburn	530515	TRUCCA11
783876	100289962	West	CA	Auburn	530515	TRUCCA11
783877	100289961	West	CA	Auburn	530515	TRUCCA11
783878	100289958	West	CA	Auburn	530515	TRUCCA11
783879	100289955	West	CA	Auburn	530515	TRUCCA11
783880	100289953	West	CA	Auburn	530515	TRUCCA11

783887	100290007	West	CA	Auburn	530515	TRUCCA11
783888	100290006	West	CA	Auburn	530515	TRUCCA11
783889	100290004	West	CA	Auburn	530515	TRUCCA11
784860	100291289	West	CA	Auburn	530475	NVCYCA11
784863	100291037	West	CA	Auburn	530535	GRVYCA12
784864	100291263	West	CA	Auburn	530475	NVCYCA11
784865	100291247	West	CA	Auburn	530475	NVCYCA11
784866	100291245	West	CA	Auburn	530475	NVCYCA11
784867	100291236	West	CA	Auburn	530475	NVCYCA11
784868	100291235	West	CA	Auburn	530475	NVCYCA11
784869	100291233	West	CA	Auburn	530475	NVCYCA11
784871	100291377	West	CA	Auburn	530475	NVCYCA11
784872	100291374	West	CA	Auburn	530475	NVCYCA11
784873	100291231	West	CA	Auburn	530475	NVCYCA11
784874	100291230	West	CA	Auburn	530475	NVCYCA11
784875	100291218	West	CA	Auburn	530475	NVCYCA11
784876	100291353	West	CA	Auburn	530475	NVCYCA11
784877	100291209	West	CA	Auburn	530475	NVCYCA11
784878	100291207	West	CA	Auburn	530475	NVCYCA11
784879	100291344	West	CA	Auburn	530475	NVCYCA11
784880	100291337	West	CA	Auburn	530475	NVCYCA11
784882	100290990	West	CA	Auburn	530535	GRVYCA12
784883	100290989	West	CA	Auburn	530535	GRVYCA12
784884	100291320	West	CA	Auburn	530475	NVCYCA11
784885	100290979	West	CA	Auburn	530535	GRVYCA12
784886	100291194	West	CA	Auburn	530475	NVCYCA11

784887	100291193	West	CA	Auburn	530475	NVCYCA11
784894	100290963	West	CA	Auburn	530535	GRVYCA12
784895	100290960	West	CA	Auburn	530535	GRVYCA12
784907	100290945	West	CA	Auburn	530535	GRVYCA12
784909	100291300	West	CA	Auburn	530475	NVCYCA11
785275	100291288	West	CA	Auburn	530475	NVCYCA11
785284	100290902	West	CA	Auburn	530535	GRVYCA12
785285	100291370	West	CA	Auburn	530475	NVCYCA11
785286	100291224	West	CA	Auburn	530475	NVCYCA11
785287	100291222	West	CA	Auburn	530475	NVCYCA11
785288	100291220	West	CA	Auburn	530475	NVCYCA11
785290	100291020	West	CA	Auburn	530535	GRVYCA12
785291	100291365	West	CA	Auburn	530475	NVCYCA11
785292	100291363	West	CA	Auburn	530475	NVCYCA11
785293	100291361	West	CA	Auburn	530475	NVCYCA11
785294	100291206	West	CA	Auburn	530475	NVCYCA11
785296	100291008	West	CA	Auburn	530535	GRVYCA12
785298	100291343	West	CA	Auburn	530475	NVCYCA11
785299	100291341	West	CA	Auburn	530475	NVCYCA11
785300	100291336	West	CA	Auburn	530475	NVCYCA11
785301	100291333	West	CA	Auburn	530475	NVCYCA11
785306	100290984	West	CA	Auburn	530535	GRVYCA12
785310	100290975	West	CA	Auburn	530535	GRVYCA12
785312	100290965	West	CA	Auburn	530535	GRVYCA12
785313	100291313	West	CA	Auburn	530475	NVCYCA11
785314	100291195	West	CA	Auburn	530475	NVCYCA11
785318	100290961	West	CA	Auburn	530535	GRVYCA12
785324	100291306	West	CA	Auburn	530475	NVCYCA11
785332	100290919	West	CA	Auburn	530535	GRVYCA12
785823	100291634	West	CA	Auburn	530480	NSJNCA11
785824	100291432	West	CA	Auburn	530475	NVCYCA11
785878	100291651	West	CA	Auburn	530480	NSJNCA11
785879	100291649	West	CA	Auburn	530480	NSJNCA11
785880	100291641	West	CA	Auburn	530480	NSJNCA11
785881	100291640	West	CA	Auburn	530480	NSJNCA11
785882	100291639	West	CA	Auburn	530480	NSJNCA11
785886	100291631	West	CA	Auburn	530480	NSJNCA11
785887	100291626	West	CA	Auburn	530480	NSJNCA11

785888	100291441	West	CA	Auburn	530475	NVCYCA11
785889	100291439	West	CA	Auburn	530475	NVCYCA11
785890	100291437	West	CA	Auburn	530475	NVCYCA11
785891	100291430	West	CA	Auburn	530475	NVCYCA11
785898	100291390	West	CA	Auburn	530475	NVCYCA11
785903	100291794	West	CA	Chico	530492	PTOLCA01
785904	100291792	West	CA	Chico	530492	PTOLCA01
785905	100291791	West	CA	Chico	530492	PTOLCA01
785910	100291789	West	CA	Chico	530492	PTOLCA01
785911	100291788	West	CA	Chico	530492	PTOLCA01
785912	100291787	West	CA	Chico	530492	PTOLCA01
785913	100291785	West	CA	Chico	530492	PTOLCA01
785914	100291782	West	CA	Chico	530492	PTOLCA01
785915	100291781	West	CA	Chico	530492	PTOLCA01
785916	100291780	West	CA	Chico	530492	PTOLCA01
785917	100291779	West	CA	Chico	530492	PTOLCA01
785929	100291803	West	CA	Chico	530492	PTOLCA01
785930	100291801	West	CA	Chico	530492	PTOLCA01
785931	100291800	West	CA	Chico	530492	PTOLCA01
785947	100291463	West	CA	Auburn	530475	NVCYCA11
785948	100291460	West	CA	Auburn	530475	NVCYCA11
785949	100291450	West	CA	Auburn	530475	NVCYCA11
785955	100291622	West	CA	Auburn	530480	NSJNCA11
785956	100291621	West	CA	Auburn	530480	NSJNCA11
785957	100291620	West	CA	Auburn	530480	NSJNCA11
785958	100291614	West	CA	Auburn	530480	NSJNCA11
785959	100291611	West	CA	Auburn	530480	NSJNCA11
785960	100291607	West	CA	Auburn	530480	NSJNCA11
785964	100291604	West	CA	Auburn	530480	NSJNCA11
785965	100291603	West	CA	Auburn	530480	NSJNCA11
786000	100291612	West	CA	Auburn	530480	NSJNCA11
786625	100292272	West	CA	Chico	530493	QNCYCA12
786635	100291825	West	CA	Chico	530493	QNCYCA12

786651	100291646	West	CA	Auburn	530480	NSJNCA11
786652	100291645	West	CA	Auburn	530480	NSJNCA11
786671	100291416	West	CA	Auburn	530475	NVCYCA11
786672	100291411	West	CA	Auburn	530475	NVCYCA11
786677	100291401	West	CA	Auburn	530475	NVCYCA11
786681	100291796	West	CA	Chico	530492	PTOLCA01
786682	100291793	West	CA	Chico	530492	PTOLCA01
786683	100291384	West	CA	Auburn	530475	NVCYCA11
786684	100291378	West	CA	Auburn	530475	NVCYCA11
786692	100291806	West	CA	Chico	530493	QNCYCA12
786708	100291625	West	CA	Auburn	530480	NSJNCA11
786710	100291461	West	CA	Auburn	530475	NVCYCA11
786711	100291456	West	CA	Auburn	530475	NVCYCA11
795430	100297462	West	CA	Chico	530493	QNCYCA12
800852	100301553	West	CA	Chico	530471	LLTNCA11
803580	100304388	West	CA	Chico	530493	QNCYCA12
804584	100305316	West	CA	Chico	530493	QNCYCA12
804585	100305313	West	CA	Chico	530493	QNCYCA12
816326	100313252	West	CA	Chico	530493	QNCYCA12
816327	100313222	West	CA	Chico	530471	LLTNCA11
819648	100316381	West	CA		530437	CHLNCA11
826485	100318590	West	CA	Auburn	530515	TRUCCA11
840815	100332304	West	CA	Chico	530433	BLRSCA12
851315	100339416	West	CA	Chico	530493	QNCYCA12
854159	100341968	West	CA	Chico	530493	QNCYCA12
854267		West	California	Auburn	530459	GRVYCA01
856763		West	California	Auburn	530475	NVCYCA11
857730		West	California	Auburn	530535	GRVYCA12
857844		West	California	Auburn	530475	NVCYCA11
858139		West	California	Auburn	530475	NVCYCA11
859519		West	California	Auburn	530475	NVCYCA11
869254		West	California	Auburn	530447	DTFLCA11
869609	100352430	West	CA	Chico	530471	LLTNCA11
870436	100353334	West	CA	Chico	530471	LLTNCA11
871390		West	California	Auburn	530447	DTFLCA11
872128		West	California	Chico	530433	BLRSCA12
872129		West	California	Chico	530433	BLRSCA12
872131		West	California	Chico	530433	BLRSCA12
872133		West	California	Chico	530433	BLRSCA12
872134		West	California	Chico	530433	BLRSCA12
911241	100384169	West	CA	Chico	530433	BLRSCA12
911242	100384135	West	CA	Chico	530433	BLRSCA12
911243	100384133	West	CA	Chico	530433	BLRSCA12
911244	100384117	West	CA	Chico	530433	BLRSCA12

911245	100384116	West	CA	Chico	530433	BLRSCA12
911246	100384114	West	CA	Chico	530433	BLRSCA12
911247	100384201	West	CA	Chico	530433	BLRSCA12
911248	100384200	West	CA	Chico	530433	BLRSCA12
911249	100384198	West	CA	Chico	530433	BLRSCA12
911250	100384195	West	CA	Chico	530433	BLRSCA12
911251	100384185	West	CA	Chico	530433	BLRSCA12
911252	100384182	West	CA	Chico	530433	BLRSCA12
911253	100384178	West	CA	Chico	530433	BLRSCA12
911254	100384176	West	CA	Chico	530433	BLRSCA12
911267	100384148	West	CA	Chico	530433	BLRSCA12
911268	100384132	West	CA	Chico	530433	BLRSCA12
911269	100384125	West	CA	Chico	530433	BLRSCA12
911270	100384206	West	CA	Chico	530433	BLRSCA12
911271	100384191	West	CA	Chico	530433	BLRSCA12
911272	100384180	West	CA	Chico	530433	BLRSCA12
911382	100384126	West	CA	Chico	530433	BLRSCA12
911383	100384124	West	CA	Chico	530433	BLRSCA12
911388	100384205	West	CA	Chico	530433	BLRSCA12
916490		West	California		530437	CHLNCA11
916491		West	California		530437	CHLNCA11
917508		West	California		530437	CHLNCA11
919502	100391818	West	CA	Auburn	530480	NSJNCA11
919503	100391873	West	CA	Auburn	530480	NSJNCA11
919505	100391783	West	CA	Auburn	530480	NSJNCA11
919506	100391782	West	CA	Auburn	530480	NSJNCA11
919546	100391779	West	CA	Auburn	530480	NSJNCA11
919549	100391775	West	CA	Auburn	530480	NSJNCA11
919639	100391811	West	CA	Auburn	530480	NSJNCA11
919640	100391810	West	CA	Auburn	530480	NSJNCA11
919643	100391794	West	CA	Auburn	530480	NSJNCA11
919647	100391859	West	CA	Auburn	530480	NSJNCA11
919651	100391785	West	CA	Auburn	530480	NSJNCA11
919653	100391774	West	CA	Auburn	530480	NSJNCA11
919659	100391832	West	CA	Auburn	530480	NSJNCA11
919660	100391773	West	CA	Auburn	530480	NSJNCA11
919663	100391764	West	CA	Auburn	530480	NSJNCA11
919666	100391758	West	CA	Auburn	530480	NSJNCA11
919667	100391754	West	CA	Auburn	530480	NSJNCA11
919668	100391745	West	CA	Auburn	530480	NSJNCA11
919672	100391913	West	CA	Auburn	530480	NSJNCA11
919679	100391895	West	CA	Auburn	530480	NSJNCA11
919681	100391892	West	CA	Auburn	530480	NSJNCA11
919690	100391729	West	CA	Auburn	530480	NSJNCA11

919694	100391824	West	CA	Auburn	530480	NSJNCA11
919716	100391938	West	CA	Auburn	530480	NSJNCA11
922739	100394842	West	CA	Auburn	530475	NVCYCA11
922744	100394756	West	CA	Auburn	530475	NVCYCA11
922767	100394780	West	CA	Auburn	530475	NVCYCA11
922771	100394784	West	CA	Auburn	530475	NVCYCA11
922773	100394786	West	CA	Auburn	530475	NVCYCA11
922797	100394897	West	CA	Auburn	530475	NVCYCA11
922838	100394891	West	CA	Auburn	530475	NVCYCA11
922842	100394895	West	CA	Auburn	530475	NVCYCA11
922864	100394848	West	CA	Auburn	530475	NVCYCA11
922873	100394857	West	CA	Auburn	530475	NVCYCA11
922880	100394660	West	CA	Chico	530433	BLRSCA12
922886	100394721	West	CA	Auburn	530475	NVCYCA11
922904	100394739	West	CA	Auburn	530475	NVCYCA11
922924	100394815	West	CA	Auburn	530475	NVCYCA11
924674	100395434	West	CA	Auburn	530475	NVCYCA11
924682	100395442	West	CA	Auburn	530475	NVCYCA11
924691	100395028	West	CA	Auburn	530475	NVCYCA11
924805	100395368	West	CA	Auburn	530475	NVCYCA11
924816	100395487	West	CA	Auburn	530475	NVCYCA11
924881	100395523	West	CA	Auburn	530475	NVCYCA11
924899	100395688	West	CA	Auburn	530475	NVCYCA11
924925	100395492	West	CA	Auburn	530475	NVCYCA11
924962	100394988	West	CA	Auburn	530475	NVCYCA11
924968	100394994	West	CA	Auburn	530475	NVCYCA11
924971	100394997	West	CA	Auburn	530475	NVCYCA11
924992	100395594	West	CA	Auburn	530475	NVCYCA11
925036	100395705	West	CA	Auburn	530475	NVCYCA11
925059	100394925	West	CA	Auburn	530475	NVCYCA11
925065	100395166	West	CA	Auburn	530475	NVCYCA11
925223	100395637	West	CA	Auburn	530475	NVCYCA11
925260	100395052	West	CA	Auburn	530475	NVCYCA11
925261	100395053	West	CA	Auburn	530475	NVCYCA11
925262	100395054	West	CA	Auburn	530475	NVCYCA11
925269	100395061	West	CA	Auburn	530475	NVCYCA11
925286	100395079	West	CA	Auburn	530475	NVCYCA11
925360	100395237	West	CA	Auburn	530475	NVCYCA11
925390	100395246	West	CA	Auburn	530475	NVCYCA11
925394	100395250	West	CA	Auburn	530475	NVCYCA11
925413	100394968	West	CA	Auburn	530475	NVCYCA11
925419	100394974	West	CA	Auburn	530475	NVCYCA11
925420	100394975	West	CA	Auburn	530475	NVCYCA11
925425	100394980	West	CA	Auburn	530475	NVCYCA11

925426	100394981	West	CA	Auburn	530475	NVCYCA11
925713	100395858	West	CA	Auburn	530475	NVCYCA11
925890	100396028	West	CA	Auburn	530475	NVCYCA11
925894	100396032	West	CA	Auburn	530475	NVCYCA11
925895	100396033	West	CA	Auburn	530475	NVCYCA11
925904	100396203	West	CA	Auburn	530475	NVCYCA11
926070	100395786	West	CA	Auburn	530475	NVCYCA11
926072	100395788	West	CA	Auburn	530475	NVCYCA11
926085	100395875	West	CA	Auburn	530475	NVCYCA11
926090	100395880	West	CA	Auburn	530475	NVCYCA11
926091	100395881	West	CA	Auburn	530475	NVCYCA11
926098	100396210	West	CA	Auburn	530475	NVCYCA11
926424	100395800	West	CA	Auburn	530475	NVCYCA11
926429	100395805	West	CA	Auburn	530475	NVCYCA11
926466	100396258	West	CA	Auburn	530475	NVCYCA11
926627	100395814	West	CA	Auburn	530475	NVCYCA11
926628	100395815	West	CA	Auburn	530475	NVCYCA11
926641	100395902	West	CA	Auburn	530475	NVCYCA11
926839	100395831	West	CA	Auburn	530475	NVCYCA11
926840	100395832	West	CA	Auburn	530475	NVCYCA11
926846	100395838	West	CA	Auburn	530475	NVCYCA11
927277	100396057	West	CA	Auburn	530475	NVCYCA11
927686	100396178	West	CA	Auburn	530475	NVCYCA11
927856	100395962	West	CA	Auburn	530475	NVCYCA11
927857	100396101	West	CA	Auburn	530475	NVCYCA11
927863	100396107	West	CA	Auburn	530475	NVCYCA11
927865	100396109	West	CA	Auburn	530475	NVCYCA11
927878	100396195	West	CA	Auburn	530475	NVCYCA11
927921	100398720	West	CA	Chico	530433	BLRSCA12
928039	100395965	West	CA	Auburn	530475	NVCYCA11
928041	100395967	West	CA	Auburn	530475	NVCYCA11
928046	100395972	West	CA	Auburn	530475	NVCYCA11
928053	100395994	West	CA	Auburn	530475	NVCYCA11
928059	100396000	West	CA	Auburn	530475	NVCYCA11
928239	100395843	West	CA	Auburn	530475	NVCYCA11
928241	100395845	West	CA	Auburn	530475	NVCYCA11
937990	100403352	West	CA	Auburn	530535	GRVYCA12
938016	100403299	West	CA	Auburn	530535	GRVYCA12
938024	100403307	West	CA	Auburn	530535	GRVYCA12
938026	100403309	West	CA	Auburn	530535	GRVYCA12
938101	100403423	West	CA	Auburn	530535	GRVYCA12
938105	100403160	West	CA	Chico	530492	PTOLCA01
938191	100403402	West	CA	Auburn	530535	GRVYCA12
938224	100403272	West	CA	Auburn	530535	GRVYCA12

938254	100403530	West	CA	Auburn	530535	GRVYCA12
938258	100403439	West	CA	Auburn	530535	GRVYCA12
940926	100405641	West	CA	Auburn	530535	GRVYCA12
940950	100405622	West	CA	Auburn	530535	GRVYCA12
940951	100405623	West	CA	Auburn	530535	GRVYCA12
945859	100410178	West	CA	Auburn	530515	TRUCCA11
945862	100410072	West	CA	Auburn	530515	TRUCCA11
945863	100410170	West	CA	Auburn	530515	TRUCCA11
945864	100410168	West	CA	Auburn	530515	TRUCCA11
945865	100410195	West	CA	Auburn	530515	TRUCCA11
945866	100410102	West	CA	Auburn	530515	TRUCCA11
945867	100410095	West	CA	Auburn	530515	TRUCCA11
945873	100410152	West	CA	Auburn	530515	TRUCCA11
945874	100410209	West	CA	Auburn	530515	TRUCCA11
945875	100410141	West	CA	Auburn	530515	TRUCCA11
945876	100410120	West	CA	Auburn	530515	TRUCCA11
945877	100410106	West	CA	Auburn	530515	TRUCCA11
945880	100410096	West	CA	Auburn	530515	TRUCCA11
945899	100410084	West	CA	Auburn	530515	TRUCCA11
945900	100410080	West	CA	Auburn	530515	TRUCCA11
945901	100410213	West	CA	Auburn	530515	TRUCCA11
945902	100410140	West	CA	Auburn	530515	TRUCCA11
945903	100410099	West	CA	Auburn	530515	TRUCCA11
945933	100410181	West	CA	Auburn	530515	TRUCCA11
945934	100410180	West	CA	Auburn	530515	TRUCCA11
945935	100410179	West	CA	Auburn	530515	TRUCCA11
945936	100410176	West	CA	Auburn	530515	TRUCCA11
945937	100410174	West	CA	Auburn	530515	TRUCCA11
945938	100410169	West	CA	Auburn	530515	TRUCCA11
945939	100410163	West	CA	Auburn	530515	TRUCCA11
945940	100410162	West	CA	Auburn	530515	TRUCCA11
945941	100410146	West	CA	Auburn	530515	TRUCCA11
945942	100410143	West	CA	Auburn	530515	TRUCCA11
945944	100410138	West	CA	Auburn	530515	TRUCCA11
945945	100410136	West	CA	Auburn	530515	TRUCCA11
945946	100410131	West	CA	Auburn	530515	TRUCCA11
945947	100410128	West	CA	Auburn	530515	TRUCCA11
945948	100410185	West	CA	Auburn	530515	TRUCCA11
945949	100410191	West	CA	Auburn	530515	TRUCCA11
945950	100410175	West	CA	Auburn	530515	TRUCCA11
947007	100411778	West	CA	Auburn	530515	TRUCCA11
947012	100411783	West	CA	Auburn	530515	TRUCCA11
947014	100411784	West	CA	Auburn	530515	TRUCCA11
947015	100411785	West	CA	Auburn	530515	TRUCCA11

947020	100411790	West	CA	Auburn	530515	TRUCCA11
947022	100411792	West	CA	Auburn	530515	TRUCCA11
947024	100411794	West	CA	Auburn	530515	TRUCCA11
947031	100411663	West	CA	Auburn	530515	TRUCCA11
947035	100411666	West	CA	Auburn	530515	TRUCCA11
947036	100411667	West	CA	Auburn	530515	TRUCCA11
947040	100411671	West	CA	Auburn	530515	TRUCCA11
947048	100411679	West	CA	Auburn	530515	TRUCCA11
947056	100411686	West	CA	Auburn	530515	TRUCCA11
947057	100411687	West	CA	Auburn	530515	TRUCCA11
947071	100411796	West	CA	Auburn	530515	TRUCCA11
947072	100411797	West	CA	Auburn	530515	TRUCCA11
947077	100411802	West	CA	Auburn	530515	TRUCCA11
947086	100411810	West	CA	Auburn	530515	TRUCCA11
947087	100411811	West	CA	Auburn	530515	TRUCCA11
947092	100411816	West	CA	Auburn	530515	TRUCCA11
947097	100411821	West	CA	Auburn	530515	TRUCCA11
947102	100411826	West	CA	Auburn	530515	TRUCCA11
947111	100411242	West	CA	Auburn	530515	TRUCCA11
947113	100411244	West	CA	Auburn	530515	TRUCCA11
947119	100411250	West	CA	Auburn	530515	TRUCCA11
947120	100411251	West	CA	Auburn	530515	TRUCCA11
947126	100411524	West	CA	Auburn	530515	TRUCCA11
947137	100411535	West	CA	Auburn	530515	TRUCCA11
947142	100411158	West	CA	Auburn	530515	TRUCCA11
947143	100411159	West	CA	Auburn	530515	TRUCCA11
947154	100411170	West	CA	Auburn	530515	TRUCCA11
947161	100411256	West	CA	Auburn	530515	TRUCCA11
947204	100411184	West	CA	Auburn	530515	TRUCCA11
947206	100411186	West	CA	Auburn	530515	TRUCCA11
947210	100411190	West	CA	Auburn	530515	TRUCCA11
947215	100411274	West	CA	Auburn	530515	TRUCCA11
947218	100411277	West	CA	Auburn	530515	TRUCCA11
947219	100411278	West	CA	Auburn	530515	TRUCCA11
947252	100411198	West	CA	Auburn	530515	TRUCCA11
947254	100411061	West	CA	Auburn	530515	TRUCCA11
947256	100411063	West	CA	Auburn	530515	TRUCCA11
947269	100411411	West	CA	Auburn	530515	TRUCCA11
947271	100411413	West	CA	Auburn	530515	TRUCCA11
947274	100411416	West	CA	Auburn	530515	TRUCCA11
947279	100411421	West	CA	Auburn	530515	TRUCCA11
947283	100411713	West	CA	Auburn	530515	TRUCCA11
947286	100411716	West	CA	Auburn	530515	TRUCCA11
947287	100411717	West	CA	Auburn	530515	TRUCCA11

947288	100411718	West	CA	Auburn	530515	TRUCCA11
947302	100411075	West	CA	Auburn	530515	TRUCCA11
947310	100411083	West	CA	Auburn	530515	TRUCCA11
947318	100411425	West	CA	Auburn	530515	TRUCCA11
947319	100411426	West	CA	Auburn	530515	TRUCCA11
947361	100411098	West	CA	Auburn	530515	TRUCCA11
947365	100411283	West	CA	Auburn	530515	TRUCCA11
947372	100411443	West	CA	Auburn	530515	TRUCCA11
947374	100411445	West	CA	Auburn	530515	TRUCCA11
947375	100411446	West	CA	Auburn	530515	TRUCCA11
947378	100411449	West	CA	Auburn	530515	TRUCCA11
947379	100411450	West	CA	Auburn	530515	TRUCCA11
947381	100411452	West	CA	Auburn	530515	TRUCCA11
947382	100411453	West	CA	Auburn	530515	TRUCCA11
947383	100411454	West	CA	Auburn	530515	TRUCCA11
947385	100411456	West	CA	Auburn	530515	TRUCCA11
947428	100411696	West	CA	Auburn	530515	TRUCCA11
947429	100411697	West	CA	Auburn	530515	TRUCCA11
947437	100411705	West	CA	Auburn	530515	TRUCCA11
947447	100411027	West	CA	Auburn	530515	TRUCCA11
947457	100411480	West	CA	Auburn	530515	TRUCCA11
947474	100411497	West	CA	Auburn	530515	TRUCCA11
947480	100411042	West	CA	Auburn	530515	TRUCCA11
947483	100411045	West	CA	Auburn	530515	TRUCCA11
947493	100411362	West	CA	Auburn	530515	TRUCCA11
947494	100411363	West	CA	Auburn	530515	TRUCCA11
947513	100411058	West	CA	Auburn	530515	TRUCCA11
947514	100411059	West	CA	Auburn	530515	TRUCCA11
947518	100410903	West	CA	Auburn	530515	TRUCCA11
947525	100410910	West	CA	Auburn	530515	TRUCCA11
947526	100410911	West	CA	Auburn	530515	TRUCCA11
947527	100410912	West	CA	Auburn	530515	TRUCCA11
947532	100411383	West	CA	Auburn	530515	TRUCCA11
947534	100411385	West	CA	Auburn	530515	TRUCCA11
947538	100411389	West	CA	Auburn	530515	TRUCCA11
947543	100411394	West	CA	Auburn	530515	TRUCCA11
947545	100411396	West	CA	Auburn	530515	TRUCCA11
947548	100410915	West	CA	Auburn	530515	TRUCCA11
947551	100410918	West	CA	Auburn	530515	TRUCCA11
947552	100410919	West	CA	Auburn	530515	TRUCCA11
947553	100410920	West	CA	Auburn	530515	TRUCCA11
947555	100410922	West	CA	Auburn	530515	TRUCCA11
947556	100410923	West	CA	Auburn	530515	TRUCCA11
947575	100411584	West	CA	Auburn	530515	TRUCCA11

947581	100411590	West	CA	Auburn	530515	TRUCCA11
947583	100410932	West	CA	Auburn	530515	TRUCCA11
947586	100410935	West	CA	Auburn	530515	TRUCCA11
947592	100410941	West	CA	Auburn	530515	TRUCCA11
947596	100410945	West	CA	Auburn	530515	TRUCCA11
947644	100410957	West	CA	Auburn	530515	TRUCCA11
947645	100410958	West	CA	Auburn	530515	TRUCCA11
947668	100411323	West	CA	Auburn	530515	TRUCCA11
947669	100411324	West	CA	Auburn	530515	TRUCCA11
947673	100411610	West	CA	Auburn	530515	TRUCCA11
947708	100411327	West	CA	Auburn	530515	TRUCCA11
947718	100411337	West	CA	Auburn	530515	TRUCCA11
947726	100411627	West	CA	Auburn	530515	TRUCCA11
947727	100411628	West	CA	Auburn	530515	TRUCCA11
947732	100411633	West	CA	Auburn	530515	TRUCCA11
947741	100411642	West	CA	Auburn	530515	TRUCCA11
947743	100411644	West	CA	Auburn	530515	TRUCCA11
947747	100411107	West	CA	Auburn	530515	TRUCCA11
947749	100411109	West	CA	Auburn	530515	TRUCCA11
947750	100411110	West	CA	Auburn	530515	TRUCCA11
947751	100411111	West	CA	Auburn	530515	TRUCCA11
947758	100411118	West	CA	Auburn	530515	TRUCCA11
947761	100411121	West	CA	Auburn	530515	TRUCCA11
947766	100411349	West	CA	Auburn	530515	TRUCCA11
947771	100411354	West	CA	Auburn	530515	TRUCCA11
947782	100411647	West	CA	Auburn	530515	TRUCCA11
947790	100411655	West	CA	Auburn	530515	TRUCCA11
947796	100411502	West	CA	Auburn	530515	TRUCCA11
947802	100411126	West	CA	Auburn	530515	TRUCCA11
947810	100411134	West	CA	Auburn	530515	TRUCCA11
947824	100411209	West	CA	Auburn	530515	TRUCCA11
947828	100411213	West	CA	Auburn	530515	TRUCCA11
947830	100411215	West	CA	Auburn	530515	TRUCCA11
947832	100411217	West	CA	Auburn	530515	TRUCCA11
947853	100411141	West	CA	Auburn	530515	TRUCCA11
947862	100411150	West	CA	Auburn	530515	TRUCCA11
947867	100411155	West	CA	Auburn	530515	TRUCCA11
947882	100411231	West	CA	Auburn	530515	TRUCCA11
947891	100410394	West	CA	Auburn	530515	TRUCCA11
947892	100410395	West	CA	Auburn	530515	TRUCCA11
947897	100410400	West	CA	Auburn	530515	TRUCCA11
947898	100410401	West	CA	Auburn	530515	TRUCCA11
947900	100410403	West	CA	Auburn	530515	TRUCCA11
947908	100410411	West	CA	Auburn	530515	TRUCCA11

947910	100410413	West	CA	Auburn	530515	TRUCCA11
947916	100410419	West	CA	Auburn	530515	TRUCCA11
947917	100410420	West	CA	Auburn	530515	TRUCCA11
947918	100410421	West	CA	Auburn	530515	TRUCCA11
947921	100410424	West	CA	Auburn	530515	TRUCCA11
947922	100410425	West	CA	Auburn	530515	TRUCCA11
947923	100410426	West	CA	Auburn	530515	TRUCCA11
947926	100410463	West	CA	Auburn	530515	TRUCCA11
947927	100410464	West	CA	Auburn	530515	TRUCCA11
947935	100410472	West	CA	Auburn	530515	TRUCCA11
947936	100410317	West	CA	Auburn	530515	TRUCCA11
947939	100410320	West	CA	Auburn	530515	TRUCCA11
947940	100410321	West	CA	Auburn	530515	TRUCCA11
947944	100410377	West	CA	Auburn	530515	TRUCCA11
947952	100410385	West	CA	Auburn	530515	TRUCCA11
947954	100410387	West	CA	Auburn	530515	TRUCCA11
947976	100410674	West	CA	Auburn	530515	TRUCCA11
947978	100410676	West	CA	Auburn	530515	TRUCCA11
947994	100410298	West	CA	Auburn	530515	TRUCCA11
947995	100410299	West	CA	Auburn	530515	TRUCCA11
947997	100410301	West	CA	Auburn	530515	TRUCCA11
948001	100410305	West	CA	Auburn	530515	TRUCCA11
948007	100410311	West	CA	Auburn	530515	TRUCCA11
948020	100410333	West	CA	Auburn	530515	TRUCCA11
948026	100410391	West	CA	Auburn	530515	TRUCCA11
948031	100410515	West	CA	Auburn	530515	TRUCCA11
948033	100410517	West	CA	Auburn	530515	TRUCCA11
948034	100410518	West	CA	Auburn	530515	TRUCCA11
948042	100410526	West	CA	Auburn	530515	TRUCCA11
948044	100410581	West	CA	Auburn	530515	TRUCCA11
948048	100410585	West	CA	Auburn	530515	TRUCCA11
948051	100410588	West	CA	Auburn	530515	TRUCCA11
948052	100410589	West	CA	Auburn	530515	TRUCCA11
948054	100410591	West	CA	Auburn	530515	TRUCCA11
948058	100410595	West	CA	Auburn	530515	TRUCCA11
948063	100410811	West	CA	Auburn	530515	TRUCCA11
948077	100410825	West	CA	Auburn	530515	TRUCCA11
948078	100410826	West	CA	Auburn	530515	TRUCCA11
948081	100410829	West	CA	Auburn	530515	TRUCCA11
948082	100410830	West	CA	Auburn	530515	TRUCCA11
948090	100410838	West	CA	Auburn	530515	TRUCCA11
948100	100410431	West	CA	Auburn	530515	TRUCCA11
948107	100410438	West	CA	Auburn	530515	TRUCCA11
948109	100410440	West	CA	Auburn	530515	TRUCCA11

948111	100410442	West	CA	Auburn	530515	TRUCCA11
948113	100410444	West	CA	Auburn	530515	TRUCCA11
948114	100410528	West	CA	Auburn	530515	TRUCCA11
948115	100410529	West	CA	Auburn	530515	TRUCCA11
948116	100410530	West	CA	Auburn	530515	TRUCCA11
948118	100410532	West	CA	Auburn	530515	TRUCCA11
948119	100410533	West	CA	Auburn	530515	TRUCCA11
948120	100410534	West	CA	Auburn	530515	TRUCCA11
948121	100410535	West	CA	Auburn	530515	TRUCCA11
948122	100410536	West	CA	Auburn	530515	TRUCCA11
948123	100410537	West	CA	Auburn	530515	TRUCCA11
948129	100410543	West	CA	Auburn	530515	TRUCCA11
948133	100410599	West	CA	Auburn	530515	TRUCCA11
948138	100410604	West	CA	Auburn	530515	TRUCCA11
948139	100410605	West	CA	Auburn	530515	TRUCCA11
948141	100410607	West	CA	Auburn	530515	TRUCCA11
948145	100410474	West	CA	Auburn	530515	TRUCCA11
948146	100410475	West	CA	Auburn	530515	TRUCCA11
948147	100410476	West	CA	Auburn	530515	TRUCCA11
948148	100410477	West	CA	Auburn	530515	TRUCCA11
948149	100410478	West	CA	Auburn	530515	TRUCCA11
948151	100410710	West	CA	Auburn	530515	TRUCCA11
948153	100410712	West	CA	Auburn	530515	TRUCCA11
948155	100410714	West	CA	Auburn	530515	TRUCCA11
948157	100410716	West	CA	Auburn	530515	TRUCCA11
948160	100410719	West	CA	Auburn	530515	TRUCCA11
948161	100410720	West	CA	Auburn	530515	TRUCCA11
948165	100410724	West	CA	Auburn	530515	TRUCCA11
948180	100410856	West	CA	Auburn	530515	TRUCCA11
948183	100410859	West	CA	Auburn	530515	TRUCCA11
948187	100410246	West	CA	Auburn	530515	TRUCCA11
948190	100410249	West	CA	Auburn	530515	TRUCCA11
948195	100410254	West	CA	Auburn	530515	TRUCCA11
948196	100410255	West	CA	Auburn	530515	TRUCCA11
948197	100410256	West	CA	Auburn	530515	TRUCCA11
948198	100410257	West	CA	Auburn	530515	TRUCCA11
948199	100410258	West	CA	Auburn	530515	TRUCCA11
948200	100410259	West	CA	Auburn	530515	TRUCCA11
948201	100410260	West	CA	Auburn	530515	TRUCCA11
948202	100410261	West	CA	Auburn	530515	TRUCCA11
948203	100410445	West	CA	Auburn	530515	TRUCCA11
948204	100410446	West	CA	Auburn	530515	TRUCCA11
948207	100410449	West	CA	Auburn	530515	TRUCCA11
948209	100410451	West	CA	Auburn	530515	TRUCCA11

948218	100410460	West	CA	Auburn	530515	TRUCCA11
948221	100410342	West	CA	Auburn	530515	TRUCCA11
948223	100410344	West	CA	Auburn	530515	TRUCCA11
948224	100410345	West	CA	Auburn	530515	TRUCCA11
948225	100410346	West	CA	Auburn	530515	TRUCCA11
948226	100410347	West	CA	Auburn	530515	TRUCCA11
948228	100410349	West	CA	Auburn	530515	TRUCCA11
948229	100410350	West	CA	Auburn	530515	TRUCCA11
948230	100410351	West	CA	Auburn	530515	TRUCCA11
948232	100410353	West	CA	Auburn	530515	TRUCCA11
948234	100410355	West	CA	Auburn	530515	TRUCCA11
948236	100410479	West	CA	Auburn	530515	TRUCCA11
948237	100410480	West	CA	Auburn	530515	TRUCCA11
948240	100410483	West	CA	Auburn	530515	TRUCCA11
948241	100410484	West	CA	Auburn	530515	TRUCCA11
948242	100410485	West	CA	Auburn	530515	TRUCCA11
948244	100410487	West	CA	Auburn	530515	TRUCCA11
948247	100410490	West	CA	Auburn	530515	TRUCCA11
948258	100410731	West	CA	Auburn	530515	TRUCCA11
948267	100410740	West	CA	Auburn	530515	TRUCCA11
948268	100410741	West	CA	Auburn	530515	TRUCCA11
948271	100410861	West	CA	Auburn	530515	TRUCCA11
948291	100410284	West	CA	Auburn	530515	TRUCCA11
948293	100410286	West	CA	Auburn	530515	TRUCCA11
948298	100410291	West	CA	Auburn	530515	TRUCCA11
948300	100410293	West	CA	Auburn	530515	TRUCCA11
948301	100410294	West	CA	Auburn	530515	TRUCCA11
948303	100410297	West	CA	Auburn	530515	TRUCCA11
948305	100410358	West	CA	Auburn	530515	TRUCCA11
948308	100410361	West	CA	Auburn	530515	TRUCCA11
948309	100410362	West	CA	Auburn	530515	TRUCCA11
948310	100410363	West	CA	Auburn	530515	TRUCCA11
948320	100410373	West	CA	Auburn	530515	TRUCCA11
948323	100410548	West	CA	Auburn	530515	TRUCCA11
948324	100410549	West	CA	Auburn	530515	TRUCCA11
948325	100410550	West	CA	Auburn	530515	TRUCCA11
948326	100410551	West	CA	Auburn	530515	TRUCCA11
948327	100410552	West	CA	Auburn	530515	TRUCCA11
948330	100410555	West	CA	Auburn	530515	TRUCCA11
948333	100410558	West	CA	Auburn	530515	TRUCCA11
948336	100410561	West	CA	Auburn	530515	TRUCCA11
948337	100410562	West	CA	Auburn	530515	TRUCCA11
948338	100410563	West	CA	Auburn	530515	TRUCCA11
948345	100410750	West	CA	Auburn	530515	TRUCCA11

948354	100410759	West	CA	Auburn	530515	TRUCCA11
948358	100410879	West	CA	Auburn	530515	TRUCCA11
948364	100410885	West	CA	Auburn	530515	TRUCCA11
948368	100410889	West	CA	Auburn	530515	TRUCCA11
948369	100410890	West	CA	Auburn	530515	TRUCCA11
948372	100410893	West	CA	Auburn	530515	TRUCCA11
948374	100410895	West	CA	Auburn	530515	TRUCCA11
948377	100410898	West	CA	Auburn	530515	TRUCCA11
948378	100410899	West	CA	Auburn	530515	TRUCCA11
948385	100410771	West	CA	Auburn	530515	TRUCCA11
948392	100410565	West	CA	Auburn	530515	TRUCCA11
948394	100410567	West	CA	Auburn	530515	TRUCCA11
948397	100410570	West	CA	Auburn	530515	TRUCCA11
948398	100410571	West	CA	Auburn	530515	TRUCCA11
948403	100410576	West	CA	Auburn	530515	TRUCCA11
948416	100410505	West	CA	Auburn	530515	TRUCCA11
948417	100410506	West	CA	Auburn	530515	TRUCCA11
948419	100410508	West	CA	Auburn	530515	TRUCCA11
948420	100410509	West	CA	Auburn	530515	TRUCCA11
948423	100410688	West	CA	Auburn	530515	TRUCCA11
948432	100410783	West	CA	Auburn	530515	TRUCCA11
948437	100410788	West	CA	Auburn	530515	TRUCCA11
948439	100410790	West	CA	Auburn	530515	TRUCCA11
948453	100410804	West	CA	Auburn	530515	TRUCCA11
948462	100410219	West	CA	Auburn	530515	TRUCCA11
948463	100410220	West	CA	Auburn	530515	TRUCCA11
948483	100410705	West	CA	Auburn	530515	TRUCCA11
948503	100410621	West	CA	Auburn	530515	TRUCCA11
948515	100410999	West	CA	Auburn	530515	TRUCCA11
948516	100411000	West	CA	Auburn	530515	TRUCCA11
948517	100411001	West	CA	Auburn	530515	TRUCCA11
948530	100410665	West	CA	Auburn	530515	TRUCCA11
948535	100410670	West	CA	Auburn	530515	TRUCCA11
948536	100410671	West	CA	Auburn	530515	TRUCCA11
948548	100410235	West	CA	Auburn	530515	TRUCCA11
948553	100410240	West	CA	Auburn	530515	TRUCCA11
948557	100410262	West	CA	Auburn	530515	TRUCCA11
948558	100410263	West	CA	Auburn	530515	TRUCCA11
948562	100410267	West	CA	Auburn	530515	TRUCCA11
948563	100410268	West	CA	Auburn	530515	TRUCCA11
948573	100410278	West	CA	Auburn	530515	TRUCCA11
948588	100410635	West	CA	Auburn	530515	TRUCCA11
948590	100410637	West	CA	Auburn	530515	TRUCCA11
954624	100415519	West	CA	Chico	530433	BLRSCA12

955258	100415896	West	CA	Auburn	530444	DWNVCA11
955259	100415897	West	CA	Auburn	530444	DWNVCA11
955263	100415902	West	CA	Auburn	530444	DWNVCA11
955264	100415903	West	CA	Auburn	530444	DWNVCA11
955278	100415917	West	CA	Auburn	530444	DWNVCA11
955288	100415927	West	CA	Auburn	530444	DWNVCA11
955298	100415937	West	CA	Auburn	530444	DWNVCA11
955299	100415938	West	CA	Auburn	530444	DWNVCA11
955300	100415939	West	CA	Auburn	530444	DWNVCA11
955302	100415941	West	CA	Auburn	530444	DWNVCA11
955303	100415942	West	CA	Auburn	530444	DWNVCA11
955305	100415944	West	CA	Auburn	530444	DWNVCA11
955310	100415949	West	CA	Auburn	530444	DWNVCA11
955314	100415953	West	CA	Auburn	530444	DWNVCA11
955316	100415955	West	CA	Auburn	530444	DWNVCA11
955866	100416685	West	CA	Auburn	530505	SRCYCA11
955895	100416696	West	CA	Auburn	530505	SRCYCA11
956118	100416641	West	CA	Chico	530506	SRVLCA11
956122	100416645	West	CA	Chico	530506	SRVLCA11
956123	100416646	West	CA	Chico	530506	SRVLCA11
956160	100416666	West	CA	Auburn	530505	SRCYCA11
962088	100422336	West	CA	Auburn	530447	DTFLCA11
962090	100422338	West	CA	Auburn	530447	DTFLCA11
962094	100422342	West	CA	Auburn	530447	DTFLCA11
962095	100422343	West	CA	Auburn	530447	DTFLCA11
962109	100422545	West	CA	Auburn	530447	DTFLCA11
962127	100422356	West	CA	Auburn	530447	DTFLCA11
962136	100422273	West	CA	Auburn	530447	DTFLCA11
962155	100422274	West	CA	Auburn	530447	DTFLCA11
962157	100422276	West	CA	Auburn	530447	DTFLCA11
962162	100422281	West	CA	Auburn	530447	DTFLCA11
962171	100422578	West	CA	Auburn	530447	DTFLCA11
962177	100422584	West	CA	Auburn	530447	DTFLCA11
962190	100422292	West	CA	Auburn	530447	DTFLCA11
962197	100422299	West	CA	Auburn	530447	DTFLCA11
962206	100422596	West	CA	Auburn	530447	DTFLCA11
962207	100422597	West	CA	Auburn	530447	DTFLCA11
962214	100422604	West	CA	Auburn	530447	DTFLCA11
962240	100422381	West	CA	Auburn	530447	DTFLCA11
962241	100422614	West	CA	Auburn	530447	DTFLCA11
962242	100422615	West	CA	Auburn	530447	DTFLCA11
962247	100422620	West	CA	Auburn	530447	DTFLCA11
962260	100422383	West	CA	Auburn	530447	DTFLCA11
962282	100422676	West	CA	Auburn	530447	DTFLCA11

962283	100422677	West	CA	Auburn	530447	DTFLCA11
962288	100422682	West	CA	Auburn	530447	DTFLCA11
962297	100422500	West	CA	Auburn	530447	DTFLCA11
962305	100422508	West	CA	Auburn	530447	DTFLCA11
962329	100422660	West	CA	Auburn	530447	DTFLCA11
962333	100422400	West	CA	Auburn	530447	DTFLCA11
962341	100422408	West	CA	Auburn	530447	DTFLCA11
962342	100422409	West	CA	Auburn	530447	DTFLCA11
962362	100422321	West	CA	Auburn	530447	DTFLCA11
962366	100422325	West	CA	Auburn	530447	DTFLCA11
962367	100422326	West	CA	Auburn	530447	DTFLCA11
962368	100422327	West	CA	Auburn	530447	DTFLCA11
962370	100422329	West	CA	Auburn	530447	DTFLCA11
962376	100422415	West	CA	Auburn	530447	DTFLCA11
962377	100422416	West	CA	Auburn	530447	DTFLCA11
962381	100422420	West	CA	Auburn	530447	DTFLCA11
962390	100422429	West	CA	Auburn	530447	DTFLCA11
962392	100422431	West	CA	Auburn	530447	DTFLCA11
962394	100422433	West	CA	Auburn	530447	DTFLCA11
962395	100422434	West	CA	Auburn	530447	DTFLCA11
962400	100422439	West	CA	Auburn	530447	DTFLCA11
962403	100422442	West	CA	Auburn	530447	DTFLCA11
962413	100422452	West	CA	Auburn	530447	DTFLCA11
962416	100422455	West	CA	Auburn	530447	DTFLCA11
962428	100422468	West	CA	Auburn	530447	DTFLCA11
962430	100422470	West	CA	Auburn	530447	DTFLCA11
962434	100422474	West	CA	Auburn	530447	DTFLCA11
962444	100422484	West	CA	Auburn	530447	DTFLCA11
962450	100422490	West	CA	Auburn	530447	DTFLCA11
962451	100422491	West	CA	Auburn	530447	DTFLCA11
962455	100422360	West	CA	Auburn	530447	DTFLCA11
962456	100422361	West	CA	Auburn	530447	DTFLCA11
962463	100422368	West	CA	Auburn	530447	DTFLCA11
962468	100422373	West	CA	Auburn	530447	DTFLCA11
962483	100422647	West	CA	Auburn	530447	DTFLCA11
962485	100422649	West	CA	Auburn	530447	DTFLCA11
962486	100422650	West	CA	Auburn	530447	DTFLCA11
962488	100422652	West	CA	Auburn	530447	DTFLCA11
962496	100422521	West	CA	Auburn	530447	DTFLCA11
962497	100422522	West	CA	Auburn	530447	DTFLCA11
962498	100422523	West	CA	Auburn	530447	DTFLCA11
962499	100422524	West	CA	Auburn	530447	DTFLCA11
962502	100422527	West	CA	Auburn	530447	DTFLCA11
962505	100422530	West	CA	Auburn	530447	DTFLCA11

962507	100422532	West	CA	Auburn	530447	DTFLCA11
962508	100422533	West	CA	Auburn	530447	DTFLCA11
962513	100422538	West	CA	Auburn	530447	DTFLCA11
970177	100430037	West	CA		530437	CHLNCA11
970184	100430044	West	CA		530437	CHLNCA11
970190	100430050	West	CA		530437	CHLNCA11
970192	100430052	West	CA		530437	CHLNCA11
970197	100430057	West	CA		530437	CHLNCA11
970200	100430060	West	CA		530437	CHLNCA11
970201	100430061	West	CA		530437	CHLNCA11
970205	100430065	West	CA		530437	CHLNCA11
970219	100430079	West	CA		530437	CHLNCA11
970225	100430085	West	CA		530437	CHLNCA11
970234	100430094	West	CA		530437	CHLNCA11
970235	100430095	West	CA		530437	CHLNCA11
970237	100430097	West	CA		530437	CHLNCA11
970244	100430104	West	CA		530437	CHLNCA11
970246	100430106	West	CA		530437	CHLNCA11
970251	100430111	West	CA		530437	CHLNCA11
970258	100430137	West	CA		530437	CHLNCA11
970262	100430141	West	CA		530437	CHLNCA11
970266	100430145	West	CA		530437	CHLNCA11
970269	100430148	West	CA		530437	CHLNCA11
970272	100430151	West	CA		530437	CHLNCA11
970276	100429930	West	CA		530437	CHLNCA11
970277	100429931	West	CA		530437	CHLNCA11
970282	100429936	West	CA		530437	CHLNCA11
970283	100430153	West	CA		530437	CHLNCA11
970284	100430154	West	CA		530437	CHLNCA11
970294	100430164	West	CA		530437	CHLNCA11
970296	100429937	West	CA		530437	CHLNCA11
970299	100429940	West	CA		530437	CHLNCA11
970305	100429946	West	CA		530437	CHLNCA11
970318	100429959	West	CA		530437	CHLNCA11
970338	100429979	West	CA		530437	CHLNCA11
970377	100429925	West	CA		530437	CHLNCA11
970379	100429927	West	CA		530437	CHLNCA11
970381	100430116	West	CA		530437	CHLNCA11
970382	100430117	West	CA		530437	CHLNCA11
970384	100430119	West	CA		530437	CHLNCA11
970392	100430127	West	CA		530437	CHLNCA11
970396	100430131	West	CA		530437	CHLNCA11
970397	100430132	West	CA		530437	CHLNCA11
970400	100429984	West	CA		530437	CHLNCA11

970406	100429990	West	CA		530437	CHLNCA11
970408	100429992	West	CA		530437	CHLNCA11
970416	100430001	West	CA		530437	CHLNCA11
970424	100430009	West	CA		530437	CHLNCA11
970429	100430014	West	CA		530437	CHLNCA11
970430	100430015	West	CA		530437	CHLNCA11
970439	100430024	West	CA		530437	CHLNCA11
970442	100430027	West	CA		530437	CHLNCA11
970443	100430028	West	CA		530437	CHLNCA11
984766	100438469	West	CA	Chico	530492	PTOLCA01
986067	100439990	West	CA	Auburn	530459	GRVYCA01
986072	100439995	West	CA	Auburn	530459	GRVYCA01
986073	100439996	West	CA	Auburn	530459	GRVYCA01
986077	100440000	West	CA	Auburn	530459	GRVYCA01
986081	100440269	West	CA	Auburn	530459	GRVYCA01
986082	100440270	West	CA	Auburn	530459	GRVYCA01
986087	100440275	West	CA	Auburn	530459	GRVYCA01
986100	100439396	West	CA	Auburn	530459	GRVYCA01
986106	100439402	West	CA	Auburn	530459	GRVYCA01
986109	100439405	West	CA	Auburn	530459	GRVYCA01
986121	100439728	West	CA	Auburn	530459	GRVYCA01
986122	100439729	West	CA	Auburn	530459	GRVYCA01
986123	100439730	West	CA	Auburn	530459	GRVYCA01
986125	100439732	West	CA	Auburn	530459	GRVYCA01
986126	100439733	West	CA	Auburn	530459	GRVYCA01
986129	100440003	West	CA	Auburn	530459	GRVYCA01
986130	100440004	West	CA	Auburn	530459	GRVYCA01
986142	100439885	West	CA	Auburn	530459	GRVYCA01
986150	100440289	West	CA	Auburn	530459	GRVYCA01
986162	100440164	West	CA	Auburn	530459	GRVYCA01
986173	100439568	West	CA	Auburn	530459	GRVYCA01
986185	100439607	West	CA	Auburn	530459	GRVYCA01
986186	100439608	West	CA	Auburn	530459	GRVYCA01
986199	100439889	West	CA	Auburn	530459	GRVYCA01
986201	100439891	West	CA	Auburn	530459	GRVYCA01
986205	100439895	West	CA	Auburn	530459	GRVYCA01
986208	100439898	West	CA	Auburn	530459	GRVYCA01
986209	100439899	West	CA	Auburn	530459	GRVYCA01
986213	100439903	West	CA	Auburn	530459	GRVYCA01
986217	100440167	West	CA	Auburn	530459	GRVYCA01
986218	100440168	West	CA	Auburn	530459	GRVYCA01
986220	100440170	West	CA	Auburn	530459	GRVYCA01
986221	100440171	West	CA	Auburn	530459	GRVYCA01
986224	100440174	West	CA	Auburn	530459	GRVYCA01

986225	100440175	West	CA	Auburn	530459	GRVYCA01
986227	100440177	West	CA	Auburn	530459	GRVYCA01
986234	100439577	West	CA	Auburn	530459	GRVYCA01
986235	100439578	West	CA	Auburn	530459	GRVYCA01
986236	100439579	West	CA	Auburn	530459	GRVYCA01
986237	100439580	West	CA	Auburn	530459	GRVYCA01
986238	100439581	West	CA	Auburn	530459	GRVYCA01
986242	100439585	West	CA	Auburn	530459	GRVYCA01
986246	100439589	West	CA	Auburn	530459	GRVYCA01
986271	100439908	West	CA	Auburn	530459	GRVYCA01
986272	100439909	West	CA	Auburn	530459	GRVYCA01
986274	100439911	West	CA	Auburn	530459	GRVYCA01
986285	100440183	West	CA	Auburn	530459	GRVYCA01
986287	100440185	West	CA	Auburn	530459	GRVYCA01
986293	100440191	West	CA	Auburn	530459	GRVYCA01
986294	100440192	West	CA	Auburn	530459	GRVYCA01
986295	100440193	West	CA	Auburn	530459	GRVYCA01
986299	100440197	West	CA	Auburn	530459	GRVYCA01
986300	100440198	West	CA	Auburn	530459	GRVYCA01
986309	100439601	West	CA	Auburn	530459	GRVYCA01
986313	100439452	West	CA	Auburn	530459	GRVYCA01
986315	100439454	West	CA	Auburn	530459	GRVYCA01
986318	100439457	West	CA	Auburn	530459	GRVYCA01
986330	100439648	West	CA	Auburn	530459	GRVYCA01
986344	100439930	West	CA	Auburn	530459	GRVYCA01
986345	100439931	West	CA	Auburn	530459	GRVYCA01
986347	100439933	West	CA	Auburn	530459	GRVYCA01
986348	100439934	West	CA	Auburn	530459	GRVYCA01
986349	100439935	West	CA	Auburn	530459	GRVYCA01
986353	100439939	West	CA	Auburn	530459	GRVYCA01
986358	100440205	West	CA	Auburn	530459	GRVYCA01
986363	100440210	West	CA	Auburn	530459	GRVYCA01
986366	100440213	West	CA	Auburn	530459	GRVYCA01
986369	100440216	West	CA	Auburn	530459	GRVYCA01
986379	100439465	West	CA	Auburn	530459	GRVYCA01
986380	100439466	West	CA	Auburn	530459	GRVYCA01
986381	100439467	West	CA	Auburn	530459	GRVYCA01
986383	100439469	West	CA	Auburn	530459	GRVYCA01
986384	100439470	West	CA	Auburn	530459	GRVYCA01
986386	100439472	West	CA	Auburn	530459	GRVYCA01
986396	100439661	West	CA	Auburn	530459	GRVYCA01
986401	100439666	West	CA	Auburn	530459	GRVYCA01
986419	100439953	West	CA	Auburn	530459	GRVYCA01
986421	100440123	West	CA	Auburn	530459	GRVYCA01

986425	100440221	West	CA	Auburn	530459	GRVYCA01
986428	100440224	West	CA	Auburn	530459	GRVYCA01
986441	100439475	West	CA	Auburn	530459	GRVYCA01
986449	100439484	West	CA	Auburn	530459	GRVYCA01
986473	100440125	West	CA	Auburn	530459	GRVYCA01
986474	100440126	West	CA	Auburn	530459	GRVYCA01
986478	100440130	West	CA	Auburn	530459	GRVYCA01
986479	100440131	West	CA	Auburn	530459	GRVYCA01
986481	100440133	West	CA	Auburn	530459	GRVYCA01
986486	100440138	West	CA	Auburn	530459	GRVYCA01
986498	100440301	West	CA	Auburn	530459	GRVYCA01
986500	100440303	West	CA	Auburn	530459	GRVYCA01
986501	100440304	West	CA	Auburn	530459	GRVYCA01
986502	100440305	West	CA	Auburn	530459	GRVYCA01
986503	100440306	West	CA	Auburn	530459	GRVYCA01
986505	100440308	West	CA	Auburn	530459	GRVYCA01
986527	100439855	West	CA	Auburn	530459	GRVYCA01
986540	100439868	West	CA	Auburn	530459	GRVYCA01
986548	100440148	West	CA	Auburn	530459	GRVYCA01
986550	100440150	West	CA	Auburn	530459	GRVYCA01
986557	100440157	West	CA	Auburn	530459	GRVYCA01
986559	100440159	West	CA	Auburn	530459	GRVYCA01
986563	100440315	West	CA	Auburn	530459	GRVYCA01
986571	100440323	West	CA	Auburn	530459	GRVYCA01
986572	100440324	West	CA	Auburn	530459	GRVYCA01
986595	100439871	West	CA	Auburn	530459	GRVYCA01
986596	100439872	West	CA	Auburn	530459	GRVYCA01
986598	100439874	West	CA	Auburn	530459	GRVYCA01
986607	100439739	West	CA	Auburn	530459	GRVYCA01
986609	100439741	West	CA	Auburn	530459	GRVYCA01
986619	100440017	West	CA	Auburn	530459	GRVYCA01
986621	100440019	West	CA	Auburn	530459	GRVYCA01
986622	100440020	West	CA	Auburn	530459	GRVYCA01
986642	100440343	West	CA	Auburn	530459	GRVYCA01
986647	100439528	West	CA	Auburn	530459	GRVYCA01
986661	100439542	West	CA	Auburn	530459	GRVYCA01
986666	100439747	West	CA	Auburn	530459	GRVYCA01
986668	100439749	West	CA	Auburn	530459	GRVYCA01
986671	100439752	West	CA	Auburn	530459	GRVYCA01
986678	100439759	West	CA	Auburn	530459	GRVYCA01
986689	100440035	West	CA	Auburn	530459	GRVYCA01
986690	100440036	West	CA	Auburn	530459	GRVYCA01
986692	100440038	West	CA	Auburn	530459	GRVYCA01
986694	100440040	West	CA	Auburn	530459	GRVYCA01

986696	100440042	West	CA	Auburn	530459	GRVYCA01
986707	100440357	West	CA	Auburn	530459	GRVYCA01
986710	100440360	West	CA	Auburn	530459	GRVYCA01
986731	100439561	West	CA	Auburn	530459	GRVYCA01
986739	100439768	West	CA	Auburn	530459	GRVYCA01
986742	100439771	West	CA	Auburn	530459	GRVYCA01
986744	100439773	West	CA	Auburn	530459	GRVYCA01
986748	100440044	West	CA	Auburn	530459	GRVYCA01
986750	100440046	West	CA	Auburn	530459	GRVYCA01
986753	100440049	West	CA	Auburn	530459	GRVYCA01
986754	100440050	West	CA	Auburn	530459	GRVYCA01
986755	100440051	West	CA	Auburn	530459	GRVYCA01
986756	100440052	West	CA	Auburn	530459	GRVYCA01
986757	100440053	West	CA	Auburn	530459	GRVYCA01
986769	100439777	West	CA	Auburn	530459	GRVYCA01
986771	100439779	West	CA	Auburn	530459	GRVYCA01
986772	100439780	West	CA	Auburn	530459	GRVYCA01
986773	100439781	West	CA	Auburn	530459	GRVYCA01
986785	100440060	West	CA	Auburn	530459	GRVYCA01
986788	100440063	West	CA	Auburn	530459	GRVYCA01
986790	100440065	West	CA	Auburn	530459	GRVYCA01
986793	100440068	West	CA	Auburn	530459	GRVYCA01
986798	100440073	West	CA	Auburn	530459	GRVYCA01
986812	100439799	West	CA	Auburn	530459	GRVYCA01
986815	100439802	West	CA	Auburn	530459	GRVYCA01
986817	100439804	West	CA	Auburn	530459	GRVYCA01
986824	100440080	West	CA	Auburn	530459	GRVYCA01
986826	100440082	West	CA	Auburn	530459	GRVYCA01
986827	100440083	West	CA	Auburn	530459	GRVYCA01
986830	100440086	West	CA	Auburn	530459	GRVYCA01
986834	100440090	West	CA	Auburn	530459	GRVYCA01
986841	100439418	West	CA	Auburn	530459	GRVYCA01
986843	100439420	West	CA	Auburn	530459	GRVYCA01
986850	100439427	West	CA	Auburn	530459	GRVYCA01
986851	100439428	West	CA	Auburn	530459	GRVYCA01
986853	100439430	West	CA	Auburn	530459	GRVYCA01
986855	100439432	West	CA	Auburn	530459	GRVYCA01
986857	100439810	West	CA	Auburn	530459	GRVYCA01
986868	100439821	West	CA	Auburn	530459	GRVYCA01
986871	100439824	West	CA	Auburn	530459	GRVYCA01
986877	100440101	West	CA	Auburn	530459	GRVYCA01
986878	100440102	West	CA	Auburn	530459	GRVYCA01
986886	100440110	West	CA	Auburn	530459	GRVYCA01
986887	100440111	West	CA	Auburn	530459	GRVYCA01

986892	100439436	West	CA	Auburn	530459	GRVYCA01
986893	100439437	West	CA	Auburn	530459	GRVYCA01
986899	100439443	West	CA	Auburn	530459	GRVYCA01
986902	100439446	West	CA	Auburn	530459	GRVYCA01
986903	100439447	West	CA	Auburn	530459	GRVYCA01
986912	100439683	West	CA	Auburn	530459	GRVYCA01
986922	100439834	West	CA	Auburn	530459	GRVYCA01
986924	100439836	West	CA	Auburn	530459	GRVYCA01
986925	100439837	West	CA	Auburn	530459	GRVYCA01
986929	100439841	West	CA	Auburn	530459	GRVYCA01
986930	100440113	West	CA	Auburn	530459	GRVYCA01
986932	100440115	West	CA	Auburn	530459	GRVYCA01
986937	100440120	West	CA	Auburn	530459	GRVYCA01
986940	100440242	West	CA	Auburn	530459	GRVYCA01
986942	100440244	West	CA	Auburn	530459	GRVYCA01
986943	100440245	West	CA	Auburn	530459	GRVYCA01
986944	100440246	West	CA	Auburn	530459	GRVYCA01
986946	100440248	West	CA	Auburn	530459	GRVYCA01
986948	100439449	West	CA	Auburn	530459	GRVYCA01
986952	100439365	West	CA	Auburn	530459	GRVYCA01
986953	100439366	West	CA	Auburn	530459	GRVYCA01
986954	100439367	West	CA	Auburn	530459	GRVYCA01
986962	100439375	West	CA	Auburn	530459	GRVYCA01
986987	100439959	West	CA	Auburn	530459	GRVYCA01
986988	100439960	West	CA	Auburn	530459	GRVYCA01
986993	100439965	West	CA	Auburn	530459	GRVYCA01
986995	100439967	West	CA	Auburn	530459	GRVYCA01
987001	100440254	West	CA	Auburn	530459	GRVYCA01
987003	100440256	West	CA	Auburn	530459	GRVYCA01
987004	100440257	West	CA	Auburn	530459	GRVYCA01
987005	100440258	West	CA	Auburn	530459	GRVYCA01
987006	100440259	West	CA	Auburn	530459	GRVYCA01
987010	100440263	West	CA	Auburn	530459	GRVYCA01
987012	100440265	West	CA	Auburn	530459	GRVYCA01
987013	100440266	West	CA	Auburn	530459	GRVYCA01
987014	100440267	West	CA	Auburn	530459	GRVYCA01
987016	100439378	West	CA	Auburn	530459	GRVYCA01
987017	100439379	West	CA	Auburn	530459	GRVYCA01
987018	100439380	West	CA	Auburn	530459	GRVYCA01
987019	100439381	West	CA	Auburn	530459	GRVYCA01
987023	100439385	West	CA	Auburn	530459	GRVYCA01
987027	100439389	West	CA	Auburn	530459	GRVYCA01
987029	100439391	West	CA	Auburn	530459	GRVYCA01
987040	100439711	West	CA	Auburn	530459	GRVYCA01

987048	100439969	West	CA	Auburn	530459	GRVYCA01
987049	100439970	West	CA	Auburn	530459	GRVYCA01
987050	100439971	West	CA	Auburn	530459	GRVYCA01
987053	100439974	West	CA	Auburn	530459	GRVYCA01
987063	100439984	West	CA	Auburn	530459	GRVYCA01
987181	100441251	West	CA	Auburn	530459	GRVYCA01
987182	100441253	West	CA	Auburn	530459	GRVYCA01
987186	100441277	West	CA	Auburn	530459	GRVYCA01
987189	100441281	West	CA	Auburn	530459	GRVYCA01
987192	100441501	West	CA	Auburn	530459	GRVYCA01
987244	100440530	West	CA	Auburn	530459	GRVYCA01
987245	100440531	West	CA	Auburn	530459	GRVYCA01
987281	100440785	West	CA	Auburn	530459	GRVYCA01
987289	100440793	West	CA	Auburn	530459	GRVYCA01
987293	100440752	West	CA	Auburn	530459	GRVYCA01
987298	100440757	West	CA	Auburn	530459	GRVYCA01
987303	100440762	West	CA	Auburn	530459	GRVYCA01
987304	100440763	West	CA	Auburn	530459	GRVYCA01
987306	100440765	West	CA	Auburn	530459	GRVYCA01
987310	100440921	West	CA	Auburn	530459	GRVYCA01
987312	100440923	West	CA	Auburn	530459	GRVYCA01
987316	100440927	West	CA	Auburn	530459	GRVYCA01
987321	100440932	West	CA	Auburn	530459	GRVYCA01
987324	100441265	West	CA	Auburn	530459	GRVYCA01
987363	100440570	West	CA	Auburn	530459	GRVYCA01
987365	100440572	West	CA	Auburn	530459	GRVYCA01
987366	100440573	West	CA	Auburn	530459	GRVYCA01
987377	100440720	West	CA	Auburn	530459	GRVYCA01
987382	100440725	West	CA	Auburn	530459	GRVYCA01
987384	100440727	West	CA	Auburn	530459	GRVYCA01
987385	100440728	West	CA	Auburn	530459	GRVYCA01
987386	100440729	West	CA	Auburn	530459	GRVYCA01
987389	100440795	West	CA	Auburn	530459	GRVYCA01
987397	100440803	West	CA	Auburn	530459	GRVYCA01
987401	100440807	West	CA	Auburn	530459	GRVYCA01
987405	100440766	West	CA	Auburn	530459	GRVYCA01
987409	100440770	West	CA	Auburn	530459	GRVYCA01
987412	100440773	West	CA	Auburn	530459	GRVYCA01
987413	100440774	West	CA	Auburn	530459	GRVYCA01
987429	100441049	West	CA	Auburn	530459	GRVYCA01
987440	100441172	West	CA	Auburn	530459	GRVYCA01
987441	100441174	West	CA	Auburn	530459	GRVYCA01
987442	100441175	West	CA	Auburn	530459	GRVYCA01
987458	100441469	West	CA	Auburn	530459	GRVYCA01

987474	100440450	West	CA	Auburn	530459	GRVYCA01
987491	100440606	West	CA	Auburn	530459	GRVYCA01
987493	100440608	West	CA	Auburn	530459	GRVYCA01
987495	100440732	West	CA	Auburn	530459	GRVYCA01
987497	100440734	West	CA	Auburn	530459	GRVYCA01
987498	100440735	West	CA	Auburn	530459	GRVYCA01
987503	100440740	West	CA	Auburn	530459	GRVYCA01
987505	100440742	West	CA	Auburn	530459	GRVYCA01
987506	100440686	West	CA	Auburn	530459	GRVYCA01
987509	100440689	West	CA	Auburn	530459	GRVYCA01
987516	100440834	West	CA	Auburn	530459	GRVYCA01
987524	100440842	West	CA	Auburn	530459	GRVYCA01
987526	100440844	West	CA	Auburn	530459	GRVYCA01
987533	100440949	West	CA	Auburn	530459	GRVYCA01
987538	100440954	West	CA	Auburn	530459	GRVYCA01
987546	100441058	West	CA	Auburn	530459	GRVYCA01
987549	100441062	West	CA	Auburn	530459	GRVYCA01
987563	100441188	West	CA	Auburn	530459	GRVYCA01
987564	100441189	West	CA	Auburn	530459	GRVYCA01
987566	100441191	West	CA	Auburn	530459	GRVYCA01
987567	100441193	West	CA	Auburn	530459	GRVYCA01
987568	100441195	West	CA	Auburn	530459	GRVYCA01
987569	100441196	West	CA	Auburn	530459	GRVYCA01
987570	100441197	West	CA	Auburn	530459	GRVYCA01
987571	100441199	West	CA	Auburn	530459	GRVYCA01
987572	100441474	West	CA	Auburn	530459	GRVYCA01
987588	100441490	West	CA	Auburn	530459	GRVYCA01
987591	100440457	West	CA	Auburn	530459	GRVYCA01
987596	100440370	West	CA	Auburn	530459	GRVYCA01
987597	100440371	West	CA	Auburn	530459	GRVYCA01
987598	100440372	West	CA	Auburn	530459	GRVYCA01
987600	100440374	West	CA	Auburn	530459	GRVYCA01
987605	100440379	West	CA	Auburn	530459	GRVYCA01
987606	100440380	West	CA	Auburn	530459	GRVYCA01
987624	100440693	West	CA	Auburn	530459	GRVYCA01
987625	100440694	West	CA	Auburn	530459	GRVYCA01
987627	100440696	West	CA	Auburn	530459	GRVYCA01
987628	100440697	West	CA	Auburn	530459	GRVYCA01
987629	100440698	West	CA	Auburn	530459	GRVYCA01
987631	100440700	West	CA	Auburn	530459	GRVYCA01
987636	100440609	West	CA	Auburn	530459	GRVYCA01
987638	100440611	West	CA	Auburn	530459	GRVYCA01
987641	100440848	West	CA	Auburn	530459	GRVYCA01
987642	100440849	West	CA	Auburn	530459	GRVYCA01

987644	100440851	West	CA	Auburn	530459	GRVYCA01
987650	100440857	West	CA	Auburn	530459	GRVYCA01
987651	100440858	West	CA	Auburn	530459	GRVYCA01
987655	100440862	West	CA	Auburn	530459	GRVYCA01
987656	100440960	West	CA	Auburn	530459	GRVYCA01
987661	100440965	West	CA	Auburn	530459	GRVYCA01
987669	100440973	West	CA	Auburn	530459	GRVYCA01
987672	100441072	West	CA	Auburn	530459	GRVYCA01
987682	100441083	West	CA	Auburn	530459	GRVYCA01
987684	100441105	West	CA	Auburn	530459	GRVYCA01
987686	100441107	West	CA	Auburn	530459	GRVYCA01
987688	100441109	West	CA	Auburn	530459	GRVYCA01
987690	100441201	West	CA	Auburn	530459	GRVYCA01
987695	100441206	West	CA	Auburn	530459	GRVYCA01
987696	100441209	West	CA	Auburn	530459	GRVYCA01
987697	100441210	West	CA	Auburn	530459	GRVYCA01
987700	100441214	West	CA	Auburn	530459	GRVYCA01
987701	100441216	West	CA	Auburn	530459	GRVYCA01
987711	100440390	West	CA	Auburn	530459	GRVYCA01
987712	100440391	West	CA	Auburn	530459	GRVYCA01
987719	100440538	West	CA	Auburn	530459	GRVYCA01
987726	100440545	West	CA	Auburn	530459	GRVYCA01
987727	100440546	West	CA	Auburn	530459	GRVYCA01
987742	100440619	West	CA	Auburn	530459	GRVYCA01
987750	100440627	West	CA	Auburn	530459	GRVYCA01
987751	100440628	West	CA	Auburn	530459	GRVYCA01
987753	100440864	West	CA	Auburn	530459	GRVYCA01
987754	100440865	West	CA	Auburn	530459	GRVYCA01
987756	100440867	West	CA	Auburn	530459	GRVYCA01
987758	100440869	West	CA	Auburn	530459	GRVYCA01
987759	100440870	West	CA	Auburn	530459	GRVYCA01
987760	100440871	West	CA	Auburn	530459	GRVYCA01
987761	100440872	West	CA	Auburn	530459	GRVYCA01
987762	100440873	West	CA	Auburn	530459	GRVYCA01
987769	100440976	West	CA	Auburn	530459	GRVYCA01
987779	100440986	West	CA	Auburn	530459	GRVYCA01
987781	100440988	West	CA	Auburn	530459	GRVYCA01
987782	100440989	West	CA	Auburn	530459	GRVYCA01
987783	100440990	West	CA	Auburn	530459	GRVYCA01
987784	100440991	West	CA	Auburn	530459	GRVYCA01
987787	100441112	West	CA	Auburn	530459	GRVYCA01
987789	100441114	West	CA	Auburn	530459	GRVYCA01
987800	100441145	West	CA	Auburn	530459	GRVYCA01
987801	100441217	West	CA	Auburn	530459	GRVYCA01

987802	100441218	West	CA	Auburn	530459	GRVYCA01
987815	100440398	West	CA	Auburn	530459	GRVYCA01
987820	100440403	West	CA	Auburn	530459	GRVYCA01
987826	100440503	West	CA	Auburn	530459	GRVYCA01
987829	100440506	West	CA	Auburn	530459	GRVYCA01
987830	100440507	West	CA	Auburn	530459	GRVYCA01
987831	100440554	West	CA	Auburn	530459	GRVYCA01
987833	100440556	West	CA	Auburn	530459	GRVYCA01
987838	100440465	West	CA	Auburn	530459	GRVYCA01
987843	100440470	West	CA	Auburn	530459	GRVYCA01
987844	100440471	West	CA	Auburn	530459	GRVYCA01
987845	100440472	West	CA	Auburn	530459	GRVYCA01
987846	100440473	West	CA	Auburn	530459	GRVYCA01
987848	100440475	West	CA	Auburn	530459	GRVYCA01
987850	100440630	West	CA	Auburn	530459	GRVYCA01
987851	100440631	West	CA	Auburn	530459	GRVYCA01
987853	100440633	West	CA	Auburn	530459	GRVYCA01
987856	100440636	West	CA	Auburn	530459	GRVYCA01
987857	100440637	West	CA	Auburn	530459	GRVYCA01
987870	100440884	West	CA	Auburn	530459	GRVYCA01
987871	100440886	West	CA	Auburn	530459	GRVYCA01
987874	100440815	West	CA	Auburn	530459	GRVYCA01
987879	100440820	West	CA	Auburn	530459	GRVYCA01
987880	100440821	West	CA	Auburn	530459	GRVYCA01
987881	100440822	West	CA	Auburn	530459	GRVYCA01
987884	100440995	West	CA	Auburn	530459	GRVYCA01
987889	100441000	West	CA	Auburn	530459	GRVYCA01
987893	100441004	West	CA	Auburn	530459	GRVYCA01
987894	100441005	West	CA	Auburn	530459	GRVYCA01
987897	100441008	West	CA	Auburn	530459	GRVYCA01
987906	100441154	West	CA	Auburn	530459	GRVYCA01
987907	100441155	West	CA	Auburn	530459	GRVYCA01
987912	100441124	West	CA	Auburn	530459	GRVYCA01
987916	100441351	West	CA	Auburn	530459	GRVYCA01
987917	100441352	West	CA	Auburn	530459	GRVYCA01
987923	100441362	West	CA	Auburn	530459	GRVYCA01
987928	100440510	West	CA	Auburn	530459	GRVYCA01
987929	100440511	West	CA	Auburn	530459	GRVYCA01
987931	100440513	West	CA	Auburn	530459	GRVYCA01
987933	100440515	West	CA	Auburn	530459	GRVYCA01
987934	100440516	West	CA	Auburn	530459	GRVYCA01
987935	100440517	West	CA	Auburn	530459	GRVYCA01
987937	100440519	West	CA	Auburn	530459	GRVYCA01
987946	100440479	West	CA	Auburn	530459	GRVYCA01

987948	100440481	West	CA	Auburn	530459	GRVYCA01
987950	100440483	West	CA	Auburn	530459	GRVYCA01
987952	100440485	West	CA	Auburn	530459	GRVYCA01
987953	100440486	West	CA	Auburn	530459	GRVYCA01
987956	100440489	West	CA	Auburn	530459	GRVYCA01
987957	100440490	West	CA	Auburn	530459	GRVYCA01
987959	100440492	West	CA	Auburn	530459	GRVYCA01
987964	100440649	West	CA	Auburn	530459	GRVYCA01
987965	100440650	West	CA	Auburn	530459	GRVYCA01
987967	100440652	West	CA	Auburn	530459	GRVYCA01
987972	100440657	West	CA	Auburn	530459	GRVYCA01
987974	100440659	West	CA	Auburn	530459	GRVYCA01
987977	100440662	West	CA	Auburn	530459	GRVYCA01
987978	100440663	West	CA	Auburn	530459	GRVYCA01
987979	100440823	West	CA	Auburn	530459	GRVYCA01
987990	100440744	West	CA	Auburn	530459	GRVYCA01
987997	100441012	West	CA	Auburn	530459	GRVYCA01
988004	100440893	West	CA	Auburn	530459	GRVYCA01
988010	100440899	West	CA	Auburn	530459	GRVYCA01
988012	100441127	West	CA	Auburn	530459	GRVYCA01
988013	100441128	West	CA	Auburn	530459	GRVYCA01
988014	100441130	West	CA	Auburn	530459	GRVYCA01
988017	100441133	West	CA	Auburn	530459	GRVYCA01
988018	100441135	West	CA	Auburn	530459	GRVYCA01
988019	100441136	West	CA	Auburn	530459	GRVYCA01
988020	100441137	West	CA	Auburn	530459	GRVYCA01
988021	100441139	West	CA	Auburn	530459	GRVYCA01
988038	100441492	West	CA	Auburn	530459	GRVYCA01
988039	100441494	West	CA	Auburn	530459	GRVYCA01
988040	100441495	West	CA	Auburn	530459	GRVYCA01
988042	100440494	West	CA	Auburn	530459	GRVYCA01
988047	100440499	West	CA	Auburn	530459	GRVYCA01
988049	100440667	West	CA	Auburn	530459	GRVYCA01
988051	100440669	West	CA	Auburn	530459	GRVYCA01
988052	100440670	West	CA	Auburn	530459	GRVYCA01
988053	100440671	West	CA	Auburn	530459	GRVYCA01
988054	100440672	West	CA	Auburn	530459	GRVYCA01
988055	100440673	West	CA	Auburn	530459	GRVYCA01
988058	100440676	West	CA	Auburn	530459	GRVYCA01
988059	100440677	West	CA	Auburn	530459	GRVYCA01
988061	100440901	West	CA	Auburn	530459	GRVYCA01
988063	100440903	West	CA	Auburn	530459	GRVYCA01
988070	100440911	West	CA	Auburn	530459	GRVYCA01
988073	100440914	West	CA	Auburn	530459	GRVYCA01

988077	100441143	West	CA	Auburn	530459	GRVYCA01
988078	100441085	West	CA	Auburn	530459	GRVYCA01
988081	100441088	West	CA	Auburn	530459	GRVYCA01
988085	100441092	West	CA	Auburn	530459	GRVYCA01
988087	100441094	West	CA	Auburn	530459	GRVYCA01
988088	100441095	West	CA	Auburn	530459	GRVYCA01
988090	100441097	West	CA	Auburn	530459	GRVYCA01
988091	100441099	West	CA	Auburn	530459	GRVYCA01
988092	100441100	West	CA	Auburn	530459	GRVYCA01
988125	100441018	West	CA	Auburn	530459	GRVYCA01
988128	100441021	West	CA	Auburn	530459	GRVYCA01
988132	100441025	West	CA	Auburn	530459	GRVYCA01
988138	100441419	West	CA	Auburn	530459	GRVYCA01
988140	100441421	West	CA	Auburn	530459	GRVYCA01
988141	100441422	West	CA	Auburn	530459	GRVYCA01
988142	100441423	West	CA	Auburn	530459	GRVYCA01
988149	100441028	West	CA	Auburn	530459	GRVYCA01
988154	100441034	West	CA	Auburn	530459	GRVYCA01
988156	100441036	West	CA	Auburn	530459	GRVYCA01
988161	100441041	West	CA	Auburn	530459	GRVYCA01
988164	100441378	West	CA	Auburn	530459	GRVYCA01
988177	100441044	West	CA	Auburn	530459	GRVYCA01
988183	100441223	West	CA	Auburn	530459	GRVYCA01
988184	100441224	West	CA	Auburn	530459	GRVYCA01
988187	100441229	West	CA	Auburn	530459	GRVYCA01
988192	100441308	West	CA	Auburn	530459	GRVYCA01
988199	100441231	West	CA	Auburn	530459	GRVYCA01
988203	100441237	West	CA	Auburn	530459	GRVYCA01
988204	100441239	West	CA	Auburn	530459	GRVYCA01
988207	100441243	West	CA	Auburn	530459	GRVYCA01
988208	100441245	West	CA	Auburn	530459	GRVYCA01
988218	100441332	West	CA	Auburn	530459	GRVYCA01
989744	100442950	West	CA	Chico	530493	QNCYCA12
997623	100450197	West	CA	Chico	530492	PTOLCA01
997629	100450203	West	CA	Chico	530492	PTOLCA01
997634	100450208	West	CA	Chico	530492	PTOLCA01
997640	100450214	West	CA	Chico	530492	PTOLCA01
997642	100450247	West	CA	Chico	530492	PTOLCA01
997645	100450250	West	CA	Chico	530492	PTOLCA01
997647	100450253	West	CA	Chico	530492	PTOLCA01
997648	100450254	West	CA	Chico	530492	PTOLCA01
997649	100450256	West	CA	Chico	530492	PTOLCA01
997650	100450257	West	CA	Chico	530492	PTOLCA01
997652	100450259	West	CA	Chico	530492	PTOLCA01

997653	100450260	West	CA	Chico	530492	PTOLCA01
997655	100450262	West	CA	Chico	530492	PTOLCA01
997663	100450271	West	CA	Chico	530492	PTOLCA01
997665	100450273	West	CA	Chico	530492	PTOLCA01
997668	100450276	West	CA	Chico	530492	PTOLCA01
997669	100450277	West	CA	Chico	530492	PTOLCA01
997672	100450280	West	CA	Chico	530492	PTOLCA01
997675	100450284	West	CA	Chico	530492	PTOLCA01
997684	100450293	West	CA	Chico	530492	PTOLCA01
997685	100450294	West	CA	Chico	530492	PTOLCA01
997688	100450506	West	CA	Chico	530493	QNCYCA12
997689	100450507	West	CA	Chico	530493	QNCYCA12
997694	100450512	West	CA	Chico	530493	QNCYCA12
997696	100450514	West	CA	Chico	530493	QNCYCA12
997733	100450515	West	CA	Chico	530493	QNCYCA12
997747	100450529	West	CA	Chico	530493	QNCYCA12
997748	100450530	West	CA	Chico	530493	QNCYCA12
997768	100450215	West	CA	Chico	530492	PTOLCA01
997769	100450216	West	CA	Chico	530492	PTOLCA01
997770	100450217	West	CA	Chico	530492	PTOLCA01
997772	100450219	West	CA	Chico	530492	PTOLCA01
997774	100450221	West	CA	Chico	530492	PTOLCA01
997777	100450427	West	CA	Chico	530493	QNCYCA12
997779	100450429	West	CA	Chico	530493	QNCYCA12
997796	100450535	West	CA	Chico	530493	QNCYCA12
997798	100450537	West	CA	Chico	530493	QNCYCA12
997799	100450538	West	CA	Chico	530493	QNCYCA12
997800	100450539	West	CA	Chico	530493	QNCYCA12
997801	100450540	West	CA	Chico	530493	QNCYCA12
997802	100450541	West	CA	Chico	530493	QNCYCA12
997803	100450542	West	CA	Chico	530493	QNCYCA12
997804	100450543	West	CA	Chico	530493	QNCYCA12
997805	100450544	West	CA	Chico	530493	QNCYCA12
997807	100450546	West	CA	Chico	530493	QNCYCA12
997808	100450547	West	CA	Chico	530493	QNCYCA12
997809	100450548	West	CA	Chico	530493	QNCYCA12
997813	100450224	West	CA	Chico	530492	PTOLCA01
997816	100450227	West	CA	Chico	530492	PTOLCA01
997817	100450228	West	CA	Chico	530492	PTOLCA01
997819	100450230	West	CA	Chico	530492	PTOLCA01
997821	100450232	West	CA	Chico	530492	PTOLCA01
997823	100450234	West	CA	Chico	530492	PTOLCA01
997824	100450235	West	CA	Chico	530492	PTOLCA01
997825	100450236	West	CA	Chico	530492	PTOLCA01

997827	100450140	West	CA	Chico	530492	PTOLCA01
997828	100450141	West	CA	Chico	530492	PTOLCA01
997879	100450157	West	CA	Chico	530492	PTOLCA01
997883	100450552	West	CA	Chico	530493	QNCYCA12
997889	100450558	West	CA	Chico	530493	QNCYCA12
997890	100450559	West	CA	Chico	530493	QNCYCA12
997917	100450160	West	CA	Chico	530492	PTOLCA01
997920	100450163	West	CA	Chico	530492	PTOLCA01
997921	100450164	West	CA	Chico	530492	PTOLCA01
997922	100450165	West	CA	Chico	530492	PTOLCA01
997927	100450170	West	CA	Chico	530492	PTOLCA01
997928	100450171	West	CA	Chico	530492	PTOLCA01
997930	100450173	West	CA	Chico	530492	PTOLCA01
997933	100450176	West	CA	Chico	530492	PTOLCA01
997958	100450437	West	CA	Chico	530493	QNCYCA12
997965	100450445	West	CA	Chico	530493	QNCYCA12
997966	100450446	West	CA	Chico	530493	QNCYCA12
997967	100450447	West	CA	Chico	530493	QNCYCA12
997968	100450448	West	CA	Chico	530493	QNCYCA12
997969	100450449	West	CA	Chico	530493	QNCYCA12
997970	100450178	West	CA	Chico	530492	PTOLCA01
997971	100450179	West	CA	Chico	530492	PTOLCA01
997975	100450183	West	CA	Chico	530492	PTOLCA01
997980	100450188	West	CA	Chico	530492	PTOLCA01
997985	100450194	West	CA	Chico	530492	PTOLCA01
998010	100450477	West	CA	Chico	530493	QNCYCA12
998019	100450486	West	CA	Chico	530493	QNCYCA12
998020	100450487	West	CA	Chico	530493	QNCYCA12
998021	100450488	West	CA	Chico	530493	QNCYCA12
998022	100450489	West	CA	Chico	530493	QNCYCA12
998024	100450296	West	CA	Chico	530492	PTOLCA01
998025	100450297	West	CA	Chico	530492	PTOLCA01
998027	100450299	West	CA	Chico	530492	PTOLCA01
998028	100450300	West	CA	Chico	530492	PTOLCA01
998029	100450301	West	CA	Chico	530492	PTOLCA01
998043	100450452	West	CA	Chico	530493	QNCYCA12
998044	100450453	West	CA	Chico	530493	QNCYCA12
998045	100450454	West	CA	Chico	530493	QNCYCA12
998046	100450455	West	CA	Chico	530493	QNCYCA12
998047	100450456	West	CA	Chico	530493	QNCYCA12
998048	100450457	West	CA	Chico	530493	QNCYCA12
998049	100450458	West	CA	Chico	530493	QNCYCA12
998050	100450459	West	CA	Chico	530493	QNCYCA12
998053	100450462	West	CA	Chico	530493	QNCYCA12

998054	100450463	West	CA	Chico	530493	QNCYCA12
998078	100450315	West	CA	Chico	530493	QNCYCA12
998079	100450316	West	CA	Chico	530493	QNCYCA12
998080	100450317	West	CA	Chico	530493	QNCYCA12
998085	100450322	West	CA	Chico	530493	QNCYCA12
998106	100450403	West	CA	Chico	530493	QNCYCA12
998113	100450332	West	CA	Chico	530493	QNCYCA12
998114	100450333	West	CA	Chico	530493	QNCYCA12
998120	100450339	West	CA	Chico	530493	QNCYCA12
998121	100450340	West	CA	Chico	530493	QNCYCA12
998122	100450342	West	CA	Chico	530493	QNCYCA12
998123	100450343	West	CA	Chico	530493	QNCYCA12
998176	100450531	West	CA	Chico	530493	QNCYCA12
998178	100450533	West	CA	Chico	530493	QNCYCA12
998241	100450240	West	CA	Chico	530492	PTOLCA01
998243	100450242	West	CA	Chico	530492	PTOLCA01
998244	100450243	West	CA	Chico	530492	PTOLCA01
998248	100450491	West	CA	Chico	530493	QNCYCA12
998250	100450493	West	CA	Chico	530493	QNCYCA12
998251	100450494	West	CA	Chico	530493	QNCYCA12
998252	100450495	West	CA	Chico	530493	QNCYCA12
998254	100450497	West	CA	Chico	530493	QNCYCA12
998255	100450498	West	CA	Chico	530493	QNCYCA12
998257	100450500	West	CA	Chico	530493	QNCYCA12
1002219	100454400	West	CA	Chico	530471	LLTNCA11
1002229	100454410	West	CA	Chico	530471	LLTNCA11
1002247	100454414	West	CA	Chico	530471	LLTNCA11
1002257	100454424	West	CA	Chico	530471	LLTNCA11
1002258	100454425	West	CA	Chico	530471	LLTNCA11
1002264	100454331	West	CA	Chico	530471	LLTNCA11
1002265	100454332	West	CA	Chico	530471	LLTNCA11
1002268	100454335	West	CA	Chico	530471	LLTNCA11
1002269	100454336	West	CA	Chico	530471	LLTNCA11
1002279	100454346	West	CA	Chico	530471	LLTNCA11
1002287	100454354	West	CA	Chico	530471	LLTNCA11
1002292	100454359	West	CA	Chico	530471	LLTNCA11
1002303	100454370	West	CA	Chico	530471	LLTNCA11
1002308	100454375	West	CA	Chico	530471	LLTNCA11
1002322	100454389	West	CA	Chico	530471	LLTNCA11
1025948	100475856	West	CA	Auburn	530459	GRVYCA01
1025949	100475695	West	CA	Auburn	530459	GRVYCA01

1025950	100475686	West	CA	Auburn	530459	GRVYCA01
1026254	100475904	West	CA	Auburn	530459	GRVYCA01
1026255	100475906	West	CA	Auburn	530459	GRVYCA01
1028446	100478226	West	CA	Auburn	530459	GRVYCA01
1030151	100479886	West	CA	Auburn	530459	GRVYCA01
1030152	100479887	West	CA	Auburn	530459	GRVYCA01
1030741	100480177	West	CA	Auburn	530459	GRVYCA01
1039842	100485255	West	CA	Chico	530433	BLRSCA12
1039843	100485254	West	CA	Chico	530433	BLRSCA12
1041179	100486224	West	CA	Auburn	530459	GRVYCA01
1041208	100486293	West	CA	Auburn	530459	GRVYCA01
1041803	100486775	West	CA	Auburn	530459	GRVYCA01
1047590	100491822	West	CA	Chico	530493	QNCYCA12
1048485	100492427	West	CA	Auburn	530459	GRVYCA01
1056413	100498354	West	CA	Chico	530493	QNCYCA12
1061609	100502293	West	CA	Chico	530493	QNCYCA12
1064505	100505845	West	CA	Auburn	530459	GRVYCA01
1071340	100512620	West	CA	Auburn	530447	DTFLCA11
1072095	100513377	West	CA	Auburn	530475	NVCYCA11
1072096	100513379	West	CA	Auburn	530475	NVCYCA11
1095567	100532877	West	CA	Chico	530471	LLTNCA11
1099771		West	California	Auburn	530475	NVCYCA11
1099772		West	California	Auburn	530459	GRVYCA01
1103096	100539477	West	CA	Chico	530493	QNCYCA12
1111126	100545120	West	CA	Auburn	530515	TRUCCA11
1112160	100545933	West	CA	Chico	530493	QNCYCA12
1115961	100549226	West	CA	Auburn	530447	DTFLCA11
1115962	100549168	West	CA	Auburn	530447	DTFLCA11
1115964	100549212	West	CA	Auburn	530447	DTFLCA11
1115968	100549145	West	CA	Auburn	530447	DTFLCA11
1116057	100549238	West	CA	Auburn	530447	DTFLCA11
1116118	100549370	West	CA	Auburn	530459	GRVYCA01
1116119	100549363	West	CA	Auburn	530459	GRVYCA01
1116120	100549362	West	CA	Auburn	530459	GRVYCA01
1116121	100549345	West	CA	Auburn	530459	GRVYCA01
1116122	100549343	West	CA	Auburn	530459	GRVYCA01

1116124	100549868	West	CA	Auburn	530475	NVCYCA11
1116126	100549590	West	CA	Auburn	530459	GRVYCA01
1116129	100549862	West	CA	Auburn	530475	NVCYCA11
1116130	100549573	West	CA	Auburn	530459	GRVYCA01
1116131	100549835	West	CA	Auburn	530475	NVCYCA11
1116132	100549834	West	CA	Auburn	530475	NVCYCA11
1116133	100549563	West	CA	Auburn	530459	GRVYCA01
1116135	100549559	West	CA	Auburn	530459	GRVYCA01
1116139	100549450	West	CA	Auburn	530459	GRVYCA01
1116140	100549449	West	CA	Auburn	530459	GRVYCA01
1116142	100549734	West	CA	Auburn	530475	NVCYCA11
1116143	100550017	West	CA	Auburn	530475	NVCYCA11
1116144	100549515	West	CA	Auburn	530459	GRVYCA01
1116146	100550004	West	CA	Auburn	530475	NVCYCA11
1116147	100549977	West	CA	Auburn	530475	NVCYCA11
1116150	100549776	West	CA	Auburn	530475	NVCYCA11
1116152	100549491	West	CA	Auburn	530459	GRVYCA01
1116153	100549961	West	CA	Auburn	530475	NVCYCA11
1116154	100549755	West	CA	Auburn	530475	NVCYCA11
1116155	100549485	West	CA	Auburn	530459	GRVYCA01
1116156	100549480	West	CA	Auburn	530459	GRVYCA01
1116160	100549744	West	CA	Auburn	530475	NVCYCA11
1116162	100549826	West	CA	Auburn	530475	NVCYCA11
1116164	100549821	West	CA	Auburn	530475	NVCYCA11
1116165	100549815	West	CA	Auburn	530475	NVCYCA11
1116166	100549811	West	CA	Auburn	530475	NVCYCA11
1116167	100549700	West	CA	Auburn	530475	NVCYCA11
1116170	100549417	West	CA	Auburn	530459	GRVYCA01
1116173	100549408	West	CA	Auburn	530459	GRVYCA01
1116174	100549403	West	CA	Auburn	530459	GRVYCA01
1116177	100549554	West	CA	Auburn	530459	GRVYCA01
1116178	100549550	West	CA	Auburn	530459	GRVYCA01
1116179	100549549	West	CA	Auburn	530459	GRVYCA01
1116180	100549548	West	CA	Auburn	530459	GRVYCA01
1116181	100549544	West	CA	Auburn	530459	GRVYCA01
1116182	100549915	West	CA	Auburn	530475	NVCYCA11
1116183	100549541	West	CA	Auburn	530459	GRVYCA01
1116185	100549537	West	CA	Auburn	530459	GRVYCA01
1116186	100549536	West	CA	Auburn	530459	GRVYCA01
1116188	100549313	West	CA	Auburn	530459	GRVYCA01
1116190	100549523	West	CA	Auburn	530459	GRVYCA01
1116191	100549657	West	CA	Auburn	530459	GRVYCA01
1116192	100549292	West	CA	Auburn	530459	GRVYCA01
1116194	100549639	West	CA	Auburn	530459	GRVYCA01

1116195	100549637	West	CA	Auburn	530459	GRVYCA01
1116196	100549633	West	CA	Auburn	530459	GRVYCA01
1116198	100549887	West	CA	Auburn	530475	NVCYCA11
1116202	100549572	West	CA	Auburn	530459	GRVYCA01
1116487	100549497	West	CA	Auburn	530459	GRVYCA01
1116839	100549632	West	CA	Auburn	530459	GRVYCA01
1118747	100551742	West	CA	Auburn	530436	CMPVCA11
1118763	100551751	West	CA	Auburn	530436	CMPVCA11
1118765	100551753	West	CA	Auburn	530436	CMPVCA11
1125202	100554101	West	CA	Auburn	530480	NSJNCA11
1131136	100558614	West	CA	Auburn	530515	TRUCCA11
1131157	100558909	West	CA	Auburn	530515	TRUCCA11
1131170	100558569	West	CA	Auburn	530515	TRUCCA11
1131173	100558572	West	CA	Auburn	530515	TRUCCA11
1131176	100558575	West	CA	Auburn	530515	TRUCCA11
1131183	100558582	West	CA	Auburn	530515	TRUCCA11
1131245	100558750	West	CA	Auburn	530515	TRUCCA11
1131248	100558753	West	CA	Auburn	530515	TRUCCA11
1131251	100558756	West	CA	Auburn	530515	TRUCCA11
1131268	100558926	West	CA	Auburn	530515	TRUCCA11
1131282	100558768	West	CA	Auburn	530515	TRUCCA11
1131330	100558652	West	CA	Auburn	530515	TRUCCA11
1131358	100558680	West	CA	Auburn	530515	TRUCCA11
1131359	100558681	West	CA	Auburn	530515	TRUCCA11
1131375	100558697	West	CA	Auburn	530515	TRUCCA11
1131396	100558719	West	CA	Auburn	530515	TRUCCA11
1131398	100558721	West	CA	Auburn	530515	TRUCCA11
1131415	100558738	West	CA	Auburn	530515	TRUCCA11
1131417	100558740	West	CA	Auburn	530515	TRUCCA11
1131421	100558744	West	CA	Auburn	530515	TRUCCA11
1131422	100558745	West	CA	Auburn	530515	TRUCCA11
1131723	100559213	West	CA	Chico	530493	QNCYCA12
1131724	100559214	West	CA	Chico	530493	QNCYCA12
1131730	100559220	West	CA	Chico	530493	QNCYCA12
1131731	100559221	West	CA	Chico	530493	QNCYCA12
1131733	100559223	West	CA	Chico	530493	QNCYCA12
1131748	100559183	West	CA	Chico	530493	QNCYCA12
1131754	100559190	West	CA	Chico	530493	QNCYCA12
1131768	100559203	West	CA	Chico	530493	QNCYCA12
1131769	100559204	West	CA	Chico	530493	QNCYCA12
1131771	100559206	West	CA	Chico	530493	QNCYCA12
1139638	100566268	West	CA		530437	CHLNCA11
1139677	100566293	West	CA		530437	CHLNCA11
1143880	100570150	West	CA	Chico	530493	QNCYCA12

1174493	100587062	West	CA	Auburn	530444	DWNVCA11
1175821	100588379	West	CA	Chico	530433	BLRSCA12
1184083	100594973	West	CA	Chico	530492	PTOLCA01
1185700	100596150	West	CA	Chico	530471	LLTNCA11
1192981	100603225	West	CA	Chico	530493	QNCYCA12
1198039	100604670	West	CA	Auburn	530447	DTFLCA11
1198053	100604684	West	CA	Auburn	530447	DTFLCA11
1198063	100604600	West	CA	Auburn	530447	DTFLCA11
1198086	100604624	West	CA	Auburn	530447	DTFLCA11
1204930	100610923	West	CA	Auburn	530535	GRVYCA12
1225416	100625589	West	CA	Auburn	530459	GRVYCA01
1230505	100630417	West	CA	Auburn	530447	DTFLCA11
1230506	100630402	West	CA	Auburn	530447	DTFLCA11
1230507	100630407	West	CA	Auburn	530447	DTFLCA11
1312497	100691768	West	CA	Auburn	530535	GRVYCA12
1338077	100709530	West	CA	Auburn	530447	DTFLCA11
1339076	100710514	West	CA	Auburn	530447	DTFLCA11
1339112	100710542	West	CA	Auburn	530447	DTFLCA11
1340357	100711507	West	CA	Auburn	530447	DTFLCA11
1340358	100711511	West	CA	Auburn	530447	DTFLCA11
1340887	100711965	West	CA	Auburn	530447	DTFLCA11
1340888	100712010	West	CA	Auburn	530447	DTFLCA11
1341214	100712224	West	CA	Auburn	530447	DTFLCA11
1346767	100717340	West	CA	Chico	530433	BLRSCA12
1350849		West	California		530437	CHLNCA11
1351160		West	California	Auburn	530447	DTFLCA11
1351161		West	California	Auburn	530447	DTFLCA11
1352326		West	California	Auburn	530447	DTFLCA11
1352329		West	California	Auburn	530459	GRVYCA01
1352330		West	California	Auburn	530459	GRVYCA01
1352331		West	California	Auburn	530459	GRVYCA01
1352332		West	California	Auburn	530447	DTFLCA11
1353659		West	California	Auburn	530475	NVCYCA11
1353660		West	California	Auburn	530459	GRVYCA01
1355534		West	California	Auburn	530436	CMPVCA11
1355535		West	California	Auburn	530459	GRVYCA01
1356182	100725980	West	CA		530437	CHLNCA11
1356606		West	California	Auburn	530459	GRVYCA01
1356844		West	California	Auburn	530459	GRVYCA01
1356845		West	California	Auburn	530459	GRVYCA01
1360976	100730424	West	CA	Auburn	530436	CMPVCA11
1361290	100730554	West	CA	Auburn	530535	GRVYCA12
1375653	100740968	West	CA	Auburn	530459	GRVYCA01
1375656	100741205	West	CA	Auburn	530459	GRVYCA01

1375659	100740734	West	CA	Auburn	530447	DTFLCA11
1375665	100740703	West	CA	Auburn	530447	DTFLCA11
1375681	100741070	West	CA	Auburn	530459	GRVYCA01
1375686	100741206	West	CA	Auburn	530459	GRVYCA01
1376323	100741567	West	CA	Auburn	530459	GRVYCA01
1376329	100741444	West	CA	Auburn	530459	GRVYCA01
1376338	100741559	West	CA	Auburn	530459	GRVYCA01
1378363	100743156	West	CA	Auburn	530475	NVCYCA11
1378992	100743604	West	CA	Auburn	530515	TRUCCA11
1439239		West	California	Auburn	530447	DTFLCA11
1439240		West	California	Auburn	530459	GRVYCA01
1439241		West	California	Auburn	530459	GRVYCA01
1439242		West	California	Auburn	530459	GRVYCA01
1439909	100791475	West	CA	Auburn	530480	NSJNCA11
1453191	100801701	West	CA	Auburn	530459	GRVYCA01
1455730	100804152	West	CA	Auburn	530459	GRVYCA01
1455731	100804153	West	CA	Auburn	530459	GRVYCA01
1455732	100804149	West	CA	Auburn	530447	DTFLCA11
1468422	100813846	West	CA	Auburn	530459	GRVYCA01
1474319	100819782	West	CA	Auburn	530475	NVCYCA11
1474320	100819776	West	CA	Auburn	530459	GRVYCA01
1474321	100819769	West	CA	Auburn	530459	GRVYCA01
1474322	100819756	West	CA	Auburn	530459	GRVYCA01
1474323	100819772	West	CA	Auburn	530459	GRVYCA01
1480549	100824902	West	CA	Auburn	530515	TRUCCA11

WC_NAME	CREATE_DATE	DUE_DATE	CLOSED_DATE	CREATED_UUID	FORCE_TECH
GRASS VALLEY	7/2/2019	7/2/2024	7/30/2023	VU1396	VC6131
LAKE WILDWOOD	7/8/2019	7/8/2022	8/31/2021	VU1396	NH2812
GRASS VALLEY	7/9/2019	7/9/2024	11/19/2020	VU1396	
GRASS VALLEY	7/11/2019	7/11/2022	9/27/2021	VU1396	SM4953
GRASS VALLEY	7/17/2019	7/19/2019	11/5/2019	RT9712	
NEVADA CITY	8/18/2019	8/17/2022	9/6/2019	RW5286	
NEVADA CITY	9/5/2019	5/22/2020	3/22/2021	INSPTR	
NEVADA CITY	9/5/2019	5/22/2020	3/22/2021	INSPTR	
NEVADA CITY	9/5/2019	5/22/2020	3/22/2021	INSPTR	
BLAIRSDEN	9/5/2019	5/13/2020	1/6/2021	INSPTR	
BLAIRSDEN	9/5/2019	5/13/2020	1/6/2021	INSPTR	
BLAIRSDEN	9/5/2019	5/13/2020	5/27/2020	INSPTR	
BLAIRSDEN	9/5/2019	5/14/2020	1/6/2021	INSPTR	
BLAIRSDEN	9/5/2019	5/14/2020	1/6/2021	INSPTR	
NEVADA CITY	9/5/2019	5/21/2020	3/22/2021	INSPTR	
BLAIRSDEN	9/5/2019	5/13/2020	1/6/2021	INSPTR	
BLAIRSDEN	9/5/2019	5/13/2020	1/6/2021	INSPTR	
BLAIRSDEN	9/5/2019	5/14/2020	1/6/2021	INSPTR	
BLAIRSDEN	9/5/2019	5/13/2020	1/6/2021	INSPTR	
NEVADA CITY	9/5/2019	5/21/2020	9/22/2020	INSPTR	
NEVADA CITY	9/5/2019	5/21/2020	11/7/2019	INSPTR	AG2675
BLAIRSDEN	9/5/2019	5/13/2020	1/6/2021	INSPTR	
NEVADA CITY	9/5/2019	5/21/2020	11/4/2019	INSPTR	RT9712
BLAIRSDEN	9/5/2019	5/14/2020	9/5/2019	INSPTR	SF8537
NEVADA CITY	9/5/2019	5/23/2020	3/22/2021	INSPTR	
BLAIRSDEN	9/5/2019	5/13/2020	1/6/2021	INSPTR	
BLAIRSDEN	9/5/2019	5/14/2020	1/6/2021	INSPTR	
NEVADA CITY	9/5/2019	5/22/2024	4/3/2020	INSPTR	
NEVADA CITY	9/5/2019	5/21/2024	4/3/2020	INSPTR	
NEVADA CITY	9/5/2019	5/22/2024	4/3/2020	INSPTR	
NEVADA CITY	9/5/2019	5/21/2022	6/29/2021	INSPTR	NH2812
NEVADA CITY	9/5/2019	5/21/2022	6/9/2021	INSPTR	EK6957
NEVADA CITY	9/5/2019	5/21/2022	6/30/2021	INSPTR	EK6957
BLAIRSDEN	9/5/2019	5/13/2022	5/13/2021	INSPTR	SF8537
BLAIRSDEN	9/5/2019	5/14/2022	5/14/2021	INSPTR	SF8537
TRUCKEE	9/19/2019	6/12/2020	11/10/2020	INSPTR	
TRUCKEE	9/19/2019	6/11/2020	11/20/2020	INSPTR	
TRUCKEE	9/19/2019	6/12/2020	7/28/2020	INSPTR	
TRUCKEE	9/19/2019	6/11/2020	9/25/2020	INSPTR	
TRUCKEE	9/19/2019	6/10/2020	6/8/2020	INSPTR	
TRUCKEE	9/19/2019	6/11/2020	6/8/2020	INSPTR	

TRUCKEE	9/19/2019	6/11/2020	6/8/2020	INSPTR	
TRUCKEE	9/19/2019	6/13/2024	12/10/2020	INSPTR	
TRUCKEE	9/19/2019	6/12/2024	9/25/2020	INSPTR	
TRUCKEE	9/19/2019	6/12/2024	9/25/2020	INSPTR	
TRUCKEE	9/19/2019	6/11/2024	9/25/2020	INSPTR	
TRUCKEE	9/19/2019	6/13/2024	9/25/2020	INSPTR	
TRUCKEE	9/19/2019	6/13/2024	9/24/2020	INSPTR	
TRUCKEE	9/19/2019	6/13/2024	9/24/2020	INSPTR	
TRUCKEE	9/19/2019	6/11/2024	11/19/2020	INSPTR	
TRUCKEE	9/19/2019	6/11/2024	11/4/2020	INSPTR	
TRUCKEE	9/19/2019	6/12/2024	9/25/2020	INSPTR	
TRUCKEE	9/19/2019	6/12/2024	9/25/2020	INSPTR	
TRUCKEE	9/19/2019	6/13/2024	9/24/2020	INSPTR	
TRUCKEE	9/19/2019	6/13/2024	9/25/2020	INSPTR	
TRUCKEE	9/19/2019	6/13/2024	9/25/2020	INSPTR	
TRUCKEE	9/19/2019	6/12/2024	9/24/2020	INSPTR	
TRUCKEE	9/19/2019	6/13/2024	9/24/2020	INSPTR	
TRUCKEE	9/19/2019	6/11/2024	1/8/2024	INSPTR	PG6512
TRUCKEE	9/19/2019	6/12/2024	11/10/2020	INSPTR	
TRUCKEE	9/19/2019	6/13/2024	9/24/2020	INSPTR	
TRUCKEE	9/19/2019	6/12/2024	11/19/2020	INSPTR	
TRUCKEE	9/19/2019	6/11/2024	1/11/2024	INSPTR	CD5628
TRUCKEE	9/19/2019	6/13/2024	9/30/2020	INSPTR	
TRUCKEE	9/19/2019	6/12/2024	11/10/2020	INSPTR	
TRUCKEE	9/19/2019	6/10/2024	9/25/2020	INSPTR	
TRUCKEE	9/19/2019	6/10/2024	9/25/2020	INSPTR	
TRUCKEE	9/19/2019	6/12/2024	9/25/2020	INSPTR	
TRUCKEE	9/19/2019	6/12/2024	10/1/2020	INSPTR	
TRUCKEE	9/19/2019	6/10/2024	10/5/2020	INSPTR	
TRUCKEE	9/19/2019	6/11/2024	9/30/2020	INSPTR	
TRUCKEE	9/19/2019	6/12/2024	1/18/2024	INSPTR	CD5628
TRUCKEE	9/19/2019	6/13/2024	9/30/2020	INSPTR	
TRUCKEE	9/19/2019	6/13/2024	1/2/2024	INSPTR	CD5628
TRUCKEE	9/19/2019	6/11/2024	9/30/2020	INSPTR	
TRUCKEE	9/19/2019	6/10/2024	1/18/2024	INSPTR	CD5628
TRUCKEE	9/19/2019	6/10/2024	10/5/2020	INSPTR	
TRUCKEE	9/19/2019	6/13/2024	11/23/2020	INSPTR	
TRUCKEE	9/19/2019	6/11/2024	10/1/2020	INSPTR	
TRUCKEE	9/19/2019	6/10/2024	1/11/2024	INSPTR	CD5628
TRUCKEE	9/19/2019	6/10/2024	9/30/2020	INSPTR	
TRUCKEE	9/19/2019	6/13/2024	9/28/2020	INSPTR	
TRUCKEE	9/19/2019	6/11/2024	11/20/2020	INSPTR	
TRUCKEE	9/19/2019	6/13/2024	11/11/2020	INSPTR	

TRUCKEE	9/19/2019	6/13/2024	11/11/2020	INSPTR	
TRUCKEE	9/19/2019	6/10/2024	10/14/2020	INSPTR	
TRUCKEE	9/19/2019	6/12/2024	10/6/2020	INSPTR	
TRUCKEE	9/19/2019	6/11/2024	12/10/2020	INSPTR	
TRUCKEE	9/19/2019	6/13/2024	1/15/2024	INSPTR	CD5628
TRUCKEE	9/19/2019	6/11/2024	9/30/2020	INSPTR	
TRUCKEE	9/19/2019	6/13/2024	9/30/2020	INSPTR	
TRUCKEE	9/19/2019	6/12/2024	10/5/2020	INSPTR	
TRUCKEE	9/19/2019	6/13/2024	9/30/2020	INSPTR	
TRUCKEE	9/19/2019	6/12/2024	2/8/2021	INSPTR	
TRUCKEE	9/19/2019	6/13/2024	9/30/2020	INSPTR	
TRUCKEE	9/19/2019	6/11/2024	9/30/2020	INSPTR	
TRUCKEE	9/19/2019	6/12/2024	9/30/2020	INSPTR	
TRUCKEE	9/19/2019	6/6/2024	2/8/2021	INSPTR	
TRUCKEE	9/19/2019	6/6/2024	2/8/2021	INSPTR	
TRUCKEE	9/19/2019	6/13/2024	9/30/2020	INSPTR	
TRUCKEE	9/19/2019	6/10/2024	9/30/2020	INSPTR	
TRUCKEE	9/19/2019	6/13/2024	9/30/2020	INSPTR	
TRUCKEE	9/19/2019	6/10/2024	9/30/2020	INSPTR	
TRUCKEE	9/19/2019	6/10/2022	11/25/2021	INSPTR	JH3145
TRUCKEE	9/19/2019	6/10/2022	8/24/2021	INSPTR	PG6512
TRUCKEE	9/19/2019	6/13/2022	3/23/2022	INSPTR	JQ2645
TRUCKEE	9/19/2019	6/13/2022	2/26/2022	INSPTR	DD6738
TRUCKEE	9/19/2019	6/10/2022	8/17/2021	INSPTR	JH3145
TRUCKEE	9/19/2019	6/11/2022	8/27/2021	INSPTR	DD6738
TRUCKEE	9/19/2019	6/11/2022	11/26/2021	INSPTR	DD6738
TRUCKEE	9/19/2019	6/10/2022	9/16/2021	INSPTR	JH3145
TRUCKEE	9/19/2019	6/11/2022	9/17/2021	INSPTR	DD6738
TRUCKEE	9/19/2019	6/13/2022	11/26/2021	INSPTR	DD6738
TRUCKEE	9/19/2019	6/10/2022	9/1/2021	INSPTR	JH3145
TRUCKEE	9/19/2019	6/13/2022	2/16/2022	INSPTR	DD6738
TRUCKEE	9/19/2019	6/13/2022	3/23/2022	INSPTR	JQ2645
TRUCKEE	9/19/2019	6/13/2022	3/24/2022	INSPTR	JH3145
TRUCKEE	9/19/2019	6/11/2022	8/30/2021	INSPTR	DD6738
TRUCKEE	9/19/2019	6/10/2022	9/1/2021	INSPTR	DD6738
TRUCKEE	9/19/2019	6/13/2022	2/26/2022	INSPTR	DD6738
TRUCKEE	9/19/2019	6/11/2022	11/26/2021	INSPTR	DD6738
TRUCKEE	9/19/2019	6/13/2022	4/1/2022	INSPTR	JH3145
TRUCKEE	9/19/2019	6/13/2022	9/24/2021	INSPTR	JH3145
TRUCKEE	9/19/2019	6/11/2022	12/10/2021	INSPTR	JH3145
TRUCKEE	9/19/2019	6/11/2022	11/30/2021	INSPTR	DD6738
TRUCKEE	9/19/2019	6/10/2022	12/8/2021	INSPTR	JH3145
TRUCKEE	9/19/2019	6/11/2022	10/20/2021	INSPTR	PG6512
TRUCKEE	9/19/2019	6/13/2022	10/5/2020	INSPTR	

TRUCKEE	9/19/2019	6/11/2022	12/9/2021	INSPTR	DD6738
TRUCKEE	9/19/2019	6/11/2022	11/22/2021	INSPTR	DD6738
TRUCKEE	9/19/2019	6/12/2022	9/30/2021	INSPTR	JH3145
TRUCKEE	9/19/2019	6/12/2022	8/23/2021	INSPTR	PG6512
TRUCKEE	9/19/2019	6/11/2022	9/3/2021	INSPTR	DD6738
TRUCKEE	9/19/2019	6/11/2022	9/1/2021	INSPTR	JH3145
TRUCKEE	9/19/2019	6/11/2022	11/27/2021	INSPTR	DD6738
TRUCKEE	9/19/2019	6/13/2022	5/31/2022	INSPTR	
TRUCKEE	9/19/2019	6/13/2022	4/6/2022	INSPTR	DD6738
TRUCKEE	9/19/2019	6/13/2022	4/1/2022	INSPTR	JH3145
TRUCKEE	9/19/2019	6/10/2022	9/17/2021	INSPTR	JH3145
TRUCKEE	9/19/2019	6/10/2022	12/16/2021	INSPTR	JH3145
TRUCKEE	9/19/2019	6/11/2022	9/3/2021	INSPTR	DD6738
TRUCKEE	9/19/2019	6/11/2022	11/29/2021	INSPTR	DD6738
TRUCKEE	9/19/2019	6/13/2022	10/19/2021	INSPTR	PG6512
TRUCKEE	9/19/2019	6/11/2022	10/22/2021	INSPTR	DD6738
TRUCKEE	9/19/2019	6/11/2022	9/2/2021	INSPTR	PG6512
TRUCKEE	9/19/2019	6/11/2022	9/16/2021	INSPTR	DD6738
TRUCKEE	9/19/2019	6/11/2022	11/30/2021	INSPTR	DD6738
TRUCKEE	9/19/2019	6/10/2022	8/27/2021	INSPTR	DD6738
TRUCKEE	9/19/2019	6/13/2022	12/13/2021	INSPTR	SM3126
TRUCKEE	9/19/2019	6/12/2022	3/21/2022	INSPTR	PG6512
TRUCKEE	9/19/2019	6/13/2022	10/14/2020	INSPTR	
TRUCKEE	9/19/2019	6/13/2022	3/23/2022	INSPTR	JQ2645
TRUCKEE	9/19/2019	6/11/2022	9/30/2021	INSPTR	PG6512
TRUCKEE	9/19/2019	6/11/2022	10/1/2021	INSPTR	PG6512
TRUCKEE	9/19/2019	6/11/2022	9/7/2021	INSPTR	DD6738
TRUCKEE	9/19/2019	6/11/2022	12/7/2021	INSPTR	DD6738
TRUCKEE	9/19/2019	6/11/2022	11/30/2021	INSPTR	DD6738
TRUCKEE	9/19/2019	6/12/2022	7/6/2022	INSPTR	
TRUCKEE	9/19/2019	6/11/2022	10/20/2021	INSPTR	PG6512
TRUCKEE	9/19/2019	6/10/2022	9/17/2021	INSPTR	JH3145
TRUCKEE	9/19/2019	6/11/2022	12/3/2021	INSPTR	PG6512
TRUCKEE	9/19/2019	6/10/2022	9/1/2021	INSPTR	DD6738
TRUCKEE	9/19/2019	6/12/2022	4/6/2022	INSPTR	PG6512
TRUCKEE	9/19/2019	6/13/2022	12/13/2021	INSPTR	SM3126
TRUCKEE	9/19/2019	6/11/2022	12/6/2021	INSPTR	JH3145
TRUCKEE	9/19/2019	6/13/2022	11/18/2021	INSPTR	DD6738
TRUCKEE	9/19/2019	6/12/2022	8/23/2021	INSPTR	PG6512
TRUCKEE	9/19/2019	6/12/2022	9/30/2021	INSPTR	JH3145
TRUCKEE	9/19/2019	6/11/2022	11/29/2021	INSPTR	DD6738
TRUCKEE	9/19/2019	6/13/2022	10/14/2020	INSPTR	
TRUCKEE	9/19/2019	6/12/2022	3/21/2022	INSPTR	PG6512
TRUCKEE	9/19/2019	6/12/2022	8/21/2021	INSPTR	PG6512

TRUCKEE	9/19/2019	6/10/2022	11/24/2021	INSPTR	DD6738
TRUCKEE	9/19/2019	6/10/2022	7/13/2021	INSPTR	JH3145
TRUCKEE	9/20/2019	6/14/2020	11/11/2020	INSPTR	
TRUCKEE	9/20/2019	6/10/2020	6/8/2020	INSPTR	
TRUCKEE	9/20/2019	6/13/2020	7/28/2020	INSPTR	
TRUCKEE	9/20/2019	6/14/2020	8/5/2020	INSPTR	
TRUCKEE	9/20/2019	6/14/2020	6/4/2020	INSPTR	
TRUCKEE	9/20/2019	6/10/2020	9/30/2020	INSPTR	
TRUCKEE	9/20/2019	6/11/2020	6/4/2020	INSPTR	
TRUCKEE	9/20/2019	6/13/2020	8/6/2020	INSPTR	
TRUCKEE	9/20/2019	6/14/2020	8/5/2020	INSPTR	
TRUCKEE	9/20/2019	6/11/2020	6/8/2020	INSPTR	
TRUCKEE	9/20/2019	6/12/2024	11/20/2020	INSPTR	
TRUCKEE	9/20/2019	6/13/2024	9/30/2020	INSPTR	
TRUCKEE	9/20/2019	6/14/2024	10/5/2020	INSPTR	
TRUCKEE	9/20/2019	6/13/2024	9/30/2020	INSPTR	
TRUCKEE	9/20/2019	6/14/2024	11/20/2020	INSPTR	
TRUCKEE	9/20/2019	6/14/2024	10/5/2020	INSPTR	
TRUCKEE	9/20/2019	6/10/2024	10/1/2020	INSPTR	
TRUCKEE	9/20/2019	6/13/2024	10/5/2020	INSPTR	
TRUCKEE	9/20/2019	6/14/2024	10/5/2020	INSPTR	
TRUCKEE	9/20/2019	6/14/2024	10/5/2020	INSPTR	
TRUCKEE	9/20/2019	6/12/2024	1/18/2024	INSPTR	CD5628
TRUCKEE	9/20/2019	6/14/2024	10/5/2020	INSPTR	
TRUCKEE	9/20/2019	6/14/2024	10/5/2020	INSPTR	
TRUCKEE	9/20/2019	6/14/2024	11/20/2020	INSPTR	
TRUCKEE	9/20/2019	6/14/2024	10/14/2020	INSPTR	
TRUCKEE	9/20/2019	6/14/2024	10/14/2020	INSPTR	
TRUCKEE	9/20/2019	6/13/2024	10/5/2020	INSPTR	
TRUCKEE	9/20/2019	6/13/2024	10/14/2020	INSPTR	
TRUCKEE	9/20/2019	6/11/2024	2/8/2021	INSPTR	
TRUCKEE	9/20/2019	6/14/2024	11/20/2020	INSPTR	
TRUCKEE	9/20/2019	6/13/2024	11/11/2020	INSPTR	
TRUCKEE	9/20/2019	6/14/2024	12/10/2020	INSPTR	
TRUCKEE	9/20/2019	6/11/2024	11/4/2020	INSPTR	
TRUCKEE	9/20/2019	6/14/2024	11/4/2020	INSPTR	
TRUCKEE	9/20/2019	6/12/2024	11/9/2020	INSPTR	
TRUCKEE	9/20/2019	6/12/2024	1/18/2024	INSPTR	CD5628
TRUCKEE	9/20/2019	6/14/2024	12/10/2020	INSPTR	

TRUCKEE	9/20/2019	6/14/2024	12/10/2020	INSPTR	
TRUCKEE	9/20/2019	6/14/2024	11/4/2020	INSPTR	
TRUCKEE	9/20/2019	6/14/2024	12/10/2020	INSPTR	
TRUCKEE	9/20/2019	6/14/2024	12/10/2020	INSPTR	
TRUCKEE	9/20/2019	6/13/2024	3/25/2021	INSPTR	
TRUCKEE	9/20/2019	6/12/2024	11/10/2020	INSPTR	
TRUCKEE	9/20/2019	6/14/2024	11/19/2020	INSPTR	
TRUCKEE	9/20/2019	6/14/2024	11/4/2020	INSPTR	
TRUCKEE	9/20/2019	6/14/2024	11/4/2020	INSPTR	
TRUCKEE	9/20/2019	6/13/2024	11/20/2020	INSPTR	
TRUCKEE	9/20/2019	6/14/2024	3/25/2021	INSPTR	
TRUCKEE	9/20/2019	6/14/2024	3/25/2021	INSPTR	
TRUCKEE	9/20/2019	6/13/2024	3/25/2021	INSPTR	
TRUCKEE	9/20/2019	6/14/2024	3/25/2021	INSPTR	
TRUCKEE	9/20/2019	6/14/2024	3/25/2021	INSPTR	
TRUCKEE	9/20/2019	6/14/2024	3/25/2021	INSPTR	
TRUCKEE	9/20/2019	6/10/2022	9/7/2021	INSPTR	DD6738
TRUCKEE	9/20/2019	6/11/2022	11/30/2021	INSPTR	DD6738
TRUCKEE	9/20/2019	6/14/2022	12/13/2021	INSPTR	SM3126
TRUCKEE	9/20/2019	6/12/2022	7/6/2022	INSPTR	
TRUCKEE	9/20/2019	6/10/2022	7/13/2021	INSPTR	JH3145
TRUCKEE	9/20/2019	6/10/2022	12/13/2021	INSPTR	JH3145
TRUCKEE	9/20/2019	6/14/2022	5/11/2022	INSPTR	JQ2645
TRUCKEE	9/20/2019	6/10/2022	12/7/2021	INSPTR	JH3145
TRUCKEE	9/20/2019	6/10/2022	3/14/2022	INSPTR	JQ2645
TRUCKEE	9/20/2019	6/10/2022	10/21/2021	INSPTR	DD6738
TRUCKEE	9/20/2019	6/11/2022	11/22/2021	INSPTR	PG6512
TRUCKEE	9/20/2019	6/11/2022	9/6/2021	INSPTR	PG6512
TRUCKEE	9/20/2019	6/11/2022	12/1/2021	INSPTR	JH3145
TRUCKEE	9/20/2019	6/10/2022	12/7/2021	INSPTR	JH3145
TRUCKEE	9/20/2019	6/13/2022	3/7/2022	INSPTR	DD6738
TRUCKEE	9/20/2019	6/14/2022	12/13/2021	INSPTR	SM3126
TRUCKEE	9/20/2019	6/11/2022	12/9/2021	INSPTR	PG6512
TRUCKEE	9/20/2019	6/11/2022	3/23/2022	INSPTR	DD6738
TRUCKEE	9/20/2019	6/14/2022	3/29/2022	INSPTR	JH3145
TRUCKEE	9/20/2019	6/14/2022	3/23/2022	INSPTR	JQ2645
TRUCKEE	9/20/2019	6/14/2022	5/11/2022	INSPTR	JQ2645
TRUCKEE	9/20/2019	6/13/2022	3/23/2022	INSPTR	JQ2645
TRUCKEE	9/20/2019	6/14/2022	3/29/2022	INSPTR	JH3145
TRUCKEE	9/20/2019	6/11/2022	12/2/2021	INSPTR	JH3145
TRUCKEE	9/20/2019	6/13/2022	11/18/2021	INSPTR	DD6738
TRUCKEE	9/20/2019	6/11/2022	11/30/2021	INSPTR	JH3145
TRUCKEE	9/20/2019	6/14/2022	12/13/2021	INSPTR	DD6738
TRUCKEE	9/20/2019	6/14/2022	5/4/2022	INSPTR	JQ2645

TRUCKEE	9/20/2019	6/10/2022	12/10/2021	INSPTR	DD6738
TRUCKEE	9/20/2019	6/11/2022	11/24/2021	INSPTR	DD6738
TRUCKEE	9/20/2019	6/11/2022	3/7/2022	INSPTR	DD6738
TRUCKEE	9/20/2019	6/10/2022	5/25/2022	INSPTR	
TRUCKEE	9/20/2019	6/10/2022	12/10/2021	INSPTR	DD6738
TRUCKEE	9/20/2019	6/13/2022	11/18/2021	INSPTR	DD6738
TRUCKEE	9/20/2019	6/13/2022	8/23/2021	INSPTR	TL5296
TRUCKEE	9/20/2019	6/10/2022	10/22/2021	INSPTR	DD6738
TRUCKEE	9/20/2019	6/10/2022	12/8/2021	INSPTR	JH3145
TRUCKEE	9/20/2019	6/11/2022	3/8/2022	INSPTR	DD6738
TRUCKEE	9/20/2019	6/13/2022	11/29/2021	INSPTR	DD6738
TRUCKEE	9/20/2019	6/14/2022	4/7/2022	INSPTR	DD6738
TRUCKEE	9/20/2019	6/13/2022	8/24/2021	INSPTR	TL5296
TRUCKEE	9/20/2019	6/14/2022	3/23/2022	INSPTR	JQ2645
TRUCKEE	9/20/2019	6/14/2022	10/24/2021	INSPTR	SM3126
TRUCKEE	9/20/2019	6/13/2022	9/3/2021	INSPTR	PG6512
TRUCKEE	9/20/2019	6/12/2022	9/30/2021	INSPTR	JH3145
TRUCKEE	9/20/2019	6/11/2022	3/7/2022	INSPTR	PG6512
TRUCKEE	9/20/2019	6/11/2022	11/30/2021	INSPTR	JH3145
TRUCKEE	9/20/2019	6/10/2022	12/10/2021	INSPTR	JH3145
TRUCKEE	9/20/2019	6/10/2022	5/25/2022	INSPTR	
TRUCKEE	9/20/2019	6/10/2022	12/13/2021	INSPTR	JH3145
TRUCKEE	9/20/2019	6/11/2022	11/27/2021	INSPTR	DD6738
QUINCY	9/26/2019	9/28/2019	1/16/2020	MM9751	
ALTA/DUTCH FLATS	10/2/2019	10/2/2020	10/21/2019	MR2414	SC2675
GRASS VALLEY	10/9/2019	10/8/2020	2/3/2021	PT8429	
QUINCY	10/19/2019	5/14/2020	8/25/2020	INSPTR	
QUINCY	10/19/2019	5/15/2020	1/6/2021	INSPTR	
QUINCY	10/19/2019	5/15/2020	1/6/2021	INSPTR	
ALTA/DUTCH FLATS	10/19/2019	5/22/2020	3/22/2021	INSPTR	
QUINCY	10/19/2019	5/14/2020	10/23/2019	INSPTR	MM9751
QUINCY	10/19/2019	5/15/2020	10/22/2019	INSPTR	MM9751
QUINCY	10/19/2019	5/14/2020	1/6/2021	INSPTR	
QUINCY	10/19/2019	5/15/2020	10/22/2019	INSPTR	SF8537
QUINCY	10/19/2019	5/14/2020	10/22/2019	INSPTR	SF8537
QUINCY	10/19/2019	5/14/2020	8/25/2020	INSPTR	
QUINCY	10/19/2019	5/14/2020	8/25/2020	INSPTR	
QUINCY	10/19/2019	5/14/2020	8/25/2020	INSPTR	
QUINCY	10/19/2019	5/14/2024	5/16/2023	INSPTR	SF8537
QUINCY	10/19/2019	5/14/2024	5/17/2023	INSPTR	SF8537
ALTA/DUTCH FLATS	10/19/2019	5/24/2024	5/24/2023	INSPTR	TL3147
QUINCY	10/19/2019	5/14/2024	5/16/2023	INSPTR	SF8537
QUINCY	10/19/2019	5/14/2024	9/28/2023	INSPTR	SF8537
QUINCY	10/19/2019	5/14/2024	5/16/2023	INSPTR	SF8537

QUINCY	10/19/2019	5/15/2024	5/19/2023	INSPTR	SF8537
QUINCY	10/19/2019	5/14/2024	8/1/2023	INSPTR	SF8537
QUINCY	10/19/2019	5/14/2024	5/17/2023	INSPTR	SF8537
QUINCY	10/19/2019	5/14/2024	9/28/2023	INSPTR	SF8537
QUINCY	10/19/2019	5/14/2024	9/28/2023	INSPTR	SF8537
ALTA/DUTCH FLATS	10/19/2019	5/27/2019	11/27/2019	INSPTR	
ALTA/DUTCH FLATS	10/19/2019	7/24/2019	10/19/2019	INSPTR	DM6529
ALTA/DUTCH FLATS	10/19/2019	7/24/2019	10/19/2019	INSPTR	DM6529
QUINCY	10/19/2019	5/14/2022	5/14/2021	INSPTR	MM9751
QUINCY	10/19/2019	5/14/2022	5/14/2021	INSPTR	MM9751
QUINCY	10/23/2019	10/25/2019	10/23/2019	SF8537	SF8537
NEVADA CITY	10/25/2019	10/25/2020	3/22/2021	MR2414	
GRASS VALLEY	10/26/2019	5/7/2020	3/22/2021	INSPTR	
GRASS VALLEY	10/26/2019	5/1/2020	3/22/2021	INSPTR	
GRASS VALLEY	10/26/2019	4/30/2020	3/22/2021	INSPTR	
GRASS VALLEY	10/26/2019	5/10/2020	2/3/2021	INSPTR	
GRASS VALLEY	10/26/2019	4/30/2020	2/3/2021	INSPTR	
GRASS VALLEY	10/26/2019	4/30/2020	2/3/2021	INSPTR	
GRASS VALLEY	10/26/2019	5/1/2020	6/5/2020	INSPTR	
GRASS VALLEY	10/26/2019	4/30/2020	6/5/2020	INSPTR	
GRASS VALLEY	10/26/2019	5/15/2020	11/3/2019	INSPTR	MR1213
GRASS VALLEY	10/26/2019	5/1/2020	6/5/2020	INSPTR	
GRASS VALLEY	10/26/2019	5/4/2020	2/3/2021	INSPTR	
GRASS VALLEY	10/26/2019	5/7/2024	7/22/2023	INSPTR	JM1295
GRASS VALLEY	10/26/2019	5/8/2022	9/5/2021	INSPTR	MD4156
GRASS VALLEY	10/26/2019	5/4/2022	9/1/2021	INSPTR	JM1295
GRASS VALLEY	10/26/2019	5/3/2022	8/29/2021	INSPTR	QB6851
GRASS VALLEY	10/26/2019	5/3/2022	9/2/2021	INSPTR	NH2812
GRASS VALLEY	10/26/2019	5/6/2022	7/6/2021	INSPTR	EK6957
GRASS VALLEY	10/26/2019	5/7/2022	9/5/2021	INSPTR	MD4156
GRASS VALLEY	10/26/2019	5/7/2022	9/2/2021	INSPTR	JM1295
GRASS VALLEY	10/26/2019	5/15/2022	9/5/2021	INSPTR	VC6131
GRASS VALLEY	10/26/2019	5/14/2022	9/5/2021	INSPTR	VC6131
GRASS VALLEY	10/26/2019	5/13/2022	9/5/2021	INSPTR	JM1295
GRASS VALLEY	10/26/2019	5/13/2022	9/5/2021	INSPTR	JM1295
GRASS VALLEY	10/26/2019	5/13/2022	9/5/2021	INSPTR	JM1295
GRASS VALLEY	10/26/2019	5/6/2022	8/30/2021	INSPTR	DM820T
GRASS VALLEY	10/26/2019	5/7/2022	8/26/2021	INSPTR	NH2812
GRASS VALLEY	10/26/2019	5/7/2022	9/2/2021	INSPTR	RW5286
GRASS VALLEY	10/26/2019	5/7/2022	9/5/2021	INSPTR	MD4156
GRASS VALLEY	10/26/2019	5/9/2022	9/5/2021	INSPTR	MD4156
GRASS VALLEY	10/26/2019	5/7/2022	8/30/2021	INSPTR	NH2812
GRASS VALLEY	10/27/2019	5/14/2020	3/22/2021	INSPTR	

GRASS VALLEY	10/27/2019	5/15/2020	2/3/2021	INSPTR	
GRASS VALLEY	10/27/2019	5/14/2020	11/4/2019	INSPTR	AG2675
GRASS VALLEY	10/27/2019	5/18/2020	12/1/2020	INSPTR	
GRASS VALLEY	10/27/2019	5/18/2020	2/3/2021	INSPTR	
GRASS VALLEY	10/27/2019	5/17/2020	11/6/2019	INSPTR	RT9712
GRASS VALLEY	10/27/2019	5/17/2020	11/6/2019	INSPTR	MS7970
GRASS VALLEY	10/27/2019	5/16/2020	6/5/2020	INSPTR	
GRASS VALLEY	10/27/2019	5/18/2020	6/5/2020	INSPTR	
GRASS VALLEY	10/27/2019	5/18/2020	11/4/2019	INSPTR	BL1527
GRASS VALLEY	10/27/2019	5/18/2020	2/3/2021	INSPTR	
GRASS VALLEY	10/27/2019	5/18/2020	11/6/2019	INSPTR	OM3842
GRASS VALLEY	10/27/2019	5/16/2022	9/2/2021	INSPTR	NH2812
GRASS VALLEY	10/27/2019	5/14/2022	9/5/2021	INSPTR	JM1295
GRASS VALLEY	10/27/2019	5/18/2022	9/13/2021	INSPTR	NH2812
GRASS VALLEY	10/27/2019	5/18/2022	7/1/2021	INSPTR	NH2812
GRASS VALLEY	10/27/2019	5/17/2022	9/5/2021	INSPTR	VC6131
GRASS VALLEY	10/27/2019	5/17/2022	8/30/2021	INSPTR	NH2812
GRASS VALLEY	10/27/2019	5/15/2022	6/21/2021	INSPTR	QB6851
GRASS VALLEY	10/27/2019	5/15/2022	4/16/2022	INSPTR	
GRASS VALLEY	11/7/2019	11/9/2019	12/4/2019	RT9712	
CHALLENGE	11/9/2019	8/18/2020	8/19/2020	INSPTR	
GRASS VALLEY	11/9/2019	8/14/2020	11/9/2019	INSPTR	JH2859
DOWNEYVILLE	11/9/2019	8/21/2020	2/11/2020	INSPTR	
CHALLENGE	11/9/2019	2/20/2020	11/25/2019	INSPTR	AC1532
CHALLENGE	11/9/2019	2/20/2020	1/20/2020	INSPTR	CC2745
GRASS VALLEY	11/9/2019	2/17/2020	9/25/2020	INSPTR	
ALLEGHANEY	11/9/2019	2/19/2020	7/16/2020	INSPTR	
CHALLENGE	11/9/2019	2/20/2020	1/20/2020	INSPTR	CC2745
DOWNEYVILLE	11/9/2019	2/20/2020	2/11/2020	INSPTR	
CHALLENGE	11/9/2019	2/18/2020	1/21/2020	INSPTR	AC1532
GRASS VALLEY	11/9/2019	2/18/2020	3/22/2021	INSPTR	
CHALLENGE	11/9/2019	2/18/2020	11/21/2019	INSPTR	CC2745
DOWNEYVILLE	11/9/2019	2/20/2020	7/16/2020	INSPTR	
CHALLENGE	11/9/2019	2/18/2020	11/20/2019	INSPTR	CC2745
CHALLENGE	11/9/2019	2/20/2020	11/22/2019	INSPTR	AC1532
CHALLENGE	11/9/2019	2/18/2020	11/21/2019	INSPTR	CC2745
CHALLENGE	11/9/2019	2/18/2020	11/13/2019	INSPTR	AC1532
CHALLENGE	11/9/2019	2/20/2020	11/20/2019	INSPTR	AC1532
CHALLENGE	11/9/2019	2/18/2020	11/13/2019	INSPTR	AC1532
CHALLENGE	11/9/2019	2/19/2020	11/19/2019	INSPTR	AC1532
CHALLENGE	11/9/2019	2/20/2020	11/20/2019	INSPTR	AC1532
CHALLENGE	11/9/2019	2/18/2020	11/20/2019	INSPTR	CC2745
CHALLENGE	11/9/2019	2/19/2020	11/19/2019	INSPTR	AC1532
CHALLENGE	11/9/2019	2/18/2020	11/13/2019	INSPTR	AC1532

GRASS VALLEY	11/9/2019	2/14/2020	9/22/2020	INSPTR	
GRASS VALLEY	11/9/2019	2/16/2020	12/1/2020	INSPTR	
CHALLENGE	11/9/2019	2/20/2020	11/13/2019	INSPTR	AC1532
CAMPTONVILLE	11/9/2019	2/15/2020	7/16/2020	INSPTR	
CHALLENGE	11/9/2019	2/19/2020	11/16/2019	INSPTR	AC1532
CHALLENGE	11/9/2019	2/19/2020	11/19/2019	INSPTR	AC1532
CHALLENGE	11/9/2019	2/20/2020	11/21/2019	INSPTR	CC2745
CHALLENGE	11/9/2019	2/19/2020	11/13/2019	INSPTR	AC1532
GRASS VALLEY	11/9/2019	2/14/2020	6/5/2020	INSPTR	
CHALLENGE	11/9/2019	2/18/2020	11/20/2019	INSPTR	CC2745
CHALLENGE	11/9/2019	2/20/2020	11/13/2019	INSPTR	AC1532
ALLEGHANEY	11/9/2019	2/19/2020	7/17/2020	INSPTR	
DOWNEYVILLE	11/9/2019	2/20/2020	2/11/2020	INSPTR	
ALLEGHANEY	11/9/2019	2/16/2020	7/16/2020	INSPTR	
DOWNEYVILLE	11/9/2019	2/20/2020	2/11/2020	INSPTR	
ALLEGHANEY	11/9/2019	2/16/2020	7/16/2020	INSPTR	
ALLEGHANEY	11/9/2019	8/19/2024	7/17/2022	INSPTR	MD2797
CHALLENGE	11/9/2019	8/18/2024	11/18/2023	INSPTR	AC1532
CHALLENGE	11/9/2019	8/18/2024	3/12/2024	INSPTR	DM258S
CHALLENGE	11/9/2019	8/18/2024	3/12/2024	INSPTR	DM258S
CHALLENGE	11/9/2019	8/20/2024	10/31/2023	INSPTR	
ALLEGHANEY	11/9/2019	8/19/2024	3/22/2022	INSPTR	DM820T
CHALLENGE	11/9/2019	8/18/2024	10/23/2023	INSPTR	DB8381
DOWNEYVILLE	11/9/2019	8/20/2024	10/3/2022	INSPTR	QB6851
ALLEGHANEY	11/9/2019	8/19/2024	3/22/2022	INSPTR	DM820T
CHALLENGE	11/9/2019	8/18/2024	3/13/2024	INSPTR	RH749C
ALLEGHANEY	11/9/2019	8/19/2024	3/22/2022	INSPTR	DM820T
ALLEGHANEY	11/9/2019	8/19/2024	3/17/2022	INSPTR	QB6851
DOWNEYVILLE	11/9/2019	8/21/2024	9/24/2022	INSPTR	QB6851
ALLEGHANEY	11/9/2019	8/19/2024	3/15/2022	INSPTR	GG8932
ALLEGHANEY	11/9/2019	8/19/2024	3/15/2022	INSPTR	GG8932
CHALLENGE	11/9/2019	8/19/2024	11/18/2023	INSPTR	AC1532
ALLEGHANEY	11/9/2019	8/19/2024	3/15/2022	INSPTR	GG8932
GRASS VALLEY	11/9/2019	8/19/2019	1/3/2020	INSPTR	
ALLEGHANEY	11/9/2019	8/22/2019	12/6/2019	INSPTR	
GRASS VALLEY	11/9/2019	8/15/2022	9/17/2021	INSPTR	NH2812
CHALLENGE	11/9/2019	8/18/2022	8/31/2021	INSPTR	AC1532
DOWNEYVILLE	11/9/2019	8/21/2022	9/10/2021	INSPTR	SM4953
CHALLENGE	11/9/2019	8/19/2022	9/24/2021	INSPTR	AC1532
CHALLENGE	11/9/2019	8/19/2022	9/17/2021	INSPTR	DB8381
CHALLENGE	11/9/2019	8/20/2022	10/7/2021	INSPTR	AC1532
CHALLENGE	11/9/2019	8/19/2022	9/27/2021	INSPTR	CC2745
GRASS VALLEY	11/9/2019	8/14/2022	9/10/2021	INSPTR	MM3647
CHALLENGE	11/9/2019	8/20/2022	8/31/2021	INSPTR	AC1532

CHALLENGE	11/9/2019	8/19/2022	8/31/2021	INSPTR	AC1532
GRASS VALLEY	11/9/2019	8/15/2022	9/16/2021	INSPTR	NH2812
DOWNEYVILLE	11/9/2019	8/21/2022	9/10/2021	INSPTR	SM4953
GRASS VALLEY	11/9/2019	8/14/2022	9/9/2021	INSPTR	QB6851
ALLEGHANEY	11/9/2019	8/19/2022	3/1/2022	INSPTR	QB6851
DOWNEYVILLE	11/9/2019	8/21/2022	9/8/2021	INSPTR	SM4953
CHALLENGE	11/9/2019	8/18/2022	10/2/2021	INSPTR	AC1532
ALLEGHANEY	11/9/2019	8/19/2022	3/6/2022	INSPTR	OD4318
DOWNEYVILLE	11/9/2019	8/21/2022	9/24/2021	INSPTR	SM4953
CHALLENGE	11/9/2019	8/18/2022	8/23/2021	INSPTR	CC2745
DOWNEYVILLE	11/9/2019	8/21/2022	9/24/2021	INSPTR	SM4953
GRASS VALLEY	11/9/2019	8/14/2022	9/16/2021	INSPTR	QB6851
NORTH SAN JUAN	11/13/2019	8/14/2020	3/22/2021	INSPTR	
NORTH SAN JUAN	11/13/2019	8/14/2020	3/22/2021	INSPTR	
NORTH SAN JUAN	11/13/2019	8/15/2020	11/15/2019	INSPTR	SM4953
NORTH SAN JUAN	11/13/2019	2/15/2020	7/16/2020	INSPTR	
NORTH SAN JUAN	11/13/2019	2/16/2020	3/22/2021	INSPTR	
NORTH SAN JUAN	11/13/2019	2/16/2020	3/22/2021	INSPTR	
NORTH SAN JUAN	11/13/2019	8/15/2022	9/16/2021	INSPTR	SM4953
NORTH SAN JUAN	11/13/2019	8/15/2022	9/16/2021	INSPTR	SM4953
BLAIRSDEN	11/13/2019	11/12/2022	11/14/2022	SF8537	SF8537
NEVADA CITY	11/16/2019	8/13/2020	3/22/2021	INSPTR	
NEVADA CITY	11/16/2019	8/11/2020	3/22/2021	INSPTR	
NEVADA CITY	11/16/2019	8/13/2020	3/22/2021	INSPTR	
NEVADA CITY	11/16/2019	8/13/2020	3/22/2021	INSPTR	
NEVADA CITY	11/16/2019	8/11/2020	3/22/2021	INSPTR	
NEVADA CITY	11/16/2019	8/10/2020	3/22/2021	INSPTR	
GRASS VALLEY	11/16/2019	8/13/2020	3/22/2021	INSPTR	
GRASS VALLEY	11/16/2019	8/14/2020	3/22/2021	INSPTR	
NEVADA CITY	11/16/2019	2/15/2020	12/1/2020	INSPTR	
NEVADA CITY	11/16/2019	2/15/2020	3/22/2021	INSPTR	
NEVADA CITY	11/16/2019	2/11/2020	3/22/2021	INSPTR	
NEVADA CITY	11/16/2019	2/13/2020	3/22/2021	INSPTR	
NEVADA CITY	11/16/2019	2/15/2020	3/22/2021	INSPTR	
NEVADA CITY	11/16/2019	2/11/2020	3/22/2021	INSPTR	
NEVADA CITY	11/16/2019	2/15/2020	3/22/2021	INSPTR	
NEVADA CITY	11/16/2019	2/15/2020	3/22/2021	INSPTR	
NEVADA CITY	11/16/2019	2/15/2020	3/22/2021	INSPTR	
NEVADA CITY	11/16/2019	2/10/2020	3/22/2021	INSPTR	
NEVADA CITY	11/16/2019	2/10/2020	3/22/2021	INSPTR	
NEVADA CITY	11/16/2019	2/10/2020	3/22/2021	INSPTR	
NEVADA CITY	11/16/2019	2/10/2020	3/22/2021	INSPTR	
NEVADA CITY	11/16/2019	2/10/2020	3/22/2021	INSPTR	
GRASS VALLEY	11/16/2019	2/16/2020	12/17/2020	INSPTR	

NEVADA CITY	11/16/2019	2/12/2020	3/22/2021	INSPTR	
NEVADA CITY	11/16/2019	2/13/2020	3/22/2021	INSPTR	
NEVADA CITY	11/16/2019	2/11/2020	3/22/2021	INSPTR	
NEVADA CITY	11/16/2019	2/11/2020	3/22/2021	INSPTR	
NEVADA CITY	11/16/2019	2/13/2020	3/22/2021	INSPTR	
NEVADA CITY	11/16/2019	2/15/2020	3/22/2021	INSPTR	
NEVADA CITY	11/16/2019	2/12/2020	3/22/2021	INSPTR	
NEVADA CITY	11/16/2019	2/15/2020	3/22/2021	INSPTR	
GRASS VALLEY	11/16/2019	2/12/2020	3/22/2021	INSPTR	
GRASS VALLEY	11/16/2019	11/6/2019	10/15/2020	INSPTR	
NEVADA CITY	11/16/2019	2/10/2020	3/22/2021	INSPTR	
NEVADA CITY	11/16/2019	2/12/2020	3/22/2021	INSPTR	
NEVADA CITY	11/16/2019	2/12/2020	2/12/2020	INSPTR	
NEVADA CITY	11/16/2019	2/10/2020	9/2/2021	INSPTR	
NEVADA CITY	11/16/2019	2/10/2020	3/22/2021	INSPTR	
GRASS VALLEY	11/16/2019	2/13/2020	3/22/2021	INSPTR	
NEVADA CITY	11/16/2019	8/15/2024	8/17/2023	INSPTR	JM1295
GRASS VALLEY	11/16/2019	8/14/2024	8/29/2023	INSPTR	LP848K
GRASS VALLEY	11/16/2019	8/10/2024	8/21/2023	INSPTR	DM820T
GRASS VALLEY	11/16/2019	8/14/2024	8/19/2023	INSPTR	JM1295
GRASS VALLEY	11/16/2019	8/10/2024	8/21/2023	INSPTR	DM820T
NEVADA CITY	11/16/2019	8/15/2019	11/16/2019	INSPTR	MR1213
GRASS VALLEY	11/16/2019	8/17/2019	1/3/2020	INSPTR	
NEVADA CITY	11/16/2019	8/13/2022	9/7/2021	INSPTR	RD3541
NEVADA CITY	11/16/2019	8/15/2022	9/10/2021	INSPTR	JM1295
NEVADA CITY	11/16/2019	8/12/2022	9/7/2021	INSPTR	NH2812
NEVADA CITY	11/16/2019	8/10/2022	8/30/2021	INSPTR	GB1263
GRASS VALLEY	11/16/2019	8/16/2022	9/12/2021	INSPTR	PC9347
GRASS VALLEY	11/16/2019	8/16/2022	8/29/2021	INSPTR	SM4953
GRASS VALLEY	11/16/2019	8/16/2022	8/20/2021	INSPTR	NH2812
NEVADA CITY	11/16/2019	8/13/2022	9/7/2021	INSPTR	NH2812
NEVADA CITY	11/16/2019	8/13/2022	9/7/2021	INSPTR	NH2812
NEVADA CITY	11/16/2019	8/12/2022	8/30/2021	INSPTR	GB1263
GRASS VALLEY	11/16/2019	8/15/2022	8/19/2021	INSPTR	RD3541
GRASS VALLEY	11/16/2019	8/13/2022	8/29/2021	INSPTR	JH3986
GRASS VALLEY	11/16/2019	8/10/2022	8/29/2021	INSPTR	WE2989
GRASS VALLEY	11/16/2019	8/14/2022	9/10/2021	INSPTR	MM3647
TRUCKEE	11/17/2019	2/15/2020	6/4/2020	INSPTR	
TRUCKEE	11/17/2019	2/14/2020	6/4/2020	INSPTR	
TRUCKEE	11/17/2019	2/15/2020	6/8/2020	INSPTR	
TRUCKEE	11/17/2019	8/14/2024	3/4/2021	INSPTR	
TRUCKEE	11/17/2019	8/13/2024	4/10/2024	INSPTR	DD6738
TRUCKEE	11/17/2019	8/13/2024	3/4/2021	INSPTR	

TRUCKEE	11/17/2019	8/13/2024	4/10/2024	INSPTR	DD6738
TRUCKEE	11/17/2019	8/14/2024	3/4/2021	INSPTR	
TRUCKEE	11/17/2019	8/15/2022	12/9/2021	INSPTR	PG6512
TRUCKEE	11/17/2019	8/15/2022	12/10/2021	INSPTR	SM3126
TRUCKEE	11/17/2019	8/15/2022	1/29/2022	INSPTR	DD6738
TRUCKEE	11/17/2019	8/13/2022	4/7/2022	INSPTR	JH3145
TRUCKEE	11/17/2019	8/15/2022	12/10/2021	INSPTR	SM3126
TRUCKEE	11/17/2019	8/15/2022	12/10/2021	INSPTR	SM3126
TRUCKEE	11/17/2019	8/15/2022	4/4/2022	INSPTR	JH3145
TRUCKEE	11/17/2019	8/13/2022	4/7/2022	INSPTR	JH3145
TRUCKEE	11/17/2019	8/13/2022	10/13/2021	INSPTR	PG6512
TRUCKEE	11/17/2019	8/15/2022	3/8/2022	INSPTR	PG6512
TRUCKEE	11/17/2019	8/14/2022	12/10/2021	INSPTR	SM3126
TRUCKEE	11/17/2019	8/14/2022	11/24/2021	INSPTR	DD6738
TRUCKEE	11/17/2019	8/15/2022	3/8/2022	INSPTR	PG6512
TRUCKEE	11/17/2019	8/15/2022	12/10/2021	INSPTR	SM3126
TRUCKEE	11/17/2019	8/15/2022	3/29/2022	INSPTR	JQ2645
TRUCKEE	11/17/2019	8/14/2022	11/29/2021	INSPTR	DD6738
TRUCKEE	11/17/2019	8/15/2022	2/16/2022	INSPTR	DD6738
TRUCKEE	11/17/2019	8/13/2022	3/8/2022	INSPTR	PG6512
TRUCKEE	11/17/2019	8/14/2022	12/10/2021	INSPTR	SM3126
TRUCKEE	11/17/2019	8/15/2022	3/29/2022	INSPTR	JQ2645
TRUCKEE	11/17/2019	8/15/2022	3/29/2022	INSPTR	JQ2645
TRUCKEE	11/17/2019	8/13/2022	11/27/2021	INSPTR	DD6738
TRUCKEE	11/17/2019	8/13/2022	4/2/2022	INSPTR	DD6738
TRUCKEE	11/17/2019	8/13/2022	12/10/2021	INSPTR	JQ2645
TRUCKEE	11/17/2019	8/14/2022	12/10/2021	INSPTR	SM3126
TRUCKEE	11/17/2019	8/15/2022	3/29/2022	INSPTR	JQ2645
TRUCKEE	11/17/2019	8/14/2022	5/18/2022	INSPTR	DD6738
NEVADA CITY	11/17/2019	8/16/2022	9/10/2021	INSPTR	NH2812
ALTA/DUTCH FLATS	11/20/2019	8/28/2020	3/22/2021	INSPTR	
ALTA/DUTCH FLATS	11/20/2019	8/28/2020	3/22/2021	INSPTR	
ALTA/DUTCH FLATS	11/20/2019	8/28/2020	3/22/2021	INSPTR	
ALTA/DUTCH FLATS	11/20/2019	8/28/2020	3/22/2021	INSPTR	
ALTA/DUTCH FLATS	11/20/2019	8/28/2020	2/13/2020	INSPTR	
ALTA/DUTCH FLATS	11/20/2019	8/22/2020	11/20/2019	INSPTR	SC2675
ALTA/DUTCH FLATS	11/20/2019	8/27/2020	12/1/2020	INSPTR	
ALTA/DUTCH FLATS	11/20/2019	8/28/2020	12/1/2020	INSPTR	
ALTA/DUTCH FLATS	11/20/2019	8/28/2020	12/1/2020	INSPTR	
ALTA/DUTCH FLATS	11/20/2019	8/28/2020	12/1/2020	INSPTR	
ALTA/DUTCH FLATS	11/20/2019	2/22/2020	2/12/2020	INSPTR	
ALTA/DUTCH FLATS	11/20/2019	2/27/2020	6/28/2021	INSPTR	
ALTA/DUTCH FLATS	11/20/2019	8/29/2024	4/9/2024	INSPTR	SC2675

ALTA/DUTCH FLATS	11/20/2019	8/30/2019	10/27/2020	INSPTR	
ALTA/DUTCH FLATS	11/20/2019	8/28/2022	3/15/2022	INSPTR	JM3821
ALTA/DUTCH FLATS	11/20/2019	8/27/2022	3/15/2022	INSPTR	JI2512
ALTA/DUTCH FLATS	11/20/2019	8/28/2022	3/12/2022	INSPTR	EL8648
ALTA/DUTCH FLATS	11/20/2019	8/28/2022	3/15/2022	INSPTR	JM3821
ALTA/DUTCH FLATS	11/20/2019	8/28/2022	3/16/2022	INSPTR	EL8648
ALTA/DUTCH FLATS	11/20/2019	8/22/2022	3/14/2022	INSPTR	JA1893
ALTA/DUTCH FLATS	11/20/2019	8/10/2022	3/14/2022	INSPTR	BK2151
QUINCY	11/26/2019	9/23/2022	9/23/2021	INSPTR	SF8537
QUINCY	11/26/2019	9/22/2022	9/23/2021	INSPTR	SF8537
QUINCY	11/26/2019	9/22/2022	9/23/2021	INSPTR	SF8537
QUINCY	11/26/2019	9/22/2022	9/23/2021	INSPTR	SF8537
QUINCY	11/26/2019	9/22/2022	9/22/2021	INSPTR	SF8537
QUINCY	11/26/2019	9/22/2022	9/23/2021	INSPTR	SF8537
QUINCY	11/26/2019	9/23/2022	9/24/2021	INSPTR	MM9751
QUINCY	11/26/2019	9/22/2022	9/22/2021	INSPTR	SF8537
BLAIRSDEN	12/12/2019	12/14/2019	12/12/2019	SF8537	SF8537
TRUCKEE	12/13/2019	9/19/2020	9/15/2020	INSPTR	
TRUCKEE	12/13/2019	9/20/2022	11/25/2021	INSPTR	JH3145
TRUCKEE	12/13/2019	9/20/2022	11/24/2021	INSPTR	JH3145
GRASS VALLEY	2/1/2020	1/31/2023	2/26/2022	RX2347	AM8121
QUINCY	2/7/2020	2/9/2020	2/7/2020	SF8537	SF8537
PORTOLA	2/22/2020	2/24/2020	2/24/2020	SF8537	SF8537
QUINCY	3/4/2020	3/6/2020	3/6/2020	SF8537	SF8537
QUINCY	3/25/2020	3/27/2020	3/30/2020	SF8537	SF8537
DOWNEYVILLE	4/1/2020	4/4/2020	4/30/2020	MR2414	
NEVADA CITY	4/8/2020	4/10/2020	4/30/2020	RD3541	
NEVADA CITY	4/8/2020	4/10/2020	4/14/2020	RD3541	
QUINCY	5/12/2020	5/14/2020	5/12/2020	SF8537	SF8537
QUINCY	5/28/2020	5/30/2020	6/1/2020	SF8537	SF8537
BLAIRSDEN	6/2/2020	6/4/2020	6/3/2020	SF8537	SF8537
GRASS VALLEY	6/11/2020	6/10/2023	3/5/2022	RX2347	JM3821
LOYALTON	7/14/2020	7/16/2020	7/14/2020	SF8537	SF8537
PORTOLA	7/15/2020	7/17/2020	7/30/2020	SF8537	SF8537
SIERRAVILLE	7/15/2020	7/17/2020	7/15/2020	SF8537	SF8537
PORTOLA	7/15/2020	7/17/2020	7/20/2020	SF8537	SF8537
PORTOLA	7/15/2020	7/17/2020	7/15/2020	SF8537	SF8537
LOYALTON	7/15/2020	7/17/2020	7/16/2020	SF8537	SF8537
LOYALTON	7/21/2020	7/23/2020	7/27/2020	SF8537	SF8537
BLAIRSDEN	7/22/2020	7/24/2020	7/27/2020	SF8537	SF8537
PORTOLA	7/28/2020	7/30/2020	7/28/2020	SF8537	SF8537
LOYALTON	7/29/2020	7/31/2020	8/4/2020	SF8537	SF8537
LOYALTON	7/29/2020	7/31/2020	7/30/2020	SF8537	SF8537
QUINCY	8/5/2020	8/7/2020	8/5/2020	SF8537	SF8537

BLAIRSDEN	8/5/2020	8/7/2020	8/5/2020	SF8537	SF8537
PORTOLA	8/5/2020	8/7/2020	8/6/2020	SF8537	SF8537
QUINCY	8/7/2020	8/9/2020	8/7/2020	SF8537	SF8537
QUINCY	8/20/2020	8/22/2020	9/11/2020	SF8537	SF8537
PORTOLA	9/15/2020	9/17/2020	9/18/2020	SF8537	SF8537
LOYALTON	9/22/2020	9/24/2020	9/23/2020	SF8537	SF8537
PORTOLA	9/29/2020	10/1/2020	9/29/2020	SF8537	SF8537
PORTOLA	9/29/2020	10/1/2020	9/29/2020	SF8537	SF8537
LOYALTON	10/16/2020	10/18/2020	10/16/2020	SF8537	SF8537
BLAIRSDEN	10/28/2020	10/30/2020	10/28/2020	SF8537	SF8537
QUINCY	1/15/2021	1/17/2021	1/15/2021	SF8537	SF8537
PORTOLA	1/15/2021	1/17/2021	1/15/2021	SF8537	SF8537
QUINCY	2/17/2021	2/19/2021	2/17/2021	SF8537	SF8537
ALTA/DUTCH FLATS	2/20/2021	4/26/2021	3/14/2021	INSPTR	SC2675
ALTA/DUTCH FLATS	2/20/2021	4/27/2021	6/28/2021	INSPTR	
ALTA/DUTCH FLATS	2/20/2021	4/27/2021	3/14/2021	INSPTR	SC2675
ALTA/DUTCH FLATS	2/20/2021	4/26/2021	8/29/2021	INSPTR	JS3172
ALTA/DUTCH FLATS	2/20/2021	4/26/2021	8/24/2021	INSPTR	TL3147
CAMPTONVILLE	2/20/2021	5/12/2021	5/12/2021	INSPTR	SM4953
CAMPTONVILLE	2/20/2021	5/12/2021	8/30/2021	INSPTR	SM4953
CAMPTONVILLE	2/20/2021	5/12/2021	7/16/2021	INSPTR	NH2812
CAMPTONVILLE	2/20/2021	5/12/2021	7/21/2021	INSPTR	NH2812
CAMPTONVILLE	2/20/2021	5/12/2021	7/19/2021	INSPTR	NH2812
CAMPTONVILLE	2/20/2021	5/12/2021	7/16/2021	INSPTR	NH2812
CAMPTONVILLE	2/20/2021	5/12/2021	7/16/2021	INSPTR	NH2812
CAMPTONVILLE	2/20/2021	5/12/2021	7/16/2021	INSPTR	NH2812
CAMPTONVILLE	2/20/2021	5/12/2021	4/7/2021	INSPTR	SM4953
CAMPTONVILLE	2/20/2021	5/12/2021	8/30/2021	INSPTR	SM4953
CHALLENGE	2/20/2021	4/27/2021	5/21/2021	INSPTR	AC1532
CHALLENGE	2/20/2021	4/27/2021	5/11/2021	INSPTR	AC1532
CHALLENGE	2/20/2021	4/27/2021	5/11/2021	INSPTR	AC1532
DOWNEYVILLE	2/20/2021	5/18/2021	7/19/2021	INSPTR	
ALTA/DUTCH FLATS	2/20/2021	4/27/2021	6/28/2021	INSPTR	
ALTA/DUTCH FLATS	2/20/2021	4/27/2021	7/12/2021	INSPTR	
ALTA/DUTCH FLATS	2/20/2021	4/27/2021	6/22/2021	INSPTR	

ALTA/DUTCH FLATS	2/20/2021	4/28/2021	6/22/2021	INSPTR	
ALTA/DUTCH FLATS	2/20/2021	4/27/2021	3/13/2021	INSPTR	SC2675
ALTA/DUTCH FLATS	2/20/2021	4/27/2021	3/9/2021	INSPTR	SC2675
CAMPTONVILLE	2/20/2021	5/13/2021	7/2/2021	INSPTR	EK6957
GRASS VALLEY	2/20/2021	4/30/2021	7/6/2021	INSPTR	
GRASS VALLEY	2/20/2021	4/29/2021	3/24/2021	INSPTR	NH2812
GRASS VALLEY	2/20/2021	4/28/2021	3/24/2021	INSPTR	JM1295
GRASS VALLEY	2/20/2021	4/27/2021	2/23/2021	INSPTR	EK6957
CAMPTONVILLE	2/20/2021	5/12/2021	7/16/2021	INSPTR	NH2812
CAMPTONVILLE	2/20/2021	5/12/2021	7/12/2021	INSPTR	NH2812
CAMPTONVILLE	2/20/2021	5/12/2021	5/25/2021	INSPTR	EK6957
CAMPTONVILLE	2/20/2021	5/12/2021	7/12/2021	INSPTR	EK6957
GRASS VALLEY	2/20/2021	4/24/2021	3/16/2021	INSPTR	NH2812
ALLEGHANEY	2/20/2021	6/2/2021	4/22/2021	INSPTR	SM4953
ALLEGHANEY	2/20/2021	6/2/2021	5/12/2021	INSPTR	SM4953
GRASS VALLEY	2/20/2021	4/29/2021	4/14/2021	INSPTR	NH2812
GRASS VALLEY	2/20/2021	4/26/2021	3/14/2021	INSPTR	VC6131
GRASS VALLEY	2/20/2021	4/29/2021	6/28/2021	INSPTR	
GRASS VALLEY	2/20/2021	4/26/2021	3/14/2021	INSPTR	VC6131
ALTA/DUTCH FLATS	2/20/2021	10/27/2023	3/21/2022	INSPTR	DI1638
ALTA/DUTCH FLATS	2/20/2021	10/26/2023	3/19/2022	INSPTR	BK2151
ALTA/DUTCH FLATS	2/20/2021	10/26/2023	3/20/2022	INSPTR	NP5869
CAMPTONVILLE	2/20/2021	11/12/2023	3/8/2022	INSPTR	EL8648
ALTA/DUTCH FLATS	2/20/2021	10/27/2023	3/27/2022	INSPTR	MD4156
ALTA/DUTCH FLATS	2/20/2021	10/27/2023	3/26/2022	INSPTR	PC9347
ALTA/DUTCH FLATS	2/20/2021	10/27/2023	3/19/2022	INSPTR	JS6852
ALTA/DUTCH FLATS	2/20/2021	10/27/2023	3/27/2022	INSPTR	MD4156
ALTA/DUTCH FLATS	2/20/2021	10/26/2023	3/27/2022	INSPTR	MD4156
ALTA/DUTCH FLATS	2/20/2021	10/28/2023	3/21/2022	INSPTR	OD4318
CHALLENGE	2/20/2021	10/24/2023	10/27/2022	INSPTR	AC1532
ALTA/DUTCH FLATS	2/20/2021	10/26/2023	3/21/2022	INSPTR	PC9347
ALTA/DUTCH FLATS	2/20/2021	10/28/2023	3/20/2022	INSPTR	NP5869
CHALLENGE	2/20/2021	10/23/2023	10/31/2022	INSPTR	AC1532
CHALLENGE	2/20/2021	10/23/2023	11/7/2022	INSPTR	AC1532
CHALLENGE	2/20/2021	10/23/2023	10/31/2022	INSPTR	AC1532
GRASS VALLEY	2/20/2021	10/26/2023	3/5/2022	INSPTR	EL8648
GRASS VALLEY	2/20/2021	10/26/2023	3/6/2022	INSPTR	JM2792
GRASS VALLEY	2/20/2021	10/28/2023	9/13/2022	INSPTR	GG8932
GRASS VALLEY	2/20/2021	10/27/2023	3/5/2022	INSPTR	JM2792

ALTA/DUTCH FLATS	2/20/2021	10/27/2023	3/21/2022	INSPTR	NP5869
GRASS VALLEY	2/20/2021	10/27/2023	3/5/2022	INSPTR	JM3821
GRASS VALLEY	2/20/2021	10/28/2023	9/17/2022	INSPTR	PC9347
GRASS VALLEY	2/20/2021	10/28/2023	9/13/2022	INSPTR	DM820T
GRASS VALLEY	2/20/2021	10/26/2023	3/5/2022	INSPTR	DI1638
GRASS VALLEY	2/20/2021	10/28/2023	9/14/2022	INSPTR	RW5286
GRASS VALLEY	2/20/2021	10/26/2023	3/5/2022	INSPTR	DI1638
GRASS VALLEY	2/20/2021	10/24/2023	3/5/2022	INSPTR	JM2792
ALLEGHANEY	2/20/2021	12/2/2023	3/6/2022	INSPTR	JM2792
ALLEGHANEY	2/20/2021	12/2/2023	3/8/2022	INSPTR	EL8648
GRASS VALLEY	2/20/2021	10/26/2023	3/5/2022	INSPTR	JM3821
GRASS VALLEY	2/20/2021	10/28/2023	9/6/2022	INSPTR	RW5286
GRASS VALLEY	2/20/2021	10/26/2023	3/6/2022	INSPTR	MG1262
GRASS VALLEY	2/20/2021	10/28/2023	3/5/2022	INSPTR	JM2792
GRASS VALLEY	2/20/2021	10/26/2023	3/5/2022	INSPTR	SM1897
GRASS VALLEY	2/20/2021	10/26/2023	3/5/2022	INSPTR	EL8648
GRASS VALLEY	2/20/2021	10/28/2023	3/5/2022	INSPTR	EL8648
GRASS VALLEY	2/20/2021	10/28/2023	3/5/2022	INSPTR	JI2512
GRASS VALLEY	2/20/2021	10/28/2023	3/5/2022	INSPTR	JI2512
GRASS VALLEY	2/20/2021	10/26/2023	3/5/2022	INSPTR	JS6852
GRASS VALLEY	2/20/2021	10/28/2023	3/5/2022	INSPTR	MM3647
GRASS VALLEY	2/20/2021	10/26/2023	3/6/2022	INSPTR	MG1262

GRASS VALLEY	2/21/2021	5/3/2021	6/28/2021	INSPTR	
GRASS VALLEY	2/21/2021	5/2/2021	2/28/2021	INSPTR	EK6957
GRASS VALLEY	2/21/2021	11/2/2023	9/17/2022	INSPTR	DM820T
GRASS VALLEY	2/21/2021	11/3/2023	9/17/2022	INSPTR	DM820T
GRASS VALLEY	2/21/2021	11/2/2023	9/15/2022	INSPTR	MD4156
GRASS VALLEY	2/21/2021	11/2/2023	9/16/2022	INSPTR	AG2675
GRASS VALLEY	2/21/2021	11/3/2023	9/15/2022	INSPTR	MM3647
GRASS VALLEY	2/21/2021	10/28/2023	3/5/2022	INSPTR	AG2675
GRASS VALLEY	2/21/2021	10/26/2023	3/5/2022	INSPTR	AG2675
GRASS VALLEY	2/21/2021	11/10/2023	9/17/2022	INSPTR	LP848K
GRASS VALLEY	2/21/2021	11/9/2023	9/10/2022	INSPTR	GG8932
GRASS VALLEY	2/21/2021	11/2/2023	9/15/2022	INSPTR	QB6851
TRUCKEE	2/22/2021	5/22/2021	2/22/2021	INSPTR	TL5296
SIERRA CITY	2/22/2021	11/21/2021	5/17/2021	INSPTR	EK6957
SIERRA CITY	2/22/2021	11/21/2021	10/13/2021	INSPTR	SM4953
SIERRA CITY	2/22/2021	11/21/2021	3/19/2021	INSPTR	SM4953
SIERRA CITY	2/22/2021	11/21/2021	3/17/2021	INSPTR	SM4953
SIERRA CITY	2/22/2021	11/21/2021	8/30/2021	INSPTR	SM4953
SIERRA CITY	2/22/2021	11/21/2021	8/30/2021	INSPTR	SM4953

TRUCKEE	2/22/2021	5/22/2021	2/24/2021	INSPTR	JQ2645
SIERRA CITY	2/22/2021	11/21/2021	10/13/2021	INSPTR	SM4953
TRUCKEE	2/22/2021	11/22/2023	3/3/2023	INSPTR	JH3145
TRUCKEE	2/22/2021	11/24/2023	7/21/2023	INSPTR	DD1636
TRUCKEE	2/22/2021	11/22/2023	4/27/2023	INSPTR	DD6738
TRUCKEE	2/22/2021	11/24/2023	3/1/2023	INSPTR	JH3145
TRUCKEE	2/22/2021	11/23/2023	4/25/2023	INSPTR	DD6738
TRUCKEE	2/22/2021	11/24/2023	7/22/2023	INSPTR	DD1636
TRUCKEE	2/22/2021	11/22/2023	4/26/2023	INSPTR	DD6738
TRUCKEE	2/22/2021	11/23/2023	7/6/2023	INSPTR	PG6512
TRUCKEE	2/22/2021	11/24/2023	5/8/2023	INSPTR	DD6738
TRUCKEE	2/22/2021	11/23/2023	1/9/2023	INSPTR	CD5628
TRUCKEE	2/22/2021	11/22/2023	3/3/2023	INSPTR	JH3145
TRUCKEE	2/22/2021	11/22/2023	3/3/2023	INSPTR	DD6738
TRUCKEE	2/22/2021	11/21/2023	3/3/2023	INSPTR	JH3145
TRUCKEE	2/22/2021	11/21/2023	11/24/2022	INSPTR	JH3145
TRUCKEE	2/22/2021	11/21/2023	11/24/2022	INSPTR	JH3145
TRUCKEE	2/22/2021	11/24/2023	4/19/2023	INSPTR	JH3145
TRUCKEE	2/22/2021	11/23/2023	6/28/2023	INSPTR	PG6512
TRUCKEE	2/22/2021	11/24/2023	2/27/2023	INSPTR	JH3145
TRUCKEE	2/22/2021	11/22/2023	12/5/2022	INSPTR	CD5628
TRUCKEE	2/22/2021	11/23/2023	4/26/2023	INSPTR	WC8687
TRUCKEE	2/22/2021	11/22/2023	3/3/2023	INSPTR	DD6738
TRUCKEE	2/22/2021	11/22/2023	3/3/2023	INSPTR	DD6738
TRUCKEE	2/22/2021	11/23/2023	7/21/2023	INSPTR	PG2676
TRUCKEE	2/22/2021	11/24/2023	6/5/2023	INSPTR	WC8687
TRUCKEE	2/22/2021	11/24/2023	5/9/2023	INSPTR	DD6738
TRUCKEE	2/22/2021	11/24/2023	1/30/2023	INSPTR	DD6738
TRUCKEE	2/22/2021	11/22/2023	2/7/2023	INSPTR	DD6738
TRUCKEE	2/22/2021	11/24/2023	12/22/2022	INSPTR	DD6738
TRUCKEE	2/22/2021	11/22/2023	12/5/2022	INSPTR	CD5628
TRUCKEE	2/22/2021	11/24/2023	5/8/2023	INSPTR	DD6738
TRUCKEE	2/22/2021	11/22/2023	4/25/2023	INSPTR	PG6512
TRUCKEE	2/22/2021	11/22/2023	12/15/2022	INSPTR	DD6738
TRUCKEE	2/22/2021	11/24/2023	4/26/2023	INSPTR	DD6738
TRUCKEE	2/22/2021	11/21/2023	12/15/2022	INSPTR	CD5628
TRUCKEE	2/22/2021	11/21/2023	12/20/2022	INSPTR	DD6738
TRUCKEE	2/22/2021	11/21/2023	11/28/2022	INSPTR	CD5628
TRUCKEE	2/22/2021	11/21/2023	12/2/2022	INSPTR	WC8687
TRUCKEE	2/22/2021	11/21/2023	11/24/2022	INSPTR	JH3145
TRUCKEE	2/22/2021	11/21/2023	12/21/2022	INSPTR	DD6738
TRUCKEE	2/22/2021	11/21/2023	11/24/2022	INSPTR	JH3145
TRUCKEE	2/22/2021	11/23/2023	1/9/2023	INSPTR	CD5628
TRUCKEE	2/22/2021	11/24/2023	4/26/2023	INSPTR	PG6512

TRUCKEE	2/22/2021	11/23/2023	1/9/2023	INSPTR	CD5628
TRUCKEE	2/22/2021	11/23/2023	5/9/2023	INSPTR	DD6738
TRUCKEE	2/22/2021	11/23/2023	5/4/2023	INSPTR	DD6738
TRUCKEE	2/22/2021	11/24/2023	8/3/2023	INSPTR	DD6738
TRUCKEE	2/22/2021	11/22/2023	12/15/2022	INSPTR	CD5628
TRUCKEE	2/22/2021	11/23/2023	5/10/2023	INSPTR	DD6738
TRUCKEE	2/22/2021	11/23/2023	4/28/2023	INSPTR	PG6512
TRUCKEE	2/22/2021	11/24/2023	7/28/2023	INSPTR	DD6738
TRUCKEE	2/22/2021	11/22/2023	12/15/2022	INSPTR	DD6738
TRUCKEE	2/22/2021	11/22/2023	12/15/2022	INSPTR	DD6738
TRUCKEE	2/22/2021	11/22/2023	7/21/2023	INSPTR	DM141G
TRUCKEE	2/22/2021	11/24/2023	4/25/2023	INSPTR	DD6738
TRUCKEE	2/22/2021	11/23/2023	2/3/2023	INSPTR	DD6738
TRUCKEE	2/22/2021	11/24/2023	12/20/2022	INSPTR	DD6738
TRUCKEE	2/22/2021	11/23/2023	5/5/2023	INSPTR	DD6738
TRUCKEE	2/22/2021	11/24/2023	7/24/2023	INSPTR	PG2676
TRUCKEE	2/22/2021	11/22/2023	1/23/2023	INSPTR	CD5628
TRUCKEE	2/22/2021	11/22/2023	4/25/2023	INSPTR	PG6512
TRUCKEE	2/22/2021	11/24/2023	7/24/2023	INSPTR	DD1636
TRUCKEE	2/22/2021	11/22/2023	4/21/2023	INSPTR	DD6738
TRUCKEE	2/22/2021	11/24/2023	4/6/2023	INSPTR	PG6512
TRUCKEE	2/22/2021	11/22/2023	1/6/2023	INSPTR	DD6738
TRUCKEE	2/22/2021	11/24/2023	9/1/2023	INSPTR	DD6738
TRUCKEE	2/22/2021	11/23/2023	2/3/2023	INSPTR	DD6738
TRUCKEE	2/22/2021	11/24/2023	4/25/2023	INSPTR	DD6738
TRUCKEE	2/22/2021	11/22/2023	4/12/2023	INSPTR	PG6512
TRUCKEE	2/22/2021	11/23/2023	5/16/2023	INSPTR	DD6738
TRUCKEE	2/22/2021	11/24/2023	7/22/2023	INSPTR	PG2676
TRUCKEE	2/22/2021	11/23/2023	12/22/2022	INSPTR	DD6738
TRUCKEE	2/22/2021	11/23/2023	4/25/2023	INSPTR	JH3145
TRUCKEE	2/22/2021	11/22/2023	1/10/2023	INSPTR	DD6738
TRUCKEE	2/22/2021	11/22/2023	1/6/2023	INSPTR	DD6738
TRUCKEE	2/22/2021	11/22/2023	4/25/2023	INSPTR	WC8687
TRUCKEE	2/22/2021	11/22/2023	1/10/2023	INSPTR	DD6738
TRUCKEE	2/22/2021	11/23/2023	5/23/2023	INSPTR	DD6738
TRUCKEE	2/22/2021	11/22/2023	11/25/2022	INSPTR	JH3145
TRUCKEE	2/22/2021	11/23/2023	3/1/2023	INSPTR	DD6738
TRUCKEE	2/22/2021	11/23/2023	5/31/2023	INSPTR	DD6738
TRUCKEE	2/22/2021	11/23/2023	5/16/2023	INSPTR	DD6738
TRUCKEE	2/22/2021	11/23/2023	5/10/2023	INSPTR	CD5628
TRUCKEE	2/22/2021	11/22/2023	11/25/2022	INSPTR	JH3145
TRUCKEE	2/22/2021	11/24/2023	6/30/2023	INSPTR	DD6738
TRUCKEE	2/22/2021	11/22/2023	1/23/2023	INSPTR	CD5628
TRUCKEE	2/22/2021	11/23/2023	4/25/2023	INSPTR	DD6738

TRUCKEE	2/22/2021	11/24/2023	4/25/2023	INSPTR	CD5628
TRUCKEE	2/22/2021	11/24/2023	4/20/2023	INSPTR	CD5628
TRUCKEE	2/22/2021	11/24/2023	1/25/2023	INSPTR	DD6738
NEVADA CITY	2/24/2021	5/3/2021	7/12/2021	INSPTR	
LAKE WILDWOOD	2/24/2021	11/9/2021	7/6/2021	INSPTR	
NEVADA CITY	2/24/2021	5/4/2021	5/8/2021	INSPTR	PC9347
NEVADA CITY	2/24/2021	4/30/2021	5/8/2021	INSPTR	DL1623
NEVADA CITY	2/24/2021	4/30/2021	3/18/2021	INSPTR	JM1295
NEVADA CITY	2/24/2021	4/30/2021	3/18/2021	INSPTR	EK6957
NEVADA CITY	2/24/2021	4/30/2021	3/18/2021	INSPTR	SM4953
NEVADA CITY	2/24/2021	4/30/2021	5/11/2021	INSPTR	EK6957
NEVADA CITY	2/24/2021	5/4/2021	6/28/2021	INSPTR	
NEVADA CITY	2/24/2021	5/3/2021	7/19/2021	INSPTR	
NEVADA CITY	2/24/2021	4/29/2021	4/13/2021	INSPTR	NH2812
NEVADA CITY	2/24/2021	4/30/2021	5/10/2021	INSPTR	EK6957
NEVADA CITY	2/24/2021	4/30/2021	5/10/2021	INSPTR	EK6957
NEVADA CITY	2/24/2021	5/4/2021	5/14/2021	INSPTR	EK6957
NEVADA CITY	2/24/2021	4/29/2021	3/7/2021	INSPTR	EK6957
NEVADA CITY	2/24/2021	4/30/2021	3/16/2021	INSPTR	EK6957
NEVADA CITY	2/24/2021	5/3/2021	7/19/2021	INSPTR	
NEVADA CITY	2/24/2021	5/4/2021	5/17/2021	INSPTR	EK6957
LAKE WILDWOOD	2/24/2021	11/11/2021	3/14/2021	INSPTR	TS3269
LAKE WILDWOOD	2/24/2021	11/10/2021	3/8/2021	INSPTR	NH2812
NEVADA CITY	2/24/2021	5/4/2021	5/8/2021	INSPTR	QB6851
LAKE WILDWOOD	2/24/2021	11/10/2021	3/8/2021	INSPTR	FR1292
NEVADA CITY	2/24/2021	4/30/2021	7/6/2021	INSPTR	

NEVADA CITY	2/24/2021	4/29/2021	5/13/2021	INSPTR	EK6957
LAKE WILDWOOD	2/24/2021	11/9/2021	7/6/2021	INSPTR	
LAKE WILDWOOD	2/24/2021	11/9/2021	3/7/2021	INSPTR	FR1292
LAKE WILDWOOD	2/24/2021	11/11/2021	3/8/2021	INSPTR	MS7970
NEVADA CITY	2/24/2021	5/4/2021	7/6/2021	INSPTR	
NEVADA CITY	2/24/2021	11/3/2023	9/17/2022	INSPTR	MM3647
LAKE WILDWOOD	2/24/2021	11/7/2023	9/14/2022	INSPTR	DM820T
NEVADA CITY	2/24/2021	11/4/2023	9/26/2022	INSPTR	GG8932
NEVADA CITY	2/24/2021	10/29/2023	9/11/2022	INSPTR	JM1295
NEVADA CITY	2/24/2021	10/29/2023	9/15/2022	INSPTR	JI2512
NEVADA CITY	2/24/2021	10/30/2023	9/17/2022	INSPTR	GG8932
LAKE WILDWOOD	2/24/2021	11/9/2023	9/14/2022	INSPTR	DM6529
NEVADA CITY	2/24/2021	11/4/2023	9/17/2022	INSPTR	MM3647
NEVADA CITY	2/24/2021	11/2/2023	9/18/2022	INSPTR	BR5481
NEVADA CITY	2/24/2021	11/4/2023	9/22/2022	INSPTR	PC9347
NEVADA CITY	2/24/2021	10/29/2023	9/11/2022	INSPTR	QB6851
LAKE WILDWOOD	2/24/2021	11/11/2023	9/21/2022	INSPTR	QB6851
NEVADA CITY	2/24/2021	11/2/2023	9/18/2022	INSPTR	MD4156
NEVADA CITY	2/24/2021	11/2/2023	9/17/2022	INSPTR	MM3647
NEVADA CITY	2/24/2021	11/4/2023	9/17/2022	INSPTR	RN2732
NEVADA CITY	2/24/2021	11/4/2023	9/19/2022	INSPTR	VC6131
LAKE WILDWOOD	2/24/2021	11/9/2023	9/16/2022	INSPTR	DM6529
LAKE WILDWOOD	2/24/2021	11/12/2023	9/16/2022	INSPTR	DM820T
LAKE WILDWOOD	2/24/2021	11/11/2023	9/13/2022	INSPTR	MD4156
NEVADA CITY	2/24/2021	11/2/2023	9/13/2022	INSPTR	PC9347
NEVADA CITY	2/24/2021	10/29/2023	9/17/2022	INSPTR	MD4156
LAKE WILDWOOD	2/24/2021	11/11/2023	10/3/2022	INSPTR	MD4156
NEVADA CITY	2/24/2021	11/2/2023	10/3/2022	INSPTR	JM1295
LAKE WILDWOOD	2/24/2021	11/7/2023	9/16/2022	INSPTR	QB6851
NORTH SAN JUAN	2/25/2021	11/10/2021	7/12/2021	INSPTR	
NEVADA CITY	2/25/2021	11/3/2021	7/6/2021	INSPTR	
NORTH SAN JUAN	2/25/2021	5/10/2021	5/20/2021	INSPTR	SM4953
NORTH SAN JUAN	2/25/2021	5/10/2021	7/21/2021	INSPTR	NH2812
NORTH SAN JUAN	2/25/2021	5/10/2021	4/12/2021	INSPTR	SM4953
NORTH SAN JUAN	2/25/2021	5/10/2021	3/7/2021	INSPTR	EK6957
NORTH SAN JUAN	2/25/2021	5/10/2021	8/29/2021	INSPTR	SM4953
NORTH SAN JUAN	2/25/2021	5/10/2021	5/24/2021	INSPTR	RD3541
NORTH SAN JUAN	2/25/2021	5/10/2021	7/15/2021	INSPTR	EK6957

NEVADA CITY	2/25/2021	5/4/2021	7/6/2021	INSPTR	
NEVADA CITY	2/25/2021	5/3/2021	4/8/2021	INSPTR	SM4953
NEVADA CITY	2/25/2021	5/4/2021	4/11/2021	INSPTR	SM4953
NEVADA CITY	2/25/2021	5/4/2021	4/23/2021	INSPTR	EK6957
NEVADA CITY	2/25/2021	5/4/2021	5/10/2021	INSPTR	EK6957
PORTOLA	2/25/2021	11/22/2021	3/5/2021	INSPTR	SF8537
PORTOLA	2/25/2021	11/23/2021	3/12/2021	INSPTR	SF8537
PORTOLA	2/25/2021	11/22/2021	3/5/2021	INSPTR	SF8537
PORTOLA	2/25/2021	11/22/2021	2/26/2021	INSPTR	SF8537
PORTOLA	2/25/2021	11/23/2021	3/9/2021	INSPTR	SF8537
PORTOLA	2/25/2021	11/22/2021	3/4/2021	INSPTR	SF8537
PORTOLA	2/25/2021	11/23/2021	3/11/2021	INSPTR	SF8537
PORTOLA	2/25/2021	11/23/2021	3/8/2021	INSPTR	SF8537
PORTOLA	2/25/2021	11/23/2021	3/12/2021	INSPTR	SF8537
PORTOLA	2/25/2021	11/22/2021	3/5/2021	INSPTR	SF8537
PORTOLA	2/25/2021	11/23/2021	3/22/2021	INSPTR	SF8537
PORTOLA	2/25/2021	11/22/2021	2/26/2021	INSPTR	SF8537
PORTOLA	2/25/2021	11/22/2021	3/8/2021	INSPTR	SF8537
PORTOLA	2/25/2021	11/22/2021	3/8/2021	INSPTR	SF8537
NEVADA CITY	2/25/2021	5/5/2021	4/17/2021	INSPTR	RK7932
NEVADA CITY	2/25/2021	5/5/2021	3/8/2021	INSPTR	EK6957
NEVADA CITY	2/25/2021	5/5/2021	3/8/2021	INSPTR	EK6957
NORTH SAN JUAN	2/25/2021	5/10/2021	5/26/2021	INSPTR	QB6851
NORTH SAN JUAN	2/25/2021	5/10/2021	4/7/2021	INSPTR	SM4953
NORTH SAN JUAN	2/25/2021	5/10/2021	5/23/2021	INSPTR	PC9347
NORTH SAN JUAN	2/25/2021	5/10/2021	5/23/2021	INSPTR	PC9347
NORTH SAN JUAN	2/25/2021	5/10/2021	3/1/2021	INSPTR	EK6957
NORTH SAN JUAN	2/25/2021	5/10/2021	2/28/2021	INSPTR	EK6957
NORTH SAN JUAN	2/25/2021	5/6/2021	7/12/2021	INSPTR	
NORTH SAN JUAN	2/25/2021	5/6/2021	7/12/2021	INSPTR	
NORTH SAN JUAN	2/25/2021	5/9/2021	8/27/2021	INSPTR	
QUINCY	2/25/2021	2/27/2021	2/25/2021	SF8537	SF8537
QUINCY	2/25/2021	11/11/2023	11/30/2022	INSPTR	SF8537

NORTH SAN JUAN	2/25/2021	11/10/2023	3/8/2022	INSPTR	EL8648
NORTH SAN JUAN	2/25/2021	11/10/2023	3/8/2022	INSPTR	EL8648
NEVADA CITY	2/25/2021	11/2/2023	9/15/2022	INSPTR	JI2512
NEVADA CITY	2/25/2021	11/2/2023	9/17/2022	INSPTR	MD4156
NEVADA CITY	2/25/2021	11/4/2023	9/27/2022	INSPTR	LP848K
PORTOLA	2/25/2021	11/22/2023	11/29/2022	INSPTR	SF8537
PORTOLA	2/25/2021	11/23/2023	11/29/2022	INSPTR	SF8537
NEVADA CITY	2/25/2021	11/2/2023	9/18/2022	INSPTR	MD4156
NEVADA CITY	2/25/2021	11/3/2023	9/27/2022	INSPTR	LP848K
QUINCY	2/25/2021	11/11/2023	11/29/2022	INSPTR	SF8537
NORTH SAN JUAN	2/25/2021	11/9/2023	3/16/2022	INSPTR	QB6851
NEVADA CITY	2/25/2021	11/5/2023	10/3/2022	INSPTR	JM1295
NEVADA CITY	2/25/2021	11/5/2023	9/14/2022	INSPTR	MD4156
QUINCY	3/4/2021	3/6/2021	3/24/2021	SF8537	MM9751
LOYALTON	3/17/2021	3/19/2021	3/17/2021	SF8537	SF8537
QUINCY	3/24/2021	3/26/2021	4/6/2021	MM9751	
QUINCY	3/26/2021	3/28/2021	3/26/2021	SF8537	SF8537
QUINCY	3/26/2021	3/28/2021	3/26/2021	SF8537	SF8537
QUINCY	4/20/2021	4/23/2021	5/12/2021	SF8537	SF8537
LOYALTON	4/20/2021	4/23/2021	4/22/2021	SF8537	SF8537
CHALLENGE	4/29/2021	4/29/2024	5/12/2023	AC1532	AC1532
TRUCKEE	5/6/2021	5/6/2024	5/2/2024	JQ2645	
BLAIRSDEN	5/28/2021	5/30/2021	5/28/2021	SF8537	SF8537
QUINCY	6/7/2021	6/10/2021	6/8/2021	SF8537	SF8537
QUINCY	6/15/2021	6/17/2021	6/15/2021	SF8537	SF8537
GRASS VALLEY	6/15/2021	6/18/2021	6/17/2021	MR2414	
NEVADA CITY	6/21/2021	6/24/2021	6/24/2021	MR2414	
LAKE WILDWOOD	6/24/2021	6/27/2021	6/29/2021	MR2414	
NEVADA CITY	6/24/2021	6/27/2021	6/29/2021	DW2564	
NEVADA CITY	6/25/2021	6/28/2021	6/30/2021	MR2414	
NEVADA CITY	6/30/2021	7/3/2021	7/7/2021	MR2414	
ALTA/DUTCH FLATS	7/12/2021	7/15/2021	5/10/2022	MR2414	
LOYALTON	7/13/2021	7/15/2021	7/13/2021	SF8537	SF8537
LOYALTON	7/14/2021	7/16/2021	7/14/2021	SF8537	SF8537
ALTA/DUTCH FLATS	7/19/2021	7/22/2021	8/18/2021	DW2564	
BLAIRSDEN	7/23/2021	7/23/2024	8/10/2023	MR2414	SF8537
BLAIRSDEN	7/23/2021	7/23/2022	7/29/2021	MR2414	SF8537
BLAIRSDEN	7/23/2021	7/23/2022	7/29/2021	MR2414	SF8537
BLAIRSDEN	7/23/2021	7/23/2022	7/30/2021	MR2414	SF8537
BLAIRSDEN	7/23/2021	7/23/2022	7/30/2021	MR2414	SF8537
BLAIRSDEN	9/9/2021	7/22/2024	7/27/2023	INSPTR	SF8537
BLAIRSDEN	9/9/2021	7/15/2024	7/18/2023	INSPTR	SF8537
BLAIRSDEN	9/9/2021	7/15/2024	7/18/2023	INSPTR	SF8537
BLAIRSDEN	9/9/2021	7/22/2024	8/10/2023	INSPTR	SF8537

BLAIRSDEN	9/9/2021	7/22/2024	8/10/2023	INSPTR	SF8537
BLAIRSDEN	9/9/2021	7/16/2024	7/28/2023	INSPTR	SF8537
BLAIRSDEN	9/9/2021	7/20/2024	7/28/2023	INSPTR	SF8537
BLAIRSDEN	9/9/2021	7/20/2024	7/28/2023	INSPTR	SF8537
BLAIRSDEN	9/9/2021	7/20/2024	7/28/2023	INSPTR	SF8537
BLAIRSDEN	9/9/2021	7/21/2024	7/27/2023	INSPTR	SF8537
BLAIRSDEN	9/9/2021	7/19/2024	7/27/2023	INSPTR	SF8537
BLAIRSDEN	9/9/2021	7/19/2024	7/27/2023	INSPTR	SF8537
BLAIRSDEN	9/9/2021	7/20/2024	7/28/2023	INSPTR	SF8537
BLAIRSDEN	9/9/2021	7/20/2024	7/28/2023	INSPTR	SF8537
BLAIRSDEN	9/9/2021	7/17/2024	8/4/2023	INSPTR	SF8537
BLAIRSDEN	9/9/2021	7/15/2024	7/17/2023	INSPTR	SF8537
BLAIRSDEN	9/9/2021	7/14/2024	7/18/2023	INSPTR	SF8537
BLAIRSDEN	9/9/2021	7/19/2024	8/4/2023	INSPTR	SF8537
BLAIRSDEN	9/9/2021	7/20/2024	8/10/2023	INSPTR	SF8537
BLAIRSDEN	9/9/2021	7/19/2024	8/22/2023	INSPTR	SF8537
BLAIRSDEN	9/9/2021	7/14/2024	7/18/2023	INSPTR	SF8537
BLAIRSDEN	9/9/2021	7/14/2024	7/18/2023	INSPTR	SF8537
BLAIRSDEN	9/9/2021	7/19/2024	8/4/2023	INSPTR	SF8537
CHALLENGE	9/16/2021	9/16/2022	2/27/2022	MR2414	CC2745
CHALLENGE	9/16/2021	9/16/2022	1/26/2022	MR2414	AC1532
CHALLENGE	9/20/2021	9/20/2024	3/13/2024	DW2564	RH749C
NORTH SAN JUAN	9/23/2021	6/24/2022	3/17/2022	INSPTR	QB6851
NORTH SAN JUAN	9/23/2021	6/30/2022	10/15/2021	INSPTR	SM4953
NORTH SAN JUAN	9/23/2021	12/23/2021	2/28/2022	INSPTR	QB6851
NORTH SAN JUAN	9/23/2021	12/23/2021	2/28/2022	INSPTR	QB6851
NORTH SAN JUAN	9/23/2021	6/23/2026	9/25/2022	INSPTR	TL3147
NORTH SAN JUAN	9/23/2021	6/23/2026	3/19/2022	INSPTR	QB6851
NORTH SAN JUAN	9/23/2021	6/24/2024	3/16/2022	INSPTR	JS2145
NORTH SAN JUAN	9/23/2021	6/24/2024	3/16/2022	INSPTR	MM3647
NORTH SAN JUAN	9/23/2021	6/23/2024	3/15/2022	INSPTR	QB6851
NORTH SAN JUAN	9/23/2021	6/28/2024	3/17/2022	INSPTR	QB6851
NORTH SAN JUAN	9/23/2021	6/23/2024	3/15/2022	INSPTR	QB6851
NORTH SAN JUAN	9/23/2021	6/23/2024	3/17/2022	INSPTR	RW5286
NORTH SAN JUAN	9/23/2021	6/25/2024	3/6/2022	INSPTR	JM2792
NORTH SAN JUAN	9/23/2021	6/23/2024	3/17/2022	INSPTR	DM820T
NORTH SAN JUAN	9/23/2021	6/24/2024	3/15/2022	INSPTR	AG2675
NORTH SAN JUAN	9/23/2021	6/28/2024	3/16/2022	INSPTR	RW5286
NORTH SAN JUAN	9/23/2021	6/28/2024	3/7/2022	INSPTR	EL8648
NORTH SAN JUAN	9/23/2021	6/28/2024	3/16/2022	INSPTR	MM3647
NORTH SAN JUAN	9/23/2021	7/1/2024	3/13/2022	INSPTR	BK2151
NORTH SAN JUAN	9/23/2021	6/29/2024	3/7/2022	INSPTR	EL8648
NORTH SAN JUAN	9/23/2021	6/29/2024	3/6/2022	INSPTR	NP5869
NORTH SAN JUAN	9/23/2021	7/1/2024	3/13/2022	INSPTR	BK2151

NORTH SAN JUAN	9/23/2021	6/24/2024	3/6/2022	INSPTR	EL8648
NORTH SAN JUAN	9/23/2021	1/7/2022	10/15/2021	INSPTR	SM4953
NEVADA CITY	9/30/2021	6/30/2024	8/17/2023	INSPTR	MM3647
NEVADA CITY	9/30/2021	12/24/2021	2/15/2022	INSPTR	DI1638
NEVADA CITY	9/30/2021	12/21/2021	2/25/2022	INSPTR	AG2675
NEVADA CITY	9/30/2021	12/21/2021	2/10/2022	INSPTR	JM1295
NEVADA CITY	9/30/2021	12/21/2021	2/25/2022	INSPTR	OD4318
NEVADA CITY	9/30/2021	1/1/2022	8/15/2022	INSPTR	
NEVADA CITY	9/30/2021	12/29/2021	2/17/2022	INSPTR	SM1897
NEVADA CITY	9/30/2021	6/30/2024	11/17/2023	INSPTR	MM3647
NEVADA CITY	9/30/2021	6/16/2024	7/27/2023	INSPTR	SB6349
NEVADA CITY	9/30/2021	12/24/2021	2/13/2022	INSPTR	QB6851
BLAIRSDEN	9/30/2021	10/2/2021	10/1/2021	SF8537	MM9751
NEVADA CITY	9/30/2021	6/21/2024	12/7/2023	INSPTR	CB281C
NEVADA CITY	9/30/2021	1/2/2022	11/4/2022	INSPTR	
NEVADA CITY	9/30/2021	12/20/2021	2/22/2022	INSPTR	JI2512
NEVADA CITY	10/5/2021	12/22/2021	2/25/2022	INSPTR	AG2675
NEVADA CITY	10/5/2021	6/23/2024	12/7/2023	INSPTR	CB281C
NEVADA CITY	10/5/2021	6/16/2024	7/12/2023	INSPTR	MD4156
NEVADA CITY	10/5/2021	6/23/2024	8/2/2023	INSPTR	MM3647
NEVADA CITY	10/5/2021	6/24/2024	7/31/2023	INSPTR	JS2145
NEVADA CITY	10/5/2021	12/24/2021	2/13/2022	INSPTR	EH3437
NEVADA CITY	10/5/2021	12/28/2021	2/13/2022	INSPTR	EH3437
NEVADA CITY	10/5/2021	12/24/2021	2/13/2022	INSPTR	QB6851
NEVADA CITY	10/5/2021	6/16/2024	8/5/2023	INSPTR	JS2145
NEVADA CITY	10/5/2021	6/16/2024	8/5/2023	INSPTR	JS2145
NEVADA CITY	10/5/2021	6/16/2024	7/27/2023	INSPTR	JS2145
NEVADA CITY	10/5/2021	12/25/2021	2/25/2022	INSPTR	AG2675
NEVADA CITY	10/5/2021	12/31/2021	8/15/2022	INSPTR	
NEVADA CITY	10/5/2021	7/8/2024	7/18/2023	INSPTR	MD4156
NEVADA CITY	10/5/2021	6/17/2024	7/29/2023	INSPTR	MD2797
NEVADA CITY	10/5/2021	6/25/2024	12/7/2023	INSPTR	CB281C
NEVADA CITY	10/5/2021	6/17/2024	7/19/2023	INSPTR	MD4156
NEVADA CITY	10/5/2021	6/17/2024	7/19/2023	INSPTR	MD4156
NEVADA CITY	10/5/2021	6/17/2024	7/19/2023	INSPTR	MD4156
NEVADA CITY	10/5/2021	6/17/2024	8/4/2023	INSPTR	QB6851
NEVADA CITY	10/5/2021	6/17/2024	10/3/2023	INSPTR	MM3647
NEVADA CITY	10/5/2021	6/21/2024	8/2/2023	INSPTR	JS2145
NEVADA CITY	10/5/2021	6/22/2024	8/19/2023	INSPTR	MD4156
NEVADA CITY	10/5/2021	6/22/2024	8/2/2023	INSPTR	JS2145
NEVADA CITY	10/5/2021	12/18/2021	2/25/2022	INSPTR	AG2675
NEVADA CITY	10/5/2021	12/18/2021	1/27/2022	INSPTR	RW5286
NEVADA CITY	10/5/2021	12/18/2021	2/15/2022	INSPTR	JM3821
NEVADA CITY	10/5/2021	12/18/2021	2/22/2022	INSPTR	GG8932

NEVADA CITY	10/5/2021	6/18/2024	7/29/2023	INSPTR	MD2797
NEVADA CITY	10/5/2021	6/29/2024	7/27/2023	INSPTR	DM820T
NEVADA CITY	10/5/2021	7/2/2024	7/27/2023	INSPTR	DM820T
NEVADA CITY	10/5/2021	7/2/2024	7/27/2023	INSPTR	DM820T
NEVADA CITY	10/5/2021	1/2/2022	2/21/2022	INSPTR	BK2151
NEVADA CITY	10/5/2021	7/8/2024	7/18/2023	INSPTR	MD4156
NEVADA CITY	10/5/2021	12/28/2021	9/8/2022	INSPTR	
NEVADA CITY	10/5/2021	12/28/2021	11/3/2022	INSPTR	
NEVADA CITY	10/5/2021	12/29/2021	2/25/2022	INSPTR	AG2675
NEVADA CITY	10/5/2021	6/29/2024	8/10/2023	INSPTR	RC5742
NEVADA CITY	10/5/2021	6/29/2024	8/9/2023	INSPTR	RC5742
NEVADA CITY	10/5/2021	7/8/2024	7/18/2023	INSPTR	MD4156
NEVADA CITY	10/5/2021	12/28/2021	2/22/2022	INSPTR	GG8932
NEVADA CITY	10/5/2021	12/28/2021	11/4/2022	INSPTR	
NEVADA CITY	10/5/2021	1/13/2022	8/15/2023	INSPTR	
NEVADA CITY	10/5/2021	12/29/2021	2/13/2022	INSPTR	CG4741
NEVADA CITY	10/5/2021	12/29/2021	2/15/2022	INSPTR	AM8121
NEVADA CITY	10/5/2021	12/29/2021	11/4/2022	INSPTR	
NEVADA CITY	10/5/2021	6/29/2024	8/17/2023	INSPTR	DM820T
NEVADA CITY	10/5/2021	6/29/2024	8/7/2023	INSPTR	JO1454
NEVADA CITY	10/5/2021	6/30/2024	8/17/2023	INSPTR	DM820T
NEVADA CITY	10/5/2021	7/2/2022	2/25/2022	INSPTR	DM820T
NEVADA CITY	10/5/2021	7/7/2024	7/31/2023	INSPTR	SB6349
NEVADA CITY	10/5/2021	7/1/2024	9/28/2023	INSPTR	DM820T
NEVADA CITY	10/5/2021	7/2/2024	10/2/2023	INSPTR	MM3647
NEVADA CITY	10/5/2021	1/6/2022	10/17/2021	INSPTR	MD4156
NEVADA CITY	10/5/2021	7/6/2024	8/10/2023	INSPTR	JS2145
NEVADA CITY	10/5/2021	7/7/2024	4/3/2024	INSPTR	MM3647
BLAIRSDEN	10/5/2021	10/4/2021	10/6/2021	SF8537	SF8537
NEVADA CITY	10/5/2021	7/1/2024	8/15/2023	INSPTR	QB6851
NEVADA CITY	10/5/2021	7/1/2024	8/15/2023	INSPTR	QB6851
NEVADA CITY	10/5/2021	7/1/2024	8/15/2023	INSPTR	QB6851
NEVADA CITY	10/5/2021	7/1/2024	7/27/2023	INSPTR	JS2145
NEVADA CITY	10/5/2021	7/1/2024	7/25/2023	INSPTR	QB6851
NEVADA CITY	10/5/2021	7/1/2024	7/27/2023	INSPTR	SB6349
NEVADA CITY	10/5/2021	7/1/2024	7/22/2023	INSPTR	JS2145
LAKE WILDWOOD	10/13/2021	6/21/2024	8/23/2023	INSPTR	MM3647
LAKE WILDWOOD	10/13/2021	6/18/2024	7/19/2024	INSPTR	VC6131
LAKE WILDWOOD	10/13/2021	6/18/2022	10/17/2021	INSPTR	RW1952
LAKE WILDWOOD	10/13/2021	6/19/2024	7/21/2023	INSPTR	DM820T
LAKE WILDWOOD	10/13/2021	6/22/2022	10/17/2021	INSPTR	RW1952
PORTOLA	10/13/2021	10/15/2021	10/14/2021	SF8537	SF8537
LAKE WILDWOOD	10/13/2021	6/23/2022	12/13/2021	INSPTR	WW1427
LAKE WILDWOOD	10/13/2021	6/17/2024	8/30/2023	INSPTR	QB6851

LAKE WILDWOOD	10/13/2021	6/29/2022	10/15/2021	INSPTR	RW1952
LAKE WILDWOOD	10/13/2021	6/23/2024	7/21/2023	INSPTR	DM6529
LAKE WILDWOOD	10/21/2021	6/29/2022	12/7/2021	INSPTR	DC2631
LAKE WILDWOOD	10/21/2021	6/21/2024	7/22/2023	INSPTR	RC5742
LAKE WILDWOOD	10/21/2021	6/21/2024	7/22/2023	INSPTR	RC5742
TRUCKEE	10/28/2021	6/28/2022	12/6/2021	INSPTR	TL5296
TRUCKEE	10/28/2021	6/25/2024	1/25/2024	INSPTR	PG6512
TRUCKEE	10/28/2021	7/1/2024	2/7/2024	INSPTR	DD6738
TRUCKEE	10/28/2021	8/10/2024	5/22/2024	INSPTR	DD6738
TRUCKEE	10/28/2021	6/24/2024	1/24/2024	INSPTR	CD5628
TRUCKEE	10/28/2021	7/9/2024	2/7/2024	INSPTR	DD6738
TRUCKEE	10/28/2021	7/8/2024	2/14/2024	INSPTR	PG6512
TRUCKEE	10/28/2021	7/8/2024	2/13/2024	INSPTR	JH3145
TRUCKEE	10/28/2021	7/20/2024	4/6/2024	INSPTR	JH3145
TRUCKEE	10/28/2021	7/29/2024	5/22/2024	INSPTR	CD5628
TRUCKEE	10/28/2021	7/8/2024	2/6/2024	INSPTR	DD6738
TRUCKEE	10/28/2021	7/8/2024	2/22/2024	INSPTR	CD5628
TRUCKEE	10/28/2021	7/9/2024	2/7/2024	INSPTR	DD6738
TRUCKEE	10/28/2021	7/6/2024	2/10/2024	INSPTR	PG6512
TRUCKEE	10/28/2021	7/6/2024	2/2/2024	INSPTR	CD5628
TRUCKEE	10/28/2021	7/1/2024	1/30/2024	INSPTR	PG6512
TRUCKEE	10/28/2021	8/6/2024	5/17/2024	INSPTR	DD6738
TRUCKEE	10/28/2021	7/9/2024	3/22/2024	INSPTR	CD5628
TRUCKEE	10/28/2021	6/29/2024	1/25/2024	INSPTR	PG6512
TRUCKEE	10/28/2021	6/28/2024	1/4/2024	INSPTR	DD6738
TRUCKEE	10/28/2021	6/28/2024	1/30/2024	INSPTR	CD5628
TRUCKEE	10/28/2021	6/28/2024	1/4/2024	INSPTR	DD6738
TRUCKEE	10/28/2021	6/28/2024	1/4/2024	INSPTR	DD6738
TRUCKEE	10/28/2021	8/10/2024	5/22/2024	INSPTR	DD6738
TRUCKEE	10/28/2021	6/30/2024	1/27/2024	INSPTR	PG6512
TRUCKEE	10/28/2021	6/30/2024	1/27/2024	INSPTR	PG6512
TRUCKEE	10/28/2021	7/9/2024	2/14/2024	INSPTR	PG6512
TRUCKEE	10/28/2021	7/6/2024	2/10/2024	INSPTR	PG6512
TRUCKEE	10/28/2021	8/6/2024	5/17/2024	INSPTR	DD6738
TRUCKEE	10/28/2021	8/6/2024	5/17/2024	INSPTR	DD6738
TRUCKEE	10/28/2021	8/6/2024	6/14/2024	INSPTR	CD5628
TRUCKEE	10/28/2021	8/6/2024	6/14/2024	INSPTR	CD5628
TRUCKEE	10/28/2021	6/28/2022	6/8/2022	INSPTR	
TRUCKEE	10/28/2021	6/23/2022	6/6/2022	INSPTR	
TRUCKEE	10/28/2021	6/28/2022	12/27/2021	INSPTR	PG6512
TRUCKEE	10/31/2021	8/11/2024	7/12/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	8/9/2024	7/13/2024	INSPTR	JQ2645
TRUCKEE	10/31/2021	8/9/2024	5/22/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	8/9/2024	5/23/2024	INSPTR	CD5628

TRUCKEE	10/31/2021	8/9/2024	7/13/2024	INSPTR	JQ2645
TRUCKEE	10/31/2021	8/12/2024	4/10/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	8/12/2024	2/27/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	8/6/2024	5/22/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	8/9/2024	6/1/2024	INSPTR	JQ2645
TRUCKEE	10/31/2021	8/9/2024	6/1/2024	INSPTR	JQ2645
TRUCKEE	10/31/2021	8/9/2024	7/12/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	8/10/2024	7/20/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	8/10/2024	7/20/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	2/10/2022	3/7/2022	INSPTR	DD6738
TRUCKEE	10/31/2021	8/12/2024	2/12/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	8/12/2024	2/12/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	8/13/2024	4/10/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	8/10/2024	7/12/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	8/10/2024	7/12/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	8/10/2024	7/13/2024	INSPTR	JQ2645
TRUCKEE	10/31/2021	8/10/2024	7/12/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	8/10/2024	7/13/2024	INSPTR	JQ2645
TRUCKEE	10/31/2021	7/26/2024	4/26/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	7/26/2024	4/20/2024	INSPTR	JQ2645
TRUCKEE	10/31/2021	7/28/2024	5/7/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/28/2024	5/7/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	8/4/2024	5/14/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	8/4/2024	5/14/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	7/19/2022	5/10/2022	INSPTR	PG6512
TRUCKEE	10/31/2021	7/19/2024	3/22/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	7/23/2024	4/19/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	7/28/2024	8/18/2023	INSPTR	DD6738
TRUCKEE	10/31/2021	7/23/2024	4/19/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	7/23/2024	4/19/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	7/23/2024	4/9/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/26/2024	4/20/2024	INSPTR	JQ2645
TRUCKEE	10/31/2021	7/26/2024	4/20/2024	INSPTR	JQ2645
TRUCKEE	10/31/2021	7/26/2024	5/2/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	7/23/2024	4/19/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	7/21/2024	4/17/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	7/21/2024	4/26/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	1/29/2022	3/2/2022	INSPTR	JH3145
TRUCKEE	10/31/2021	7/29/2024	7/4/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/29/2024	4/22/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	7/29/2024	4/22/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	2/10/2022	3/7/2022	INSPTR	DD6738
TRUCKEE	10/31/2021	8/10/2024	7/12/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	8/10/2024	7/12/2024	INSPTR	PG6512

TRUCKEE	10/31/2021	8/10/2022	5/18/2022	INSPTR	JQ2645
TRUCKEE	10/31/2021	7/20/2024	4/11/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	7/20/2024	3/22/2024	INSPTR	JH3145
TRUCKEE	10/31/2021	7/29/2024	5/6/2024	INSPTR	JQ2645
TRUCKEE	10/31/2021	7/29/2024	5/6/2024	INSPTR	JQ2645
TRUCKEE	10/31/2021	7/20/2024	3/22/2024	INSPTR	JH3145
TRUCKEE	10/31/2021	7/26/2024	4/20/2024	INSPTR	JQ2645
TRUCKEE	10/31/2021	7/30/2024	5/10/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/30/2024	5/10/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/30/2024	5/11/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	7/27/2024	4/22/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	7/27/2024	4/22/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	7/27/2024	4/27/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/27/2024	4/27/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/27/2024	4/23/2024	INSPTR	JH3145
TRUCKEE	10/31/2021	8/2/2024	5/11/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	8/10/2024	11/25/2023	INSPTR	JH3145
TRUCKEE	10/31/2021	8/10/2024	11/25/2023	INSPTR	JH3145
TRUCKEE	10/31/2021	8/10/2024	11/25/2023	INSPTR	JH3145
TRUCKEE	10/31/2021	7/22/2024	5/8/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	8/2/2024	5/13/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	8/4/2024	5/14/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	7/20/2024	4/2/2024	INSPTR	JH3145
TRUCKEE	10/31/2021	7/20/2024	4/11/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	7/27/2024	4/19/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	7/27/2024	4/19/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	7/21/2024	4/17/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	7/21/2024	4/9/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/13/2022	4/4/2022	INSPTR	PG6512
TRUCKEE	10/31/2021	7/13/2024	3/22/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	7/15/2024	2/27/2024	INSPTR	JH3145
TRUCKEE	10/31/2021	7/15/2024	2/27/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/28/2024	5/18/2024	INSPTR	JH3145
TRUCKEE	10/31/2021	7/28/2024	2/29/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/27/2024	4/22/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	7/28/2024	5/7/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/28/2024	5/7/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/15/2024	2/27/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/13/2024	2/8/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/13/2022	4/13/2022	INSPTR	PG6512
TRUCKEE	10/31/2021	7/13/2024	2/8/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/14/2024	2/8/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	7/14/2024	2/27/2024	INSPTR	JH3145
TRUCKEE	10/31/2021	8/5/2024	5/31/2024	INSPTR	DD6738

TRUCKEE	10/31/2021	8/5/2024	5/31/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/21/2024	4/25/2024	INSPTR	JH3145
TRUCKEE	10/31/2021	7/21/2024	4/6/2024	INSPTR	JH3145
TRUCKEE	10/31/2021	7/21/2024	4/6/2024	INSPTR	JH3145
TRUCKEE	10/31/2021	7/21/2024	4/22/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/22/2024	4/19/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	7/22/2024	4/19/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	7/27/2024	4/23/2024	INSPTR	JH3145
TRUCKEE	10/31/2021	7/27/2024	4/23/2024	INSPTR	JH3145
TRUCKEE	10/31/2021	8/5/2024	5/31/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/27/2024	5/11/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	7/27/2024	5/18/2024	INSPTR	JH3145
TRUCKEE	10/31/2021	8/6/2024	5/22/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	8/6/2024	5/14/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	8/6/2024	5/14/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	8/6/2024	5/22/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	8/6/2024	5/14/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/20/2024	4/11/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	7/21/2024	4/5/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/21/2024	4/5/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/21/2024	4/5/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/20/2024	5/6/2024	INSPTR	JQ2645
TRUCKEE	10/31/2021	7/20/2024	4/25/2024	INSPTR	JH3145
TRUCKEE	10/31/2021	7/27/2024	5/2/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	7/27/2024	5/2/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	8/6/2024	5/22/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	8/6/2024	5/14/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	8/4/2024	5/31/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/20/2024	3/29/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/20/2024	3/29/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/23/2024	4/9/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/23/2024	5/8/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/23/2024	4/18/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	7/23/2024	4/27/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/20/2024	3/22/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	7/20/2024	3/22/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	7/21/2024	4/5/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	7/28/2024	5/11/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	6/25/2024	1/2/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	6/25/2024	1/22/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	6/25/2024	1/25/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	6/25/2024	1/26/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	12/25/2021	2/25/2022	INSPTR	JH3145
TRUCKEE	10/31/2021	12/31/2021	2/25/2022	INSPTR	JH3145

TRUCKEE	10/31/2021	6/30/2024	1/5/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	6/30/2024	2/7/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	6/30/2024	12/29/2023	INSPTR	DD6738
TRUCKEE	10/31/2021	6/28/2024	2/2/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	6/28/2024	1/15/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	6/28/2024	1/15/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	6/28/2024	2/3/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	6/30/2024	12/26/2023	INSPTR	DD6738
TRUCKEE	10/31/2021	6/30/2022	7/6/2022	INSPTR	
TRUCKEE	10/31/2021	6/30/2024	2/5/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/30/2024	7/29/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/12/2024	2/23/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/12/2024	2/23/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	6/25/2024	1/2/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	6/25/2024	1/25/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	6/25/2022	6/6/2022	INSPTR	
TRUCKEE	10/31/2021	7/6/2024	2/7/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/6/2022	7/6/2022	INSPTR	
TRUCKEE	10/31/2021	7/21/2024	4/5/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	7/20/2024	3/27/2024	INSPTR	JH3145
TRUCKEE	10/31/2021	7/20/2024	3/28/2024	INSPTR	JH3145
TRUCKEE	10/31/2021	7/21/2024	4/29/2024	INSPTR	JH3145
TRUCKEE	10/31/2021	7/28/2024	5/10/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	6/23/2024	1/22/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	6/25/2024	1/25/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	6/29/2022	7/6/2022	INSPTR	
TRUCKEE	10/31/2021	6/29/2022	7/6/2022	INSPTR	
TRUCKEE	10/31/2021	6/29/2024	1/30/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	6/29/2022	7/6/2022	INSPTR	
TRUCKEE	10/31/2021	7/1/2022	7/6/2022	INSPTR	
TRUCKEE	10/31/2021	7/2/2024	2/7/2024	INSPTR	JH3145
TRUCKEE	10/31/2021	7/2/2022	7/6/2022	INSPTR	
TRUCKEE	10/31/2021	7/2/2024	2/5/2024	INSPTR	JQ2645
TRUCKEE	10/31/2021	7/2/2024	2/7/2024	INSPTR	JH3145
TRUCKEE	10/31/2021	7/2/2022	7/6/2022	INSPTR	
TRUCKEE	10/31/2021	7/8/2024	2/22/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	7/8/2024	2/7/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	7/8/2024	2/5/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	7/8/2024	2/13/2024	INSPTR	JH3145
TRUCKEE	10/31/2021	7/8/2024	2/7/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	7/8/2024	2/5/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	6/28/2022	6/6/2022	INSPTR	
TRUCKEE	10/31/2021	6/28/2024	1/4/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	6/28/2024	1/5/2024	INSPTR	CD5628

TRUCKEE	10/31/2021	6/28/2024	2/1/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	6/28/2022	6/8/2022	INSPTR	
TRUCKEE	10/31/2021	6/29/2024	1/15/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	6/29/2024	2/1/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	6/29/2022	7/6/2022	INSPTR	
TRUCKEE	10/31/2021	6/29/2024	2/3/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	6/29/2022	7/6/2022	INSPTR	
TRUCKEE	10/31/2021	6/29/2024	1/22/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	6/29/2024	2/5/2024	INSPTR	JQ2645
TRUCKEE	10/31/2021	6/29/2022	5/6/2022	INSPTR	PG6512
TRUCKEE	10/31/2021	6/29/2022	5/10/2022	INSPTR	DD6738
TRUCKEE	10/31/2021	6/29/2024	2/5/2024	INSPTR	JH3145
TRUCKEE	10/31/2021	7/2/2022	7/6/2022	INSPTR	
TRUCKEE	10/31/2021	7/2/2024	2/5/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	7/2/2024	2/5/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	7/2/2024	2/5/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	6/30/2022	4/13/2022	INSPTR	PG6512
TRUCKEE	10/31/2021	6/30/2024	1/27/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	6/30/2024	2/6/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	6/30/2022	7/6/2022	INSPTR	
TRUCKEE	10/31/2021	6/30/2024	2/6/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/9/2024	2/8/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	7/9/2024	2/9/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	7/9/2024	2/10/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	7/9/2024	2/24/2024	INSPTR	JH3145
TRUCKEE	10/31/2021	7/9/2024	3/7/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/9/2022	7/6/2022	INSPTR	
TRUCKEE	10/31/2021	7/6/2024	2/10/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	7/8/2024	3/1/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	7/8/2024	3/1/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	6/28/2024	2/1/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	6/25/2022	6/8/2022	INSPTR	
TRUCKEE	10/31/2021	7/19/2024	4/2/2024	INSPTR	JH3145
TRUCKEE	10/31/2021	7/19/2024	4/11/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	7/19/2024	3/29/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/19/2024	3/29/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/19/2024	3/22/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	7/19/2024	3/22/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	7/19/2024	3/22/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	7/20/2024	4/2/2024	INSPTR	JH3145
TRUCKEE	10/31/2021	6/28/2024	2/1/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	6/28/2024	1/4/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	6/28/2022	6/8/2022	INSPTR	
TRUCKEE	10/31/2021	6/28/2022	6/8/2022	INSPTR	

TRUCKEE	10/31/2021	6/28/2024	2/2/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	6/23/2024	1/25/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	6/23/2022	7/6/2022	INSPTR	
TRUCKEE	10/31/2021	6/23/2024	1/13/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	6/23/2024	12/27/2023	INSPTR	DD6738
TRUCKEE	10/31/2021	6/23/2024	1/22/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	6/23/2022	6/6/2022	INSPTR	
TRUCKEE	10/31/2021	6/23/2024	12/19/2023	INSPTR	DD6738
TRUCKEE	10/31/2021	6/24/2024	12/27/2023	INSPTR	DD6738
TRUCKEE	10/31/2021	6/24/2024	1/2/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	6/24/2022	5/4/2022	INSPTR	JQ2645
TRUCKEE	10/31/2021	6/30/2022	7/6/2022	INSPTR	
TRUCKEE	10/31/2021	6/30/2024	9/1/2023	INSPTR	DD6738
TRUCKEE	10/31/2021	6/30/2022	7/6/2022	INSPTR	
TRUCKEE	10/31/2021	7/1/2024	1/30/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	7/1/2024	1/5/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/1/2024	1/5/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	6/28/2022	4/3/2024	INSPTR	
TRUCKEE	10/31/2021	7/7/2024	3/2/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	7/7/2024	2/5/2024	INSPTR	JH3145
TRUCKEE	10/31/2021	7/7/2024	1/30/2024	INSPTR	JH3145
TRUCKEE	10/31/2021	7/8/2024	3/6/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	7/14/2024	2/8/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	7/14/2024	2/8/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	7/13/2024	2/8/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/13/2024	2/8/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/13/2024	2/8/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/21/2024	4/9/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	6/24/2024	1/13/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	6/24/2022	6/6/2022	INSPTR	
TRUCKEE	10/31/2021	6/24/2022	7/6/2022	INSPTR	
TRUCKEE	10/31/2021	6/24/2024	12/19/2023	INSPTR	DD6738
TRUCKEE	10/31/2021	6/24/2024	1/24/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	6/29/2022	7/6/2022	INSPTR	
TRUCKEE	10/31/2021	6/29/2024	1/26/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	6/29/2024	1/26/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	6/29/2022	7/6/2022	INSPTR	
TRUCKEE	10/31/2021	6/29/2024	2/5/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	6/29/2024	2/5/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/1/2024	2/7/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	7/1/2022	7/6/2022	INSPTR	
TRUCKEE	10/31/2021	7/1/2024	2/6/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	7/1/2022	7/6/2022	INSPTR	
TRUCKEE	10/31/2021	7/7/2022	5/13/2022	INSPTR	PG6512

TRUCKEE	10/31/2021	7/7/2024	1/30/2024	INSPTR	JH3145
TRUCKEE	10/31/2021	7/14/2024	2/8/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	7/12/2024	2/24/2024	INSPTR	JH3145
TRUCKEE	10/31/2021	7/14/2024	2/2/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	7/14/2024	2/26/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	7/14/2024	3/22/2024	INSPTR	JH3145
TRUCKEE	10/31/2021	7/14/2024	2/26/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	7/14/2024	2/8/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	7/15/2024	2/27/2024	INSPTR	JH3145
TRUCKEE	10/31/2021	7/7/2024	1/30/2024	INSPTR	JH3145
TRUCKEE	10/31/2021	7/1/2022	7/6/2022	INSPTR	
TRUCKEE	10/31/2021	7/1/2024	2/6/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/1/2024	2/6/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	7/1/2022	7/6/2022	INSPTR	
TRUCKEE	10/31/2021	7/1/2024	2/5/2024	INSPTR	JQ2645
TRUCKEE	10/31/2021	7/1/2024	2/7/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/1/2022	7/6/2022	INSPTR	
TRUCKEE	10/31/2021	7/1/2022	7/6/2022	INSPTR	
TRUCKEE	10/31/2021	7/1/2022	4/7/2022	INSPTR	DD6738
TRUCKEE	10/31/2021	7/9/2024	3/7/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/8/2024	2/7/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	7/8/2024	2/22/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	7/8/2024	2/14/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	7/8/2024	2/13/2024	INSPTR	JH3145
TRUCKEE	10/31/2021	7/1/2024	1/30/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	7/1/2024	1/30/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	7/9/2024	3/7/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/9/2024	3/11/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	7/22/2024	4/22/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/22/2024	4/26/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	7/22/2024	12/13/2023	INSPTR	CD5628
TRUCKEE	10/31/2021	7/6/2024	2/2/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	7/6/2024	12/13/2023	INSPTR	CD5628
TRUCKEE	10/31/2021	7/6/2024	2/24/2024	INSPTR	JH3145
TRUCKEE	10/31/2021	6/24/2024	1/24/2024	INSPTR	CD5628
TRUCKEE	10/31/2021	6/30/2024	1/3/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/20/2024	3/22/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	7/20/2024	1/3/2024	INSPTR	DD6738
TRUCKEE	10/31/2021	7/15/2024	3/25/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	7/15/2024	3/25/2024	INSPTR	PG6512
TRUCKEE	10/31/2021	7/15/2024	12/18/2023	INSPTR	PG6512
TRUCKEE	10/31/2021	7/9/2022	12/10/2021	INSPTR	SM3126
TRUCKEE	10/31/2021	7/9/2024	12/18/2023	INSPTR	PG6512
BLAIRSDEN	11/10/2021	11/13/2021	11/10/2021	SF8537	SF8537

DOWNEYVILLE	11/11/2021	7/26/2024	3/20/2022	INSPTR	QB6851
DOWNEYVILLE	11/11/2021	7/26/2024	3/17/2022	INSPTR	KS6734
DOWNEYVILLE	11/11/2021	7/26/2024	3/17/2022	INSPTR	MD4156
DOWNEYVILLE	11/11/2021	7/26/2024	3/17/2022	INSPTR	MD4156
DOWNEYVILLE	11/11/2021	8/4/2024	3/20/2022	INSPTR	QB6851
DOWNEYVILLE	11/11/2021	8/5/2024	3/20/2022	INSPTR	QB6851
DOWNEYVILLE	11/11/2021	2/6/2022	2/28/2022	INSPTR	JI2512
DOWNEYVILLE	11/11/2021	8/6/2024	3/20/2022	INSPTR	QB6851
DOWNEYVILLE	11/11/2021	8/6/2024	3/20/2022	INSPTR	QB6851
DOWNEYVILLE	11/11/2021	8/6/2024	9/14/2022	INSPTR	QB6851
DOWNEYVILLE	11/11/2021	2/6/2022	2/28/2022	INSPTR	CG4741
DOWNEYVILLE	11/11/2021	2/6/2022	2/28/2022	INSPTR	GG8932
DOWNEYVILLE	11/11/2021	8/9/2024	3/27/2022	INSPTR	QB6851
DOWNEYVILLE	11/11/2021	8/9/2024	3/27/2022	INSPTR	QB6851
DOWNEYVILLE	11/11/2021	8/9/2024	3/27/2022	INSPTR	QB6851
SIERRA CITY	11/12/2021	8/4/2024	3/11/2022	INSPTR	QB6851
SIERRA CITY	11/12/2021	8/6/2024	3/12/2022	INSPTR	RH5983
SIERRAVILLE	11/12/2021	7/30/2024	8/22/2023	INSPTR	SF8537
SIERRAVILLE	11/12/2021	7/30/2022	11/15/2021	INSPTR	SF8537
SIERRAVILLE	11/12/2021	7/30/2022	11/15/2021	INSPTR	SF8537
SIERRA CITY	11/12/2021	7/31/2022	3/12/2022	INSPTR	QB6851
ALTA/DUTCH FLATS	11/18/2021	7/1/2022	3/15/2022	INSPTR	GS6496
ALTA/DUTCH FLATS	11/18/2021	7/1/2022	3/14/2022	INSPTR	JS6852
ALTA/DUTCH FLATS	11/18/2021	7/6/2024	7/29/2023	INSPTR	RX3937
ALTA/DUTCH FLATS	11/18/2021	7/6/2024	8/14/2023	INSPTR	SC2675
ALTA/DUTCH FLATS	11/18/2021	7/12/2024	8/13/2023	INSPTR	SC2675
ALTA/DUTCH FLATS	11/18/2021	7/6/2024	8/17/2023	INSPTR	SC2675
ALTA/DUTCH FLATS	11/18/2021	1/21/2022	3/13/2022	INSPTR	RA4618
ALTA/DUTCH FLATS	11/18/2021	1/15/2022	3/13/2022	INSPTR	RA4618
ALTA/DUTCH FLATS	11/18/2021	1/15/2022	3/13/2022	INSPTR	RA4618
ALTA/DUTCH FLATS	11/18/2021	12/31/2021	12/1/2021	INSPTR	
ALTA/DUTCH FLATS	11/18/2021	1/13/2022	3/12/2022	INSPTR	KS8192
ALTA/DUTCH FLATS	11/18/2021	7/13/2024	8/14/2023	INSPTR	SC2675
ALTA/DUTCH FLATS	11/18/2021	7/1/2024	8/19/2023	INSPTR	SC2675
ALTA/DUTCH FLATS	11/18/2021	1/20/2022	3/13/2022	INSPTR	HP4528
ALTA/DUTCH FLATS	11/18/2021	7/13/2024	8/16/2023	INSPTR	SC2675
ALTA/DUTCH FLATS	11/18/2021	1/13/2022	3/11/2022	INSPTR	HP4528
ALTA/DUTCH FLATS	11/18/2021	7/16/2024	8/19/2023	INSPTR	SC2675
ALTA/DUTCH FLATS	11/18/2021	7/7/2024	8/22/2023	INSPTR	SC2675
ALTA/DUTCH FLATS	11/18/2021	7/13/2024	8/19/2023	INSPTR	SC2675
ALTA/DUTCH FLATS	11/18/2021	7/13/2024	8/13/2023	INSPTR	SC2675
ALTA/DUTCH FLATS	11/18/2021	7/13/2024	8/13/2023	INSPTR	SC2675
ALTA/DUTCH FLATS	11/18/2021	7/7/2022	3/14/2022	INSPTR	MD4156
ALTA/DUTCH FLATS	11/18/2021	7/20/2024	8/26/2023	INSPTR	SC2675

ALTA/DUTCH FLATS	11/18/2021	7/20/2024	8/21/2023	INSPTR	SC2675
ALTA/DUTCH FLATS	11/18/2021	1/20/2022	3/13/2022	INSPTR	RA4618
ALTA/DUTCH FLATS	11/18/2021	7/14/2024	8/14/2023	INSPTR	SC2675
ALTA/DUTCH FLATS	11/18/2021	7/12/2024	8/17/2023	INSPTR	CN2921
ALTA/DUTCH FLATS	11/18/2021	7/20/2024	8/21/2023	INSPTR	SC2675
ALTA/DUTCH FLATS	11/18/2021	7/7/2024	4/8/2024	INSPTR	TL3147
ALTA/DUTCH FLATS	11/18/2021	7/8/2022	3/15/2022	INSPTR	GS6496
ALTA/DUTCH FLATS	11/18/2021	7/8/2024	9/13/2023	INSPTR	SC2675
ALTA/DUTCH FLATS	11/18/2021	7/1/2024	8/22/2023	INSPTR	SC2675
ALTA/DUTCH FLATS	11/18/2021	7/1/2024	8/19/2023	INSPTR	SC2675
ALTA/DUTCH FLATS	11/18/2021	7/1/2024	8/18/2023	INSPTR	TL3147
ALTA/DUTCH FLATS	11/18/2021	7/1/2022	3/11/2022	INSPTR	GS6496
ALTA/DUTCH FLATS	11/18/2021	7/1/2024	8/18/2023	INSPTR	TL3147
ALTA/DUTCH FLATS	11/18/2021	1/13/2022	3/15/2022	INSPTR	GS6496
ALTA/DUTCH FLATS	11/18/2021	1/13/2022	3/5/2022	INSPTR	MG1262
ALTA/DUTCH FLATS	11/18/2021	7/7/2024	8/17/2023	INSPTR	JS3172
ALTA/DUTCH FLATS	11/18/2021	7/9/2024	8/14/2023	INSPTR	SC2675
ALTA/DUTCH FLATS	11/18/2021	1/9/2022	3/12/2022	INSPTR	KS8192
ALTA/DUTCH FLATS	11/18/2021	1/9/2022	3/8/2022	INSPTR	AW2727
ALTA/DUTCH FLATS	11/18/2021	7/9/2024	4/4/2024	INSPTR	TL3147
ALTA/DUTCH FLATS	11/18/2021	1/7/2022	3/12/2022	INSPTR	KS8192
ALTA/DUTCH FLATS	11/18/2021	1/7/2022	3/8/2022	INSPTR	AW2727
ALTA/DUTCH FLATS	11/18/2021	7/8/2024	7/19/2023	INSPTR	CN2921
ALTA/DUTCH FLATS	11/18/2021	7/8/2024	8/17/2023	INSPTR	JS3172
ALTA/DUTCH FLATS	11/18/2021	7/9/2024	8/17/2023	INSPTR	CN2921
ALTA/DUTCH FLATS	11/18/2021	7/9/2024	8/17/2023	INSPTR	SC2675
ALTA/DUTCH FLATS	11/18/2021	1/11/2022	3/8/2022	INSPTR	KS6734
ALTA/DUTCH FLATS	11/18/2021	7/14/2024	8/16/2023	INSPTR	JS3172
ALTA/DUTCH FLATS	11/18/2021	7/14/2024	8/16/2023	INSPTR	CN2921
ALTA/DUTCH FLATS	11/18/2021	7/14/2024	8/13/2023	INSPTR	SC2675
ALTA/DUTCH FLATS	11/18/2021	7/6/2024	8/16/2023	INSPTR	CN2921
ALTA/DUTCH FLATS	11/18/2021	7/6/2024	8/15/2023	INSPTR	PM8616
ALTA/DUTCH FLATS	11/18/2021	7/7/2024	8/15/2023	INSPTR	PM8616
ALTA/DUTCH FLATS	11/18/2021	7/7/2024	8/15/2023	INSPTR	SG1898
ALTA/DUTCH FLATS	11/18/2021	7/19/2024	8/15/2023	INSPTR	SG1898
ALTA/DUTCH FLATS	11/18/2021	7/19/2024	8/15/2023	INSPTR	WA6713
ALTA/DUTCH FLATS	11/18/2021	7/19/2024	8/10/2023	INSPTR	KL2356
ALTA/DUTCH FLATS	11/18/2021	7/19/2024	7/28/2023	INSPTR	DS4637
ALTA/DUTCH FLATS	11/18/2021	7/12/2024	8/15/2023	INSPTR	WA6713
ALTA/DUTCH FLATS	11/18/2021	7/12/2024	8/14/2023	INSPTR	MD2797
ALTA/DUTCH FLATS	11/18/2021	7/12/2024	8/7/2023	INSPTR	CN2921
ALTA/DUTCH FLATS	11/18/2021	7/12/2024	8/7/2023	INSPTR	CN2921
ALTA/DUTCH FLATS	11/18/2021	7/12/2024	7/13/2023	INSPTR	CN2921
ALTA/DUTCH FLATS	11/18/2021	7/12/2022	3/6/2022	INSPTR	RK7932

ALTA/DUTCH FLATS	11/18/2021	1/15/2022	3/6/2022	INSPTR	RK7932
ALTA/DUTCH FLATS	11/18/2021	1/15/2022	3/7/2022	INSPTR	AV1412
ALTA/DUTCH FLATS	11/18/2021	1/15/2022	3/5/2022	INSPTR	MG1262
CHALLENGE	11/28/2021	3/17/2022	9/29/2023	INSPTR	
CHALLENGE	11/28/2021	3/17/2022	9/29/2023	INSPTR	
CHALLENGE	11/28/2021	9/21/2024	10/23/2023	INSPTR	DB8381
CHALLENGE	11/28/2021	3/21/2022	4/25/2023	INSPTR	
CHALLENGE	11/28/2021	3/20/2022	2/10/2022	INSPTR	AC1532
CHALLENGE	11/28/2021	3/20/2022	2/10/2022	INSPTR	AC1532
CHALLENGE	11/28/2021	3/20/2022	2/10/2022	INSPTR	AC1532
CHALLENGE	11/28/2021	3/21/2022	2/15/2022	INSPTR	AC1532
CHALLENGE	11/28/2021	9/23/2024	3/13/2024	INSPTR	RH749C
CHALLENGE	11/28/2021	3/23/2022	2/16/2022	INSPTR	AC1532
CHALLENGE	11/28/2021	9/22/2024	11/18/2023	INSPTR	AC1532
CHALLENGE	11/28/2021	3/21/2022	2/7/2023	INSPTR	
CHALLENGE	11/28/2021	3/24/2022	2/16/2022	INSPTR	AC1532
CHALLENGE	11/28/2021	3/22/2022	2/7/2023	INSPTR	
CHALLENGE	11/28/2021	3/24/2022	4/11/2022	INSPTR	CC2745
CHALLENGE	11/28/2021	3/22/2022	2/16/2022	INSPTR	AC1532
CHALLENGE	11/28/2021	9/29/2024	7/1/2024	INSPTR	AC1532
CHALLENGE	11/28/2021	3/27/2022	2/24/2022	INSPTR	AC1532
CHALLENGE	11/28/2021	9/30/2024	12/9/2023	INSPTR	RH749C
CHALLENGE	11/28/2021	10/1/2024	12/11/2023	INSPTR	DB8381
CHALLENGE	11/28/2021	3/31/2022	3/31/2022	INSPTR	AC1532
CHALLENGE	11/28/2021	3/14/2022	2/16/2022	INSPTR	AC1532
CHALLENGE	11/28/2021	3/14/2022	3/18/2022	INSPTR	AC1532
CHALLENGE	11/28/2021	3/17/2022	2/25/2022	INSPTR	AC1532
CHALLENGE	11/28/2021	3/31/2022	3/6/2022	INSPTR	AC1532
CHALLENGE	11/28/2021	3/31/2022	4/11/2022	INSPTR	CC2745
CHALLENGE	11/28/2021	4/1/2022	2/27/2022	INSPTR	CC2745
CHALLENGE	11/28/2021	9/13/2024	12/16/2023	INSPTR	AC1532
CHALLENGE	11/28/2021	9/23/2024	3/13/2024	INSPTR	RH749C
CHALLENGE	11/28/2021	3/15/2022	2/25/2022	INSPTR	CC2745
CHALLENGE	11/28/2021	9/29/2022	3/6/2022	INSPTR	AC1532
CHALLENGE	11/28/2021	3/14/2022	4/28/2022	INSPTR	CC2745
CHALLENGE	11/28/2021	9/21/2024	12/11/2023	INSPTR	DB8381
CHALLENGE	11/28/2021	3/22/2022	2/25/2022	INSPTR	AC1532
CHALLENGE	11/28/2021	9/22/2024	11/18/2023	INSPTR	AC1532
CHALLENGE	11/28/2021	3/21/2022	2/7/2023	INSPTR	
CHALLENGE	11/28/2021	3/24/2022	7/13/2022	INSPTR	AC1532
CHALLENGE	11/28/2021	3/28/2022	8/29/2022	INSPTR	
CHALLENGE	11/28/2021	9/28/2024	12/11/2023	INSPTR	DB8381
CHALLENGE	11/28/2021	9/28/2024	12/11/2023	INSPTR	DB8381
CHALLENGE	11/28/2021	9/10/2024	11/18/2023	INSPTR	AC1532

CHALLENGE	11/28/2021	9/15/2024	11/18/2023	INSPTR	AC1532
CHALLENGE	11/28/2021	3/15/2022	3/6/2022	INSPTR	AC1532
CHALLENGE	11/28/2021	3/15/2022	3/6/2022	INSPTR	AC1532
CHALLENGE	11/28/2021	9/15/2024	12/11/2023	INSPTR	DB8381
CHALLENGE	11/28/2021	3/13/2022	2/25/2022	INSPTR	AC1532
CHALLENGE	11/28/2021	9/14/2024	12/11/2023	INSPTR	DB8381
CHALLENGE	11/28/2021	3/15/2022	3/6/2022	INSPTR	AC1532
CHALLENGE	11/28/2021	9/15/2024	11/17/2023	INSPTR	AC1532
CHALLENGE	11/28/2021	9/15/2024	3/12/2024	INSPTR	DM258S
PORTOLA	12/8/2021	12/11/2021	12/8/2021	SF8537	SF8537
GRASS VALLEY	12/9/2021	6/9/2024	8/19/2023	INSPTR	MD2797
GRASS VALLEY	12/9/2021	6/9/2024	8/16/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/9/2024	8/16/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/9/2024	8/26/2023	INSPTR	MD4156
GRASS VALLEY	12/9/2021	6/14/2024	8/24/2023	INSPTR	MM3647
GRASS VALLEY	12/9/2021	6/14/2024	8/24/2023	INSPTR	MM3647
GRASS VALLEY	12/9/2021	6/14/2024	8/11/2023	INSPTR	MD2797
GRASS VALLEY	12/9/2021	12/29/2021	2/15/2022	INSPTR	JS2145
GRASS VALLEY	12/9/2021	6/4/2024	8/3/2023	INSPTR	JS2145
GRASS VALLEY	12/9/2021	6/7/2024	8/13/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/4/2024	8/4/2023	INSPTR	RC5742
GRASS VALLEY	12/9/2021	6/4/2024	8/8/2023	INSPTR	MD2797
GRASS VALLEY	12/9/2021	12/4/2021	2/19/2022	INSPTR	SM1897
GRASS VALLEY	12/9/2021	12/4/2021	2/13/2022	INSPTR	FR1292
GRASS VALLEY	12/9/2021	12/4/2021	2/13/2022	INSPTR	FR1292
GRASS VALLEY	12/9/2021	6/9/2022	12/13/2021	INSPTR	JA1893
GRASS VALLEY	12/9/2021	6/9/2024	8/26/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/8/2024	8/2/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/15/2024	8/29/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/11/2022	12/13/2021	INSPTR	JJ6768
GRASS VALLEY	12/9/2021	6/9/2024	8/26/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/18/2024	8/29/2023	INSPTR	DM820T
GRASS VALLEY	12/9/2021	6/18/2024	8/29/2023	INSPTR	DM820T
GRASS VALLEY	12/9/2021	6/8/2024	8/2/2023	INSPTR	DM820T
GRASS VALLEY	12/9/2021	6/8/2024	8/2/2023	INSPTR	DM820T
GRASS VALLEY	12/9/2021	6/8/2024	8/2/2023	INSPTR	DM820T
GRASS VALLEY	12/9/2021	6/8/2024	8/2/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/8/2024	8/16/2023	INSPTR	DM820T
GRASS VALLEY	12/9/2021	12/8/2021	2/14/2022	INSPTR	FR1292
GRASS VALLEY	12/9/2021	6/11/2024	8/15/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/11/2022	12/13/2021	INSPTR	JJ6768
GRASS VALLEY	12/9/2021	6/11/2024	8/15/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/11/2024	8/15/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/11/2024	10/9/2023	INSPTR	MM3647

GRASS VALLEY	12/9/2021	6/11/2024	8/19/2023	INSPTR	JM1295
GRASS VALLEY	12/9/2021	6/11/2024	8/9/2023	INSPTR	MD2797
GRASS VALLEY	12/9/2021	6/14/2024	9/2/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/14/2024	9/2/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/14/2024	10/8/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/14/2024	9/2/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/14/2024	9/2/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/15/2024	9/26/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/15/2024	9/26/2023	INSPTR	PC9347
GRASS VALLEY	12/9/2021	6/8/2024	8/16/2023	INSPTR	DM820T
GRASS VALLEY	12/9/2021	6/8/2024	8/16/2023	INSPTR	DM820T
GRASS VALLEY	12/9/2021	6/8/2024	8/16/2023	INSPTR	DM820T
GRASS VALLEY	12/9/2021	6/14/2024	8/31/2023	INSPTR	RW5286
GRASS VALLEY	12/9/2021	6/14/2024	10/13/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/14/2024	10/9/2023	INSPTR	MM3647
GRASS VALLEY	12/9/2021	6/14/2024	8/20/2023	INSPTR	PC9347
GRASS VALLEY	12/9/2021	6/14/2024	8/1/2023	INSPTR	JM1295
GRASS VALLEY	12/9/2021	6/14/2024	8/18/2023	INSPTR	DM820T
GRASS VALLEY	12/9/2021	6/14/2024	8/18/2023	INSPTR	DM820T
GRASS VALLEY	12/9/2021	6/23/2024	9/29/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/7/2024	8/10/2023	INSPTR	SB6349
GRASS VALLEY	12/9/2021	6/7/2024	8/13/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/14/2024	10/14/2023	INSPTR	MM3647
GRASS VALLEY	12/9/2021	6/9/2024	8/16/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/8/2024	8/10/2023	INSPTR	JS2145
GRASS VALLEY	12/9/2021	6/8/2024	8/7/2023	INSPTR	MD2797
GRASS VALLEY	12/9/2021	6/8/2024	8/16/2023	INSPTR	DM820T
GRASS VALLEY	12/9/2021	6/8/2024	8/2/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/8/2024	8/2/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/8/2024	8/2/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/14/2024	8/28/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/14/2024	9/15/2023	INSPTR	JM1295
GRASS VALLEY	12/9/2021	6/14/2024	10/14/2023	INSPTR	MM3647
GRASS VALLEY	12/9/2021	6/14/2024	8/18/2023	INSPTR	DM820T
GRASS VALLEY	12/9/2021	6/7/2024	8/14/2023	INSPTR	WE5739
GRASS VALLEY	12/9/2021	6/7/2022	12/13/2021	INSPTR	DC2631
GRASS VALLEY	12/9/2021	6/7/2024	8/15/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/7/2024	8/15/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/7/2022	12/13/2021	INSPTR	DC2631
GRASS VALLEY	12/9/2021	12/25/2021	2/15/2022	INSPTR	BK2151
GRASS VALLEY	12/9/2021	7/29/2024	8/29/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/28/2024	7/22/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/8/2022	12/13/2021	INSPTR	DC2631
GRASS VALLEY	12/9/2021	6/10/2024	9/16/2023	INSPTR	RW5286

GRASS VALLEY	12/9/2021	6/14/2024	8/28/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/14/2024	10/6/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/4/2024	8/7/2023	INSPTR	RC5742
GRASS VALLEY	12/9/2021	6/21/2022	12/13/2021	INSPTR	EL8648
GRASS VALLEY	12/9/2021	6/10/2024	7/22/2023	INSPTR	DM820T
GRASS VALLEY	12/9/2021	6/10/2022	12/13/2021	INSPTR	JJ6768
GRASS VALLEY	12/9/2021	6/10/2024	7/22/2023	INSPTR	DM820T
GRASS VALLEY	12/9/2021	6/10/2024	8/31/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	12/10/2021	2/22/2022	INSPTR	JI2512
GRASS VALLEY	12/9/2021	6/10/2024	7/22/2023	INSPTR	RW5286
GRASS VALLEY	12/9/2021	6/15/2024	8/18/2023	INSPTR	MD2797
GRASS VALLEY	12/9/2021	6/15/2024	9/26/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/15/2024	8/18/2023	INSPTR	MD2797
GRASS VALLEY	12/9/2021	6/15/2024	8/18/2023	INSPTR	MD2797
GRASS VALLEY	12/9/2021	12/15/2021	2/15/2022	INSPTR	AM2764
GRASS VALLEY	12/9/2021	6/15/2024	9/26/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/7/2024	8/12/2023	INSPTR	RC5742
GRASS VALLEY	12/9/2021	6/7/2024	8/12/2023	INSPTR	RC5742
GRASS VALLEY	12/9/2021	6/10/2024	9/12/2023	INSPTR	MD4156
GRASS VALLEY	12/9/2021	6/10/2024	9/15/2023	INSPTR	JM1295
GRASS VALLEY	12/9/2021	6/11/2024	9/15/2023	INSPTR	RW5286
GRASS VALLEY	12/9/2021	6/11/2024	10/7/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/15/2024	8/1/2023	INSPTR	SB6349
GRASS VALLEY	12/9/2021	6/15/2024	9/26/2023	INSPTR	PC9347
GRASS VALLEY	12/9/2021	6/15/2024	9/26/2023	INSPTR	PC9347
GRASS VALLEY	12/9/2021	6/7/2022	12/13/2021	INSPTR	DC2631
GRASS VALLEY	12/9/2021	6/7/2024	8/11/2023	INSPTR	RB2427
GRASS VALLEY	12/9/2021	6/7/2024	8/12/2023	INSPTR	JM1295
GRASS VALLEY	12/9/2021	6/4/2024	8/9/2023	INSPTR	SB6349
GRASS VALLEY	12/9/2021	6/4/2024	8/11/2023	INSPTR	ML1973
GRASS VALLEY	12/9/2021	6/9/2024	8/16/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/9/2024	8/18/2023	INSPTR	MD4156
GRASS VALLEY	12/9/2021	6/9/2022	12/13/2021	INSPTR	JA1893
GRASS VALLEY	12/9/2021	6/15/2024	11/30/2023	INSPTR	MM3647
GRASS VALLEY	12/9/2021	6/25/2024	8/29/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/9/2024	8/16/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/4/2022	12/13/2021	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/4/2022	12/13/2021	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/4/2022	12/13/2021	INSPTR	QB6851
GRASS VALLEY	12/9/2021	12/4/2021	2/22/2022	INSPTR	JI2512
GRASS VALLEY	12/9/2021	6/9/2022	12/13/2021	INSPTR	JJ6768
GRASS VALLEY	12/9/2021	6/9/2024	8/15/2023	INSPTR	DM820T
GRASS VALLEY	12/9/2021	6/9/2022	12/13/2021	INSPTR	JA1893
GRASS VALLEY	12/9/2021	6/9/2024	8/15/2023	INSPTR	DM820T

GRASS VALLEY	12/9/2021	6/10/2024	8/21/2023	INSPTR	MD2797
GRASS VALLEY	12/9/2021	6/15/2024	9/16/2023	INSPTR	RW5286
GRASS VALLEY	12/9/2021	6/15/2024	9/16/2023	INSPTR	RW5286
GRASS VALLEY	12/9/2021	6/10/2024	8/21/2023	INSPTR	MD2797
GRASS VALLEY	12/9/2021	12/4/2021	2/16/2022	INSPTR	VC6131
GRASS VALLEY	12/9/2021	6/4/2024	7/29/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/4/2024	8/2/2023	INSPTR	JS2145
GRASS VALLEY	12/9/2021	6/9/2022	12/13/2021	INSPTR	JA1893
GRASS VALLEY	12/9/2021	6/9/2024	8/15/2023	INSPTR	DM820T
GRASS VALLEY	12/9/2021	6/9/2024	8/14/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/9/2024	8/14/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/9/2024	8/14/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/9/2024	8/14/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/9/2024	8/16/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/4/2024	7/13/2023	INSPTR	DM820T
GRASS VALLEY	12/9/2021	6/4/2024	8/3/2023	INSPTR	JS2145
GRASS VALLEY	12/9/2021	6/4/2024	8/3/2023	INSPTR	JM1295
GRASS VALLEY	12/9/2021	6/4/2024	8/4/2023	INSPTR	RW5286
GRASS VALLEY	12/9/2021	6/10/2024	8/21/2023	INSPTR	MD2797
GRASS VALLEY	12/9/2021	6/10/2024	7/13/2023	INSPTR	RW5286
GRASS VALLEY	12/9/2021	6/10/2024	8/26/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/10/2024	6/29/2023	INSPTR	PC9347
GRASS VALLEY	12/9/2021	6/10/2024	8/28/2023	INSPTR	JM1295
GRASS VALLEY	12/9/2021	6/7/2024	8/12/2023	INSPTR	SB6349
GRASS VALLEY	12/9/2021	6/7/2024	8/11/2023	INSPTR	RX3937
GRASS VALLEY	12/9/2021	6/7/2024	8/11/2023	INSPTR	RX3937
GRASS VALLEY	12/9/2021	6/10/2024	8/7/2023	INSPTR	WE5739
GRASS VALLEY	12/9/2021	6/10/2024	8/10/2023	INSPTR	MD2797
GRASS VALLEY	12/9/2021	6/10/2024	8/21/2023	INSPTR	MD2797
GRASS VALLEY	12/9/2021	6/10/2022	12/13/2021	INSPTR	JJ6768
GRASS VALLEY	12/9/2021	6/10/2024	9/12/2023	INSPTR	MD4156
GRASS VALLEY	12/9/2021	6/4/2024	8/3/2023	INSPTR	JO1454
GRASS VALLEY	12/9/2021	6/4/2024	8/4/2023	INSPTR	PC9347
GRASS VALLEY	12/9/2021	6/7/2024	8/11/2023	INSPTR	RP6278
GRASS VALLEY	12/9/2021	6/4/2022	2/21/2022	INSPTR	JA1893
GRASS VALLEY	12/9/2021	12/18/2021	2/23/2022	INSPTR	AG2675
GRASS VALLEY	12/9/2021	6/7/2024	8/11/2023	INSPTR	RP6278
GRASS VALLEY	12/9/2021	6/7/2024	8/11/2023	INSPTR	JM1295
GRASS VALLEY	12/9/2021	6/7/2024	8/11/2023	INSPTR	KL2356
GRASS VALLEY	12/9/2021	6/7/2024	8/11/2023	INSPTR	KL2356
GRASS VALLEY	12/9/2021	6/10/2024	8/10/2023	INSPTR	MD2797
GRASS VALLEY	12/9/2021	6/10/2024	8/10/2023	INSPTR	MD2797
GRASS VALLEY	12/9/2021	12/10/2021	2/22/2022	INSPTR	JI2512
GRASS VALLEY	12/9/2021	6/10/2024	9/12/2023	INSPTR	MD4156

GRASS VALLEY	12/9/2021	1/2/2022	2/15/2022	INSPTR	BK2151
GRASS VALLEY	12/9/2021	6/14/2024	10/8/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/4/2024	8/4/2023	INSPTR	SB6349
GRASS VALLEY	12/9/2021	6/7/2024	8/11/2023	INSPTR	JM1295
GRASS VALLEY	12/9/2021	6/4/2024	8/4/2023	INSPTR	RC5742
GRASS VALLEY	12/9/2021	5/27/2024	7/22/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/7/2024	8/12/2023	INSPTR	MD2797
GRASS VALLEY	12/9/2021	6/7/2024	8/11/2023	INSPTR	MM3647
GRASS VALLEY	12/9/2021	6/7/2024	8/12/2023	INSPTR	WE5739
GRASS VALLEY	12/9/2021	6/7/2024	8/12/2023	INSPTR	WE5739
GRASS VALLEY	12/9/2021	6/10/2024	8/10/2023	INSPTR	MD2797
GRASS VALLEY	12/9/2021	6/10/2024	8/26/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/10/2024	7/28/2023	INSPTR	DM820T
GRASS VALLEY	12/9/2021	6/14/2024	7/28/2023	INSPTR	DM820T
GRASS VALLEY	12/9/2021	6/14/2024	7/28/2023	INSPTR	DM820T
GRASS VALLEY	12/9/2021	6/14/2024	8/18/2023	INSPTR	DM820T
GRASS VALLEY	12/9/2021	6/14/2024	10/8/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/14/2024	8/18/2023	INSPTR	DM820T
GRASS VALLEY	12/9/2021	12/10/2021	2/22/2022	INSPTR	JI2512
GRASS VALLEY	12/9/2021	6/5/2024	8/10/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/5/2024	8/10/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/4/2024	8/8/2023	INSPTR	RC5742
GRASS VALLEY	12/9/2021	6/5/2024	8/10/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/8/2022	12/13/2021	INSPTR	DC2631
GRASS VALLEY	12/9/2021	6/8/2024	8/2/2023	INSPTR	DM820T
GRASS VALLEY	12/9/2021	6/9/2024	8/18/2023	INSPTR	MD4156
GRASS VALLEY	12/9/2021	6/9/2024	8/19/2023	INSPTR	MD2797
GRASS VALLEY	12/9/2021	6/14/2024	10/6/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/14/2024	8/18/2023	INSPTR	MD4156
GRASS VALLEY	12/9/2021	6/14/2024	8/18/2023	INSPTR	MD4156
GRASS VALLEY	12/9/2021	6/14/2024	8/18/2023	INSPTR	RW5286
GRASS VALLEY	12/9/2021	6/14/2024	8/18/2023	INSPTR	RW5286
GRASS VALLEY	12/9/2021	6/14/2024	8/18/2023	INSPTR	JM1295
GRASS VALLEY	12/9/2021	6/14/2024	7/29/2023	INSPTR	DM820T
GRASS VALLEY	12/9/2021	6/14/2024	7/29/2023	INSPTR	DM820T
GRASS VALLEY	12/9/2021	6/14/2024	7/29/2023	INSPTR	DM820T
GRASS VALLEY	12/9/2021	6/5/2024	8/11/2023	INSPTR	ML1973
GRASS VALLEY	12/9/2021	6/5/2024	8/10/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/8/2024	8/2/2023	INSPTR	DM820T
GRASS VALLEY	12/9/2021	6/5/2024	8/10/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/7/2024	8/13/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/7/2024	8/13/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	12/9/2021	2/23/2022	INSPTR	MD4156
GRASS VALLEY	12/9/2021	6/3/2024	7/22/2023	INSPTR	RC5742

GRASS VALLEY	12/9/2021	6/9/2024	8/18/2023	INSPTR	JM1295
GRASS VALLEY	12/9/2021	6/9/2022	12/13/2021	INSPTR	JA1893
GRASS VALLEY	12/9/2021	6/9/2024	8/19/2023	INSPTR	MD2797
GRASS VALLEY	12/9/2021	6/9/2024	8/19/2023	INSPTR	MD2797
GRASS VALLEY	12/9/2021	6/9/2024	8/19/2023	INSPTR	MD2797
GRASS VALLEY	12/9/2021	7/20/2024	9/26/2023	INSPTR	PC9347
GRASS VALLEY	12/9/2021	7/20/2024	9/26/2023	INSPTR	PC9347
GRASS VALLEY	12/9/2021	1/29/2022	2/22/2022	INSPTR	JS2145
GRASS VALLEY	12/9/2021	7/29/2024	10/10/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	8/7/2024	8/15/2023	INSPTR	MD2797
GRASS VALLEY	12/9/2021	12/17/2021	2/23/2022	INSPTR	AM8121
GRASS VALLEY	12/9/2021	6/17/2024	8/15/2023	INSPTR	MM3647
GRASS VALLEY	12/9/2021	6/22/2024	8/10/2023	INSPTR	VC6131
GRASS VALLEY	12/9/2021	6/23/2024	8/10/2023	INSPTR	VC6131
GRASS VALLEY	12/9/2021	6/22/2024	8/10/2023	INSPTR	JO1454
GRASS VALLEY	12/9/2021	6/22/2022	12/13/2021	INSPTR	BK2151
GRASS VALLEY	12/9/2021	6/22/2024	8/19/2023	INSPTR	JM1295
GRASS VALLEY	12/9/2021	12/22/2021	2/23/2022	INSPTR	AG2675
GRASS VALLEY	12/9/2021	6/22/2024	7/22/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/26/2024	10/14/2023	INSPTR	RW5286
GRASS VALLEY	12/9/2021	6/26/2024	3/24/2024	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/26/2024	3/24/2024	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/28/2024	7/22/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	1/30/2022	2/15/2022	INSPTR	AM2764
GRASS VALLEY	12/9/2021	6/17/2024	10/20/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/17/2024	7/21/2023	INSPTR	MM3647
GRASS VALLEY	12/9/2021	6/17/2024	12/13/2023	INSPTR	PC9347
GRASS VALLEY	12/9/2021	6/21/2024	12/13/2023	INSPTR	PC9347
GRASS VALLEY	12/9/2021	6/22/2024	8/29/2023	INSPTR	MD4156
GRASS VALLEY	12/9/2021	6/23/2024	12/13/2023	INSPTR	RW5286
GRASS VALLEY	12/9/2021	6/23/2024	10/15/2023	INSPTR	RW5286
GRASS VALLEY	12/9/2021	6/23/2024	10/18/2023	INSPTR	MD4156
GRASS VALLEY	12/9/2021	6/23/2024	10/15/2023	INSPTR	RW5286
GRASS VALLEY	12/9/2021	6/23/2024	10/13/2023	INSPTR	MM3647
GRASS VALLEY	12/9/2021	6/23/2024	8/7/2023	INSPTR	MD2797
GRASS VALLEY	12/9/2021	6/22/2024	7/22/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/22/2024	8/19/2023	INSPTR	JM1295
GRASS VALLEY	12/9/2021	6/22/2022	12/13/2021	INSPTR	BK2151
GRASS VALLEY	12/9/2021	6/22/2024	10/5/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/29/2022	2/15/2022	INSPTR	JR8198
GRASS VALLEY	12/9/2021	7/8/2024	10/5/2023	INSPTR	RW5286
GRASS VALLEY	12/9/2021	7/8/2024	10/5/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	7/8/2024	10/4/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	8/6/2024	10/3/2023	INSPTR	LP848K

GRASS VALLEY	12/9/2021	6/16/2024	9/27/2023	INSPTR	MM3647
GRASS VALLEY	12/9/2021	6/18/2024	7/22/2023	INSPTR	DM820T
GRASS VALLEY	12/9/2021	6/18/2024	7/22/2023	INSPTR	DM820T
GRASS VALLEY	12/9/2021	6/23/2024	9/26/2023	INSPTR	RW5286
GRASS VALLEY	12/9/2021	6/23/2024	8/29/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/23/2022	12/13/2021	INSPTR	BK2151
GRASS VALLEY	12/9/2021	6/23/2024	8/10/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/23/2024	8/29/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/21/2024	8/29/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/22/2024	9/12/2023	INSPTR	PC9347
GRASS VALLEY	12/9/2021	6/24/2024	9/12/2023	INSPTR	PC9347
GRASS VALLEY	12/9/2021	6/24/2024	9/12/2023	INSPTR	PC9347
GRASS VALLEY	12/9/2021	6/24/2024	9/26/2023	INSPTR	RW5286
GRASS VALLEY	12/9/2021	6/30/2024	9/26/2023	INSPTR	MM3647
GRASS VALLEY	12/9/2021	12/31/2021	2/15/2022	INSPTR	JA1893
GRASS VALLEY	12/9/2021	6/29/2024	9/22/2023	INSPTR	MM3647
GRASS VALLEY	12/9/2021	6/29/2024	9/12/2023	INSPTR	DM820T
GRASS VALLEY	12/9/2021	7/14/2024	9/12/2023	INSPTR	DM820T
GRASS VALLEY	12/9/2021	7/14/2024	8/17/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	7/14/2024	8/31/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	7/14/2024	8/31/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	7/14/2024	8/31/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	7/14/2022	2/23/2022	INSPTR	AG2675
GRASS VALLEY	12/9/2021	7/14/2022	2/24/2022	INSPTR	SM1897
GRASS VALLEY	12/9/2021	7/14/2024	8/31/2023	INSPTR	PC9347
GRASS VALLEY	12/9/2021	8/6/2024	9/12/2023	INSPTR	DM820T
GRASS VALLEY	12/9/2021	8/6/2024	9/16/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/16/2024	8/18/2023	INSPTR	JS2145
GRASS VALLEY	12/9/2021	6/15/2024	8/15/2023	INSPTR	MD4156
GRASS VALLEY	12/9/2021	6/15/2024	8/1/2023	INSPTR	WE5739
GRASS VALLEY	12/9/2021	6/15/2024	8/17/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/15/2024	8/17/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/15/2024	9/16/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/16/2024	9/12/2023	INSPTR	MD4156
GRASS VALLEY	12/9/2021	6/21/2024	8/25/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/21/2024	7/22/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/21/2024	8/29/2023	INSPTR	MM3647
GRASS VALLEY	12/9/2021	6/21/2022	12/13/2021	INSPTR	EL8648
GRASS VALLEY	12/9/2021	6/21/2022	12/13/2021	INSPTR	EL8648
GRASS VALLEY	12/9/2021	6/22/2024	8/15/2023	INSPTR	MM3647
GRASS VALLEY	12/9/2021	6/18/2024	8/17/2023	INSPTR	MD4156
GRASS VALLEY	12/9/2021	6/18/2024	8/10/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/24/2024	8/29/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/24/2024	8/29/2023	INSPTR	MM3647

GRASS VALLEY	12/9/2021	6/24/2024	8/29/2023	INSPTR	VC6131
GRASS VALLEY	12/9/2021	6/24/2024	8/15/2023	INSPTR	RC5742
GRASS VALLEY	12/9/2021	6/24/2024	8/25/2023	INSPTR	PC9347
GRASS VALLEY	12/9/2021	6/24/2024	8/24/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/30/2024	8/24/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/30/2024	8/24/2023	INSPTR	PC9347
GRASS VALLEY	12/9/2021	12/28/2021	2/16/2022	INSPTR	OD4318
GRASS VALLEY	12/9/2021	6/29/2024	8/24/2023	INSPTR	PC9347
GRASS VALLEY	12/9/2021	7/1/2024	8/24/2023	INSPTR	VC6131
GRASS VALLEY	12/9/2021	7/2/2024	8/15/2023	INSPTR	WE5739
GRASS VALLEY	12/9/2021	7/2/2024	8/24/2023	INSPTR	VC6131
GRASS VALLEY	12/9/2021	7/2/2024	8/22/2023	INSPTR	MD4156
GRASS VALLEY	12/9/2021	7/15/2024	8/14/2023	INSPTR	SB6349
GRASS VALLEY	12/9/2021	7/15/2024	8/10/2023	INSPTR	MM3647
GRASS VALLEY	12/9/2021	7/15/2024	8/10/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	7/16/2024	8/10/2023	INSPTR	MM3647
GRASS VALLEY	12/9/2021	7/16/2024	8/10/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	7/16/2024	8/10/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/16/2024	8/21/2023	INSPTR	JS2145
GRASS VALLEY	12/9/2021	6/16/2024	8/17/2023	INSPTR	VC6131
GRASS VALLEY	12/9/2021	12/17/2021	2/15/2022	INSPTR	BK2151
GRASS VALLEY	12/9/2021	6/17/2024	8/17/2023	INSPTR	VC6131
GRASS VALLEY	12/9/2021	6/17/2024	8/17/2023	INSPTR	PC9347
GRASS VALLEY	12/9/2021	6/18/2024	8/17/2023	INSPTR	PC9347
GRASS VALLEY	12/9/2021	6/18/2024	8/11/2023	INSPTR	WE5739
GRASS VALLEY	12/9/2021	6/18/2024	8/16/2023	INSPTR	MD2797
GRASS VALLEY	12/9/2021	6/24/2024	8/14/2023	INSPTR	PC9347
GRASS VALLEY	12/9/2021	6/24/2024	8/10/2023	INSPTR	VC6131
GRASS VALLEY	12/9/2021	6/24/2024	8/10/2023	INSPTR	VC6131
GRASS VALLEY	12/9/2021	6/24/2024	8/16/2023	INSPTR	MD4156
GRASS VALLEY	12/9/2021	6/24/2024	8/14/2023	INSPTR	PC9347
GRASS VALLEY	12/9/2021	6/24/2024	8/16/2023	INSPTR	MD4156
GRASS VALLEY	12/9/2021	6/24/2024	8/9/2023	INSPTR	JO1454
GRASS VALLEY	12/9/2021	6/24/2024	8/16/2023	INSPTR	MM3647
GRASS VALLEY	12/9/2021	6/28/2022	2/23/2022	INSPTR	JA1893
GRASS VALLEY	12/9/2021	6/28/2022	2/23/2022	INSPTR	AM8121
GRASS VALLEY	12/9/2021	6/28/2024	8/16/2023	INSPTR	RW5286
GRASS VALLEY	12/9/2021	6/28/2022	2/22/2022	INSPTR	JA1893
GRASS VALLEY	12/9/2021	6/28/2024	8/16/2023	INSPTR	VC6131
GRASS VALLEY	12/9/2021	6/28/2024	8/16/2023	INSPTR	RW5286
GRASS VALLEY	12/9/2021	7/2/2024	8/16/2023	INSPTR	VC6131
GRASS VALLEY	12/9/2021	7/2/2024	8/14/2023	INSPTR	JS2145
GRASS VALLEY	12/9/2021	7/6/2024	8/14/2023	INSPTR	VC6131
GRASS VALLEY	12/9/2021	7/16/2024	8/14/2023	INSPTR	VC6131

GRASS VALLEY	12/9/2021	7/13/2024	8/10/2023	INSPTR	RC5742
GRASS VALLEY	12/9/2021	6/16/2024	8/9/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/16/2024	8/9/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/17/2024	8/9/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/17/2024	8/9/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/17/2024	8/10/2023	INSPTR	JS2145
GRASS VALLEY	12/9/2021	6/17/2022	2/23/2022	INSPTR	DI1638
GRASS VALLEY	12/9/2021	6/17/2022	12/13/2021	INSPTR	EL8648
GRASS VALLEY	12/9/2021	6/16/2024	8/10/2023	INSPTR	JS2145
GRASS VALLEY	12/9/2021	6/16/2024	8/10/2023	INSPTR	JS2145
GRASS VALLEY	12/9/2021	12/16/2021	2/15/2022	INSPTR	BK2151
GRASS VALLEY	12/9/2021	6/16/2024	8/10/2023	INSPTR	JO1454
GRASS VALLEY	12/9/2021	6/16/2024	8/10/2023	INSPTR	JO1454
GRASS VALLEY	12/9/2021	6/16/2024	8/10/2023	INSPTR	JO1454
GRASS VALLEY	12/9/2021	12/18/2021	2/21/2022	INSPTR	JA1893
GRASS VALLEY	12/9/2021	6/18/2024	8/5/2023	INSPTR	DM820T
GRASS VALLEY	12/9/2021	6/18/2024	8/10/2023	INSPTR	RW5286
GRASS VALLEY	12/9/2021	6/18/2024	8/10/2023	INSPTR	RW5286
GRASS VALLEY	12/9/2021	12/18/2021	2/21/2022	INSPTR	JA1893
GRASS VALLEY	12/9/2021	6/25/2022	2/15/2022	INSPTR	CC6897
GRASS VALLEY	12/9/2021	6/25/2024	8/8/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/23/2022	12/13/2021	INSPTR	WW1427
GRASS VALLEY	12/9/2021	6/23/2024	8/8/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	6/23/2024	8/7/2023	INSPTR	VC6131
GRASS VALLEY	12/9/2021	6/23/2024	8/7/2023	INSPTR	WE5739
GRASS VALLEY	12/9/2021	6/30/2024	8/4/2023	INSPTR	MM3647
GRASS VALLEY	12/9/2021	6/30/2024	7/27/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/30/2024	7/27/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/30/2024	7/27/2023	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/30/2024	8/3/2023	INSPTR	DM820T
GRASS VALLEY	12/9/2021	7/7/2024	8/3/2023	INSPTR	MM3647
GRASS VALLEY	12/9/2021	7/7/2024	8/3/2023	INSPTR	DM820T
GRASS VALLEY	12/9/2021	7/9/2024	8/3/2023	INSPTR	MM3647
GRASS VALLEY	12/9/2021	2/4/2022	2/15/2022	INSPTR	AM2764
GRASS VALLEY	12/9/2021	8/4/2024	8/11/2023	INSPTR	RC5742
GRASS VALLEY	12/9/2021	8/4/2024	8/4/2023	INSPTR	VC6131
GRASS VALLEY	12/9/2021	12/17/2021	2/23/2022	INSPTR	JS2145
GRASS VALLEY	12/9/2021	6/17/2024	8/3/2023	INSPTR	MM3647
GRASS VALLEY	12/9/2021	6/17/2024	7/20/2023	INSPTR	VC6131
GRASS VALLEY	12/9/2021	6/17/2024	8/3/2023	INSPTR	RC5742
GRASS VALLEY	12/9/2021	12/17/2021	12/14/2021	INSPTR	SM4953
GRASS VALLEY	12/9/2021	6/17/2024	7/29/2023	INSPTR	JM1295
GRASS VALLEY	12/9/2021	6/17/2024	8/4/2023	INSPTR	VC6131
GRASS VALLEY	12/9/2021	6/16/2024	8/4/2023	INSPTR	QB6851

GRASS VALLEY	12/9/2021	6/16/2024	8/4/2023	INSPTR	JS2145
GRASS VALLEY	12/9/2021	6/16/2024	8/4/2023	INSPTR	JS2145
GRASS VALLEY	12/9/2021	6/16/2024	8/3/2023	INSPTR	JM1295
GRASS VALLEY	12/9/2021	6/16/2024	8/3/2023	INSPTR	JM1295
GRASS VALLEY	12/9/2021	6/17/2024	7/20/2023	INSPTR	DM820T
GRASS VALLEY	12/9/2021	6/17/2024	8/3/2023	INSPTR	JM1295
GRASS VALLEY	12/9/2021	6/17/2024	7/19/2023	INSPTR	JM1295
GRASS VALLEY	12/9/2021	6/18/2024	8/3/2023	INSPTR	PC9347
GRASS VALLEY	12/9/2021	6/18/2024	8/3/2023	INSPTR	PC9347
GRASS VALLEY	12/9/2021	6/18/2024	8/3/2023	INSPTR	PC9347
GRASS VALLEY	12/9/2021	6/21/2022	12/13/2021	INSPTR	BK2151
GRASS VALLEY	12/9/2021	6/21/2024	8/3/2023	INSPTR	VC6131
GRASS VALLEY	12/9/2021	6/21/2024	8/3/2023	INSPTR	VC6131
GRASS VALLEY	12/9/2021	6/21/2022	12/13/2021	INSPTR	BK2151
GRASS VALLEY	12/9/2021	6/23/2024	8/3/2023	INSPTR	VC6131
GRASS VALLEY	12/9/2021	6/23/2024	8/2/2023	INSPTR	ML1973
GRASS VALLEY	12/9/2021	6/30/2024	7/31/2023	INSPTR	VC6131
GRASS VALLEY	12/9/2021	6/25/2024	7/31/2023	INSPTR	VC6131
GRASS VALLEY	12/9/2021	6/25/2022	12/13/2021	INSPTR	WW1427
GRASS VALLEY	12/9/2021	7/9/2024	7/31/2023	INSPTR	JO1454
GRASS VALLEY	12/9/2021	7/9/2024	7/31/2023	INSPTR	JO1454
GRASS VALLEY	12/9/2021	7/9/2024	7/24/2023	INSPTR	DM820T
GRASS VALLEY	12/9/2021	7/6/2024	7/24/2023	INSPTR	DM820T
GRASS VALLEY	12/9/2021	7/6/2024	7/24/2023	INSPTR	DM820T
GRASS VALLEY	12/9/2021	7/6/2024	7/17/2023	INSPTR	RW5286
GRASS VALLEY	12/9/2021	7/6/2024	7/31/2023	INSPTR	JS2145
GRASS VALLEY	12/9/2021	7/6/2024	7/31/2023	INSPTR	WE5739
GRASS VALLEY	12/9/2021	8/7/2024	8/8/2023	INSPTR	VC6131
GRASS VALLEY	12/9/2021	8/7/2024	8/8/2023	INSPTR	MM3647
GRASS VALLEY	12/9/2021	8/7/2024	8/8/2023	INSPTR	MM3647
GRASS VALLEY	12/9/2021	6/17/2024	7/31/2023	INSPTR	MM3647
GRASS VALLEY	12/9/2021	6/17/2024	7/31/2023	INSPTR	MM3647
GRASS VALLEY	12/9/2021	6/21/2024	7/24/2023	INSPTR	PC9347
GRASS VALLEY	12/9/2021	6/21/2024	7/24/2023	INSPTR	PC9347
GRASS VALLEY	12/9/2021	6/21/2024	7/20/2023	INSPTR	MD4156
GRASS VALLEY	12/9/2021	6/21/2024	7/28/2023	INSPTR	RW5286
GRASS VALLEY	12/9/2021	6/21/2024	7/28/2023	INSPTR	RW5286
GRASS VALLEY	12/9/2021	6/21/2024	8/2/2023	INSPTR	WE5739
GRASS VALLEY	12/9/2021	6/21/2024	7/27/2023	INSPTR	MD2797
GRASS VALLEY	12/9/2021	6/21/2024	7/26/2023	INSPTR	JS2145
GRASS VALLEY	12/9/2021	6/25/2024	7/25/2023	INSPTR	JS2145
GRASS VALLEY	12/9/2021	6/25/2024	7/22/2023	INSPTR	VC6131
GRASS VALLEY	12/9/2021	6/25/2024	7/22/2023	INSPTR	JM1295
GRASS VALLEY	12/9/2021	6/25/2024	7/20/2023	INSPTR	PC9347

GRASS VALLEY	12/9/2021	7/6/2024	7/20/2023	INSPTR	MM3647
GRASS VALLEY	12/9/2021	7/1/2024	7/20/2023	INSPTR	MM3647
GRASS VALLEY	12/9/2021	7/1/2024	7/20/2023	INSPTR	VC6131
GRASS VALLEY	12/9/2021	7/1/2024	7/20/2023	INSPTR	PC9347
GRASS VALLEY	12/9/2021	7/1/2024	7/20/2023	INSPTR	VC6131
GRASS VALLEY	12/9/2021	7/1/2024	10/8/2022	INSPTR	RW5286
GRASS VALLEY	12/9/2021	7/1/2024	10/8/2022	INSPTR	JM1295
GRASS VALLEY	12/9/2021	7/1/2024	10/8/2022	INSPTR	VC6131
GRASS VALLEY	12/9/2021	7/1/2024	10/8/2022	INSPTR	VC6131
GRASS VALLEY	12/9/2021	7/1/2024	10/8/2022	INSPTR	MD4156
GRASS VALLEY	12/9/2021	6/29/2024	10/13/2022	INSPTR	LP848K
GRASS VALLEY	12/9/2021	6/29/2022	12/10/2021	INSPTR	JO1454
GRASS VALLEY	12/9/2021	8/5/2024	10/12/2022	INSPTR	QB6851
GRASS VALLEY	12/9/2021	8/5/2024	10/12/2022	INSPTR	CG4741
GRASS VALLEY	12/9/2021	8/5/2024	10/12/2022	INSPTR	AG2675
GRASS VALLEY	12/9/2021	8/5/2024	10/17/2022	INSPTR	MD4156
GRASS VALLEY	12/9/2021	6/29/2024	10/14/2022	INSPTR	GG8932
GRASS VALLEY	12/9/2021	6/29/2024	10/8/2022	INSPTR	PC9347
GRASS VALLEY	12/9/2021	6/29/2024	10/17/2022	INSPTR	VC6131
GRASS VALLEY	12/9/2021	6/29/2024	10/16/2022	INSPTR	QB6851
GRASS VALLEY	12/9/2021	8/4/2024	10/8/2022	INSPTR	GG8932
GRASS VALLEY	12/9/2021	6/29/2024	10/8/2022	INSPTR	PC9347
GRASS VALLEY	12/9/2021	7/13/2024	7/20/2023	INSPTR	QB6851
GRASS VALLEY	12/9/2021	7/13/2024	10/13/2022	INSPTR	CG4741
GRASS VALLEY	12/9/2021	7/13/2024	10/13/2022	INSPTR	AG2675
GRASS VALLEY	12/9/2021	8/1/2024	10/16/2022	INSPTR	QB6851
GRASS VALLEY	12/9/2021	7/21/2024	10/14/2022	INSPTR	QB6851
GRASS VALLEY	12/9/2021	7/19/2024	10/7/2022	INSPTR	CG4741
GRASS VALLEY	12/9/2021	7/21/2024	10/7/2022	INSPTR	GG8932
GRASS VALLEY	12/9/2021	7/19/2024	10/8/2022	INSPTR	QB6851
GRASS VALLEY	12/9/2021	7/20/2024	10/10/2022	INSPTR	MM3647
GRASS VALLEY	12/9/2021	8/2/2024	10/8/2022	INSPTR	JM1295
QUINCY	12/10/2021	12/13/2021	2/2/2022	SF8537	SF8537
PORTOLA	12/21/2021	9/27/2024	10/16/2023	INSPTR	SF8537
PORTOLA	12/21/2021	9/28/2024	3/26/2024	INSPTR	SF8537
PORTOLA	12/21/2021	9/28/2024	10/16/2023	INSPTR	SF8537
PORTOLA	12/21/2021	10/11/2024	4/2/2024	INSPTR	SF8537
PORTOLA	12/21/2021	10/12/2024	1/4/2024	INSPTR	SF8537
PORTOLA	12/21/2021	10/12/2024	2/7/2024	INSPTR	SF8537
PORTOLA	12/21/2021	10/11/2024	4/2/2024	INSPTR	SF8537
PORTOLA	12/21/2021	10/11/2024	4/1/2024	INSPTR	SF8537
PORTOLA	12/21/2021	10/11/2024	4/1/2024	INSPTR	SF8537
PORTOLA	12/21/2021	10/11/2024	4/1/2024	INSPTR	SF8537
PORTOLA	12/21/2021	10/11/2024	4/1/2024	INSPTR	SF8537

PORTOLA	12/21/2021	10/11/2024	4/1/2024	INSPTR	SF8537
PORTOLA	12/21/2021	10/11/2024	4/1/2024	INSPTR	SF8537
PORTOLA	12/21/2021	10/18/2024	11/17/2023	INSPTR	SF8537
PORTOLA	12/21/2021	10/19/2024	12/13/2023	INSPTR	SF8537
PORTOLA	12/21/2021	10/18/2024	2/1/2024	INSPTR	SF8537
PORTOLA	12/21/2021	10/18/2024	2/1/2024	INSPTR	SF8537
PORTOLA	12/21/2021	10/19/2024	12/13/2023	INSPTR	SF8537
PORTOLA	12/21/2021	10/19/2024	12/13/2023	INSPTR	SF8537
PORTOLA	12/21/2021	10/18/2024	2/7/2024	INSPTR	SF8537
PORTOLA	12/21/2021	10/18/2024	11/27/2023	INSPTR	SF8537
QUINCY	12/21/2021	10/5/2024	10/12/2023	INSPTR	SF8537
QUINCY	12/21/2021	10/5/2022	2/18/2022	INSPTR	SF8537
QUINCY	12/21/2021	10/5/2024	10/12/2023	INSPTR	SF8537
QUINCY	12/21/2021	10/5/2024	10/24/2023	INSPTR	SF8537
QUINCY	12/21/2021	10/6/2024	1/31/2024	INSPTR	SF8537
QUINCY	12/21/2021	10/6/2024	2/13/2024	INSPTR	SF8537
QUINCY	12/21/2021	10/6/2024	2/13/2024	INSPTR	SF8537
PORTOLA	12/21/2021	10/11/2024	4/2/2024	INSPTR	SF8537
PORTOLA	12/21/2021	10/11/2024	3/15/2024	INSPTR	SF8537
PORTOLA	12/21/2021	10/11/2024	3/15/2024	INSPTR	SF8537
PORTOLA	12/21/2021	10/11/2024	4/2/2024	INSPTR	SF8537
PORTOLA	12/21/2021	10/11/2024	3/15/2024	INSPTR	SF8537
QUINCY	12/21/2021	9/29/2024	10/2/2023	INSPTR	SF8537
QUINCY	12/21/2021	9/29/2024	10/2/2023	INSPTR	SF8537
QUINCY	12/21/2021	10/7/2024	10/12/2023	INSPTR	SF8537
QUINCY	12/21/2021	10/7/2024	2/13/2024	INSPTR	SF8537
QUINCY	12/21/2021	10/7/2024	10/19/2023	INSPTR	SF8537
QUINCY	12/21/2021	10/7/2024	2/13/2024	INSPTR	SF8537
QUINCY	12/21/2021	10/7/2024	2/13/2024	INSPTR	SF8537
QUINCY	12/21/2021	10/7/2024	10/19/2023	INSPTR	SF8537
QUINCY	12/21/2021	10/7/2024	10/17/2023	INSPTR	SF8537
QUINCY	12/21/2021	10/7/2024	10/19/2023	INSPTR	SF8537
QUINCY	12/21/2021	10/7/2024	10/19/2023	INSPTR	SF8537
QUINCY	12/21/2021	10/7/2024	10/18/2023	INSPTR	SF8537
QUINCY	12/21/2021	10/7/2024	10/19/2023	INSPTR	SF8537
QUINCY	12/21/2021	10/7/2024	10/17/2023	INSPTR	SF8537
PORTOLA	12/21/2021	10/12/2024	11/27/2023	INSPTR	SF8537
PORTOLA	12/21/2021	10/12/2024	11/27/2023	INSPTR	SF8537
PORTOLA	12/21/2021	10/12/2024	2/7/2024	INSPTR	SF8537
PORTOLA	12/21/2021	10/12/2024	11/27/2023	INSPTR	SF8537
PORTOLA	12/21/2021	10/12/2024	3/14/2024	INSPTR	SF8537
PORTOLA	12/21/2021	10/12/2024	3/14/2024	INSPTR	SF8537
PORTOLA	12/21/2021	10/12/2024	3/14/2024	INSPTR	SF8537
PORTOLA	12/21/2021	10/12/2024	2/7/2024	INSPTR	SF8537

PORTOLA	12/21/2021	10/18/2024	11/17/2023	INSPTR	SF8537
PORTOLA	12/21/2021	10/20/2024	12/13/2023	INSPTR	SF8537
PORTOLA	12/21/2021	10/19/2024	3/26/2024	INSPTR	SF8537
QUINCY	12/21/2021	10/7/2024	10/18/2023	INSPTR	SF8537
QUINCY	12/21/2021	4/8/2022	2/3/2022	INSPTR	SF8537
QUINCY	12/21/2021	10/8/2024	10/10/2023	INSPTR	SF8537
PORTOLA	12/21/2021	10/12/2024	3/26/2024	INSPTR	SF8537
PORTOLA	12/21/2021	10/9/2024	10/16/2023	INSPTR	SF8537
PORTOLA	12/21/2021	10/12/2024	3/14/2024	INSPTR	SF8537
PORTOLA	12/21/2021	10/12/2024	3/14/2024	INSPTR	SF8537
PORTOLA	12/21/2021	9/24/2024	10/3/2023	INSPTR	SF8537
PORTOLA	12/21/2021	9/25/2024	1/23/2024	INSPTR	SF8537
PORTOLA	12/21/2021	9/25/2024	10/13/2023	INSPTR	SF8537
PORTOLA	12/21/2021	9/25/2024	10/13/2023	INSPTR	SF8537
QUINCY	12/21/2021	9/27/2024	9/27/2023	INSPTR	SF8537
QUINCY	12/21/2021	9/29/2024	10/18/2023	INSPTR	SF8537
QUINCY	12/21/2021	9/30/2024	10/5/2023	INSPTR	SF8537
QUINCY	12/21/2021	9/30/2024	10/12/2023	INSPTR	SF8537
QUINCY	12/21/2021	9/30/2024	10/18/2023	INSPTR	SF8537
QUINCY	12/21/2021	9/30/2024	10/5/2023	INSPTR	SF8537
PORTOLA	12/21/2021	9/25/2024	11/30/2023	INSPTR	SF8537
PORTOLA	12/21/2021	9/25/2024	10/13/2023	INSPTR	SF8537
PORTOLA	12/21/2021	9/27/2024	1/4/2024	INSPTR	SF8537
PORTOLA	12/21/2021	9/27/2024	1/4/2024	INSPTR	SF8537
PORTOLA	12/21/2021	9/27/2024	10/16/2023	INSPTR	SF8537
QUINCY	12/21/2021	9/28/2024	9/28/2023	INSPTR	SF8537
QUINCY	12/21/2021	10/1/2024	10/12/2023	INSPTR	SF8537
QUINCY	12/21/2021	10/1/2024	10/12/2023	INSPTR	SF8537
QUINCY	12/21/2021	10/1/2024	10/17/2023	INSPTR	SF8537
QUINCY	12/21/2021	10/1/2024	10/12/2023	INSPTR	SF8537
PORTOLA	12/21/2021	10/18/2024	11/27/2023	INSPTR	SF8537
PORTOLA	12/21/2021	10/20/2024	12/13/2023	INSPTR	SF8537
PORTOLA	12/21/2021	10/20/2024	3/27/2024	INSPTR	SF8537
PORTOLA	12/21/2021	10/20/2024	3/27/2024	INSPTR	SF8537
PORTOLA	12/21/2021	10/20/2024	4/3/2024	INSPTR	SF8537
QUINCY	12/21/2021	9/30/2024	10/12/2023	INSPTR	SF8537
QUINCY	12/21/2021	9/30/2024	10/19/2023	INSPTR	SF8537
QUINCY	12/21/2021	9/30/2024	10/18/2023	INSPTR	SF8537
QUINCY	12/21/2021	9/30/2024	10/5/2023	INSPTR	SF8537
QUINCY	12/21/2021	9/30/2024	10/5/2023	INSPTR	SF8537
QUINCY	12/21/2021	9/30/2024	10/18/2023	INSPTR	SF8537
QUINCY	12/21/2021	9/30/2024	10/18/2023	INSPTR	SF8537
QUINCY	12/21/2021	9/30/2024	10/17/2023	INSPTR	SF8537
QUINCY	12/21/2021	9/30/2024	10/5/2023	INSPTR	SF8537

QUINCY	12/21/2021	9/30/2024	10/5/2023	INSPTR	SF8537
QUINCY	12/21/2021	9/27/2024	9/27/2023	INSPTR	SF8537
QUINCY	12/21/2021	9/27/2024	9/27/2023	INSPTR	SF8537
QUINCY	12/21/2021	9/27/2024	9/27/2023	INSPTR	SF8537
QUINCY	12/21/2021	10/8/2024	10/18/2023	INSPTR	SF8537
QUINCY	12/21/2021	3/24/2022	2/3/2022	INSPTR	SF8537
QUINCY	12/21/2021	9/27/2024	9/27/2023	INSPTR	SF8537
QUINCY	12/21/2021	10/5/2024	10/24/2023	INSPTR	SF8537
QUINCY	12/21/2021	10/5/2024	10/19/2023	INSPTR	SF8537
QUINCY	12/21/2021	9/27/2024	9/27/2023	INSPTR	SF8537
QUINCY	12/21/2021	10/5/2022	2/17/2022	INSPTR	SF8537
QUINCY	12/21/2021	10/5/2022	2/17/2022	INSPTR	SF8537
QUINCY	12/21/2021	10/7/2024	10/18/2023	INSPTR	SF8537
QUINCY	12/21/2021	10/7/2024	10/17/2023	INSPTR	SF8537
PORTOLA	12/21/2021	10/12/2024	2/7/2024	INSPTR	SF8537
PORTOLA	12/21/2021	10/12/2024	2/7/2024	INSPTR	SF8537
PORTOLA	12/21/2021	10/12/2024	2/7/2024	INSPTR	SF8537
QUINCY	12/21/2021	10/1/2024	10/24/2023	INSPTR	SF8537
QUINCY	12/21/2021	10/1/2024	10/19/2023	INSPTR	SF8537
QUINCY	12/21/2021	10/1/2024	10/12/2023	INSPTR	SF8537
QUINCY	12/21/2021	10/1/2024	10/12/2023	INSPTR	SF8537
QUINCY	12/21/2021	10/1/2024	10/18/2023	INSPTR	SF8537
QUINCY	12/21/2021	10/1/2024	10/18/2023	INSPTR	SF8537
QUINCY	12/21/2021	10/1/2024	10/2/2023	INSPTR	SF8537
LOYALTON	12/26/2021	8/7/2024	8/17/2023	INSPTR	SF8537
LOYALTON	12/26/2021	8/7/2024	8/21/2023	INSPTR	SF8537
LOYALTON	12/26/2021	8/7/2024	8/17/2023	INSPTR	SF8537
LOYALTON	12/26/2021	8/13/2024	2/17/2024	INSPTR	CD5628
LOYALTON	12/26/2021	8/13/2024	3/7/2024	INSPTR	JH3145
LOYALTON	12/26/2021	7/29/2024	2/17/2024	INSPTR	CD5628
LOYALTON	12/26/2021	7/29/2024	3/7/2024	INSPTR	JH3145
LOYALTON	12/26/2021	7/29/2024	2/17/2024	INSPTR	CD5628
LOYALTON	12/26/2021	7/29/2024	3/7/2024	INSPTR	JH3145
LOYALTON	12/26/2021	7/30/2024	8/21/2023	INSPTR	SF8537
LOYALTON	12/26/2021	8/4/2024	8/21/2023	INSPTR	SF8537
LOYALTON	12/26/2021	8/4/2022	2/10/2022	INSPTR	SF8537
LOYALTON	12/26/2021	8/4/2022	2/10/2022	INSPTR	SF8537
LOYALTON	12/26/2021	8/4/2022	2/10/2022	INSPTR	SF8537
LOYALTON	12/26/2021	8/4/2022	2/10/2022	INSPTR	SF8537
GRASS VALLEY	1/19/2022	1/22/2022	4/11/2022	OR1393	
GRASS VALLEY	1/19/2022	1/22/2022	4/11/2022	JM1827	

GRASS VALLEY	1/19/2022	1/22/2022	4/11/2022	JM1827	
GRASS VALLEY	1/20/2022	1/23/2022	4/11/2022	JM1827	
GRASS VALLEY	1/20/2022	1/23/2022	4/11/2022	JM1827	
GRASS VALLEY	1/23/2022	1/26/2022	4/11/2022	OR1393	
GRASS VALLEY	1/26/2022	1/29/2022	2/11/2022	OR1393	DL4872
GRASS VALLEY	1/26/2022	1/29/2022	2/11/2022	OR1393	JM1827
GRASS VALLEY	1/26/2022	1/29/2022	4/11/2022	JM1827	
BLAIRSDEN	2/8/2022	2/12/2022	2/9/2022	SF8537	SF8537
BLAIRSDEN	2/8/2022	2/12/2022	2/9/2022	SF8537	SF8537
GRASS VALLEY	2/10/2022	2/13/2022	4/11/2022	RB2427	
GRASS VALLEY	2/11/2022	2/14/2022	2/23/2022	JM1827	JS2145
GRASS VALLEY	2/12/2022	2/15/2022	4/11/2022	OR1393	
QUINCY	2/27/2022	3/2/2022	2/28/2022	SF8537	SF8537
GRASS VALLEY	3/1/2022	3/1/2025	5/27/2024	JM2792	RW5286
QUINCY	3/9/2022	3/12/2022	3/10/2022	SF8537	SF8537
QUINCY	3/15/2022	3/17/2022	3/16/2022	SF8537	SF8537
GRASS VALLEY	3/17/2022	3/19/2022	4/11/2022	JI2512	
ALTA/DUTCH FLATS	3/21/2022	3/24/2022	3/22/2022	SC9431	JS6852
NEVADA CITY	3/23/2022	3/25/2022	3/24/2022	DI1638	QB6851
NEVADA CITY	3/23/2022	3/25/2022	4/26/2022	DI1638	
LOYALTON	4/7/2022	4/10/2022	7/26/2022	SF8537	SF8537
NEVADA CITY	4/15/2022	4/18/2022	5/3/2022	DW2564	
GRASS VALLEY	4/15/2022	4/18/2022	5/3/2022	DW2564	
QUINCY	4/21/2022	4/24/2022	5/27/2022	SF8537	SF8537
TRUCKEE	5/6/2022	5/8/2022	7/6/2022	JQ2645	
QUINCY	5/10/2022	5/12/2022	5/13/2022	SF8537	SF8537
ALTA/DUTCH FLATS	5/22/2022	10/19/2022	7/18/2022	INSPTR	GG8932
ALTA/DUTCH FLATS	5/22/2022	10/18/2022	8/15/2022	INSPTR	JS3172
ALTA/DUTCH FLATS	5/22/2022	10/18/2022	7/18/2022	INSPTR	GG8932
ALTA/DUTCH FLATS	5/22/2022	10/19/2022	7/17/2022	INSPTR	GG8932
ALTA/DUTCH FLATS	5/22/2022	4/22/2025	5/27/2024	INSPTR	SC2675
GRASS VALLEY	5/23/2022	10/12/2022	7/30/2022	INSPTR	VC6131
GRASS VALLEY	5/23/2022	10/12/2022	7/31/2022	INSPTR	PC9347
GRASS VALLEY	5/23/2022	10/12/2022	7/31/2022	INSPTR	PC9347
GRASS VALLEY	5/23/2022	10/14/2022	8/8/2022	INSPTR	PC9347
GRASS VALLEY	5/23/2022	10/12/2022	7/28/2022	INSPTR	VC6131

NEVADA CITY	5/23/2022	10/15/2022	8/3/2022	INSPTR	AG2675
GRASS VALLEY	5/23/2022	10/18/2022	8/1/2022	INSPTR	PC9347
NEVADA CITY	5/23/2022	10/15/2022	8/8/2022	INSPTR	CG4741
GRASS VALLEY	5/23/2022	10/18/2022	8/10/2022	INSPTR	CG4741
NEVADA CITY	5/23/2022	10/15/2022	8/14/2022	INSPTR	GG8932
NEVADA CITY	5/23/2022	10/15/2022	7/17/2022	INSPTR	MO1513
GRASS VALLEY	5/23/2022	10/16/2022	8/3/2022	INSPTR	JM1295
GRASS VALLEY	5/23/2022	10/16/2022	8/3/2022	INSPTR	JM1295
GRASS VALLEY	5/23/2022	10/13/2022	8/8/2022	INSPTR	PC9347
GRASS VALLEY	5/23/2022	10/14/2022	8/10/2022	INSPTR	GG8932
NEVADA CITY	5/23/2022	10/14/2022	8/14/2022	INSPTR	GG8932
NEVADA CITY	5/23/2022	10/25/2022	8/16/2022	INSPTR	JS2145
GRASS VALLEY	5/23/2022	10/15/2022	8/11/2022	INSPTR	MD4156
NEVADA CITY	5/23/2022	10/25/2022	8/16/2022	INSPTR	SB6349
NEVADA CITY	5/23/2022	10/26/2022	8/23/2022	INSPTR	OD4318
NEVADA CITY	5/23/2022	10/13/2022	7/17/2022	INSPTR	CG4741
GRASS VALLEY	5/23/2022	10/14/2022	8/25/2022	INSPTR	QB6851
NEVADA CITY	5/23/2022	10/26/2022	8/30/2022	INSPTR	DM820T
NEVADA CITY	5/23/2022	10/14/2022	8/12/2022	INSPTR	MD4156
GRASS VALLEY	5/23/2022	10/12/2022	7/30/2022	INSPTR	VC6131
GRASS VALLEY	5/23/2022	10/12/2022	7/30/2022	INSPTR	VC6131
NEVADA CITY	5/23/2022	10/14/2022	8/12/2022	INSPTR	MD4156
NEVADA CITY	5/23/2022	10/15/2022	8/26/2022	INSPTR	RW5286
NEVADA CITY	5/23/2022	10/15/2022	7/17/2022	INSPTR	MO1513
NEVADA CITY	5/23/2022	10/15/2022	8/12/2022	INSPTR	LP848K
NEVADA CITY	5/23/2022	10/15/2022	8/27/2022	INSPTR	JM1295
NEVADA CITY	5/23/2022	10/13/2022	7/17/2022	INSPTR	CG4741
GRASS VALLEY	5/23/2022	10/14/2022	8/23/2022	INSPTR	MD4156
GRASS VALLEY	5/23/2022	10/12/2022	8/26/2022	INSPTR	RW5286
GRASS VALLEY	5/23/2022	10/13/2022	8/13/2022	INSPTR	GG8932
GRASS VALLEY	5/23/2022	10/16/2022	8/12/2022	INSPTR	MM3647
GRASS VALLEY	5/23/2022	10/16/2022	7/31/2022	INSPTR	GG8932
GRASS VALLEY	5/23/2022	10/16/2022	7/31/2022	INSPTR	GG8932
GRASS VALLEY	5/23/2022	10/16/2022	8/12/2022	INSPTR	MM3647
GRASS VALLEY	5/23/2022	10/15/2022	8/24/2022	INSPTR	JM2792
NEVADA CITY	5/23/2022	10/25/2022	8/15/2022	INSPTR	MM3647
GRASS VALLEY	5/23/2022	10/15/2022	7/21/2022	INSPTR	GG8932
GRASS VALLEY	5/23/2022	10/15/2022	8/26/2022	INSPTR	JM1295
GRASS VALLEY	5/23/2022	10/15/2022	8/24/2022	INSPTR	JM2792
GRASS VALLEY	5/23/2022	10/13/2022	8/13/2022	INSPTR	GG8932
GRASS VALLEY	5/23/2022	10/15/2022	8/24/2022	INSPTR	JM1295
GRASS VALLEY	5/23/2022	10/18/2022	8/11/2022	INSPTR	MM3647
GRASS VALLEY	5/23/2022	10/12/2022	8/15/2022	INSPTR	MD4156
GRASS VALLEY	5/23/2022	10/18/2022	7/17/2022	INSPTR	VC6131

GRASS VALLEY	5/23/2022	10/18/2022	8/4/2022	INSPTR	PC9347
GRASS VALLEY	5/23/2022	10/19/2022	7/29/2022	INSPTR	AG2675
NEVADA CITY	5/23/2022	10/16/2022	11/3/2022	INSPTR	
GRASS VALLEY	5/23/2022	10/18/2022	8/15/2022	INSPTR	
GRASS VALLEY	5/23/2022	4/13/2027	5/6/2024	INSPTR	
GRASS VALLEY	5/23/2022	4/19/2025	6/12/2024	INSPTR	RW5286
CAMPTONVILLE	5/27/2022	11/4/2022	9/1/2022	INSPTR	PC9347
CAMPTONVILLE	5/27/2022	11/3/2022	9/1/2022	INSPTR	PC9347
CAMPTONVILLE	5/27/2022	11/3/2022	7/21/2022	INSPTR	GG8932
NORTH SAN JUAN	6/3/2022	10/15/2022	12/8/2023	INSPTR	
TRUCKEE	6/21/2022	4/14/2025	5/16/2024	INSPTR	PG6512
TRUCKEE	6/21/2022	5/18/2025	6/13/2024	INSPTR	JH3145
TRUCKEE	6/21/2022	4/14/2025	4/26/2024	INSPTR	DD6738
TRUCKEE	6/21/2022	4/13/2025	7/25/2024	INSPTR	DD6738
TRUCKEE	6/21/2022	4/14/2025	4/26/2024	INSPTR	DD6738
TRUCKEE	6/21/2022	4/14/2025	5/16/2024	INSPTR	PG6512
TRUCKEE	6/21/2022	4/15/2025	4/26/2024	INSPTR	PG6512
TRUCKEE	6/21/2022	4/15/2025	4/26/2024	INSPTR	PG6512
TRUCKEE	6/21/2022	4/15/2025	5/16/2024	INSPTR	PG6512
TRUCKEE	6/21/2022	5/18/2025	6/13/2024	INSPTR	JH3145
TRUCKEE	6/21/2022	4/15/2025	5/16/2024	INSPTR	PG6512
TRUCKEE	6/21/2022	4/13/2025	7/25/2024	INSPTR	DD6738
TRUCKEE	6/21/2022	4/13/2025	5/23/2024	INSPTR	DD6738
TRUCKEE	6/21/2022	4/13/2025	5/23/2024	INSPTR	DD6738
TRUCKEE	6/21/2022	4/13/2025	7/25/2024	INSPTR	DD6738
TRUCKEE	6/21/2022	4/15/2025	4/26/2024	INSPTR	DD6738
TRUCKEE	6/21/2022	4/15/2025	4/26/2024	INSPTR	DD6738
TRUCKEE	6/21/2022	4/15/2025	4/24/2024	INSPTR	JH3145
TRUCKEE	6/21/2022	4/15/2025	4/24/2024	INSPTR	JH3145
TRUCKEE	6/21/2022	10/15/2022	7/22/2022	INSPTR	DD6738
TRUCKEE	6/21/2022	4/15/2025	4/24/2024	INSPTR	JH3145
QUINCY	6/21/2022	5/19/2025	5/31/2024	INSPTR	SF8537
QUINCY	6/21/2022	5/18/2025	6/3/2024	INSPTR	TM3217
QUINCY	6/21/2022	5/19/2025	7/12/2024	INSPTR	SF8537
QUINCY	6/21/2022	5/19/2025	6/4/2024	INSPTR	SF8537
QUINCY	6/21/2022	5/19/2025	6/7/2024	INSPTR	DD043U
QUINCY	6/21/2022	5/19/2025	5/31/2024	INSPTR	SF8537
QUINCY	6/21/2022	5/19/2025	6/4/2024	INSPTR	SF8537
QUINCY	6/21/2022	5/19/2025	6/28/2024	INSPTR	SF8537
QUINCY	6/21/2022	5/18/2025	5/30/2024	INSPTR	SF8537
QUINCY	6/21/2022	5/19/2025	5/31/2024	INSPTR	SF8537
CHALLENGE	7/5/2022	5/5/2025	5/24/2024	INSPTR	DB8381
CHALLENGE	7/5/2022	5/4/2025	5/24/2024	INSPTR	DB8381
QUINCY	7/25/2022	7/28/2022	7/29/2022	SF8537	SF8537

DOWNEYVILLE	10/8/2022	10/11/2022	10/25/2022	GG8932	
BLAIRSDEN	10/12/2022	10/15/2022	10/17/2022	SF8537	SF8537
PORTOLA	11/2/2022	11/5/2022	2/7/2023	SF8537	SF8537
LOYALTON	11/7/2022	11/10/2022	11/28/2022	SF8537	SF8537
QUINCY	11/30/2022	12/3/2022	2/8/2023	SF8537	SF8537
ALTA/DUTCH FLATS	12/5/2022	10/18/2022	2/14/2023	INSPTR	SC2675
ALTA/DUTCH FLATS	12/5/2022	10/19/2022	2/14/2023	INSPTR	SC2675
ALTA/DUTCH FLATS	12/5/2022	10/19/2022	2/14/2023	INSPTR	SC2675
ALTA/DUTCH FLATS	12/5/2022	10/18/2022	2/14/2023	INSPTR	SC2675
LAKE WILDWOOD	12/27/2022	12/30/2022	1/3/2023	MM3647	
GRASS VALLEY	2/15/2023	2/18/2023	3/20/2023	ST4537	
ALTA/DUTCH FLATS	2/23/2023	2/26/2023	4/14/2023	SC2675	CN2921
ALTA/DUTCH FLATS	2/23/2023	2/26/2023	4/9/2023	SC2675	CN2921
ALTA/DUTCH FLATS	2/23/2023	2/26/2023	4/9/2023	SC2675	CN2921
LAKE WILDWOOD	7/10/2023	7/13/2023	7/21/2023	JG2182	DM820T
ALTA/DUTCH FLATS	8/16/2023	2/16/2024	8/17/2023	SC2675	SC2675
ALTA/DUTCH FLATS	8/19/2023	8/22/2023	8/21/2023	SC2675	JS3172
ALTA/DUTCH FLATS	8/19/2023	8/22/2023	8/21/2023	SC2675	SC2675
ALTA/DUTCH FLATS	8/22/2023	8/25/2023	8/23/2023	SC2675	SC2675
ALTA/DUTCH FLATS	8/22/2023	8/25/2023	8/23/2023	SC2675	SC2675
ALTA/DUTCH FLATS	8/23/2023	8/26/2023	8/25/2023	SC2675	SC2675
ALTA/DUTCH FLATS	8/23/2023	8/27/2023	8/25/2023	SC2675	SC2675
ALTA/DUTCH FLATS	8/24/2023	2/24/2024	2/14/2024	SC2675	SC2675
BLAIRSDEN	9/7/2023	9/10/2023	9/14/2023	SF8537	SF8537
CHALLENGE	9/13/2023	9/13/2024	12/11/2023	DW2564	DB8381
ALTA/DUTCH FLATS	9/14/2023	9/17/2023	11/10/2023	DW2564	
ALTA/DUTCH FLATS	9/14/2023	9/17/2023	11/10/2023	DW2564	
ALTA/DUTCH FLATS	9/18/2023	9/21/2023	11/10/2023	DW2564	
GRASS VALLEY	9/18/2023	9/21/2023	9/21/2023	DW2564	VC6131
GRASS VALLEY	9/18/2023	9/21/2023	11/10/2023	DW2564	
GRASS VALLEY	9/18/2023	9/21/2023	11/10/2023	DW2564	
ALTA/DUTCH FLATS	9/18/2023	9/21/2023	11/10/2023	DW2564	
NEVADA CITY	9/20/2023	9/23/2023	11/10/2023	MR2414	
GRASS VALLEY	9/20/2023	9/23/2023	9/21/2023	MR2414	VC6131
CAMPTONVILLE	9/22/2023	9/25/2023	11/10/2023	DW2564	
GRASS VALLEY	9/22/2023	9/25/2023	9/26/2023	DW2564	MM3647
CHALLENGE	9/25/2023	3/7/2024	2/29/2024	INSPTR	
GRASS VALLEY	9/26/2023	9/29/2023	11/10/2023	MR2414	
GRASS VALLEY	9/26/2023	9/29/2023	11/10/2023	DW2564	
GRASS VALLEY	9/26/2023	9/26/2024	9/27/2023	DW2564	MM3647
CAMPTONVILLE	10/4/2023	3/14/2024	3/22/2024	INSPTR	QB6851
LAKE WILDWOOD	10/4/2023	9/29/2023	4/26/2024	INSPTR	DM820T
GRASS VALLEY	11/4/2023	9/13/2024	12/13/2023	INSPTR	RW5286
GRASS VALLEY	11/4/2023	9/15/2024	11/17/2023	INSPTR	QB6851

ALTA/DUTCH FLATS	11/4/2023	3/12/2024	5/2/2024	INSPTR	SC2675
ALTA/DUTCH FLATS	11/4/2023	3/13/2024	5/2/2024	INSPTR	SC2675
GRASS VALLEY	11/4/2023	3/14/2024	11/17/2023	INSPTR	QB6851
GRASS VALLEY	11/4/2023	9/15/2024	11/15/2023	INSPTR	RW5286
GRASS VALLEY	11/4/2023	9/22/2024	11/15/2023	INSPTR	RW5286
GRASS VALLEY	11/4/2023	3/21/2024	11/14/2023	INSPTR	LP848K
GRASS VALLEY	11/4/2023	9/22/2024	11/15/2023	INSPTR	MM3647
NEVADA CITY	11/8/2023	3/14/2024	11/15/2023	INSPTR	MM3647
TRUCKEE	11/8/2023	3/29/2024	11/16/2023	INSPTR	WC8687
ALTA/DUTCH FLATS	3/7/2024	3/10/2024	4/2/2024	KM1231	
GRASS VALLEY	3/7/2024	3/10/2024	4/2/2024	KM1231	
GRASS VALLEY	3/7/2024	3/10/2024	4/2/2024	KM1231	
GRASS VALLEY	3/7/2024	3/10/2024	4/2/2024	KM1231	
NORTH SAN JUAN	3/8/2024	3/11/2024	4/10/2024	KM1231	
GRASS VALLEY	4/5/2024	4/8/2024	6/3/2024	KM1231	
GRASS VALLEY	4/11/2024	4/14/2024	4/29/2024	KM1231	
GRASS VALLEY	4/11/2024	4/14/2024	4/29/2024	KM1231	
ALTA/DUTCH FLATS	4/11/2024	4/14/2024	5/2/2024	KM1231	SC2675
GRASS VALLEY	5/6/2024	5/9/2024	6/3/2024	KM1231	
NEVADA CITY	5/15/2024	5/18/2024	6/11/2024	KM1231	
GRASS VALLEY	5/15/2024	5/18/2024	6/20/2024	KM1231	
GRASS VALLEY	5/15/2024	5/18/2024	6/11/2024	KM1231	
GRASS VALLEY	5/15/2024	5/18/2024	6/11/2024	KM1231	
GRASS VALLEY	5/15/2024	5/18/2024	6/11/2024	KM1231	
TRUCKEE	5/22/2024	3/13/2027	6/26/2024	INSPTR	

PACKAGE_STATUS	BPC_TYPE	BPC_OWNER	TOWN
Complete	GO95_TFS	TFS	GRASS VALLEY
Complete	GO95_TFS	TFS	PENN VALLEY
Complete	GO95_CE	CON	GRASS VALLEY
Complete	GO95_TFS	TFS	GRASS VALLEY
Complete	GO95_CE	ENG	Grass Valley
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Echo Ridge Estates
Complete	GO95_CE	CON	Blairsden-Graeagle
Complete	GO95_CE	CON	Blairsden-Graeagle
Complete	GO95_CE	CON	Blairsden-Graeagle
Complete	GO95_CE	CON	Blairsden-Graeagle
Complete	GO95_CE	CON	Clio
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Blairsden-Graeagle
Complete	GO95_CE	CON	Blairsden-Graeagle
Complete	GO95_CE	CON	Blairsden-Graeagle
Complete	GO95_CE	CON	Quincy
Complete	GO95_CE	CON	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_CE	CON	Blairsden-Graeagle
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Blairsden-Graeagle
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Blairsden-Graeagle
Complete	GO95_CE	CON	Clio
Complete	GO95_CE	ENG	Nevada City
Complete	GO95_CE	ENG	Nevada City
Complete	GO95_CE	ENG	Grass Valley
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Blairsden-Graeagle
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee

Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Tahoe City
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Donner Lake
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_CE	CON	Donner Lake
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee

Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Tahoe City
Complete	GO95_CE	CON	Sierraville
Complete	GO95_CE	CON	Sierraville
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Donner Lake
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Donner Lake
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Donner Lake
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Donner Lake
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_CE	CON	Truckee

Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Donner Lake
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Donner Lake
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Tahoe City
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Donner Lake
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Donner Lake
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Tahoe City
Complete	GO95_TFS	TFS	Truckee

Complete	GO95_TFS	TFS	Donner Lake
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON

Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Donner Lake
Complete	GO95_TFS	TFS	Donner Lake
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Donner Lake
Complete	GO95_TFS	TFS	Donner Lake
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Donner Lake
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Donner Lake
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Donner Lake
Complete	GO95_TFS	TFS	Donner Lake
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Donner Lake
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee

Complete	GO95_TFS	TFS	Donner Lake
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Donner Lake
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Donner Lake
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Donner Lake
Complete	GO95_CE	CON	Donner Lake
Complete	GO95_TFS	TFS	Donner Lake
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_CE	CON	Quincy
Complete	GO95_TFS	TFS	
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Quincy
Complete	GO95_CE	CON	Greenhorn
Complete	GO95_CE	CON	Greenhorn
Complete	GO95_CE	CON	Soda Springs
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_CE	CON	Quincy
Complete	GO95_TFS	TFS	Greenhorn
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_CE	CON	Quincy
Complete	GO95_CE	CON	Quincy
Complete	GO95_CE	CON	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Canyondam
Complete	GO95_TFS	TFS	Quincy

Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Canyondam
Complete	GO95_TFS	TFS	Canyondam
Complete	GO95_CE	ENG	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Twain
Complete	GO95_TFS	TFS	Twain
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_CE	CON	
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_CE	CON	Grass Valley

Complete	GO95_CE	CON	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_CE	CON	Alta Sierra
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Alta Sierra
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Alta Sierra
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_CE	ENG	Grass Valley
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_CE	CON	Brownsville
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_CE	CON	Downieville
Complete	GO95_TFS	TFS	Strawberry Valley
Complete	GO95_TFS	TFS	Strawberry Valley
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_CE	CON	Alleghany
Complete	GO95_TFS	TFS	Clipper Mills
Complete	GO95_CE	CON	Downieville
Complete	GO95_TFS	TFS	Brownsville
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_TFS	TFS	Brownsville
Complete	GO95_CE	CON	Downieville
Complete	GO95_TFS	TFS	Brownsville
Complete	GO95_TFS	TFS	Clipper Mills
Complete	GO95_TFS	TFS	Brownsville
Complete	GO95_TFS	TFS	Brownsville
Complete	GO95_TFS	TFS	Strawberry Valley
Complete	GO95_TFS	TFS	Brownsville
Complete	GO95_TFS	TFS	Oroville
Complete	GO95_TFS	TFS	Strawberry Valley
Complete	GO95_TFS	TFS	Brownsville
Complete	GO95_TFS	TFS	Challenge
Complete	GO95_TFS	TFS	Brownsville

Complete	GO95_CE	CON	Grass Valley
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_TFS	TFS	Brownsville
Complete	GO95_CE	CON	Camptonville
Complete	GO95_TFS	TFS	Challenge
Complete	GO95_TFS	TFS	Oroville
Complete	GO95_TFS	TFS	Clipper Mills
Complete	GO95_TFS	TFS	Brownsville
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_TFS	TFS	Brownsville
Complete	GO95_TFS	TFS	Brownsville
Complete	GO95_CE	CON	Alleghany
Complete	GO95_CE	CON	Downieville
Complete	GO95_CE	CON	Alleghany
Complete	GO95_CE	CON	Alleghany
Complete	GO95_CE	CON	Alleghany
Complete	GO95_TFS	TFS	Alleghany
Complete	GO95_TFS	TFS	Brownsville
Complete	GO95_TFS	TFS	Brownsville
Complete	GO95_TFS	TFS	Brownsville
Complete	GO95_CE	CON	Brownsville
Complete	GO95_TFS	TFS	Alleghany
Complete	GO95_TFS	TFS	Brownsville
Complete	GO95_TFS	TFS	Downieville
Complete	GO95_TFS	TFS	Alleghany
Complete	GO95_TFS	TFS	Brownsville
Complete	GO95_TFS	TFS	Alleghany
Complete	GO95_TFS	TFS	Alleghany
Complete	GO95_TFS	TFS	Alleghany
Complete	GO95_TFS	TFS	Alleghany
Complete	GO95_TFS	TFS	Alleghany
Complete	GO95_TFS	TFS	Challenge
Complete	GO95_TFS	TFS	Alleghany
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_CE	CON	Alleghany
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Brownsville
Complete	GO95_TFS	TFS	Alleghany
Complete	GO95_TFS	TFS	Forbestown
Complete	GO95_TFS	TFS	Forbestown
Complete	GO95_TFS	TFS	Clipper Mills
Complete	GO95_TFS	TFS	Forbestown
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Strawberry Valley

Complete	GO95_TFS	TFS	Forbestown
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Alleghany
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Alleghany
Complete	GO95_TFS	TFS	Downieville
Complete	GO95_TFS	TFS	Brownsville
Complete	GO95_TFS	TFS	Alleghany
Complete	GO95_TFS	TFS	Alleghany
Complete	GO95_TFS	TFS	Brownsville
Complete	GO95_TFS	TFS	Alleghany
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_TFS	TFS	North San Juan
Complete	GO95_CE	CON	North San Juan
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_TFS	TFS	North San Juan
Complete	GO95_TFS	TFS	North San Juan
Complete	GO95_TFS	TFS	Portola
Complete	GO95_CE	CON	Cascade Shores
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Grass Valley

Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	ENG	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Washington
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_CE	ENG	Prosser Lakeview Estates

Complete	GO95_TFS	TFS	Prosser Lakeview Estates
Complete	GO95_CE	ENG	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Prosser Lakeview Estates
Complete	GO95_TFS	TFS	Prosser Lakeview Estates
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Prosser Lakeview Estates
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Soda Springs
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Emigrant Gap
Complete	GO95_TFS	TFS	Alta
Complete	GO95_CE	CON	Alta
Complete	GO95_CE	CON	Alta
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Alta
Complete	GO95_CE	ENG	Alta
Complete	GO95_TFS	TFS	Alta

Complete	GO95_CE	ENG	Alta
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Soda Springs
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Gold Run
Complete	GO95_TFS	TFS	Meadow Valley
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Portola
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Floriston
Complete	GO95_TFS	TFS	Floriston
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Beckwourth
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_CE	CON	
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Sierra City
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Vinton
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Calpine
Complete	GO95_TFS	TFS	Beckwourth
Complete	GO95_TFS	TFS	Beckwourth
Complete	GO95_TFS	TFS	Vinton
Complete	GO95_TFS	TFS	Loyalton
Complete	GO95_TFS	TFS	Blairsden Graeagle
Complete	GO95_TFS	TFS	Beckwourth
Complete	GO95_TFS	TFS	Loyalton
Complete	GO95_TFS	TFS	Doyle
Complete	GO95_TFS	TFS	Quincy

Complete	GO95_TFS	TFS	Cromberg
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Doyle
Complete	GO95_TFS	TFS	Beckwourth
Complete	GO95_TFS	TFS	Beckwourth
Complete	GO95_TFS	TFS	Doyle
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Colfax
Complete	GO95_CE	CON	Alta
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Colfax
Complete	GO95_TFS	TFS	Colfax
Complete	GO95_TFS	TFS	Camptonville
Complete	GO95_TFS	TFS	Camptonville
Complete	GO95_TFS	TFS	Sweetland
Complete	GO95_TFS	TFS	North San Juan
Complete	GO95_TFS	TFS	Camptonville
Complete	GO95_TFS	TFS	Camptonville
Complete	GO95_TFS	TFS	Camptonville
Complete	GO95_TFS	TFS	Camptonville
Complete	GO95_TFS	TFS	Camptonville
Complete	GO95_TFS	TFS	Camptonville
Complete	GO95_TFS	TFS	Forbestown
Complete	GO95_TFS	TFS	Forbestown
Complete	GO95_TFS	TFS	Forbestown
Complete	GO95_CE	CON	Camptonville
Complete	GO95_CE	CON	Dutch Flat
Complete	GO95_CE	CON	Dutch Flat
Complete	GO95_CE	CON	Alta

Complete	GO95_CE	CON	Nevada City
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	North San Juan

Complete	GO95_CE	CON	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Camptonville
Complete	GO95_TFS	TFS	Camptonville
Complete	GO95_TFS	TFS	North San Juan
Complete	GO95_TFS	TFS	Camptonville
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Alleghany
Complete	GO95_TFS	TFS	Alleghany
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Gold Run
Complete	GO95_TFS	TFS	Colfax
Complete	GO95_TFS	TFS	Camptonville
Complete	GO95_TFS	TFS	Dutch Flat
Complete	GO95_TFS	TFS	Dutch Flat
Complete	GO95_TFS	TFS	Dutch Flat
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Dutch Flat
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Clipper Mills
Complete	GO95_TFS	TFS	Dutch Flat
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Challenge
Complete	GO95_TFS	TFS	Yuba Foothills
Complete	GO95_TFS	TFS	Yuba Foothills
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Grass Valley

Complete	GO95_TFS	TFS	Dutch Flat
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Alleghany
Complete	GO95_TFS	TFS	Alleghany
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley

Complete	GO95_CE	CON	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Sierra City
Complete	GO95_TFS	TFS	Sierra City
Complete	GO95_TFS	TFS	Sierra City
Complete	GO95_TFS	TFS	Sierra City
Complete	GO95_TFS	TFS	Sierra City
Complete	GO95_TFS	TFS	Sierra City

Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Sierra City
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee

Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee

Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Penn Valley
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Rough and Ready
Complete	GO95_TFS	TFS	Penn Valley
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Penn Valley
Complete	GO95_CE	CON	Nevada City

Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_CE	CON	Penn Valley
Complete	GO95_TFS	TFS	Penn Valley
Complete	GO95_TFS	TFS	Penn Valley
Complete	GO95_CE	CON	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Penn Valley
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Penn Valley
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Rough and Ready
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Penn Valley
Complete	GO95_TFS	TFS	Penn Valley
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Rough and Ready
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Penn Valley
Complete	GO95_CE	CON	North San Juan
Complete	GO95_CE	CON	Nevada City
Complete	GO95_TFS	TFS	North San Juan
Complete	GO95_TFS	TFS	North San Juan
Complete	GO95_TFS	TFS	North San Juan
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	North San Juan
Complete	GO95_TFS	TFS	North San Juan
Complete	GO95_TFS	TFS	Nevada City

Complete	GO95_CE	CON	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Delleker
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	North San Juan
Complete	GO95_TFS	TFS	North San Juan
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City

Complete	GO95_CE	CON	Nevada City

Complete	GO95_CE	CON	North San Juan

Complete	GO95_CE	ENG	Nevada City
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	East Quincy

Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Loyalton
Complete	GO95_CE	CON	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Loyalton
Complete	GO95_TFS	TFS	Brownsville
Complete	GO95_CE	ENG	Truckee
Complete	GO95_TFS	TFS	Blairsden Graeagle
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_CE	CON	
Complete	GO95_CE	CON	
Complete	GO95_CE	CON	
Complete	GO95_CE	CON	NEVADA CITY
Complete	GO95_CE	CON	
Complete	GO95_CE	CON	
Complete	GO95_CE	CON	
Complete	GO95_TFS	TFS	Beckwourth
Complete	GO95_TFS	TFS	Beckwourth
Complete	GO95_CE	CON	DUTCH FLAT
Complete	GO95_TFS	TFS	
Complete	GO95_TFS	TFS	
Complete	GO95_TFS	TFS	
Complete	GO95_TFS	TFS	
Complete	GO95_TFS	TFS	
Complete	GO95_TFS	TFS	Graeagle
Complete	GO95_TFS	TFS	Clio
Complete	GO95_TFS	TFS	Clio
Complete	GO95_TFS	TFS	Graeagle

Complete	GO95_TFS	TFS	Graeagle
Complete	GO95_TFS	TFS	Graeagle
Complete	GO95_TFS	TFS	Graeagle
Complete	GO95_TFS	TFS	Graeagle
Complete	GO95_TFS	TFS	Graeagle
Complete	GO95_TFS	TFS	Graeagle
Complete	GO95_TFS	TFS	Graeagle
Complete	GO95_TFS	TFS	Graeagle
Complete	GO95_TFS	TFS	Graeagle
Complete	GO95_TFS	TFS	Graeagle
Complete	GO95_TFS	TFS	Cromberg
Complete	GO95_TFS	TFS	Cromberg
Complete	GO95_TFS	TFS	Graeagle
Complete	GO95_TFS	TFS	Blairsden
Complete	GO95_TFS	TFS	Graeagle
Complete	GO95_TFS	TFS	Blairsden
Complete	GO95_TFS	TFS	Graeagle
Complete	GO95_TFS	TFS	Graeagle
Complete	GO95_TFS	TFS	Cromberg
Complete	GO95_TFS	TFS	
Complete	GO95_TFS	TFS	
Complete	GO95_TFS	TFS	
Complete	GO95_TFS	TFS	North San Juan
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	North San Juan
Complete	GO95_TFS	TFS	North San Juan
Complete	GO95_TFS	TFS	North San Juan
Complete	GO95_TFS	TFS	North San Juan
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	North San Juan
Complete	GO95_TFS	TFS	North San Juan
Complete	GO95_TFS	TFS	North San Juan
Complete	GO95_TFS	TFS	North San Juan
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City

Complete	GO95_TFS	TFS	North San Juan
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_CE	ENG	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Blairsden Graeagle
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_CE	ENG	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_CE	ENG	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City

Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_CE	ENG	Nevada City
Complete	GO95_CE	ENG	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_CE	ENG	Nevada City
Complete	GO95_CE	ENG	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_CE	ENG	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Blairsden Graeagle
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Penn Valley
Complete	GO95_TFS	TFS	Penn Valley
Complete	GO95_TFS	TFS	Penn Valley
Complete	GO95_TFS	TFS	Penn Valley
Complete	GO95_TFS	TFS	Penn Valley
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Penn Valley
Complete	GO95_TFS	TFS	Penn Valley

Complete	GO95_TFS	TFS	Penn Valley
Complete	GO95_TFS	TFS	Penn Valley
Complete	GO95_TFS	TFS	Penn Valley
Complete	GO95_TFS	TFS	Penn Valley
Complete	GO95_TFS	TFS	Penn Valley
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee

Complete	GO95_TFS	TFS	Donner
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Sierraville
Complete	GO95_TFS	TFS	Sierraville
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee

Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee

Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee

Complete	GO95_TFS	TFS	Prosser
Complete	GO95_TFS	TFS	Prosser
Complete	GO95_TFS	TFS	Prosser
Complete	GO95_TFS	TFS	Prosser
Complete	GO95_TFS	TFS	Prosser
Complete	GO95_TFS	TFS	Prosser
Complete	GO95_TFS	TFS	Prosser
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Prosser
Complete	GO95_TFS	TFS	Downtown Truckee
Complete	GO95_CE	CON	Prosser
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Floriston
Complete	GO95_TFS	TFS	Prosser
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Prosser
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_CE	CON	Prosser
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee

Complete	GO95_TFS	TFS	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Prosser
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Prosser
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Prosser
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Prosser
Complete	GO95_TFS	TFS	Prosser
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee

Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Floriston
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Prosser
Complete	GO95_TFS	TFS	Prosser
Complete	GO95_TFS	TFS	Prosser
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Tahoe City
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Prosser
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Truckee

Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS

Complete	GO95_TFS	TFS	Downieville
Complete	GO95_TFS	TFS	Downieville
Complete	GO95_TFS	TFS	Downieville
Complete	GO95_TFS	TFS	Downieville
Complete	GO95_TFS	TFS	Downieville
Complete	GO95_TFS	TFS	Downieville
Complete	GO95_TFS	TFS	Goodyears Bar
Complete	GO95_TFS	TFS	Downieville
Complete	GO95_TFS	TFS	Downieville
Complete	GO95_TFS	TFS	Goodyears Bar
Complete	GO95_TFS	TFS	Goodyears Bar
Complete	GO95_TFS	TFS	Goodyears Bar
Complete	GO95_TFS	TFS	Goodyears Bar
Complete	GO95_TFS	TFS	Goodyears Bar
Complete	GO95_TFS	TFS	Goodyears Bar
Complete	GO95_TFS	TFS	Sierra City
Complete	GO95_TFS	TFS	Sierra City
Complete	GO95_TFS	TFS	Sierraville
Complete	GO95_TFS	TFS	Sierraville
Complete	GO95_TFS	TFS	Sierraville
Complete	GO95_TFS	TFS	Sierra City
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Dutch Flat
Complete	GO95_TFS	TFS	Dutch Flat
Complete	GO95_TFS	TFS	Dutch Flat
Complete	GO95_CE	ENG	Dutch Flat
Complete	GO95_TFS	TFS	Colfax
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Dutch Flat
Complete	GO95_TFS	TFS	Colfax
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Colfax
Complete	GO95_TFS	TFS	Emigrant Gap
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Nevada City

Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Dutch Flat
Complete	GO95_TFS	TFS	Emigrant Gap
Complete	GO95_TFS	TFS	Dutch Flat
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Colfax
Complete	GO95_TFS	TFS	Colfax
Complete	GO95_TFS	TFS	Colfax
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Dutch Flat
Complete	GO95_TFS	TFS	Dutch Flat
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Gold Run
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Soda Springs
Complete	GO95_TFS	TFS	Kingvale
Complete	GO95_TFS	TFS	Soda Springs
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Alta

Complete	GO95_TFS	TFS	Dutch Flat
Complete	GO95_TFS	TFS	Dutch Flat
Complete	GO95_TFS	TFS	Emigrant Gap
Complete	GO95_CE	ENG	Yuba Foothills
Complete	GO95_CE	ENG	Yuba Foothills
Complete	GO95_TFS	TFS	Yuba Foothills
Complete	GO95_CE	ENG	Yuba Foothills
Complete	GO95_TFS	TFS	Clipper Mills
Complete	GO95_TFS	TFS	Clipper Mills
Complete	GO95_TFS	TFS	Clipper Mills
Complete	GO95_TFS	TFS	Clipper Mills
Complete	GO95_TFS	TFS	Forbestown
Complete	GO95_TFS	TFS	Forbestown
Complete	GO95_TFS	TFS	Forbestown
Complete	GO95_CE	ENG	Yuba Foothills
Complete	GO95_TFS	TFS	Forbestown
Complete	GO95_CE	ENG	Yuba Foothills
Complete	GO95_TFS	TFS	Forbestown
Complete	GO95_TFS	TFS	Yuba Foothills
Complete	GO95_TFS	TFS	Forbestown
Complete	GO95_TFS	TFS	Challenge
Complete	GO95_TFS	TFS	Oroville
Complete	GO95_TFS	TFS	Challenge
Complete	GO95_TFS	TFS	Forbestown
Complete	GO95_TFS	TFS	Yuba Foothills
Complete	GO95_TFS	TFS	Yuba Foothills
Complete	GO95_TFS	TFS	Clipper Mills
Complete	GO95_TFS	TFS	Forbestown
Complete	GO95_TFS	TFS	Forbestown
Complete	GO95_TFS	TFS	Forbestown
Complete	GO95_TFS	TFS	Clipper Mills
Complete	GO95_TFS	TFS	Forbestown
Complete	GO95_TFS	TFS	Yuba Foothills
Complete	GO95_TFS	TFS	Oroville
Complete	GO95_TFS	TFS	Yuba Foothills
Complete	GO95_TFS	TFS	Yuba Foothills
Complete	GO95_TFS	TFS	Yuba Foothills
Complete	GO95_TFS	TFS	Forbestown
Complete	GO95_CE	ENG	Yuba Foothills
Complete	GO95_TFS	TFS	Forbestown
Complete	GO95_CE	ENG	Yuba Foothills
Complete	GO95_TFS	TFS	Yuba Foothills
Complete	GO95_TFS	TFS	Yuba Foothills
Complete	GO95_TFS	TFS	Strawberry Valley

Complete	GO95_TFS	TFS	Yuba Foothills
Complete	GO95_TFS	TFS	Yuba Foothills
Complete	GO95_TFS	TFS	Yuba Foothills
Complete	GO95_TFS	TFS	Yuba Foothills
Complete	GO95_TFS	TFS	Clipper Mills
Complete	GO95_TFS	TFS	Yuba Foothills
Complete	GO95_TFS	TFS	Yuba Foothills
Complete	GO95_TFS	TFS	Challenge
Complete	GO95_TFS	TFS	Challenge
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Penn Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass

Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley

Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley

Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Spring Hill
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley

Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley

Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Rough and Ready
Complete	GO95_TFS	TFS	Rough and Ready
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley

Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Rough and Ready
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Rough and Ready
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley

Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Penn Valley
Complete	GO95_TFS	TFS	Penn Valley
Complete	GO95_TFS	TFS	Penn Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Lake Wildwood
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Penn Valley

Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Rough and Ready
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Rough and Ready
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley

Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Rough and Ready
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Rough and Ready
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Alta Sierra
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley

Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Rough and Ready
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Rough and Ready
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola

Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Delleker
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola

Complete	GO95_TFS	TFS	Delleker
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Meadow Valley
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Delleker
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Spring Garden
Complete	GO95_TFS	TFS	Quincy

Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Loyalton
Complete	GO95_TFS	TFS	Sierraville
Complete	GO95_TFS	TFS	Loyalton
Complete	GO95_TFS	TFS	Doyle
Complete	GO95_TFS	TFS	Doyle
Complete	GO95_TFS	TFS	Doyle
Complete	GO95_TFS	TFS	Doyle
Complete	GO95_TFS	TFS	Doyle
Complete	GO95_TFS	TFS	Doyle
Complete	GO95_TFS	TFS	Sierraville
Complete	GO95_TFS	TFS	Loyalton
Complete	GO95_TFS	TFS	Loyalton
Complete	GO95_TFS	TFS	Loyalton
Complete	GO95_TFS	TFS	Loyalton
Complete	GO95_TFS	TFS	Sierraville
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_CE	CON	Grass Valley

Complete	GO95_CE	CON	Grass Valley
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_TFS	TFS	Cromberg
Complete	GO95_TFS	TFS	Cromberg
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Meadow Valley
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_TFS	TFS	Colfax
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_CE	CON	Nevada City
Complete	GO95_TFS	TFS	Loyalton
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_TFS	TFS	Blairsden Graeagle
Complete	GO95_CE	CON	Truckee
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Dutch Flat
Complete	GO95_TFS	TFS	Colfax
Complete	GO95_TFS	TFS	Colfax
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley

Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	North Bloomfield
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Nevada City

Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_CE	ENG	Nevada City
Complete	GO95_CE	ENG	Nevada City
Complete	GO95_CE	ENG	Grass Valley
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Camptonville
Complete	GO95_TFS	TFS	Camptonville
Complete	GO95_TFS	TFS	Camptonville
Complete	GO95_CE	ENG	Nevada City
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Prosser
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Meadow Valley
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Quincy
Complete	GO95_TFS	TFS	Yuba Foothills
Complete	GO95_TFS	TFS	Yuba Foothills
Complete	GO95_TFS	TFS	Quincy

Complete	GO95_CE	CON	Camptonville
Complete	GO95_TFS	TFS	Cromberg
Complete	GO95_TFS	TFS	Portola
Complete	GO95_TFS	TFS	Loyalton
Complete	GO95_TFS	TFS	Meadow Valley
Complete	GO95_TFS	TFS	Colfax
Complete	GO95_TFS	TFS	Dutch Flat
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Colfax
Complete	GO95_CE	ENG	Penn Valley
Complete	GO95_CE	ENG	Penn Valley
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Colfax
Complete	GO95_TFS	TFS	Penn Valley
Complete	GO95_TFS	TFS	Emigrant Gap
Complete	GO95_TFS	TFS	Emigrant Gap
Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Colfax
Complete	GO95_TFS	TFS	Colfax
Complete	GO95_TFS	TFS	Dutch Flat
Complete	GO95_TFS	TFS	Dutch Flat
Complete	GO95_TFS	TFS	Emigrant Gap
Complete	GO95_TFS	TFS	Sierra City
Complete	GO95_TFS	TFS	Challenge
Complete	GO95_CE	CON	EMIGRANT
Complete	GO95_CE	CON	
Complete	GO95_CE	CON	EMIGRANT GAP
Complete	GO95_TFS	TFS	GRASS VALLEY
Complete	GO95_CE	CON	ALTA SIERRA
Complete	GO95_CE	CON	ALTA SIERRA
Complete	GO95_CE	CON	Graniteville
Complete	GO95_CE	CON	
Complete	GO95_TFS	TFS	
Complete	GO95_CE	CON	camptonville
Complete	GO95_TFS	TFS	
Complete	GO95_CE	ENG	Clipper Mills
Complete	GO95_CE	CON	
Complete	GO95_CE	CON	GRASS VALLEY
Complete	GO95_TFS	TFS	GRASS VALLEY
Complete	GO95_TFS	TFS	Camptonville
Complete	GO95_TFS	TFS	Penn Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley

Complete	GO95_TFS	TFS	Alta
Complete	GO95_TFS	TFS	Gold Run
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Grass Valley
Complete	GO95_TFS	TFS	Nevada City
Complete	GO95_TFS	TFS	Truckee
Complete	GO95_CE	CON	Dutch Flat
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_TFS	TFS	Colfax
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_CE	CON	Nevada City
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_CE	CON	Grass Valley
Complete	GO95_CE	CON	Truckee

ADDRESS	TROUBLE_LOCATION	SERVICE_PRIORITY
12124 PINE CONE CIR		GO95
SPO 1NWO 10288 CHANCE RD	Street Address	GO95
12759 SQUIRREL CREEK RD	Street Address	GO95
14781 BENTON PL	Street Address	GO95
14381-14425 Dog Bar Rd	Pole Address	GO95
10869-10967 Morning Star Ln	Street Address	GO95
16559 Old Downieville Hwy	Pole Address	GO95
10281 Tillicum Way	Street Address	GO95
15720 Shannon Way	Street Address	GO95
26 Iroquois Trail	Street Address	GO95
21 Chinook Trail	Street Address	GO95
87 Yonkalla Trail	Street Address	GO95
7 Paiute Trail	Street Address	GO95
1323 Red Fox Rd	Street Address	GO95
14954 Monte Vista Dr	Street Address	GO95
6 Osage Trail	Street Address	GO95
9 Navajo Trail	Street Address	GO95
24 Shasta Trail	Street Address	GO95
58495 Cedar Ln	Street Address	GO95
143 Nevada City Hwy	Street Address	GO95
301 Gethsemane St	Street Address	GO95
4 Osage Trail	Street Address	GO95
10735 Morning Star Ln	Street Address	GO95
2 Shasta Trail	Street Address	GO95
207 Jordan St	Street Address	GO95
18 Chinook Trail	Street Address	GO95
1201 Red Fox Rd	Street Address	GO95
207 Clay St	Pole Address	GO95
11065 White Oak Way	Pole Address	GO95
830 Atkins Rd	Pole Address	GO95
447 Zion St	Street Address	GO95
143 Nevada City Hwy	Street Address	GO95
15225 Monte Vista Dr	Street Address	GO95
58590 Cedar Ln	Street Address	GO95
5 Korominu Trail	Street Address	GO95
10681 Martis Dr	Street Address	GO95
10024 S River St	Street Address	GO95
10281 Columbine Rd	Street Address	GO95
11258 Brockway Rd	Street Address	GO95
10731 Donner Lake Rd	Street Address	GO95
15026 S Shore Dr	Street Address	GO95

13800 S Shore Dr	Street Address	GO95
11200 Dorchester Dr	Street Address	GO95
40200 Truckee-Tahoe Airport Rd	Street Address	GO95
40200 Truckee-Tahoe Airport Rd	Street Address	GO95
11018 Donner Pass Rd	Street Address	GO95
10019 Floriston Ct	Street Address	GO95
14629 Glenshire Dr	Street Address	GO95
14629 Glenshire Dr	Street Address	GO95
14624 Mt Judah Dr	Street Address	GO95
15580 S Shore Dr	Street Address	GO95
11662 Hope Ct	Street Address	GO95
11662 Hope Ct	Street Address	GO95
11691 Kayhoe Ct	Street Address	GO95
11357 Huntsman Leap	Street Address	GO95
11121 Huntsman Leap	Street Address	GO95
10664 Glenshire Dr	Street Address	GO95
11906 Stallion Way	Street Address	GO95
15621 Conifer St	Street Address	GO95
10450 Golden Pine Rd	Street Address	GO95
10148 Laburnham Circle	Street Address	GO95
6425 W River Rd	Street Address	GO95
11642 Silver Fir Circle	Street Address	GO95
10629 Manchester Dr	Street Address	GO95
9705 N Shore Blvd	Street Address	GO95
12773 Donner Pass Rd	Street Address	GO95
12773 Donner Pass Rd	Street Address	GO95
10281 Columbine Rd	Street Address	GO95
10281 Columbine Rd	Street Address	GO95
16320 Ute Dr	Street Address	GO95
12005 Deerfield Dr	Street Address	GO95
9761 Martis Rd	Street Address	GO95
11151 Dorchester Dr	Street Address	GO95
12116 Highland Ave	Street Address	GO95
11330 Skyline Ct	Street Address	GO95
10048 Oriole Ln	Street Address	GO95
16320 Ute Dr	Street Address	GO95
10545 Manchester Dr	Street Address	GO95
10695 Brockway Rd	Street Address	GO95
13701 Donner Pass Rd	Street Address	GO95
12849 Donner Pass Rd	Street Address	GO95
10686 Manchester Dr	Street Address	GO95
10416 Palisades Dr	Street Address	GO95
15575 Waterloo Circle	Street Address	GO95

11111 Dorchester Dr	Street Address	GO95
13860 Donner Pass Rd	Street Address	GO95
10598 Martis Dr	Street Address	GO95
11882 Rio Vista Dr	Street Address	GO95
15630 Archery View	Street Address	GO95
11244 Spring Ln	Street Address	GO95
10373 Evensham Pl	Street Address	GO95
10911 Glenshire Dr	Street Address	GO95
15354 Glenshire Dr	Street Address	GO95
10716 Jeffery Pine Rd	Pole Address	GO95
15504 Glenshire Dr	Street Address	GO95
10695 Brockway Rd	Street Address	GO95
7900 W River Rd	Street Address	GO95
Stampede Dam Rd	Street Address	GO95
Stampede Dam Rd	Street Address	GO95
11414 Whitehorse Rd	Street Address	GO95
15244 Donner Pass Rd	Street Address	GO95
15731 Rolands Way	Street Address	GO95
16231 Ute Dr	Street Address	GO95
13655 Donner Pass Rd	Street Address	GO95
13600 Olympic Dr	Street Address	GO95
15633 Waterloo Circle	Street Address	GO95
10244 Laburnham Circle	Street Address	GO95
13604 Moraine Rd	Street Address	GO95
10515 Dogwood St	Street Address	GO95
10777 Gooseberry Ct	Street Address	GO95
13281 Donner Pass Rd	Street Address	GO95
15609 Spruce St	Street Address	GO95
16047 Glenshire Dr	Street Address	GO95
10253 Washoe Rd	Street Address	GO95
10245 Olympic Blvd	Street Address	GO95
14691 Boca View Ct	Street Address	GO95
15353 Crown Circle	Street Address	GO95
10121 Lake Ave	Street Address	GO95
16193 Ute Dr	Street Address	GO95
10148 Laburnham Circle	Street Address	GO95
14578 S Shore Dr	Street Address	GO95
10632 Laburnham Circle	Street Address	GO95
10568 Laburnham Circle	Street Address	GO95
14625 Red Mountain Rd	Street Address	GO95
15533 S Shore Dr	Street Address	GO95
14845 Denton Ave	Street Address	GO95
10159 Riverside Dr	Street Address	GO95
10846 Dorchester Dr	Street Address	GO95

10792 Aspenwood Rd	Street Address	GO95
14515 S Shore Dr	Street Address	GO95
9761 Martis Rd	Street Address	GO95
10869 Torrey Pine Rd	Street Address	GO95
15670 S Shore Dr	Street Address	GO95
15691 Conifer St	Street Address	GO95
10623 Ponderosa Dr	Street Address	GO95
16175 Glenshire Dr	Street Address	GO95
10851 Whitehorse Rd	Street Address	GO95
10321 Evensham Pl	Street Address	GO95
13579 Donner Pass Rd	Street Address	GO95
13579 Donner Pass Rd	Street Address	GO95
14926 S Shore Dr	Street Address	GO95
15749 Spruce St	Street Address	GO95
10424 Olympic Blvd	Street Address	GO95
11600 Deerfield Dr	Street Address	GO95
11659 Deerfield Dr	Street Address	GO95
15331 Conifer Dr	Street Address	GO95
11880 Deerfield Dr	Street Address	GO95
16251 Old Highway Dr	Street Address	GO95
16685 Glenshire Dr	Street Address	GO95
7860 W River Rd	Street Address	GO95
11551 Highland Ave	Street Address	GO95
11551 Highland Ave	Street Address	GO95
11945 Rio Vista Dr	Street Address	GO95
11945 Rio Vista Dr	Street Address	GO95
14227 S Shore Dr	Street Address	GO95
10140 S River St	Street Address	GO95
11815 Deerfield Dr	Street Address	GO95
10458 Stone Pine Rd	Street Address	GO95
11287 Brockway Rd	Street Address	GO95
15404 Donner Pass Rd	Street Address	GO95
10111 Lake Ave	Street Address	GO95
15760 Willow St	Street Address	GO95
10911 Glenshire Dr	Street Address	GO95
15445 Glenshire Dr	Street Address	GO95
10580 Cedar Dr	Street Address	GO95
15504 Glenshire Dr	Street Address	GO95
10578 Red Fir Rd	Street Address	GO95
10578 Red Fir Rd	Street Address	GO95
15402 S Shore Dr	Street Address	GO95
10419 Briar Circle	Street Address	GO95
7900 W River Rd	Street Address	GO95
10440 Golden Pine Rd	Street Address	GO95

16201 Old Highway Dr	Street Address	GO95
14816 Pioneer Dr	Street Address	GO95
10420 Regency Circle	Pole Address	GO95
13440 Olympic Dr	Street Address	GO95
14821 Berkshire Circle	Street Address	GO95
13969 Juniper Creek Rd	Street Address	GO95
10644 Regency Circle	Street Address	GO95
13273 Sierra Dr	Street Address	GO95
10262 W River St	Street Address	GO95
10114 Dorchester Dr	Street Address	GO95
10125 Wiltshire Ln	Street Address	GO95
14780 Mt Judah Dr	Street Address	GO95
11272 Bishop Pine Rd	Street Address	GO95
15058 Berkshire Circle	Street Address	GO95
15631 Donnington Ln	Street Address	GO95
11243 Dorchester Dr	Street Address	GO95
10220 Surrey Pl	Street Address	GO95
10068 Hirschdale Rd	Street Address	GO95
12353 Deerfield Dr	Street Address	GO95
14821 Berkshire Circle	Street Address	GO95
16463 Tewksbury Dr	Street Address	GO95
10708 Somerset Dr	Street Address	GO95
10520 Golden Pine Rd	Street Address	GO95
15952 Tewksbury Dr	Street Address	GO95
10304 Courtenay Ln	Street Address	GO95
15024 Nelson St	Street Address	GO95
10499 Saxon Way	Street Address	GO95
15975 Canterbury Ln	Street Address	GO95
15655 Waterloo Circle	Street Address	GO95
15385 Icknield Way	Street Address	GO95
10838 Blueberry Rd	Street Address	GO95
15675 Donnington Ln	Street Address	GO95
15636 Colt Ct	Street Address	GO95
14907 Cavalier Rise	Street Address	GO95
10296 Brockway Rd	Street Address	GO95
16814 Walden Dr	Street Address	GO95
10664 Glenshire Dr	Street Address	GO95
11272 Bishop Pine Rd	Street Address	GO95
14519 Donnington Ln	Street Address	GO95

10464 The Strand	Street Address	GO95
15615 Kent Dr	Street Address	GO95
10465 Stuart Staithe	Street Address	GO95
14620 Donnington Ln	Street Address	GO95
11851 Highland Ave	Street Address	GO95
10481 Pine Cone Dr	Street Address	GO95
10409 Courtenay Ln	Street Address	GO95
17144 Uxbridge Dr	Street Address	GO95
16945 Uxbridge Dr	Street Address	GO95
16015 Woodbridge Ct	Street Address	GO95
10588 Royal Crest Dr	Street Address	GO95
14415 Donnington Ln	Street Address	GO95
15389 Crown Circle	Street Address	GO95
11039 Coldwater Rd	Street Address	GO95
10540 The Strand	Street Address	GO95
10455 Saxon Way	Street Address	GO95
10457 Washoe Rd	Street Address	GO95
10550 Dogwood St	Street Address	GO95
15114 Donnington Ln	Street Address	GO95
10279 E River St	Street Address	GO95
15841 Summit Ct	Street Address	GO95
15779 Spruce St	Street Address	GO95
10199 Sheffield Pl	Street Address	GO95
10343 Washoe Rd	Street Address	GO95
12984 Donner Pass Rd	Street Address	GO95
15790 Pine St	Street Address	GO95
10735 Ponderosa Dr	Street Address	GO95
15661 Conifer St	Street Address	GO95
10560 Larch St	Street Address	GO95
16480 Old Highway Dr	Street Address	GO95
11692 Highland Ave	Street Address	GO95
15631 Donnington Ln	Street Address	GO95
11445 Silver Fir Dr	Street Address	GO95
10647 Ponderosa Dr	Street Address	GO95
15952 Tewksbury Dr	Street Address	GO95
12659 Crest Way	Street Address	GO95
16067 Martis Peak Rd	Street Address	GO95
12116 Highland Ave	Street Address	GO95
15806 Kent Dr	Street Address	GO95
10560 Larch St	Street Address	GO95
16455 Glenshire Dr	Street Address	GO95
14255 S Shore Dr	Street Address	GO95
10389 St James Pl	Street Address	GO95
16174 Lancaster Pl	Street Address	GO95

15811 Willow St	Street Address	GO95
10855 W River St	Street Address	GO95
15212 Point Dr	Street Address	GO95
14931 Denton Ave	Street Address	GO95
13821 Donner Pass Rd	Street Address	GO95
15379 Mare Ct	Street Address	GO95
15688 Archery View	Street Address	GO95
16483 Salmon St	Street Address	GO95
13434 Moraine Rd	Street Address	GO95
15619 Cottonwood Dr	Street Address	GO95
14981 Glenshire Dr	Street Address	GO95
10395 Stampede Meadows Rd	Street Address	GO95
10360 Olympic Blvd	Street Address	GO95
12697 Crest Way	Street Address	GO95
10577 Stuart Staithe	Street Address	GO95
15844 Archery View	Street Address	GO95
11748 Old Mill Rd	Street Address	GO95
11652 Silver Fir Circle	Street Address	GO95
14614 S Shore Dr	Street Address	GO95
15998 Old Highway Dr	Street Address	GO95
15790 Pine St	Street Address	GO95
15678 Spruce St	Street Address	GO95
10884 Silver Fir Dr	Street Address	GO95
25 Main St	Street Address	GO95
15 WO 39475 Kearsarge Mill Rd	Street Address	GO95
13000-13078 White Canoe Ln	Street Address	GO95
41784 CA-70	Pole Address	GO95
1947 Greenhorn Rd	Street Address	GO95
1533 Greenhorn Ranch Rd	Street Address	GO95
10290 Crystal Lake Rd	Pole Address	GO95
41784 CA-70	Street Address	GO95
48908 CA-70	Street Address	GO95
179 Chandler Rd	Street Address	GO95
2541 Rideout Trail	Street Address	GO95
41525 CA-70	Street Address	GO95
1528 Lee Rd	Street Address	GO95
1528 Lee Rd	Street Address	GO95
1528 Lee Rd	Street Address	GO95
666 Lee Rd	Street Address	GO95
869 Bresciani Circle	Street Address	GO95
37333 Obsidian Way	Street Address	GO95
32 Bell Ln	Street Address	GO95
2852 Caribou Rd	Street Address	GO95
1151 Lee Rd	Street Address	GO95

565 Hillside Dr	Street Address	GO95
41379 West's Ranch Dr	Street Address	GO95
666 Lee Rd	Street Address	GO95
2863 Caribou Rd	Street Address	GO95
2856 Caribou Rd	Street Address	GO95
15425 Bowman Lake Rd	Pole Address	GO95
18152 Bowman Lake Rd	Street Address	GO95
13110 Bowman Lake Rd	Street Address	GO95
8180 Butterfly Valley-Twain Rd	Street Address	GO95
8175 Butterfly Valley-Twain Rd	Street Address	GO95
2-18 Greenhorn Ranch Rd	Street Address	GO95
2P SO 3423 Lupin Ln	Street Address	GO95
244 E Main St	Street Address	GO95
13781 Strubels Ln	Street Address	GO95
15362 Doolittle Rd	Street Address	GO95
13527 Mystic Mine Rd	Street Address	GO95
17921 Mustang Valley Pl	Street Address	GO95
18112 Mustang Valley Pl	Street Address	GO95
16738 Indian Hill Circle	Street Address	GO95
20205 McCourtney Rd	Street Address	GO95
17511 CA-49	Street Address	GO95
13388 Fernglen Ct	Street Address	GO95
12893 Hidden Valley Rd	Street Address	GO95
405 W Main St	Street Address	GO95
10299 Adam Ave	Street Address	GO95
12893 Hidden Valley Rd	Street Address	GO95
15174 Beyers Ln	Street Address	GO95
15326 Beyers Ln	Street Address	GO95
315 Hughes Rd	Street Address	GO95
10942 Sunrise Heights	Street Address	GO95
10700 Mountaineer Trail	Street Address	GO95
17692 Ridge Crest Ln	Street Address	GO95
11228 McCourtney Rd	Street Address	GO95
14566 Talking Pines Rd	Street Address	GO95
17753 Cindy Ln	Street Address	GO95
15066 Chattering Pines Rd	Street Address	GO95
12297 Nevada City Hwy	Street Address	GO95
345 Carol Dr	Street Address	GO95
110 Doris Dr	Street Address	GO95
10563 Sierra Dr	Street Address	GO95
13396 Bitney Springs Rd	Street Address	GO95
406 W Main St	Street Address	GO95
11122 Bonnie View Way	Pole Address	GO95

10606 Pekolee Dr	Street Address	GO95
15332 Auburn Rd	Street Address	GO95
10846 Ball Rd	Street Address	GO95
13283 Allison Ranch Rd	Street Address	GO95
12005 Allison Ranch Rd	Street Address	GO95
606 Kechley Ave	Street Address	GO95
16837 Lena Ct	Street Address	GO95
10159 Quail Creek Dr	Street Address	GO95
10851 Thornicroft Way	Street Address	GO95
16431 Old State Hwy	Street Address	GO95
15338 Penfold Pl	Street Address	GO95
11281 Sunset Way	Street Address	GO95
11195 Bixler Pl	Street Address	GO95
10516 Quail Dr	Street Address	GO95
12528 Allison Ranch Rd	Street Address	GO95
11671 Allison Ranch Rd	Street Address	GO95
15924 Names Dr	Street Address	GO95
11305 Pekolee Dr	Street Address	GO95
17338 Grace Ct	Pole Address	GO95
10984-10998 Allison Ranch Rd	Street Address	GO95
16458 Frenchtown Rd	Pole Address	GO95
15474 Marina Dr	Street Address	GO95
134 Belle St	Street Address	GO95
13317 La Porte Rd	Street Address	GO95
13410 Old La Porte Rd	Street Address	GO95
15515 Niels Meade Dr	Street Address	GO95
1040 Foote Crossing Rd	Street Address	GO95
12463 Bean Clipper Rd	Street Address	GO95
119 E River St	Street Address	GO95
9332 La Porte Rd	Street Address	GO95
13408 Capitol Dr	Street Address	GO95
16455 Frenchtown Rd	Street Address	GO95
CA-49	Street Address	GO95
16322 Frenchtown Rd	Street Address	GO95
12177 La Porte Rd	Street Address	GO95
15801 Frenchtown Rd	Street Address	GO95
9256 La Porte Rd	Street Address	GO95
13989 La Porte Rd	Street Address	GO95
9256 La Porte Rd	Street Address	GO95
18947 New York Flat Rd	Street Address	GO95
13989 La Porte Rd	Street Address	GO95
15697 Frenchtown Rd	Street Address	GO95
10115 La Porte Rd	Street Address	GO95
9256 La Porte Rd	Street Address	GO95

16008 Mt Olive Rd	Street Address	GO95
15594 Poverty Pond Rd	Street Address	GO95
8742 La Porte Rd	Street Address	GO95
16770 CA-49	Street Address	GO95
9827 La Porte Rd	Street Address	GO95
18644 New York Flat Rd	Street Address	GO95
167 Binet Rd	Street Address	GO95
9692 La Porte Rd	Street Address	GO95
15934 Mt Olive Rd	Street Address	GO95
16382 Frenchtown Rd	Street Address	GO95
17340 Hummingbird Ln	Street Address	GO95
245 Main St	Street Address	GO95
104 E River St	Street Address	GO95
Pliocene Ridge Rd	Street Address	GO95
495 Mountain House Rd	Street Address	GO95
Pliocene Ridge Rd	Street Address	GO95
700 Kanaka Rd	Street Address	GO95
8556 La Porte Rd	Street Address	GO95
9726 Ruff Hill Trail	Street Address	GO95
9381 La Porte Rd	Street Address	GO95
17340 Hummingbird Ln	Street Address	GO95
349 Main St	Street Address	GO95
16918 Halverson Way	Street Address	GO95
327 Commercial St	Street Address	GO95
360 Main St	Street Address	GO95
16190 Thistle Way	Street Address	GO95
245 Main St	Street Address	GO95
359 Main St	Street Address	GO95
347 Goodyear Creek Rd	Street Address	GO95
Hells Half Acre	Street Address	GO95
233 Main St	Street Address	GO95
9862 La Porte Rd	Street Address	GO95
123 Main St	Street Address	GO95
15519 Greenhorn Rd	Street Address	GO95
632 Mammoth Springs Rd	Street Address	GO95
14727 Sontag Rd	Street Address	GO95
8927 La Porte Rd	Street Address	GO95
280 Goodyear Creek Rd	Street Address	GO95
102 Big Fur Rd	Street Address	GO95
16 Buckeye Dr	Street Address	GO95
294 Binet Rd	Street Address	GO95
45 Larem Ln	Street Address	GO95
14102 Judy Ln	Street Address	GO95
1459 Little Grass Valley Rd	Street Address	GO95

31 Jimmy Ct	Street Address	GO95
12711 Pearson Rd	Street Address	GO95
369 Goodyear Creek Rd	Street Address	GO95
15474 Marina Dr	Street Address	GO95
102 Mountain House Rd	Street Address	GO95
134 Belle St	Street Address	GO95
9093 Nero Rd	Street Address	GO95
Foote Crossing Rd	Street Address	GO95
411 Goodyear Creek Rd	Street Address	GO95
8492 La Porte Rd	Street Address	GO95
397 Goodyear Creek Rd	Street Address	GO95
15111 Orchard Springs Rd	Street Address	GO95
15256 Kilham Circle	Street Address	GO95
11045 Tyler Foote Rd	Street Address	GO95
22858 Pleasant Valley Rd	Street Address	GO95
22676 Pleasant Valley Rd	Street Address	GO95
19774 Oak Tree Rd	Street Address	GO95
27515 Blue Sage Way	Street Address	GO95
20305 Pleasant Valley Rd	Street Address	GO95
22570 Pleasant Valley Rd	Street Address	GO95
430 Meadowlark Ln	Street Address	GO95
13035 Sadie D Dr	Street Address	GO95
22912 Scotts Flat Rd	Street Address	GO95
16564 Old Downieville Hwy	Pole Address	GO95
16681 Maybert Rd	Street Address	GO95
10814 Genasci Rd	Street Address	GO95
13515 Banner Mountain Trail	Street Address	GO95
12727 Lower Colfax Rd	Pole Address	GO95
13779 Crawford Ln	Pole Address	GO95
20750 CA-20	Street Address	GO95
20750 CA-20	Street Address	GO95
13479 Gracie Rd	Street Address	GO95
17895 Maybert Rd	Street Address	GO95
10450 Harmony Ridge Resort Rd	Street Address	GO95
12771 Joe Day Ranch Rd	Street Address	GO95
20860 CA-20	Street Address	GO95
20978 CA-20	Street Address	GO95
23896 CA-20	Street Address	GO95
15052 Lolas Echo Rd	Street Address	GO95
12765 Quaker Hill Cross Rd	Street Address	GO95
12827 Quaker Hill Cross Rd	Street Address	GO95
14806 Red Dog Rd	Street Address	GO95
14854 Red Dog Rd	Street Address	GO95
12003 La Barr Meadows Rd	Street Address	GO95

19626 CA-20	Street Address	GO95
24131 CA-20	Street Address	GO95
10747 Red Dog Rd	Street Address	GO95
12197 Poke Pl	Street Address	GO95
17515 CA-20	Street Address	GO95
20928 CA-20	Street Address	GO95
16343 Cooper Rd	Street Address	GO95
14573 N Bloomfield Rd	Street Address	GO95
11777 Kathryn Ln	Street Address	GO95
10085 Banner Lava Cap Rd	Street Address	GO95
12302 Buckeye Rd	Street Address	GO95
14700 N Bloomfield Rd	Street Address	GO95
757 Old Washington Rd	Street Address	GO95
13676 Quaker Hill Cross Rd	Pole Address	GO95
13515 Banner Mountain Trail	Street Address	GO95
12577 Cedar Crest Ct	Street Address	GO95
23092 CA-20	Street Address	GO95
502 Kate Hayes St	Street Address	GO95
10501 Banner Lava Cap Rd	Street Address	GO95
10836 Footwall Dr	Street Address	GO95
10827 Banner Lava Cap Rd	Street Address	GO95
19888 CA-20	Street Address	GO95
438 Kate Hayes St	Street Address	GO95
13673 Lightning Tree Rd	Street Address	GO95
13996 Bear Run Rd	Street Address	GO95
757 Old Washington Rd	Street Address	GO95
12300 Short Circle	Street Address	GO95
10493 Cole Way	Street Address	GO95
13241 Dog Bar Rd	Street Address	GO95
712 S Auburn St	Street Address	GO95
15100 Old Washington Rd	Street Address	GO95
25626 CA-20	Street Address	GO95
14848 N Bloomfield Rd	Street Address	GO95
13287 Rattlesnake Rd	Street Address	GO95
13901 Colfax Hwy	Street Address	GO95
11275 Crescent Dr	Street Address	GO95
13557 Sunshine Valley Rd	Street Address	GO95
15569 Glacier Way	Street Address	GO95
14080 Hansel Ave	Street Address	GO95
11770 Snowpeak Way	Street Address	GO95
11899 Muhlebach Way	Street Address	GO95
11487 Alder Dr	Street Address	GO95
10381 Snow Shoe Circle	Pole Address	GO95

11897 Rainbow Dr	Street Address	GO95
11855 Northwoods Blvd	Pole Address	GO95
12165 Bernese Ln	Street Address	GO95
13476 Hillside Dr	Street Address	GO95
13231 Oberwald Way	Street Address	GO95
10098 E Alder Creek Rd	Street Address	GO95
13421 Davos Dr	Street Address	GO95
13851 Copenhagen Dr	Street Address	GO95
11673 Rhineland Ave	Street Address	GO95
10089 E Alder Creek Rd	Street Address	GO95
10580 Whitetail Ct	Street Address	GO95
14110 Glacier View Dr	Street Address	GO95
13921 Hansel Ave	Street Address	GO95
14514 Hansel Ave	Street Address	GO95
13830 Ski View Loop	Street Address	GO95
14779 Copenhagen Dr	Street Address	GO95
12903 Ski View Loop	Street Address	GO95
12235 Landeau Ln	Street Address	GO95
14535 Wolfgang Rd	Street Address	GO95
11255 Beacon Rd	Street Address	GO95
13886 Hansel Ave	Street Address	GO95
12074 Bernese Ln	Street Address	GO95
13687 Heidi Way	Street Address	GO95
10515 Laurelwood Dr	Street Address	GO95
12784 Lee Rd	Street Address	GO95
12185 Sierra Dr	Street Address	GO95
12150 Muhlebach Way	Street Address	GO95
12268 Bernese Ln	Street Address	GO95
11725 Tundra Dr	Street Address	GO95
18570 Bear Canyon Rd	Street Address	GO95
10261 Lake Spaulding Rd	Street Address	GO95
11112 Bowman Lake Rd	Street Address	GO95
40070 CA-20	Street Address	GO95
13291 Bowman Lake Rd	Pole Address	GO95
43034 Laing Rd	Street Address	GO95
34265 Alta Bonnynook Rd	Street Address	GO95
295 Drum Forebay Rd	Street Address	GO95
42005 Nyack Rd	Street Address	GO95
10251 Lake Spaulding Rd	Street Address	GO95
10280 Lake Spaulding Rd	Street Address	GO95
440 Caine Rd	Street Address	GO95
40225 Airport Rd	Pole Address	GO95
565 Serenity Ln	Street Address	GO95

Blue Canyon Rd	Pole Address	GO95
10280 Lake Spaulding Rd	Street Address	GO95
150 Bonnynook Rd	Street Address	GO95
10261 Lake Spaulding Rd	Street Address	GO95
10255 Lake Spaulding Rd	Street Address	GO95
39950 CA-20	Street Address	GO95
34260 Alta Bonnynook Rd	Street Address	GO95
31190 Gold Run Rd	Street Address	GO95
110 Oakleaf Dr	Street Address	GO95
179 5th St	Street Address	GO95
157 Claremont Ct	Street Address	GO95
157 Claremont Ct	Street Address	GO95
1237 Pioneer Rd	Street Address	GO95
146 3rd St	Street Address	GO95
870 Haskins Circle	Street Address	GO95
138 Sugar Pine Dr	Street Address	GO95
69028-69080 Porcupine Rd	Street Address	GO95
14942 Skislope Way	Street Address	GO95
22207 Spruce St	Street Address	GO95
22216 Cedar St	Street Address	GO95
14741-14799 Lower Colfax Rd	Street Address	GO95
2445 E Main St	Street Address	GO95
80921 Feather River Hwy	Street Address	GO95
2077 E Main St	Street Address	GO95
2061 E Main St	Street Address	GO95
4307 BRANDY CITY RD	Street Address	GO95
15974 Maybert Rd	Street Address	GO95
17701-17747 CA-20	Street Address	GO95
742 Mile High Rd	Street Address	GO95
2168 Chandler Rd	Street Address	GO95
AHN 4	Street Address	GO95
11011 Thornicroft Way	Street Address	GO95
7199 Vinton Loyalton Rd	Street Address	GO95
7165 Sylvan Rd	Street Address	GO95
19085-19099 CA-49	Street Address	GO95
80765 Feather River Hwy	Street Address	GO95
84463 CA-70	Street Address	GO95
94217 CA-70	Street Address	GO95
211 Antelope Valley Rd	Street Address	GO95
169-199 Cottonwood Dr	Street Address	GO95
80901-81005 Feather River Hwy	Street Address	GO95
148-150 Smithneck Rd	Street Address	GO95
2 Phillips rd	Street Address	GO95
961 Bucks Lake Rd	Street Address	GO95

60452-60498 Old Mill Pond Rd	Street Address	GO95
76980 hwy 70	Street Address	GO95
47901-47947 CA-70	Street Address	GO95
200-268 County Hospital Rd	Street Address	GO95
7735 Whitethorn Trail	Street Address	GO95
404185 Scott rd	Street Address	GO95
80898 Feather River Hwy	Street Address	GO95
80922 Feather River Hwy	Street Address	GO95
404185 scott rd	Street Address	GO95
1933 Greenhorn Ranch Rd.	Street Address	GO95
283 Carol Ln W	Street Address	GO95
5929 Grizzly Rd	Street Address	GO95
23990	Street Address	GO95
3 Woolley Rd	Street Address	GO95
35370 Baxter Rd	Street Address	GO95
440 Caine Rd	Street Address	GO95
27297 Norton Grade Rd	Street Address	GO95
28045 Manzanita Trail	Street Address	GO95
13952 Moonshine Rd	Street Address	GO95
13747 Moonshine Rd	Street Address	GO95
15953 State Highway 49	Street Address	GO95
15679 Cleveland Ave	Street Address	GO95
15987 Cleveland Ave	Street Address	GO95
14682 Marysville Rd	Street Address	GO95
13746 Moonshine Rd	Street Address	GO95
16834 State Highway 49	Street Address	GO95
14918 Kelly Rd	Street Address	GO95
13855 Moonshine Rd	Street Address	GO95
9094 Hiatt Ln	Street Address	GO95
8870 Idlewood Circle	Street Address	GO95
18615 New York Flat Rd	Street Address	GO95
5101 State Highway 49	Street Address	GO95
32565 Frost Hill Pl	Street Address	GO95
635 Frost Hill Rd	Street Address	GO95
35151 Baxter Rd	Street Address	GO95

10982 Bowman Lake Rd	Street Address	GO95
440 Caine Rd	Street Address	GO95
510 Lee Rd	Street Address	GO95
1709 Ridge Rd	Street Address	GO95

14421 You Bet Rd	Street Address	GO95
15648 Greenhorn Rd	Street Address	GO95
12942 Boreham Ln	Street Address	GO95
450 Bennett St	Street Address	GO95
17548 State Highway 49	Street Address	GO95
15740 De Groot Ln	Street Address	GO95
15448 Cleveland Ave	Street Address	GO95
16134 Mountain House Rd	Street Address	GO95
104 Village Way	Street Address	GO95
104 Main St	Street Address	GO95
Hells Half Acre	Street Address	GO95
13348 Grass Valley Ave	Street Address	GO95
12845 Francis Dr	Street Address	GO95
14449 Lower Colfax Rd	Street Address	GO95
13055 La Barr Meadows Rd	Street Address	GO95
34145 Alta Bonnynook Rd	Street Address	GO95
128 Main St	Street Address	GO95
257 Sunnyside Dr	Street Address	GO95
14520 Pendola Rd	Street Address	GO95
32565 Frost Hill Pl	Street Address	GO95
597 Sacramento St	Street Address	GO95
32687 Main St	Street Address	GO95
489 Alta Powerhouse Rd	Street Address	GO95
Gold Run School Rd	Street Address	GO95
11028 Bowman Lake Rd	Street Address	GO95
11710 La Porte Rd	Street Address	GO95
300 Canyon Mine Rd	Street Address	GO95
777 Blue Canyon Rd	Street Address	GO95
8492 La Porte Rd	Street Address	GO95
16586 Willow Glen Rd	Street Address	GO95
16548 Willow Glen Rd	Street Address	GO95
10066 Smith Rd	Street Address	GO95
12808 Francis Dr	Street Address	GO95
11912 Black Oak Dr	Street Address	GO95
125 E Empire St	Street Address	GO95

928 Sacramento St	Street Address	GO95
321 Empire Ct	Street Address	GO95
10451 Pittsburg Rd	Street Address	GO95
15862 Rattlesnake Rd	Street Address	GO95
10292 Sugar Pine Ct	Street Address	GO95
12577 Butterfly Dr	Street Address	GO95
13334 La Barr Meadows Rd	Street Address	GO95
11337 Grange Ct	Street Address	GO95
511 Miners St	Street Address	GO95
221 Main St	Street Address	GO95
13390 La Barr Meadows Rd	Street Address	GO95
13183 Wood Rose Way	Street Address	GO95
15438 Lorie Dr	Street Address	GO95
16259 Rattlesnake Rd	Street Address	GO95
11478 Avern Way	Street Address	GO95
14608 Dog Bar Rd	Street Address	GO95
12210 Valley View Rd	Street Address	GO95
13859 Greenhorn Rd	Street Address	GO95
19919 Casa Loma Dr	Street Address	GO95
10079 Crestview Dr	Street Address	GO95
15365 Birch Meadows Circle	Street Address	GO95
13431 La Barr Meadows Rd	Street Address	GO95

13420 Sunshine Valley Rd	Street Address	GO95
10883 Pine Hill Dr	Street Address	GO95
13671 Meadow View Dr	Street Address	GO95
12118 Sunshine Valley Rd	Street Address	GO95
11121 Cedar Ridge Dr	Street Address	GO95
11071 Cedar Ridge Dr	Street Address	GO95
13420 Sunshine Valley Rd	Street Address	GO95
12442 Gayle Ln	Street Address	GO95
10037 Cornette Way	Street Address	GO95
13964 Birch Rd	Street Address	GO95
12442 Valley View Rd	Street Address	GO95
11173 Cedar Ridge Dr	Street Address	GO95
11638 Donner Pass Rd	Street Address	GO95
30 Hayes Rd	Street Address	GO95
102 Main St	Street Address	GO95
104 Main St	Street Address	GO95
115 Main St	Street Address	GO95
120 Main St	Street Address	GO95
135 Wild Plum Rd	Street Address	GO95

10990 Donner Pass Rd	Street Address	GO95
118 Wild Plum Rd	Street Address	GO95
12131 Sierra Dr E	Street Address	GO95
15226 Alder Creek Rd	Street Address	GO95
14075 Herringbone Way	Street Address	GO95
12295 Stockholm Way	Street Address	GO95
11628 Sitzmark Way	Street Address	GO95
11400 Sun Valley Rd	Street Address	GO95
10986 Bolzano Dr	Street Address	GO95
11709 Tundra Dr	Street Address	GO95
11754 Chalet Rd	Street Address	GO95
14128 Hansel Ave	Street Address	GO95
13687 Heidi Way	Street Address	GO95
11742 Bull Pine Trail	Street Address	GO95
12298 Lemon Ct	Street Address	GO95
10556 Jeffrey Way	Street Address	GO95
10725 Jeffrey Way	Street Address	GO95
14019 Ramshorn St	Street Address	GO95
12870 Northwoods Blvd	Street Address	GO95
14095 Glacier View Dr	Street Address	GO95
14796 Copenhagen Dr	Street Address	GO95
12958 Hansel Ave	Street Address	GO95
Teton Way	Street Address	GO95
10319 Prosser Dr	Street Address	GO95
11677 Northwoods Blvd	Street Address	GO95
12275 Stockholm Way	Street Address	GO95
12292 Viking Way	Street Address	GO95
13945 Ski View Loop	Street Address	GO95
11291 Zermatt Dr	Street Address	GO95
13466 Hillside Dr	Street Address	GO95
14600 Copenhagen Dr	Street Address	GO95
11435 Norse Ave	Street Address	GO95
11627 Baden Rd	Street Address	GO95
12946 Davos Dr	Street Address	GO95
14521 Wolfgang Rd	Street Address	GO95
10829 Barnes Dr	Street Address	GO95
10423 Lenelle Ln	Street Address	GO95
10826 Heather Rd	Street Address	GO95
10103 E Alder Creek Rd	Street Address	GO95
11171 Alder Dr	Street Address	GO95
12023 Rainbow Dr	Street Address	GO95
12479 Greenwood Dr	Street Address	GO95
13312 Hansel Ave	Street Address	GO95
14052 Ramshorn St	Street Address	GO95

14396 Hansel Ave	Street Address	GO95
11753 Nordic Ln	Street Address	GO95
12018 Kitzbuhel Rd	Street Address	GO95
14096 Ramshorn St	Street Address	GO95
12127 Bernese Ln	Street Address	GO95
11851 Saint Bernard Dr	Street Address	GO95
13232 Falcon Point Pl	Street Address	GO95
14768 Wolfgang Rd	Street Address	GO95
13168 Davos Dr	Street Address	GO95
13421 Davos Dr	Street Address	GO95
12715 Palisade St	Street Address	GO95
11751 Chateau Way	Street Address	GO95
12398 Greenleaf Way	Street Address	GO95
14913 Swiss Ln	Street Address	GO95
10512 Mougle Ln	Street Address	GO95
14100 Ski View Loop	Street Address	GO95
10715 Ski Slope Way	Street Address	GO95
13286 Davos Dr	Street Address	GO95
13230 Oberwald Way	Street Address	GO95
11852 Ski Slope Way	Street Address	GO95
15075 Wolfgang Rd	Street Address	GO95
11175 Zermatt Dr	Street Address	GO95
14048 Ski View Loop	Street Address	GO95
14274 Hansel Ave	Street Address	GO95
12878 Ski View Loop	Street Address	GO95
14737 Copenhagen Dr	Street Address	GO95
11733 Kitzbuhel Rd	Street Address	GO95
13271 Ski Slope Way	Street Address	GO95
12025 Bennett Flat Rd	Street Address	GO95
11400 Chamonix Rd	Street Address	GO95
12811 Dulzura St	Street Address	GO95
14378 Copenhagen Dr	Street Address	GO95
11281 Zermatt Dr	Street Address	GO95
12966 Dulzura St	Street Address	GO95
12136 Muhlebach Way	Street Address	GO95
12312 Sierra Dr E	Street Address	GO95
13907 Hansel Ave	Street Address	GO95
11866 Kitzbuhel Rd	Street Address	GO95
12508 Saint Bernard Dr	Street Address	GO95
10687 Mougle Ln	Street Address	GO95
12210 Sierra Dr E	Street Address	GO95
11598 Rhineland Ave	Street Address	GO95
11239 Ski Slope Way	Street Address	GO95
11683 Bennett Flat Rd	Street Address	GO95

14914 Slalom Way	Street Address	GO95
11891 Chalet Rd	Street Address	GO95
14232 Saint Croix Way	Street Address	GO95
17748 Maybert Rd	Street Address	GO95
19035 Siesta Dr	Street Address	GO95
13113 Quaker Hill Cross Rd	Street Address	GO95
504 Moon Ridge Rd	Street Address	GO95
554 E Broad St	Street Address	GO95
306 American Hill Rd	Street Address	GO95
345 American Hill Rd	Street Address	GO95
15415 Lake Vera Purdon Rd	Street Address	GO95
10901 Genasci Rd	Street Address	GO95
16304 Cooper Rd	Street Address	GO95
18561 Yuba-Donner Scenic Byway	Street Address	GO95
15474 Airport Rd	Street Address	GO95
15474 Airport Rd	Street Address	GO95
13226 Quaker Hill Cross Rd	Street Address	GO95
18167 Yuba-Donner Scenic Byway	Street Address	GO95
524 N Pine St	Street Address	GO95
19311 State Highway 20	Street Address	GO95
14098 Quaker Hill Cross Rd	Street Address	GO95
10770 Garden Ln	Street Address	GO95
18325 Lake Forest Dr	Street Address	GO95
18552 State Highway 20	Street Address	GO95
13833 Lake Wildwood Dr	Street Address	GO95
550 N Pine St	Street Address	GO95

13313 Bodie Ridge Rd	Street Address	GO95
18474 Easy St	Street Address	GO95
18031 Penn Valley Dr	Street Address	GO95
13284 Thistle Loop	Street Address	GO95
10455 Conservation Rd	Street Address	GO95
10227 Missouri Bar Rd	Street Address	GO95
10555 Devonshire Circle	Street Address	GO95
14663 Pear Tree Ln	Street Address	GO95
10500 Sun Shadow Circle	Street Address	GO95
17610 Shoshoni Trail Ct	Street Address	GO95
15547 Old Downieville Hwy	Street Address	GO95
10575 Crows Nest Ln	Street Address	GO95
11023 Berggren Ln	Street Address	GO95
14263 Idaho Maryland Rd	Street Address	GO95
12199 Red Dog Rd	Street Address	GO95
16797 Yuba-Donner Scenic Byway	Street Address	GO95
11475 Burkard Ln	Street Address	GO95
21252 Running Horse Rd	Street Address	GO95
11464 Banner Mountain Trail	Street Address	GO95
14098 Quaker Hill Cross Rd	Street Address	GO95
12247 Pasquale Rd	Street Address	GO95
10625 Willow Ln	Street Address	GO95
18325 Piper Ln	Street Address	GO95
13853 Beitler Rd	Street Address	GO95
13441 Banner Lava Cap Rd	Street Address	GO95
17151 Country Circle	Street Address	GO95
11387 Meadow View Way	Street Address	GO95
13441 Gracie Rd	Street Address	GO95
20107 Big Oak Dr	Street Address	GO95
24223 Pleasant Valley Rd	Pole Address	GO95
16778 Maybert Rd	Pole Address	GO95
22630 Pleasant Valley Rd	Street Address	GO95
22630 Pleasant Valley Rd	Street Address	GO95
27955 Sweetland Rd	Street Address	GO95
26281 Yuba-Donner Scenic Byway	Street Address	GO95
23381 Pleasant Valley Rd	Street Address	GO95
22286 Pleasant Valley Rd	Street Address	GO95
19610 Oak Tree Rd	Street Address	GO95

18848 State Highway 20	Street Address	GO95
16756 Maybert Rd	Street Address	GO95
12998 Quaker Hill Cross Rd	Street Address	GO95
13160 Quaker Hill Cross Rd	Street Address	GO95
22042 State Highway 20	Street Address	GO95
540 Ellen Ave	Street Address	GO95
278 Bella Vista Dr	Street Address	GO95
480 E Spruce Ave	Street Address	GO95
297 W Loyalton Ave	Street Address	GO95
96 1st Ave	Street Address	GO95
540 E Loyalton Ave	Street Address	GO95
6107 Semaphore Rd	Street Address	GO95
73875 Old County Rd	Street Address	GO95
324 Bella Vista Dr	Street Address	GO95
636 West St	Street Address	GO95
280 5th Ave	Street Address	GO95
267 E Sierra St	Street Address	GO95
640 Redbud St	Street Address	GO95
76696 Aspen Dr	Street Address	GO95
14843 Lewis Rd	Street Address	GO95
725 Nevada St	Street Address	GO95
16447 State Highway 20	Street Address	GO95
12600 Vicki Dr	Street Address	GO95
27007 Sweetland Rd	Street Address	GO95
19672 Oak Tree Rd	Street Address	GO95
11463 Tyler Foote Rd	Street Address	GO95
27001 Yuba-Donner Scenic Byway	Street Address	GO95
27039 Yuba-Donner Scenic Byway	Street Address	GO95
25675 Yuba-Donner Scenic Byway	Street Address	GO95
24368 Pleasant Valley Rd	Street Address	GO95
12700 Robinson Rd	Pole Address	GO95
1216 La Porte Rd	Street Address	GO95
353 S Redberg Ave	Street Address	GO95

11100 Tyler Foote Rd	Street Address	GO95
10759 Ivey Ln	Street Address	GO95
14078 Banner Mountain Lookout	Street Address	GO95
15832 Airport Rd	Street Address	GO95
21596 State Highway 20	Street Address	GO95
340 N Gulling St	Street Address	GO95
421 Nevada St	Street Address	GO95
14862 Brush Creek Ct	Street Address	GO95
11689 Casci Ridge Rd	Street Address	GO95
1955 E Claremont Way	Street Address	GO95
13847 Tyler Foote Rd	Street Address	GO95
13673 Lightning Tree Rd	Street Address	GO95
15832 State Highway 20	Street Address	GO95
200 Crescent St	Street Address	GO95
59200 CA-49	Street Address	GO95
150 N Mill Creek Rd	Street Address	GO95
68 S Mill Creek Rd	Street Address	GO95
144 S Mill Creek Rd	Street Address	GO95
6232-6276 Feather River Hwy	Street Address	GO95
546 Longhorn Dr	Street Address	GO95
8979 La Porte Rd	Street Address	GO95
10172 Donner Trail Rd	Pole Address	GO95
110 Evergreen Cir	Street Address	GO95
2435 Greenhorn Ranch Rd.	Street Address	GO95
2205 Lee Rd	Street Address	GO95
12980 SQUIRREL CREEK RD.	Street Address	GO95
ALONG STATE HWY 20 305	Street Address	GO95
13577 COUNTRY HEIGHTS RD	Street Address	GO95
	Street Address	GO95
13174 HIDDEN LN	Street Address	GO95
16058 PASQUALE ROAD	Street Address	GO95
39.2308450, -120.7606646	Pole Address	GO95
1662 Trosi Canyon rd.	Street Address	GO95
1945-1995 Trosi Ranch Rd	Street Address	GO95
39.3080028, -120.6558579	Pole Address	GO95
725 FT N/O GRAEAGLE RD	Street Address	GO95
1300 FT N/O GRAEAGLE RD	Street Address	GO95
1500 FT GRAEGLE RD	Street Address	GO95
1850 FT N/O GRAEAGLE RD	Street Address	GO95
2600 FT N/O GRAEGLE RD	Street Address	GO95
107 Paiute Trail	Street Address	GO95
114 Bark Way	Street Address	GO95
17 Portola-McLears Rd	Street Address	GO95
425 Bonta St	Street Address	GO95

559 Blairsden Graeagle Rd	Street Address	GO95
332 Pine St	Street Address	GO95
12 Mattole Trail	Street Address	GO95
32 Korominu Trail	Street Address	GO95
22 Shasta Trail	Street Address	GO95
23 Paiute Trail	Street Address	GO95
30 Kato Trail	Street Address	GO95
7 Kato Trail	Street Address	GO95
18 W Chilula Trail	Street Address	GO95
54 Klamath Trail	Street Address	GO95
58599 Horsetail Rd	Street Address	GO95
57421 Jackson Peak Rd	Street Address	GO95
9 Chinook Trail	Street Address	GO95
58421 State Highway 70	Street Address	GO95
5556 Johnsville Rd	Street Address	GO95
59106 State Highway 70	Street Address	GO95
8 Iroquois Trail	Pole Address	GO95
109 State Highway 89	Pole Address	GO95
59171 Overload Rd	Pole Address	GO95
NEW YORK HOUSE RD	Street Address	GO95
NEW YORK HOUSE RD	Street Address	GO95
RD 100	Pole Address	GO95
29026 State Highway 49	Street Address	GO95
16144 Sages Rd	Street Address	GO95
26269 Yuba-donner Scenic Byway	Street Address	GO95
26921 Yuba-donner Scenic Byway	Street Address	GO95
26335 Sweetland Rd	Street Address	GO95
26968 Sweetland Rd	Street Address	GO95
10233 School St	Street Address	GO95
26151 Sweetland Rd	Street Address	GO95
28111 Sweetland Rd	Street Address	GO95
19286 Oak Tree Rd	Street Address	GO95
26130 Yuba-donner Scenic Byway	Street Address	GO95
26968 Sweetland Rd	Street Address	GO95
10164 Stotler Ave	Street Address	GO95
26968 Sweetland Rd	Street Address	GO95
27971 State Highway 49	Street Address	GO95
19286 Oak Tree Rd	Street Address	GO95
18470 Oak Tree Rd	Street Address	GO95
18528 Oak Tree Rd	Street Address	GO95
13847 Tyler Foote Rd	Street Address	GO95
24590 Poplar Meadow Ln	Street Address	GO95
24313 Bodhi Ct	Street Address	GO95
16079 Big Sky Rd	Street Address	GO95

28499 Sweetland Rd	Street Address	GO95
30998 State Highway 49	Street Address	GO95
15969 Red Dog Rd	Pole Address	GO95
16455 State Highway 20	Street Address	GO95
19311 State Highway 20	Street Address	GO95
19311 State Highway 20	Street Address	GO95
19311 State Highway 20	Street Address	GO95
12344 Pawnee Trail	Pole Address	GO95
16677 Banner Quaker Hill Rd	Street Address	GO95
12923 Sadie D Dr	Pole Address	GO95
14695 Red Dog Rd	Pole Address	GO95
12830 Quaker Hill Cross Rd	Street Address	GO95
7735 CA-89	Street Address	GO95
134 Boulder St	Street Address	GO95
13683 Quaker Hill Cross Rd	Pole Address	GO95
21073 State Highway 20	Street Address	GO95
11112 Erin Ln	Street Address	GO95
537 Coyote St	Street Address	GO95
18200 Rainbows End Rd	Street Address	GO95
61 Bourbon Hill Rd	Street Address	GO95
12765 Quaker Hill Cross Rd	Pole Address	GO95
16362 Pasquale Rd	Street Address	GO95
16418 Banner Quaker Hill Rd	Street Address	GO95
13113 Quaker Hill Cross Rd	Street Address	GO95
14811 Oak Ridge Rd	Pole Address	GO95
14585 Oak Ridge Rd	Pole Address	GO95
14900 Red Dog Rd	Pole Address	GO95
15531 Cascade Dr	Street Address	GO95
15990 Pasquale Rd	Pole Address	GO95
10406 N Bloomfield Rd	Street Address	GO95
18180 Round Mountain Ranch Rd	Street Address	GO95
754 Zion St	Street Address	GO95
13901 Red Dog Rd	Pole Address	GO95
13621 Red Dog Rd	Pole Address	GO95
13637 Red Dog Rd	Pole Address	GO95
11930 Crystal Wells Rd	Pole Address	GO95
17647 Shoshoni Trail Ct	Street Address	GO95
19217 Scotts Flat Rd	Street Address	GO95
19163 Scotts Flat Rd	Pole Address	GO95
10 Galena Way	Street Address	GO95
12840 Old Washington Rd	Street Address	GO95
Old Washington Rd	Street Address	GO95
24691 State Highway 20	Street Address	GO95
12840 Old Washington Rd	Street Address	GO95

15166 Old Washington Rd	Street Address	GO95
13283 Little York Close	Pole Address	GO95
11287 Red Ranch Rd	Pole Address	GO95
10961 John Muir Ln	Pole Address	GO95
10961 John Muir Ln	Street Address	GO95
10490 N Bloomfield Rd	Pole Address	GO95
18849 Brindejon Rd	Pole Address	GO95
13939 Nimbus Dam Rd	Pole Address	GO95
12389 Pawnee Trail	Street Address	GO95
16948 Pasquale Rd	Pole Address	GO95
16878 Pasquale Rd	Street Address	GO95
10775 N Bloomfield Rd	Pole Address	GO95
12983 Aurora Close	Street Address	GO95
13030 Aurora Close	Pole Address	GO95
16999 Maybert Rd	Pole Address	GO95
12738 Summit Ridge Dr	Street Address	GO95
12952 Summit Ridge Dr	Street Address	GO95
15749 Mountain View Dr	Pole Address	GO95
12672 Summit Ridge Dr	Street Address	GO95
12672 Summit Ridge Dr	Street Address	GO95
13900 Lava Dome Way	Street Address	GO95
14117 Quail Nest Way	Street Address	GO95
15898 Bush Rd	Pole Address	GO95
10901 Mill Springs Dr	Street Address	GO95
15801 Turtleback Hill Rd	Pole Address	GO95
11112 Erin Ln	Street Address	GO95
17889 Douglas Rd	Pole Address	GO95
11150 N Bloomfield Rd	Street Address	GO95
900-934 Graeagle Johnsville Rd	Street Address	GO95
10833 Murchie Mine Rd	Street Address	GO95
11507 Red Dog Rd	Pole Address	GO95
21253 Running Horse Rd	Street Address	GO95
19146 Rock Creek Rd	Pole Address	GO95
18834 ROCK CREEK	Street Address	GO95
848 Gold Flat Rd	Street Address	GO95
14585 Oak Ridge Rd	Pole Address	GO95
14408 Sun Forest Dr	Pole Address	GO95
13560 Forest Park Circle	Pole Address	GO95
17086 Kozy Nest Ct	Street Address	GO95
20103 Big Oak Dr	Street Address	GO95
17455 Indian Springs Rd	Street Address	GO95
448 E Magnolia Ave	Street Address	GO95
17695 Oak View Ln	Street Address	GO95
13302 Sugarbush Ct	Pole Address	GO95

10981 Spenceville Rd	Street Address	GO95
17645 Penn Valley Dr	Street Address	GO95
10514 Spenceville Rd	Street Address	GO95
13572 Lake Wildwood Dr	Pole Address	GO95
13719 Lake Wildwood Dr	Pole Address	GO95
10328 Reynold Way	Street Address	GO95
11068 W River St	Street Address	GO95
10561 Golden Pine Rd	Street Address	GO95
14825 Old Highway 89	Street Address	GO95
11856 Riverview Ct	Street Address	GO95
11716 Donner Pass Rd	Street Address	GO95
12337 Sierra Dr E	Street Address	GO95
11213 Sitzmark Way	Street Address	GO95
12055 Bavarian Way	Street Address	GO95
Northwoods Blvd	Street Address	GO95
12802 Palisade St	Street Address	GO95
12715 Parker Rd	Street Address	GO95
11760 Donner Pass Rd	Street Address	GO95
11252 Tahoe Dr	Street Address	GO95
10175 Levone Ave	Street Address	GO95
10964 Alder Dr	Street Address	GO95
15715 Martis Peak Rd	Street Address	GO95
11732 Donner Pass Rd	Street Address	GO95
10099 S River St	Pole Address	GO95
10380 Reynold Way	Pole Address	GO95
10437 Estates Dr	Pole Address	GO95
10294 Reynold Way	Pole Address	GO95
10248 Reynold Way	Pole Address	GO95
14825 Old Highway 89	Pole Address	GO95
15343 Icknield Way	Pole Address	GO95
15311 Icknield Way	Pole Address	GO95
15655 Glenshire Dr	Pole Address	GO95
15197 Chatham Reach	Pole Address	GO95
15645 Martis Peak Rd	Pole Address	GO95
14895 Martis Peak Rd	Pole Address	GO95
14600 Martis Peak Rd	Pole Address	GO95
14464 Martis Peak Rd	Pole Address	GO95
10534 Martis Dr	Street Address	GO95
11653 Kayhoe Ct	Street Address	GO95
10462 Martis Dr	Street Address	GO95
13312 Hansel Ave	Street Address	GO95
18168 La Mirada Rd	Pole Address	GO95
12648 Crest Way	Street Address	GO95
12797 Crest Way	Street Address	GO95

La Mirada Rd	Pole Address	GO95
10577 Dogwood Rd	Pole Address	GO95
16021 HOBART MILLS	Street Address	GO95
11782 Chamonix Rd	Street Address	GO95
17768 Stoney Pt	Street Address	GO95
17768 Stoney Pt	Street Address	GO95
14374 Martis Peak Rd	Pole Address	GO95
14615 Tyrol Rd	Street Address	GO95
14675 Tyrol Rd	Street Address	GO95
13175 Ski View Loop	Street Address	GO95
Stampede Dam Rd	Pole Address	GO95
Stampede Dam Rd	Pole Address	GO95
15875 Summit Ct	Pole Address	GO95
14192 Hansel Ave	Street Address	GO95
14112 Hansel Ave	Street Address	GO95
14274 Hansel Ave	Street Address	GO95
14396 Hansel Ave	Street Address	GO95
14499 Hansel Ave	Street Address	GO95
11252 Bolzano Dr	Street Address	GO95
13853 Davos Dr	Street Address	GO95
12074 Bernese Ln	Street Address	GO95
12140 Bernese Ln	Street Address	GO95
13172 Solvang Way	Street Address	GO95
13499 Hillside Dr	Street Address	GO95
10515 Dogwood St	Street Address	GO95
15530 S Shore Dr	Street Address	GO95
11457 Zermatt Dr	Street Address	GO95
12230 Bernese Ln	Street Address	GO95
11059 Zermatt Dr	Street Address	GO95
11627 Baden Rd	Street Address	GO95
16646 Ski Slope Way	Street Address	GO95
14179 Davos Dr	Street Address	GO95
13561 Heidi Way	Street Address	GO95
14195 Davos Dr	Street Address	GO95
11441 Baden Rd	Street Address	GO95
11496 Saint Bernard Dr	Street Address	GO95
12958 Hansel Ave	Street Address	GO95
13693 Cristallina Way	Street Address	GO95
12912 Pinnacle Loop	Street Address	GO95
14936 Wolfgang Rd	Street Address	GO95
15075 Wolfgang Rd	Street Address	GO95
14099 Ski View Loop	Street Address	GO95
10492 Klondike Flat Rd	Street Address	GO95
10370 Klondike Flat Rd	Pole Address	GO95

10370 Klondike Flat Rd	Street Address	GO95
13359 Hansel Ave	Street Address	GO95
12311 Saint Bernard Dr	Street Address	GO95
12296 Stockholm Way	Street Address	GO95
12317 Stockholm Way	Street Address	GO95
12508 Saint Bernard Dr	Street Address	GO95
13789 Heidi Way	Street Address	GO95
11531 Sun Valley Rd	Street Address	GO95
11366 Sun Valley Rd	Street Address	GO95
14896 Swiss Ln	Street Address	GO95
11664 Rhineland Ave	Street Address	GO95
11784 Rhineland Ave	Street Address	GO95
Chalet Rd	Street Address	GO95
Chalet Rd	Street Address	GO95
Chateau Way	Street Address	GO95
15109 Swiss Ln	Street Address	GO95
12962 Ski View Loop	Street Address	GO95
12878 Ski View Loop	Street Address	GO95
14193 Ski View Loop	Street Address	GO95
12150 Muhlebach Way	Street Address	GO95
11672 Oslo Dr	Street Address	GO95
14094 Saint Croix Way	Street Address	GO95
14437 S Shore Dr	Street Address	GO95
12196 Sierra Dr E	Street Address	GO95
12965 Davos Dr	Street Address	GO95
12946 Davos Dr	Street Address	GO95
11515 Saint Bernard Dr	Street Address	GO95
12454 Ski Slope Way	Street Address	GO95
12849 Donner Pass Rd	Street Address	GO95
13420 Olympic Dr	Street Address	GO95
15888 Donner Pass Rd	Street Address	GO95
10447 Washoe Rd	Street Address	GO95
13814 Alder Creek Rd	Street Address	GO95
13230 Oberwald Way	Street Address	GO95
11582 Rhineland Ave	Street Address	GO95
12721 Bernese Ln	Street Address	GO95
12644 Bernese Ln	Street Address	GO95
10237 Washoe Rd	Street Address	GO95
13655 Moraine Rd	Street Address	GO95
13655 Donner Pass Rd	Street Address	GO95
13687 Moraine Rd	Street Address	GO95
13253 Donner Pass Rd	Street Address	GO95
13253 Donner Pass Rd	Street Address	GO95
12699 Saint Moritz Ln	Street Address	GO95

13945 Ski View Loop	Street Address	GO95
14319 Herringbone Way	Street Address	GO95
13447 Pathway Ave	Street Address	GO95
13477 Pathway Ave	Street Address	GO95
12362 Greenleaf Way	Street Address	GO95
15179 Northwoods Blvd	Street Address	GO95
15113 Northwoods Blvd	Street Address	GO95
14065 Ramshorn St	Street Address	GO95
14035 Ramshorn St	Street Address	GO95
14094 Tyrol Rd	Street Address	GO95
14096 Ramshorn St	Street Address	GO95
10986 Bolzano Dr	Street Address	GO95
11841 Chamonix Rd	Street Address	GO95
13119 Falcon Point Pl	Street Address	GO95
12688 Falcon Point Pl	Street Address	GO95
11702 Chamonix Rd	Street Address	GO95
12931 Falcon Point Pl	Street Address	GO95
11851 Saint Bernard Dr	Street Address	GO95
14366 Copenhagen Dr	Street Address	GO95
14590 Copenhagen Dr	Street Address	GO95
14737 Copenhagen Dr	Street Address	GO95
11261 Mougle Ln	Street Address	GO95
12020 Bennett Flat Rd	Street Address	GO95
13177 Davos Dr	Street Address	GO95
13039 Davos Dr	Street Address	GO95
11400 Chamonix Rd	Street Address	GO95
12870 Northwoods Blvd	Street Address	GO95
13707 Northwoods Blvd	Street Address	GO95
10512 Mougle Ln	Street Address	GO95
10865 Mougle Ln	Street Address	GO95
16606 Ski Slope Way	Street Address	GO95
12579 Bear Meadow Ct	Street Address	GO95
11306 Zermatt Dr	Street Address	GO95
16949 Northwoods Blvd	Street Address	GO95
11006 K T Dr	Street Address	GO95
11048 K T Dr	Street Address	GO95
12605 Ski Slope Way	Street Address	GO95
16565 Northwoods Blvd	Street Address	GO95
10424 E Alder Creek Rd	Street Address	GO95
10579 Foxmead Ln	Street Address	GO95
I-80 W	Pole Address	GO95
10068 Hirschdale Rd	Pole Address	GO95
10570 Iris Rd	Street Address	GO95
12098 Pine Forest Rd	Street Address	GO95

12139 Pine Forest Rd	Street Address	GO95
12100 Lariat Ln	Street Address	GO95
12050 Lariat Ln	Street Address	GO95
10297 Jeffrey Way	Street Address	GO95
12468 Greenwood Dr	Street Address	GO95
12592 Greenwood Dr	Street Address	GO95
12660 Madrone Ln	Street Address	GO95
11525 Silverfir Dr	Pole Address	GO95
11642 Silverfir Dr	Street Address	GO95
11902 Rio Vista Dr	Street Address	GO95
Alder Creek Rd	Street Address	GO95
12296 Deerfield Dr	Street Address	GO95
12296 Deerfield Dr	Street Address	GO95
10098 E Alder Creek Rd	Street Address	GO95
10557 Foxmead Ln	Pole Address	GO95
10371 E Alder Creek Rd	Street Address	GO95
11166 Donner Pass Rd	Street Address	GO95
11061 Spring Ln	Street Address	GO95
12381 Ski Slope Way	Street Address	GO95
13945 Herringbone Way	Street Address	GO95
13285 Davos Dr	Street Address	GO95
10448 Teton Way	Street Address	GO95
Slalom Way	Street Address	GO95
22195 Spruce St	Street Address	GO95
10423 Lenelle Ln	Street Address	GO95
9908 River Rd	Street Address	GO95
19021 W River St	Street Address	GO95
12420 Rainbow Dr	Street Address	GO95
11054 Whitehorse Rd	Street Address	GO95
10581 Martis Valley Rd	Street Address	GO95
11420 Lockwood Dr	Street Address	GO95
11131 Beacon Rd	Street Address	GO95
11012 Beacon Rd	Street Address	GO95
11190 Barnes Dr	Street Address	GO95
10481 Pine Cone Dr	Street Address	GO95
10322 Prosser Dr	Street Address	GO95
12948 Dulzura St	Street Address	GO95
11746 Kitzbuhel Rd	Street Address	GO95
11854 Kitzbuhel Rd	Street Address	GO95
12931 Dulzura St	Street Address	GO95
11719 Kitzbuhel Rd	Street Address	GO95
12804 Rainbow Dr	Street Address	GO95
12169 Stallion Way	Pole Address	GO95
12134 Stallion Way	Pole Address	GO95

10571 Rosa Ct	Street Address	GO95
10732 Martis Dr	Street Address	GO95
15845 Archery View	Street Address	GO95
11851 Whitehorse Rd	Pole Address	GO95
11121 Huntsman Leap	Street Address	GO95
15636 Colt Ct	Pole Address	GO95
10792 Pine Cone Dr	Street Address	GO95
12371 Snow Shoe Ct	Street Address	GO95
10884 Silverfir Dr	Pole Address	GO95
10815 Snowflower Ct	Street Address	GO95
10851 Silverfir Dr	Street Address	GO95
10499 Snow Shoe Circle	Street Address	GO95
15450 Donnington Ln	Street Address	GO95
10830 Barnes Dr	Street Address	GO95
10867 Cheyenne Way	Street Address	GO95
10558 Stuart Staithe	Street Address	GO95
11928 Rio Vista Dr	Street Address	GO95
10423 Palisades Dr	Street Address	GO95
10416 Palisades Dr	Pole Address	GO95
10419 Briar Circle	Street Address	GO95
10431 Briar Circle	Street Address	GO95
11737 Deerfield Dr	Street Address	GO95
11675 Deerfield Dr	Street Address	GO95
11605 Deerfield Dr	Street Address	GO95
11880 Deerfield Dr	Street Address	GO95
15730 Windsor Way	Pole Address	GO95
15664 Sherwood Dr	Street Address	GO95
11480 Glen Rd	Street Address	GO95
10418 Beckett Pl	Pole Address	GO95
16139 Lancaster Pl	Pole Address	GO95
12298 Lemon Ct	Street Address	GO95
10040 Alder Creek Rd	Street Address	GO95
15301 S Shore Dr	Street Address	GO95
15370 Conifer Dr	Street Address	GO95
14646 Red Mountain Rd	Street Address	GO95
14591 Red Mountain Rd	Street Address	GO95
14595 S Shore Dr	Street Address	GO95
15500 S Shore Dr	Street Address	GO95
14618 S Shore Dr	Street Address	GO95
14376 S Shore Dr	Street Address	GO95
12346 Pine Forest Rd	Street Address	GO95
12346 Pine Forest Rd	Street Address	GO95
10769 Martis Dr	Street Address	GO95
10809 Martis Dr	Street Address	GO95

10829 Martis Dr	Street Address	GO95
22187 Tamarack St	Street Address	GO95
6780-68 River Rd	Street Address	GO95
10053 Olympic Blvd	Street Address	GO95
10053 Olympic Blvd	Street Address	GO95
11700 Kayhoe Ct	Pole Address	GO95
10115 Olympic Blvd	Street Address	GO95
11463 Highland Ave	Street Address	GO95
10438 Olympic Blvd	Pole Address	GO95
11662 Highland Ave	Street Address	GO95
10019 Floriston Ct	Street Address	GO95
10529 Evensham Pl	Street Address	GO95
10457 Evensham Pl	Street Address	GO95
10339 Briar Circle	Street Address	GO95
11874 Rainbow Dr	Street Address	GO95
11940 Pine Forest Rd	Street Address	GO95
12022 Pine Forest Rd	Street Address	GO95
10296 Brockway Rd	Street Address	GO95
6210 River Rd	Street Address	GO95
7880 River Rd	Street Address	GO95
11298 Bennett Flat Rd	Street Address	GO95
16204 Edinburgh Dr	Street Address	GO95
15364 Donner Pass Rd	Street Address	GO95
15404 Donner Pass Rd	Street Address	GO95
13093 Moraine Rd	Street Address	GO95
13424 Moraine Rd	Street Address	GO95
13604 Moraine Rd	Street Address	GO95
12349 Ski Slope Way	Street Address	GO95
10316 Olympic Blvd	Pole Address	GO95
11908 Highland Ave	Street Address	GO95
11878 Highland Ave	Street Address	GO95
11893 Highland Ave	Street Address	GO95
12454 Prosser Dam Rd	Street Address	GO95
11330 Skyline Ct	Street Address	GO95
10792 Aspenwood Rd	Pole Address	GO95
10792 Aspenwood Rd	Street Address	GO95
15417 Archery View	Street Address	GO95
10851 Whitehorse Rd	Street Address	GO95
15352 Crown Circle	Street Address	GO95
11146 Alder Dr	Street Address	GO95
15326 Waterloo Circle	Street Address	GO95
10374 Manchester Dr	Pole Address	GO95
11264 Star Pine Rd	Street Address	GO95
7874 River Rd	Street Address	GO95

11735 Bennett Flat Rd	Street Address	GO95
13821 Donner Pass Rd	Street Address	GO95
11955 Deerfield Dr	Pole Address	GO95
10096 Oriole Ln	Street Address	GO95
14210 Donner Ave	Street Address	GO95
14945 Pioneer Dr	Street Address	GO95
14570 Donner Ave	Street Address	GO95
14814 Donner Pass Rd	Street Address	GO95
15600 Donner Pass Rd	Street Address	GO95
11683 Bennett Flat Rd	Street Address	GO95
10266 Cromley Sq	Street Address	GO95
14909 Glenshire Dr	Pole Address	GO95
10553 Stone Pine Rd	Pole Address	GO95
10442 Stone Pine Rd	Street Address	GO95
11399 Beacon Rd	Street Address	GO95
10165 Columbine Rd	Pole Address	GO95
10240 Columbine Rd	Street Address	GO95
10245 Shore Pine Rd	Street Address	GO95
11609 Redbud Ct	Street Address	GO95
11734 Nordic Ln	Street Address	GO95
11695 Lausanne Way	Street Address	GO95
11641 Lausanne Way	Street Address	GO95
16471 Glenshire Dr	Street Address	GO95
12018 Kitzbuhel Rd	Street Address	GO95
11261 Alder Dr	Street Address	GO95
11310 Alder Dr	Street Address	GO95
11776 Mougle Ln	Street Address	GO95
12292 Brookstone Dr	Street Address	GO95
12244 Greenleaf Way	Street Address	GO95
13824 Hansel Ave	Street Address	GO95
13971 Hansel Ave	Street Address	GO95
10056 Sierra Ave	Street Address	GO95
11109 Donner Pass Rd	Street Address	GO95
11300 Donner Way	Street Address	GO95
11536 Tinkers Landing	Street Address	GO95
12260 Greenwood Dr	Street Address	GO95
14210 S Shore Dr	Street Address	GO95
14186 S Shore Dr	Street Address	GO95
10620 Washoe Rd	Street Address	GO95
16232 Old Highway Dr	Street Address	GO95
15963 S Shore Dr	Street Address	GO95
12650 Glenshire Dr	Street Address	GO95
12254 Richards Blvd	Pole Address	GO95
60571-60599 Mountain Creek Bri	Street Address	GO95

420 Main St	Street Address	GO95
160 Pearl St	Street Address	GO95
204 Durgan Flat St	Street Address	GO95
303 Durgan Flat St	Street Address	GO95
141 Belle St	Street Address	GO95
151 Galloway St	Street Address	GO95
942 Old Toll Bridge Rd	Street Address	GO95
15921 State Highway 49	Street Address	GO95
15921 State Highway 49	Street Address	GO95
942 Old Toll Bridge Rd	Street Address	GO95
1060 Old Toll Bridge Rd	Street Address	GO95
1064 Old Toll Bridge Rd	Street Address	GO95
251 Goodyear Creek Rd	Street Address	GO95
335 Goodyear Creek Rd	Street Address	GO95
303 Goodyear Creek Rd	Street Address	GO95
15 Busch St	Street Address	GO95
121 Wild Plum Rd	Street Address	GO95
358 Lincoln St	Pole Address	GO95
597 Old Truckee Rd	Street Address	GO95
618 Old Truckee Rd	Street Address	GO95
211 Edna Dr	Street Address	GO95
34310 Alta Bonnynook Rd	Street Address	GO95
34055 Towle Hill Rd	Street Address	GO95
33883 Rail Fence Rd	Street Address	GO95
33758 Rail Fence Rd	Street Address	GO95
39110 Kearsarge Mill Rd	Street Address	GO95
684 Alta Powerhouse Rd	Street Address	GO95
32306 Ridge Rd	Street Address	GO95
449 Sacramento St	Street Address	GO95
627 Sacramento St	Street Address	GO95
34066 Casa Loma Rd	Pole Address	GO95
28100 Magra Rd	Street Address	GO95
40225 Airport Rd	Street Address	GO95
33695 Main St	Street Address	GO95
33525 Main St	Street Address	GO95
762 Blue Canyon Rd	Street Address	GO95
3 Woolley Rd	Street Address	GO95
44200 State Highway 20	Street Address	GO95
650 Caine Rd	Street Address	GO95
580 Blue Canyon Rd	Pole Address	GO95
1 Fulda Rd	Street Address	GO95
41158 Skyline Dr	Street Address	GO95
34648 Trail End Ct	Street Address	GO95
12655 Zeibright Rd	Street Address	GO95

12655 Zeibright Rd	Street Address	GO95
33150 Ridge Rd	Street Address	GO95
42200 Nyack Rd	Street Address	GO95
300 Canyon Mine Rd	Street Address	GO95
12764 Zeibright Rd	Street Address	GO95
34735 E Towle Rd	Street Address	GO95
573 Lee Rd	Street Address	GO95
573 Lee Rd	Street Address	GO95
167 W Towle Rd	Street Address	GO95
127 W Towle Rd	Street Address	GO95
105 W Towle Rd	Pole Address	GO95
34105 Alta Bonnynook Rd	Street Address	GO95
34055 Towle Hill Rd	Street Address	GO95
27398 Cape Horn Rd	Street Address	GO95
27301 Norton Grade Rd	Street Address	GO95
17598 Chicago Park Powerhouse	Street Address	GO95
1299 Alta Powerhouse Rd	Street Address	GO95
37500 KEARSARGE MILL	Street Address	GO95
I-80 W	Street Address	GO95
I-80 W	Street Address	GO95
32362 Monte Vista Ln	Street Address	GO95
32355 Lincoln Rd	Street Address	GO95
725 Alta Reservoir Rd	Pole Address	GO95
940 Alta Reservoir Rd	Pole Address	GO95
36000 Finn Ln	Street Address	GO95
34950 Culberson Rd	Pole Address	GO95
1268 Garrett Rd	Street Address	GO95
41448 Putt Rd	Pole Address	GO95
41390 Putt Rd	Pole Address	GO95
41340 Putt Rd	Street Address	GO95
34484 Little Bear Creek Ln	Pole Address	GO95
34645 Little Bear Creek Ln	Pole Address	GO95
34377 E Towle Rd	Pole Address	GO95
110 Bonnynook Rd	Street Address	GO95
11112 Bowman Lake Rd	Street Address	GO95
12726 Bowman Lake Rd	Street Address	GO95
14783 Bowman Lake Rd	Street Address	GO95
36515 Grouse Ridge Rd	Pole Address	GO95
510 Kearsarge Ct	Pole Address	GO95
500 Kearsarge Ct	Pole Address	GO95
545 Kearsarge Ct	Pole Address	GO95
505 Kearsarge Ct	Street Address	GO95
38625 Kearsarge Mill Rd	Pole Address	GO95
38625 Kearsarge Mill Rd	Street Address	GO95

449 Sacramento St	Street Address	GO95
32367 Squire Canyon Ln	Street Address	GO95
42600 Texas Hill Rd	Street Address	GO95
8790 La Porte Rd	Pole Address	GO95
8749 La Porte Rd	Pole Address	GO95
9110 Nero Rd	Street Address	GO95
8959 Nero Rd	Pole Address	GO95
12353 La Porte Rd	Street Address	GO95
12338 La Porte Rd	Street Address	GO95
12326 La Porte Rd	Street Address	GO95
2181 La Porte Rd	Street Address	GO95
5773 Forbestown Rd	Street Address	GO95
5699 Forbestown Rd	Street Address	GO95
19721 Mount Hope Rd	Street Address	GO95
9188 La Porte Rd	Pole Address	GO95
5389 Forbestown Rd	Street Address	GO95
9246 La Porte Rd	Pole Address	GO95
5823 Forbestown Rd	Street Address	GO95
9381 La Porte Rd	Street Address	GO95
241 Old Forbestown Rd	Street Address	GO95
9466 Forsythe Rd	Street Address	GO95
5 Westar Ct	Street Address	GO95
16772 New York House Rd	Street Address	GO95
18896 New York Flat Rd	Street Address	GO95
9683 La Porte Rd	Street Address	GO95
9639 La Porte Rd	Street Address	GO95
12725 La Porte Rd	Street Address	GO95
18968 New York Flat Rd	Street Address	GO95
19114 New York Flat Rd	Street Address	GO95
25 Cloverleaf Ln	Street Address	GO95
12791 La Porte Rd	Street Address	GO95
102 Big Fur Rd	Street Address	GO95
9111 Red Bud	Street Address	GO95
19452 Forbestown Rd	Street Address	GO95
9683 La Porte Rd	Street Address	GO95
9214 La Porte Rd	Street Address	GO95
9414 La Porte Rd	Street Address	GO95
19721 Mount Hope Rd	Street Address	GO95
9204 La Porte Rd	Pole Address	GO95
5530 Forbestown Rd	Street Address	GO95
15822 Willow Glen Rd	Pole Address	GO95
15887 Willow Glen Rd	Street Address	GO95
16592 Willow Glen Rd	Street Address	GO95
258 Tamarack Way	Street Address	GO95

16408 Frenchtown Rd	Street Address	GO95
16373 Frenchtown Rd	Street Address	GO95
16052 Frenchtown Rd	Street Address	GO95
15234 Frenchtown Rd	Street Address	GO95
11670 La Porte Rd	Street Address	GO95
8899 Frenchtown Ext	Street Address	GO95
17759 New York House Rd	Street Address	GO95
18092 Joy Circle	Street Address	GO95
11875 Moran Rd	Street Address	GO95
680 W Plumas Ave	Street Address	GO95
13002 Golden Eagle Way	Pole Address	GO95
16525 Meadow Way	Pole Address	GO95
16525 Meadow Way	Street Address	GO95
11402 Idaho Maryland Rd	Street Address	GO95
16932 Lawrence Way	Pole Address	GO95
16965 Lawrence Way	Pole Address	GO95
13883 Rattlesnake Rd	Street Address	GO95
13131 Sunshine Valley Rd	Street Address	GO95
16176 Raylene Ct	Street Address	GO95
18938 Saint Paul Pl	Pole Address	GO95
11754 Ragan Way	Street Address	GO95
14605 Clover Ridge Ln	Street Address	GO95
12182 Francis Dr	Street Address	GO95
12263 Elizabeth Way	Street Address	GO95
12301 Elizabeth Way	Street Address	GO95
18766 Old Coach Way	Street Address	GO95
18766 Old Coach Way	Pole Address	GO95
12695 Rough and Ready Hwy	Street Address	GO95
720 S Auburn St	Street Address	GO95
16142 Tina Ct	Pole Address	GO95
17832 Norlene Way	Street Address	GO95
15248 Carrie Dr	Pole Address	GO95
15248 Carrie Dr	Street Address	GO95
15101 Apple Blossom Way	Pole Address	GO95
15166 Moore Hill Rd	Pole Address	GO95
15247 Claim Jumper Ln	Pole Address	GO95
12685 Rough and Ready Hwy	Street Address	GO95
11460 Arabian Ranch Pl	Street Address	GO95
15756 Rattlesnake Rd	Street Address	GO95
10650 Dixon Rd	Street Address	GO95
18910 Connie Dr	Pole Address	GO95
10595 Dixon Rd	Street Address	GO95
10595 Dixon Rd	Street Address	GO95
16297 David Way	Street Address	GO95

10731 Footwall Dr	Street Address	GO95
10836 Footwall Dr	Street Address	GO95
17110 Norlene Way	Pole Address	GO95
17241 Norlene Way	Pole Address	GO95
16985 Lawrence Way	Street Address	GO95
16870 Alioto Dr	Pole Address	GO95
16816 Alioto Dr	Pole Address	GO95
16142 Sharon Way	Pole Address	GO95
11884 Tammy Way	Pole Address	GO95
14556 Powerline Rd	Street Address	GO95
10126 Bitney Springs Rd	Street Address	GO95
15038 Barlow Ct	Pole Address	GO95
12956 Rattlesnake Rd	Street Address	GO95
14128 Highland Dr	Street Address	GO95
14651 Storm Ridge Rd	Pole Address	GO95
15721 Shebley Rd	Street Address	GO95
15658 Shebley Rd	Street Address	GO95
16784 Oscar Dr	Pole Address	GO95
16725 Oscar Dr	Pole Address	GO95
15462 Lorie Dr	Pole Address	GO95
15330 Orchard Springs Rd	Street Address	GO95
15232 Orchard Springs Rd	Pole Address	GO95
12728 Rattlesnake Rd	Street Address	GO95
12126 McCourtney Rd	Street Address	GO95
10565 Douglas Ln	Street Address	GO95
16488 Lower Colfax Rd	Pole Address	GO95
17766 Wolf Mountain Rd	Street Address	GO95
16966 Aileen Way	Street Address	GO95
16966 Aileen Way	Street Address	GO95
16683 Aileen Way	Street Address	GO95
16851 Oscar Dr	Pole Address	GO95
17074 Oscar Dr	Pole Address	GO95
17113 Oscar Dr	Street Address	GO95
16964 Oscar Dr	Pole Address	GO95
15269 Orchard Springs Rd	Pole Address	GO95
15269 Orchard Springs Rd	Street Address	GO95
15496 Marina Dr	Street Address	GO95
15474 Marina Dr	Street Address	GO95
15474 Marina Dr	Street Address	GO95
13895 Colfax Hwy	Street Address	GO95
McCourtney Rd	Pole Address	GO95
16779 Indian Hill Circle	Pole Address	GO95
14116 Judy Ln	Street Address	GO95
13785 Manion Canyon Rd	Pole Address	GO95

17015 Oscar Dr	Street Address	GO95
17722 Oak Way	Pole Address	GO95
17241 Virginia Way	Street Address	GO95
10552 Bragg Ave	Pole Address	GO95
17403 Alexandra Way	Street Address	GO95
17403 Alexandra Way	Pole Address	GO95
17598 Alexandra Way	Street Address	GO95
17615 Rollins View Dr	Pole Address	GO95
14279 Ryans Ranch Rd	Street Address	GO95
18014 Alexandra Way	Street Address	GO95
16215 Sharon Way	Pole Address	GO95
16269 Sharon Way	Street Address	GO95
16218 Sharon Way	Pole Address	GO95
16218 Sharon Way	Street Address	GO95
13049 Greenhorn Rd	Street Address	GO95
16399 Sharon Way	Pole Address	GO95
13055 La Barr Meadows Rd	Street Address	GO95
19919 Casa Loma Dr	Street Address	GO95
11486 Lower Colfax Rd	Street Address	GO95
13528 Brooks Rd	Street Address	GO95
12732 Squirrel Creek Rd	Pole Address	GO95
13091 Idaho Maryland Rd	Street Address	GO95
125 E Empire St	Street Address	GO95
11758 Tammy Way	Pole Address	GO95
11685 Tammy Way	Pole Address	GO95
15619 Orchard Springs Rd	Street Address	GO95
15487 Lakeview Dr	Street Address	GO95
15411 Lakeview Dr	Street Address	GO95
17386 Virginia Way	Street Address	GO95
17435 Virginia Way	Street Address	GO95
10906 Yukon Way	Street Address	GO95
18206 Spring Valley Dr	Pole Address	GO95
18206 Spring Valley Dr	Street Address	GO95
11369 Michael Way	Pole Address	GO95
535 Richardson St	Street Address	GO95
10943 Yukon Way	Street Address	GO95
17089 Old State Hwy	Street Address	GO95
17089 Old State Hwy	Street Address	GO95
18142 Wallis Dr	Pole Address	GO95
15389 Gary Way	Street Address	GO95
15374 Georges Meadows	Street Address	GO95
15127 Chattering Pines Rd	Pole Address	GO95
14979 Chattering Pines Rd	Street Address	GO95
15066 Chattering Pines Rd	Street Address	GO95

768 Woodland Way	Street Address	GO95
11961 Slate Creek Rd	Street Address	GO95
11742 Slate Creek Rd	Street Address	GO95
17060 Alexandra Way	Street Address	GO95
12845 Francis Dr	Street Address	GO95
12808 Francis Dr	Street Address	GO95
17472 Troy Ct	Street Address	GO95
17089 Old State Hwy	Street Address	GO95
15380 Chattering Pines Rd	Pole Address	GO95
2153 Nevada City Hwy	Street Address	GO95
2297 Nevada City Hwy	Street Address	GO95
2322 Nevada City Hwy	Street Address	GO95
2153 Nevada City Hwy	Street Address	GO95
19598 Tiger Lily Ln	Street Address	GO95
10682 Quail Creek Rd	Street Address	GO95
10395 Quail Creek Rd	Street Address	GO95
10947 Round Valley Rd	Street Address	GO95
10800 Round Valley Rd	Street Address	GO95
15318 Little Pines Rd	Street Address	GO95
14139 Metz Ranch Rd	Street Address	GO95
150 Apple Ave	Street Address	GO95
265 W Olympia Dr	Street Address	GO95
12786 S Ponderosa Way	Street Address	GO95
10478 Waterford Pl	Street Address	GO95
21324 Oak Ridge Dr	Street Address	GO95
17454 Echo Valley Dr	Street Address	GO95
14827 Lakewood Ln	Street Address	GO95
15791 Lakewood Ln	Street Address	GO95
13773 Squirrel Creek Rd	Street Address	GO95
17652 Shadow Pines Dr	Street Address	GO95
15033 Brooks Rd	Street Address	GO95
13751 Roundhouse Ct	Pole Address	GO95
14249 Lost Lake Rd	Street Address	GO95
15474 Marina Dr	Pole Address	GO95
13950 Lost Lake Rd	Street Address	GO95
13911 Peardale Ln	Street Address	GO95
15156 Orchard Springs Rd	Pole Address	GO95
11261 Pekolee Dr	Street Address	GO95
16984 Scott Way	Pole Address	GO95
16883 Scott Way	Street Address	GO95
15625 Lakewood Ln	Street Address	GO95
15455 Lakewood Ln	Pole Address	GO95
14132 Manion Canyon Rd	Street Address	GO95
14314 Manion Canyon Rd	Pole Address	GO95

14292 Colfax Hwy	Street Address	GO95
13871 Highland Dr	Street Address	GO95
14421 You Bet Rd	Street Address	GO95
18471 Reese Ln	Street Address	GO95
14285 You Bet Rd	Street Address	GO95
20604 McCourtney Rd	Street Address	GO95
11218 Agnes Way	Pole Address	GO95
312 Colfax Ave	Street Address	GO95
408 Colfax Ave	Street Address	GO95
17495 Anona Ct	Street Address	GO95
15159 Lakewood Ln	Street Address	GO95
11607 View Dr	Street Address	GO95
15012 Lakewood Ln	Pole Address	GO95
17027 Lawrence Way	Pole Address	GO95
311 Hughes Rd	Street Address	GO95
12876 Lost Lake Rd	Pole Address	GO95
235 Bresee Pl	Street Address	GO95
12915 Lost Lake Rd	Street Address	GO95
13508 Brooks Rd	Street Address	GO95
16281 Mount Olive Rd	Pole Address	GO95
16065 Mount Olive Rd	Pole Address	GO95
15390 Birch Meadows Circle	Street Address	GO95
15959 Mount Olive Rd	Pole Address	GO95
18616 Norlene Way	Pole Address	GO95
13499 Sunshine Meadows Trail	Pole Address	GO95
16433 Kiwi Rd	Pole Address	GO95
16343 Auburn Rd	Pole Address	GO95
18006 Oak Way	Pole Address	GO95
17878 Maple Way	Street Address	GO95
14013 Birch Rd	Street Address	GO95
12784 Madrone Forest Dr	Street Address	GO95
17082 Alioto Dr	Pole Address	GO95
16927 Angelina Way	Pole Address	GO95
16647 Alioto Dr	Pole Address	GO95
16708 Alioto Dr	Pole Address	GO95
16998 Alioto Dr	Pole Address	GO95
17252 Blum Rd	Pole Address	GO95
15865 Mount Olive Rd	Street Address	GO95
11098 Wheeler Cross Rd	Street Address	GO95
15630 Mount Olive Rd	Pole Address	GO95
18938 Saint Paul Pl	Street Address	GO95
18701 End Three Ln	Pole Address	GO95
15594 Del Vista Ct	Street Address	GO95
13649 Lupine Ct	Street Address	GO95

18545 Cactus Ln	Pole Address	GO95
18570 Cactus Ln	Street Address	GO95
17040 Round Valley Circle	Pole Address	GO95
18240 Old Coach Way	Street Address	GO95
17202 Bivens Pl	Street Address	GO95
10189 Shady Oak Pl	Street Address	GO95
10189 Shady Oak Pl	Street Address	GO95
13348 Grass Valley Ave	Street Address	GO95
14130 Liquidambar Ln	Street Address	GO95
18638 McCourtney Rd	Street Address	GO95
11363 Cedar Ridge Dr	Street Address	GO95
11363 Cedar Ridge Dr	Street Address	GO95
12328 Rough and Ready Hwy	Street Address	GO95
13055 Blue Jay Hill Rd	Street Address	GO95
15252 Clover Valley Rd	Pole Address	GO95
12291 Kenneth Ct	Street Address	GO95
13289 Lower Anchor Ln	Street Address	GO95
14451 Little Hill Ln	Street Address	GO95
13036 Capitol Dr	Pole Address	GO95
14621 Cherokee Ln	Street Address	GO95
14000 Arrowhead Mine Rd	Pole Address	GO95
13992 Arrowhead Mine Rd	Street Address	GO95
16829 Indian Hill Circle	Pole Address	GO95
13226 Greenhorn Rd	Street Address	GO95
10475 Alta St	Street Address	GO95
10687 Alta St	Street Address	GO95
10400 Alta St	Street Address	GO95
14185 Sontag Hill Rd	Pole Address	GO95
14580 Oak Leaf Ln	Street Address	GO95
15833 Kitkitdizze Dr	Pole Address	GO95
11478 Avern Way	Street Address	GO95
12933 Cedar Crest Ln	Street Address	GO95
15575 Kitkitdizze Dr	Pole Address	GO95
15689 Strawberry Ln	Pole Address	GO95
13083 Wild Life Ln	Pole Address	GO95
13036 Capitol Dr	Street Address	GO95
13271 Lower Anchor Ln	Pole Address	GO95
14972 Carrie Dr	Street Address	GO95
15708 You Bet Rd	Pole Address	GO95
14155 Thoroughbred Loop	Street Address	GO95
10975 Will O Wisp Ct	Street Address	GO95
11244 Lone Lobo Trail	Pole Address	GO95
13440 Jones Bar Rd	Street Address	GO95
12281 Madrona Way	Street Address	GO95

13977 Cameo Ln	Street Address	GO95
846 Forest Glade Circle	Street Address	GO95
840 Forest Glade Circle	Street Address	GO95
11422 Avern Way	Pole Address	GO95
14585 Fifield Rd	Pole Address	GO95
14585 Fifield Rd	Street Address	GO95
14477 Makikuja Dr	Pole Address	GO95
15088 Lorie Dr	Pole Address	GO95
15120 Fay Rd	Pole Address	GO95
15488 You Bet Rd	Pole Address	GO95
11892 Paradise Ln	Street Address	GO95
16148 You Bet Rd	Pole Address	GO95
16800 You Bet Rd	Pole Address	GO95
21498 You Bet Rd	Street Address	GO95
13556 Crawford Ln	Street Address	GO95
20588 You Bet Rd	Street Address	GO95
20625 You Bet Rd	Pole Address	GO95
13680 Bitney Springs Rd	Pole Address	GO95
13804 Bitney Springs Rd	Pole Address	GO95
13422 N Ponderosa Way	Pole Address	GO95
13846 Gold Fork Rd	Pole Address	GO95
13717 Witt Ln	Pole Address	GO95
13422 N Ponderosa Way	Pole Address	GO95
13422 N Ponderosa Way	Pole Address	GO95
14614 Bitney Springs Rd	Street Address	GO95
12332 Madrona Way	Street Address	GO95
12200 Cascade Way	Street Address	GO95
14527 Rough and Ready Hwy	Street Address	GO95
115 Grey Owl Ct	Pole Address	GO95
578 Douglas Ave	Street Address	GO95
10856 Gold Hill Dr	Street Address	GO95
10890 Gold Hill Dr	Street Address	GO95
12771 Ridge Rd	Street Address	GO95
13747 Rough and Ready Hwy	Street Address	GO95
13670 Capitol Dr	Pole Address	GO95
13036 Capitol Dr	Pole Address	GO95
14909 Kelsey Ln	Pole Address	GO95
14909 Kelsey Ln	Street Address	GO95
19164 Wolf Creek Rd	Street Address	GO95
13601 Clancy Way	Street Address	GO95
13353 Peardale Rd	Street Address	GO95
14369 Greenpeace Ln	Pole Address	GO95
16890 You Bet Rd	Pole Address	GO95
16876 You Bet Rd	Street Address	GO95

13572 Mule Canyon Rd	Street Address	GO95
16236 Inyokern Way	Street Address	GO95
16481 Inyokern Way	Pole Address	GO95
17223 You Bet Rd	Pole Address	GO95
12312 Polaris Dr	Pole Address	GO95
14163 Jokers Wild Ln	Pole Address	GO95
15318 Lower Colfax Rd	Street Address	GO95
101 Leahy Rd	Street Address	GO95
405 E Main St	Street Address	GO95
11220 Bitney Springs Rd	Street Address	GO95
13504 Empress Rd	Street Address	GO95
13194 Kentucky Flat Rd	Street Address	GO95
11823 Lost Ranch Way	Pole Address	GO95
13985 Holland Dr	Street Address	GO95
14153 Lily Creek Trail	Pole Address	GO95
14266 Indian Springs Rd	Street Address	GO95
12941 Wild Rose Ct	Pole Address	GO95
12638 Wild Rose Ct	Street Address	GO95
14431 Greenhorn Access Rd	Pole Address	GO95
14620 Rollins Park Dr	Pole Address	GO95
13071 Colfax Hwy	Street Address	GO95
13856 Seven Cedars Dr	Pole Address	GO95
17354 Brewer Rd	Pole Address	GO95
11120 Glen Loop	Street Address	GO95
14727 Sontag Rd	Street Address	GO95
10073 Westhill Rd	Street Address	GO95
11588 Shockley Rd	Pole Address	GO95
11460 Squirrel Creek Rd	Street Address	GO95
10455 Robin Ave	Pole Address	GO95
10555 No Name Dr	Pole Address	GO95
10343 Robin Ave	Street Address	GO95
11580 Crestwood St	Street Address	GO95
11046 Nugget Ln	Pole Address	GO95
10161 Owl Rd	Street Address	GO95
17188 Lawton Way	Street Address	GO95
18788 You Bet Rd	Street Address	GO95
13613 Old Emigrant Trail	Pole Address	GO95
13613 Old Emigrant Trail	Street Address	GO95
13831 Old Emigrant Trail	Pole Address	GO95
18987 You Bet Rd	Pole Address	GO95
13690 Hopeful Hill Rd	Pole Address	GO95
13502 Hopeful Hill Rd	Street Address	GO95
12826 Newtown Rd	Pole Address	GO95
14564 Indian Springs Rd	Street Address	GO95

13421 Rocky Rhodes Pl	Street Address	GO95
14219 Rollins Park Dr	Pole Address	GO95
14446 Rollins Park Dr	Street Address	GO95
15543 Wolf Mountain Rd	Street Address	GO95
14433 Dalmatian Dr	Pole Address	GO95
14598 Dalmatian Dr	Pole Address	GO95
17082 Brewer Rd	Street Address	GO95
16960 Brewer Rd	Street Address	GO95
11355 Brunswick Dr	Street Address	GO95
11257 Brunswick Dr	Street Address	GO95
12719 Colfax Hwy	Street Address	GO95
14527 Rough and Ready Hwy	Street Address	GO95
10665 Cedar Way	Street Address	GO95
10942 Sunrise Heights	Street Address	GO95
13120 Loma Rica Dr	Street Address	GO95
10104 Westhill Rd	Street Address	GO95
10104 Westhill Rd	Street Address	GO95
13059 John Bauer Ave	Street Address	GO95
12908 Loma Rica Dr	Street Address	GO95
550 Ivy St	Pole Address	GO95
412 Linden Ave	Street Address	GO95
15365 Zinfandel Ln	Street Address	GO95
10290 Gold Dr	Pole Address	GO95
10548 Cedar Ave	Street Address	GO95
11243 Squirrel Creek Rd	Street Address	GO95
13146 Hidden Valley Rd	Pole Address	GO95
236 N Church St	Street Address	GO95
10701 Walker Dr	Street Address	GO95
10606 Walker Dr	Street Address	GO95
11320 Alpine Ln	Street Address	GO95
13175 Personeni Ln	Street Address	GO95
13073 Woolman Ln	Street Address	GO95
10523 Tasha Rd	Street Address	GO95
12894 Greenhorn Rd	Street Address	GO95
12803 Macboyle Way	Street Address	GO95
15490 Clear Creek Pl	Street Address	GO95
11121 Cedar Ridge Dr	Street Address	GO95
11156 Cedar Ridge Dr	Street Address	GO95
14741 Dalmatian Dr	Pole Address	GO95
10038 Rough and Ready Rd	Street Address	GO95
11097 Brunswick Dr	Street Address	GO95
11025 Cedar Ridge Dr	Street Address	GO95
10904 Brunswick Rd	Street Address	GO95
10912 Canyon View Dr	Pole Address	GO95

10961 Cedar Way	Street Address	GO95
13173 Ridge Rd	Street Address	GO95
11292 Vista Ave	Street Address	GO95
13261 Ridge Rd	Street Address	GO95
10426 Carey Dr	Street Address	GO95
14570 Rough and Ready Hwy	Street Address	GO95
13368 Ridge Rd	Street Address	GO95
16006 Clover Valley Rd	Pole Address	GO95
14602 You Bet Rd	Pole Address	GO95
13528 Fawn Hill Dr	Street Address	GO95
14107 Sontag Rd	Street Address	GO95
14030 Sontag Rd	Pole Address	GO95
18714 Wolf Creek Rd	Pole Address	GO95
18714 Wolf Creek Rd	Street Address	GO95
11163 Squirrel Creek Rd	Street Address	GO95
18451 Fay Ridge Ct	Pole Address	GO95
10781 Walker Dr	Street Address	GO95
110 Carpenter St	Street Address	GO95
20307 Red Dog Rd	Street Address	GO95
10583 Tasha Rd	Street Address	GO95
13205 Artic Owl Rd	Street Address	GO95
13509 Myers Pl	Street Address	GO95
12273 Jones Bar Rd	Street Address	GO95
12751 Kentucky Flat Rd	Street Address	GO95
13075 Woolman Ln	Street Address	GO95
12820 Woolman Ln	Pole Address	GO95
12959 Woolman Ln	Pole Address	GO95
12894 Woodlake Rd	Street Address	GO95
12538 Woodlake Rd	Street Address	GO95
12538 Woodlake Rd	Pole Address	GO95
14570 Rough and Ready Hwy	Street Address	GO95
13924 Day Spring Rd	Street Address	GO95
16091 John Way	Pole Address	GO95
16385 Clover Valley Rd	Pole Address	GO95
15971 John Way	Pole Address	GO95
11101 Rough and Ready Hwy	Street Address	GO95
11101 Rough and Ready Hwy	Street Address	GO95
18395 Wolf Creek Rd	Pole Address	GO95
11415 Rough and Ready Hwy	Street Address	GO95
10700 Mountaineer Trail	Street Address	GO95
14262 Meadow Dr	Street Address	GO95
10539 Oak St	Street Address	GO95
13530 Eowana Ln	Pole Address	GO95
807 W Main St	Street Address	GO95

13074 Woolman Ln	Street Address	GO95
155 Harris St	Street Address	GO95
348 E Main St	Street Address	GO95
152 Harris St	Street Address	GO95
11176 Glen Meadow Dr	Street Address	GO95
704 1/2 Butler St	Street Address	GO95
11117 Gibson Dr	Pole Address	GO95
11221 Glen Meadow Dr	Street Address	GO95
11203 Glen Meadow Dr	Street Address	GO95
15615 Luckie Rd	Pole Address	GO95
13206 McCarter Way	Pole Address	GO95
16378 Hound Dog Dr	Street Address	GO95
11866 Forest View Dr	Street Address	GO95
11398 Banner Lava Cap Rd	Street Address	GO95
11398 Banner Lava Cap Rd	Street Address	GO95
11649 Banner Lava Cap Rd	Street Address	GO95
14950 S Ponderosa Way	Pole Address	GO95
13892 Thoroughbred Loop	Pole Address	GO95
14826 You Win Ct	Pole Address	GO95
13655 Khalid Ct	Pole Address	GO95
16806 Greenhorn Rd	Street Address	GO95
14233 Thoroughbred Loop	Pole Address	GO95
14274 Rudd Rd	Pole Address	GO95
15050 Skaith Bend Rd	Street Address	GO95
15155 Skaith Bend Rd	Street Address	GO95
15606 Kardale Ct	Street Address	GO95
10500 Rex Reservoir Rd	Pole Address	GO95
10978 Bitney Springs Rd	Street Address	GO95
13136 White Canoe Ln	Street Address	GO95
10660 Douglas Ln	Pole Address	GO95
13865 Lost Trail	Street Address	GO95
12645 La Barr Meadows Rd	Street Address	GO95
40178-40226 CA-70	Street Address	GO95
970 Lake Davis Rd	Pole Address	GO95
660 Colorado St	Street Address	GO95
109 Virgilia Ave	Street Address	GO95
5685 Iron Horse Dr	Pole Address	GO95
241 Ladera Ln	Street Address	GO95
5323 Portola-McLears Rd	Pole Address	GO95
5846 IRON HORSE	Pole Address	GO95
6052 Semaphore Rd	Street Address	GO95
5878 Semaphore Rd	Pole Address	GO95
5878 Semaphore Rd	Pole Address	GO95
6105 SEMAPHORE	Pole Address	GO95

6143 Semaphore Rd	Pole Address	GO95
5600 Semaphore Rd	Street Address	GO95
73559 State Route 70	Street Address	GO95
76728 Sunset Dr	Pole Address	GO95
713 Wolf Ave	Street Address	GO95
713 Wolf Ave	Pole Address	GO95
678 Sagebrush St	Pole Address	GO95
675 Sagebrush St	Pole Address	GO95
74524 State Route 70	Pole Address	GO95
73783 S Delleker Rd	Pole Address	GO95
41413 Purdy Ln	Pole Address	GO95
42045 State Highway 70	Street Address	GO95
202 Spanish Creek Rd	Street Address	GO95
124 Spanish Creek Rd	Pole Address	GO95
41511 Wests Ranch Rd	Street Address	GO95
1977 Greenhorn Ranch Rd	Pole Address	GO95
1917 Greenhorn Ranch Rd	Pole Address	GO95
5847 Iron Horse Dr	Pole Address	GO95
5774 Casey Jones Rd	Pole Address	GO95
5576 Casey Jones Rd	Street Address	GO95
5915 Iron Horse Dr	Pole Address	GO95
6075 Crackerjack Creek Rd	Street Address	GO95
1970 Bucks Lake Rd	Pole Address	GO95
1919 Bucks Lake Rd	Pole Address	GO95
2176 Pine Cone Ln	Pole Address	GO95
2469 Greenhorn Ranch Rd	Pole Address	GO95
2675 Crooked Creek Ln	Pole Address	GO95
2648 Greenhorn Ranch Rd	Pole Address	GO95
2430 Greenhorn Ranch Rd	Pole Address	GO95
2530 Golden West Rd	Pole Address	GO95
2538 Greenhorn Ranch Rd	Pole Address	GO95
2481 Fountain Springs Ln	Street Address	GO95
2489 Fountain Springs Ln	Pole Address	GO95
560 Hillside Dr	Pole Address	GO95
2397 Running Springs Ln	Pole Address	GO95
2232 Buckhorn Trail	Pole Address	GO95
89 Delleker Dr	Pole Address	GO95
183 DELLEKER	Street Address	GO95
259 LADERA	Pole Address	GO95
328 Bella Vista Dr	Pole Address	GO95
254 Bella Vista Dr	Pole Address	GO95
302 Bella Vista Dr	Pole Address	GO95
286 Bella Vista Dr	Pole Address	GO95
200 Colina Ct	Pole Address	GO95

74509 State Route 70	Street Address	GO95
76601 Aspen Dr	Pole Address	GO95
815 Meadow Way	Pole Address	GO95
1260 Chandler Rd	Street Address	GO95
575 Quincy Junction Rd	Street Address	GO95
123 Sugar Pine Dr	Street Address	GO95
218 DELLEKER PARK	Pole Address	GO95
217 Portola-McLears Rd	Pole Address	GO95
306 BELLA VISTA	Pole Address	GO95
316 Bella Vista Dr	Pole Address	GO95
340 N Gulling St	Street Address	GO95
217 E Magnolia Ave	Street Address	GO95
355 Joy Way	Street Address	GO95
623 N Beckwith St	Street Address	GO95
276 Clarence Ln	Street Address	GO95
8071 Bucks Lake Rd	Street Address	GO95
31 S Mill Creek Rd	Pole Address	GO95
178 S Mill Creek Rd	Pole Address	GO95
1958 E Claremont Way	Street Address	GO95
127 Sierra Way	Pole Address	GO95
510 E Magnolia Ave	Pole Address	GO95
870 Ellen Ave	Street Address	GO95
80 W Mohawk Ave	Street Address	GO95
80 Reno Ave	Street Address	GO95
654 Lake Davis Rd	Pole Address	GO95
32160 Paxton Rd	Street Address	GO95
2525 Bucks Lake Rd	Street Address	GO95
2117 Mansell St	Street Address	GO95
2266 Bucks Lake Rd	Pole Address	GO95
77 1st St	Pole Address	GO95
73944 Old County Rd	Pole Address	GO95
76608 Aspen Dr	Pole Address	GO95
76687 Parkside Ter	Pole Address	GO95
76689 Parkside Terrace	Pole Address	GO95
76755 Rocky Point Rd	Pole Address	GO95
2025 E Claremont Way	Pole Address	GO95
240 Miller Rd	Pole Address	GO95
304 S Mill Creek Rd	Street Address	GO95
48 N Mill Creek Rd	Pole Address	GO95
62 N Mill Creek Rd	Street Address	GO95
2037 Lee Rd	Pole Address	GO95
1906 Lee Rd	Pole Address	GO95
47 Vierra Dr	Pole Address	GO95
116 Clough St	Street Address	GO95

23 Clough St	Street Address	GO95
746 Lee Rd	Street Address	GO95
670 Lee Rd	Pole Address	GO95
358 Bell Ln	Pole Address	GO95
730 Bresciani Circle	Street Address	GO95
86 S Lindan Ave	Street Address	GO95
852 Quincy Junction Rd	Street Address	GO95
72 Beskeen Ln	Street Address	GO95
41784 State Highway 70	Street Address	GO95
845 Quincy Junction Rd	Pole Address	GO95
41572 State Highway 70	Street Address	GO95
41548 State Highway 70	Street Address	GO95
48545 State Highway 70	Street Address	GO95
2125 Blackridge Trail	Pole Address	GO95
241 Ladera Ln	Pole Address	GO95
259 CUESTA	Pole Address	GO95
248 LADERA	Pole Address	GO95
165 5th St	Pole Address	GO95
2298 Mansell St	Pole Address	GO95
2210 Center St	Street Address	GO95
2086 Bucks Lake Rd	Street Address	GO95
2116 Bucks Lake Rd	Pole Address	GO95
2393 Bucks Lake Rd	Street Address	GO95
1991 Bucks Lake Rd	Street Address	GO95
119 Smithneck Rd	Street Address	GO95
623 Bear Valley Rd	Street Address	GO95
422 Rancho Circle Dr	Street Address	GO95
405005 Scott Rd	Pole Address	GO95
Sheep Ranch Rd	Pole Address	GO95
403505 SCOTT	Street Address	GO95
Country Ln	Street Address	GO95
752250 SCOTT	Street Address	GO95
Scott Rd	Street Address	GO95
957 W Sierra Brooks Dr	Street Address	GO95
937 W Sierra Brooks Dr	Street Address	GO95
515 Longhorn Dr	Pole Address	GO95
709 Roundup Dr	Pole Address	GO95
728 Roundup Dr	Pole Address	GO95
59 Mustang Trail	Pole Address	GO95
15780 Brooks Rd	Street Address	GO95
20362 Casa Loma Dr	Street Address	GO95

20362 Casa Loma Dr	Street Address	GO95
18047 Alexandra Way	Street Address	GO95
18047 Alexandra Way	Street Address	GO95
16525 Joey Ct	Street Address	GO95
12313 Crescent Dr	Street Address	GO95
12313 Crescent Dr	Street Address	GO95
14418-14450 Sontag Rd	Street Address	GO95
58448 Cedar Ln	Street Address	GO95
58913-58955 Old Stagecoach Rd	Street Address	GO95
11267 Diamond Back Way	Street Address	GO95
21597 You Bet Rd	Street Address	GO95
15092 Meadow Dr	Street Address	GO95
164 Jackson St	Street Address	GO95
10073 Greenwood Rd	Street Address	GO95
40-98 Willow Way	Street Address	GO95
54 Bell Ln	Street Address	GO95
13901 Wheeler Acres Rd	Street Address	GO95
27300-27356 Cape Horn Rd E	Street Address	GO95
24601 CA-20	Street Address	GO95
23298-23398 CA-20	Street Address	GO95
59186-59414 CA-49	Street Address	GO95
15473 Cascade dr	Pole Address	GO95
12003 La Barr Meadows Rd	Pole Address	GO95
3959-4289 Quincy-La Porte Rd	Street Address	GO95
10551 Larch St	Street Address	GO95
214-230 Bucklin Rd	Street Address	GO95
201 Bear River View Ln	Street Address	GO95
Secret Town Rd	Street Address	GO95
Secret Town Rd	Street Address	GO95
33740 Nary Red Rd	Street Address	GO95
41158 Skyline Dr	Street Address	GO95
10819 Pine Hill Dr	Street Address	GO95
127 Race St	Street Address	GO95
10679 Footwall Dr	Street Address	GO95
12465 Oak Cir	Street Address	GO95
444 Kate Hayes St	Street Address	GO95

10371 Crooked Arrow Ln	Street Address	GO95
10069 Banner Lava Cap Rd	Street Address	GO95
10450 Harmony Ridge Rd	Street Address	GO95
11949 Banner Lava Cap Rd	Street Address	GO95
12351 N Bloomfield Rd	Street Address	GO95
17114 Yuba-donner Scenic Byway	Street Address	GO95
12457 Loma Rica Dr	Street Address	GO95
12725 Idaho Maryland Rd	Street Address	GO95
11780 E Brookview Dr	Street Address	GO95
11733 Slow Poke Ln	Street Address	GO95
656 W Broad St	Street Address	GO95
18180 Round Mountain Ranch Rd	Street Address	GO95
13874 Greenhorn Rd	Street Address	GO95
668 E Broad St	Street Address	GO95
17377 Rock Creek Rd	Street Address	GO95
11410 N Bloomfield Rd	Street Address	GO95
10662 E Bennett Rd	Street Address	GO95
116 Orchard St	Street Address	GO95
81 Cement Hill Rd	Street Address	GO95
10858 Bartlett Dr	Street Address	GO95
10747 Bartlett Dr	Street Address	GO95
75 Cement Hill Rd	Street Address	GO95
611 Chief Kelly Dr	Street Address	GO95
17162 Yuba-donner Scenic Byway	Street Address	GO95
17407 State Highway 49	Street Address	GO95
15669 American Hill Rd	Street Address	GO95
11372 N Bloomfield Rd	Street Address	GO95
14720 Colfax Hwy	Street Address	GO95
158 Lucas Ln	Street Address	GO95
12904 Brunswick Rd	Street Address	GO95
13281 Grass Valley Ave	Street Address	GO95
13120 Loma Rica Dr	Street Address	GO95
12556 Loma Rica Dr	Street Address	GO95
13010 Loma Rica Dr	Street Address	GO95
15649 Greenhorn Rd	Street Address	GO95
15495 Lake Vera Purdon Rd	Street Address	GO95
13943 Greenhorn Rd	Street Address	GO95
11177 La Barr Meadows Rd	Street Address	GO95
10046 Smith Rd	Street Address	GO95
12018 Lower Colfax Rd	Street Address	GO95
14027 Christopher Robin Way	Street Address	GO95
12134 Gayle Ln	Street Address	GO95
11510 Colfax Hwy	Street Address	GO95
13017 Boreham Ln	Street Address	GO95

12942 Boreham Ln	Street Address	GO95
12718 Spring Rd	Street Address	GO95
13939 Nimbus Dam Rd	Pole Address	GO95
11949 Banner Lava Cap Rd	Pole Address	GO95
14161 Brooks Rd	Pole Address	GO95
12718 Spring Rd	Street Address	GO95
17047 Weeds Point Rd	Street Address	GO95
15616 Fawn Trail	Street Address	GO95
16554 Calvin Ln	Street Address	GO95
27621 Yuba-donner Scenic Byway	Pole Address	GO95
10868 Barnes Dr	Street Address	GO95
13134 Davos Dr	Street Address	GO95
11442 Alder Dr	Street Address	GO95
13109 Hillside Dr	Street Address	GO95
10424 E Alder Creek Rd	Street Address	GO95
11190 Barnes Dr	Street Address	GO95
13329 Hansel Ave	Street Address	GO95
13881 Hansel Ave	Street Address	GO95
12345 Bennett Flat Rd	Street Address	GO95
13110 Davos Dr	Street Address	GO95
12025 Bennett Flat Rd	Street Address	GO95
12824 Hillside Dr	Street Address	GO95
12715 Parker Rd	Street Address	GO95
12715 Parker Rd	Street Address	GO95
13387 Hillside Dr	Street Address	GO95
12932 Falcon Point Pl	Street Address	GO95
12898 Falcon Point Pl	Street Address	GO95
11709 Lausanne Way	Street Address	GO95
11718 Lausanne Way	Street Address	GO95
14305 Tyrol Rd	Street Address	GO95
11582 Oslo Dr	Street Address	GO95
105 Nugget Ln	Street Address	GO95
261 Silver Creek Rd	Street Address	GO95
6473 Bucks Lake Rd	Street Address	GO95
292 East St	Street Address	GO95
60 Myers St	Street Address	GO95
208 5th St	Street Address	GO95
404 Alder Ct	Street Address	GO95
242 Cate St	Street Address	GO95
16788 Bucks Lake Rd	Street Address	GO95
75 Jackson St	Street Address	GO95
16625 New York House Rd	Street Address	GO95
16556 Frenchtown Rd	Street Address	GO95
355 Lawrence St	Street Address	GO95

2-198 Fiddle Creek Rd	Street Address	GO95
60549 Mountain Creek Bridge	Street Address	GO95
6770 Sylvan Rd	Street Address	GO95
156 Beckwith St	Street Address	GO95
8530 Bucks Lake Rd	Street Address	GO95
Secret Town Rd	Street Address	GO95
201 Bear River View Ln	Street Address	GO95
33740 Nary Red Rd	Street Address	GO95
Secret Town Rd	Street Address	GO95
11159 Spenceville Rd	Pole Address	GO95
12690 Angie Ct	Pole Address	GO95
1000-1176 Moody Ridge Rd	Street Address	GO95
1930 Moody Ridge Rd	Street Address	GO95
1300 Moody Ridge Rd	Street Address	GO95
18197 Wildflower Dr	Street Address	GO95
504-514 Blue Canyon Rd	Street Address	GO95
816 Blue Canyon Rd	Street Address	GO95
34010 Alta Bonnynook Rd	Street Address	GO95
34401-34599 Dogwood Ln	Street Address	GO95
34638 Trail End Ct	Street Address	GO95
631 Timber Ln	Street Address	GO95
34445 Culberson Rd	Street Address	GO95
100-198 Bear Valley Road	Street Address	GO95
7 Gold Lake Forest Hwy	Street Address	GO95
17470 New York House Rd	Street Address	GO95
CA 20	Street Address	GO95
LAKE SPAULDING DR	Street Address	GO95
BOWMAN LAKE RD	Street Address	GO95
12873 BANNER LAVA CAP	Street Address	GO95
16996 MEYER LN	Street Address	GO95
16123 AUBURN RD	Street Address	GO95
Bowman Lake Rd	Street Address	GO95
BLACKBERRY PL	Street Address	GO95
13511 MEADOW VIEW	Street Address	GO95
16933HENNESS PASS RD	Street Address	GO95
13511 MEADOW VIEW	Street Address	GO95
11698 La Porte Rd	Pole Address	GO95
14235 ARROWHEAD MINE	Street Address	GO95
20967 YOU BET	Street Address	GO95
21597 YOU BET	Street Address	GO95
16653 Mountain House Rd	Street Address	GO95
20842 John Born Rd	Street Address	GO95
16787 Patricia Way	Street Address	GO95
15233 Sierra Star Ln	Street Address	GO95

34609 Trail End Ct	Street Address	GO95
31055 Knob Cone Rd	Street Address	GO95
11118 Banner Lava Cap Rd	Street Address	GO95
17590 State Highway 49	Street Address	GO95
15766 Vandevere Rd	Street Address	GO95
10831 Bartlett Dr	Street Address	GO95
18638 Mccourtney Rd	Street Address	GO95
21073 State Highway 20	Street Address	GO95
13316 Davos Dr	Street Address	GO95
1331 Lovers Leap Road	Street Address	GO95
16008 Diamond D Drive	Street Address	GO95
16973 Scott Way	Street Address	GO95
15651 Lorie Drive	Street Address	GO95
11699 Birchville Rd	Street Address	GO95
11339 Colfax Hwy	Pole Address	GO95
14495 Mill Creek Ln	Street Address	GO95
19218 Greenhorn Rd	Street Address	GO95
29824-29848 Secret Town Rd	Street Address	GO95
15046 Meadow Dr	Street Address	GO95
23849 CA-20	Street Address	GO95
11337 Grange Ln	Street Address	GO95
21704 Rambling Rd	Street Address	GO95
21833 Rambling Rd	Street Address	GO95
12730 La Barr Meadows Rd	Street Address	GO95
13342 Skiview Loop	Pole Address	GO95

CATEGORY	SUB_CAT
GO95 Service Drop	Drop route incorrect
GO95 Service Drop	Clearance to ground
GO95 Pole	Complete pole transfer / buddy pole
GO95 Service Drop	Clearance to ground
GO95 Pole	Deteriorated/Decayed/Damaged
GO95 Cable	Clearance to ground
GO95 Pole	Leaning
GO95 Cable	Clearance to power
GO95 Guardarm/Crossarm	Cable arm
GO95 Cable	Clearance to power
GO95 Cable	Clearance to power
GO95 Cable	Clearance to power
GO95 Cable	Clearance to power
GO95 Cable	Clearance to power
GO95 Cable	Clearance to power
GO95 Cable	Clearance to power
GO95 Cable	Clearance to power
GO95 Cable	Clearance to power
GO95 Cable	Clearance to power
GO95 Guys/Anchors	Down guy
GO95 Vegetation	Strain
GO95 Cable	Clearance to ground
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Cable	Clearance to power
GO95 Cable	Clearance to power
GO95 Cable	Clearance to power
GO95 Pole	Complete pole transfer / buddy pole
GO95 Pole	Complete pole transfer / buddy pole
GO95 Pole	Complete pole transfer / buddy pole
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Guys/Anchors	Down guy
GO95 Cable	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Cable	Broken lashing wire
GO95 Cable	Clearance to ground

GO95 Guys/Anchors	Down guy
GO95 Cable	Hardware
GO95 Guys/Anchors	Down guy
GO95 Cable	Hardware
GO95 Cable	Broken lashing wire
GO95 Cable	Broken lashing wire
GO95 Guys/Anchors	Down guy
GO95 Guys/Anchors	Down guy
GO95 Guys/Anchors	Down guy
GO95 Cable	Clearance to ground
GO95 Cable	Broken lashing wire
GO95 Cable	Hardware
GO95 Guys/Anchors	Down guy
GO95 Cable	Clearance to ground
GO95 Cable	Hardware
GO95 Cable	Hardware
GO95 Guys/Anchors	Down guy
GO95 Service Drop	Clearance to ground
GO95 Guys/Anchors	Down guy
GO95 Guys/Anchors	Down guy
GO95 Guys/Anchors	Down guy
GO95 Service Drop	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Guys/Anchors	Down guy
GO95 Guys/Anchors	Down guy
GO95 Cable	Broken lashing wire
GO95 Cable	Hardware
GO95 Cable	Broken lashing wire
GO95 Guys/Anchors	Down guy
GO95 Cable	Hardware
GO95 Service Drop	Clearance to ground
GO95 Cable	Hardware
GO95 Service Drop	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Cable	Broken lashing wire
GO95 Cable	Hardware
GO95 Cable	Broken lashing wire
GO95 Service Drop	Lines down
GO95 Cable	Broken lashing wire
GO95 Guys/Anchors	Down guy
GO95 Guys/Anchors	Down guy
GO95 Guys/Anchors	Down guy

GO95 Guys/Anchors	Down guy
GO95 Guys/Anchors	Down guy
GO95 Guys/Anchors	Down guy
GO95 Cable	Hardware
GO95 Service Drop	Clearance to ground
GO95 Guys/Anchors	Down guy
GO95 Guys/Anchors	Down guy
GO95 Cable	Broken lashing wire
GO95 Guys/Anchors	Down guy
GO95 Pole	Cable Riser
GO95 Cable	Broken lashing wire
GO95 Cable	Hardware
GO95 Guys/Anchors	Down guy
GO95 Guys/Anchors	Down guy
GO95 Guys/Anchors	Down guy
GO95 Cable	Broken lashing wire
GO95 Cable	Broken lashing wire
GO95 Guys/Anchors	Down guy
GO95 Cable	Broken lashing wire
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Cable	Clearance to communications

GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Cable	Clearance to communications
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Cable	Clearance to communications
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Cable	Clearance to communications
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Cable	Clearance to communications
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down

GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Pole	Leaning
GO95 Guys/Anchors	Down guy
GO95 Cable	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Guys/Anchors	Down guy
GO95 Guys/Anchors	Down guy
GO95 Cable	Broken lashing wire
GO95 Guys/Anchors	Down guy
GO95 Cable	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Cable	Hardware
GO95 Guys/Anchors	Down guy
GO95 Cable	Broken lashing wire
GO95 Guys/Anchors	Down guy
GO95 Guys/Anchors	Down guy
GO95 Guys/Anchors	Down guy
GO95 Cable	Clearance to ground
GO95 Cable	Broken lashing wire
GO95 Guys/Anchors	Down guy
GO95 Cable	Hardware
GO95 Service Drop	Clearance to ground
GO95 Guys/Anchors	Down guy
GO95 Guys/Anchors	Down guy
GO95 Cable	Clearance to ground
GO95 Guys/Anchors	Down guy
GO95 Guys/Anchors	Down guy
GO95 Guys/Anchors	Down guy
GO95 Cable	Hardware
GO95 Guys/Anchors	Down guy
GO95 Cable	Clearance to ground
GO95 Guys/Anchors	Down guy
GO95 Cable	Hardware
GO95 Cable	Hardware
GO95 Guys/Anchors	Down guy
GO95 Cable	Broken lashing wire
GO95 Service Drop	Clearance to ground
GO95 Cable	Hardware

GO95 Cable	Hardware
GO95 Guys/Anchors	Down guy
GO95 Cable	Hardware
GO95 Cable	Hardware
GO95 Cable	Broken lashing wire
GO95 Guys/Anchors	Down guy
GO95 Guys/Anchors	Down guy
GO95 Guys/Anchors	Down guy
GO95 Cable	Clearance to ground
GO95 Cable	Broken lashing wire
GO95 Cable	Hardware
GO95 Cable	Hardware
GO95 Cable	Hardware
GO95 Cable	Hardware
GO95 Cable	Hardware
GO95 Cable	Hardware
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Cable	Clearance to communications
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Vegetation	Causing low cable
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Vegetation	Causing low cable
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Vegetation	Causing low cable
GO95 Vegetation	Causing low cable

GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Cable	Clearance to communications
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Cable	Clearance to communications
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Equipment/Antenna/Splice	Equipment/Splice attachment
GO95 Vegetation	Hazardous strain
GO95 Guardarm/Crossarm	New guard arm required
GO95 Pole	Leaning
GO95 Cable	Clearance to power
GO95 Cable	Clearance to power
GO95 Pole	Leaning
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Guys/Anchors	Down guy
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Cable	Clearance to power
GO95 Cable	Clearance to power
GO95 Cable	Clearance to power
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down

GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to power
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Pole	Deteriorated/Decayed/Damaged
GO95 Vegetation	Hazardous strain
GO95 Vegetation	Hazardous strain
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Pole	Complete pole transfer / buddy pole
GO95 Cable	Clearance to power
GO95 Cable	Clearance to power
GO95 Cable	Clearance to power
GO95 Cable	Clearance to power
GO95 Cable	Clearance to power
GO95 Cable	Clearance to power
GO95 Guys/Anchors	Down guy
GO95 Cable	Broken lashing wire
GO95 Vegetation	Strain
GO95 Guys/Anchors	Down guy
GO95 Cable	Clearance to power
GO95 Vegetation	Cable Damage
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Vegetation	Causing low cable
GO95 Vegetation	Causing low cable
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Vegetation	Causing low cable
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Vegetation	Causing low cable
GO95 Service Drop	Clearance to ground
GO95 Pole	Leaning

GO95 Cable	Clearance to ground
GO95 Vegetation	Strain
GO95 Guys/Anchors	Down guy
GO95 Cable	Clearance to ground
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Guys/Anchors	Down guy
GO95 Cable	Broken lashing wire
GO95 Vegetation	Strain
GO95 Guys/Anchors	Down guy
GO95 Service Drop	Clearance to power
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Pole	Complete pole transfer / buddy pole
GO95 Cable	Lines down
GO95 Pole	Leaning
GO95 Service Drop	Clearance to power
GO95 Cable	Clearance to power
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Guys/Anchors	Down guy
GO95 Cable	Clearance to ground
GO95 Vegetation	Strain
GO95 Guys/Anchors	Down guy
GO95 Vegetation	Strain
GO95 Cable	Clearance to ground
GO95 Vegetation	Strain
GO95 Cable	Broken lashing wire
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain

GO95 Guys/Anchors	Down guy
GO95 Cable	Broken lashing wire
GO95 Vegetation	Strain
GO95 Guys/Anchors	Down guy
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Guys/Anchors	Down guy
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Cable	Clearance to power
GO95 Cable	Clearance to power
GO95 Cable	Clearance to power
GO95 Cable	Clearance to power
GO95 Cable	Clearance to power
GO95 Vegetation	Cable Damage
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to power
GO95 Service Drop	Lines down
GO95 Cable	Broken lashing wire
GO95 Vegetation	Cable Damage
GO95 Service Drop	Lines down
GO95 Vegetation	Cable Damage
GO95 Vegetation	Cable Damage
GO95 Vegetation	Causing low service drop
GO95 Vegetation	Cable Damage
GO95 Vegetation	Cable Damage
GO95 Service Drop	Lines down
GO95 Vegetation	Cable Damage
GO95 Vegetation	Cable Damage
GO95 Service Drop	Lines down
GO95 Vegetation	Cable Damage
GO95 Cable	Clearance to ground
GO95 Cable	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Vegetation	Causing low cable
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Vegetation	Causing low cable
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down

GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Vegetation	Causing low cable
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Vegetation	Causing low cable
GO95 Service Drop	Lines down
GO95 Cable	Clearance to power
GO95 Cable	Clearance to power
GO95 Service Drop	Clearance to power
GO95 Cable	Clearance to ground
GO95 Guys/Anchors	Down guy
GO95 Cable	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to power
GO95 Guardarm/Crossarm	Guard arm
GO95 Cable	Clearance to power
GO95 Pole	Leaning
GO95 Cable	Clearance to power
GO95 Cable	Clearance to power
GO95 Guardarm/Crossarm	Cable arm
GO95 Pole	Leaning
GO95 Pole	Leaning
GO95 Cable	Broken lashing wire
GO95 Cable	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Cable	Broken lashing wire

GO95 Cable	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Cable	Clearance to power
GO95 Cable	Clearance to power
GO95 Pole	Deteriorated/Decayed/Damaged
GO95 Cable	Clearance to power
GO95 Cable	Clearance to power
GO95 Vegetation	Cable Damage
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Vegetation	Hazardous strain
GO95 Guardarm/Crossarm	Cable arm
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Vegetation	Causing low cable
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Cable	Broken lashing wire
GO95 Guys/Anchors	Down guy
GO95 Cable	Broken lashing wire
GO95 Cable	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Pole	Complete pole transfer / buddy pole

GO95 Service Drop	Clearance to ground
GO95 Pole	Complete pole transfer / buddy pole
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Vegetation	Causing low cable
GO95 Guardarm/Crossarm	Cable arm
GO95 Guardarm/Crossarm	Cable arm
GO95 Guardarm/Crossarm	Cable arm
GO95 Pole	Leaning
GO95 Guardarm/Crossarm	Cable arm
GO95 Service Drop	Clearance to power
GO95 Guardarm/Crossarm	Guard arm
GO95 Guardarm/Crossarm	Cable arm
GO95 Guardarm/Crossarm	Cable arm
GO95 Guardarm/Crossarm	Cable arm
GO95 Guys/Anchors	Down guy

GO95 Pole	Deteriorated/Decayed/Damaged
GO95 Service Drop	Lines down

GO95 Pole	Deteriorated/Decayed/Damaged
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Cable	Clearance to power
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Vegetation	Causing low cable
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Equipment/Antenna/Splice	Equipment/Splice attachment
GO95 Cable	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Vegetation	Hazard tree
GO95 Vegetation	Hazardous strain
GO95 Service Drop	Lines down
GO95 Vegetation	Hazardous strain
GO95 Vegetation	Hazardous strain
GO95 Vegetation	Hazardous strain
GO95 Vegetation	Hazardous strain
GO95 Vegetation	Hazardous strain
GO95 Vegetation	Hazardous strain
GO95 Vegetation	Hazardous strain
GO95 Vegetation	Hazardous strain
GO95 Vegetation	Hazardous strain
GO95 Service Drop	Lines down

GO95 Vegetation	Hazardous strain
GO95 Vegetation	Hazardous strain
GO95 Vegetation	Hazardous strain
GO95 Vegetation	Hazardous strain
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Vegetation	Strain
GO95 Cable	Clearance to ground
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Cable	Broken lashing wire
GO95 Cable	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Cable	Broken lashing wire

GO95 Guys/Anchors	Down guy
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain

GO95 Cable	Broken lashing wire
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Guys/Anchors	Down guy
GO95 Vegetation	Strain
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down

GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down

GO95 Guys/Anchors	Down guy
GO95 Vegetation	Strain
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain

GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground

GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground

GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground

GO95 Cable	Broken lashing wire

GO95 Cable	Clearance to ground
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain

GO95 Cable	Broken lashing wire

GO95 Cable	Clearance to ground
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain

GO95 Cable	Broken lashing wire
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain

GO95 Cable	Broken lashing wire

GO95 Vegetation	Strain
GO95 Cable	Broken lashing wire
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Cable	Broken lashing wire
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Pole	Leaning
GO95 Pole	Leaning
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain

GO95 Cable	Broken lashing wire
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain

GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Vegetation	Hazardous strain
GO95 Cable	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Vegetation	Hazardous strain
GO95 Service Drop	Clearance to ground
GO95 Pole	Complete pole transfer / buddy pole
GO95 Service Drop	Lines down
GO95 Vegetation	Hazardous strain
GO95 Service Drop	Lines down
GO95 Cable	Broken lashing wire
GO95 Cable	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Cable	Lines down
GO95 Cable	Clearance to ground
GO95 Pole	Leaning
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Pole	Leaning
GO95 Vegetation	Hazardous strain
GO95 Vegetation	Hazardous strain
GO95 Vegetation	Hazardous strain
GO95 Vegetation	Hazardous strain
GO95 Vegetation	Hazardous strain
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground

GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Vegetation	Hazardous strain
GO95 Vegetation	Hazardous strain
GO95 Vegetation	Hazardous strain
GO95 Service Drop	Clearance to power
GO95 Service Drop	Clearance to power
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Cable Damage
GO95 Vegetation	Causing low service drop
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Vegetation	Causing low cable
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Vegetation	Causing low cable
GO95 Service Drop	Clearance to ground
GO95 Vegetation	Causing low cable
GO95 Vegetation	Causing low cable
GO95 Vegetation	Causing low cable
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground

GO95 Service Drop	Clearance to ground
GO95 Vegetation	Strain
GO95 Pole	Service drop riser
GO95 Vegetation	Strain
GO95 Vegetation	Hazard tree
GO95 Vegetation	Hazard tree
GO95 Vegetation	Hazard tree
GO95 Pole	Deteriorated/Decayed/Damaged
GO95 Vegetation	Strain
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Vegetation	Strain
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Pole	Deteriorated/Decayed/Damaged
GO95 Vegetation	Hazard tree
GO95 Vegetation	Strain
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Vegetation	Strain
GO95 Pole	Deteriorated/Decayed/Damaged
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Vegetation	Hazard tree
GO95 Vegetation	Hazard tree
GO95 Vegetation	Hazard tree
GO95 Vegetation	Hazard tree

GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Vegetation	Strain
GO95 Pole	Service drop riser
GO95 Pole	Deteriorated/Decayed/Damaged
GO95 Pole	Deteriorated/Decayed/Damaged
GO95 Vegetation	Strain
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Vegetation	Strain
GO95 Pole	Deteriorated/Decayed/Damaged
GO95 Pole	Deteriorated/Decayed/Damaged
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Pole	Deteriorated/Decayed/Damaged
GO95 Vegetation	Causing low cable
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Service Drop	Clearance to power
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Vegetation	Strain
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Vegetation	Strain
GO95 Service Drop	Clearance to ground
GO95 Vegetation	Strain
GO95 Service Drop	Lines down
GO95 Vegetation	Strain
GO95 Pole	Service drop riser

GO95 Vegetation	Strain
GO95 Service Drop	Lines down
GO95 Vegetation	Strain
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Vegetation	Hazard tree
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Cable	Clearance to power
GO95 Cable	Clearance to power
GO95 Service Drop	Clearance to power
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down

GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Vegetation	Strain
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Vegetation	Strain
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Vegetation	Strain
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Vegetation	Strain
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Pole	Service drop riser

GO95 Service Drop	Clearance to power
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Vegetation	Strain
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Vegetation	Strain
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground

GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground

GO95 Service Drop	Hardware loose/missing/damaged
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Service Drop	Lines down
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Pole	Service drop riser
GO95 Cable	Clearance to power
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Guardarm/Crossarm	Guard arm
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Cable	Broken lashing wire
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Cable	Clearance to power
GO95 Cable	Clearance to power
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Cable	Clearance to power
GO95 Cable	Clearance to power
GO95 Service Drop	Clearance to ground
GO95 Guardarm/Crossarm	Guard arm
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Service Drop	Lines down
GO95 Cable	Clearance to power
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Guardarm/Crossarm	Guard arm
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser

GO95 Vegetation	Causing low cable
GO95 Cable	Clearance to power
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Cable	Clearance to power
GO95 Pole	Service drop riser
GO95 Cable	Clearance to power
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to power
GO95 Service Drop	Clearance to power
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Cable	Clearance to power
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to power
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Cable	Clearance to power
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Cable	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Guardarm/Crossarm	Guard arm
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Cable	Clearance to power
GO95 Cable	Clearance to power

GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Cable	Clearance to power
GO95 Vegetation	Causing low cable
GO95 Vegetation	Causing low cable
GO95 Pole	Service drop riser
GO95 Cable	Clearance to power
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Vegetation	Causing low cable
GO95 Service Drop	Clearance to power
GO95 Cable	Clearance to power
GO95 Service Drop	Lines down
GO95 Cable	Clearance to power
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Guys/Anchors	Down guy
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Cable	Clearance to power
GO95 Cable	Clearance to power
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Cable	Clearance to power
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Cable	Clearance to power
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Cable	Clearance to power
GO95 Pole	Service drop riser
GO95 Cable	Clearance to power
GO95 Service Drop	Clearance to power

GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Cable	Clearance to power
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Cable	Clearance to power
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Cable	Clearance to power
GO95 Cable	Clearance to power
GO95 Service Drop	Clearance to power
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to power
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down

GO95 Service Drop	Hardware loose/missing/damaged
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Vegetation	Hazard tree
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Vegetation	Causing low cable
GO95 Vegetation	Hazard tree
GO95 Vegetation	Hazard tree
GO95 Vegetation	Causing low cable
GO95 Vegetation	Causing low cable
GO95 Vegetation	Causing low cable
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Service Drop	Clearance to power
GO95 Service Drop	Clearance to power
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Vegetation	Hazard tree
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Pole	Complete pole transfer / buddy pole
GO95 Vegetation	Strain
GO95 Vegetation	Causing low cable
GO95 Service Drop	Clearance to ground
GO95 Vegetation	Hazard tree
GO95 Vegetation	Causing low cable
GO95 Vegetation	Strain
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to power
GO95 Service Drop	Lines down

GO95 Service Drop	Lines down
GO95 Vegetation	Strain
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to power
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to power
GO95 Service Drop	Lines down
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Causing low cable
GO95 Service Drop	Lines down
GO95 Vegetation	Hazard tree
GO95 Vegetation	Hazard tree
GO95 Vegetation	Causing low cable
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Vegetation	Strain
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Vegetation	Causing low cable
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to power

GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Hazard tree
GO95 Pole	Deteriorated/Decayed/Damaged
GO95 Pole	Deteriorated/Decayed/Damaged
GO95 Service Drop	Lines down
GO95 Pole	Deteriorated/Decayed/Damaged
GO95 Vegetation	Hazard tree
GO95 Vegetation	Hazard tree
GO95 Vegetation	Hazard tree
GO95 Vegetation	Hazard tree
GO95 Service Drop	Lines down
GO95 Vegetation	Strain
GO95 Service Drop	Lines down
GO95 Pole	Deteriorated/Decayed/Damaged
GO95 Vegetation	Strain
GO95 Pole	Deteriorated/Decayed/Damaged
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Service Drop	Lines down
GO95 Vegetation	Strain
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Vegetation	Strain
GO95 Vegetation	Hazard tree
GO95 Vegetation	Hazard tree
GO95 Vegetation	Hazard tree
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Vegetation	Strain
GO95 Service Drop	Clearance to power
GO95 Vegetation	Hazard tree
GO95 Service Drop	Lines down
GO95 Vegetation	Strain
GO95 Service Drop	Clearance to ground
GO95 Pole	Deteriorated/Decayed/Damaged
GO95 Vegetation	Strain
GO95 Pole	Deteriorated/Decayed/Damaged
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground

GO95 Service Drop	Lines down
GO95 Vegetation	Strain
GO95 Vegetation	Hazard tree
GO95 Vegetation	Causing low cable
GO95 Vegetation	Hazard tree
GO95 Service Drop	Lines down
GO95 Vegetation	Hazard tree
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to ground
GO95 Vegetation	Strain
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Service Drop	Clearance to power
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Pole	Climbing/Working space impaired
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Vegetation	Strain
GO95 Service Drop	Clearance to ground
GO95 Pole	Climbing/Working space impaired
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Vegetation	Causing low cable

GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Vegetation	Causing low cable
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to ground
GO95 Vegetation	Causing low cable
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Vegetation	Causing low cable
GO95 Vegetation	Causing low cable
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Vegetation	Causing low cable
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to power
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to power
GO95 Vegetation	Strain
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to power
GO95 Pole	Service drop riser

GO95 Vegetation	Causing low cable
GO95 Pole	Service drop riser
GO95 Vegetation	Causing low cable
GO95 Pole	Climbing/Working space impaired
GO95 Service Drop	Lines down
GO95 Pole	Climbing/Working space impaired
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Vegetation	Strain
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Vegetation	Causing low cable
GO95 Pole	Service drop riser
GO95 Vegetation	Causing low cable
GO95 Vegetation	Strain
GO95 Pole	Service drop riser
GO95 Vegetation	Causing low cable
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to power
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Vegetation	Causing low cable
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to power
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Pole	Climbing/Working space impaired
GO95 Vegetation	Strain
GO95 Service Drop	Clearance to power
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to power
GO95 Service Drop	Lines down

GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Vegetation	Causing low cable
GO95 Vegetation	Strain
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Vegetation	Strain
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to power
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to power
GO95 Vegetation	Strain
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Vegetation	Strain
GO95 Pole	Service drop riser

GO95 Vegetation	Strain
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Vegetation	Causing low cable
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Vegetation	Strain
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Pole	Climbing/Working space impaired
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Vegetation	Strain
GO95 Service Drop	Lines down

GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to power
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Vegetation	Strain
GO95 Service Drop	Clearance to ground
GO95 Vegetation	Causing low cable
GO95 Vegetation	Strain
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to power
GO95 Service Drop	Lines down
GO95 Vegetation	Strain
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Vegetation	Strain
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to power
GO95 Pole	Service drop riser
GO95 Vegetation	Strain
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground

GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to power
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Vegetation	Strain
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Climbing/Working space impaired
GO95 Pole	Climbing/Working space impaired
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to power
GO95 Service Drop	Clearance to power
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down

GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Vegetation	Strain
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Vegetation	Hazard tree
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to power
GO95 Service Drop	Clearance to power
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to power
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down

GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to power
GO95 Service Drop	Clearance to power
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Vegetation	Hazard tree
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Vegetation	Hazard tree
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Vegetation	Strain
GO95 Pole	Climbing/Working space impaired
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to power
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Vegetation	Strain
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Vegetation	Strain
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Vegetation	Strain
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser

GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to power
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to power
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to power
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to ground

GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to power
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser

GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Vegetation	Strain
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser

GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Vegetation	Strain
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Hardware loose/missing/damaged

GO95 Service Drop	Hardware loose/missing/damaged
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Vegetation	Hazard tree
GO95 Service Drop	Lines down
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Pole	Service drop riser
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Service Drop	Lines down
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Pole	Service drop riser
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Service Drop	Hardware loose/missing/damaged
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Pole	Service drop riser
GO95 Pole	Service drop riser
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Pole	Climbing/Working space impaired
GO95 Pole	Climbing/Working space impaired
GO95 Pole	Climbing/Working space impaired
GO95 Pole	Climbing/Working space impaired
GO95 Cable	Lines down
GO95 Cable	Lines down

GO95 Cable	Lines down
GO95 Cable	Lines down
GO95 Cable	Lines down
GO95 Cable	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Cable	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Cable	Lines down
GO95 Vegetation	Hazardous strain
GO95 Cable	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Vegetation	Hazardous strain
GO95 Service Drop	Lines down
GO95 Cable	Lines down
GO95 Vegetation	Hazardous strain
GO95 Vegetation	Hazardous strain
GO95 Cable	Lines down
GO95 Service Drop	Lines down
GO95 Cable	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Service Drop	Lines down
GO95 Cable	Lines down
GO95 Service Drop	Lines down
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Service Drop	Lines down
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain

GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain

GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Pole	Deteriorated/Decayed/Damaged
GO95 Pole	Complete pole transfer / buddy pole
GO95 Pole	Complete pole transfer / buddy pole
GO95 Service Drop	Clearance to ground
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Pole	Deteriorated/Decayed/Damaged
GO95 Vegetation	Causing low cable
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Vegetation	Strain
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Clearance to ground
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down

GO95 Cable	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Pole	Deteriorated/Decayed/Damaged
GO95 Pole	Deteriorated/Decayed/Damaged
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Vegetation	Hazard tree
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Service Drop	Lines down
GO95 Vegetation	Hazard tree
GO95 Service Drop	Lines down
GO95 Vegetation	Hazardous strain
GO95 Cable	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Service Drop	Lines down
GO95 Cable	Broken lashing wire
GO95 Cable	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Service Drop	Lines down
GO95 Cable	Clearance to ground
GO95 Service Drop	Lines down
GO95 Pole	Deteriorated/Decayed/Damaged
GO95 Cable	Clearance to ground
GO95 Pole	Leaning
GO95 Vegetation	Hazardous strain
GO95 Vegetation	Strain
GO95 Service Drop	Lines down
GO95 Service Drop	Clearance to power
GO95 Service Drop	Clearance to power

GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Service Drop	Clearance to power
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Vegetation	Strain
GO95 Cable	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Cable	Clearance to ground
GO95 Cable	Lines down
GO95 Pole	Leaning
GO95 Cable	Lines down
GO95 Cable	Lines down
GO95 Vegetation	Hazardous strain
GO95 Cable	Lines down
GO95 Cable	Lines down
GO95 Cable	Lines down
GO95 Cable	Lines down
GO95 Cable	Lines down
GO95 Cable	Broken lashing wire
GO95 Pole	Cable Riser

TYPE_OF_TROUBLE

GO95 Service Drop

GO95 Service Drop

GO95 Pole

GO95 Service Drop

Hazardous Pole with Immediate Risk due to Deterioration, Insect or Bird Damage, or Damage by any other means

Clearance to ground between 8 and 12ft parallel to roadway

Pole Lean of 10 percent or more of height above ground

Secondary Power to Cable Between 24 and 48in

Cable Arm or Hardware Loose/Decayed/Damaged/Missing

Secondary Power to Cable Between 24 and 48in

Secondary Power to Cable Between 24 and 48in

Secondary Power to Cable Between 24 and 48in

Secondary Power to Cable Between 24 and 48in

Secondary Power to Cable Between 24 and 48in

Secondary Power to Cable Between 48 and 72in - Pl Guard Arm

Secondary Power to Cable Between 24 and 48in

Secondary Power to Cable Between 24 and 48in

Secondary Power to Cable Between 48 and 72in - Pl Guard Arm

Secondary Power to Cable Between 24 and 48in

Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Clearance to Ground Between 12 and 15ft over roadway

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Secondary Power to Cable Less Than 24in

Secondary Power to Cable Less Than 24in

Secondary Power to Cable Less Than 24in

Pole Transfer Required with old pole set in ground

Pole Transfer Required with old pole set in ground

Pole Transfer Required with old pole set in ground

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Hanging or Cut Drop

Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing

Clearance to ground between 8 and 12ft parallel to roadway

Clearance to Ground Between 12 and 15ft over roadway

Clearance to ground between 8 and 12ft parallel to roadway

Broken lashing wire hanging More Than 3ft above or below strand

Clearance to Ground Between 12 and 15ft over roadway

Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing
Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk
Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor
Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk
Broken lashing wire hanging Less Than 3ft above or below strand
Broken lashing wire hanging Less Than 3ft above or below strand
Re-Tension Guy
Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor
Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor
Clearance to Ground Between 15 and 18ft over roadway
Broken lashing wire hanging Less Than 3ft above or below strand
Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk
Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor
Clearance to Ground Between 15 and 18ft over roadway
Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk
Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk
Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor
Clearance to Ground Between 12 and 18ft over roadway or 16ft at the curb
Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor
Re-Tension Guy
Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor
Clearance to Ground Between 12 and 18ft over roadway or 16ft at the curb
Clearance to Ground Between 15 and 18ft over roadway
Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor
Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor
Broken lashing wire hanging Less Than 3ft above or below strand
Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk
Broken lashing wire hanging Less Than 3ft above or below strand
Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor
Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk
Clearance to Ground Between 12 and 18ft over roadway or 16ft at the curb
Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk
Clearance to Ground Between 12 and 18ft over roadway or 16ft at the curb
Clearance to Ground Between 15 and 18ft over roadway
Clearance to Ground Between 12 and 18ft over roadway or 16ft at the curb
Broken lashing wire hanging Less Than 3ft above or below strand
Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk
Broken lashing wire hanging Less Than 3ft above or below strand
Inaccessible to Public Lines Down
Broken lashing wire hanging Less Than 3ft above or below strand
Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor
Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor
Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor

Re-Tension Guy
Re-Tension Guy
Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor
Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk
Clearance to Ground Between 12 and 18ft over roadway or 16ft at the curb
Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor
Re-Tension Guy
Broken lashing wire hanging Less Than 3ft above or below strand
Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor
Riser Cover (U-Guard) - Loose/Missing/Damaged - Inaccessible to Public
Broken lashing wire hanging Less Than 3ft above or below strand
Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk
Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor
Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor
Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor
Broken lashing wire hanging Less Than 3ft above or below strand
Broken lashing wire hanging Less Than 3ft above or below strand
Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor
Broken lashing wire hanging Less Than 3ft above or below strand
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Hanging or Cut Drop
Hanging or Cut Drop
Accessible to Public Lines Down
Hanging or Cut Drop
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Hanging or Cut Drop
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Hanging or Cut Drop
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Horizontal Clearance between Comm Cables on the same arm <3in

Accessible to Public Lines Down
Hanging or Cut Drop
Accessible to Public Lines Down
Hanging or Cut Drop
Hanging or Cut Drop
Accessible to Public Lines Down
Accessible to Public Lines Down
Horizontal Clearance between Comm Cables on the same arm <3in
Accessible to Public Lines Down
Hanging or Cut Drop
Accessible to Public Lines Down
Clearance to Ground Less Than 12ft over Driveway or Private Road
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Hanging or Cut Drop
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Horizontal Clearance between Comm Cables on the same arm <3in
Accessible to Public Lines Down
Hanging or Cut Drop
Clearance to Ground Less Than 12ft over Driveway or Private Road
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Horizontal Clearance between Comm Cables on the same arm <3in
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Clearance to Ground Less Than 12ft over Driveway or Private Road
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Accessible to Public Lines Down
Horizontal Clearance between Comm Cables on the same arm <3in
Accessible to Public Lines Down
Accessible to Public Lines Down

Accessible to Public Lines Down
Accessible to Public Lines Down
Pole Lean of 10 percent or more of height above ground

Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing
Clearance to Ground Between 12 and 15ft over roadway
Clearance to ground between 8 and 12ft parallel to roadway

Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing

Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing

Broken lashing wire hanging More Than 3ft above or below strand
Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing
Clearance to Ground Between 12 and 15ft over roadway
Clearance to Ground Between 12 and 15ft over roadway
Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk
Re-Tension Guy
Broken lashing wire hanging Less Than 3ft above or below strand
Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor
Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor
Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor
Clearance to Ground Between 15 and 18ft over roadway
Broken lashing wire hanging Less Than 3ft above or below strand
Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor
Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk
Clearance to Ground Between 12 and 18ft over roadway or 16ft at the curb
Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor
Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor
Clearance to Ground Between 15 and 18ft over roadway
Re-Tension Guy
Re-Tension Guy
Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor
Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk
Re-Tension Guy
Clearance to Ground Between 15 and 18ft over roadway
Re-Tension Guy
Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk
Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk
Re-Tension Guy
Broken lashing wire hanging Less Than 3ft above or below strand
Clearance to Ground Between 12 and 18ft over roadway or 16ft at the curb
Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk

Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk
Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor
Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk
Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk
Broken lashing wire hanging Less Than 3ft above or below strand
Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor
Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor
Place New Guy Marker that is Loose/Damaged/Missing - Guy Marker required on outermost guy on each anchor
Clearance to Ground Between 15 and 18ft over roadway
Broken lashing wire hanging Less Than 3ft above or below strand
Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk
Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk
Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk
Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk
Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk
Loose/Missing/Damaged -Inaccessible to Public or Not Immediate Risk
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Horizontal Clearance between Comm Cables on the same arm <3in
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Hanging or Cut Drop
Vegetation management required to resolve low cable
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Hanging or Cut Drop
Vegetation management required to resolve low cable
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Accessible to Public Lines Down
Vegetation management required to resolve low cable
Vegetation management required to resolve low cable

Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Horizontal Clearance between Comm Cables on the same arm <3in
Accessible to Public Lines Down
Hanging or Cut Drop
Hanging or Cut Drop
Accessible to Public Lines Down
Accessible to Public Lines Down
Hanging or Cut Drop
Accessible to Public Lines Down
Accessible to Public Lines Down
Clearance to Ground Less Than 12ft over Driveway or Private Road
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Horizontal Clearance between Comm Cables on the same arm <3in
Accessible to Public Lines Down
Accessible to Public Lines Down
Equipment/Splice or Related hardware Loose/Missing/Damaged
GO95 Vegetation
Communications Facilities between 4 and 6ft from Secondary Power
Pole Lean of 10 percent or more of height above ground
Secondary Power to Cable Between 24 and 48in
Secondary Power to Cable Between 48 and 72in - Pl Guard Arm
Pole Lean of 10 percent or more of height above ground
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
750V-20KV Primary Power to Cable 4-5ft on pole and at least 3ft at midspan
750V-20KV Primary Power to Cable 4-5ft on pole and at least 3ft at midspan
750V-20KV Primary Power to Cable 4-5ft on pole and at least 3ft at midspan
Inaccessible to Public Lines Down
Inaccessible to Public Lines Down
Inaccessible to Public Lines Down
Inaccessible to Public Lines Down
Inaccessible to Public Lines Down
Inaccessible to Public Lines Down

Inaccessible to Public Lines Down
Inaccessible to Public Lines Down
Secondary Power to Service Drop Between 48 and 72in at Pole - Pl Guard Arm
Inaccessible to Public Lines Down
Inaccessible to Public Lines Down
Hazardous Pole with Immediate Risk due to Deterioration, Insect or Bird Damage, or Damage by any other means
Hazardous Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Hazardous Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Crossing or Parallel to Public Roadway
GO95 Pole
Secondary Power to Cable Between 24 and 48in
Secondary Power to Cable Between 24 and 48in
Secondary Power to Cable Between 48 and 72in - Pl Guard Arm
Secondary Power to Cable Between 24 and 48in
Secondary Power to Cable Between 48 and 72in - Pl Guard Arm
Secondary Power to Cable Between 24 and 48in
Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing
Broken lashing wire hanging More Than 3ft above or below strand
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing
Secondary Power to Cable Less Than 24in
Vegetation Causing Damage to Interior of Cable Due to Abrasion
Clearance to Ground <8ft accessible to public
Hanging or Cut Drop
Vegetation management required to resolve low cable
Vegetation management required to resolve low cable
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground Less Than 12ft over Driveway or Private Road
Vegetation management required to resolve low cable
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Vegetation management required to resolve low cable
Clearance to Ground <8ft accessible to public
Pole Lean of 10 percent or more of height above ground

Clearance to Ground Between 12 and 15ft over roadway
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing
Clearance to Ground Between 12 and 15ft over roadway
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing
Broken lashing wire hanging More Than 3ft above or below strand
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Missing Down Guy with Pole Lean or Deflection
Primary Power to Service Drop Less Than 36in at Pole
Hanging or Cut Drop
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Hanging or Cut Drop
Clearance to Ground <8ft accessible to public
Pole Transfer Required - Section of old pole attached to new pole (Cut/Kick)
Accessible to Public
Pole Lean of 10 percent or more of height above ground
Secondary Power to Service Drop Between 36 and 48in at Pole
Secondary Power to Cable Between 24 and 48in
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing
Clearance to Ground Between 12 and 15ft over roadway
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Clearance to Ground Between 12 and 15ft over roadway
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Broken lashing wire hanging More Than 3ft above or below strand
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing
Broken lashing wire hanging More Than 3ft above or below strand
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
750V-20KV Primary Power to Cable 4-5ft on pole and at least 3ft at midspan
Secondary Power to Cable Less Than 24in
750V-20KV Primary Power to Cable 4-5ft on pole and at least 3ft at midspan
Secondary Power to Cable Less Than 24in
750V-20KV Primary Power to Cable 4-5ft on pole and at least 3ft at midspan
Vegetation Causing Damage to Interior of Cable Due to Abrasion
Inaccessible to Public Lines Down
Secondary Power to Service Drop Between 48 and 72in at Pole - Pl Guard Arm
Inaccessible to Public Lines Down
Broken lashing wire hanging Less Than 3ft above or below strand
Vegetation Causing Damage to Interior of Cable Due to Abrasion
Inaccessible to Public Lines Down
Vegetation Causing Damage to Interior of Cable Due to Abrasion
Vegetation Causing Damage to Interior of Cable Due to Abrasion
Vegetation management required to resolve low service drop
Vegetation Causing Damage to Interior of Cable Due to Abrasion
Vegetation Causing Damage to Interior of Cable Due to Abrasion
Inaccessible to Public Lines Down
Vegetation Causing Damage to Interior of Cable Due to Abrasion
Vegetation Causing Damage to Interior of Cable Due to Abrasion
Inaccessible to Public Lines Down
Vegetation Causing Damage to Interior of Cable Due to Abrasion
Hazardous - Clearance to Ground <8ft accessible to public
Accessible to Public
Accessible to Public Lines Down
Accessible to Public Lines Down
Vegetation management required to resolve low cable
Accessible to Public Lines Down
Accessible to Public Lines Down
Vegetation management required to resolve low cable
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down

Accessible to Public Lines Down
Hanging or Cut Drop
Vegetation management required to resolve low cable
Accessible to Public Lines Down
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Hanging or Cut Drop
Hanging or Cut Drop
Accessible to Public Lines Down
Vegetation management required to resolve low cable
Accessible to Public Lines Down
Secondary Power to Cable Between 48 and 72in - Pl Guard Arm
Secondary Power to Cable Between 48 and 72in - Pl Guard Arm
Secondary Power to Service Drop Between 36 and 48in at Pole
Clearance to Ground Between 12 and 15ft over roadway
Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing
Clearance to Ground Between 12 and 15ft over roadway
Hanging or Cut Drop
Clearance to Ground Less Than 12ft over Driveway or Private Road
Service Wire to Comm Service Drop Less than 12in within 15ft of point of attachment to Customer Structure for either
Guard Arm or Hardware Loose/Decayed/Damaged/Missing
Secondary Power to Cable Between 24 and 48in
Pole Lean of 10 percent or more of height above ground
Secondary Power to Cable Between 48 and 72in - Pl Guard Arm
Secondary Power to Cable Between 48 and 72in - Pl Guard Arm
Cable Arm or Hardware Loose/Decayed/Damaged/Missing
Pole Lean of 10 percent or more of height above ground
Pole Lean of 10 percent or more of height above ground
Broken lashing wire hanging More Than 3ft above or below strand
Clearance to ground between 8 and 12ft parallel to roadway
Clearance to ground between 8 and 12ft parallel to roadway
Clearance to Ground Between 12 and 15ft over roadway
Clearance to Ground Between 12 and 15ft over roadway
Clearance to ground between 8 and 12ft parallel to roadway
Clearance to ground between 8 and 12ft parallel to roadway
Clearance to ground between 8 and 12ft parallel to roadway
Clearance to ground between 8 and 12ft parallel to roadway
Clearance to Ground Between 12 and 15ft over roadway
Clearance to Ground Between 12 and 15ft over roadway
Clearance to Ground Between 12 and 15ft over roadway
Clearance to Ground Between 12 and 15ft over roadway
Clearance to Ground Between 12 and 15ft over roadway
Broken lashing wire hanging More Than 3ft above or below strand

Clearance to ground between 8 and 12ft parallel to roadway
Clearance to ground between 8 and 12ft parallel to roadway
Clearance to ground between 8 and 12ft parallel to roadway
Clearance to ground between 8 and 12ft parallel to roadway
Clearance to ground between 8 and 12ft parallel to roadway
Clearance to ground between 8 and 12ft parallel to roadway
Clearance to ground between 8 and 12ft parallel to roadway
Clearance to Ground Between 12 and 15ft over roadway
Clearance to ground between 8 and 12ft parallel to roadway
Clearance to ground between 8 and 12ft parallel to roadway
Clearance to ground between 8 and 12ft parallel to roadway
Secondary Power to Cable Less Than 24in
750V-20KV Primary Power to Cable 4-5ft on pole and at least 3ft at midspan
Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement
750V-20KV Primary Power to Cable 4-5ft on pole and at least 3ft at midspan
Secondary Power to Cable Less Than 24in
Vegetation Causing Damage to Interior of Cable Due to Abrasion
Inaccessible to Public Lines Down
Inaccessible to Public Lines Down
Inaccessible to Public Lines Down
Inaccessible to Public Lines Down
Hazardous Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Hazardous - Arm or Hardware Loose/Decayed/Damaged/Missing
Accessible to Public Lines Down
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Hanging or Cut Drop
Hanging or Cut Drop
Accessible to Public Lines Down
Vegetation management required to resolve low cable
Accessible to Public Lines Down
Hanging or Cut Drop
Clearance to Ground Less Than 12ft over Driveway or Private Road
Hanging or Cut Drop
Hanging or Cut Drop
Broken lashing wire hanging More Than 3ft above or below strand
Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing

Broken lashing wire hanging More Than 3ft above or below strand
Clearance to Ground Between 15 and 18ft over roadway
Clearance to Ground <8ft inaccessible to public Service Drop
Pole Transfer Required with old pole set in ground

Clearance to Ground <8ft inaccessible to public Service Drop
Pole Transfer Required with old pole set in ground
Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop
Clearance to Ground <8ft accessible to public
Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop
Clearance to Ground <8ft accessible to public
Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop
Clearance to Ground Less Than 12ft over Driveway or Private Road
Hanging or Cut Drop
Clearance to Ground <8ft accessible to public
Hanging or Cut Drop
Clearance to Ground Less Than 12ft over roadway
Hanging or Cut Drop
Clearance to Ground <8ft accessible to public
Hanging or Cut Drop
Hanging or Cut Drop
Accessible to Public Lines Down
Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop
Clearance to Ground <8ft accessible to public
Vegetation management required to resolve low cable
Cable Arm or Hardware Loose/Decayed/Damaged/Missing
Cable Arm or Hardware Loose/Decayed/Damaged/Missing
Cable Arm or Hardware Loose/Decayed/Damaged/Missing
Pole Lean of 10 percent or more of height above ground
Cable Arm or Hardware Loose/Decayed/Damaged/Missing
Secondary Power to Service Drop Between 36 and 48in at Pole
Guard Arm or Hardware Loose/Decayed/Damaged/Missing
Cable Arm or Hardware Loose/Decayed/Damaged/Missing
Cable Arm or Hardware Loose/Decayed/Damaged/Missing
Cable Arm or Hardware Loose/Decayed/Damaged/Missing
Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing

Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement
Inaccessible to Public Lines Down

Hazardous Pole with Immediate Risk due to Deterioration, Insect or Bird Damage, or Damage by any other means
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop
Crossing or Parallel to Public Roadway
Secondary Power to Cable Between 24 and 48in
Hanging or Cut Drop
Accessible to Public Lines Down
Vegetation management required to resolve low cable
Crossing or Parallel to Public Roadway
Crossing or Parallel to Public Roadway
Crossing or Parallel to Public Roadway
Crossing or Parallel to Public Roadway
GO95 Equipment/Antenna/Splice
Hazardous - Clearance to Ground <12ft over roadway
Hazardous - Clearance to Ground <8ft accessible to public
Crossing or Parallel to Public Roadway
Crossing or Parallel to Public Roadway
Crossing or Parallel to Public Roadway
Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand
Hazardous Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Crossing or Parallel to Public Roadway
Hazardous Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Hazardous Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Hazardous Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Hazardous Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Hazardous Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Hazardous Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Hazardous Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Hazardous Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Crossing or Parallel to Public Roadway

Hazardous Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Hazardous Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Hazardous Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Hazardous Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Crossing or Parallel to Public Roadway
Crossing or Parallel to Public Roadway
Crossing or Parallel to Public Roadway
Crossing or Parallel to Public Roadway
Crossing or Parallel to Public Roadway
Crossing or Parallel to Public Roadway
Crossing or Parallel to Public Roadway
Crossing or Parallel to Public Roadway
Crossing or Parallel to Public Roadway
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Clearance to ground between 8 and 12ft parallel to roadway
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Broken lashing wire hanging More Than 3ft above or below strand

Clearance to ground between 8 and 12ft parallel to roadway

Clearance to ground between 8 and 12ft parallel to roadway

Broken lashing wire hanging More Than 3ft above or below strand

Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Broken lashing wire hanging More Than 3ft above or below strand
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop
Clearance to Ground <8ft accessible to public
Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop
Accessible to Public Lines Down
Clearance to Ground Less Than 12ft over Driveway or Private Road
Hanging or Cut Drop
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down

Hanging or Cut Drop
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Hanging or Cut Drop
Hanging or Cut Drop
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down

Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop

Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop

Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop

Broken lashing wire hanging More Than 3ft above or below strand

Clearance to ground between 8 and 12ft parallel to roadway
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Broken lashing wire hanging More Than 3ft above or below strand

Clearance to ground between 8 and 12ft parallel to roadway
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Broken lashing wire hanging More Than 3ft above or below strand
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Broken lashing wire hanging More Than 3ft above or below strand

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Broken lashing wire hanging More Than 3ft above or below strand
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Broken lashing wire hanging More Than 3ft above or below strand
Accessible to Public Lines Down
Hanging or Cut Drop
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Hanging or Cut Drop
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Accessible to Public Lines Down
Hanging or Cut Drop
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop
Accessible to Public Lines Down
Accessible to Public Lines Down
Clearance to Ground Less Than 12ft over Driveway or Private Road
Clearance to Ground <8ft accessible to public
Hanging or Cut Drop
Pole Lean of 10 percent or more of height above ground

Pole Lean of 10 percent or more of height above ground
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Broken lashing wire hanging More Than 3ft above or below strand
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Broken lashing wire hanging More Than 3ft above or below strand

Clearance to ground between 8 and 12ft parallel to roadway

Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement
Crossing or Parallel to Public Roadway
Accessible to Public Lines Down

Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Crossing or Parallel to Public Roadway
Hazardous Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Accessible to Public
Crossing or Parallel to Public Roadway
Crossing or Parallel to Public Roadway
Crossing or Parallel to Public Roadway
Hazardous Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Clearance to Ground <8ft accessible to public
Pole Transfer Required - Section of old pole attached to new pole (Cut/Kick)
Crossing or Parallel to Public Roadway
Hazardous Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Crossing or Parallel to Public Roadway
GO95 Cable
GO95 Cable
GO95 Cable
GO95 Cable
GO95 Cable
GO95 Cable
GO95 Pole
Crossing or Parallel to Public Roadway
Crossing or Parallel to Public Roadway
GO95 Pole
GO95 Vegetation
GO95 Vegetation
GO95 Vegetation
GO95 Vegetation
GO95 Vegetation
Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop

Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
GO95 Vegetation
GO95 Vegetation
GO95 Vegetation
Secondary Power to Service Drop Between 36 and 48in at Pole
Secondary Power to Service Drop Between 36 and 48in at Pole
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Causing Damage to Interior of Cable Due to Abrasion
Vegetation management required to resolve low service drop
Hanging or Cut Drop
Clearance to Ground <8ft accessible to public
Hanging or Cut Drop
Vegetation management required to resolve low cable
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Vegetation management required to resolve low cable
Hanging or Cut Drop
Vegetation management required to resolve low cable
Vegetation management required to resolve low cable
Vegetation management required to resolve low cable
Hanging or Cut Drop
Hanging or Cut Drop
Clearance to Ground <8ft accessible to public
Hanging or Cut Drop

Hanging or Cut Drop
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand
Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand
Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand
Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Crossing or Parallel to Public Roadway
Accessible to Public Lines Down
Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement
Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Clearance to Ground <8ft accessible to public
Hanging or Cut Drop
Clearance to Ground <8ft accessible to public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement
Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Loose/Missing/Damaged - Accessible to Public
Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand
Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand
Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand
Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand

Hanging or Cut Drop
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement
Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Clearance to Ground <8ft accessible to public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement
Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement
Vegetation management required to resolve low cable
Clearance to Ground <8ft accessible to public
Loose/Missing/Damaged - Accessible to Public
Secondary Power to Service Drop Between 36 and 48in at Pole
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Clearance to Ground <8ft accessible to public
Crossing or Parallel to Public Roadway
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Hanging or Cut Drop
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Hanging or Cut Drop
Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Clearance to Ground <8ft accessible to public
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Crossing or Parallel to Public Roadway
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Riser Cover - Loose/Missing/Damaged - Accessible to Public

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Accessible to Public Lines Down
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground Less Than 12ft over roadway
Loose/Missing/Damaged - Accessible to Public
Loose/Missing/Damaged - Accessible to Public
Loose/Missing/Damaged - Accessible to Public
Loose/Missing/Damaged - Accessible to Public
Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Secondary Power to Cable Between 48 and 72in - Pl Guard Arm
Secondary Power to Cable Between 48 and 72in - Pl Guard Arm
Secondary Power to Service Drop Between 36 and 48in at Pole
Clearance to Ground <8ft accessible to public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Hanging or Cut Drop
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public

Secondary Power to Service Drop Between 36 and 48in at Pole

Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public

Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public

Loose/Missing/Damaged - Accessible to Public
Loose/Missing/Damaged - Accessible to Public
Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Loose/Missing/Damaged - Accessible to Public
Loose/Missing/Damaged - Accessible to Public
Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Secondary Power to Cable Between 48 and 72in - Pl Guard Arm
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Guard Arm or Hardware Loose/Decayed/Damaged/Missing
Loose/Missing/Damaged - Accessible to Public
Broken lashing wire hanging More Than 3ft above or below strand
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Secondary Power to Cable Between 48 and 72in - Pl Guard Arm
Secondary Power to Cable Between 48 and 72in - Pl Guard Arm
Loose/Missing/Damaged - Accessible to Public
Secondary Power to Cable Between 24 and 48in
Secondary Power to Cable Between 48 and 72in - Pl Guard Arm
Clearance to Ground <8ft accessible to public
Guard Arm or Hardware Loose/Decayed/Damaged/Missing
Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Secondary Power to Cable Between 48 and 72in - Pl Guard Arm
Accessible to Public Lines Down
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Guard Arm or Hardware Loose/Decayed/Damaged/Missing
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public

Vegetation management required to resolve low cable
Secondary Power to Cable Between 48 and 72in - Pl Guard Arm
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Secondary Power to Cable Between 24 and 48in
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Secondary Power to Cable Between 48 and 72in - Pl Guard Arm
Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Secondary Power to Service Drop Between 36 and 48in at Pole
Secondary Power to Service Drop Between 36 and 48in at Pole
Loose/Missing/Damaged - Accessible to Public
Secondary Power to Cable Between 48 and 72in - Pl Guard Arm
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Secondary Power to Service Drop Between 36 and 48in at Pole
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Secondary Power to Cable Between 48 and 72in - Pl Guard Arm
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Clearance to ground between 8 and 12ft parallel to roadway
Clearance to Ground <8ft accessible to public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Guard Arm or Hardware Loose/Decayed/Damaged/Missing
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Loose/Missing/Damaged - Accessible to Public
Secondary Power to Cable Between 48 and 72in - Pl Guard Arm
Secondary Power to Cable Between 48 and 72in - Pl Guard Arm

Accessible to Public Lines Down
Accessible to Public Lines Down
Secondary Power to Cable Between 48 and 72in - Pl Guard Arm
Vegetation management required to resolve low cable
Vegetation management required to resolve low cable
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Secondary Power to Cable Between 24 and 48in
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Vegetation management required to resolve low cable
Secondary Power to Service Drop Between 36 and 48in at Pole
Secondary Power to Cable Between 48 and 72in - Pl Guard Arm
Accessible to Public Lines Down
Secondary Power to Cable Between 48 and 72in - Pl Guard Arm
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Place/Replace Down Guy and/or Down Guy Hardware - Insufficient or Loose/Damaged/Missing
Accessible to Public Lines Down
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Secondary Power to Cable Between 48 and 72in - Pl Guard Arm
Secondary Power to Cable Between 48 and 72in - Pl Guard Arm
Accessible to Public Lines Down
Accessible to Public Lines Down
Secondary Power to Cable Between 24 and 48in
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Secondary Power to Cable Between 24 and 48in
Accessible to Public Lines Down
Hanging or Cut Drop
Clearance to Ground <8ft accessible to public
Secondary Power to Cable Between 48 and 72in - Pl Guard Arm
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Secondary Power to Cable Between 48 and 72in - Pl Guard Arm
Secondary Power to Service Drop Between 36 and 48in at Pole

Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Secondary Power to Cable Between 48 and 72in - Pl Guard Arm
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Secondary Power to Cable Between 48 and 72in - Pl Guard Arm
Clearance to Ground <8ft accessible to public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Secondary Power to Cable Between 48 and 72in - Pl Guard Arm
Secondary Power to Cable Between 48 and 72in - Pl Guard Arm
Secondary Power to Service Drop Between 36 and 48in at Pole
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Loose/Missing/Damaged - Accessible to Public
Loose/Missing/Damaged - Accessible to Public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Secondary Power to Service Drop Between 36 and 48in at Pole
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Crossing or Parallel to Public Roadway

Loose/Missing/Damaged - Accessible to Public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Hanging or Cut Drop
Hanging or Cut Drop
Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand
Hanging or Cut Drop
Hanging or Cut Drop
Vegetation management required to resolve low cable
Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand
Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand
Vegetation management required to resolve low cable
Vegetation management required to resolve low cable
Vegetation management required to resolve low cable
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Secondary Power to Service Drop Between 36 and 48in at Pole
Secondary Power to Service Drop Between 36 and 48in at Pole
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Pole Transfer Required with Impairments (Clearances, leaning, etc.)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation management required to resolve low cable
Clearance to Ground <8ft accessible to public
Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand
Vegetation management required to resolve low cable
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Accessible to Public Lines Down
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Accessible to Public Lines Down
Secondary Power to Service Drop Between 36 and 48in at Pole
Accessible to Public Lines Down

Accessible to Public Lines Down
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Secondary Power to Service Drop Between 36 and 48in at Pole
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Secondary Power to Service Drop Between 36 and 48in at Pole
Accessible to Public Lines Down
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation management required to resolve low cable
Accessible to Public Lines Down
Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand
Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand
Vegetation management required to resolve low cable
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Accessible to Public Lines Down
Vegetation management required to resolve low cable
Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Secondary Power to Service Drop Between 36 and 48in at Pole

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand
Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement
Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement
Accessible to Public Lines Down
Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement
Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand
Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand
Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand
Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand
Accessible to Public Lines Down
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Accessible to Public Lines Down
Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Accessible to Public Lines Down
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand
Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand
Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Primary Power to Service Drop Between 36 and 72in at Pole
Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand
Accessible to Public Lines Down
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Clearance to Ground <8ft accessible to public
Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public

Accessible to Public Lines Down
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand
Vegetation management required to resolve low cable
Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand
Accessible to Public Lines Down
Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Crossing or Parallel to Public Roadway
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Clearance to Ground <8ft accessible to public
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Secondary Power to Service Drop Between 36 and 48in at Pole
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Accessible to Public Lines Down
Drops - Service Drop (Aerial, Riser, or 6-Pair Terminal) in Climbing Space or Working Space
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Riser More than 3in from Base of Pole, Needs to Be Moved- Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Clearance to Ground <8ft accessible to public
Drops - Service Drop (Aerial, Riser, or 6-Pair Terminal) in Climbing Space or Working Space
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Vegetation management required to resolve low cable

Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Vegetation management required to resolve low cable
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Clearance to Ground <8ft accessible to public
Vegetation management required to resolve low cable
Clearance to Ground Less Than 12ft over roadway
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Accessible to Public Lines Down
Vegetation management required to resolve low cable
Vegetation management required to resolve low cable
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Vegetation management required to resolve low cable
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Secondary Power to Service Drop Between 36 and 48in at Pole
Accessible to Public Lines Down
Accessible to Public Lines Down
Secondary Power to Service Drop Between 36 and 48in at Pole
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Secondary Power to Service Drop Between 36 and 48in at Pole
Riser Cover - Loose/Missing/Damaged - Accessible to Public

Vegetation management required to resolve low cable
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Vegetation management required to resolve low cable
Drops - Service Drop (Aerial, Riser, or 6-Pair Terminal) in Climbing Space or Working Space
Accessible to Public Lines Down
Drops - Service Drop (Aerial, Riser, or 6-Pair Terminal) in Climbing Space or Working Space
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Vegetation management required to resolve low cable
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Vegetation management required to resolve low cable
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Vegetation management required to resolve low cable
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Secondary Power to Service Drop Between 36 and 48in at Pole
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Vegetation management required to resolve low cable
Clearance to Ground <8ft accessible to public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Secondary Power to Service Drop Between 36 and 48in at Pole
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Clearance to Ground <8ft accessible to public
Clearance to Ground Less Than 12ft over Driveway or Private Road
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Drops - Service Drop (Aerial, Riser, or 6-Pair Terminal) in Climbing Space or Working Space
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Secondary Power to Service Drop Between 36 and 48in at Pole
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Secondary Power to Service Drop Between 36 and 48in at Pole
Accessible to Public Lines Down

Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Vegetation management required to resolve low cable
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Secondary Power to Service Drop Between 36 and 48in at Pole
Clearance to Ground <8ft accessible to public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Secondary Power to Service Drop Between 36 and 48in at Pole
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Riser Cover - Loose/Missing/Damaged - Accessible to Public

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Accessible to Public Lines Down
Loose/Missing/Damaged - Accessible to Public
Clearance to Ground <8ft accessible to public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Accessible to Public Lines Down
Vegetation management required to resolve low cable
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Accessible to Public Lines Down
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Clearance to Ground <8ft accessible to public
Riser More than 3in from Base of Pole, Needs to Be Moved- Accessible to Public
Drops - Service Drop (Aerial, Riser, or 6-Pair Terminal) in Climbing Space or Working Space
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Riser More than 3in from Base of Pole, Needs to Be Moved- Accessible to Public
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Accessible to Public Lines Down

Riser Cover - Loose/Missing/Damaged - Accessible to Public
Secondary Power to Service Drop Between 36 and 48in at Pole
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Clearance to Ground Less Than 12ft over Driveway or Private Road
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Clearance to Ground <8ft accessible to public
Vegetation management required to resolve low cable
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Secondary Power to Service Drop Between 36 and 48in at Pole
Accessible to Public Lines Down
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Clearance to Ground <8ft accessible to public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Secondary Power to Service Drop Between 36 and 48in at Pole
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public

Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Secondary Power to Service Drop Between 36 and 48in at Pole
Riser More than 3in from Base of Pole, Needs to Be Moved- Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Clearance to Ground <8ft accessible to public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser More than 3in from Base of Pole, Needs to Be Moved- Accessible to Public
Accessible to Public Lines Down
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Drops - Service Drop (Aerial, Riser, or 6-Pair Terminal) in Climbing Space or Working Space
Drops - Service Drop (Aerial, Riser, or 6-Pair Terminal) in Climbing Space or Working Space
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Riser More than 3in from Base of Pole, Needs to Be Moved- Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Secondary Power to Service Drop Between 36 and 48in at Pole
Secondary Power to Service Drop Between 36 and 48in at Pole
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Riser More than 3in from Base of Pole, Needs to Be Moved- Accessible to Public
Riser More than 3in from Base of Pole, Needs to Be Moved- Accessible to Public
Accessible to Public Lines Down

Accessible to Public Lines Down
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Clearance to Ground <8ft accessible to public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Clearance to Ground <8ft accessible to public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser More than 3in from Base of Pole, Needs to Be Moved- Accessible to Public
Accessible to Public Lines Down
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Clearance to Ground <8ft accessible to public
Secondary Power to Service Drop Between 36 and 48in at Pole
Secondary Power to Service Drop Between 36 and 48in at Pole
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Secondary Power to Service Drop Between 36 and 48in at Pole
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Clearance to Ground <8ft accessible to public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down

Clearance to Ground <8ft accessible to public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Accessible to Public Lines Down
Riser More than 3in from Base of Pole, Needs to Be Moved- Accessible to Public
Riser More than 3in from Base of Pole, Needs to Be Moved- Accessible to Public
Secondary Power to Service Drop Between 36 and 48in at Pole
Secondary Power to Service Drop Between 36 and 48in at Pole
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand
Accessible to Public Lines Down
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Drops - Service Drop (Aerial, Riser, or 6-Pair Terminal) in Climbing Space or Working Space
Clearance to Ground <8ft accessible to public
Secondary Power to Service Drop Between 36 and 48in at Pole
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Clearance to Ground <8ft accessible to public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public

Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser More than 3in from Base of Pole, Needs to Be Moved- Accessible to Public
Accessible to Public Lines Down
Secondary Power to Service Drop Between 36 and 48in at Pole
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Secondary Power to Service Drop Between 36 and 48in at Pole
Clearance to Ground <8ft accessible to public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Secondary Power to Service Drop Between 36 and 48in at Pole
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Clearance to Ground <8ft accessible to public
Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Hanging or Cut Drop
Clearance to Ground <8ft accessible to public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Clearance to Ground <8ft accessible to public

Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Clearance to Ground <8ft accessible to public
Clearance to Ground <8ft accessible to public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Secondary Power to Service Drop Between 36 and 48in at Pole
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Clearance to Ground <8ft accessible to public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Hanging or Cut Drop
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Clearance to Ground <8ft accessible to public
Accessible to Public Lines Down
Crossing or Parallel to Public Roadway
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public

Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public

Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Loose/Missing/Damaged - Accessible to Public
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Loose/Missing/Damaged - Accessible to Public
Loose/Missing/Damaged - Accessible to Public
Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Loose/Missing/Damaged - Accessible to Public

Loose/Missing/Damaged - Accessible to Public
Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand
Accessible to Public Lines Down
Loose/Missing/Damaged - Accessible to Public
Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Accessible to Public Lines Down
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Loose/Missing/Damaged - Accessible to Public
Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Loose/Missing/Damaged - Accessible to Public
Loose/Missing/Damaged - Accessible to Public
Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Clearance to Ground <8ft accessible to public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Riser Cover - Loose/Missing/Damaged - Accessible to Public
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Drops - Service Drop (Aerial, Riser, or 6-Pair Terminal) in Climbing Space or Working Space
Drops - Service Drop (Aerial, Riser, or 6-Pair Terminal) in Climbing Space or Working Space
Drops - Service Drop (Aerial, Riser, or 6-Pair Terminal) in Climbing Space or Working Space
Drops - Service Drop (Aerial, Riser, or 6-Pair Terminal) in Climbing Space or Working Space

Accessible to Public

Accessible to Public

Accessible to Public

Accessible to Public

Accessible to Public

Accessible to Public
Crossing or Parallel to Public Roadway
Crossing or Parallel to Public Roadway

Accessible to Public
Crossing or Parallel to Public Roadway
Crossing or Parallel to Public Roadway

Accessible to Public
Hazardous Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Accessible to Public
Crossing or Parallel to Public Roadway
Accessible to Public Lines Down
Hazardous Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Crossing or Parallel to Public Roadway

Accessible to Public
Hazardous Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Hazardous Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Accessible to Public
Crossing or Parallel to Public Roadway
GO95 Cable
GO95 Cable
Crossing or Parallel to Public Roadway
Accessible to Public
Crossing or Parallel to Public Roadway
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Accessible to Public Lines Down
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement
Pole Transfer Required with Impairments (Clearances, leaning, etc.)
Pole Transfer Required with old pole set in ground
Hanging or Cut Drop
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement
Vegetation management required to resolve low cable
Accessible to Public Lines Down
Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop
Clearance to Ground Less Than 12ft over Driveway or Private Road
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Hanging or Cut Drop
Accessible to Public Lines Down
Hanging or Cut Drop
Accessible to Public Lines Down
Hanging or Cut Drop
Hanging or Cut Drop
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Accessible to Public Lines Down
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Accessible to Public Lines Down
Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop
Hanging or Cut Drop
Accessible to Public Lines Down
Accessible to Public Lines Down
Crossing or Parallel to Public Roadway

Accessible to Public
Crossing or Parallel to Public Roadway
Crossing or Parallel to Public Roadway
Crossing or Parallel to Public Roadway
Crossing or Parallel to Public Roadway
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Hazardous Pole with Immediate Risk due to Deterioration, Insect or Bird Damage, or Damage by any other means
Hazardous Pole with Immediate Risk due to Deterioration, Insect or Bird Damage, or Damage by any other means
Crossing or Parallel to Public Roadway
Crossing or Parallel to Public Roadway
Crossing or Parallel to Public Roadway
Crossing or Parallel to Public Roadway
Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand
Crossing or Parallel to Public Roadway
Crossing or Parallel to Public Roadway
Crossing or Parallel to Public Roadway
Crossing or Parallel to Public Roadway
Crossing or Parallel to Public Roadway
Crossing or Parallel to Public Roadway
Hazard Tree - Dead Tree or Portion of Tree that may fall into Cable/Strand
Crossing or Parallel to Public Roadway
GO95 Vegetation
GO95 Cable
GO95 Cable
GO95 Cable
GO95 Service Drop
GO95 Cable
GO95 Cable
GO95 Cable
GO95 Cable
GO95 Service Drop
GO95 Cable
GO95 Service Drop
Pole Deterioration, Insect or Bird Damage, or Damage by any other means that requires evaluation for replacement
GO95 Cable
GO95 Pole
GO95 Vegetation
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Crossing or Parallel to Public Roadway
Secondary Power to Service Drop Between 36 and 48in at Pole
Secondary Power to Service Drop Between 36 and 48in at Pole

Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Secondary Power to Service Drop Between 36 and 48in at Pole
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
GO95 Cable
GO95 Cable
GO95 Cable
GO95 Cable
Accessible to Public
Hazardous Pole Lean with Immediate Risk
Accessible to Public
Accessible to Public
Hazardous Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Accessible to Public
Accessible to Public
Accessible to Public
Accessible to Public
Accessible to Public
Broken lashing wire likely to Contact High Voltage (Primary/Transmission) Conductor
Riser Cover (U-Guard) - Loose/Missing/Damaged - Accessible to Public

DESCRIPTION

UNAUTHORIZED ATTACHMENT ON PG&E SOLELY OWNED POLES

UNAUTHORIZED ON PG&E SOLELY OWNED POLE.

POLE TRANSFER

UNAUTHORIZED ATTACHMENT ON PG&E POLE

MARKIT Broken double arm assembly

MARKIT Tree took out pole, PG&E replaced pole, cable developed slack hanging low mid span

MARKIT Straighten In-Line Pole - 16559 Old Downieville Hwy

MARKIT Place Cross/Guard Arm - 10281 Tillicum Way

MARKIT Place Cross/Guard Arm - 15720 Shannon Way

MARKIT Place Cross/Guard Arm - 26 Iroquois Trail

MARKIT Place Cross/Guard Arm - 21 Chinook Trail

MARKIT Place Cross/Guard Arm - 87 Yonkalla Trail

MARKIT Place Cross/Guard Arm - 7 Paiute Trail

MARKIT Place Cross/Guard Arm - 1323 Red Fox Rd

MARKIT Place Cross/Guard Arm - 14954 Monte Vista Dr

MARKIT Place Cross/Guard Arm - 6 Osage Trail

MARKIT Place Cross/Guard Arm - 9 Navajo Trail

MARKIT Place Cross/Guard Arm - 24 Shasta Trail

MARKIT Place Cross/Guard Arm - 58495 Cedar Ln

MARKIT Replace/Install Down Guy - 143 Nevada City Hwy

MARKIT Tree Trimming Required - 301 Gethsemane St

MARKIT Raise AT&T Mainline Cable - 4 Osage Trail

MARKIT Tree Trimming Required - 10735 Morning Star Ln

MARKIT Tree Trimming Required - 2 Shasta Trail

MARKIT Lower or Raise Existing AT&T Cable - 207 Jordan St

MARKIT Lower or Raise Existing Cable - 18 Chinook Trail

MARKIT Lower or Raise Existing AT&T Cable - 1201 Red Fox Rd

'er AT&T Cable(s)Transfer AT&T Drop(s)Transfer AT&T Terminal(s);Pull Old Pole;Lead Tails No;Cable Swing Yes;Trasfer

T Transfer AT&T Cable(s)Transfer AT&T Drop(s);Pull Old Pole;Lead Tails No;Cable Swing Yes;Trasfer 3 - 11065 White Oa

ARKIT Transfer AT&T Cable(s)Transfer AT&T Drop(s);Pull Old Pole;Lead Tails No;Cable Swing Yes;Trasfer 2 - 830 Atkins

MARKIT Remove Drop - 447 Zion St

MARKIT Remove Drop - 143 Nevada City Hwy

MARKIT Remove Drop - 15225 Monte Vista Dr

MARKIT Remove Drop - 58590 Cedar Ln

MARKIT Remove Drop - 5 Korominu Trail

MARKIT Replace/Install Down Guy - 10681 Martis Dr

MARKIT Raise AT&T Mainline Cable - 10024 S River St

MARKIT Raise AT&T Mainline Cable - 10281 Columbine Rd

MARKIT Raise AT&T Mainline Cable - 11258 Brockway Rd

MARKIT Relash Existing Cables - 10731 Donner Lake Rd

MARKIT Raise AT&T Mainline Cable - 15026 S Shore Dr

MARKIT Replace/Install Down Guy - 13800 S Shore Dr
MARKIT Repair/Replace Hardware - 11200 Dorchester Dr
MARKIT Place/Replace Down Guy Guard - 40200 Truckee-Tahoe Airport Rd
MARKIT Repair/Replace Hardware - 40200 Truckee-Tahoe Airport Rd
MARKIT Relash Existing Cables - 11018 Donner Pass Rd
MARKIT Relash Existing Cables - 10019 Floriston Ct
MARKIT Re-tension Down Guy All Sizes - 14629 Glenshire Dr
MARKIT Place/Replace Down Guy Guard - 14629 Glenshire Dr
MARKIT Place/Replace Down Guy Guard - 14624 Mt Judah Dr
MARKIT Raise AT&T Mainline Cable - 15580 S Shore Dr
MARKIT Relash Existing Cables - 11662 Hope Ct
MARKIT Repair/Replace Hardware - 11662 Hope Ct
MARKIT Place/Replace Down Guy Guard - 11691 Kayhoe Ct
MARKIT Raise AT&T Mainline Cable - 11357 Huntsman Leap
MARKIT Repair/Replace Hardware - 11121 Huntsman Leap
MARKIT Repair/Replace Hardware - 10664 Glenshire Dr
MARKIT Place/Replace Down Guy Guard - 11906 Stallion Way
MARKIT Raise AT&T Service Drop - 15621 Conifer St
MARKIT Place/Replace Down Guy Guard - 10450 Golden Pine Rd
MARKIT Re-tension Down Guy All Sizes - 10148 Laburnham Circle
MARKIT Place/Replace Down Guy Guard - 6425 W River Rd
MARKIT Raise AT&T Service Drop - 11642 Silver Fir Circle
MARKIT Raise AT&T Mainline Cable - 10629 Manchester Dr
MARKIT Place/Replace Down Guy Guard - 9705 N Shore Blvd
MARKIT Place/Replace Down Guy Guard - 12773 Donner Pass Rd
MARKIT Relash Existing Cables - 12773 Donner Pass Rd
MARKIT Repair/Replace Hardware - 10281 Columbine Rd
MARKIT Relash Existing Cables - 10281 Columbine Rd
MARKIT Place/Replace Down Guy Guard - 16320 Ute Dr
MARKIT Repair/Replace Hardware - 12005 Deerfield Dr
MARKIT Raise AT&T Service Drop - 9761 Martis Rd
MARKIT Repair/Replace Hardware - 11151 Dorchester Dr
MARKIT Raise AT&T Service Drop - 12116 Highland Ave
MARKIT Raise AT&T Mainline Cable - 11330 Skyline Ct
MARKIT Raise AT&T Service Drop - 10048 Oriole Ln
MARKIT Relash Existing Cables - 16320 Ute Dr
MARKIT Repair/Replace Hardware - 10545 Manchester Dr
MARKIT Relash Existing Cables - 10695 Brockway Rd
MARKIT Remove Drop - 13701 Donner Pass Rd
MARKIT Relash Existing Cables - 12849 Donner Pass Rd
MARKIT Place/Replace Down Guy Guard - 10686 Manchester Dr
MARKIT Place/Replace Down Guy Guard - 10416 Palisades Dr
MARKIT Place/Replace Down Guy Guard - 15575 Waterloo Circle

MARKIT Re-tension Down Guy All Sizes - 11111 Dorchester Dr
MARKIT Re-tension Down Guy All Sizes - 13860 Donner Pass Rd
MARKIT Place/Replace Down Guy Guard - 10598 Martis Dr
MARKIT Repair/Replace Hardware - 11882 Rio Vista Dr
MARKIT Raise AT&T Service Drop - 15630 Archery View
MARKIT Place/Replace Down Guy Guard - 11244 Spring Ln
MARKIT Re-tension Down Guy All Sizes - 10373 Evensham Pl
MARKIT Relash Existing Cables - 10911 Glenshire Dr
MARKIT Place/Replace Down Guy Guard - 15354 Glenshire Dr
MARKIT Repair/Replace Hardware - 10716 Jeffery Pine Rd
MARKIT Relash Existing Cables - 15504 Glenshire Dr
MARKIT Repair/Replace Hardware - 10695 Brockway Rd
MARKIT Place/Replace Down Guy Guard - 7900 W River Rd
MARKIT Place/Replace Down Guy Guard - Stampede Dam Rd
MARKIT Place/Replace Down Guy Guard - Stampede Dam Rd
MARKIT Relash Existing Cables - 11414 Whitehorse Rd
MARKIT Relash Existing Cables - 15244 Donner Pass Rd
MARKIT Place/Replace Down Guy Guard - 15731 Rolands Way
MARKIT Relash to existing Messenger - 16231 Ute Dr
MARKIT Remove Drop - 13655 Donner Pass Rd
MARKIT Remove Drop - 13600 Olympic Dr
MARKIT Remove Drop - 15633 Waterloo Circle
MARKIT Remove Drop - 10244 Laburnham Circle
MARKIT Remove Drop - 13604 Moraine Rd
MARKIT Remove Drop - 10515 Dogwood St
MARKIT Remove Drop - 10777 Gooseberry Ct
MARKIT Remove Drop - 13281 Donner Pass Rd
MARKIT Remove Drop - 15609 Spruce St
MARKIT Remove Drop - 16047 Glenshire Dr
MARKIT Remove Drop - 10253 Washoe Rd
MARKIT Remove Drop - 10245 Olympic Blvd
MARKIT Remove Drop - 14691 Boca View Ct
MARKIT Remove Drop - 15353 Crown Circle
MARKIT Raise AT&T Service Drop - 10121 Lake Ave
MARKIT Remove Drop - 16193 Ute Dr
MARKIT Remove Drop - 10148 Laburnham Circle
MARKIT Remove Drop - 14578 S Shore Dr
MARKIT Remove Drop - 10632 Laburnham Circle
MARKIT Remove Drop - 10568 Laburnham Circle
MARKIT Remove Drop - 14625 Red Mountain Rd
MARKIT Remove Drop - 15533 S Shore Dr
MARKIT Remove Drop - 14845 Denton Ave
MARKIT Remove Drop - 10159 Riverside Dr
MARKIT Lower or Raise Existing - Other Comm - 10846 Dorchester Dr

MARKIT Remove Drop - 10792 Aspenwood Rd
MARKIT Remove Drop - 14515 S Shore Dr
MARKIT Remove Drop - 9761 Martis Rd
MARKIT Remove Drop - 10869 Torrey Pine Rd
MARKIT Remove Drop - 15670 S Shore Dr
MARKIT Remove Drop - 15691 Conifer St
MARKIT Remove Drop - 10623 Ponderosa Dr
MARKIT Lower or Raise Existing - Other Comm - 16175 Glenshire Dr
MARKIT Remove Drop - 10851 Whitehorse Rd
MARKIT Remove Drop - 10321 Evensham Pl
MARKIT Remove Drop - 13579 Donner Pass Rd
MARKIT Raise AT&T Service Drop - 13579 Donner Pass Rd
MARKIT Remove Drop - 14926 S Shore Dr
MARKIT Remove Drop - 15749 Spruce St
MARKIT Remove Drop - 10424 Olympic Blvd
MARKIT Remove Drop - 11600 Deerfield Dr
MARKIT Remove Drop - 11659 Deerfield Dr
MARKIT Remove Drop - 15331 Conifer Dr
MARKIT Remove Drop - 11880 Deerfield Dr
MARKIT Remove Drop - 16251 Old Highway Dr
MARKIT Remove Drop - 16685 Glenshire Dr
MARKIT Remove Drop - 7860 W River Rd
MARKIT Tree Trimming Required - 11551 Highland Ave
MARKIT Remove Drop - 11551 Highland Ave
MARKIT Remove Drop - 11945 Rio Vista Dr
MARKIT Raise AT&T Service Drop - 11945 Rio Vista Dr
MARKIT Remove Drop - 14227 S Shore Dr
MARKIT Remove Drop - 10140 S River St
MARKIT Remove Drop - 11815 Deerfield Dr
MARKIT Lower or Raise Existing - Other Comm - 10458 Stone Pine Rd
MARKIT Remove Drop - 11287 Brockway Rd
MARKIT Remove Drop - 15404 Donner Pass Rd
MARKIT Remove Drop - 10111 Lake Ave
MARKIT Remove Drop - 15760 Willow St
MARKIT Remove Drop - 10911 Glenshire Dr
MARKIT Remove Drop - 15445 Glenshire Dr
MARKIT Remove Drop - 10580 Cedar Dr
MARKIT Raise AT&T Service Drop - 15504 Glenshire Dr
MARKIT Raise AT&T Service Drop - 10578 Red Fir Rd
MARKIT Remove Drop - 10578 Red Fir Rd
MARKIT Remove Drop - 15402 S Shore Dr
MARKIT Tree Trimming Required - 10419 Briar Circle
MARKIT Remove Drop - 7900 W River Rd
MARKIT Remove Drop - 10440 Golden Pine Rd

MARKIT Remove Drop - 16201 Old Highway Dr
MARKIT Remove Drop - 14816 Pioneer Dr
MARKIT Straighten In-Line Pole - 10420 Regency Circle

MARKIT Replace/Install Down Guy - 13440 Olympic Dr
MARKIT Raise AT&T Mainline Cable - 14821 Berkshire Circle
MARKIT Raise AT&T Mainline Cable - 13969 Juniper Creek Rd

MARKIT Replace/Install Down Guy - 10644 Regency Circle

MARKIT Replace/Install Down Guy - 13273 Sierra Dr

MARKIT Relash Existing Cables - 10262 W River St
MARKIT Replace/Install Down Guy - 10114 Dorchester Dr
MARKIT Raise AT&T Mainline Cable - 10125 Wiltshire Ln
MARKIT Raise AT&T Mainline Cable - 14780 Mt Judah Dr
MARKIT Repair/Replace Hardware - 11272 Bishop Pine Rd
MARKIT Re-tension Down Guy All Sizes - 15058 Berkshire Circle
MARKIT Relash Existing Cables - 15631 Donnington Ln
MARKIT Place/Replace Down Guy Guard - 11243 Dorchester Dr
MARKIT Place/Replace Down Guy Guard - 10220 Surrey Pl
MARKIT Place/Replace Down Guy Guard - 10068 Hirschdale Rd
MARKIT Raise AT&T Mainline Cable - 12353 Deerfield Dr
MARKIT Relash Existing Cables - 14821 Berkshire Circle
MARKIT Place/Replace Down Guy Guard - 16463 Tewksbury Dr
MARKIT Repair/Replace Hardware - 10708 Somerset Dr
MARKIT Raise AT&T Service Drop - 10520 Golden Pine Rd
MARKIT Place/Replace Down Guy Guard - 15952 Tewksbury Dr
MARKIT Place/Replace Down Guy Guard - 10304 Courtenay Ln
MARKIT Raise AT&T Mainline Cable - 15024 Nelson St
MARKIT Re-tension Down Guy All Sizes - 10499 Saxon Way
MARKIT Re-tension Down Guy All Sizes - 15975 Canterbury Ln
MARKIT Place/Replace Down Guy Guard - 15655 Waterloo Circle
MARKIT Repair/Replace Hardware - 15385 Icknield Way
MARKIT Re-tension Down Guy All Sizes - 10838 Blueberry Rd
MARKIT Raise AT&T Mainline Cable - 15675 Donnington Ln
MARKIT Re-tension Down Guy All Sizes - 15636 Colt Ct
MARKIT Repair/Replace Hardware - 14907 Cavalier Rise
MARKIT Repair/Replace Hardware - 10296 Brockway Rd
MARKIT Re-tension Down Guy All Sizes - 16814 Walden Dr
MARKIT Relash Existing Cables - 10664 Glenshire Dr
MARKIT Raise AT&T Service Drop - 11272 Bishop Pine Rd
MARKIT Repair/Replace Hardware - 14519 Donnington Ln

MARKIT Repair/Replace Hardware - 10464 The Strand
MARKIT Place/Replace Down Guy Guard - 15615 Kent Dr
MARKIT Repair/Replace Hardware - 10465 Stuart Staithe
MARKIT Repair/Replace Hardware - 14620 Donnington Ln
MARKIT Relash Existing Cables - 11851 Highland Ave
MARKIT Place/Replace Down Guy Guard - 10481 Pine Cone Dr
MARKIT Place/Replace Down Guy Guard - 10409 Courtenay Ln
MARKIT Place/Replace Down Guy Guard - 17144 Uxbridge Dr
MARKIT Raise AT&T Mainline Cable - 16945 Uxbridge Dr
MARKIT Relash Existing Cables - 16015 Woodbridge Ct
MARKIT Repair/Replace Hardware - 10588 Royal Crest Dr
MARKIT Repair/Replace Hardware - 14415 Donnington Ln
MARKIT Repair/Replace Hardware - 15389 Crown Circle
MARKIT Repair/Replace Hardware - 11039 Coldwater Rd
MARKIT Repair/Replace Hardware - 10540 The Strand
MARKIT Repair/Replace Hardware - 10455 Saxon Way
MARKIT Remove Drop - 10457 Washoe Rd
MARKIT Remove Drop - 10550 Dogwood St
MARKIT Remove Drop - 15114 Donnington Ln
MARKIT Lower or Raise Existing - Other Comm - 10279 E River St
MARKIT Remove Drop - 15841 Summit Ct
MARKIT Remove Drop - 15779 Spruce St
MARKIT Remove Drop - 10199 Sheffield Pl
MARKIT Remove Drop - 10343 Washoe Rd
MARKIT Vegetation Removal Required - 12984 Donner Pass Rd
MARKIT Remove Drop - 15790 Pine St
MARKIT Remove Drop - 10735 Ponderosa Dr
MARKIT Remove Drop - 15661 Conifer St
MARKIT Remove Drop - 10560 Larch St
MARKIT Remove Drop - 16480 Old Highway Dr
MARKIT Remove Drop - 11692 Highland Ave
MARKIT Remove Drop - 15631 Donnington Ln
MARKIT Remove Drop - 11445 Silver Fir Dr
MARKIT Tree Trimming Required - 10647 Ponderosa Dr
MARKIT Remove Drop - 15952 Tewksbury Dr
MARKIT Remove Drop - 12659 Crest Way
MARKIT Remove Drop - 16067 Martis Peak Rd
MARKIT Remove Drop - 12116 Highland Ave
MARKIT Remove Drop - 15806 Kent Dr
MARKIT Raise AT&T Service Drop - 10560 Larch St
MARKIT Remove Drop - 16455 Glenshire Dr
MARKIT Remove Drop - 14255 S Shore Dr
MARKIT Tree Trimming Required - 10389 St James Pl
MARKIT Tree Trimming Required - 16174 Lancaster Pl

MARKIT Remove Drop - 15811 Willow St
MARKIT Remove Drop - 10855 W River St
MARKIT Remove Drop - 15212 Point Dr
MARKIT Lower or Raise Existing - Other Comm - 14931 Denton Ave
MARKIT Remove Drop - 13821 Donner Pass Rd
MARKIT Remove Drop - 15379 Mare Ct
MARKIT Remove Drop - 15688 Archery View
MARKIT Remove Drop - 16483 Salmon St
MARKIT Remove Drop - 13434 Moraine Rd
MARKIT Remove Drop - 15619 Cottonwood Dr
MARKIT Remove Drop - 14981 Glenshire Dr
MARKIT Remove Drop - 10395 Stampede Meadows Rd
MARKIT Raise AT&T Service Drop - 10360 Olympic Blvd
MARKIT Remove Drop - 12697 Crest Way
MARKIT Remove Drop - 10577 Stuart Staithe
MARKIT Remove Drop - 15844 Archery View
MARKIT Remove Drop - 11748 Old Mill Rd
MARKIT Remove Drop - 11652 Silver Fir Circle
MARKIT Remove Drop - 14614 S Shore Dr
MARKIT Remove Drop - 15998 Old Highway Dr
MARKIT Lower or Raise Existing - Other Comm - 15790 Pine St
MARKIT Remove Drop - 15678 Spruce St
MARKIT Remove Drop - 10884 Silver Fir Dr
MARKIT Cable splices hanging out of closures
Tree on phone line
MARKIT guard arm broken supporting att 200 and 400 pair cables cross country lead but driveable, multiple access
MARKIT Straighten In-Line Pole - 41784 CA-70
MARKIT Lower or Raise Existing AT&T Cable - 1947 Greenhorn Rd
MARKIT Lower or Raise Existing AT&T Cable - 1533 Greenhorn Ranch Rd
MARKIT Straighten In-Line Pole - 10290 Crystal Lake Rd
MARKIT Tree Trimming Required - 41784 CA-70
MARKIT Tree Trimming Required - 48908 CA-70
MARKIT Replace/Install Down Guy - 179 Chandler Rd
MARKIT Tree Trimming Required - 2541 Rideout Trail
MARKIT Vegetation Removal Required - 41525 CA-70
MARKIT Lower or Raise Existing AT&T Cable - 1528 Lee Rd
MARKIT Lower or Raise Existing AT&T Cable - 1528 Lee Rd
MARKIT Lower or Raise Existing AT&T Cable - 1528 Lee Rd
MARKIT Remove Drop - 666 Lee Rd
MARKIT Remove Drop - 869 Bresciani Circle
MARKIT Remove Drop - 37333 Obsidian Way
MARKIT Remove Drop - 32 Bell Ln
MARKIT Remove Drop - 2852 Caribou Rd
MARKIT Remove Drop - 1151 Lee Rd

MARKIT Remove Drop - 565 Hillside Dr
MARKIT Remove Drop - 41379 West's Ranch Dr
MARKIT Lower or Raise Existing AT&T Drop - 666 Lee Rd
MARKIT Remove Drop - 2863 Caribou Rd
MARKIT Remove Drop - 2856 Caribou Rd
MARKIT Contact Local AT&T Office for Remediation - 15425 Bowman Lake Rd
MARKIT Contact Local AT&T Office for Remediation - 18152 Bowman Lake Rd
MARKIT Contact Local AT&T Office for Remediation - 13110 Bowman Lake Rd
MARKIT Remove Drop - 8180 Butterfly Valley-Twain Rd
MARKIT Raise AT&T Service Drop - 8175 Butterfly Valley-Twain Rd
IT 5302830854 customer number @10 Greenhorn Ranch rd. Service drop on ground parrellel to Hwy70. Needs replace
ad bad, needs communications transferred to new pole and separate anchor and guy installed on new pole to suppo
MARKIT Lower or Raise Existing AT&T Cable - 244 E Main St
MARKIT Lower or Raise Existing AT&T Cable - 13781 Strubels Ln
MARKIT Place Cross/Guard Arm - 15362 Doolittle Rd
MARKIT Lower or Raise Existing AT&T Cable - 13527 Mystic Mine Rd
MARKIT Place Cross/Guard Arm - 17921 Mustang Valley Pl
MARKIT Place Cross/Guard Arm - 18112 Mustang Valley Pl
MARKIT Replace/Install Down Guy - 16738 Indian Hill Circle
MARKIT Relash Existing Cables - 20205 McCourtney Rd
MARKIT Tree Trimming Required - 17511 CA-49

MARKIT Replace/Install Down Guy - 13388 Fernglen Ct
MARKIT Lower or Raise Existing AT&T Cable - 12893 Hidden Valley Rd
MARKIT Tree Trimming Required - 405 W Main St
MARKIT Remove Drop - 10299 Adam Ave
MARKIT Raise AT&T Service Drop - 12893 Hidden Valley Rd
MARKIT Tree Trimming Required - 15174 Beyers Ln
MARKIT Tree Trimming Required - 15326 Beyers Ln
MARKIT Remove Drop - 315 Hughes Rd
MARKIT Remove Drop - 10942 Sunrise Heights
MARKIT Remove Drop - 10700 Mountaineer Trail
MARKIT Raise AT&T Service Drop - 17692 Ridge Crest Ln
MARKIT Tree Trimming Required - 11228 McCourtney Rd
MARKIT Remove Drop - 14566 Talking Pines Rd
MARKIT Remove Drop - 17753 Cindy Ln
MARKIT Remove Drop - 15066 Chattering Pines Rd
MARKIT Remove Drop - 12297 Nevada City Hwy
MARKIT Remove Drop - 345 Carol Dr
MARKIT Remove Drop - 110 Doris Dr
MARKIT Remove Drop - 10563 Sierra Dr
MARKIT Tree Trimming Required - 13396 Bitney Springs Rd
MARKIT Remove Drop - 406 W Main St
MARKIT Straighten In-Line Pole - 11122 Bonnie View Way

MARKIT Raise AT&T Mainline Cable - 10606 Pekolee Dr
MARKIT Vegetation Removal Required - 15332 Auburn Rd
MARKIT Replace/Install Down Guy - 10846 Ball Rd
MARKIT Raise AT&T Mainline Cable - 13283 Allison Ranch Rd
MARKIT Vegetation Removal Required - 12005 Allison Ranch Rd
MARKIT Tree Trimming Required - 606 Kechley Ave
MARKIT Replace/Install Down Guy - 16837 Lena Ct
MARKIT Relash Existing Cables - 10159 Quail Creek Dr
MARKIT Vegetation Removal Required - 10851 Thornicroft Way
MARKIT Replace/Install Down Guy - 16431 Old State Hwy
MARKIT Lower or Raise Existing AT&T Drop - 15338 Penfold Pl
MARKIT Remove Drop - 11281 Sunset Way
MARKIT Remove Drop - 11195 Bixler Pl
MARKIT Remove Drop - 10516 Quail Dr
MARKIT Remove Drop - 12528 Allison Ranch Rd
MARKIT Raise AT&T Service Drop - 11671 Allison Ranch Rd
MARKIT Remove Drop - 15924 Names Dr
MARKIT Remove Drop - 11305 Pekolee Dr
AT&T Cable(s)Transfer AT&T Terminal(s)Transfer AT&T Drop(s);Pull Old Pole;Lead Tails No;Cable Swing Yes;Trasfer 2 -
MARKIT Lines down in road#attatchment failure
MARKIT Straighten In-Line Pole - 16458 Frenchtown Rd
MARKIT Lower or Raise Existing AT&T Drop - 15474 Marina Dr
MARKIT Lower or Raise Existing Cable - 134 Belle St
MARKIT Vegetation Removal Required - 13317 La Porte Rd
MARKIT Vegetation Removal Required - 13410 Old La Porte Rd
MARKIT Replace/Install Down Guy - 15515 Niels Meade Dr
MARKIT Raise AT&T Mainline Cable - 1040 Foote Crossing Rd
MARKIT Tree Trimming Required - 12463 Bean Clipper Rd
MARKIT Replace/Install Down Guy - 119 E River St
MARKIT Tree Trimming Required - 9332 La Porte Rd
MARKIT Raise AT&T Mainline Cable - 13408 Capitol Dr
MARKIT Tree Trimming Required - 16455 Frenchtown Rd
MARKIT Relash to existing Messenger - CA-49
MARKIT Vegetation Removal Required - 16322 Frenchtown Rd
MARKIT Vegetation Removal Required - 12177 La Porte Rd
MARKIT Tree Trimming Required - 15801 Frenchtown Rd
MARKIT Tree Trimming Required - 9256 La Porte Rd
MARKIT Vegetation Removal Required - 13989 La Porte Rd
MARKIT Vegetation Removal Required - 9256 La Porte Rd
MARKIT Vegetation Removal Required - 18947 New York Flat Rd
MARKIT Vegetation Removal Required - 13989 La Porte Rd
MARKIT Tree Trimming Required - 15697 Frenchtown Rd
MARKIT Tree Trimming Required - 10115 La Porte Rd
MARKIT Vegetation Removal Required - 9256 La Porte Rd

MARKIT Replace/Install Down Guy - 16008 Mt Olive Rd
MARKIT Relash to existing Messenger - 15594 Poverty Pond Rd
MARKIT Tree Trimming Required - 8742 La Porte Rd
MARKIT Replace/Install Down Guy - 16770 CA-49
MARKIT Vegetation Removal Required - 9827 La Porte Rd
MARKIT Tree Trimming Required - 18644 New York Flat Rd
MARKIT Tree Trimming Required - 167 Binet Rd
MARKIT Vegetation Removal Required - 9692 La Porte Rd
MARKIT Replace/Install Down Guy - 15934 Mt Olive Rd
MARKIT Tree Trimming Required - 16382 Frenchtown Rd
MARKIT Tree Trimming Required - 17340 Hummingbird Ln
MARKIT Place Cross/Guard Arm - 245 Main St
MARKIT Lower or Raise Existing Cable - 104 E River St
MARKIT Place Cross/Guard Arm - Pliocene Ridge Rd
MARKIT Lower or Raise Existing Cable - 495 Mountain House Rd
MARKIT Place Cross/Guard Arm - Pliocene Ridge Rd
MARKIT Repair/Replace Hardware - 700 Kanaka Rd
MARKIT Remove Drop - 8556 La Porte Rd
MARKIT Lower or Raise Existing Cable - 9726 Ruff Hill Trail
MARKIT Remove Drop - 9381 La Porte Rd
MARKIT Relash Existing Cables - 17340 Hummingbird Ln
MARKIT Tree Trimming Required - 349 Main St
MARKIT Remove Drop - 16918 Halverson Way
MARKIT Tree Trimming Required - 327 Commercial St
MARKIT Tree Trimming Required - 360 Main St
MARKIT Vegetation Removal Required - 16190 Thistle Way
MARKIT Tree Trimming Required - 245 Main St
MARKIT Tree Trimming Required - 359 Main St
MARKIT Remove Drop - 347 Goodyear Creek Rd
MARKIT Tree Trimming Required - Hells Half Acre
MARKIT Tree Trimming Required - 233 Main St
MARKIT Remove Drop - 9862 La Porte Rd
MARKIT Tree Trimming Required - 123 Main St
MARKIT Contact Local AT&T Office for Remediation - 15519 Greenhorn Rd
MARKIT Contact Local AT&T Office for Remediation - 632 Mammoth Springs Rd
MARKIT Remove Drop - 14727 Sontag Rd
MARKIT Remove Drop - 8927 La Porte Rd
MARKIT Vegetation Removal Required - 280 Goodyear Creek Rd
MARKIT Remove Drop - 102 Big Fur Rd
MARKIT Remove Drop - 16 Buckeye Dr
MARKIT Vegetation Removal Required - 294 Binet Rd
MARKIT Remove Drop - 45 Larem Ln
MARKIT Remove Drop - 14102 Judy Ln
MARKIT Remove Drop - 1459 Little Grass Valley Rd

MARKIT Remove Drop - 31 Jimmy Ct
MARKIT Remove Drop - 12711 Pearson Rd
MARKIT Vegetation Removal Required - 369 Goodyear Creek Rd
MARKIT Remove Drop - 15474 Marina Dr
MARKIT Remove Drop - 102 Mountain House Rd
MARKIT Remove Drop - 134 Belle St
MARKIT Remove Drop - 9093 Nero Rd
MARKIT Remove Drop - Foote Crossing Rd
MARKIT Remove Drop - 411 Goodyear Creek Rd
MARKIT Remove Drop - 8492 La Porte Rd
MARKIT Vegetation Removal Required - 397 Goodyear Creek Rd
MARKIT Remove Drop - 15111 Orchard Springs Rd
MARKIT Place Cross/Guard Arm - 15256 Kilham Circle
MARKIT Place Cross/Guard Arm - 11045 Tyler Foote Rd
MARKIT Place Cross/Guard Arm - 22858 Pleasant Valley Rd
MARKIT Raise AT&T Mainline Cable - 22676 Pleasant Valley Rd
MARKIT Replace/Install Down Guy - 19774 Oak Tree Rd
MARKIT Raise AT&T Mainline Cable - 27515 Blue Sage Way
MARKIT Remove Drop - 20305 Pleasant Valley Rd
MARKIT Raise AT&T Service Drop - 22570 Pleasant Valley Rd
MARKIT Rural wire extremely close in midspan to power. Need lowering or replacement to lower
MARKIT Place Cross/Guard Arm - 13035 Sadie D Dr
MARKIT Lower or Raise Existing Cable - 22912 Scotts Flat Rd
MARKIT Straighten In-Line Pole - 16564 Old Downieville Hwy
MARKIT Lower or Raise Existing AT&T Cable - 16681 Maybert Rd
MARKIT Place Cross/Guard Arm - 10814 Genasci Rd
MARKIT Repair/Replace Hardware - 13515 Banner Mountain Trail
MARKIT Straighten In-Line Pole - 12727 Lower Colfax Rd
MARKIT Straighten In-Line Pole - 13779 Crawford Ln
MARKIT Relash to existing Messenger - 20750 CA-20
MARKIT Raise AT&T Mainline Cable - 20750 CA-20
MARKIT Raise AT&T Mainline Cable - 13479 Gracie Rd
MARKIT Raise AT&T Mainline Cable - 17895 Maybert Rd
MARKIT Raise AT&T Mainline Cable - 10450 Harmony Ridge Resort Rd
MARKIT Raise AT&T Mainline Cable - 12771 Joe Day Ranch Rd
MARKIT Remove Cable - 20860 CA-20
MARKIT Remove Cable - 20978 CA-20
MARKIT Raise AT&T Mainline Cable - 23896 CA-20
MARKIT Raise AT&T Mainline Cable - 15052 Lolas Echo Rd
MARKIT Raise AT&T Mainline Cable - 12765 Quaker Hill Cross Rd
MARKIT Raise AT&T Mainline Cable - 12827 Quaker Hill Cross Rd
MARKIT Raise AT&T Mainline Cable - 14806 Red Dog Rd
MARKIT Raise AT&T Mainline Cable - 14854 Red Dog Rd
MARKIT Relash Existing Cables - 12003 La Barr Meadows Rd

MARKIT Raise AT&T Mainline Cable - 19626 CA-20
MARKIT Raise AT&T Mainline Cable - 24131 CA-20
MARKIT Raise AT&T Mainline Cable - 10747 Red Dog Rd
MARKIT Raise AT&T Mainline Cable - 12197 Poke Pl
MARKIT Raise AT&T Mainline Cable - 17515 CA-20
MARKIT Remove Cable - 20928 CA-20
MARKIT Raise AT&T Mainline Cable - 16343 Cooper Rd
MARKIT Raise AT&T Mainline Cable - 14573 N Bloomfield Rd
MARKIT Raise AT&T Mainline Cable - 11777 Kathryn Ln
MARKIT Raise AT&T Mainline Cable - 10085 Banner Lava Cap Rd
MARKIT Raise AT&T Mainline Cable - 12302 Buckeye Rd
MARKIT Lower or Raise Existing Cable - 14700 N Bloomfield Rd
MARKIT Lower or Raise Existing Cable - 757 Old Washington Rd
MARKIT Intrusive Inspection Required - 13676 Quaker Hill Cross Rd
MARKIT Lower or Raise Existing AT&T Cable - 13515 Banner Mountain Trail
MARKIT Lower or Raise Existing Cable - 12577 Cedar Crest Ct
MARKIT Repair/Replace Hardware - 23092 CA-20
MARKIT Raise AT&T Service Drop - 502 Kate Hayes St
MARKIT Remove Drop - 10501 Banner Lava Cap Rd
MARKIT Remove Drop - 10836 Footwall Dr
MARKIT Remove Drop - 10827 Banner Lava Cap Rd
MARKIT Contact Local AT&T Office for Remediation - 19888 CA-20
MARKIT Contact Local AT&T Office for Remediation - 438 Kate Hayes St
MARKIT Remove Drop - 13673 Lightning Tree Rd
MARKIT Raise AT&T Service Drop - 13996 Bear Run Rd
MARKIT Remove Drop - 757 Old Washington Rd
MARKIT Remove Drop - 12300 Short Circle
MARKIT Remove Drop - 10493 Cole Way
MARKIT Raise AT&T Service Drop - 13241 Dog Bar Rd
MARKIT Remove Drop - 712 S Auburn St
MARKIT Remove Drop - 15100 Old Washington Rd
MARKIT Vegetation Removal Required - 25626 CA-20
MARKIT Remove Drop - 14848 N Bloomfield Rd
MARKIT Remove Drop - 13287 Rattlesnake Rd
MARKIT Raise AT&T Service Drop - 13901 Colfax Hwy
MARKIT Remove Drop - 11275 Crescent Dr
MARKIT Remove Drop - 13557 Sunshine Valley Rd
MARKIT Relash Existing Cables - 15569 Glacier Way
MARKIT Replace/Install Down Guy - 14080 Hansel Ave

MARKIT Relash to existing Messenger - 11770 Snowpeak Way
MARKIT Raise AT&T Mainline Cable - 11899 Muhlebach Way
MARKIT Raise AT&T Service Drop - 11487 Alder Dr
MARKIT Transfer AT&T Cable(s);Pull Old Pole;Lead Tails No;Cable Swing Yes;Trasfer 1 - 10381 Snow Shoe Circle

MARKIT Remove Drop - 11897 Rainbow Dr
AT&T Cable(s)Replace/Install Down GuyRemove Anchor;Pull Old Pole;Lead Tails No;Cable Swing No;Trasfer 5 - 11855
MARKIT Remove Drop - 12165 Bernese Ln
MARKIT Remove Drop - 13476 Hillside Dr
MARKIT Remove Drop - 13231 Oberwald Way
MARKIT Remove Drop - 10098 E Alder Creek Rd
MARKIT Remove Drop - 13421 Davos Dr
MARKIT Remove Drop - 13851 Copenhagen Dr
MARKIT Remove Drop - 11673 Rhineland Ave
MARKIT Remove Drop - 10089 E Alder Creek Rd
MARKIT Remove Drop - 10580 Whitetail Ct
MARKIT Remove Drop - 14110 Glacier View Dr
MARKIT Remove Drop - 13921 Hansel Ave
MARKIT Remove Drop - 14514 Hansel Ave
MARKIT Remove Drop - 13830 Ski View Loop
MARKIT Raise AT&T Service Drop - 14779 Copenhagen Dr
MARKIT Remove Drop - 12903 Ski View Loop
MARKIT Remove Drop - 12235 Landeau Ln
MARKIT Remove Drop - 14535 Wolfgang Rd
MARKIT Remove Drop - 11255 Beacon Rd
MARKIT Remove Drop - 13886 Hansel Ave
MARKIT Remove Drop - 12074 Bernese Ln
MARKIT Remove Drop - 13687 Heidi Way
MARKIT Remove Drop - 10515 Laurelwood Dr
MARKIT Raise AT&T Service Drop - 12784 Lee Rd
MARKIT Remove Drop - 12185 Sierra Dr
MARKIT Remove Drop - 12150 Muhlebach Way
MARKIT Tree Trimming Required - 12268 Bernese Ln
MARKIT Remove Drop - 11725 Tundra Dr
MARKIT Vegetation Removal Required - 18570 Bear Canyon Rd
MARKIT Repair/Replace Hardware - 10261 Lake Spaulding Rd
MARKIT Repair/Replace Hardware - 11112 Bowman Lake Rd
MARKIT Repair/Replace Hardware - 40070 CA-20
MARKIT Straighten In-Line Pole - 13291 Bowman Lake Rd
MARKIT Repair/Replace Hardware - 43034 Laing Rd
MARKIT Lower or Raise Existing AT&T Drop - 34265 Alta Bonnynook Rd
MARKIT Place Cross/Guard Arm - 295 Drum Forebay Rd
MARKIT Repair/Replace Hardware - 42005 Nyack Rd
MARKIT Repair/Replace Hardware - 10251 Lake Spaulding Rd
MARKIT Repair/Replace Hardware - 10280 Lake Spaulding Rd
MARKIT Replace/Install Down Guy - 440 Caine Rd

MARKIT Intrusive Inspection Required - 40225 Airport Rd
MARKIT Raise AT&T Service Drop - 565 Serenity Ln

MARKIT Contact Local AT&T Office for Remediation - Blue Canyon Rd
MARKIT Remove Drop - 10280 Lake Spaulding Rd
MARKIT Remove Drop - 150 Bonnynook Rd
MARKIT Remove Drop - 10261 Lake Spaulding Rd
MARKIT Remove Drop - 10255 Lake Spaulding Rd
MARKIT Remove Drop - 39950 CA-20
MARKIT Raise AT&T Service Drop - 34260 Alta Bonnynook Rd
MARKIT Remove Drop - 31190 Gold Run Rd
MARKIT Remove Drop - 110 Oakleaf Dr
MARKIT Remove Drop - 179 5th St
MARKIT Remove Drop - 157 Claremont Ct
MARKIT Remove Drop - 157 Claremont Ct
MARKIT Remove Drop - 1237 Pioneer Rd
MARKIT Remove Drop - 146 3rd St
MARKIT Remove Drop - 870 Haskins Circle
MARKIT Remove Drop - 138 Sugar Pine Dr
MARKIT Rural wire down due to dead tree attachment,crossing roadway. Creating obstruction to traffic
MARKIT Lower or Raise Existing Cable - 14942 Skislope Way
MARKIT Remove Drop - 22207 Spruce St
MARKIT Remove Drop - 22216 Cedar St
MARKIT Tree branch on cables.
MARKIT Lines down along Hwy70 @P2341 e main st. Suspect hardware off pole.
MARKIT Drops down along Hwy 70 @ P5 e-o main,hwy 70.
MARKIT Lines on ground-low, 5302830311
MARKIT Service drops hazzard along side roadway and customer property.needs replacement, and rehab mpoe.
Equipment needs transferred
MARKIT Large oak on cable, also, attachment broken 2000ft beyond.
MARKIT Multiple Trees down on cable.
MARKIT Hazzard drp across driveways.
MARKIT Drop needs to be removed from hazzard tree along roadside. Rerouted or moved out of clearance.
'atituchi rural wire down due to tree fall. Service drop is temp repair, laying along forest service road causing hazzard.n
MARKIT Need tree trimming to clear cable
MARKIT Vegatation control needed for vault access to r.t. site
MARKIT Service drop to 7175 sylvan rd laying on ground two spans. Need to access and repairASW or replace section.
MARKIT Vegetation control for fire safety and splice vault access. Parking access to R.T. site and bbox needed.
MARKIT R.T. Site needs vegetation clearing for safety issue. Remove vegetation for fire safety concerns in area.
MARKIT Vegetation neds to be cleared for fire safety and access to splice pedestal.safety issue-hazzardous.
etation blocking access to sidewalk box splice vault. Needs clearing for access and fire control surrounding R.T. site. S
MARKIT R.T. site@ P1 B6 smithneck rd,need vegetation control fire work safety and fire danger.
MARKIT Removed excess vegetation at R.T. site, 200x Lundy ln.. Fire and safety issue.
MARKIT Remove tree off cable along highway 70
MARKIT R.T. Site @P21 smithneckrd, needs brush control for fire safety and clear work environment.
MARKIT R.T. Site P139 Hwy70. Remove brush to create safe work environment and fire safety.
MARKIT Remove asw abandoned off house,hanging over driveway at midspan.

MARKIT Remove excess vegetation surrounding r.t site@P7 old mill pond rd
MARKIT Removed excess vegetation for work and fire safety
MARKIT Remove excess vegetation for fire safty and work safety protection.
MARKIT Vegetation needs clean up for work and fire safety
MARKIT Service cable and drops along raodway, need repairs
MARKIT Line down in access. 5309934296
MARKIT Asw down along side state Hwy70, car pole incident.
MARKIT ASW down after car,pole incident. Laying along side State Hwy70
MARKIT Aerial drop down,need replacement or reattchment. loyalton fire complex. 5309934296
MARKIT Asw on ground, reported to tech from loacal power company.
MARKIT Reported to tech via local power company, service drop on ground.
MARKIT Service drp down and tangled. Reported by local power company
MARKIT ASWDown on ground,state HWY 70, needs to be cleared, from road way and reattached.
MARKIT Tree Trimming Required - 3 Woolley Rd
MARKIT Raise AT&T Mainline Cable - 35370 Baxter Rd
MARKIT Tree Trimming Required - 440 Caine Rd
MARKIT Tree Trimming Required - 27297 Norton Grade Rd
MARKIT Vegetation Removal Required - 28045 Manzanita Trail
MARKIT Vegetation Removal Required - 13952 Moonshine Rd
MARKIT Tree Trimming Required - 13747 Moonshine Rd
MARKIT Vegetation Removal Required - 15953 State Highway 49
MARKIT Vegetation Removal Required - 15679 Cleveland Ave
MARKIT Vegetation Removal Required - 15987 Cleveland Ave
MARKIT Tree Trimming Required - 14682 Marysville Rd
MARKIT Tree Trimming Required - 13746 Moonshine Rd
MARKIT Vegetation Removal Required - 16834 State Highway 49
MARKIT Tree Trimming Required - 14918 Kelly Rd
MARKIT Tree Trimming Required - 13855 Moonshine Rd
MARKIT Tree Trimming Required - 9094 Hiatt Ln
MARKIT Tree Trimming Required - 8870 Idlewood Circle
MARKIT Tree Trimming Required - 18615 New York Flat Rd

MARKIT Relash Existing Cables - 5101 State Highway 49

MARKIT Raise AT&T Mainline Cable - 32565 Frost Hill Pl

MARKIT Raise AT&T Mainline Cable - 635 Frost Hill Rd

MARKIT Relash Existing Cables - 35151 Baxter Rd

MARKIT Replace/Install Down Guy - 10982 Bowman Lake Rd
MARKIT Vegetation Removal Required - 440 Caine Rd
MARKIT Vegetation Removal Required - 510 Lee Rd
MARKIT Tree Trimming Required - 1709 Ridge Rd

MARKIT Relash Existing Cables - 14421 You Bet Rd
MARKIT Tree Trimming Required - 15648 Greenhorn Rd
MARKIT Tree Trimming Required - 12942 Boreham Ln
MARKIT Tree Trimming Required - 450 Bennett St
MARKIT Vegetation Removal Required - 17548 State Highway 49
MARKIT Vegetation Removal Required - 15740 De Groot Ln
MARKIT Tree Trimming Required - 15448 Cleveland Ave
MARKIT Vegetation Removal Required - 16134 Mountain House Rd
MARKIT Tree Trimming Required - 104 Village Way
MARKIT Vegetation Removal Required - 104 Main St
MARKIT Tree Trimming Required - Hells Half Acre
MARKIT Tree Trimming Required - 13348 Grass Valley Ave
MARKIT Tree Trimming Required - 12845 Francis Dr
MARKIT Replace/Install Down Guy - 14449 Lower Colfax Rd
MARKIT Tree Trimming Required - 13055 La Barr Meadows Rd
MARKIT Remove Drop - 34145 Alta Bonnynook Rd
MARKIT Remove Drop - 128 Main St
MARKIT Remove Drop - 257 Sunnyside Dr
MARKIT Remove Drop - 14520 Pendola Rd
MARKIT Remove Drop - 32565 Frost Hill Pl
MARKIT Remove Drop - 597 Sacramento St
MARKIT Remove Drop - 32687 Main St
MARKIT Remove Drop - 489 Alta Powerhouse Rd
MARKIT Remove Drop - Gold Run School Rd
MARKIT Remove Drop - 11028 Bowman Lake Rd
MARKIT Remove Drop - 11710 La Porte Rd
MARKIT Raise AT&T Service Drop - 300 Canyon Mine Rd
MARKIT Remove Drop - 777 Blue Canyon Rd
MARKIT Remove Drop - 8492 La Porte Rd
MARKIT Remove Drop - 16586 Willow Glen Rd
MARKIT Remove Drop - 16548 Willow Glen Rd
MARKIT Remove Drop - 10066 Smith Rd
MARKIT Remove Drop - 12808 Francis Dr
MARKIT Remove Drop - 11912 Black Oak Dr
MARKIT Remove Drop - 125 E Empire St

MARKIT Remove Drop - 928 Sacramento St
MARKIT Remove Drop - 321 Empire Ct
MARKIT Remove Drop - 10451 Pittsburg Rd
MARKIT Remove Drop - 15862 Rattlesnake Rd
MARKIT Remove Drop - 10292 Sugar Pine Ct
MARKIT Remove Drop - 12577 Butterfly Dr
MARKIT Remove Drop - 13334 La Barr Meadows Rd
MARKIT Remove Drop - 11337 Grange Ct
MARKIT Remove Drop - 511 Miners St
MARKIT Remove Drop - 221 Main St
MARKIT Remove Drop - 13390 La Barr Meadows Rd
MARKIT Remove Drop - 13183 Wood Rose Way
MARKIT Remove Drop - 15438 Lorie Dr
MARKIT Remove Drop - 16259 Rattlesnake Rd
MARKIT Remove Drop - 11478 Avern Way
MARKIT Remove Drop - 14608 Dog Bar Rd
MARKIT Remove Drop - 12210 Valley View Rd
MARKIT Remove Drop - 13859 Greenhorn Rd
MARKIT Remove Drop - 19919 Casa Loma Dr
MARKIT Remove Drop - 10079 Crestview Dr
MARKIT Remove Drop - 15365 Birch Meadows Circle
MARKIT Remove Drop - 13431 La Barr Meadows Rd

MARKIT Replace/Install Down Guy - 13420 Sunshine Valley Rd
MARKIT Tree Trimming Required - 10883 Pine Hill Dr
MARKIT Remove Drop - 13671 Meadow View Dr
MARKIT Remove Drop - 12118 Sunshine Valley Rd
MARKIT Remove Drop - 11121 Cedar Ridge Dr
MARKIT Remove Drop - 11071 Cedar Ridge Dr
MARKIT Raise AT&T Service Drop - 13420 Sunshine Valley Rd
MARKIT Remove Drop - 12442 Gayle Ln
MARKIT Remove Drop - 10037 Cornette Way
MARKIT Remove Drop - 13964 Birch Rd
MARKIT Remove Drop - 12442 Valley View Rd
MARKIT Remove Drop - 11173 Cedar Ridge Dr
MARKIT Tree Trimming Required - 11638 Donner Pass Rd
MARKIT Tree Trimming Required - 30 Hayes Rd
MARKIT Tree Trimming Required - 102 Main St
MARKIT Tree Trimming Required - 104 Main St
MARKIT Tree Trimming Required - 115 Main St
MARKIT Tree Trimming Required - 120 Main St
MARKIT Tree Trimming Required - 135 Wild Plum Rd

MARKIT Tree Trimming Required - 10990 Donner Pass Rd
MARKIT Tree Trimming Required - 118 Wild Plum Rd
MARKIT Remove Drop - 12131 Sierra Dr E
MARKIT Remove Drop - 15226 Alder Creek Rd
MARKIT Remove Drop - 14075 Herringbone Way
MARKIT Remove Drop - 12295 Stockholm Way
MARKIT Remove Drop - 11628 Sitzmark Way
MARKIT Remove Drop - 11400 Sun Valley Rd
MARKIT Remove Drop - 10986 Bolzano Dr
MARKIT Remove Drop - 11709 Tundra Dr
MARKIT Remove Drop - 11754 Chalet Rd
MARKIT Remove Drop - 14128 Hansel Ave
MARKIT Remove Drop - 13687 Heidi Way
MARKIT Remove Drop - 11742 Bull Pine Trail
MARKIT Remove Drop - 12298 Lemon Ct
MARKIT Remove Drop - 10556 Jeffrey Way
MARKIT Remove Drop - 10725 Jeffrey Way
MARKIT Remove Drop - 14019 Ramshorn St
MARKIT Remove Drop - 12870 Northwoods Blvd
MARKIT Remove Drop - 14095 Glacier View Dr
MARKIT Remove Drop - 14796 Copenhagen Dr
MARKIT Remove Drop - 12958 Hansel Ave
MARKIT Remove Drop - Teton Way
MARKIT Remove Drop - 10319 Prosser Dr
MARKIT Remove Drop - 11677 Northwoods Blvd
MARKIT Remove Drop - 12275 Stockholm Way
MARKIT Remove Drop - 12292 Viking Way
MARKIT Remove Drop - 13945 Ski View Loop
MARKIT Remove Drop - 11291 Zermatt Dr
MARKIT Remove Drop - 13466 Hillside Dr
MARKIT Remove Drop - 14600 Copenhagen Dr
MARKIT Remove Drop - 11435 Norse Ave
MARKIT Remove Drop - 11627 Baden Rd
MARKIT Remove Drop - 12946 Davos Dr
MARKIT Remove Drop - 14521 Wolfgang Rd
MARKIT Remove Drop - 10829 Barnes Dr
MARKIT Remove Drop - 10423 Lenelle Ln
MARKIT Remove Drop - 10826 Heather Rd
MARKIT Remove Drop - 10103 E Alder Creek Rd
MARKIT Remove Drop - 11171 Alder Dr
MARKIT Remove Drop - 12023 Rainbow Dr
MARKIT Remove Drop - 12479 Greenwood Dr
MARKIT Remove Drop - 13312 Hansel Ave
MARKIT Remove Drop - 14052 Ramshorn St

MARKIT Remove Drop - 14396 Hansel Ave
MARKIT Remove Drop - 11753 Nordic Ln
MARKIT Remove Drop - 12018 Kitzbuhel Rd
MARKIT Remove Drop - 14096 Ramshorn St
MARKIT Remove Drop - 12127 Bernese Ln
MARKIT Remove Drop - 11851 Saint Bernard Dr
MARKIT Remove Drop - 13232 Falcon Point Pl
MARKIT Remove Drop - 14768 Wolfgang Rd
MARKIT Remove Drop - 13168 Davos Dr
MARKIT Remove Drop - 13421 Davos Dr
MARKIT Remove Drop - 12715 Palisade St
MARKIT Remove Drop - 11751 Chateau Way
MARKIT Remove Drop - 12398 Greenleaf Way
MARKIT Remove Drop - 14913 Swiss Ln
MARKIT Remove Drop - 10512 Mougle Ln
MARKIT Remove Drop - 14100 Ski View Loop
MARKIT Remove Drop - 10715 Ski Slope Way
MARKIT Remove Drop - 13286 Davos Dr
MARKIT Remove Drop - 13230 Oberwald Way
MARKIT Remove Drop - 11852 Ski Slope Way
MARKIT Remove Drop - 15075 Wolfgang Rd
MARKIT Remove Drop - 11175 Zermatt Dr
MARKIT Remove Drop - 14048 Ski View Loop
MARKIT Remove Drop - 14274 Hansel Ave
MARKIT Remove Drop - 12878 Ski View Loop
MARKIT Remove Drop - 14737 Copenhagen Dr
MARKIT Remove Drop - 11733 Kitzbuhel Rd
MARKIT Remove Drop - 13271 Ski Slope Way
MARKIT Remove Drop - 12025 Bennett Flat Rd
MARKIT Remove Drop - 11400 Chamonix Rd
MARKIT Remove Drop - 12811 Dulzura St
MARKIT Remove Drop - 14378 Copenhagen Dr
MARKIT Remove Drop - 11281 Zermatt Dr
MARKIT Remove Drop - 12966 Dulzura St
MARKIT Remove Drop - 12136 Muhlebach Way
MARKIT Remove Drop - 12312 Sierra Dr E
MARKIT Remove Drop - 13907 Hansel Ave
MARKIT Remove Drop - 11866 Kitzbuhel Rd
MARKIT Remove Drop - 12508 Saint Bernard Dr
MARKIT Remove Drop - 10687 Mougle Ln
MARKIT Remove Drop - 12210 Sierra Dr E
MARKIT Remove Drop - 11598 Rhineland Ave
MARKIT Remove Drop - 11239 Ski Slope Way
MARKIT Remove Drop - 11683 Bennett Flat Rd

MARKIT Remove Drop - 14914 Slalom Way
MARKIT Remove Drop - 11891 Chalet Rd
MARKIT Remove Drop - 14232 Saint Croix Way

MARKIT Relash Existing Cables - 17748 Maybert Rd

MARKIT Raise AT&T Mainline Cable - 19035 Siesta Dr
MARKIT Tree Trimming Required - 13113 Quaker Hill Cross Rd
MARKIT Tree Trimming Required - 504 Moon Ridge Rd
MARKIT Tree Trimming Required - 554 E Broad St
MARKIT Tree Trimming Required - 306 American Hill Rd
MARKIT Tree Trimming Required - 345 American Hill Rd
MARKIT Tree Trimming Required - 15415 Lake Vera Purdon Rd

MARKIT Relash Existing Cables - 10901 Genasci Rd

MARKIT Raise AT&T Mainline Cable - 16304 Cooper Rd
MARKIT Tree Trimming Required - 18561 Yuba-Donner Scenic Byway
MARKIT Tree Trimming Required - 15474 Airport Rd
MARKIT Tree Trimming Required - 15474 Airport Rd
MARKIT Tree Trimming Required - 13226 Quaker Hill Cross Rd
MARKIT Tree Trimming Required - 18167 Yuba-Donner Scenic Byway
MARKIT Tree Trimming Required - 524 N Pine St

MARKIT Relash Existing Cables - 19311 State Highway 20
MARKIT Tree Trimming Required - 14098 Quaker Hill Cross Rd
MARKIT Tree Trimming Required - 10770 Garden Ln
MARKIT Tree Trimming Required - 18325 Lake Forest Dr
MARKIT Tree Trimming Required - 18552 State Highway 20
MARKIT Tree Trimming Required - 13833 Lake Wildwood Dr

MARKIT Relash Existing Cables - 550 N Pine St

MARKIT Tree Trimming Required - 13313 Bodie Ridge Rd

MARKIT Relash Existing Cables - 18474 Easy St
MARKIT Tree Trimming Required - 18031 Penn Valley Dr
MARKIT Tree Trimming Required - 13284 Thistle Loop

MARKIT Relash Existing Cables - 10455 Conservation Rd
MARKIT Remove Drop - 10227 Missouri Bar Rd
MARKIT Remove Drop - 10555 Devonshire Circle
MARKIT Remove Drop - 14663 Pear Tree Ln
MARKIT Remove Drop - 10500 Sun Shadow Circle
MARKIT Remove Drop - 17610 Shoshoni Trail Ct
MARKIT Remove Drop - 15547 Old Downieville Hwy
MARKIT Remove Drop - 10575 Crows Nest Ln
MARKIT Remove Drop - 11023 Berggren Ln
MARKIT Remove Drop - 14263 Idaho Maryland Rd
MARKIT Remove Drop - 12199 Red Dog Rd
MARKIT Remove Drop - 16797 Yuba-Donner Scenic Byway
MARKIT Remove Drop - 11475 Burkard Ln
MARKIT Remove Drop - 21252 Running Horse Rd
MARKIT Remove Drop - 11464 Banner Mountain Trail
MARKIT Remove Drop - 14098 Quaker Hill Cross Rd
MARKIT Remove Drop - 12247 Pasquale Rd
MARKIT Remove Drop - 10625 Willow Ln
MARKIT Remove Drop - 18325 Piper Ln
MARKIT Remove Drop - 13853 Beitler Rd
MARKIT Remove Drop - 13441 Banner Lava Cap Rd
MARKIT Remove Drop - 17151 Country Circle
MARKIT Raise AT&T Service Drop - 11387 Meadow View Way
MARKIT Tree Trimming Required - 13441 Gracie Rd
MARKIT Remove Drop - 20107 Big Oak Dr
MARKIT Straighten In-Line Pole - 24223 Pleasant Valley Rd

MARKIT Straighten In-Line Pole - 16778 Maybert Rd
MARKIT Tree Trimming Required - 22630 Pleasant Valley Rd
MARKIT Tree Trimming Required - 22630 Pleasant Valley Rd
MARKIT Tree Trimming Required - 27955 Sweetland Rd
MARKIT Tree Trimming Required - 26281 Yuba-Donner Scenic Byway
MARKIT Tree Trimming Required - 23381 Pleasant Valley Rd
MARKIT Tree Trimming Required - 22286 Pleasant Valley Rd
MARKIT Tree Trimming Required - 19610 Oak Tree Rd

MARKIT Relash Existing Cables - 18848 State Highway 20
MARKIT Vegetation Removal Required - 16756 Maybert Rd
MARKIT Tree Trimming Required - 12998 Quaker Hill Cross Rd
MARKIT Tree Trimming Required - 13160 Quaker Hill Cross Rd
MARKIT Vegetation Removal Required - 22042 State Highway 20
MARKIT Tree Trimming Required - 540 Ellen Ave
MARKIT Tree Trimming Required - 278 Bella Vista Dr
MARKIT Tree Trimming Required - 480 E Spruce Ave
MARKIT Tree Trimming Required - 297 W Loyalton Ave
MARKIT Tree Trimming Required - 96 1st Ave
MARKIT Tree Trimming Required - 540 E Loyalton Ave
MARKIT Tree Trimming Required - 6107 Semaphore Rd
MARKIT Tree Trimming Required - 73875 Old County Rd
MARKIT Tree Trimming Required - 324 Bella Vista Dr
MARKIT Tree Trimming Required - 636 West St
MARKIT Tree Trimming Required - 280 5th Ave
MARKIT Tree Trimming Required - 267 E Sierra St
MARKIT Tree Trimming Required - 640 Redbud St
MARKIT Tree Trimming Required - 76696 Aspen Dr
MARKIT Tree Trimming Required - 14843 Lewis Rd
MARKIT Vegetation Removal Required - 725 Nevada St
MARKIT Vegetation Removal Required - 16447 State Highway 20
MARKIT Tree Trimming Required - 12600 Vicki Dr
MARKIT Tree Trimming Required - 27007 Sweetland Rd
MARKIT Tree Trimming Required - 19672 Oak Tree Rd
MARKIT Tree Trimming Required - 11463 Tyler Foote Rd
MARKIT Tree Trimming Required - 27001 Yuba-Donner Scenic Byway
MARKIT Tree Trimming Required - 27039 Yuba-Donner Scenic Byway

MARKIT Relash Existing Cables - 25675 Yuba-Donner Scenic Byway

MARKIT Raise AT&T Mainline Cable - 24368 Pleasant Valley Rd

MARKIT Intrusive Inspection Required - 12700 Robinson Rd
MARKIT 5302839005. BSW temp on ground. Needs hazzard removed. Dig isolated.
MARKIT Remove Drop - 353 S Redberg Ave

MARKIT Remove Drop - 11100 Tyler Foote Rd
MARKIT Raise AT&T Service Drop - 10759 Ivey Ln
MARKIT Remove Drop - 14078 Banner Mountain Lookout Rd
MARKIT Remove Drop - 15832 Airport Rd
MARKIT Remove Drop - 21596 State Highway 20
MARKIT Remove Drop - 340 N Gulling St
MARKIT Remove Drop - 421 Nevada St
MARKIT Remove Drop - 14862 Brush Creek Ct
MARKIT Remove Drop - 11689 Casci Ridge Rd
MARKIT Remove Drop - 1955 E Claremont Way
MARKIT Remove Drop - 13847 Tyler Foote Rd
MARKIT Remove Drop - 13673 Lightning Tree Rd
MARKIT Remove Drop - 15832 State Highway 20
MARKIT Temp on ground, need further isolation, 5302839298.
MARKIT Excess strain on cable and asw.
ıd cable,Pg&e placed pole,need cable reconnected,0314x301-325,150ft cable,need 25 Pr terminal cut in,house addre
Remove abandoned asw hang from mid spans 2 locations on property to work.. Property owner stopped tech today, 3-2
MARKIT Remove abandoned asw ried to tree. Public hazzrd.
emp cable on ground along State Hwy70. Servicing R.T. Site P43 Tobin. Need to asses buried cable and try to eliminate
MARKIT Excessive branches straining cable downward
MARKIT Drop is low from tree falling on to it. Drop needs to be reattached to pole
MARKIT Requires pole transfer
MARKIT Lines down,need attention,accessible to public.
MARKIT Excessive weight on cable, terminal work possible,
MARKIT Multiple asw drops hanging from pole, hazzardous along public roadway.
Cable 1 Broken lashing wire likely to Contact High Voltage (Primary/Transmission) Conductor
DETACHED FROM TREE, OVER/PARALLEL TO HORSE RIDING TRAIL
Cable 1 - Hazardous - Clearance to Ground <8ft accessible to public
Cable 1 - Hazardous - Clearance to Ground <8ft accessible to public
Cable 1 - Hazardous - Loose/Missing/Damaged - Accessible to Public and Immediate Risk
Cable 1 - Hazardous - Clearance to Ground <8ft accessible to public
POLE DOWN
MARKIT Service drp down over fire break lone.
MARKIT Fire burnt up aerial service drp, hanging over access roads
Pole 1 - Hazardous Pole Lean with Immediate Risk
Vegetation 1 - Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation 1 - Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation 1 - Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
Vegetation 1 - Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole
Vegetation 1 - Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
MARKIT REMOVE DROP - 107 PAIUTE TRAIL
MARKIT REMOVE DROP - 114 BARK WAY
MARKIT REMOVE DROP - 17 PORTOLA-MCLEARS RD
MARKIT REMOVE DROP - 425 BONTA ST

MARKIT REMOVE DROP - 559 BLAIRSDEN GRAEAGLE RD
MARKIT REMOVE DROP - 332 PINE ST
MARKIT REMOVE DROP - 12 MATTOLE TRAIL
MARKIT REMOVE DROP - 32 KOROMINU TRAIL
MARKIT REMOVE DROP - 22 SHASTA TRAIL
MARKIT REMOVE DROP - 23 PAIUTE TRAIL
MARKIT REMOVE DROP - 30 KATO TRAIL
MARKIT REMOVE DROP - 7 KATO TRAIL
MARKIT REMOVE DROP - 18 W CHILULA TRAIL
MARKIT REMOVE DROP - 54 KLAMATH TRAIL
MARKIT RAISE AT&T SERVICE DROP - 58599 HORSETAIL RD
MARKIT RAISE AT&T SERVICE DROP - 57421 JACKSON PEAK RD
MARKIT RAISE AT&T SERVICE DROP - 9 CHINOOK TRAIL
MARKIT RAISE AT&T SERVICE DROP - 58421 STATE HIGHWAY 70
MARKIT RAISE AT&T SERVICE DROP - 5556 JOHNSVILLE RD
MARKIT RAISE AT&T SERVICE DROP - 59106 STATE HIGHWAY 70
MARKIT REPAIR/REPLACE HARDWARE - 8 IROQUOIS TRAIL
MARKIT REPAIR/REPLACE HARDWARE - 109 STATE HIGHWAY 89
MARKIT REPAIR/REPLACE HARDWARE - 59171 OVERLOAD RD
Vegetation 1 - Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole

Vegetation 1 - Vegetation Strain/Deflection affecting pole or pole attachment (e.g. leaning pole)
MARKIT PLACE CROSS/GUARD ARM - 29026 STATE HIGHWAY 49
MARKIT PLACE CROSS/GUARD ARM - 16144 SAGES RD
MARKIT VEGETATION REMOVAL REQUIRED - 26269 YUBA-DONNER SCENIC BYWAY
MARKIT VEGETATION REMOVAL REQUIRED - 26921 YUBA-DONNER SCENIC BYWAY
MARKIT VEGETATION REMOVAL REQUIRED - 26335 SWEETLAND RD
MARKIT VEGETATION REMOVAL REQUIRED - 26968 SWEETLAND RD
MARKIT REMOVE DROP - 10233 SCHOOL ST
MARKIT RAISE AT&T SERVICE DROP - 26151 SWEETLAND RD
MARKIT REMOVE DROP - 28111 SWEETLAND RD
MARKIT VEGETATION REMOVAL REQUIRED - 19286 OAK TREE RD
MARKIT RAISE AT&T SERVICE DROP - 26130 YUBA-DONNER SCENIC BYWAY
MARKIT REMOVE DROP - 26968 SWEETLAND RD
MARKIT RAISE AT&T SERVICE DROP - 10164 STOTLER AVE
MARKIT VEGETATION REMOVAL REQUIRED - 26968 SWEETLAND RD
MARKIT REMOVE DROP - 27971 STATE HIGHWAY 49
MARKIT VEGETATION REMOVAL REQUIRED - 19286 OAK TREE RD
MARKIT VEGETATION REMOVAL REQUIRED - 18470 OAK TREE RD
MARKIT VEGETATION REMOVAL REQUIRED - 18528 OAK TREE RD
MARKIT RAISE AT&T SERVICE DROP - 13847 TYLER FOOTE RD
MARKIT REMOVE DROP - 24590 POPLAR MEADOW LN
MARKIT RAISE AT&T SERVICE DROP - 24313 BODHI CT
MARKIT REMOVE DROP - 16079 BIG SKY RD

MARKIT REMOVE DROP - 28499 SWEETLAND RD
MARKIT VEGETATION REMOVAL REQUIRED - 30998 STATE HIGHWAY 49
MARKIT REPAIR/REPLACE HARDWARE - 15969 RED DOG RD
MARKIT TREE TRIMMING REQUIRED - 16455 STATE HIGHWAY 20
MARKIT VEGETATION REMOVAL REQUIRED - 19311 STATE HIGHWAY 20
MARKIT VEGETATION REMOVAL REQUIRED - 19311 STATE HIGHWAY 20
MARKIT VEGETATION REMOVAL REQUIRED - 19311 STATE HIGHWAY 20
MARKIT INTRUSIVE INSPECTION REQUIRED - 12344 PAWNEE TRAIL
MARKIT TREE TRIMMING REQUIRED - 16677 BANNER QUAKER HILL RD
MARKIT REPAIR/REPLACE HARDWARE - 12923 SADIE D DR
MARKIT REPAIR/REPLACE HARDWARE - 14695 RED DOG RD
MARKIT VEGETATION REMOVAL REQUIRED - 12830 QUAKER HILL CROSS RD
MARKIT Asw needs reroute,running over power and attached to tree that is to be removed due to hazzaedous.
MARKIT REMOVE DROP - 134 BOULDER ST
MARKIT INTRUSIVE INSPECTION REQUIRED - 13683 QUAKER HILL CROSS RD
MARKIT VEGETATION REMOVAL REQUIRED - 21073 STATE HIGHWAY 20
MARKIT TREE TRIMMING REQUIRED - 11112 ERIN LN
MARKIT REMOVE DROP - 537 COYOTE ST
MARKIT REMOVE DROP - 18200 RAINBOWS END RD
MARKIT RAISE AT&T SERVICE DROP - 61 BOURBON HILL RD
MARKIT REPAIR/REPLACE HARDWARE - 12765 QUAKER HILL CROSS RD
MARKIT TREE TRIMMING REQUIRED - 16362 PASQUALE RD
MARKIT TREE TRIMMING REQUIRED - 16418 BANNER QUAKER HILL RD
MARKIT VEGETATION REMOVAL REQUIRED - 13113 QUAKER HILL CROSS RD
MARKIT REPAIR/REPLACE HARDWARE - 14811 OAK RIDGE RD
MARKIT REPAIR/REPLACE HARDWARE - 14585 OAK RIDGE RD
MARKIT REPAIR/REPLACE HARDWARE - 14900 RED DOG RD
MARKIT TREE TRIMMING REQUIRED - 15531 CASCADE DR
MARKIT INTRUSIVE INSPECTION REQUIRED - 15990 PASQUALE RD
MARKIT REMOVE DROP - 10406 N BLOOMFIELD RD
MARKIT REMOVE DROP - 18180 ROUND MOUNTAIN RANCH RD
MARKIT REMOVE DROP - 754 ZION ST
MARKIT REPAIR/REPLACE HARDWARE - 13901 RED DOG RD
MARKIT REPAIR/REPLACE HARDWARE - 13621 RED DOG RD
MARKIT REPAIR/REPLACE HARDWARE - 13637 RED DOG RD
MARKIT REPAIR/REPLACE HARDWARE - 11930 CRYSTAL WELLS RD
MARKIT REMOVE DROP - 17647 SHOSHONI TRAIL CT
MARKIT RAISE AT&T SERVICE DROP - 19217 SCOTTS FLAT RD
MARKIT REPAIR/REPLACE HARDWARE - 19163 SCOTTS FLAT RD
MARKIT REPAIR/REPLACE HARDWARE - 10 GALENA WAY
MARKIT VEGETATION REMOVAL REQUIRED - 12840 OLD WASHINGTON RD
MARKIT VEGETATION REMOVAL REQUIRED - OLD WASHINGTON RD
MARKIT VEGETATION REMOVAL REQUIRED - 24691 STATE HIGHWAY 20
MARKIT VEGETATION REMOVAL REQUIRED - 12840 OLD WASHINGTON RD

MARKIT REMOVE DROP - 15166 OLD WASHINGTON RD
MARKIT REPAIR/REPLACE HARDWARE - 13283 LITTLE YORK CLOSE
MARKIT REPAIR/REPLACE HARDWARE - 11287 RED RANCH RD
MARKIT REPAIR/REPLACE HARDWARE - 10961 JOHN MUIR LN
MARKIT TREE TRIMMING REQUIRED - 10961 JOHN MUIR LN
MARKIT REPAIR/REPLACE HARDWARE - 10490 N BLOOMFIELD RD
MARKIT INTRUSIVE INSPECTION REQUIRED - 18849 BRINDEJON RD
MARKIT INTRUSIVE INSPECTION REQUIRED - 13939 NIMBUS DAM RD
MARKIT TREE TRIMMING REQUIRED - 12389 PAWNEE TRAIL
MARKIT REPAIR/REPLACE HARDWARE - 16948 PASQUALE RD
MARKIT RAISE AT&T SERVICE DROP - 16878 PASQUALE RD
MARKIT REPAIR/REPLACE HARDWARE - 10775 N BLOOMFIELD RD
MARKIT TREE TRIMMING REQUIRED - 12983 AURORA CLOSE
MARKIT INTRUSIVE INSPECTION REQUIRED - 13030 AURORA CLOSE
MARKIT INTRUSIVE INSPECTION REQUIRED - 16999 MAYBERT RD
MARKIT TREE TRIMMING REQUIRED - 12738 SUMMIT RIDGE DR
MARKIT VEGETATION REMOVAL REQUIRED - 12952 SUMMIT RIDGE DR
MARKIT INTRUSIVE INSPECTION REQUIRED - 15749 MOUNTAIN VIEW DR
MARKIT TREE TRIMMING REQUIRED - 12672 SUMMIT RIDGE DR
MARKIT RAISE AT&T SERVICE DROP - 12672 SUMMIT RIDGE DR
MARKIT REPAIR/REPLACE HARDWARE - 13900 LAVA DOME WAY
MARKIT PLACE CROSS/GUARD ARM - 14117 QUAIL NEST WAY
MARKIT REPAIR/REPLACE HARDWARE - 15898 BUSH RD
MARKIT RAISE AT&T SERVICE DROP - 10901 MILL SPRINGS DR
MARKIT REPAIR/REPLACE HARDWARE - 15801 TURTLEBACK HILL RD
MARKIT TREE TRIMMING REQUIRED - 11112 ERIN LN
MARKIT REPAIR/REPLACE HARDWARE - 17889 DOUGLAS RD
MARKIT RAISE AT&T SERVICE DROP - 11150 N BLOOMFIELD RD
MARKIT RMVlines down, hazzard.@988 graeagle johnsville rd
MARKIT RAISE AT&T SERVICE DROP - 10833 MURCHIE MINE RD
MARKIT REPAIR/REPLACE HARDWARE - 11507 RED DOG RD
MARKIT REMOVE DROP - 21253 RUNNING HORSE RD
MARKIT REPAIR/REPLACE HARDWARE - 19146 ROCK CREEK RD
MARKIT REMOVE DROP - 18834 ROCK CREEK
MARKIT REPAIR/REPLACE HARDWARE - 848 GOLD FLAT RD
MARKIT REPAIR/REPLACE HARDWARE - 14585 OAK RIDGE RD
MARKIT REPAIR/REPLACE HARDWARE - 14408 SUN FOREST DR
MARKIT REPAIR/REPLACE HARDWARE - 13560 FOREST PARK CIRCLE
MARKIT TREE TRIMMING REQUIRED - 17086 KOZY NEST CT
MARKIT REMOVE DROP - 20103 BIG OAK DR
MARKIT TREE TRIMMING REQUIRED - 17455 INDIAN SPRINGS RD
MARKIT Line down crossing access,needs replacement,DSL customer.
MARKIT TREE TRIMMING REQUIRED - 17695 OAK VIEW LN
MARKIT REPAIR/REPLACE HARDWARE - 13302 SUGARBUSH CT

MARKIT TREE TRIMMING REQUIRED - 10981 SPENCEVILLE RD
MARKIT REMOVE DROP - 17645 PENN VALLEY DR
MARKIT TREE TRIMMING REQUIRED - 10514 SPENCEVILLE RD
MARKIT REPAIR/REPLACE HARDWARE - 13572 LAKE WILDWOOD DR
MARKIT REPAIR/REPLACE HARDWARE - 13719 LAKE WILDWOOD DR
MARKIT VEGETATION REMOVAL REQUIRED - 10328 REYNOLD WAY
MARKIT REMOVE DROP - 11068 W RIVER ST
MARKIT REMOVE DROP - 10561 GOLDEN PINE RD
MARKIT REMOVE DROP - 14825 OLD HIGHWAY 89
MARKIT REMOVE DROP - 11856 RIVERVIEW CT
MARKIT REMOVE DROP - 11716 DONNER PASS RD
MARKIT RAISE AT&T SERVICE DROP - 12337 SIERRA DR E
MARKIT REMOVE DROP - 11213 SITZMARK WAY
MARKIT REMOVE DROP - 12055 BAVARIAN WAY
MARKIT REMOVE DROP - NORTHWOODS BLVD
MARKIT REMOVE DROP - 12802 PALISADE ST
MARKIT REMOVE DROP - 12715 PARKER RD
MARKIT RAISE AT&T SERVICE DROP - 11760 DONNER PASS RD
MARKIT REPAIR/REPLACE HARDWARE - 11252 TAHOE DR
MARKIT REPAIR/REPLACE HARDWARE - 10175 LEVONE AVE
MARKIT REPAIR/REPLACE HARDWARE - 10964 ALDER DR
MARKIT REPAIR/REPLACE HARDWARE - 15715 MARTIS PEAK RD
MARKIT REPAIR/REPLACE HARDWARE - 11732 DONNER PASS RD
MARKIT REPAIR/REPLACE HARDWARE - 10099 S RIVER ST
MARKIT REPAIR/REPLACE HARDWARE - 10380 REYNOLD WAY
MARKIT REPAIR/REPLACE HARDWARE - 10437 ESTATES DR
MARKIT REPAIR/REPLACE HARDWARE - 10294 REYNOLD WAY
MARKIT REPAIR/REPLACE HARDWARE - 10248 REYNOLD WAY
MARKIT REPAIR/REPLACE HARDWARE - 14825 OLD HIGHWAY 89
MARKIT REPAIR/REPLACE HARDWARE - 15343 ICKNIELD WAY
MARKIT REPAIR/REPLACE HARDWARE - 15311 ICKNIELD WAY
MARKIT REPAIR/REPLACE HARDWARE - 15655 GLENSHIRE DR
MARKIT REPAIR/REPLACE HARDWARE - 15197 CHATHAM REACH
MARKIT REPAIR/REPLACE HARDWARE - 15645 MARTIS PEAK RD
MARKIT REPAIR/REPLACE HARDWARE - 14895 MARTIS PEAK RD
MARKIT REPAIR/REPLACE HARDWARE - 14600 MARTIS PEAK RD
MARKIT REPAIR/REPLACE HARDWARE - 14464 MARTIS PEAK RD
MARKIT PLACE CROSS/GUARD ARM - 10534 MARTIS DR
MARKIT PLACE CROSS/GUARD ARM - 11653 KAYHOE CT
MARKIT LOWER OR RAISE EXISTING CABLE - 10462 MARTIS DR/NOTES: SERVICE DROP POLE
MARKIT REMOVE DROP - 13312 HANSEL AVE
MARKIT REPAIR/REPLACE HARDWARE - 18168 LA MIRADA RD
MARKIT REMOVE DROP - 12648 CREST WAY
MARKIT REMOVE DROP - 12797 CREST WAY

MARKIT REPAIR/REPLACE HARDWARE - LA MIRADA RD
MARKIT REPAIR/REPLACE HARDWARE - 10577 DOGWOOD RD
MARKIT REMOVE DROP - 16021 HOBART MILLS
MARKIT REMOVE DROP - 11782 CHAMONIX RD
MARKIT RAISE AT&T SERVICE DROP - 17768 STONEY PT
MARKIT RAISE AT&T SERVICE DROP - 17768 STONEY PT
MARKIT REPAIR/REPLACE HARDWARE - 14374 MARTIS PEAK RD
MARKIT REMOVE DROP - 14615 TYROL RD
MARKIT REMOVE DROP - 14675 TYROL RD
MARKIT TREE TRIMMING REQUIRED - 13175 SKI VIEW LOOP
MARKIT REPAIR/REPLACE HARDWARE - STAMPEDE DAM RD
MARKIT REPAIR/REPLACE HARDWARE - STAMPEDE DAM RD
MARKIT REPAIR/REPLACE HARDWARE - 15875 SUMMIT CT
MARKIT REMOVE DROP - 14192 HANSEL AVE
MARKIT REMOVE DROP - 14112 HANSEL AVE
MARKIT REMOVE DROP - 14274 HANSEL AVE
MARKIT REMOVE DROP - 14396 HANSEL AVE
MARKIT REMOVE DROP - 14499 HANSEL AVE
MARKIT REMOVE DROP - 11252 BOLZANO DR
MARKIT REMOVE DROP - 13853 DAVOS DR
MARKIT REMOVE DROP - 12074 BERNESE LN
MARKIT REMOVE DROP - 12140 BERNESE LN
MARKIT REMOVE DROP - 13172 SOLVANG WAY
MARKIT REMOVE DROP - 13499 HILLSIDE DR
MARKIT TREE TRIMMING REQUIRED - 10515 DOGWOOD ST
MARKIT REMOVE DROP - 15530 S SHORE DR
MARKIT REMOVE DROP - 11457 ZERMATT DR
MARKIT REMOVE DROP - 12230 BERNESE LN
MARKIT REMOVE DROP - 11059 ZERMATT DR
MARKIT REMOVE DROP - 11627 BADEN RD
MARKIT REMOVE DROP - 16646 SKI SLOPE WAY
MARKIT REMOVE DROP - 14179 DAVOS DR
MARKIT REMOVE DROP - 13561 HEIDI WAY
MARKIT REMOVE DROP - 14195 DAVOS DR
MARKIT REMOVE DROP - 11441 BADEN RD
MARKIT REMOVE DROP - 11496 SAINT BERNARD DR
MARKIT REMOVE DROP - 12958 HANSEL AVE
MARKIT TREE TRIMMING REQUIRED - 13693 CRISTALLINA WAY
MARKIT REMOVE DROP - 12912 PINNACLE LOOP
MARKIT REMOVE DROP - 14936 WOLFGANG RD
MARKIT REMOVE DROP - 15075 WOLFGANG RD
MARKIT TREE TRIMMING REQUIRED - 14099 SKI VIEW LOOP
MARKIT REPAIR/REPLACE HARDWARE - 10492 KLONDIKE FLAT RD
MARKIT REPAIR/REPLACE HARDWARE - 10370 KLONDIKE FLAT RD

MARKIT PLACE CROSS/GUARD ARM - 10370 KLONDIKE FLAT RD
MARKIT REMOVE DROP - 13359 HANSEL AVE
MARKIT REMOVE DROP - 12311 SAINT BERNARD DR
MARKIT REMOVE DROP - 12296 STOCKHOLM WAY
MARKIT REMOVE DROP - 12317 STOCKHOLM WAY
MARKIT REMOVE DROP - 12508 SAINT BERNARD DR
MARKIT REMOVE DROP - 13789 HEIDI WAY
MARKIT REMOVE DROP - 11531 SUN VALLEY RD
MARKIT REMOVE DROP - 11366 SUN VALLEY RD
MARKIT REMOVE DROP - 14896 SWISS LN
MARKIT REMOVE DROP - 11664 RHINELAND AVE
MARKIT REMOVE DROP - 11784 RHINELAND AVE
MARKIT REMOVE DROP - CHALET RD
MARKIT REMOVE DROP - CHALET RD
MARKIT REMOVE DROP - CHATEAU WAY
MARKIT REMOVE DROP - 15109 SWISS LN
MARKIT REMOVE DROP - 12962 SKI VIEW LOOP
MARKIT REMOVE DROP - 12878 SKI VIEW LOOP
MARKIT REMOVE DROP - 14193 SKI VIEW LOOP
MARKIT REMOVE DROP - 12150 MUHLEBACH WAY
MARKIT REMOVE DROP - 11672 OSLO DR
MARKIT REMOVE DROP - 14094 SAINT CROIX WAY
MARKIT REMOVE DROP - 14437 S SHORE DR
MARKIT REMOVE DROP - 12196 SIERRA DR E
MARKIT REMOVE DROP - 12965 DAVOS DR
MARKIT REMOVE DROP - 12946 DAVOS DR
MARKIT REMOVE DROP - 11515 SAINT BERNARD DR
MARKIT REMOVE DROP - 12454 SKI SLOPE WAY
MARKIT TREE TRIMMING REQUIRED - 12849 DONNER PASS RD
MARKIT REMOVE DROP - 13420 OLYMPIC DR
MARKIT REMOVE DROP - 15888 DONNER PASS RD
MARKIT REMOVE DROP - 10447 WASHOE RD
MARKIT REMOVE DROP - 13814 ALDER CREEK RD
MARKIT REMOVE DROP - 13230 OBERWALD WAY
MARKIT REMOVE DROP - 11582 RHINELAND AVE
MARKIT REMOVE DROP - 12721 BERNESE LN
MARKIT REMOVE DROP - 12644 BERNESE LN
MARKIT REMOVE DROP - 10237 WASHOE RD
MARKIT REMOVE DROP - 13655 MORAINE RD
MARKIT TREE TRIMMING REQUIRED - 13655 DONNER PASS RD
MARKIT REMOVE DROP - 13687 MORAINE RD
MARKIT REMOVE DROP - 13253 DONNER PASS RD
MARKIT REMOVE DROP - 13253 DONNER PASS RD
MARKIT REMOVE DROP - 12699 SAINT MORITZ LN

MARKIT REMOVE DROP - 13945 SKI VIEW LOOP
MARKIT REMOVE DROP - 14319 HERRINGBONE WAY
MARKIT REMOVE DROP - 13447 PATHWAY AVE
MARKIT REMOVE DROP - 13477 PATHWAY AVE
MARKIT REMOVE DROP - 12362 GREENLEAF WAY
MARKIT REMOVE DROP - 15179 NORTHWOODS BLVD
MARKIT REMOVE DROP - 15113 NORTHWOODS BLVD
MARKIT REMOVE DROP - 14065 RAMSHORN ST
MARKIT REMOVE DROP - 14035 RAMSHORN ST
MARKIT REMOVE DROP - 14094 TYROL RD
MARKIT REMOVE DROP - 14096 RAMSHORN ST
MARKIT REMOVE DROP - 10986 BOLZANO DR
MARKIT REMOVE DROP - 11841 CHAMONIX RD
MARKIT REMOVE DROP - 13119 FALCON POINT PL
MARKIT REMOVE DROP - 12688 FALCON POINT PL
MARKIT REMOVE DROP - 11702 CHAMONIX RD
MARKIT REMOVE DROP - 12931 FALCON POINT PL
MARKIT REMOVE DROP - 11851 SAINT BERNARD DR
MARKIT REMOVE DROP - 14366 COPENHAGEN DR
MARKIT REMOVE DROP - 14590 COPENHAGEN DR
MARKIT REMOVE DROP - 14737 COPENHAGEN DR
MARKIT REMOVE DROP - 11261 MOUGLE LN
MARKIT REMOVE DROP - 12020 BENNETT FLAT RD
MARKIT REMOVE DROP - 13177 DAVOS DR
MARKIT REMOVE DROP - 13039 DAVOS DR
MARKIT REMOVE DROP - 11400 CHAMONIX RD
MARKIT REMOVE DROP - 12870 NORTHWOODS BLVD
MARKIT REMOVE DROP - 13707 NORTHWOODS BLVD
MARKIT REMOVE DROP - 10512 MOUGLE LN
MARKIT REMOVE DROP - 10865 MOUGLE LN
MARKIT REMOVE DROP - 16606 SKI SLOPE WAY
MARKIT REMOVE DROP - 12579 BEAR MEADOW CT
MARKIT REMOVE DROP - 11306 ZERMATT DR
MARKIT REMOVE DROP - 16949 NORTHWOODS BLVD
MARKIT REMOVE DROP - 11006 K T DR
MARKIT REMOVE DROP - 11048 K T DR
MARKIT REMOVE DROP - 12605 SKI SLOPE WAY
MARKIT REMOVE DROP - 16565 NORTHWOODS BLVD
MARKIT REPAIR/REPLACE HARDWARE - 10424 E ALDER CREEK RD
MARKIT REMOVE DROP - 10579 FOXMEAD LN/NOTES: SERVICE DROP POLE
MARKIT REPAIR/REPLACE HARDWARE - I-80 W
MARKIT REPAIR/REPLACE HARDWARE - 10068 HIRSCHDALE RD
MARKIT TREE TRIMMING REQUIRED - 10570 IRIS RD
MARKIT TREE TRIMMING REQUIRED - 12098 PINE FOREST RD

MARKIT REPAIR/REPLACE HARDWARE - 12139 PINE FOREST RD
MARKIT REPAIR/REPLACE HARDWARE - 12100 LARIAT LN
MARKIT REPAIR/REPLACE HARDWARE - 12050 LARIAT LN
MARKIT RAISE AT&T SERVICE DROP - 10297 JEFFREY WAY
MARKIT REPAIR/REPLACE HARDWARE - 12468 GREENWOOD DR
MARKIT REPAIR/REPLACE HARDWARE - 12592 GREENWOOD DR
MARKIT REPAIR/REPLACE HARDWARE - 12660 MADRONE LN
MARKIT REPAIR/REPLACE HARDWARE - 11525 SILVERFIR DR
MARKIT PLACE CROSS/GUARD ARM - 11642 SILVERFIR DR
MARKIT REMOVE DROP - 11902 RIO VISTA DR
MARKIT RAISE AT&T SERVICE DROP - ALDER CREEK RD
MARKIT REMOVE DROP - 12296 DEERFIELD DR
MARKIT REPAIR/REPLACE HARDWARE - 12296 DEERFIELD DR
MARKIT REMOVE DROP - 10098 E ALDER CREEK RD
MARKIT REPAIR/REPLACE HARDWARE - 10557 FOXMEAD LN
MARKIT PLACE CROSS/GUARD ARM - 10371 E ALDER CREEK RD
MARKIT REPAIR/REPLACE HARDWARE - 11166 DONNER PASS RD
MARKIT RELASH EXISTING CABLES - 11061 SPRING LN
MARKIT REMOVE DROP - 12381 SKI SLOPE WAY
MARKIT REMOVE DROP - 13945 HERRINGBONE WAY
MARKIT REMOVE DROP - 13285 DAVOS DR
MARKIT REMOVE DROP - 10448 TETON WAY
MARKIT REMOVE DROP - SLALOM WAY
MARKIT REMOVE DROP - 22195 SPRUCE ST
MARKIT REMOVE DROP - 10423 LENELLE LN
MARKIT PLACE CROSS/GUARD ARM - 9908 RIVER RD
MARKIT PLACE CROSS/GUARD ARM - 19021 W RIVER ST
MARKIT REPAIR/REPLACE HARDWARE - 12420 RAINBOW DR
MARKIT LOWER OR RAISE EXISTING AT&T CABLE - 11054 WHITEHORSE RD
MARKIT PLACE CROSS/GUARD ARM - 10581 MARTIS VALLEY RD
MARKIT REMOVE DROP - 11420 LOCKWOOD DR
MARKIT PLACE CROSS/GUARD ARM - 11131 BEACON RD
MARKIT REPAIR/REPLACE HARDWARE - 11012 BEACON RD
MARKIT REMOVE DROP - 11190 BARNES DR
MARKIT PLACE CROSS/GUARD ARM - 10481 PINE CONE DR
MARKIT REMOVE DROP - 10322 PROSSER DR
MARKIT REMOVE DROP - 12948 DULZURA ST
MARKIT REMOVE DROP - 11746 KITZBUHEL RD
MARKIT REMOVE DROP - 11854 KITZBUHEL RD
MARKIT RAISE AT&T SERVICE DROP - 12931 DULZURA ST
MARKIT REMOVE DROP - 11719 KITZBUHEL RD
MARKIT PLACE CROSS/GUARD ARM - 12804 RAINBOW DR
MARKIT REPAIR/REPLACE HARDWARE - 12169 STALLION WAY
MARKIT REPAIR/REPLACE HARDWARE - 12134 STALLION WAY

MARKIT TREE TRIMMING REQUIRED - 10571 ROSA CT
MARKIT PLACE CROSS/GUARD ARM - 10732 MARTIS DR
MARKIT REMOVE DROP - 15845 ARCHERY VIEW
MARKIT REPAIR/REPLACE HARDWARE - 11851 WHITEHORSE RD
MARKIT PLACE CROSS/GUARD ARM - 11121 HUNTSMAN LEAP
MARKIT REPAIR/REPLACE HARDWARE - 15636 COLT CT
MARKIT PLACE CROSS/GUARD ARM - 10792 PINE CONE DR
MARKIT REPAIR/REPLACE HARDWARE - 12371 SNOW SHOE CT
MARKIT REPAIR/REPLACE HARDWARE - 10884 SILVERFIR DR
MARKIT LOWER OR RAISE EXISTING CABLE - 10815 SNOWFLOWER CT/NOTES: SERVICE DROP POLE
MARKIT LOWER OR RAISE EXISTING CABLE - 10851 SILVERFIR DR/NOTES: SERVICE DROP POLE
MARKIT REPAIR/REPLACE HARDWARE - 10499 SNOW SHOE CIRCLE
MARKIT PLACE CROSS/GUARD ARM - 15450 DONNINGTON LN
MARKIT REMOVE DROP - 10830 BARNES DR
MARKIT RAISE AT&T SERVICE DROP - 10867 CHEYENNE WAY
MARKIT REMOVE DROP - 10558 STUART STAITHE
MARKIT LOWER OR RAISE EXISTING CABLE - 11928 RIO VISTA DR/NOTES: SERVICE DROP POLE
MARKIT REMOVE DROP - 10423 PALISADES DR
MARKIT REPAIR/REPLACE HARDWARE - 10416 PALISADES DR
MARKIT PLACE CROSS/GUARD ARM - 10419 BRIAR CIRCLE
MARKIT REMOVE DROP - 10431 BRIAR CIRCLE
MARKIT REMOVE DROP - 11737 DEERFIELD DR
MARKIT REMOVE DROP - 11675 DEERFIELD DR
MARKIT REMOVE DROP - 11605 DEERFIELD DR
MARKIT REMOVE DROP - 11880 DEERFIELD DR
MARKIT REPAIR/REPLACE HARDWARE - 15730 WINDSOR WAY
MARKIT RAISE AT&T MAINLINE CABLE - 15664 SHERWOOD DR
MARKIT RAISE AT&T SERVICE DROP - 11480 GLEN RD
MARKIT REPAIR/REPLACE HARDWARE - 10418 BECKETT PL
MARKIT REPAIR/REPLACE HARDWARE - 16139 LANCASTER PL
MARKIT REMOVE DROP - 12298 LEMON CT
MARKIT PLACE CROSS/GUARD ARM - 10040 ALDER CREEK RD
MARKIT REMOVE DROP - 15301 S SHORE DR
MARKIT REMOVE DROP - 15370 CONIFER DR
MARKIT REMOVE DROP - 14646 RED MOUNTAIN RD
MARKIT REMOVE DROP - 14591 RED MOUNTAIN RD
MARKIT REMOVE DROP - 14595 S SHORE DR
MARKIT REMOVE DROP - 15500 S SHORE DR
MARKIT REMOVE DROP - 14618 S SHORE DR
MARKIT REMOVE DROP - 14376 S SHORE DR
MARKIT REMOVE DROP - 12346 PINE FOREST RD
MARKIT REPAIR/REPLACE HARDWARE - 12346 PINE FOREST RD
MARKIT PLACE CROSS/GUARD ARM - 10769 MARTIS DR
MARKIT PLACE CROSS/GUARD ARM - 10809 MARTIS DR

MARKIT REMOVE DROP - 10829 MARTIS DR
MARKIT REMOVE DROP - 22187 TAMARACK ST
MARKIT PLACE CROSS/GUARD ARM - 6780-68 RIVER RD
MARKIT TREE TRIMMING REQUIRED - 10053 OLYMPIC BLVD
MARKIT TREE TRIMMING REQUIRED - 10053 OLYMPIC BLVD
MARKIT REPAIR/REPLACE HARDWARE - 11700 KAYHOE CT
MARKIT PLACE CROSS/GUARD ARM - 10115 OLYMPIC BLVD
MARKIT REMOVE DROP - 11463 HIGHLAND AVE
MARKIT REPAIR/REPLACE HARDWARE - 10438 OLYMPIC BLVD
MARKIT TREE TRIMMING REQUIRED - 11662 HIGHLAND AVE
MARKIT LOWER OR RAISE EXISTING CABLE - 10019 FLORISTON CT
MARKIT PLACE CROSS/GUARD ARM - 10529 EVENSHAM PL
MARKIT REMOVE DROP - 10457 EVENSHAM PL
MARKIT PLACE CROSS/GUARD ARM - 10339 BRIAR CIRCLE
MARKIT REMOVE DROP - 11874 RAINBOW DR
MARKIT REMOVE DROP - 11940 PINE FOREST RD
MARKIT REMOVE DROP - 12022 PINE FOREST RD
MARKIT REPLACE/INSTALL DOWN GUY - 10296 BROCKWAY RD
MARKIT REMOVE DROP - 6210 RIVER RD
MARKIT REMOVE DROP - 7880 RIVER RD
MARKIT REMOVE DROP - 11298 BENNETT FLAT RD
MARKIT REMOVE DROP - 16204 EDINBURGH DR
MARKIT REMOVE DROP - 15364 DONNER PASS RD
MARKIT REMOVE DROP - 15404 DONNER PASS RD
MARKIT REMOVE DROP - 13093 MORAINE RD
MARKIT REMOVE DROP - 13424 MORAINE RD
MARKIT REMOVE DROP - 13604 MORAINE RD
MARKIT REMOVE DROP - 12349 SKI SLOPE WAY
MARKIT REPAIR/REPLACE HARDWARE - 10316 OLYMPIC BLVD
MARKIT PLACE CROSS/GUARD ARM - 11908 HIGHLAND AVE
MARKIT PLACE CROSS/GUARD ARM - 11878 HIGHLAND AVE
MARKIT REMOVE DROP - 11893 HIGHLAND AVE
MARKIT REMOVE DROP - 12454 PROSSER DAM RD
MARKIT LOWER OR RAISE EXISTING CABLE - 11330 SKYLINE CT
MARKIT REPAIR/REPLACE HARDWARE - 10792 ASPENWOOD RD
MARKIT REMOVE DROP - 10792 ASPENWOOD RD
MARKIT PLACE CROSS/GUARD ARM - 15417 ARCHERY VIEW
MARKIT REMOVE DROP - 10851 WHITEHORSE RD
MARKIT REMOVE DROP - 15352 CROWN CIRCLE
MARKIT REMOVE DROP - 11146 ALDER DR
MARKIT PLACE CROSS/GUARD ARM - 15326 WATERLOO CIRCLE
MARKIT REPAIR/REPLACE HARDWARE - 10374 MANCHESTER DR
MARKIT PLACE CROSS/GUARD ARM - 11264 STAR PINE RD
MARKIT LOWER OR RAISE EXISTING CABLE - 7874 RIVER RD/NOTES: SERVICE DROP POLE

MARKIT REMOVE DROP - 11735 BENNETT FLAT RD
MARKIT REMOVE DROP - 13821 DONNER PASS RD
MARKIT REPAIR/REPLACE HARDWARE - 11955 DEERFIELD DR
MARKIT REMOVE DROP - 10096 ORIOLE LN
MARKIT REMOVE DROP - 14210 DONNER AVE
MARKIT REMOVE DROP - 14945 PIONEER DR
MARKIT REMOVE DROP - 14570 DONNER AVE
MARKIT REMOVE DROP - 14814 DONNER PASS RD
MARKIT REMOVE DROP - 15600 DONNER PASS RD
MARKIT REMOVE DROP - 11683 BENNETT FLAT RD
MARKIT PLACE CROSS/GUARD ARM - 10266 CROMLEY SQ
MARKIT REPAIR/REPLACE HARDWARE - 14909 GLENSHIRE DR
MARKIT REPAIR/REPLACE HARDWARE - 10553 STONE PINE RD
MARKIT PLACE CROSS/GUARD ARM - 10442 STONE PINE RD
MARKIT REMOVE DROP - 11399 BEACON RD
MARKIT REPAIR/REPLACE HARDWARE - 10165 COLUMBINE RD
MARKIT PLACE CROSS/GUARD ARM - 10240 COLUMBINE RD
MARKIT PLACE CROSS/GUARD ARM - 10245 SHORE PINE RD
MARKIT LOWER OR RAISE EXISTING CABLE - 11609 REDBUD CT
MARKIT REMOVE DROP - 11734 NORDIC LN
MARKIT REMOVE DROP - 11695 LAUSANNE WAY
MARKIT REMOVE DROP - 11641 LAUSANNE WAY
MARKIT REMOVE DROP - 16471 GLENSHIRE DR
MARKIT REMOVE DROP - 12018 KITZBUHEL RD
MARKIT REPAIR/REPLACE HARDWARE - 11261 ALDER DR
MARKIT REMOVE DROP - 11310 ALDER DR
MARKIT REMOVE DROP - 11776 MOUGLE LN
MARKIT REMOVE DROP - 12292 BROOKSTONE DR
MARKIT REMOVE DROP - 12244 GREENLEAF WAY
MARKIT RAISE AT&T SERVICE DROP - 13824 HANSEL AVE
MARKIT REMOVE DROP - 13971 HANSEL AVE
MARKIT REMOVE DROP - 10056 SIERRA AVE
MARKIT RAISE AT&T SERVICE DROP - 11109 DONNER PASS RD
MARKIT REMOVE DROP - 11300 DONNER WAY
MARKIT REPAIR/REPLACE HARDWARE - 11536 TINKERS LANDING
MARKIT REPAIR/REPLACE HARDWARE - 12260 GREENWOOD DR
MARKIT REMOVE DROP - 14210 S SHORE DR
MARKIT REMOVE DROP - 14186 S SHORE DR
MARKIT REMOVE DROP - 10620 WASHOE RD
MARKIT REMOVE DROP - 16232 OLD HIGHWAY DR
MARKIT REMOVE DROP - 15963 S SHORE DR
MARKIT LOWER OR RAISE EXISTING CABLE - 12650 GLENSHIRE DR
MARKIT REPAIR/REPLACE HARDWARE - 12254 RICHARDS BLVD
MARKIT Low lines and cable along roadway,Jeanette ccon, 5302493130

MARKIT REPAIR/REPLACE HARDWARE - 420 MAIN ST
MARKIT REMOVE DROP - 160 PEARL ST
MARKIT REMOVE DROP - 204 DURGAN FLAT ST
MARKIT REMOVE DROP - 303 DURGAN FLAT ST
MARKIT REMOVE DROP - 141 BELLE ST
MARKIT REMOVE DROP - 151 GALLOWAY ST
MARKIT VEGETATION REMOVAL REQUIRED - 942 OLD TOLL BRIDGE RD
MARKIT REMOVE DROP - 15921 STATE HIGHWAY 49
MARKIT REMOVE DROP - 15921 STATE HIGHWAY 49
MARKIT VEGETATION REMOVAL REQUIRED - 942 OLD TOLL BRIDGE RD
MARKIT VEGETATION REMOVAL REQUIRED - 1060 OLD TOLL BRIDGE RD
MARKIT VEGETATION REMOVAL REQUIRED - 1064 OLD TOLL BRIDGE RD
D - 251 GOODYEAR CREEK RD/NOTES: MAINLINE GOING THROUGH HEAVY VEGETATION TREE FELL ON LINE TREE ST.
MARKIT VEGETATION REMOVAL REQUIRED - 335 GOODYEAR CREEK RD
MARKIT VEGETATION REMOVAL REQUIRED - 303 GOODYEAR CREEK RD
MARKIT REMOVE DROP - 15 BUSCH ST
MARKIT REMOVE DROP - 121 WILD PLUM RD
MARKIT REPAIR/REPLACE HARDWARE - 358 LINCOLN ST
MARKIT TREE TRIMMING REQUIRED - 597 OLD TRUCKEE RD
MARKIT TREE TRIMMING REQUIRED - 618 OLD TRUCKEE RD
MARKIT TREE TRIMMING REQUIRED - 211 EDNA DR
MARKIT PLACE CROSS/GUARD ARM - 34310 ALTA BONNYNOOK RD
MARKIT PLACE CROSS/GUARD ARM - 34055 TOWLE HILL RD
MARKIT REMOVE DROP - 33883 RAIL FENCE RD
MARKIT REMOVE DROP - 33758 RAIL FENCE RD
MARKIT REMOVE DROP - 39110 KEARSARGE MILL RD
MARKIT REMOVE DROP - 684 ALTA POWERHOUSE RD
MARKIT VEGETATION REMOVAL REQUIRED - 32306 RIDGE RD
MARKIT TREE TRIMMING REQUIRED - 449 SACRAMENTO ST
MARKIT VEGETATION REMOVAL REQUIRED - 627 SACRAMENTO ST
/INSTALL DOWN GUY;TRANSFER AT&T CABLE(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 2 - 340
MARKIT VEGETATION REMOVAL REQUIRED - 28100 MAGRA RD
MARKIT VEGETATION REMOVAL REQUIRED - 40225 AIRPORT RD
MARKIT RAISE AT&T SERVICE DROP - 33695 MAIN ST
MARKIT TREE TRIMMING REQUIRED - 33525 MAIN ST
MARKIT VEGETATION REMOVAL REQUIRED - 762 BLUE CANYON RD
MARKIT TREE TRIMMING REQUIRED - 3 WOOLLEY RD
MARKIT REMOVE DROP - 44200 STATE HIGHWAY 20
MARKIT REMOVE DROP - 650 CAINE RD
MARKIT REPAIR/REPLACE HARDWARE - 580 BLUE CANYON RD
MARKIT REMOVE DROP - 1 FULDA RD
MARKIT REMOVE DROP - 41158 SKYLINE DR
MARKIT PLACE CROSS/GUARD ARM - 34648 TRAIL END CT
MARKIT REMOVE DROP - 12655 ZEIBRIGHT RD

MARKIT REMOVE DROP - 12655 ZEIBRIGHT RD
MARKIT TREE TRIMMING REQUIRED - 33150 RIDGE RD
MARKIT REMOVE DROP - 42200 NYACK RD
MARKIT REMOVE DROP - 300 CANYON MINE RD
MARKIT REMOVE DROP - 12764 ZEIBRIGHT RD
MARKIT REMOVE DROP - 34735 E TOWLE RD
MARKIT PLACE CROSS/GUARD ARM - 573 LEE RD
MARKIT REMOVE DROP - 573 LEE RD
MARKIT REMOVE DROP - 167 W TOWLE RD
MARKIT REMOVE DROP - 127 W TOWLE RD
MARKIT REPAIR/REPLACE HARDWARE - 105 W TOWLE RD
MARKIT PLACE CROSS/GUARD ARM - 34105 ALTA BONNYNOOK RD
MARKIT REMOVE DROP - 34055 TOWLE HILL RD
MARKIT TREE TRIMMING REQUIRED - 27398 CAPE HORN RD
MARKIT TREE TRIMMING REQUIRED - 27301 NORTON GRADE RD
MARKIT VEGETATION REMOVAL REQUIRED - 17598 CHICAGO PARK POWERHOUSE RD
MARKIT REMOVE DROP - 1299 ALTA POWERHOUSE RD
MARKIT VEGETATION REMOVAL REQUIRED - 37500 KEARSARGE MILL
MARKIT VEGETATION REMOVAL REQUIRED - I-80 W
MARKIT VEGETATION REMOVAL REQUIRED - I-80 W
MARKIT TREE TRIMMING REQUIRED - 32362 MONTE VISTA LN
MARKIT TREE TRIMMING REQUIRED - 32355 LINCOLN RD
MARKIT REPAIR/REPLACE HARDWARE - 725 ALTA RESERVOIR RD
MARKIT REPAIR/REPLACE HARDWARE - 940 ALTA RESERVOIR RD
MARKIT REMOVE DROP - 36000 FINN LN
MARKIT REPAIR/REPLACE HARDWARE - 34950 CULBERSON RD
MARKIT VEGETATION REMOVAL REQUIRED - 1268 GARRETT RD
MARKIT REPAIR/REPLACE HARDWARE - 41448 PUTT RD
MARKIT REPAIR/REPLACE HARDWARE - 41390 PUTT RD
MARKIT REMOVE DROP - 41340 PUTT RD
MARKIT REPAIR/REPLACE HARDWARE - 34484 LITTLE BEAR CREEK LN
MARKIT REPAIR/REPLACE HARDWARE - 34645 LITTLE BEAR CREEK LN
MARKIT REPAIR/REPLACE HARDWARE - 34377 E TOWLE RD
MARKIT REMOVE DROP - 110 BONNYNOOK RD
MARKIT REMOVE DROP - 11112 BOWMAN LAKE RD
MARKIT VEGETATION REMOVAL REQUIRED - 12726 BOWMAN LAKE RD
MARKIT REPAIR/REPLACE HARDWARE - 14783 BOWMAN LAKE RD
MARKIT REPAIR/REPLACE HARDWARE - 36515 GROUSE RIDGE RD
MARKIT REPAIR/REPLACE HARDWARE - 510 KEARSARGE CT
MARKIT REPAIR/REPLACE HARDWARE - 500 KEARSARGE CT
MARKIT REPAIR/REPLACE HARDWARE - 545 KEARSARGE CT
MARKIT REMOVE DROP - 505 KEARSARGE CT
MARKIT REPAIR/REPLACE HARDWARE - 38625 KEARSARGE MILL RD
MARKIT PLACE CROSS/GUARD ARM - 38625 KEARSARGE MILL RD

MARKIT VEGETATION REMOVAL REQUIRED - 449 SACRAMENTO ST
MARKIT VEGETATION REMOVAL REQUIRED - 32367 SQUIRE CANYON LN
MARKIT VEGETATION REMOVAL REQUIRED - 42600 TEXAS HILL RD
MARKIT INTRUSIVE INSPECTION REQUIRED - 8790 LA PORTE RD
MARKIT INTRUSIVE INSPECTION REQUIRED - 8749 LA PORTE RD
MARKIT REMOVE DROP - 9110 NERO RD
MARKIT INTRUSIVE INSPECTION REQUIRED - 8959 NERO RD
MARKIT VEGETATION REMOVAL REQUIRED - 12353 LA PORTE RD
MARKIT VEGETATION REMOVAL REQUIRED - 12338 LA PORTE RD
MARKIT VEGETATION REMOVAL REQUIRED - 12326 LA PORTE RD
MARKIT VEGETATION REMOVAL REQUIRED - 2181 LA PORTE RD
MARKIT RAISE AT&T SERVICE DROP - 5773 FORBESTOWN RD
MARKIT TREE TRIMMING REQUIRED - 5699 FORBESTOWN RD
MARKIT RAISE AT&T SERVICE DROP - 19721 MOUNT HOPE RD/NOTES: SERVICE DROP LINE
MARKIT INTRUSIVE INSPECTION REQUIRED - 9188 LA PORTE RD
MARKIT TREE TRIMMING REQUIRED - 5389 FORBESTOWN RD
MARKIT INTRUSIVE INSPECTION REQUIRED - 9246 LA PORTE RD
MARKIT TREE TRIMMING REQUIRED - 5823 FORBESTOWN RD
MARKIT TREE TRIMMING REQUIRED - 9381 LA PORTE RD
MARKIT REMOVE DROP - 241 OLD FORBESTOWN RD
MARKIT TREE TRIMMING REQUIRED - 9466 FORSYTHE RD
MARKIT RAISE AT&T SERVICE DROP - 5 WESTAR CT
MARKIT REMOVE DROP - 16772 NEW YORK HOUSE RD
MARKIT TREE TRIMMING REQUIRED - 18896 NEW YORK FLAT RD
MARKIT VEGETATION REMOVAL REQUIRED - 9683 LA PORTE RD
MARKIT VEGETATION REMOVAL REQUIRED - 9639 LA PORTE RD
MARKIT VEGETATION REMOVAL REQUIRED - 12725 LA PORTE RD
MARKIT TREE TRIMMING REQUIRED - 18968 NEW YORK FLAT RD
MARKIT TREE TRIMMING REQUIRED - 19114 NEW YORK FLAT RD
MARKIT TREE TRIMMING REQUIRED - 25 CLOVERLEAF LN
MARKIT REMOVE DROP - 12791 LA PORTE RD
MARKIT REMOVE DROP - 102 BIG FUR RD
MARKIT TREE TRIMMING REQUIRED - 9111 RED BUD
MARKIT LOWER OR RAISE EXISTING CABLE - 19452 FORBESTOWN RD
MARKIT VEGETATION REMOVAL REQUIRED - 9683 LA PORTE RD
MARKIT REMOVE DROP - 9214 LA PORTE RD
MARKIT TREE TRIMMING REQUIRED - 9414 LA PORTE RD
MARKIT RAISE AT&T SERVICE DROP - 19721 MOUNT HOPE RD
MARKIT INTRUSIVE INSPECTION REQUIRED - 9204 LA PORTE RD
MARKIT TREE TRIMMING REQUIRED - 5530 FORBESTOWN RD
MARKIT INTRUSIVE INSPECTION REQUIRED - 15822 WILLOW GLEN RD
MARKIT REMOVE DROP - 15887 WILLOW GLEN RD
MARKIT REMOVE DROP - 16592 WILLOW GLEN RD
MARKIT REMOVE DROP - 258 TAMARACK WAY

MARKIT REMOVE DROP - 16408 FRENCHTOWN RD
MARKIT TREE TRIMMING REQUIRED - 16373 FRENCHTOWN RD
MARKIT VEGETATION REMOVAL REQUIRED - 16052 FRENCHTOWN RD
MARKIT TREE TRIMMING REQUIRED - 15234 FRENCHTOWN RD
MARKIT VEGETATION REMOVAL REQUIRED - 11670 LA PORTE RD
MARKIT REMOVE DROP - 8899 FRENCHTOWN EXT/NOTES: SERVICE DROP LINE
MARKIT VEGETATION REMOVAL REQUIRED - 17759 NEW YORK HOUSE RD
MARKIT REMOVE DROP - 18092 JOY CIRCLE
MARKIT REMOVE DROP - 11875 MORAN RD
MARKIT Line down, 5308324143, need to be reattahed @Terminal pole.
MARKIT REPAIR/REPLACE HARDWARE - 13002 GOLDEN EAGLE WAY
MARKIT REPAIR/REPLACE HARDWARE - 16525 MEADOW WAY
MARKIT REMOVE DROP - 16525 MEADOW WAY
MARKIT REMOVE DROP - 11402 IDAHO MARYLAND RD
MARKIT REPAIR/REPLACE HARDWARE - 16932 LAWRENCE WAY
MARKIT REPAIR/REPLACE HARDWARE - 16965 LAWRENCE WAY
MARKIT REMOVE DROP - 13883 RATTLESNAKE RD
MARKIT TREE TRIMMING REQUIRED - 13131 SUNSHINE VALLEY RD
MARKIT REMOVE DROP - 16176 RAYLENE CT
MARKIT REPAIR/REPLACE HARDWARE - 18938 SAINT PAUL PL
MARKIT REMOVE DROP - 11754 RAGAN WAY
MARKIT REMOVE DROP - 14605 CLOVER RIDGE LN
MARKIT TREE TRIMMING REQUIRED - 12182 FRANCIS DR
MARKIT TREE TRIMMING REQUIRED - 12263 ELIZABETH WAY
MARKIT TREE TRIMMING REQUIRED - 12301 ELIZABETH WAY
MARKIT PLACE CROSS/GUARD ARM - 18766 OLD COACH WAY
MARKIT REPAIR/REPLACE HARDWARE - 18766 OLD COACH WAY
MARKIT REMOVE DROP - 12695 ROUGH AND READY HWY
MARKIT REMOVE DROP - 720 S AUBURN ST
MARKIT RAISE AT&T SERVICE DROP - 16142 TINA CT
MARKIT REMOVE DROP - 17832 NORLENE WAY
MARKIT REPAIR/REPLACE HARDWARE - 15248 CARRIE DR
MARKIT REMOVE DROP - 15248 CARRIE DR
MARKIT REPAIR/REPLACE HARDWARE - 15101 APPLE BLOSSOM WAY
MARKIT REPAIR/REPLACE HARDWARE - 15166 MOORE HILL RD
MARKIT REPAIR/REPLACE HARDWARE - 15247 CLAIM JUMPER LN
MARKIT REMOVE DROP - 12685 ROUGH AND READY HWY
MARKIT REMOVE DROP - 11460 ARABIAN RANCH PL
MARKIT TREE TRIMMING REQUIRED - 15756 RATTLESNAKE RD
MARKIT RAISE AT&T SERVICE DROP - 10650 DIXON RD
MARKIT RAISE AT&T SERVICE DROP - 18910 CONNIE DR
MARKIT RAISE AT&T SERVICE DROP - 10595 DIXON RD
MARKIT REMOVE DROP - 10595 DIXON RD
MARKIT TREE TRIMMING REQUIRED - 16297 DAVID WAY

MARKIT REMOVE DROP - 10731 FOOTWALL DR
MARKIT REMOVE DROP - 10836 FOOTWALL DR
MARKIT REPAIR/REPLACE HARDWARE - 17110 NORLENE WAY
MARKIT REPAIR/REPLACE HARDWARE - 17241 NORLENE WAY
MARKIT TREE TRIMMING REQUIRED - 16985 LAWRENCE WAY
MARKIT REPAIR/REPLACE HARDWARE - 16870 ALIOTO DR
MARKIT REPAIR/REPLACE HARDWARE - 16816 ALIOTO DR
MARKIT REPAIR/REPLACE HARDWARE - 16142 SHARON WAY
MARKIT REPAIR/REPLACE HARDWARE - 11884 TAMMY WAY
MARKIT REMOVE DROP - 14556 POWERLINE RD
MARKIT REMOVE DROP - 10126 BITNEY SPRINGS RD
MARKIT REPAIR/REPLACE HARDWARE - 15038 BARLOW CT
MARKIT REMOVE DROP - 12956 RATTLESNAKE RD
MARKIT REMOVE DROP - 14128 HIGHLAND DR
MARKIT REPAIR/REPLACE HARDWARE - 14651 STORM RIDGE RD
MARKIT REMOVE DROP - 15721 SHEBLEY RD
MARKIT REMOVE DROP - 15658 SHEBLEY RD
MARKIT REPAIR/REPLACE HARDWARE - 16784 OSCAR DR
MARKIT REPAIR/REPLACE HARDWARE - 16725 OSCAR DR
MARKIT REPAIR/REPLACE HARDWARE - 15462 LORIE DR
MARKIT REMOVE DROP - 15330 ORCHARD SPRINGS RD
MARKIT REPAIR/REPLACE HARDWARE - 15232 ORCHARD SPRINGS RD
MARKIT REMOVE DROP - 12728 RATTLESNAKE RD
MARKIT TREE TRIMMING REQUIRED - 12126 MCCOURTNEY RD
MARKIT RAISE AT&T SERVICE DROP - 10565 DOUGLAS LN
MARKIT REPAIR/REPLACE HARDWARE - 16488 LOWER COLFAX RD
MARKIT RAISE AT&T SERVICE DROP - 17766 WOLF MOUNTAIN RD
MARKIT REMOVE DROP - 16966 AILEEN WAY
MARKIT TREE TRIMMING REQUIRED - 16966 AILEEN WAY
MARKIT TREE TRIMMING REQUIRED - 16683 AILEEN WAY
MARKIT REPAIR/REPLACE HARDWARE - 16851 OSCAR DR
MARKIT REPAIR/REPLACE HARDWARE - 17074 OSCAR DR
MARKIT TREE TRIMMING REQUIRED - 17113 OSCAR DR
MARKIT REPAIR/REPLACE HARDWARE - 16964 OSCAR DR
MARKIT REPAIR/REPLACE HARDWARE - 15269 ORCHARD SPRINGS RD
MARKIT PLACE CROSS/GUARD ARM - 15269 ORCHARD SPRINGS RD
MARKIT REMOVE DROP - 15496 MARINA DR
MARKIT REMOVE DROP - 15474 MARINA DR
MARKIT PLACE CROSS/GUARD ARM - 15474 MARINA DR
MARKIT TREE TRIMMING REQUIRED - 13895 COLFAX HWY
MARKIT REPAIR/REPLACE HARDWARE - MCCOURTNEY RD
MARKIT REPAIR/REPLACE HARDWARE - 16779 INDIAN HILL CIRCLE
MARKIT PLACE CROSS/GUARD ARM - 14116 JUDY LN
MARKIT REPAIR/REPLACE HARDWARE - 13785 MANION CANYON RD

MARKIT TREE TRIMMING REQUIRED - 17015 OSCAR DR
MARKIT REPAIR/REPLACE HARDWARE - 17722 OAK WAY
MARKIT TREE TRIMMING REQUIRED - 17241 VIRGINIA WAY
MARKIT REMOVE DROP - 10552 BRAGG AVE
MARKIT REMOVE DROP - 17403 ALEXANDRA WAY
MARKIT RAISE AT&T SERVICE DROP - 17403 ALEXANDRA WAY
MARKIT REMOVE DROP - 17598 ALEXANDRA WAY
MARKIT REPAIR/REPLACE HARDWARE - 17615 ROLLINS VIEW DR
MARKIT TREE TRIMMING REQUIRED - 14279 RYANS RANCH RD
MARKIT REMOVE DROP - 18014 ALEXANDRA WAY
MARKIT REPAIR/REPLACE HARDWARE - 16215 SHARON WAY
MARKIT TREE TRIMMING REQUIRED - 16269 SHARON WAY
MARKIT REPAIR/REPLACE HARDWARE - 16218 SHARON WAY
MARKIT TREE TRIMMING REQUIRED - 16218 SHARON WAY
MARKIT VEGETATION REMOVAL REQUIRED - 13049 GREENHORN RD
MARKIT REPAIR/REPLACE HARDWARE - 16399 SHARON WAY
MARKIT TREE TRIMMING REQUIRED - 13055 LA BARR MEADOWS RD
MARKIT REMOVE DROP - 19919 CASA LOMA DR
MARKIT REMOVE DROP - 11486 LOWER COLFAX RD
MARKIT REMOVE DROP - 13528 BROOKS RD
MARKIT REPAIR/REPLACE HARDWARE - 12732 SQUIRREL CREEK RD
MARKIT REMOVE DROP - 13091 IDAHO MARYLAND RD
MARKIT REMOVE DROP - 125 E EMPIRE ST
MARKIT REPAIR/REPLACE HARDWARE - 11758 TAMMY WAY
MARKIT REPAIR/REPLACE HARDWARE - 11685 TAMMY WAY
MARKIT PLACE CROSS/GUARD ARM - 15619 ORCHARD SPRINGS RD
MARKIT REMOVE DROP - 15487 LAKEVIEW DR
MARKIT REMOVE DROP - 15411 LAKEVIEW DR
MARKIT REMOVE DROP - 17386 VIRGINIA WAY
MARKIT TREE TRIMMING REQUIRED - 17435 VIRGINIA WAY
MARKIT REMOVE DROP - 10906 YUKON WAY
MARKIT REPAIR/REPLACE HARDWARE - 18206 SPRING VALLEY DR
MARKIT PLACE CROSS/GUARD ARM - 18206 SPRING VALLEY DR
MARKIT REPAIR/REPLACE HARDWARE - 11369 MICHAEL WAY
MARKIT REMOVE DROP - 535 RICHARDSON ST
MARKIT RAISE AT&T SERVICE DROP - 10943 YUKON WAY
MARKIT TREE TRIMMING REQUIRED - 17089 OLD STATE HWY
MARKIT VEGETATION REMOVAL REQUIRED - 17089 OLD STATE HWY
MARKIT RAISE AT&T SERVICE DROP - 18142 WALLIS DR
MARKIT TREE TRIMMING REQUIRED - 15389 GARY WAY
MARKIT PLACE CROSS/GUARD ARM - 15374 GEORGES MEADOWS
MARKIT REPAIR/REPLACE HARDWARE - 15127 CHATTERING PINES RD
MARKIT PLACE CROSS/GUARD ARM - 14979 CHATTERING PINES RD
MARKIT REMOVE DROP - 15066 CHATTERING PINES RD

MARKIT REMOVE DROP - 768 WOODLAND WAY
MARKIT REMOVE DROP - 11961 SLATE CREEK RD
MARKIT REMOVE DROP - 11742 SLATE CREEK RD
MARKIT TREE TRIMMING REQUIRED - 17060 ALEXANDRA WAY
MARKIT TREE TRIMMING REQUIRED - 12845 FRANCIS DR
MARKIT REMOVE DROP - 12808 FRANCIS DR
MARKIT REMOVE DROP - 17472 TROY CT
MARKIT VEGETATION REMOVAL REQUIRED - 17089 OLD STATE HWY
MARKIT REPAIR/REPLACE HARDWARE - 15380 CHATTERING PINES RD
MARKIT REMOVE DROP - 2153 NEVADA CITY HWY
MARKIT REMOVE DROP - 2297 NEVADA CITY HWY
MARKIT REMOVE DROP - 2322 NEVADA CITY HWY
MARKIT REMOVE DROP - 2153 NEVADA CITY HWY
MARKIT REMOVE DROP - 19598 TIGER LILY LN
MARKIT RAISE AT&T SERVICE DROP - 10682 QUAIL CREEK RD
MARKIT RAISE AT&T SERVICE DROP - 10395 QUAIL CREEK RD
MARKIT RAISE AT&T SERVICE DROP - 10947 ROUND VALLEY RD
MARKIT RAISE AT&T SERVICE DROP - 10800 ROUND VALLEY RD
MARKIT REMOVE DROP - 15318 LITTLE PINES RD
MARKIT REMOVE DROP - 14139 METZ RANCH RD
MARKIT REMOVE DROP - 150 APPLE AVE
MARKIT REMOVE DROP - 265 W OLYMPIA DR
MARKIT REMOVE DROP - 12786 S PONDEROSA WAY
MARKIT RAISE AT&T SERVICE DROP - 10478 WATERFORD PL
MARKIT REMOVE DROP - 21324 OAK RIDGE DR
MARKIT RAISE AT&T SERVICE DROP - 17454 ECHO VALLEY DR
MARKIT REMOVE DROP - 14827 LAKEWOOD LN
MARKIT REMOVE DROP - 15791 LAKEWOOD LN
MARKIT REMOVE DROP - 13773 SQUIRREL CREEK RD
MARKIT PLACE CROSS/GUARD ARM - 17652 SHADOW PINES DR
MARKIT REMOVE DROP - 15033 BROOKS RD
MARKIT REPAIR/REPLACE HARDWARE - 13751 ROUNDHOUSE CT
MARKIT REMOVE DROP - 14249 LOST LAKE RD
MARKIT REPAIR/REPLACE HARDWARE - 15474 MARINA DR
MARKIT PLACE CROSS/GUARD ARM - 13950 LOST LAKE RD
MARKIT VEGETATION REMOVAL REQUIRED - 13911 PEARDALE LN
MARKIT REPAIR/REPLACE HARDWARE - 15156 ORCHARD SPRINGS RD
MARKIT RAISE AT&T SERVICE DROP - 11261 PEKOLEE DR
MARKIT REPAIR/REPLACE HARDWARE - 16984 SCOTT WAY
MARKIT RAISE AT&T SERVICE DROP - 16883 SCOTT WAY
MARKIT REMOVE DROP - 15625 LAKEWOOD LN
MARKIT REPAIR/REPLACE HARDWARE - 15455 LAKEWOOD LN
MARKIT TREE TRIMMING REQUIRED - 14132 MANION CANYON RD
MARKIT REPAIR/REPLACE HARDWARE - 14314 MANION CANYON RD

MARKIT TREE TRIMMING REQUIRED - 14292 COLFAX HWY
MARKIT REMOVE DROP - 13871 HIGHLAND DR
MARKIT REMOVE DROP - 14421 YOU BET RD
MARKIT REMOVE DROP - 18471 REESE LN
MARKIT REPAIR/REPLACE HARDWARE - 14285 YOU BET RD
MARKIT RAISE AT&T SERVICE DROP - 20604 MCCOURTNEY RD
MARKIT REPAIR/REPLACE HARDWARE - 11218 AGNES WAY
MARKIT REMOVE DROP - 312 COLFAX AVE
MARKIT REMOVE DROP - 408 COLFAX AVE
MARKIT TREE TRIMMING REQUIRED - 17495 ANONA CT
MARKIT REMOVE DROP - 15159 LAKEWOOD LN
MARKIT REMOVE DROP - 11607 VIEW DR
MARKIT REPAIR/REPLACE HARDWARE - 15012 LAKEWOOD LN
MARKIT REPAIR/REPLACE HARDWARE - 17027 LAWRENCE WAY
MARKIT REMOVE DROP - 311 HUGHES RD
MARKIT REPAIR/REPLACE HARDWARE - 12876 LOST LAKE RD
MARKIT REMOVE DROP - 235 BRESEE PL
MARKIT REMOVE DROP - 12915 LOST LAKE RD
MARKIT TREE TRIMMING REQUIRED - 13508 BROOKS RD
MARKIT REPAIR/REPLACE HARDWARE - 16281 MOUNT OLIVE RD
MARKIT REPAIR/REPLACE HARDWARE - 16065 MOUNT OLIVE RD
MARKIT REMOVE DROP - 15390 BIRCH MEADOWS CIRCLE
MARKIT REPAIR/REPLACE HARDWARE - 15959 MOUNT OLIVE RD
MARKIT RAISE AT&T SERVICE DROP - 18616 NORLENE WAY
MARKIT REPAIR/REPLACE HARDWARE - 13499 SUNSHINE MEADOWS TRAIL
MARKIT REPAIR/REPLACE HARDWARE - 16433 KIWI RD
MARKIT REPAIR/REPLACE HARDWARE - 16343 AUBURN RD
MARKIT REPAIR/REPLACE HARDWARE - 18006 OAK WAY
MARKIT REMOVE DROP - 17878 MAPLE WAY
MARKIT REMOVE DROP - 14013 BIRCH RD
MARKIT REMOVE DROP - 12784 MADRONE FOREST DR
MARKIT REPAIR/REPLACE HARDWARE - 17082 ALIOTO DR
MARKIT REPAIR/REPLACE HARDWARE - 16927 ANGELINA WAY
MARKIT REPAIR/REPLACE HARDWARE - 16647 ALIOTO DR
MARKIT REPAIR/REPLACE HARDWARE - 16708 ALIOTO DR
MARKIT REPAIR/REPLACE HARDWARE - 16998 ALIOTO DR
MARKIT REPAIR/REPLACE HARDWARE - 17252 BLUM RD
MARKIT REMOVE DROP - 15865 MOUNT OLIVE RD
MARKIT REMOVE DROP - 11098 WHEELER CROSS RD
MARKIT REPAIR/REPLACE HARDWARE - 15630 MOUNT OLIVE RD
MARKIT RAISE AT&T SERVICE DROP - 18938 SAINT PAUL PL
MARKIT REPAIR/REPLACE HARDWARE - 18701 END THREE LN
MARKIT TREE TRIMMING REQUIRED - 15594 DEL VISTA CT
MARKIT REMOVE DROP - 13649 LUPINE CT

MARKIT REPAIR/REPLACE HARDWARE - 18545 CACTUS LN
MARKIT PLACE CROSS/GUARD ARM - 18570 CACTUS LN
MARKIT REPAIR/REPLACE HARDWARE - 17040 ROUND VALLEY CIRCLE
MARKIT REMOVE DROP - 18240 OLD COACH WAY
MARKIT RAISE AT&T SERVICE DROP - 17202 BIVENS PL
MARKIT REMOVE DROP - 10189 SHADY OAK PL
MARKIT RAISE AT&T SERVICE DROP - 10189 SHADY OAK PL
MARKIT TREE TRIMMING REQUIRED - 13348 GRASS VALLEY AVE
MARKIT REMOVE DROP - 14130 LIQUIDAMBAR LN
MARKIT VEGETATION REMOVAL REQUIRED - 18638 MCCOURTNEY RD
MARKIT TREE TRIMMING REQUIRED - 11363 CEDAR RIDGE DR
MARKIT REMOVE DROP - 11363 CEDAR RIDGE DR
MARKIT REMOVE DROP - 12328 ROUGH AND READY HWY
MARKIT REMOVE DROP - 13055 BLUE JAY HILL RD
MARKIT REPAIR/REPLACE HARDWARE - 15252 CLOVER VALLEY RD
MARKIT LOWER OR RAISE EXISTING CABLE - 12291 KENNETH CT
MARKIT REMOVE DROP - 13289 LOWER ANCHOR LN
MARKIT TREE TRIMMING REQUIRED - 14451 LITTLE HILL LN
MARKIT REPAIR/REPLACE HARDWARE - 13036 CAPITOL DR
MARKIT REMOVE DROP - 14621 CHEROKEE LN
MARKIT REPAIR/REPLACE HARDWARE - 14000 ARROWHEAD MINE RD
MARKIT REMOVE DROP - 13992 ARROWHEAD MINE RD
MARKIT REPAIR/REPLACE HARDWARE - 16829 INDIAN HILL CIRCLE
MARKIT TREE TRIMMING REQUIRED - 13226 GREENHORN RD
MARKIT REMOVE DROP - 10475 ALTA ST
MARKIT REMOVE DROP - 10687 ALTA ST
MARKIT REMOVE DROP - 10400 ALTA ST
MARKIT REPAIR/REPLACE HARDWARE - 14185 SONTAG HILL RD
MARKIT REMOVE DROP - 14580 OAK LEAF LN
MARKIT REPAIR/REPLACE HARDWARE - 15833 KITKITDIZZE DR
MARKIT REMOVE DROP - 11478 AVERN WAY
MARKIT REMOVE DROP - 12933 CEDAR CREST LN
MARKIT REPAIR/REPLACE HARDWARE - 15575 KITKITDIZZE DR
MARKIT REPAIR/REPLACE HARDWARE - 15689 STRAWBERRY LN
MARKIT REPAIR/REPLACE HARDWARE - 13083 WILD LIFE LN
MARKIT REMOVE DROP - 13036 CAPITOL DR
MARKIT REPAIR/REPLACE HARDWARE - 13271 LOWER ANCHOR LN
MARKIT LOWER OR RAISE EXISTING CABLE - 14972 CARRIE DR
MARKIT REPAIR/REPLACE HARDWARE - 15708 YOU BET RD
MARKIT TREE TRIMMING REQUIRED - 14155 THOROUGHBRED LOOP
MARKIT REMOVE DROP - 10975 WILL O WISP CT
MARKIT REPAIR/REPLACE HARDWARE - 11244 LONE LOBO TRAIL
MARKIT REMOVE DROP - 13440 JONES BAR RD
MARKIT REMOVE DROP - 12281 MADRONA WAY

MARKIT REMOVE DROP - 13977 CAMEO LN
MARKIT REMOVE DROP - 846 FOREST GLADE CIRCLE
MARKIT REMOVE DROP - 840 FOREST GLADE CIRCLE
MARKIT REPAIR/REPLACE HARDWARE - 11422 AVERN WAY
MARKIT REPAIR/REPLACE HARDWARE - 14585 FIFIELD RD
MARKIT PLACE CROSS/GUARD ARM - 14585 FIFIELD RD
MARKIT REPAIR/REPLACE HARDWARE - 14477 MAKIKUJA DR
MARKIT REPAIR/REPLACE HARDWARE - 15088 LORIE DR
MARKIT REPAIR/REPLACE HARDWARE - 15120 FAY RD
MARKIT REPAIR/REPLACE HARDWARE - 15488 YOU BET RD
MARKIT REMOVE DROP - 11892 PARADISE LN
MARKIT REPAIR/REPLACE HARDWARE - 16148 YOU BET RD
MARKIT REPAIR/REPLACE HARDWARE - 16800 YOU BET RD
MARKIT REMOVE DROP - 21498 YOU BET RD
MARKIT TREE TRIMMING REQUIRED - 13556 CRAWFORD LN
MARKIT REMOVE DROP - 20588 YOU BET RD
MARKIT REPAIR/REPLACE HARDWARE - 20625 YOU BET RD
MARKIT REPAIR/REPLACE HARDWARE - 13680 BITNEY SPRINGS RD
MARKIT REPAIR/REPLACE HARDWARE - 13804 BITNEY SPRINGS RD
MARKIT REPAIR/REPLACE HARDWARE - 13422 N PONDEROSA WAY
MARKIT REPAIR/REPLACE HARDWARE - 13846 GOLD FORK RD
MARKIT REPAIR/REPLACE HARDWARE - 13717 WITT LN
MARKIT REPAIR/REPLACE HARDWARE - 13422 N PONDEROSA WAY
MARKIT REPAIR/REPLACE HARDWARE - 13422 N PONDEROSA WAY
MARKIT REMOVE DROP - 14614 BITNEY SPRINGS RD
MARKIT REMOVE DROP - 12332 MADRONA WAY
MARKIT REMOVE DROP - 12200 CASCADE WAY
MARKIT REMOVE DROP - 14527 ROUGH AND READY HWY
MARKIT REPAIR/REPLACE HARDWARE - 115 GREY OWL CT
MARKIT REMOVE DROP - 578 DOUGLAS AVE
MARKIT REMOVE DROP - 10856 GOLD HILL DR
MARKIT REMOVE DROP - 10890 GOLD HILL DR
MARKIT REMOVE DROP - 12771 RIDGE RD
MARKIT REMOVE DROP - 13747 ROUGH AND READY HWY
MARKIT REPAIR/REPLACE HARDWARE - 13670 CAPITOL DR
MARKIT REPAIR/REPLACE HARDWARE - 13036 CAPITOL DR
MARKIT REPAIR/REPLACE HARDWARE - 14909 KELSEY LN
MARKIT PLACE CROSS/GUARD ARM - 14909 KELSEY LN
MARKIT LOWER OR RAISE EXISTING CABLE - 19164 WOLF CREEK RD
MARKIT REMOVE DROP - 13601 CLANCY WAY
MARKIT REMOVE DROP - 13353 PEARDALE RD
MARKIT REPAIR/REPLACE HARDWARE - 14369 GREENPEACE LN
MARKIT REPAIR/REPLACE HARDWARE - 16890 YOU BET RD
MARKIT REMOVE DROP - 16876 YOU BET RD

MARKIT REMOVE DROP - 13572 MULE CANYON RD
MARKIT REMOVE DROP - 16236 INYOKERN WAY
MARKIT REPAIR/REPLACE HARDWARE - 16481 INYOKERN WAY
MARKIT REPAIR/REPLACE HARDWARE - 17223 YOU BET RD
MARKIT REPAIR/REPLACE HARDWARE - 12312 POLARIS DR
MARKIT REPAIR/REPLACE HARDWARE - 14163 JOKERS WILD LN
MARKIT TREE TRIMMING REQUIRED - 15318 LOWER COLFAX RD
MARKIT REMOVE DROP - 101 LEAHY RD
MARKIT REMOVE DROP - 405 E MAIN ST
MARKIT REMOVE DROP - 11220 BITNEY SPRINGS RD
MARKIT REMOVE DROP - 13504 EMPRESS RD
MARKIT REMOVE DROP - 13194 KENTUCKY FLAT RD
MARKIT REPAIR/REPLACE HARDWARE - 11823 LOST RANCH WAY
MARKIT REPAIR/REPLACE HARDWARE - 13985 HOLLAND DR
MARKIT REPAIR/REPLACE HARDWARE - 14153 LILY CREEK TRAIL
MARKIT REMOVE DROP - 14266 INDIAN SPRINGS RD
MARKIT REPAIR/REPLACE HARDWARE - 12941 WILD ROSE CT
MARKIT REMOVE DROP - 12638 WILD ROSE CT
MARKIT REPAIR/REPLACE HARDWARE - 14431 GREENHORN ACCESS RD
MARKIT REPAIR/REPLACE HARDWARE - 14620 ROLLINS PARK DR
MARKIT VEGETATION REMOVAL REQUIRED - 13071 COLFAX HWY
MARKIT REPAIR/REPLACE HARDWARE - 13856 SEVEN CEDARS DR
MARKIT REPAIR/REPLACE HARDWARE - 17354 BREWER RD
MARKIT REMOVE DROP - 11120 GLEN LOOP
MARKIT REMOVE DROP - 14727 SONTAG RD
MARKIT REMOVE DROP - 10073 WESTHILL RD
MARKIT REPAIR/REPLACE HARDWARE - 11588 SHOCKLEY RD
MARKIT REMOVE DROP - 11460 SQUIRREL CREEK RD
MARKIT REPAIR/REPLACE HARDWARE - 10455 ROBIN AVE
MARKIT REPAIR/REPLACE HARDWARE - 10555 NO NAME DR
MARKIT REMOVE DROP - 10343 ROBIN AVE
MARKIT REMOVE DROP - 11580 CRESTWOOD ST
MARKIT REPAIR/REPLACE HARDWARE - 11046 NUGGET LN
MARKIT REMOVE DROP - 10161 OWL RD
MARKIT PLACE CROSS/GUARD ARM - 17188 LAWTON WAY
MARKIT PLACE CROSS/GUARD ARM - 18788 YOU BET RD
MARKIT REPAIR/REPLACE HARDWARE - 13613 OLD EMIGRANT TRAIL
MARKIT PLACE CROSS/GUARD ARM - 13613 OLD EMIGRANT TRAIL
MARKIT REPAIR/REPLACE HARDWARE - 13831 OLD EMIGRANT TRAIL
MARKIT REPAIR/REPLACE HARDWARE - 18987 YOU BET RD
MARKIT REPAIR/REPLACE HARDWARE - 13690 HOPEFUL HILL RD
MARKIT REMOVE DROP - 13502 HOPEFUL HILL RD
MARKIT REPAIR/REPLACE HARDWARE - 12826 NEWTOWN RD
MARKIT REMOVE DROP - 14564 INDIAN SPRINGS RD

MARKIT REMOVE DROP - 13421 ROCKY RHODES PL
MARKIT REPAIR/REPLACE HARDWARE - 14219 ROLLINS PARK DR
MARKIT REMOVE DROP - 14446 ROLLINS PARK DR
MARKIT REMOVE DROP - 15543 WOLF MOUNTAIN RD
MARKIT REPAIR/REPLACE HARDWARE - 14433 DALMATIAN DR
MARKIT REPAIR/REPLACE HARDWARE - 14598 DALMATIAN DR
MARKIT PLACE CROSS/GUARD ARM - 17082 BREWER RD
MARKIT PLACE CROSS/GUARD ARM - 16960 BREWER RD
MARKIT REMOVE DROP - 11355 BRUNSWICK DR
MARKIT REMOVE DROP - 11257 BRUNSWICK DR
MARKIT TREE TRIMMING REQUIRED - 12719 COLFAX HWY
MARKIT REMOVE DROP - 14527 ROUGH AND READY HWY
MARKIT REMOVE DROP - 10665 CEDAR WAY
MARKIT REMOVE DROP - 10942 SUNRISE HEIGHTS
MARKIT VEGETATION REMOVAL REQUIRED - 13120 LOMA RICA DR
MARKIT REMOVE DROP - 10104 WESTHILL RD
MARKIT REMOVE DROP - 10104 WESTHILL RD
MARKIT REMOVE DROP - 13059 JOHN BAUER AVE
MARKIT VEGETATION REMOVAL REQUIRED - 12908 LOMA RICA DR
MARKIT REPAIR/REPLACE HARDWARE - 550 IVY ST
MARKIT REMOVE DROP - 412 LINDEN AVE
MARKIT PLACE CROSS/GUARD ARM - 15365 ZINFANDEL LN
MARKIT REPAIR/REPLACE HARDWARE - 10290 GOLD DR
MARKIT REMOVE DROP - 10548 CEDAR AVE
MARKIT REMOVE DROP - 11243 SQUIRREL CREEK RD
MARKIT REPAIR/REPLACE HARDWARE - 13146 HIDDEN VALLEY RD
MARKIT REMOVE DROP - 236 N CHURCH ST
MARKIT REMOVE DROP - 10701 WALKER DR
MARKIT REMOVE DROP - 10606 WALKER DR
MARKIT REMOVE DROP - 11320 ALPINE LN
MARKIT REMOVE DROP - 13175 PERSONENI LN
MARKIT REMOVE DROP - 13073 WOOLMAN LN
MARKIT REMOVE DROP - 10523 TASHA RD
MARKIT TREE TRIMMING REQUIRED - 12894 GREENHORN RD
MARKIT REMOVE DROP - 12803 MACBOYLE WAY
MARKIT REMOVE DROP - 15490 CLEAR CREEK PL
MARKIT TREE TRIMMING REQUIRED - 11121 CEDAR RIDGE DR
MARKIT REMOVE DROP - 11156 CEDAR RIDGE DR
MARKIT REPAIR/REPLACE HARDWARE - 14741 DALMATIAN DR
MARKIT REMOVE DROP - 10038 ROUGH AND READY RD
MARKIT TREE TRIMMING REQUIRED - 11097 BRUNSWICK DR
MARKIT REMOVE DROP - 11025 CEDAR RIDGE DR
MARKIT REMOVE DROP - 10904 BRUNSWICK RD
MARKIT REPAIR/REPLACE HARDWARE - 10912 CANYON VIEW DR

MARKIT REMOVE DROP - 10961 CEDAR WAY
MARKIT REMOVE DROP - 13173 RIDGE RD
MARKIT REMOVE DROP - 11292 VISTA AVE
MARKIT REMOVE DROP - 13261 RIDGE RD
MARKIT REMOVE DROP - 10426 CAREY DR
MARKIT REMOVE DROP - 14570 ROUGH AND READY HWY
MARKIT REMOVE DROP - 13368 RIDGE RD
MARKIT REPAIR/REPLACE HARDWARE - 16006 CLOVER VALLEY RD
MARKIT REPAIR/REPLACE HARDWARE - 14602 YOU BET RD
MARKIT REMOVE DROP - 13528 FAWN HILL DR
MARKIT PLACE CROSS/GUARD ARM - 14107 SONTAG RD
MARKIT REPAIR/REPLACE HARDWARE - 14030 SONTAG RD
MARKIT REPAIR/REPLACE HARDWARE - 18714 WOLF CREEK RD
MARKIT LOWER OR RAISE EXISTING CABLE - 18714 WOLF CREEK RD
MARKIT RAISE AT&T SERVICE DROP - 11163 SQUIRREL CREEK RD
MARKIT REPAIR/REPLACE HARDWARE - 18451 FAY RIDGE CT
MARKIT REMOVE DROP - 10781 WALKER DR
MARKIT REMOVE DROP - 110 CARPENTER ST
MARKIT PLACE CROSS/GUARD ARM - 20307 RED DOG RD
MARKIT REMOVE DROP - 10583 TASHA RD
MARKIT REMOVE DROP - 13205 ARTIC OWL RD
MARKIT REMOVE DROP - 13509 MYERS PL
MARKIT REMOVE DROP - 12273 JONES BAR RD
MARKIT REMOVE DROP - 12751 KENTUCKY FLAT RD
MARKIT REMOVE DROP - 13075 WOOLMAN LN
MARKIT REPAIR/REPLACE HARDWARE - 12820 WOOLMAN LN
MARKIT REPAIR/REPLACE HARDWARE - 12959 WOOLMAN LN
MARKIT RAISE AT&T SERVICE DROP - 12894 WOODLAKE RD
MARKIT REPAIR/REPLACE HARDWARE - 12538 WOODLAKE RD
MARKIT REPAIR/REPLACE HARDWARE - 12538 WOODLAKE RD
MARKIT REMOVE DROP - 14570 ROUGH AND READY HWY
MARKIT REMOVE DROP - 13924 DAY SPRING RD
MARKIT REPAIR/REPLACE HARDWARE - 16091 JOHN WAY
MARKIT REPAIR/REPLACE HARDWARE - 16385 CLOVER VALLEY RD
MARKIT REPAIR/REPLACE HARDWARE - 15971 JOHN WAY
MARKIT REMOVE DROP - 11101 ROUGH AND READY HWY
MARKIT REMOVE DROP - 11101 ROUGH AND READY HWY
MARKIT REPAIR/REPLACE HARDWARE - 18395 WOLF CREEK RD
MARKIT REMOVE DROP - 11415 ROUGH AND READY HWY
MARKIT REMOVE DROP - 10700 MOUNTAINEER TRAIL
MARKIT REMOVE DROP - 14262 MEADOW DR
MARKIT REMOVE DROP - 10539 OAK ST
MARKIT REPAIR/REPLACE HARDWARE - 13530 EOWANA LN
MARKIT REMOVE DROP - 807 W MAIN ST

MARKIT RAISE AT&T SERVICE DROP - 13074 WOOLMAN LN
MARKIT REMOVE DROP - 155 HARRIS ST
MARKIT REMOVE DROP - 348 E MAIN ST
MARKIT REMOVE DROP - 152 HARRIS ST
MARKIT REMOVE DROP - 11176 GLEN MEADOW DR
MARKIT REMOVE DROP - 704 1/2 BUTLER ST
MARKIT REPAIR/REPLACE HARDWARE - 11117 GIBSON DR
MARKIT REMOVE DROP - 11221 GLEN MEADOW DR
MARKIT REMOVE DROP - 11203 GLEN MEADOW DR
MARKIT REPAIR/REPLACE HARDWARE - 15615 LUCKIE RD
MARKIT REPAIR/REPLACE HARDWARE - 13206 MCCARTER WAY
MARKIT PLACE CROSS/GUARD ARM - 16378 HOUND DOG DR
MARKIT REMOVE DROP - 11866 FOREST VIEW DR
MARKIT REMOVE DROP - 11398 BANNER LAVA CAP RD
MARKIT REMOVE DROP - 11398 BANNER LAVA CAP RD
MARKIT REMOVE DROP - 11649 BANNER LAVA CAP RD
MARKIT REPAIR/REPLACE HARDWARE - 14950 S PONDEROSA WAY
MARKIT REPAIR/REPLACE HARDWARE - 13892 THOROUGHBRED LOOP
MARKIT REPAIR/REPLACE HARDWARE - 14826 YOU WIN CT
MARKIT REPAIR/REPLACE HARDWARE - 13655 KHALID CT
MARKIT RAISE AT&T SERVICE DROP - 16806 GREENHORN RD
MARKIT REPAIR/REPLACE HARDWARE - 14233 THOROUGHBRED LOOP
MARKIT REPAIR/REPLACE HARDWARE - 14274 RUDD RD
MARKIT REMOVE DROP - 15050 SKAITH BEND RD
MARKIT REMOVE DROP - 15155 SKAITH BEND RD
MARKIT REMOVE DROP - 15606 KARDALE CT
MARKIT REPAIR/REPLACE HARDWARE - 10500 REX RESERVOIR RD
MARKIT REMOVE DROP - 10978 BITNEY SPRINGS RD
MARKIT REMOVE DROP - 13136 WHITE CANOE LN
MARKIT REPAIR/REPLACE HARDWARE - 10660 DOUGLAS LN
MARKIT REMOVE DROP - 13865 LOST TRAIL
MARKIT REMOVE DROP - 12645 LA BARR MEADOWS RD
MARKIT Rmvd abandoned drops.
MARKIT REPAIR/REPLACE HARDWARE - 970 LAKE DAVIS RD
MARKIT RAISE AT&T SERVICE DROP - 660 COLORADO ST
MARKIT RAISE AT&T SERVICE DROP - 109 VIRGILIA AVE
MARKIT REPAIR/REPLACE HARDWARE - 5685 IRON HORSE DR
MARKIT REMOVE DROP - 241 LADERA LN
MARKIT REPAIR/REPLACE HARDWARE - 5323 PORTOLA-MCLEARS RD
MARKIT REPAIR/REPLACE HARDWARE - 5846 IRON HORSE
MARKIT REMOVE DROP - 6052 SEMAPHORE RD
MARKIT REPAIR/REPLACE HARDWARE - 5878 SEMAPHORE RD
MARKIT REPAIR/REPLACE HARDWARE - 5878 SEMAPHORE RD
MARKIT REPAIR/REPLACE HARDWARE - 6105 SEMAPHORE

MARKIT REPAIR/REPLACE HARDWARE - 6143 SEMAPHORE RD
MARKIT REMOVE DROP - 5600 SEMAPHORE RD
MARKIT REMOVE DROP - 73559 STATE ROUTE 70
MARKIT REPAIR/REPLACE HARDWARE - 76728 SUNSET DR
MARKIT REMOVE DROP - 713 WOLF AVE
MARKIT REPAIR/REPLACE HARDWARE - 713 WOLF AVE
MARKIT REPAIR/REPLACE HARDWARE - 678 SAGEBRUSH ST
MARKIT REPAIR/REPLACE HARDWARE - 675 SAGEBRUSH ST
MARKIT REPAIR/REPLACE HARDWARE - 74524 STATE ROUTE 70
MARKIT REPAIR/REPLACE HARDWARE - 73783 S DELLEKER RD
MARKIT REPAIR/REPLACE HARDWARE - 41413 PURDY LN
MARKIT TREE TRIMMING REQUIRED - 42045 STATE HIGHWAY 70
MARKIT REMOVE DROP - 202 SPANISH CREEK RD
MARKIT REPAIR/REPLACE HARDWARE - 124 SPANISH CREEK RD
MARKIT REMOVE DROP - 41511 WESTS RANCH RD
MARKIT REPAIR/REPLACE HARDWARE - 1977 GREENHORN RANCH RD
MARKIT REPAIR/REPLACE HARDWARE - 1917 GREENHORN RANCH RD
MARKIT REPAIR/REPLACE HARDWARE - 5847 IRON HORSE DR
MARKIT REPAIR/REPLACE HARDWARE - 5774 CASEY JONES RD
MARKIT REMOVE DROP - 5576 CASEY JONES RD
MARKIT REPAIR/REPLACE HARDWARE - 5915 IRON HORSE DR
MARKIT REPAIR/REPLACE HARDWARE - 6075 CRACKERJACK CREEK RD
MARKIT REPAIR/REPLACE HARDWARE - 1970 BUCKS LAKE RD
MARKIT REPAIR/REPLACE HARDWARE - 1919 BUCKS LAKE RD
MARKIT REPAIR/REPLACE HARDWARE - 2176 PINE CONE LN
MARKIT REPAIR/REPLACE HARDWARE - 2469 GREENHORN RANCH RD
MARKIT REPAIR/REPLACE HARDWARE - 2675 CROOKED CREEK LN
MARKIT REPAIR/REPLACE HARDWARE - 2648 GREENHORN RANCH RD
MARKIT REPAIR/REPLACE HARDWARE - 2430 GREENHORN RANCH RD
MARKIT REPAIR/REPLACE HARDWARE - 2530 GOLDEN WEST RD
MARKIT REPAIR/REPLACE HARDWARE - 2538 GREENHORN RANCH RD
MARKIT REMOVE DROP - 2481 FOUNTAIN SPRINGS LN
MARKIT REPAIR/REPLACE HARDWARE - 2489 FOUNTAIN SPRINGS LN
MARKIT REPAIR/REPLACE HARDWARE - 560 HILLSIDE DR
MARKIT REPAIR/REPLACE HARDWARE - 2397 RUNNING SPRINGS LN
MARKIT REPAIR/REPLACE HARDWARE - 2232 BUCKHORN TRAIL
MARKIT REPAIR/REPLACE HARDWARE - 89 DELLEKER DR
MARKIT REMOVE DROP - 183 DELLEKER
MARKIT REPAIR/REPLACE HARDWARE - 259 LADERA
MARKIT REPAIR/REPLACE HARDWARE - 328 BELLA VISTA DR
MARKIT REPAIR/REPLACE HARDWARE - 254 BELLA VISTA DR
MARKIT REPAIR/REPLACE HARDWARE - 302 BELLA VISTA DR
MARKIT REPAIR/REPLACE HARDWARE - 286 BELLA VISTA DR
MARKIT REPAIR/REPLACE HARDWARE - 200 COLINA CT

MARKIT REMOVE DROP - 74509 STATE ROUTE 70
MARKIT REPAIR/REPLACE HARDWARE - 76601 ASPEN DR
MARKIT REPAIR/REPLACE HARDWARE - 815 MEADOW WAY
MARKIT REPAIR/REPLACE HARDWARE - 1260 CHANDLER RD
MARKIT TREE TRIMMING REQUIRED - 575 QUINCY JUNCTION RD
MARKIT REMOVE DROP - 123 SUGAR PINE DR
MARKIT REPAIR/REPLACE HARDWARE - 218 DELLEKER PARK
MARKIT REPAIR/REPLACE HARDWARE - 217 PORTOLA-MCLEARS RD
MARKIT REPAIR/REPLACE HARDWARE - 306 BELLA VISTA
MARKIT REPAIR/REPLACE HARDWARE - 316 BELLA VISTA DR
MARKIT RAISE AT&T SERVICE DROP - 340 N GULLING ST
MARKIT RAISE AT&T SERVICE DROP - 217 E MAGNOLIA AVE
MARKIT RAISE AT&T SERVICE DROP - 355 JOY WAY
MARKIT RAISE AT&T SERVICE DROP - 623 N BECKWITH ST
MARKIT REPAIR/REPLACE HARDWARE - 276 CLARENCE LN
MARKIT REMOVE DROP - 8071 BUCKS LAKE RD
MARKIT REPAIR/REPLACE HARDWARE - 31 S MILL CREEK RD
MARKIT REPAIR/REPLACE HARDWARE - 178 S MILL CREEK RD
MARKIT REMOVE DROP - 1958 E CLAREMONT WAY
MARKIT REPAIR/REPLACE HARDWARE - 127 SIERRA WAY
MARKIT REPAIR/REPLACE HARDWARE - 510 E MAGNOLIA AVE
MARKIT RAISE AT&T SERVICE DROP - 870 ELLEN AVE
MARKIT RAISE AT&T SERVICE DROP - 80 W MOHAWK AVE
MARKIT RAISE AT&T SERVICE DROP - 80 RENO AVE
MARKIT REPAIR/REPLACE HARDWARE - 654 LAKE DAVIS RD
MARKIT REPAIR/REPLACE HARDWARE - 32160 PAXTON RD
MARKIT REPAIR/REPLACE HARDWARE - 2525 BUCKS LAKE RD
MARKIT REPAIR/REPLACE HARDWARE - 2117 MANSELL ST
MARKIT REPAIR/REPLACE HARDWARE - 2266 BUCKS LAKE RD
MARKIT REPAIR/REPLACE HARDWARE - 77 1ST ST
MARKIT REPAIR/REPLACE HARDWARE - 73944 OLD COUNTY RD
MARKIT REPAIR/REPLACE HARDWARE - 76608 ASPEN DR
MARKIT REPAIR/REPLACE HARDWARE - 76687 PARKSIDE TER
MARKIT REPAIR/REPLACE HARDWARE - 76689 PARKSIDE TERRACE
MARKIT REPAIR/REPLACE HARDWARE - 76755 ROCKY POINT RD
MARKIT REPAIR/REPLACE HARDWARE - 2025 E CLAREMONT WAY
MARKIT REPAIR/REPLACE HARDWARE - 240 MILLER RD
MARKIT REMOVE DROP - 304 S MILL CREEK RD
MARKIT REPAIR/REPLACE HARDWARE - 48 N MILL CREEK RD
MARKIT REPAIR/REPLACE HARDWARE - 62 N MILL CREEK RD
MARKIT REPAIR/REPLACE HARDWARE - 2037 LEE RD
MARKIT REPAIR/REPLACE HARDWARE - 1906 LEE RD
MARKIT REPAIR/REPLACE HARDWARE - 47 VIERRA DR
MARKIT REPAIR/REPLACE HARDWARE - 116 CLOUGH ST

MARKIT REPAIR/REPLACE HARDWARE - 23 CLOUGH ST
MARKIT REPAIR/REPLACE HARDWARE - 746 LEE RD
MARKIT REPAIR/REPLACE HARDWARE - 670 LEE RD
MARKIT REPAIR/REPLACE HARDWARE - 358 BELL LN
MARKIT REMOVE DROP - 730 BRESCIANI CIRCLE
MARKIT VEGETATION REMOVAL REQUIRED - 86 S LINDAN AVE
MARKIT REMOVE DROP - 852 QUINCY JUNCTION RD
MARKIT REPAIR/REPLACE HARDWARE - 72 BESKEEN LN
MARKIT REPAIR/REPLACE HARDWARE - 41784 STATE HIGHWAY 70
MARKIT REPAIR/REPLACE HARDWARE - 845 QUINCY JUNCTION RD
MARKIT TREE TRIMMING REQUIRED - 41572 STATE HIGHWAY 70
MARKIT TREE TRIMMING REQUIRED - 41548 STATE HIGHWAY 70
MARKIT REMOVE DROP - 48545 STATE HIGHWAY 70
MARKIT REPAIR/REPLACE HARDWARE - 2125 BLACKRIDGE TRAIL
MARKIT REPAIR/REPLACE HARDWARE - 241 LADERA LN
MARKIT REPAIR/REPLACE HARDWARE - 259 CUESTA
MARKIT REPAIR/REPLACE HARDWARE - 248 LADERA
MARKIT REPAIR/REPLACE HARDWARE - 165 5TH ST
MARKIT REPAIR/REPLACE HARDWARE - 2298 MANSELL ST
MARKIT REPAIR/REPLACE HARDWARE - 2210 CENTER ST
MARKIT REPAIR/REPLACE HARDWARE - 2086 BUCKS LAKE RD
MARKIT REPAIR/REPLACE HARDWARE - 2116 BUCKS LAKE RD
MARKIT REPAIR/REPLACE HARDWARE - 2393 BUCKS LAKE RD
MARKIT REPAIR/REPLACE HARDWARE - 1991 BUCKS LAKE RD
MARKIT REPAIR/REPLACE HARDWARE - 119 SMITHNECK RD
MARKIT REMOVE DROP - 623 BEAR VALLEY RD
MARKIT RAISE AT&T SERVICE DROP - 422 RANCHO CIRCLE DR
MARKIT REPAIR/REPLACE HARDWARE - 405005 SCOTT RD
MARKIT REPAIR/REPLACE HARDWARE - SHEEP RANCH RD
MARKIT REMOVE DROP - 403505 SCOTT
MARKIT REMOVE DROP - COUNTRY LN
MARKIT REMOVE DROP - 752250 SCOTT
MARKIT REMOVE DROP - SCOTT RD
MARKIT REMOVE DROP - 957 W SIERRA BROOKS DR
MARKIT REMOVE DROP - 937 W SIERRA BROOKS DR
MARKIT REPAIR/REPLACE HARDWARE - 515 LONGHORN DR
MARKIT REPAIR/REPLACE HARDWARE - 709 ROUNDUP DR
MARKIT REPAIR/REPLACE HARDWARE - 728 ROUNDUP DR
MARKIT REPAIR/REPLACE HARDWARE - 59 MUSTANG TRAIL

MARKIT 15948 Brooks Rd Grass Valley CA

MARKIT Due to severe storm incident strand and cable are on the ground along roadway

MARKIT Due to severe storm incident strand and cable are on the ground along roadway

ıe down and snapped a pole, pole has been replaced but cable and strand are along roadway and needs replacement.

ıe down and snapped a pole, pole has been replaced but cable and strand are along roadway and needs replacement.

MARKIT 11957 Tammy Way Grass Valley CA.
MARKIT 12311 Crescent Dr Grass Valley CA
MARKIT 12311 Crescent Dr Grass Valley CA

MARKIT Due to severe 12/21 storms trees have fallen bring down strand and cable
MARKIT Replace service drop temp with new,after strom. 5308367258
MARKIT Replace temp drop on good after storm. 5308364617

d pole. Need cable placed back on pole approx 250ft. Cable laying on ground and missing from pole 11270 Diamond E
MARKIT Heavy tree weighing on pole causing terminal to get pulled out and twisted

MARKIT Cable strand broken. Cable down
MARKIT Car pole P176 Jackson, lines down hazzardous,,PGE to set new pole.
MARKIT Drop lines down and hanging from wire
MARKIT Tree creating strain on asw guy strand and pulling on splice at terminal.
MARKIT Asw laying from poles, P500-522-572 Bell ln., mobile homes were removed.

MARKIT Lines down and temp secured but and unlashed needs strands raised and resecured
MARKIT Tree branches straining aerial cable. Need to remove branches to alleviate the strain on aerial cable.
MARKIT Tree down on cable sagging it to the ground.
RKIT Tree removers cut down many trees and now cable is laying on ground one pole/tree span. Need splice rebuilt as v
MARKIT Need flaggers and construction dept for replacing down rural wire crossing over Hwy49. Long span
Cable 1 - Cable on Ground. Accessible to Public
Cable 1 - Cable on Ground. Accessible to Public
MARKIT Need onan fixed, generator OOS, to rettach rural wire to tree, temp repaired.
MARKIT Tree fell ; 2 spans damaged 25 or cable mostly self support cable;
MARKIT Temp asw on ground, needs replacement,long span. 5302839673 @ 740 Bucklin rd.
MARKIT VEGETATION REMOVAL REQUIRED - 201 BEAR RIVER VIEW LN
MARKIT VEGETATION REMOVAL REQUIRED - SECRET TOWN RD
MARKIT VEGETATION REMOVAL REQUIRED - SECRET TOWN RD
MARKIT TREE TRIMMING REQUIRED - 33740 NARY RED RD
MARKIT REMOVE DROP - 41158 SKYLINE DR
MARKIT TREE TRIMMING REQUIRED - 10819 PINE HILL DR
MARKIT TREE TRIMMING REQUIRED - 127 RACE ST
MARKIT TREE TRIMMING REQUIRED - 10679 FOOTWALL DR
MARKIT TREE TRIMMING REQUIRED - 12465 OAK CIR
MARKIT TREE TRIMMING REQUIRED - 444 KATE HAYES ST

MARKIT TREE TRIMMING REQUIRED - 10371 CROOKED ARROW LN
MARKIT TREE TRIMMING REQUIRED - 10069 BANNER LAVA CAP RD
MARKIT VEGETATION REMOVAL REQUIRED - 10450 HARMONY RIDGE RD
MARKIT TREE TRIMMING REQUIRED - 11949 BANNER LAVA CAP RD
MARKIT TREE TRIMMING REQUIRED - 12351 N BLOOMFIELD RD
MARKIT TREE TRIMMING REQUIRED - 17114 YUBA-DONNER SCENIC BYWAY
MARKIT TREE TRIMMING REQUIRED - 12457 LOMA RICA DR
MARKIT TREE TRIMMING REQUIRED - 12725 IDAHO MARYLAND RD
MARKIT VEGETATION REMOVAL REQUIRED - 11780 E BROOKVIEW DR
MARKIT TREE TRIMMING REQUIRED - 11733 SLOW POKE LN
MARKIT TREE TRIMMING REQUIRED - 656 W BROAD ST
MARKIT TREE TRIMMING REQUIRED - 18180 ROUND MOUNTAIN RANCH RD
MARKIT TREE TRIMMING REQUIRED - 13874 GREENHORN RD
MARKIT TREE TRIMMING REQUIRED - 668 E BROAD ST
MARKIT VEGETATION REMOVAL REQUIRED - 17377 ROCK CREEK RD
MARKIT TREE TRIMMING REQUIRED - 11410 N BLOOMFIELD RD
MARKIT TREE TRIMMING REQUIRED - 10662 E BENNETT RD
MARKIT TREE TRIMMING REQUIRED - 116 ORCHARD ST
MARKIT TREE TRIMMING REQUIRED - 81 CEMENT HILL RD
MARKIT TREE TRIMMING REQUIRED - 10858 BARTLETT DR
MARKIT TREE TRIMMING REQUIRED - 10747 BARTLETT DR
MARKIT TREE TRIMMING REQUIRED - 75 CEMENT HILL RD
MARKIT TREE TRIMMING REQUIRED - 611 CHIEF KELLY DR
MARKIT TREE TRIMMING REQUIRED - 17162 YUBA-DONNER SCENIC BYWAY
MARKIT TREE TRIMMING REQUIRED - 17407 STATE HIGHWAY 49
MARKIT TREE TRIMMING REQUIRED - 15669 AMERICAN HILL RD
MARKIT TREE TRIMMING REQUIRED - 11372 N BLOOMFIELD RD
MARKIT TREE TRIMMING REQUIRED - 14720 COLFAX HWY
MARKIT TREE TRIMMING REQUIRED - 158 LUCAS LN
MARKIT TREE TRIMMING REQUIRED - 12904 BRUNSWICK RD
MARKIT TREE TRIMMING REQUIRED - 13281 GRASS VALLEY AVE
MARKIT TREE TRIMMING REQUIRED - 13120 LOMA RICA DR
MARKIT TREE TRIMMING REQUIRED - 12556 LOMA RICA DR
MARKIT TREE TRIMMING REQUIRED - 13010 LOMA RICA DR
MARKIT TREE TRIMMING REQUIRED - 15649 GREENHORN RD
MARKIT TREE TRIMMING REQUIRED - 15495 LAKE VERA PURDON RD
MARKIT TREE TRIMMING REQUIRED - 13943 GREENHORN RD
MARKIT TREE TRIMMING REQUIRED - 11177 LA BARR MEADOWS RD
MARKIT TREE TRIMMING REQUIRED - 10046 SMITH RD
MARKIT TREE TRIMMING REQUIRED - 12018 LOWER COLFAX RD
MARKIT TREE TRIMMING REQUIRED - 14027 CHRISTOPHER ROBIN WAY
MARKIT TREE TRIMMING REQUIRED - 12134 GAYLE LN
MARKIT TREE TRIMMING REQUIRED - 11510 COLFAX HWY
MARKIT TREE TRIMMING REQUIRED - 13017 BOREHAM LN

MARKIT TREE TRIMMING REQUIRED - 12942 BOREHAM LN
MARKIT TREE TRIMMING REQUIRED - 12718 SPRING RD
MARKIT INTRUSIVE INSPECTION REQUIRED - 13939 NIMBUS DAM RD
STALL DOWN GUY;TRANSFER AT&T CABLE(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 5 - 11949 B
MARKIT TRANSFER AT&T CABLE(S);PULL OLD POLE;LEAD TAILS NO;CABLE SWING NO;TRASFER 1 - 14161 BROOKS RD
MARKIT REMOVE DROP - 12718 SPRING RD
MARKIT TREE TRIMMING REQUIRED - 17047 WEEDS POINT RD
MARKIT VEGETATION REMOVAL REQUIRED - 15616 FAWN TRAIL
MARKIT TREE TRIMMING REQUIRED - 16554 CALVIN LN
MARKIT INTRUSIVE INSPECTION REQUIRED - 27621 YUBA-DONNER SCENIC BYWAY
MARKIT TREE TRIMMING REQUIRED - 10868 BARNES DR
MARKIT REMOVE DROP - 13134 DAVOS DR
MARKIT REMOVE DROP - 11442 ALDER DR
MARKIT REMOVE DROP - 13109 HILLSIDE DR
MARKIT REMOVE DROP - 10424 E ALDER CREEK RD
MARKIT RAISE AT&T SERVICE DROP - 11190 BARNES DR
MARKIT REMOVE DROP - 13329 HANSEL AVE
MARKIT REMOVE DROP - 13881 HANSEL AVE
MARKIT REMOVE DROP - 12345 BENNETT FLAT RD
MARKIT REMOVE DROP - 13110 DAVOS DR
MARKIT REMOVE DROP - 12025 BENNETT FLAT RD
MARKIT REMOVE DROP - 12824 HILLSIDE DR
MARKIT REMOVE DROP - 12715 PARKER RD
MARKIT REMOVE DROP - 12715 PARKER RD
MARKIT REMOVE DROP - 13387 HILLSIDE DR
MARKIT REMOVE DROP - 12932 FALCON POINT PL
MARKIT REMOVE DROP - 12898 FALCON POINT PL
MARKIT REMOVE DROP - 11709 LAUSANNE WAY
MARKIT REMOVE DROP - 11718 LAUSANNE WAY
MARKIT TREE TRIMMING REQUIRED - 14305 TYROL RD
MARKIT REMOVE DROP - 11582 OSLO DR
MARKIT REMOVE DROP - 105 NUGGET LN
MARKIT REMOVE DROP - 261 SILVER CREEK RD
MARKIT REMOVE DROP - 6473 BUCKS LAKE RD
MARKIT REMOVE DROP - 292 EAST ST
MARKIT REMOVE DROP - 60 MYERS ST
MARKIT REMOVE DROP - 208 5TH ST
MARKIT REMOVE DROP - 404 ALDER CT
MARKIT REMOVE DROP - 242 CATE ST
MARKIT REMOVE DROP - 16788 BUCKS LAKE RD
MARKIT REMOVE DROP - 75 JACKSON ST
MARKIT RAISE AT&T SERVICE DROP - 16625 NEW YORK HOUSE RD
MARKIT RAISE AT&T SERVICE DROP - 16556 FRENCHTOWN RD
MARKIT Abandoned asw hanging from pole,public accessible.

ıd mult locations Fiddle Creek/Brandy City rd. Pole 131-135, hazardous cond to all motorized/foot traffic. Danger to pw
MARKIT Lines need to be rerouted, they are attacheddead trees to be removed.
MARKIT 5308324603. Bsw trouble.needs isolation and repair. Laying on surface.
MARKIT Asw from home on church st laying and tangled side of road.
MARKIT P236 bucks lk rd- reattach asw afterpole transfer. P225 bucks lkrd- remove abandoned asw on fence.
MARKIT VEGETATION REMOVAL REQUIRED - SECRET TOWN RD
MARKIT VEGETATION REMOVAL REQUIRED - 201 BEAR RIVER VIEW LN
MARKIT TREE TRIMMING REQUIRED - 33740 NARY RED RD
MARKIT VEGETATION REMOVAL REQUIRED - SECRET TOWN RD
MARKIT Tree fell onto cable snapping pole in half. No copper damage.
MARKIT Broken pole
MARKIT Abandoned drop down
MARKIT Abandoned drop down
MARKIT Abandoned drop down
MARKIT Cpuc complaint of lines 5 ft from ground. Please resolve non-conformance
MARKIT Remove dead tree from cable
MARKIT Abandoned downed drop needs to be removed
MARKIT Remove 2 downed drops
MARKIT Remove 2 downed drop wires
MARKIT Remove downed drop
MARKIT Remove downed drop
MARKIT Remove downed drop
MARKIT Remove tree from cable
MARKIT Customer N. Robinson, 5308362411. C wire down in multiple locations crossing over OHV road.

Cable 1 - Cable on Ground. Accessible to Public
Service Drop 1 - service drop lines down crossing or parallel to public roadway

MARKIT INTRUSIVE INSPECTION REQUIRED - 11698 LA PORTE RD
Cable 1 - Hazardous - Clearance to Ground <8ft accessible to public

MARKIT VEGETATION REMOVAL REQUIRED - 16653 MOUNTAIN HOUSE RD
MARKIT RAISE AT&T SERVICE DROP - 20842 JOHN BORN RD
MARKIT PLACE CROSS/GUARD ARM - 16787 PATRICIA WAY
MARKIT PLACE CROSS/GUARD ARM - 15233 SIERRA STAR LN

MARKIT VEGETATION REMOVAL REQUIRED - 34609 TRAIL END CT
MARKIT VEGETATION REMOVAL REQUIRED - 31055 KNOB CONE RD
MARKIT TREE TRIMMING REQUIRED - 11118 BANNER LAVA CAP RD
MARKIT TREE TRIMMING REQUIRED - 17590 STATE HIGHWAY 49
MARKIT PLACE CROSS/GUARD ARM - 15766 VANDEVERE RD
MARKIT TREE TRIMMING REQUIRED - 10831 BARTLETT DR
MARKIT TREE TRIMMING REQUIRED - 18638 MCCOURTNEY RD
MARKIT TREE TRIMMING REQUIRED - 21073 STATE HIGHWAY 20
MARKIT TREE TRIMMING REQUIRED - 13316 DAVOS DR
Cable less then 12ft above Roadway 10.69 per PGE Lidar
Cable less then 12ft above Roadway 10.38 per PGE Lidar
Cable less then 12ft above Roadway 11.75 per PGE Lidar
Cable less then 12ft above Roadway 10.33 per PGE Lidar
MARKIT Line down pole 12140948
MARKIT Pole on ground
MARKIT Line down pole 16
MARKIT Line down nPt. Line in bushes
MARKIT Tree on wire
MARKIT Pole 47. Line on the ground
MARKIT Line on the ground
MARKIT Line on the ground. Pole 9B4
MARKIT Pole 217. Cable 1 - Cable on Ground. Accessible to Public
MARKIT Line on the ground. Pole 120823021
MARKIT Lashing on the ground
MARKIT REPAIR/REPLACE HARDWARE - 13342 SKIVIEW LOOP

DESIGN_NOTES	LATITUDE	LONGITUDE	HAZARD_LEVEL
			3
	39.203736	121.221367	2
	39.217331	121.098203	3
	39.175057	120.976039	2
Hazard corrected by 46L	39.157716	-121.039766	1
complete raised cable 8/28	39.255891	-121.059979	2b
	39.262264	-121.044899	2a
	39.261311	-121.051514	2a
	39.248268	-121.056519	2a
	39.763649	-120.624733	2a
	39.767056	-120.623093	2a
CATV in violation	39.74873	-120.615908	2a
	39.761337	-120.615936	2a
	39.764366	-120.588531	2a
	39.264053	-121.089874	2a
	39.764626	-120.625191	2a
	39.765347	-120.624138	2a
	39.7598	-120.608986	2a
	39.872005	-120.705833	2a
replace preform at anchor and reattach dg	39.248344	-121.028442	2b
	39.25959	-121.020859	2b
	39.764534	-120.624809	2b
	39.261269	-121.063957	2b
	39.759781	-120.604027	2b
	39.260147	-121.020058	2c
	39.767227	-120.623314	2c
	39.76495	-120.58802	2c
PG180393HM	39.260006	-121.015205	3
ak Way	39.261856	-121.073898	3
PG180381HM	39.243427	-121.037628	3
	39.257549	-121.023224	2
	39.248192	-121.028534	2
	39.260956	-121.093285	2
	39.872017	-120.704872	2
	39.759914	-120.613754	2
all work comp./ place guy guard	39.32856	-120.162567	2b
all work comp./ cleared catv drop	39.325855	-120.183495	2b
re-sag three directions, de lash and re lash 200'	39.317776	-120.163971	2b
all work comp./ raised attachment	39.323048	-120.166016	2b
re-lash 70' of cable	39.328426	-120.283684	2b
RAISED 2 ATTACHMENTS 3' ON POLE			
REPLACED 2 DOWN GUYS	39.316452	-120.278084	2b

remove broken down guy			
place down guy	39.319061	-120.255692	2b
rk comp./ replaced term. and removed dead drop	39.363819	-120.095169	3
all work comp./ place guy guard	39.314686	-120.148773	3
all work comp./ supported cable	39.314686	-120.148773	3
all work comp./ secure cable tail	39.326019	-120.203423	3
all work comp./ supported cable	39.336193	-120.154701	3
all work comp./ removed down guy	39.353146	-120.115738	3
all work comp./ placed guy guard	39.353146	-120.115738	3
all work comp./ placed guy guard	39.316074	-120.270721	3
all work comp.	39.317364	-120.288277	3
all work comp./ re-lash section	39.319126	-120.158287	3
all work comp./ replaced down guy	39.319126	-120.158287	3
all work comp./ placed guy guard	39.334667	-120.15564	3
all work complete/ re-tensioned lead	39.368568	-120.104042	3
all work comp./ re-lash span	39.36768	-120.10273	3
all work comp./ rem. cut drop wire	39.332794	-120.172119	3
all work comp./ replaced 2 down guys	39.373516	-120.090599	3
	39.315861	-120.289063	3
all work comp./ place guy guard	39.316208	-120.16938	3
all work comp./ replaced down guy	39.361156	-120.099533	3
all work comp./ place guy guard	39.223522	-120.204407	3
	39.31601	-120.190269	3
all work comp./ raise attachment	39.361446	-120.103439	3
all work comp./ place guy guard	39.316319	-120.153008	3
all work comp./ place guy guard	39.325035	-120.235527	3
all work comp.re-lash section	39.325035	-120.235527	3
all work comp./ placed guy guard	39.317776	-120.163971	3
no trouble found	39.317776	-120.163971	3
all work comp./ placed guy guard	39.319611	-120.294998	3
all work comp./ transfer attachment	39.322189	-120.221039	3
	39.316292	-120.15947	3
all work comp./ secured cable	39.363777	-120.096184	3
	39.336597	-120.146919	3
all work comp./ raise attachment	39.318741	-120.183342	3
	39.329643	-120.255402	3
all work comp./ supported cable	39.319611	-120.294998	3
all work comp.	39.360329	-120.104111	3
all work comp./ re-lash cable	39.32642	-120.174095	3
	39.328838	-120.251236	3
no trouble found	39.325558	-120.237526	3
all work comp./ placed guy guard	39.361645	-120.10257	3
all work comp./ placed guy guard	39.322392	-120.179405	3
all work comp./ place guy guard	39.3545	-120.10025	3

all work comp./ tension down guy	39.3638	-120.097229	3
all work comp./ replace down guy	39.329433	-120.253914	3
all work comp./ placed guy guard	39.328514	-120.161171	3
all work comp./ replaced term	39.316189	-120.194931	3
	39.36636	-120.100357	3
all work comp./ re-tension down guy	39.323647	-120.20623	3
all work comp./ re-tension down guy	39.362728	-120.096855	3
no trouble found	39.332958	-120.168579	3
all work comp./ place guy guard	39.352039	-120.103752	3
All work comp./ CATV U-Guard	39.321671	-120.171967	3
all work comp./ re-lash cable	39.351002	-120.101967	3
all work comp./ secured air pipe	39.326271	-120.173317	3
all work comp./ placed guy guard	39.253681	-120.21032	3
All work comp./ Placed guy guard	39.469204	-120.102997	3
All work comp./ Placed guy guard	39.468971	-120.099808	3
all work comp./ re-lash cable, tree trim	39.370476	-120.097191	3
all work comp./ re-lash 50'	39.325104	-120.277977	3
all work comp. / placed guy guard	39.359955	-120.097153	3
all work comp./ re-lash cable	39.319569	-120.293228	3
	39.328781	-120.250282	2
	39.330265	-120.248924	2
	39.354946	-120.099617	2
	39.359829	-120.099655	2
	39.329571	-120.249229	2
	39.317204	-120.286552	2
	39.317375	-120.185646	2
	39.327599	-120.24366	2
	39.316914	-120.288696	2
	39.354271	-120.093292	2
	39.317867	-120.297707	2
	39.335876	-120.159828	2
	39.376064	-120.099022	2
	39.365288	-120.1036	2
	39.324314	-120.202118	2
	39.319885	-120.292381	2
	39.361156	-120.099533	2
	39.31723	-120.269402	2
	39.360424	-120.101151	2
	39.359703	-120.101204	2
	39.316479	-120.270638	2
	39.317245	-120.287285	2
	39.327236	-120.269867	2
	39.326126	-120.186417	2
all work comp./ re sagged catv	39.360428	-120.098534	2

	39.316967	-120.186806	2
	39.317158	-120.268181	2
	39.316292	-120.15947	2
	39.320057	-120.175278	2
	39.318268	-120.289391	2
	39.315907	-120.290199	2
	39.31979	-120.18045	2
all work complete	39.356236	-120.091438	2
	39.364479	-120.103577	2
	39.362629	-120.095978	2
	39.328705	-120.249184	2
	39.328705	-120.249184	2
	39.316628	-120.276268	2
	39.316994	-120.291229	2
	39.336895	-120.158035	2
	39.322044	-120.213036	2
	39.32206	-120.214111	2
	39.316086	-120.284172	2
	39.322163	-120.218231	2
	39.319984	-120.294365	2
	39.362812	-120.090515	2
	39.252148	-120.210213	2
all work comp./ trim tree	39.335915	-120.157951	2
	39.335915	-120.157951	2
	39.31543	-120.196037	2
	39.31543	-120.196037	2
	39.31776	-120.262909	2
	39.325199	-120.185173	2
	39.322174	-120.216927	2
Not Att plant, Sudenlink notified	39.316628	-120.169579	2
	39.321339	-120.162849	2
	39.32505	-120.280815	2
	39.324596	-120.202217	2
	39.31926	-120.290588	2
	39.332958	-120.168579	2
	39.351414	-120.102882	2
	39.316116	-120.287781	2
	39.351002	-120.101967	2
	39.319126	-120.171097	2
	39.319126	-120.171097	2
	39.316669	-120.285179	2
all work comp./ tree trim	39.364647	-120.097267	2
	39.253681	-120.21032	2
	39.315964	-120.168816	2

	39.320114	-120.293602	2
	39.326565	-120.270035	2
omp./ tension 3 down guys- pole needs replacing	39.351109	-120.089851	2a
rem 10m down guy			
place insulated 10m down guy	39.329803	-120.246223	2b
de- lash and re-lash span, re-sag span	39.353935	-120.112679	2b
Raise attachment, and re-sag at dead end	39.33844	-120.051712	2b
removed broken un-insulated down guy			
placed new down guy	39.348648	-120.088539	2b
re-placed down guy			
changed bent hardware			
re-sagged low span	39.329208	-120.24321	2b
de-lash 200'			
re-lash 200'	39.325764	-120.189011	2b
PLACE NEW ANCHOR AND MOVE 2 DOWN GUYS	39.355778	-120.107674	2b
Raise attachment and re-sag Telco and CATV	39.353924	-120.091423	2b
Re -sag 2 cables at dead end pole	39.315762	-120.273392	2b
all work comp./ removed hardware	39.316433	-120.174469	3
all work comp./ re-tension down guy	39.353085	-120.109352	3
all work comp./ re-lashed cable	39.349453	-120.100357	3
all work comp./ place guy guard	39.363625	-120.094696	3
ll work comp./ tighten overhead guy and down gu	39.349373	-120.103363	3
all work comp./ placed guy guard	39.382915	-120.083122	3
all work comp./ cable has been undergrounded	39.323112	-120.227379	3
all work comp./ re-lashed	39.353935	-120.112679	3
all work comp./ placed down guy	39.335526	-120.08432	3
all work comp.	39.345169	-120.092438	3
	39.316025	-120.170807	3
all work comp./ replaced down guy	39.33762	-120.090599	3
all work comp./ placed guy guard	39.350159	-120.091568	3
all work comp./ raised cable	39.34864	-120.109459	3
all work comp./ replace down guy	39.34761	-120.110527	3
all work comp./ replaced down guy	39.353523	-120.094521	3
all work comp./ placed guy guard	39.355343	-120.099525	3
all work complete/ supported tail	39.359226	-120.108932	3
All work comp./ re-tension down guy	39.317802	-120.184448	3
all work comp./ raise cable	39.349537	-120.099518	3
all work comp./ tension 2 down guys	39.3713	-120.095879	3
all work comp./ replaced term.	39.345127	-120.111038	3
all work complete/ secured cable	39.326351	-120.179916	3
all work comp./ replaced down guy	39.334476	-120.079361	3
all work comp./ re-lashed span	39.332184	-120.177513	3
	39.316433	-120.174469	3
all work comp./ replaced term.	39.350838	-120.110497	3

all work comp./ replaced term.	39.345886	-120.10569	3
all work comp./ raised cable, placed guy guard	39.346214	-120.097549	3
all work comp./ replaced term	39.348057	-120.112221	3
all work comp./ replaced term.	39.350166	-120.112015	3
all work comp., replaced terminal	39.336132	-120.152168	3
all work complete/ place guy guard	39.312366	-120.174507	3
all work complete/ placed guy guard	39.351433	-120.091248	3
all work comp./ placed guy guard	39.34153	-120.074646	3
all work comp./ raised wire	39.340187	-120.079277	3
all work comp./ re-lash cable	39.357304	-120.090988	3
all work comp./ replaced terminal	39.346592	-120.109612	3
all work comp./ replaced terminal	39.350597	-120.108589	3
all work comp,/ replaced terminal	39.365402	-120.10392	3
all work comp./ replaced terminal	39.337875	-120.101456	3
all work comp./ replaced terminal	39.34536	-120.105179	3
al work comp./ replaced terminal	39.348156	-120.110672	3
	39.319412	-120.300087	2
	39.316612	-120.286842	2
	39.3507	-120.107773	2
CATV Issue	39.328587	-120.178658	2
	39.320484	-120.290932	2
	39.316952	-120.291862	2
	39.349617	-120.094994	2
	39.317993	-120.299454	2
	39.326515	-120.238853	2
	39.317932	-120.291878	2
	39.318295	-120.180046	2
	39.31583	-120.289635	2
	39.316284	-120.285988	2
	39.320293	-120.298531	2
	39.336102	-120.155281	2
	39.349453	-120.100357	2
	39.315823	-120.187279	2
	39.319065	-120.180145	2
	39.33762	-120.090599	2
	39.323132	-120.052002	2
	39.317268	-120.052063	2
	39.336437	-120.147415	2
	39.346912	-120.094528	2
	39.316284	-120.285988	2
	39.359947	-120.091087	2
	39.317753	-120.263512	2
	39.348293	-120.093025	2
	39.351429	-120.088219	2

	39.31881	-120.291679	2
	39.320869	-120.195816	2
	39.31657	-120.281769	2
2 spans re-lashed , drops removed	39.326843	-120.271072	2
	39.328907	-120.253441	2
	39.367455	-120.090996	2
	39.366516	-120.101585	2
	39.318401	-120.298073	2
	39.329094	-120.246284	2
	39.316566	-120.288849	2
	39.354786	-120.109802	2
	39.386192	-120.093193	2
	39.337036	-120.158936	2
	39.320705	-120.052246	2
	39.346375	-120.11293	2
	39.367195	-120.104362	2
	39.317406	-120.167236	2
	39.315838	-120.190941	2
	39.317219	-120.270119	2
	39.322853	-120.291618	2
ashed 1 span, cable low due to secondary being	39.317932	-120.291878	2
	39.317101	-120.289886	2
	39.316154	-120.182449	2
Hazard cleared by tech MM9751	39.938407	-120.938494	1
	39.25681	-120.729744	2b
mounted new f arm w/correct hardware	39.242203	-121.111773	2a
repaired prior to inspection	39.954301	-120.958043	2a
	39.903221	-120.752708	2a
	39.899195	-120.758756	2a
	39.316277	-120.610077	2a
	39.953864	-120.958326	2b
	39.932675	-120.84996	2b
	39.954737	-120.886037	2b
	39.908565	-120.743468	2b
	39.955074	-120.957165	2b
not telco	39.939511	-120.912316	2c
prior to inspection	39.939336	-120.91186	2c
prior to inspection	39.939676	-120.912703	2c
	39.94387	-120.926035	3
	39.942708	-120.922418	3
	39.353142	-120.654633	3
	39.943823	-120.913985	3
	40.068608	-121.177424	3
	39.94132	-120.917376	3

	39.940891	-120.865	3
	39.954532	-120.955027	3
	39.94387	-120.926035	3
	40.069887	-121.176001	3
	40.069138	-121.176442	3
Cleared by 46L	39.372997	-120.675484	1
	39.431496	-120.667358	1
	39.429501	-120.669556	1
	40.018894	-121.063837	2
	40.018838	-121.064102	2
ement	39.891945	-120.784777	1
rt severe angel and old stub pole needs removed	39.235828	-121.021056	2c
	39.220218	-121.05763	2a
	39.156431	-121.131941	2a
	39.100931	-121.145743	2a
cleared raised ok	39.240152	-121.11463	2a
cleared raised ok	39.112594	-121.146032	2a
cleared raised ok	39.110816	-121.143991	2a
replaced broken dg with insulated 10m	39.156086	-121.127516	2b
cable job replaced and wrecked delashed cable	39.109809	-121.150954	2b
	39.117463	-121.080522	2b
replace 6m dg with insulated dg.			
insulate other head guy	39.158053	-121.125081	2b
cleared raised ok	39.164354	-121.098455	2c
	39.219181	-121.065015	3
	39.224517	-121.084493	2
	39.164354	-121.098455	2
	39.13026	-121.174362	2
	39.130725	-121.17478	2
	39.231804	-121.059375	2
	39.231537	-121.071949	2
	39.237671	-121.092484	2
	39.11393	-121.082848	2
	39.207476	-121.077185	2
	39.164559	-120.970377	2
	39.163801	-120.963692	2
	39.158768	-120.963134	2
	39.240456	-121.035892	2
	39.223687	-121.064711	2
	39.222601	-121.064176	2
	39.232479	-121.076241	2
	39.252839	-121.127384	2
	39.219373	-121.065126	2
	39.205998	-121.083169	2a

cleared raised ok	39.120812	-121.071764	2b
	39.150813	-121.078047	2b
old pole removed, down guy attached to anchor	39.145431	-121.060858	2b
cleared raised ok	39.175623	-121.066284	2b
	39.200717	-121.067879	2b
	39.208792	-121.064659	2b
work complete upon arrival	39.114826	-121.063373	2b
placed insulated side guy	39.131184	-121.070093	2b
	39.146767	-121.060663	2b
cleared raised ok	39.133704	-121.072579	2b
	39.166016	-121.064138	2c
	39.134921	-121.058256	2
	39.171974	-121.076839	2
	39.156034	-121.072349	2
	39.186807	-121.065438	2
	39.198631	-121.066504	2
	39.139825	-121.066201	2
	39.119021	-121.067491	2
17338 Grace Ct	39.107903	-121.055838	2
Complete by Auburn Linecrew. No project	39.198958	-121.066549	1
completed work with job# A01X7P6	39.439818	-121.272905	2a
	39.147919	-120.953758	2a
placed/ raised lower DG and or guard arm	39.55912	-120.824875	2a
	39.562587	-121.111957	2b
	39.558842	-121.120582	2b
reattach dg to anchor	39.210117	-120.942108	2b
clearance issue complete	39.462456	-120.851418	2b
	39.53134	-121.156625	2b
placed/ raised lower DG and or guard arm	39.563961	-120.823975	2b
	39.478173	-121.260145	2b
	39.194626	-120.963959	2b
	39.438927	-121.271945	2b
relashed spans, complete	39.570518	-120.739525	2b
	39.435268	-121.268165	2b
	39.532668	-121.159328	2b
	39.4224	-121.258855	2b
	39.476902	-121.262213	2b
	39.582923	-121.091895	2b
	39.47745	-121.261545	2b
	39.511373	-121.274715	2b
	39.582923	-121.091895	2b
	39.418472	-121.258882	2b
	39.486173	-121.223872	2b
	39.477394	-121.261513	2b

	39.146275	-120.973015	2b
All work complete.	39.205833	-120.961533	2b
	39.462347	-121.282828	2b
replaced DG	39.457825	-121.044884	2b
	39.480952	-121.236208	2b
	39.495567	-121.282207	2b
	39.541347	-121.16806	2b
	39.483313	-121.242358	2b
place guard on dg with queens post	39.146141	-120.973557	2b
	39.435793	-121.268773	2b
	39.46424	-121.28055	2b
clearance resolved, 7/16/2020	39.471237	-120.843796	2c
placed/ raised lower DG and or guard arm	39.563591	-120.824699	2c
corrected clearance issue 7/13/2020	39.481674	-120.8535	2c
placed/ raised lower DG and or guard arm	39.539883	-120.885165	2c
completed clearance issue	39.479946	-120.85257	2c
	39.472721	-120.842743	3
	39.455388	-121.288153	3
	39.476677	-121.250675	3
	39.478168	-121.258808	3
	39.46424	-121.28055	3
	39.471684	-120.843307	3
	39.453098	-121.256152	3
	39.559143	-120.827492	3
	39.472542	-120.842491	3
	39.430763	-121.255963	3
	39.471237	-120.843796	3
	39.473118	-120.843132	3
	39.564062	-120.880485	3
	39.481262	-120.847153	3
	39.470638	-120.843834	3
	39.480492	-121.234495	3
	39.469456	-120.843468	3
Work complete by 46L. Hazard cleared.	39.215698	-120.970413	1
Hazard Cleared by 46L	39.476833	-120.844276	1
	39.174515	-120.956528	2
	39.46861	-121.277602	2
	39.557514	-120.88295	2
	39.520775	-121.260122	2
	39.515052	-121.2649	2
	39.541582	-121.166513	2
	39.526212	-121.245178	2
	39.15675	-120.98114	2
	39.713752	-120.97756	2

	39.519048	-121.247927	2
	39.197762	-120.969986	2
	39.565844	-120.878525	2
	39.147919	-120.953758	2
	39.488033	-120.856789	2
	39.55912	-120.824875	2
	39.47474	-121.270162	2
	39.454746	-120.862259	2
	39.570087	-120.877136	2
	39.454753	-121.2907	2
	39.568562	-120.877106	2
	39.149853	-120.957863	2
	39.340421	-121.04775	2a
	39.335988	-121.095037	2a
	39.327825	-121.14442	2a
clearance issue resolved	39.326273	-121.146489	2b
	39.368803	-121.098445	2b
	39.359709	-121.098941	2b
	39.306855	-121.163437	2
	39.324881	-121.148161	2
	39.773326	-120.572552	2
	39.265522	-120.909111	2a
	39.284012	-120.923859	2a
	39.262672	-121.044449	2a
	39.357883	-120.780746	2a
	39.272186	-120.996811	2a
	39.237911	-120.973099	2a
	39.192101	-121.012291	2a
	39.184361	-120.985199	2a
all work complete.	39.307354	-120.913826	2b
	39.307354	-120.913826	2b
	39.252377	-121.00663	2b
	39.36043	-120.760931	2b
	39.28981	-120.973572	2b
	39.249378	-121.006241	2b
	39.307804	-120.913628	2b
	39.308098	-120.912827	2b
	39.322983	-120.868546	2b
	39.252296	-120.931015	2b
	39.25705	-120.968651	2b
	39.257317	-120.967758	2b
	39.251045	-120.935447	2b
	39.251034	-120.934761	2b
REPAIRED BROKEN LASHING WIRE.	39.188404	-121.048233	2b

	39.297657	-120.92485	2b
	39.322636	-120.8666	2b
	39.261261	-121.001854	2b
	39.252853	-121.000504	2b
	39.282719	-120.968819	2b
	39.307777	-120.913223	2b
	39.294407	-120.985153	2b
	39.308353	-120.973419	2b
	39.24094	-121.001129	2b
REPLACED CROSS ARM AND RAISED CABLE	39.240986	-121.030322	2b
	39.242733	-120.914024	2b
	39.309422	-120.973907	2c
raised lower cable and guard arm placed	39.271172	-121.010406	2c
PG&E via 3rd party ticketing system. 3rd Party tic	39.25967	-120.95414	2c
	39.237911	-120.973099	2c
	39.198437	-121.00946	2c
	39.321896	-120.884062	3
	39.211094	-121.060257	3
	39.238129	-121.023453	3
	39.214317	-121.046837	3
	39.238935	-121.015868	3
	39.301311	-120.919434	1
Work complete by 46L. Hazard cleared.	39.211639	-121.060173	1
	39.303279	-120.942995	2
	39.316959	-121.023308	2
	39.271172	-121.010406	2
	39.247516	-120.956329	2
	39.170444	-121.044853	2
	39.172375	-121.044861	2
	39.204086	-121.061462	2
	39.355141	-120.804108	2
	39.322994	-120.853526	2
	39.310539	-120.973877	2
	39.18861	-121.031242	2
	39.190502	-121.007195	2
	39.238636	-121.014885	2
	39.167564	-120.986122	2
ıck towards splice that was being pulled. Re-sagg	39.344162	-120.271126	2b
re-attached down guy	39.355566	-120.223272	2b
de-lash 150'			
re-lash 150'	39.353699	-120.255714	2b
	39.352795	-120.22908	3
	39.353878	-120.180443	3
	39.359314	-120.167244	3

	39.359467	-120.172867	3
Northwoods Blvd	39.34304	-120.221748	3
	39.339859	-120.214455	2
	39.36602	-120.241684	2
	39.37117	-120.244621	2
	39.368818	-120.180745	2
	39.339218	-120.229187	2
	39.340042	-120.236046	2
	39.348206	-120.253464	2
	39.368462	-120.180771	2
	39.361401	-120.165596	2
	39.352795	-120.241615	2
	39.355659	-120.220459	2
	39.358307	-120.230011	2
	39.355358	-120.238716	2
	39.34024	-120.253143	2
	39.355087	-120.247581	2
	39.357456	-120.227913	2
	39.37162	-120.247078	2
	39.351116	-120.182213	2
	39.355816	-120.219727	2
	39.339424	-120.216042	2
	39.342415	-120.235558	2
	39.365376	-120.172012	2
	39.328293	-120.236214	2
	39.326576	-120.224998	2
	39.35582	-120.227158	2
	39.339638	-120.212334	2
	39.33959	-120.199204	2
	39.385544	-121.001343	2
	39.318836	-120.637367	2a
	39.31522	-120.657639	2a
	39.318016	-120.630844	2a
	39.341011	-120.649773	2a
raised lower, guard atm	39.302219	-120.65818	2a
	39.209785	-120.803169	2a
cleared raised ok	39.243362	-120.753212	2a
cleared raised ok	39.294212	-120.675934	2a
cleared raised ok	39.318111	-120.63781	2a
cleared raised ok	39.317768	-120.638191	2a
raised lower cable	39.213161	-120.794403	2b
5/20/21 Sent to SVA Contractor for GO95.			
A01YNW1 TO REPLACE POLE	39.276588	-120.705673	2c
	39.247566	-120.735893	3

VERIFIED THAT POLE HAS BEEN REPLACED ON 1	39.281254	-120.705391	1
	39.317822	-120.638596	2
	39.208405	-120.793945	2
	39.318836	-120.637367	2
	39.318523	-120.637596	2
	39.317375	-120.632172	2
	39.209606	-120.802849	2
	39.180805	-120.855576	2
	39.944572	-121.062691	2
	39.930733	-120.894119	2
	39.934925	-120.933556	2
	39.934595	-120.933513	2
	39.936237	-120.915787	2
	39.931236	-120.896454	2
	39.87022	-121.172249	2
	39.937065	-120.91597	2
	39.774622	-120.585523	1
power secondary is loose and in Telco space	39.344166	-120.265839	2a
	39.394005	-120.021584	2
	39.393677	-120.021073	2
	39.175031	-120.997164	2
	39.934326	-120.889526	1
	39.818905	-120.378753	1
	39.934139	-120.899371	1
	39.934137	-120.89968	1
	39.522039	-121.017804	1
	39.361261	-120.791701	1
	39.284892	-120.964887	1
	39.877731	-121.187825	1
	39.958433	-120.890828	1
eeds repairs in section.	39.688495	-120.618876	1
	39.146963	-121.057647	2b
	39.803711	-120.178325	1
	39.78543	-120.483403	1
	39.614974	-120.425478	1
	39.819416	-120.381084	1
	39.813046	-120.319402	1
afety issue.	39.798285	-120.139428	1
	39.651906	-120.222041	1
	39.789993	-120.650083	1
	39.819107	-120.379953	1
	39.641703	-120.210125	1
	39.787566	-120.082327	1
	39.938697	-120.959168	1

	39.851209	-120.683264	1
	39.823933	-120.409654	1
	39.936616	-120.861809	1
	39.951456	-120.960553	1
	39.87834	-120.47186	1
	39.751944	-120.066266	1
	39.818726	-120.379104	1
	39.818582	-120.378413	1
	39.751113	-120.069249	1
	39.903236	-120.752895	1
	39.946396	-120.90866	1
	39.82613	-120.417086	1
	40.024215	-121.11236	1
	39.13803	-120.919941	2b
5/20/21 Sent to SVA Contractor.	39.214541	-120.778277	2b
	39.213467	-120.793927	2b
	39.139	-120.919899	2b
	39.146137	-120.904419	2b
	39.390301	-121.09626	2b
	39.399189	-121.098763	2b
	39.44009	-121.068962	2b
	39.454708	-121.043625	2b
	39.456711	-121.04007	2b
	39.440849	-121.07225	2b
	39.399971	-121.099754	2b
	39.460846	-121.046768	2b
	39.400478	-121.103996	2b
	39.393623	-121.09744	2b
	39.503525	-121.273573	2b
	39.49696	-121.281143	2b
	39.496733	-121.278657	2b
5/27/21 Sent GO95 to Contract. RP2967.			
7/19/21 Notified of completion by SVA. RP2967.	39.519225	-120.99163	2b
6/28/21 Notified of completion by SVA. RP2967.			
5/20/21 Sent to SVA Contractor.	39.193238	-120.823998	2b
7/12/21 Notified of completion by SVA. RP2967.			
5/20/21 Sent to SVA Contractor. RP2967.	39.194565	-120.827763	2b
5/20/21 Sent to SVA Contractor. RP2967.			
6/22/21 Notified of completion by SVA. RP2967.	39.214004	-120.779127	2b

5/20/21 Sent to SVA Contractor. RP2967.			
6/22/21 Notified of completion by SVA.			
RP2967.	39.315291	-120.659713	2b
	39.213625	-120.793938	2b
	39.21484	-120.796516	2b
	39.422485	-120.999413	2b
7/6/21 Notified of completion by SVA. RP2967.			
5/20/21 Sent to SVA Contractor for GO95.			
RP2967.	39.191287	-120.971143	2b
	39.217058	-120.9685	2b
	39.234737	-121.018861	2b
	39.216377	-121.05275	2b
	39.486271	-121.041115	2b
	39.461281	-121.03672	2b
	39.452301	-121.047279	2b
	39.45892	-121.033882	2b
	39.202793	-121.061546	2b
	39.46485	-120.84764	2b
	39.481268	-120.847175	2b
	39.218372	-121.012579	2b
	39.150604	-121.040878	2b
/20/21 Sent to SVA Contractor for GO95. RP2967	39.17728	-121.001335	2b
	39.172722	-121.047379	2b
	39.208953	-120.806197	2
	39.172211	-120.856552	2
	39.146025	-120.899171	2
	39.464809	-121.081146	2
	39.193238	-120.823998	2
	39.198613	-120.83421	2
	39.205622	-120.840917	2
	39.209624	-120.810131	2
	39.182801	-120.857303	2
	39.310341	-120.664595	2
	39.52263	-121.181647	2
	39.19518	-120.811602	2
	39.2573	-120.708845	2
	39.454821	-121.290699	2
	39.449448	-121.283795	2
	39.448218	-121.283157	2
	39.186226	-121.053436	2
	39.151272	-121.041939	2
	39.234962	-121.016633	2
	39.208633	-121.059334	2

	39.204217	-120.838617	2
	39.209797	-121.058601	2
	39.241371	-121.021627	2
	39.157795	-121.031479	2
	39.187191	-121.057526	2
	39.24211	-120.986532	2
	39.171982	-121.048485	2
	39.196407	-121.053406	2
	39.466225	-120.845723	2
	39.469672	-120.843448	2
	39.171455	-121.049263	2
	39.206394	-121.00499	2
	39.140759	-121.032387	2
	39.153187	-121.02813	2
	39.139954	-121.039658	2
	39.15406	-121.039162	2
	39.239124	-120.993273	2
	39.215752	-120.998955	2
	39.161255	-121.020943	2
	39.190033	-121.054581	2
	39.148529	-121.030861	2
	39.17091	-121.050011	2
6/28/21 Notified of completion by SVA. RP2967.			
5/20/21 Sent to SVA Contractor for GO95. RP2967.	39.166615	-120.987801	2b
	39.2066	-121.039223	2b
	39.190098	-120.993401	2
	39.159306	-121.003075	2
	39.204075	-121.020096	2
	39.205048	-121.019279	2
	39.166615	-120.987801	2
	39.233817	-121.01897	2
	39.171013	-121.053688	2
	39.169598	-120.966122	2
	39.235724	-120.992757	2
	39.203396	-121.020149	2
	39.326626	-120.214439	2b
	39.564649	-120.639067	2b
	39.563429	-120.643762	2b
	39.563255	-120.643166	2b
	39.563419	-120.641403	2b
	39.563545	-120.640747	2b
	39.569363	-120.62056	2b

39.32653	-120.203271	2b
39.56845	-120.619288	2b
39.326596	-120.223954	2
39.361278	-120.251985	2
39.338451	-120.240902	2
39.362479	-120.250788	2
39.347592	-120.199377	2
39.345309	-120.247296	2
39.340165	-120.227784	2
39.339556	-120.198986	2
39.350129	-120.250332	2
39.355779	-120.223734	2
39.342584	-120.235771	2
39.330122	-120.215562	2
39.366223	-120.16657	2
39.367146	-120.17346	2
39.367498	-120.170913	2
39.34478	-120.239986	2
39.353513	-120.234404	2
39.352432	-120.241635	2
39.340368	-120.253281	2
39.345315	-120.217512	2
39.340112	-120.25575	2
39.328877	-120.23634	2
39.343531	-120.218774	2
39.362976	-120.250752	2
39.355707	-120.255402	2
39.355273	-120.238706	2
39.341242	-120.224247	2
39.366076	-120.241768	2
39.340433	-120.249688	2
39.345179	-120.251649	2
39.347426	-120.229371	2
39.339678	-120.220607	2
39.371833	-120.247179	2
39.346861	-120.186322	2
39.36786	-120.175624	2
39.366308	-120.16637	2
39.368945	-120.180648	2
39.349111	-120.180664	2
39.35985	-120.170925	2
39.367038	-120.179782	2
39.349681	-120.214815	2
39.344574	-120.240549	2

39.357582	-120.228048	2
39.34931	-120.202431	2
39.345916	-120.204094	2
39.344322	-120.240998	2
39.339839	-120.215168	2
39.349708	-120.217724	2
39.351446	-120.226761	2
39.372419	-120.250174	2
39.339922	-120.224833	2
39.339214	-120.229126	2
39.329136	-120.235	2
39.34986	-120.248578	2
39.356679	-120.218674	2
39.345309	-120.243575	2
39.344653	-120.204569	2
39.357956	-120.242268	2
39.337374	-120.22627	2
39.338979	-120.226269	2
39.371298	-120.244657	2
39.337318	-120.241118	2
39.369895	-120.252595	2
39.341619	-120.221396	2
39.357603	-120.241213	2
39.357059	-120.226049	2
39.355307	-120.247545	2
39.340344	-120.252322	2
39.343715	-120.200252	2
39.349462	-120.255174	2
39.34867	-120.214015	2
39.3437	-120.223239	2
39.328532	-120.236586	2
39.340241	-120.245874	2
39.341479	-120.223476	2
39.328784	-120.239243	2
39.355868	-120.227229	2
39.326529	-120.227535	2
39.355683	-120.220081	2
39.345207	-120.201797	2
39.356405	-120.210965	2
39.343609	-120.202742	2
39.326621	-120.225298	2
39.347083	-120.25376	2
39.337873	-120.230478	2
39.347667	-120.209782	2

	39.356262	-120.256658	2
	39.351925	-120.250628	2
	39.361357	-120.243285	2
5/25/21 Sent GO95 to Contract. RP2967. 7/12/21 Notified of completion by SVA. RP2967.	39.359795	-120.764168	2b
7/6/21 Notified of completion by SVA. NOTE: Resagged cable but an innerset pole will need to be placed for ground clearance. I have forwarded this to the Const Mgr for this area. rp2967.			
5/24/21 Sent GO95 to Contract. RP2967.	39.201318	-121.198405	2b
	39.257397	-120.962364	2b
	39.263828	-121.028412	2b
	39.265709	-121.022453	2b
	39.263676	-121.025223	2b
	39.263802	-121.028954	2b
	39.275372	-121.022003	2b
6/28/21 Notified of completion by SVA. RP2967.			
5/25/21 Sent GO95 to Contract. RP2967.	39.270706	-120.996857	2b
5/25/21 Sent GO95 to Contract. RP2967. 7/19/21 Notified of completion by SVA. RP2967.	39.294735	-120.984795	2b
	39.276981	-121.082657	2b
	39.275394	-121.02224	2b
	39.275478	-121.02243	2b
	39.257618	-120.960251	2b
	39.273582	-121.077309	2b
	39.265507	-121.020233	2b
5/25/21 Sent GO95 to Contract. RP2967. 7/19/21 Per SVA, Observed many infractions along this cable lead (tree attachments with trees down), corrected specified location.	39.299019	-120.921883	2b
	39.260311	-120.945915	2b
	39.230653	-121.154483	2b
	39.218137	-121.192595	2b
	39.286224	-120.950737	2b
	39.240555	-121.19406	2b
7/6/21 Notified of completion by SVA. RP2967. 5/25/21 Sent GO95 to Contract. RP2967.	39.265919	-121.020782	2b

	39.286884	-121.077293	2b
7/6/21 Notified of completion by SVA. RP2967.			
5/24/21 Sent GO95 to Contract. RP2967.	39.200802	-121.193493	2b
	39.200368	-121.18717	2b
	39.243353	-121.216468	2b
7/6/21 Notified of completion by SVA. RP2967.			
5/25/21 Sent GO95 to Contract. RP2967.	39.310242	-120.910126	2b
	39.325855	-120.880843	2
	39.193885	-121.184393	2
	39.266243	-121.008247	2
	39.282887	-121.090965	2
	39.273643	-121.075363	2
	39.261761	-121.044128	2
	39.197728	-121.203873	2
	39.262489	-121.001862	2
	39.236244	-120.979385	2
	39.259754	-120.978294	2
	39.268513	-121.055946	2
	39.2345	-121.160027	2
	39.30928	-121.006943	2
	39.250034	-120.998825	2
	39.260311	-120.945915	2
	39.261467	-120.974686	2
	39.195687	-121.18994	2
	39.271887	-121.21713	2
	39.252363	-121.183372	2
	39.237759	-120.973984	2
	39.270466	-121.056023	2
	39.236902	-121.15703	2
	39.251888	-121.007843	2
	39.158202	-121.208565	2
5/24/21 Sent GO95 to Contract. RP2967.	39.341942	-121.129616	2a
7/6/21 Notified of completion by SVA. RP2967.			
5/25/21 Sent GO95 to Contract. RP2967.	39.35854	-120.775818	2a
	39.324947	-121.147896	2b
	39.32486	-121.14817	2b
	39.364208	-121.1175	2b
	39.344891	-121.120346	2b
	39.333874	-121.13942	2b
	39.321529	-121.151405	2b
	39.366325	-121.097725	2b

7/6/21 Notified of completion by SVA. RP2967.			
5/25/21 Sent GO95 to Contract. RP2967.	39.287403	-120.943352	2b
	39.358154	-120.779671	2b
	39.257481	-120.964706	2b
	39.257591	-120.96138	2b
	39.314644	-120.899506	2b
	39.816269	-120.464073	2b
	39.813164	-120.496376	2b
	39.816376	-120.459625	2b
	39.813568	-120.475044	2b
	39.806358	-120.46785	2b
	39.817257	-120.46756	2b
	39.790584	-120.492073	2b
	39.80772	-120.498993	2b
	39.813107	-120.501007	2b
	39.814472	-120.474327	2b
	39.802242	-120.468155	2b
	39.811867	-120.466797	2b
	39.818394	-120.458725	2b
	39.820255	-120.45536	2b
	39.269127	-121.007339	2b
	39.270443	-121.010612	2b
	39.281368	-120.989204	2b
	39.325012	-121.145203	2b
	39.357944	-121.123192	2b
	39.367245	-121.098511	2b
	39.338367	-121.086578	2b
	39.353546	-121.122795	2b
	39.354458	-121.122345	2b
5/24/21 Sent GO95 to Contract. RP2967. 7/12/21 Notified of completion by SVA. RP2967.	39.338631	-121.117188	2b
5/24/21 Sent GO95 to Contract. RP2967. 7/12/21 Notified of completion by SVA. RP2967.	39.343079	-121.126099	2b
08-27-21 hl1436 -- Referred to PG&E via 3rd party ticketing system. 3rd Party ticket package number is 897924.			
5/6/21 FIELDED BY SM5367, JOINT POLE REFERRED TO GH304F	39.369316	-121.067513	2c
	39.9217	-120.879024	1
	39.92895	-120.908642	2

	39.336483	-121.093361	2
	39.335888	-121.10157	2
	39.246735	-120.962753	2
	39.278839	-121.027496	2
	39.312592	-120.906754	2
	39.812572	-120.470482	2
	39.803951	-120.467247	2
	39.298817	-121.017471	2
	39.315922	-120.888474	2
	39.932007	-120.902788	2
	39.359787	-121.055756	2
	39.30323	-120.94268	2
	39.280582	-120.995956	2
	39.93996	-120.950637	1
	39.673999	-120.269908	1
ess 1975 west end rd,bucks lake,Quincy ca,	39.93771	-120.904346	1
25-2021.	39.933073	-120.904487	1
	39.931427	-120.904487	1
hazzard.	39.933664	-121.315876	1
	39.639383	-120.212239	1
	39.471879	-121.273988	2
	39.327739	-120.215543	2
	39.788988	-120.654851	1
	39.906699	-120.745158	1
	39.9343	-120.896673	1
	39.213495	-121.097737	1
	39.320175	-120.886851	1
	39.246231	-121.222061	1
	39.264256	-120.999817	1
	39.26403	-120.963442	1
	39.263332	-120.911991	1
lous Pole Lean with Immediate Risk cleared per F	39.230845	-120.760665	1
	39.842281	-120.216131	1
	39.838229	-120.21408	1
	39.308003	-120.655858	1
	39.730168	-120.659063	2b
	39.732197	-120.658732	2b
	39.735963	-120.656647	2b
	39.7371	-120.654877	2b
	39.740067	-120.652475	2b
	39.755306	-120.610649	2
	39.735525	-120.557562	2
	39.733735	-120.557023	2
	39.779192	-120.614595	2

39.777925	-120.612919	2
39.743485	-120.58155	2
39.759129	-120.612948	2
39.757512	-120.612221	2
39.759949	-120.608849	2
39.75966	-120.617739	2
39.756062	-120.606375	2
39.757851	-120.603981	2
39.760677	-120.60892	2
39.756435	-120.6092	2
39.87244	-120.704262	2
39.877449	-120.726334	2
39.767651	-120.62307	2
39.870682	-120.708054	2
39.762363	-120.694572	2
39.866211	-120.69886	2
39.766811	-120.621521	2
39.767273	-120.619614	2
39.868725	-120.697998	2
39.453579	-121.252655	2b
39.481518	-121.241783	2b
39.558971	-121.119438	2b
39.367645	-121.109428	2a
39.369137	-121.039429	2a
39.346291	-121.121223	2b
39.351983	-121.121843	2b
39.349863	-121.12286	3
39.356209	-121.123749	3
39.343925	-121.124741	2
39.344402	-121.123169	2
39.367298	-121.112197	2
39.36422	-121.092545	2
39.343464	-121.120773	2
39.356363	-121.12349	2
39.370182	-121.109697	2
39.357235	-121.123477	2
39.369582	-121.105258	2
39.364173	-121.092065	2
39.362885	-121.084242	2
39.361563	-121.07801	2
39.359562	-121.055908	2
39.366608	-121.07653	2
39.363651	-121.070549	2
39.362993	-121.037638	2

39.369447	-121.106728	2
39.383302	-121.091862	2b
39.242411	-120.925285	2
39.282043	-120.988274	2b
39.294563	-120.930189	2b
39.295416	-120.928788	2b
39.29705	-120.925707	2b
39.267304	-120.9017	2c
39.265213	-120.902267	2b
39.267087	-120.90852	2
39.250667	-120.936745	2
39.257503	-120.967865	2b
39.771139	-120.620247	1
39.262319	-121.01454	2
39.25964	-120.954068	2c
39.307476	-120.913776	2b
39.26049	-120.997566	2b
39.267738	-121.017204	2
39.387646	-120.996338	2
39.26841	-121.011147	2
39.256798	-120.969009	2
39.264935	-120.913063	2b
39.262344	-120.905823	2b
39.257328	-120.96254	2b
39.250919	-120.931854	2
39.255684	-120.930855	2
39.252113	-120.934143	2
39.263584	-120.913383	2b
39.264446	-120.919518	2c
39.273527	-121.022147	2
39.308956	-121.03035	2
39.25177	-121.0269	2
39.255501	-120.94857	2
39.255047	-120.954353	2
39.254883	-120.954018	2
39.2575	-120.957184	2
39.273544	-121.075493	2
39.283402	-120.944057	2
39.283066	-120.945451	2
39.25481	-121.015144	2
39.354	-120.804893	2b
39.352788	-120.806335	2b
39.321613	-120.850042	2b
39.353615	-120.805643	2b

39.356668	-120.803268	2
39.26524	-120.905708	2
39.262192	-120.992584	2
39.262287	-120.994652	2
39.262287	-120.994652	2b
39.274704	-121.022667	2
39.301251	-120.972385	2c
39.301545	-120.973987	2c
39.266064	-120.900955	2b
39.260605	-120.914795	2
39.259876	-120.913986	2
39.275169	-121.018181	2
39.268623	-120.899597	2b
39.268013	-120.900391	2c
39.358677	-120.775164	2c
39.266697	-120.904251	2b
39.268826	-120.904327	2b
39.261684	-120.905624	2c
39.266647	-120.905037	2
39.266647	-120.905037	2
39.231163	-120.978615	2
39.290371	-121.005898	2a
39.289652	-121.000223	2
39.265491	-120.935898	2
39.291595	-121.006546	2
39.260548	-120.997749	2b
39.306775	-120.98298	2
39.279713	-121.013046	2
39.777435	-120.633093	1
39.265972	-120.989716	2
39.261654	-120.989586	2
39.307135	-121.007993	2
39.309715	-121.004463	2
39.306648	-121.007373	2
39.249836	-121.014404	2
39.255501	-120.930878	2
39.247398	-121.187752	2
39.238049	-121.197701	2
39.190338	-121.171707	2b
39.158157	-121.208534	2
39.180002	-121.193859	2b
39.817026	-120.466669	1
39.187143	-121.196954	2b
39.243931	-121.214012	2

	39.190353	-121.182419	2b
	39.198458	-121.181025	2
	39.195689	-121.177904	2b
	39.239798	-121.190201	2
	39.240578	-121.191998	2
	39.325409	-120.16272	2b
	39.31662	-120.200775	2
	39.315796	-120.171959	2
	39.400405	-120.183547	2
	39.335754	-120.150467	2
	39.326635	-120.214985	2
	39.326557	-120.227905	2
	39.350991	-120.203381	2
	39.343461	-120.204938	2
	39.343511	-120.218756	2
	39.329419	-120.236461	2
	39.327029	-120.235124	2
	39.326317	-120.216577	2
	39.324843	-120.20663	2
	39.324197	-120.199827	2
	39.346517	-120.179878	2
	39.317882	-120.052498	2
	39.326465	-120.215945	2
	39.325336	-120.184792	2
	39.325546	-120.161766	2
	39.326618	-120.160835	2
	39.325272	-120.163429	2
	39.32516	-120.163952	2
	39.400405	-120.183547	2
	39.358719	-120.108703	2
	39.358464	-120.108219	2
	39.350991	-120.09933	2
	39.347299	-120.106293	2
	39.318835	-120.053347	2
	39.327898	-120.057058	2
	39.331448	-120.0614	2
	39.333422	-120.0598	2
Attachments are properly spaced	39.328564	-120.160759	2a
Guard arm placed, Down guy insulated	39.334553	-120.156052	2a
	39.327221	-120.160378	2a
	39.349705	-120.214806	2
	39.328115	-120.051722	2
	39.32318	-120.052295	2
	39.320992	-120.052272	2

39.32283	-120.044397	2
39.414056	-120.174648	2
39.416262	-120.176523	2
39.347555	-120.22177	2
39.343572	-120.06328	2
39.343642	-120.0643	2
39.335948	-120.05938	2
39.354244	-120.24398	2
39.353329	-120.243309	2
39.35191	-120.244637	2b
39.468999	-120.10304	2
39.469083	-120.101719	2
39.320363	-120.291502	2
39.356297	-120.224403	2
39.355751	-120.223671	2
39.357088	-120.226059	2
39.357598	-120.228108	2
39.358128	-120.229897	2
39.341724	-120.231194	2
39.343781	-120.233543	2
39.339516	-120.216049	2
39.339809	-120.215187	2
39.366524	-120.240021	2
39.365833	-120.241974	2
39.317165	-120.286705	2b
39.317348	-120.287277	2
39.342083	-120.226418	2
39.339802	-120.213341	2
39.340965	-120.219635	2
39.347279	-120.229233	2
39.358154	-120.2575	2
39.342522	-120.238762	2
39.341499	-120.234802	2
39.342332	-120.239152	2
39.345036	-120.229134	2
39.345745	-120.21933	2
39.345222	-120.217636	2
39.346741	-120.235123	2b
39.367481	-120.248756	2
39.371571	-120.252777	2
39.369877	-120.252556	2
39.35788	-120.242287	2b
39.395327	-120.19268	2
39.394038	-120.191552	2

39.394038	-120.191552	2a
39.349958	-120.214609	2
39.353523	-120.211403	2
39.362904	-120.250694	2
39.362522	-120.250824	2
39.356415	-120.210985	2
39.342831	-120.237068	2
39.346946	-120.246088	2
39.345089	-120.247383	2
39.345238	-120.243591	2
39.348133	-120.253632	2
39.349976	-120.25351	2
39.351906	-120.250633	2
39.350124	-120.250351	2
39.349834	-120.248695	2
39.346809	-120.240509	2
39.35416	-120.246887	2
39.355266	-120.247633	2
39.357922	-120.244141	2
39.355808	-120.227165	2
39.356575	-120.229988	2
39.36087	-120.240868	2
39.317165	-120.266846	2
39.32666	-120.225174	2
39.339909	-120.22097	2
39.339676	-120.220596	2
39.345802	-120.219261	2
39.33839	-120.252731	2
39.32565	-120.237425	2b
39.329529	-120.245659	2
39.32373	-120.289665	2
39.319324	-120.300079	2
39.371033	-120.236557	2
39.371323	-120.244614	2
39.347	-120.253799	2
39.338093	-120.217163	2
39.337978	-120.215652	2
39.318188	-120.297417	2
39.329369	-120.250336	2
39.328742	-120.250592	2b
39.329447	-120.249393	2
39.327515	-120.243652	2
39.327515	-120.243652	2
39.36232	-120.237305	2

39.355331	-120.238792	2
39.339035	-120.24556	2
39.355576	-120.213684	2
39.355644	-120.214317	2
39.356735	-120.218002	2
39.342472	-120.250374	2
39.343178	-120.251251	2
39.344543	-120.240518	2
39.344766	-120.240045	2
39.355381	-120.240463	2
39.344337	-120.241001	2
39.340172	-120.227745	2
39.348431	-120.221703	2
39.350277	-120.225288	2
39.350723	-120.218124	2
39.346247	-120.221305	2
39.349754	-120.222504	2
39.349602	-120.21769	2
39.340233	-120.245804	2
39.34045	-120.249657	2
39.340275	-120.252319	2
39.342697	-120.205391	2
39.34866	-120.214104	2
39.339832	-120.224762	2
39.340076	-120.222359	2
39.3437	-120.223267	2
39.353523	-120.2345	2
39.360687	-120.244034	2
39.344642	-120.204592	2
39.341202	-120.201355	2
39.357338	-120.259048	2
39.356876	-120.259491	2
39.341202	-120.224205	2
39.338566	-120.222336	2
39.338905	-120.201889	2
39.339371	-120.20237	2
39.340355	-120.254044	2
39.341632	-120.228119	2
39.369846	-120.174721	2
39.322929	-120.191978	2
39.384059	-120.088866	2
39.382586	-120.083546	2
39.368881	-120.171593	2b
39.363163	-120.174446	2b

	39.363754	-120.174263	2
	39.362877	-120.172226	2
	39.362244	-120.171631	2
	39.367943	-120.178001	2
	39.366936	-120.179855	2
	39.368587	-120.17955	2
	39.365433	-120.176247	2
	39.315777	-120.186752	2
Arms placed at 48"	39.316017	-120.190285	2a
	39.316021	-120.195816	2
	39.361305	-120.252052	2
	39.323087	-120.226325	2
	39.323087	-120.226325	2
	39.368984	-120.180687	2
	39.323193	-120.191971	2
placed guard arm	39.369698	-120.176155	2a
	39.326553	-120.203857	2
CATV Issue	39.323441	-120.202812	2b
	39.337922	-120.25163	2
	39.338364	-120.238853	2
	39.338886	-120.22628	2
	39.340157	-120.255737	2
	39.356262	-120.25666	2
	39.393998	-120.021658	2
	39.36776	-120.175697	2
ADSS fiber, arm not required	39.314289	-120.202965	2a
ADSS fiber, arm not required	39.315125	-120.201383	2a
	39.364033	-120.170372	2
Needs taller pole to maintain road clearance	39.366859	-120.102026	2a
Pole to short, power built in to our spacing	39.316849	-120.171982	2a
	39.353127	-120.183197	2
Pole to short to maintain proper clearance	39.349834	-120.184135	2a
	39.350979	-120.186089	2
	39.350239	-120.18351	2
Arm placed	39.312794	-120.174187	2a
	39.328922	-120.236412	2
	39.328804	-120.239182	2
	39.344032	-120.200523	2
	39.345173	-120.201691	2
	39.328541	-120.238831	2
	39.343716	-120.200256	2
Arm placed, All att wires at 48"	39.366249	-120.177132	2a
	39.370382	-120.087642	2
	39.371315	-120.08802	2

	39.329468	-120.163109	2
Arm placed	39.328342	-120.163589	2a
	39.367264	-120.104313	2
	39.366168	-120.09317	2
arm placed at 48"	39.367635	-120.102726	2a
	39.371993	-120.096685	2
Arm placed	39.318115	-120.181427	2a
	39.363319	-120.165756	2
	39.316044	-120.182655	2
	39.317368	-120.181763	2a
	39.315865	-120.181458	2a
	39.359791	-120.166214	2
eeds new pole, power built down in to our spacir	39.348773	-120.103542	2a
	39.346931	-120.186272	2
	39.345436	-120.181221	2
	39.346733	-120.113008	2
	39.315533	-120.195801	2a
	39.322063	-120.179451	2
	39.322716	-120.179443	2
Arm placed	39.364708	-120.097128	2a
	39.364418	-120.097323	2
	39.321964	-120.215668	2
	39.321865	-120.214447	2
	39.321899	-120.213371	2
	39.322239	-120.218529	2
	39.347776	-120.095036	2
Low dropwire removed.	39.346419	-120.096336	2b
	39.327507	-120.211319	2
	39.350148	-120.090344	2
	39.35094	-120.088158	2
	39.366216	-120.166631	2
Drops moved to 4', arm placed	39.367241	-120.183219	2a
	39.316143	-120.283455	2
	39.31609	-120.284325	2
	39.31665	-120.270744	2
	39.316784	-120.269753	2
	39.317184	-120.269455	2
	39.317329	-120.286613	2
	39.31739	-120.270248	2
	39.317562	-120.265846	2
	39.366409	-120.173225	2
	39.366409	-120.173225	2
Work complete, spacing fixed	39.328144	-120.163712	2a
Arm placed	39.327587	-120.163818	2a

	39.327209	-120.163803	2
	39.392281	-120.021471	2
NTF	39.229034	-120.204437	2a
	39.334557	-120.158279	2
	39.334557	-120.158279	2
	39.335075	-120.154388	2
Pole needs to be taller, power notified	39.334484	-120.159454	2a
	39.335835	-120.159775	2
	39.336922	-120.157768	2
	39.336147	-120.155724	2
	39.336525	-120.154648	2a
	39.360315	-120.09718	2a
	39.36163	-120.097233	2
Cables moved and arm placed at 48"	39.364775	-120.095936	2a
	39.359856	-120.173569	2
	39.360889	-120.174049	2
	39.361813	-120.174515	2
CATV Down guy, not ours	39.326385	-120.178741	2b
	39.223915	-120.20208	2
	39.253078	-120.210373	2
	39.342681	-120.208434	2
	39.350028	-120.086825	2
	39.325191	-120.280205	2
	39.325203	-120.280884	2
	39.32759	-120.240608	2
	39.329036	-120.246193	2
	39.329618	-120.249304	2
	39.337717	-120.251001	2
	39.336735	-120.160133	2
Guard arm placed, drops spaced	39.336304	-120.151245	2a
Arm placed at 48"	39.336285	-120.151878	2a
	39.336071	-120.151451	2
	39.363281	-120.156792	2
Needs a taller pole for us to be correct	39.319019	-120.183464	2a
	39.316872	-120.186867	2
	39.316872	-120.186867	2
Placed arm at 48"	39.365467	-120.100948	2a
	39.364449	-120.103525	2
	39.365077	-120.103708	2
	39.34911	-120.180725	2
arm placed	39.355327	-120.102943	2a
	39.357811	-120.105864	2
Pole to short, power built in to our spacing	39.316757	-120.168457	2a
	39.253155	-120.210037	2a

	39.347505	-120.210974	2
	39.328888	-120.253517	2
	39.322117	-120.219818	2
	39.330265	-120.255135	2
	39.328873	-120.259399	2
	39.325699	-120.272079	2
	39.327564	-120.266251	2
	39.326317	-120.270126	2
	39.325451	-120.28447	2
	39.347669	-120.209779	2
Arm placed at 48"	39.355171	-120.102395	2a
	39.354892	-120.110409	2
	39.316772	-120.171425	2
Arm placed	39.316463	-120.169456	2a
	39.353245	-120.181953	2
	39.318069	-120.161736	2
Needs new pole	39.317875	-120.163208	2a
ed, plant is built in to our spacing, down guy place	39.31675	-120.163223	2a
	39.318436	-120.162437	2a
	39.349272	-120.202515	2
	39.346832	-120.20713	2
	39.345982	-120.206863	2
	39.35998	-120.091067	2
	39.345979	-120.20411	2
	39.350909	-120.180525	2
	39.3516	-120.18079	2
	39.349728	-120.205376	2
	39.356526	-120.207956	2
	39.355759	-120.216393	2
	39.355599	-120.218616	2
	39.355625	-120.221176	2
	39.32526	-120.204185	2
	39.325832	-120.204132	2
	39.324459	-120.206909	2
	39.362788	-120.148597	2
	39.364308	-120.176064	2
	39.317966	-120.262741	2
	39.31797	-120.262054	2
	39.320255	-120.298653	2
	39.320113	-120.294245	2
	39.322926	-120.291077	2
	39.339725	-120.137505	2a
	39.325478	-120.226418	2
	39.848287	-120.68476	1

	39.561344	-120.826309	2
	39.561295	-120.825272	2
	39.559216	-120.829941	2
	39.558849	-120.831131	2
	39.559155	-120.824898	2
	39.557177	-120.828522	2
	39.555965	-120.853706	2b
	39.560718	-120.840387	2
	39.560718	-120.840387	2
	39.553875	-120.855461	2
	39.556911	-120.852867	2b
	39.557198	-120.852692	2b
ATTACHMENTS ON BOTH SIDES OF SPAN	39.556202	-120.883652	2
	39.564426	-120.880379	2
	39.561256	-120.881737	2
	39.565857	-120.630928	2
	39.568447	-120.618141	2
	39.583588	-120.368881	2
	39.560802	-120.359352	2b
	39.560184	-120.356216	2b
	39.616692	-120.588409	2b
	39.209661	-120.801981	2a
	39.205654	-120.80468	2a
	39.211837	-120.812837	2
	39.214084	-120.810947	2
	39.254864	-120.722656	2
	39.213066	-120.809341	2
	39.193433	-120.83175	2b
	39.195687	-120.832474	2b
	39.199218	-120.834684	2b
D 9/2021 TO REPLACE POLE AND TRANSFER CAI	39.202673	-120.802046	2c
	39.146664	-120.903923	2b
	39.275088	-120.706199	2
	39.206464	-120.815799	2
	39.208023	-120.818935	2b
	39.258074	-120.709576	2
	39.137825	-120.920029	2b
	39.314865	-120.637108	2
	39.217037	-120.793822	2
	39.25758	-120.711113	2
	39.285141	-120.699005	2
	39.285809	-120.69516	2
	39.208458	-120.792888	2a
	39.290627	-120.722812	2

39.290767	-120.722132	2
39.20385	-120.827301	2b
39.293041	-120.674973	2
39.195107	-120.8116	2
39.290918	-120.723558	2
39.208776	-120.789967	2
39.21686	-120.797065	2a
39.216229	-120.796877	2
39.207224	-120.808219	2
39.205356	-120.80827	2
39.206106	-120.804908	2
39.208645	-120.806829	2a
39.205899	-120.80487	2
39.136005	-120.919491	2b
39.13909	-120.919671	2b
39.153779	-120.891707	2
39.220798	-120.800545	2
39.235045	-120.756048	2b
39.232547	-120.758895	2b
39.231248	-120.760379	2
39.188641	-120.829262	2b
39.189842	-120.832527	2b
39.214521	-120.78742	2
39.217988	-120.785398	2
39.231098	-120.786324	2
39.223745	-120.799279	2
39.154332	-120.854249	2b
39.286995	-120.689799	2
39.288673	-120.691991	2
39.288376	-120.692513	2
39.217613	-120.809441	2
39.2196	-120.807357	2
39.206545	-120.797122	2
39.207558	-120.794006	2
39.311821	-120.663071	2
39.333797	-120.655138	2
39.358097	-120.664327	2
39.370648	-120.674832	2
39.241264	-120.735168	2
39.24099	-120.738693	2
39.240743	-120.737646	2
39.242562	-120.734163	2
39.247982	-120.731049	2
39.248341	-120.731128	2a

	39.194622	-120.83197	2b
	39.194153	-120.835388	2b
	39.299755	-120.66523	2b
POLE REPLACEMENT JOB A02E5AQ 7/7/2022	39.466209	-121.280144	2c
EPLACEMENT PROJECT A02E5AQ DRWN 7/7/202	39.462326	-121.283867	2c
	39.474403	-121.270172	2
JOB DRAWN A02E61J 7/7/2022	39.475414	-121.272682	2c
	39.540272	-121.150497	2b
	39.539574	-121.151016	2b
	39.538956	-121.151344	2b
	39.529049	-121.170891	2b
	39.519161	-121.257851	2
	39.517494	-121.260101	2b
	39.499348	-121.253067	2
MIC JOB CREATED 7/8/2022 A02E6P0	39.474251	-121.265831	2c
	39.519119	-121.275108	2b
MIC JOB CREATED A02E6P0 7/8/2022	39.47575	-121.263	2c
	39.516449	-121.266068	2b
	39.478325	-121.256119	2b
	39.527084	-121.284508	2
	39.431469	-121.251686	2b
	39.506001	-121.308784	2
	39.448524	-121.259933	2
	39.51255	-121.274696	2b
	39.483635	-121.244293	2b
	39.483776	-121.244911	2b
	39.547928	-121.138985	2b
	39.509308	-121.275223	2b
	39.516567	-121.274597	2b
	39.520172	-121.273643	2b
	39.552269	-121.132942	2
	39.52058	-121.259766	2
	39.440811	-121.273476	2b
	39.518078	-121.303894	2a
	39.483547	-121.243843	2b
	39.475094	-121.264084	2
	39.478939	-121.253593	2b
	39.499176	-121.253014	2
MIC JOB CREATED A02E6P0 - 7/8/2022	39.474609	-121.264915	2c
	39.517181	-121.267715	2b
JOB CREATED A02E7QL 7/11/2022	39.425575	-121.290291	2c
	39.427963	-121.289673	2
	39.4496	-121.283813	2
	39.701847	-120.964653	2

39.437965	-121.271622	2
39.436596	-121.269005	2b
39.428917	-121.263474	2b
39.412895	-121.258255	2
39.521572	-121.182663	2b
39.451935	-121.285873	2
39.481518	-121.241783	2b
39.48629	-121.22274	2
39.434887	-121.168434	2
39.811065	-120.477653	1
39.23981	-121.112143	2
39.220348	-120.927994	2
39.221111	-120.927109	2
39.224461	-121.030304	2
39.130604	-121.049828	2
39.129913	-121.049721	2
39.181904	-121.0298	2
39.16645	-120.992035	2b
39.187939	-120.969463	2
39.146883	-120.96488	2
39.145004	-121.048439	2
39.159878	-121.148697	2
39.145493	-121.047432	2b
39.146324	-121.046822	2b
39.146149	-121.046227	2b
39.148656	-120.994119	2a
39.148656	-120.994119	2
39.231766	-121.10984	2
39.203892	-121.061417	2
39.123936	-121.059265	2a
39.120361	-121.056755	2
39.144318	-121.035469	2
39.144318	-121.035469	2
39.155025	-120.96505	2
39.155029	-120.963203	2
39.155074	-120.961811	2
39.230893	-121.110085	2
39.155521	-121.031235	2
39.158539	-121.032959	2b
39.219282	-121.099673	2
39.125278	-121.048775	2a
39.219167	-121.100455	2
39.219167	-121.100455	2
39.121822	-121.060089	2

39.214787	-121.048843	2
39.214298	-121.046738	2
39.127625	-121.057243	2
39.127155	-121.05497	2
39.12949	-121.050285	2
39.131027	-121.051476	2
39.131424	-121.051323	2
39.133518	-121.053505	2
39.135811	-121.050674	2
39.156649	-120.973877	2
39.235643	-121.110207	2
39.155104	-120.973021	2
39.193253	-121.032471	2
39.187443	-121.027557	2
39.163358	-120.977338	2
39.165088	-120.96725	2
39.165319	-120.967813	2
39.115971	-121.057854	2
39.116993	-121.057037	2
39.140724	-121.032623	2
39.151659	-120.958267	2
39.152191	-120.961284	2
39.196781	-121.034012	2
39.201937	-121.090515	2
39.238013	-121.102347	2
39.158901	-120.976432	2
39.133778	-121.100067	2
39.112259	-121.053223	2
39.112259	-121.053223	2
39.115364	-121.052475	2
39.114964	-121.057816	2
39.114235	-121.058449	2
39.111584	-121.059525	2
39.113796	-121.059113	2
39.150366	-120.960039	2
39.150366	-120.960039	2a
39.147935	-120.952739	2
39.148004	-120.954094	2
39.148004	-120.954094	2a
39.191776	-121.007507	2b
39.1348	-121.142913	2
39.156277	-121.12719	2
39.157837	-120.980427	2a
39.222435	-120.945648	2

39.113075	-121.059265	2
39.169907	-120.970525	2
39.104397	-121.065125	2
39.227566	-121.066231	2a
39.121689	-121.057823	2
39.121689	-121.057823	2a
39.1241	-121.056969	2
39.163179	-120.956513	2
39.225319	-120.945328	2b
39.122055	-121.053711	2
39.131508	-121.054405	2
39.132431	-121.054337	2
39.133041	-121.054382	2
39.133041	-121.054382	2
39.212982	-121.008766	2b
39.130314	-121.055199	2
39.172619	-121.047272	2
39.161263	-121.021027	2
39.195011	-121.028915	2
39.193537	-121.027062	2
39.218093	-121.098505	2
39.229767	-121.000252	2
39.20866	-121.059288	2
39.134991	-121.052498	2
39.134892	-121.052979	2
39.147544	-120.959558	2a
39.146347	-120.954278	2
39.146097	-120.954646	2
39.103149	-121.0625	2
39.10453	-121.062988	2
39.242783	-121.118507	2
39.156863	-120.958939	2
39.156863	-120.958939	2a
39.137856	-121.046318	2
39.220395	-121.06673	2
39.24316	-121.117897	2
39.129169	-121.075668	2b
39.128574	-121.076187	2b
39.105972	-121.051254	2a
39.14463	-121.045067	2b
39.156809	-120.959661	2a
39.158669	-120.961891	2
39.158559	-120.964582	2a
39.158794	-120.963014	2

39.238033	-121.044647	2
39.243767	-121.073067	2
39.240849	-121.072273	2
39.116673	-121.05925	2
39.150631	-121.040802	2b
39.151417	-121.04187	2
39.107681	-121.052887	2
39.128357	-121.076225	2b
39.158812	-120.958208	2
39.240322	-121.035728	2
39.240559	-121.035385	2
39.24144	-121.036865	2
39.239986	-121.036247	2
39.172596	-121.029388	2
39.129612	-121.064049	2
39.131775	-121.066856	2
39.127426	-121.061829	2
39.127941	-121.065636	2
39.175678	-121.025368	2
39.160262	-120.974032	2
39.237644	-121.040276	2
39.238869	-121.041283	2
39.206928	-121.107208	2
39.118317	-121.074203	2
39.151566	-121.029366	2
39.116417	-121.071083	2
39.162417	-120.967215	2
39.163368	-120.965757	2
39.208771	-121.105049	2
39.165747	-120.963951	2a
39.180367	-121.022758	2
39.189794	-120.979831	2
39.193297	-120.977953	2
39.147995	-120.95389	2
39.1968	-120.980461	2a
39.186661	-120.986221	2b
39.152284	-120.962836	2
39.119007	-121.067284	2
39.12846	-121.058922	2
39.129295	-121.060226	2
39.162718	-120.962155	2
39.162413	-120.95981	2
39.218548	-120.949959	2b
39.218449	-120.951988	2

39.191464	-120.999618	2b
39.191468	-121.026435	2
39.191471	-120.971712	2
39.153165	-120.961947	2
39.191591	-120.972196	2
39.103889	-121.152664	2
39.130119	-121.059349	2
39.215945	-121.055937	2
39.215847	-121.055557	2
39.105385	-121.060059	2
39.160461	-120.961349	2
39.189411	-121.021164	2
39.160907	-120.964359	2
39.129078	-121.050827	2
39.231621	-121.059319	2
39.207047	-120.972969	2
39.231937	-121.060417	2
39.206635	-120.972771	2
39.193932	-121.027467	2b
39.145132	-120.96845	2
39.146193	-120.971591	2
39.14864	-121.030807	2
39.145074	-120.977915	2
39.113144	-121.055954	2a
39.157172	-120.988359	2
39.135651	-121.079964	2
39.136219	-121.076469	2
39.17017	-120.964493	2
39.168353	-120.96687	2
39.169094	-120.966026	2
39.227577	-120.992554	2
39.129139	-121.053169	2
39.130135	-121.050484	2
39.13303	-121.050957	2
39.132504	-121.051048	2
39.129692	-121.052444	2
39.14747	-120.972805	2
39.145065	-120.975517	2
39.160074	-121.038982	2
39.146901	-120.980904	2
39.14681	-120.964933	2
39.149198	-120.963033	2
39.165627	-121.040794	2b
39.185517	-121.139653	2

39.153011	-120.982342	2
39.153246	-120.982513	2a
39.12466	-121.074425	2
39.150806	-120.982953	2
39.121071	-121.076561	2
39.235909	-121.125313	2
39.235909	-121.125313	2
39.218372	-121.012566	2b
39.214851	-121.007896	2
39.129213	-121.142255	2
39.200558	-121.019859	2b
39.200558	-121.019859	2
39.229836	-121.101143	2
39.199978	-120.997452	2
39.131031	-121.030075	2
39.137779	-121.031982	2a
39.212475	-121.002434	2
39.210388	-121.004387	2b
39.199306	-120.964955	2
39.19549	-120.969812	2
39.18499	-120.939837	2
39.184399	-120.936891	2
39.155758	-121.128258	2
39.213929	-121.00648	2b
39.225746	-121.068237	2
39.228764	-121.070854	2
39.224796	-121.068398	2
39.184115	-120.962344	2
39.195183	-120.994278	2
39.18334	-120.946978	2
39.139996	-121.039696	2
39.198315	-121.002563	2
39.182515	-120.949119	2
39.195459	-120.94427	2
39.197125	-120.942715	2
39.199306	-120.964955	2
39.212784	-121.001633	2
39.146538	-121.032501	2a
39.187988	-120.948961	2
39.181442	-121.102501	2b
39.273556	-121.110268	2
39.250107	-121.12899	2
39.273376	-121.116173	2
39.23764	-120.997963	2

39.186225	-120.976325	2
39.22007	-121.070129	2
39.220367	-121.069832	2
39.140732	-121.038658	2
39.178095	-120.946828	2
39.178095	-120.946828	2a
39.178536	-120.949429	2
39.144424	-121.031898	2
39.135612	-121.041405	2
39.189651	-120.953286	2
39.185432	-121.015739	2
39.186184	-120.944812	2
39.189442	-120.937683	2
39.157851	-120.940116	2
39.182617	-120.986023	2b
39.166473	-120.932983	2
39.166004	-120.936366	2
39.253777	-121.147186	2
39.254295	-121.147827	2
39.254051	-121.153404	2
39.258579	-121.145576	2
39.252377	-121.146965	2
39.253349	-121.154549	2a
39.252281	-121.155167	2a
39.254189	-121.160896	2
39.236877	-120.998833	2
39.239178	-120.996086	2
39.22873	-121.138815	2
39.239201	-121.065819	2
39.234333	-121.066246	2
39.21286	-121.04715	2
39.212654	-121.046547	2
39.232712	-121.067795	2
39.23257	-121.125917	2
39.191383	-120.962672	2
39.199387	-120.963158	2
39.195709	-120.962497	2
39.195709	-120.962497	2a
39.107323	-121.029221	2a
39.193653	-120.951701	2
39.188065	-120.988831	2
39.179479	-120.961635	2
39.190765	-120.937919	2
39.190837	-120.938428	2

39.192249	-120.935066	2
39.19265	-120.932205	2
39.19429	-120.931854	2
39.190618	-120.932619	2
39.193626	-121.085007	2
39.186934	-120.93148	2
39.171886	-120.988693	2b
39.224167	-121.056984	2
39.221149	-121.054718	2
39.245129	-121.109398	2
39.252796	-121.108597	2
39.251858	-121.102592	2
39.282242	-121.125053	2
39.274052	-121.134315	2
39.288071	-121.118141	2
39.165901	-121.141289	2
39.171104	-121.137932	2
39.172108	-121.139984	2
39.175029	-120.968089	2
39.176319	-120.968887	2
39.198639	-121.016197	2b
39.176754	-120.978821	2
39.106815	-121.043198	2
39.203857	-121.141485	2
39.174598	-120.956605	2
39.225929	-121.079086	2
39.221756	-121.090607	2
39.223095	-121.088036	2
39.22184	-121.087868	2
39.219856	-121.090622	2
39.223808	-121.088074	2
39.223515	-121.091522	2
39.221611	-121.080391	2
39.22633	-121.089401	2
39.200608	-120.919587	2a
39.186717	-120.918695	2a
39.181971	-120.917552	2
39.181971	-120.917552	2a
39.179761	-120.91643	2
39.185137	-120.919865	2
39.247936	-121.106422	2
39.249969	-121.105042	2
39.254505	-121.097961	2
39.166496	-121.150513	2

39.257919	-121.141762	2
39.178366	-120.967444	2
39.177216	-120.970845	2
39.164875	-121.102028	2
39.18426	-120.981301	2
39.182734	-120.981599	2
39.110409	-121.041	2a
39.111958	-121.04023	2a
39.200794	-121.021126	2
39.20229	-121.021202	2
39.198605	-121.022324	2b
39.228924	-121.139313	2
39.233257	-121.074577	2
39.231602	-121.071922	2
39.221703	-121.000648	2b
39.226799	-121.079453	2
39.226738	-121.079308	2
39.222954	-121.005455	2
39.221584	-121.003273	2b
39.222435	-121.066299	2a
39.22102	-121.06488	2
39.190679	-120.949527	2a
39.224297	-121.086761	2
39.220619	-121.079506	2
39.22226	-121.084259	2
39.166878	-121.098694	2
39.223576	-121.065613	2
39.218266	-121.081604	2
39.219925	-121.081696	2
39.216084	-121.084198	2
39.261257	-121.12247	2
39.268291	-121.101959	2
39.272591	-121.107048	2
39.214493	-121.013397	2b
39.216488	-121.011658	2
39.141229	-121.164399	2
39.204151	-121.020241	2b
39.20348	-121.020203	2
39.180745	-120.982685	2
39.227205	-121.144232	2
39.204433	-121.021278	2b
39.20512	-121.019402	2
39.229168	-121.025894	2
39.233341	-121.069412	2

39.234985	-121.078484	2
39.231289	-121.075134	2
39.233391	-121.078857	2
39.230591	-121.07621	2
39.229885	-121.075798	2
39.229247	-121.139548	2
39.229794	-121.077881	2
39.12159	-121.034508	2
39.190156	-120.967836	2
39.192351	-120.966828	2
39.186114	-120.95519	2a
39.185072	-120.957198	2
39.108288	-121.034798	2
39.108288	-121.034798	2a
39.222252	-121.082024	2
39.123489	-121.036125	2
39.217426	-121.081726	2
39.220646	-121.068985	2
39.201436	-120.911671	2a
39.270855	-121.106117	2
39.270214	-121.118286	2
39.269562	-121.116043	2
39.260601	-121.106705	2
39.247971	-121.095245	2
39.268024	-121.104301	2
39.26506	-121.106834	2
39.266262	-121.105835	2
39.13821	-121.129401	2
39.135165	-121.131426	2
39.135165	-121.131426	2
39.229045	-121.13935	2
39.185076	-120.978775	2
39.13533	-121.038551	2
39.118271	-121.037102	2
39.136684	-121.039818	2
39.226223	-121.081032	2
39.226223	-121.081032	2
39.106331	-121.039246	2
39.229298	-121.093361	2
39.237556	-121.092453	2
39.182426	-120.996071	2
39.220825	-121.082817	2
39.195396	-120.92289	2
39.220943	-121.068893	2

39.268059	-121.106056	2
39.22279	-121.055893	2
39.221054	-121.055275	2
39.22316	-121.055717	2
39.209869	-121.08326	2
39.214695	-121.078308	2
39.211945	-121.087654	2
39.209854	-121.082832	2
39.210148	-121.083046	2
39.161774	-121.084831	2
39.175087	-121.111679	2
39.180207	-120.930568	2a
39.238724	-121.002914	2
39.237167	-121.007813	2
39.237167	-121.007813	2
39.236473	-121.003113	2
39.181778	-121.107811	2
39.182133	-121.09655	2
39.170915	-120.93552	2
39.179779	-121.096283	2
39.208057	-120.955574	2
39.181892	-121.103088	2
39.262238	-121.143753	2
39.274265	-121.154251	2
39.276463	-121.152519	2
39.143215	-121.063637	2
39.220829	-121.13784	2
39.242908	-121.108253	2
39.2425	-121.114456	2
39.239697	-121.102135	2
39.237164	-121.13073	2
39.181854	-121.047325	2
39.965411	-120.943851	1
39.820263	-120.477577	2
39.801331	-120.473167	2
39.806541	-120.465126	2
39.787093	-120.502574	2
39.812079	-120.49881	2
39.778972	-120.502778	2
39.789932	-120.501658	2
39.790836	-120.493098	2
39.790417	-120.496585	2
39.790359	-120.497135	2
39.791039	-120.492393	2

39.79032	-120.491966	2
39.787612	-120.499842	2
39.804819	-120.507738	2
39.819715	-120.451668	2
39.810386	-120.478111	2
39.810386	-120.478111	2
39.818801	-120.460763	2
39.82013	-120.460697	2
39.808147	-120.488344	2
39.8058	-120.497865	2
39.959778	-120.955667	2
39.948141	-120.958842	2b
39.944592	-120.951294	2
39.944703	-120.948159	2
39.954547	-120.953557	2
39.903471	-120.752247	2
39.902964	-120.753174	2
39.789867	-120.502925	2
39.787123	-120.504136	2
39.790272	-120.504015	2
39.79038	-120.502316	2
39.795925	-120.504037	2
39.934008	-120.902905	2
39.934118	-120.90435	2
39.905324	-120.748691	2
39.904671	-120.747211	2
39.90718	-120.740818	2
39.907886	-120.741673	2
39.9064	-120.745359	2
39.90643	-120.74323	2
39.907429	-120.743601	2
39.907657	-120.744947	2
39.908523	-120.744853	2
39.941204	-120.865789	2
39.906466	-120.74652	2
39.907424	-120.75313	2
39.808371	-120.499225	2
39.809748	-120.498931	2
39.811539	-120.499499	2
39.813137	-120.50133	2
39.811851	-120.496291	2
39.813142	-120.498871	2
39.813157	-120.497218	2
39.810093	-120.495983	2

39.808485	-120.486839	2
39.819305	-120.456181	2
39.81452	-120.45896	2
39.952398	-120.883673	2
39.941662	-120.933577	2b
39.936916	-120.916159	2
39.810485	-120.499239	2
39.789995	-120.489895	2
39.813238	-120.499146	2
39.813126	-120.500166	2
39.812603	-120.47065	2
39.814991	-120.469116	2
39.817219	-120.467323	2
39.815659	-120.470284	2
39.935573	-121.067695	2
39.925843	-121.069568	2
39.927156	-120.906507	2
39.930483	-120.904672	2
39.931941	-120.902702	2
39.931966	-120.901979	2
39.818233	-120.46595	2
39.816078	-120.458008	2
39.816608	-120.473549	2
39.81551	-120.471062	2
39.819702	-120.477234	2
40.038145	-120.99457	2
39.934155	-120.890087	2
39.928789	-120.896955	2
39.933714	-120.895264	2
39.932912	-120.898602	2
39.806735	-120.497903	2
39.821293	-120.455253	2
39.816422	-120.452769	2
39.81647	-120.452134	2
39.816663	-120.451411	2
39.932563	-120.901209	2
39.929031	-120.903224	2
39.927606	-120.904255	2
39.935084	-120.904658	2
39.935492	-120.904736	2
39.936124	-120.902663	2
39.936282	-120.903457	2
39.934731	-120.89636	2
39.932088	-120.892403	2

	39.933074	-120.892433	2
	39.943669	-120.924737	2
	39.944131	-120.926713	2
	39.950878	-120.914232	2
	39.943168	-120.925527	2
	39.939245	-120.938542	2b
	39.946179	-120.928238	2
	39.946866	-120.955858	2
	39.953427	-120.958761	2
	39.946226	-120.928406	2
	39.956149	-120.956432	2b
	39.956501	-120.956111	2b
	39.933921	-120.855048	2
	39.905671	-120.749078	2
	39.81176	-120.498598	2
	39.812265	-120.49909	2
	39.8122	-120.497731	2
	39.931033	-120.894068	2
	39.928816	-120.894125	2
	39.930038	-120.896509	2
	39.933902	-120.899045	2
	39.933813	-120.897907	2
	39.933887	-120.891512	2
	39.934256	-120.902414	2
	39.64753	-120.218643	2
	39.635231	-120.206253	2
	39.648438	-120.221451	2
	39.751857	-120.067755	2
	39.749931	-120.071397	2
	39.737216	-120.063538	2
	39.737296	-120.061515	2
	39.737458	-120.057646	2
	39.755653	-120.066936	2
	39.641006	-120.219208	2
	39.644089	-120.21936	2
	39.642246	-120.216011	2a
	39.641052	-120.216873	2a
	39.639521	-120.215956	2a
	39.636341	-120.205261	2a
04/07/22 Hazard cleared per RA9619			
	39.171861	-121.023697	1
04/07/22 Hazard cleared per RA9619			
	39.15767	-121.026399	1

04/07/22 Hazard cleared per RA9619			
	39.15767	-121.026399	1
04/07/22 Hazard cleared per RA9619			
	39.121332	-121.053523	1
04/07/22 Hazard cleared per RA9619			
	39.121332	-121.053523	1
04/07/22 Hazard cleared per RA9619			
	39.134306	-121.047874	1
	39.184464	-121.013116	1
	39.184464	-121.013116	1
04/07/22 Hazard cleared per RA9619			
	39.180511	-120.956483	1
	39.874209	-120.708813	1
	39.876534	-120.713942	1
04/07/22 Hazard cleared per RA9619			
	39.165109	-121.034886	1
	39.157603	-120.941614	1
04/07/22 Hazard cleared per RA9619			
	39.180863	-120.986728	1
	39.935777	-120.941546	1
	39.225557	-121.076373	2
	39.945529	-121.060837	1
	39.94384	-120.91391	1
04/07/22 Hazard cleared per RA9619			
	39.164284	-121.046549	1
	39.135241	-120.918634	1
	39.32278	-120.855881	1
rees and now cable is laying on ground one pole/	39.3234	-120.877622	1
	39.674157	-120.269931	1
, re-attached cable and sagged to proper height	39.263466	-120.914271	1
P#36 re-attached and sagged to proper height p	39.188259	-121.048248	1
	39.881514	-120.867893	1
waiting for job to be issued	39.316526	-120.285945	1
	39.877346	-121.197842	1
	39.18061	-120.860065	2b
	39.155911	-120.887984	2b
	39.158497	-120.880219	2b
	39.208747	-120.815655	2b
	39.285833	-120.695182	2
	39.207233	-121.038635	2b
	39.213047	-121.060181	2b
	39.214382	-121.04966	2b
	39.187202	-120.999863	2b
	39.211353	-121.060173	2b

39.277374	-121.067207	2b
39.241234	-121.030525	2b
39.289307	-120.97226	2b
39.23941	-120.999863	2b
39.29039	-120.997543	2b
39.271721	-121.061829	2b
39.22113	-121.010689	2b
39.226746	-121.012123	2b
39.189412	-121.018737	2b
39.214886	-121.040413	2b
39.266846	-121.026009	2b
39.308853	-121.030487	2b
39.215977	-120.997147	2b
39.268471	-121.020721	2b
39.291443	-121.016174	2b
39.282887	-121.011139	2b
39.216892	-121.050262	2b
39.266911	-121.023781	2b
39.277519	-121.044228	2b
39.20631	-121.038162	2b
39.207401	-121.03701	2b
39.276806	-121.044586	2b
39.263832	-121.028496	2b
39.271305	-121.060471	2b
39.273315	-121.064529	2b
39.264175	-121.030182	2b
39.282108	-121.011803	2b
39.192268	-120.991882	2b
39.212479	-121.058777	2b
39.204322	-121.009758	2b
39.219063	-121.012581	2b
39.221699	-121.00058	2b
39.221886	-121.008789	2b
39.221649	-121.002411	2b
39.217037	-120.968506	2b
39.275352	-121.022011	2b
39.215085	-120.995976	2b
39.198654	-121.056725	2b
39.186357	-121.053062	2b
39.194172	-121.020348	2b
39.211224	-121.004074	2b
39.236942	-121.021568	2b
39.206516	-121.039558	2b
39.234791	-121.020439	2b

	39.234715	-121.018799	2b
	39.234821	-120.989326	2b
	39.301636	-120.973984	2c
ANNER LAVA CAP RD	39.23941	-120.999863	2c
)	39.186493	-121.02342	3
	39.234821	-120.989326	2
	39.470638	-121.053818	2b
	39.484634	-121.040031	2b
	39.452038	-121.049179	2b
REPLACED WITH JOB A02FCW8 9/1/2022	39.358391	-121.120773	2c
	39.347	-120.185966	2
	39.340252	-120.224092	2
	39.353306	-120.181747	2
	39.368488	-120.237656	2
	39.369877	-120.174767	2
	39.3503	-120.183586	2
	39.349728	-120.214835	2
	39.35564	-120.219583	2
	39.350783	-120.2139	2
	39.340254	-120.223684	2
	39.348507	-120.213821	2
	39.364998	-120.236656	2
	39.327099	-120.235191	2
	39.327099	-120.235191	2
	39.367416	-120.241287	2
	39.349845	-120.222605	2
	39.350077	-120.2221	2
	39.346953	-120.207238	2
	39.346735	-120.2073	2
	39.35692	-120.243407	2b
	39.357128	-120.231313	2
	39.93514	-120.934438	2
	39.935726	-121.068024	2
	39.944515	-121.054367	2
	39.933685	-120.943657	2
	39.936118	-120.951573	2
	39.930017	-120.893913	2
	39.934616	-120.946465	2
	39.934284	-120.943253	2
	39.870693	-121.173218	2
	39.935558	-120.93512	2
	39.442791	-121.264336	2
	39.441963	-121.274605	2
	39.937669	-120.945534	1

10/25/22 Cleared per RA9619	39.521682	-121.000127	1
	39.849888	-120.686446	1
	39.789641	-120.481659	1
	39.677297	-120.247942	1
	39.922364	-121.076334	1
	39.158497	-120.880219	2b
	39.18061	-120.860065	2b
	39.208747	-120.815655	2b
	39.155911	-120.887984	2b
Hazard cleared per Sup RA9619	39.188236	-121.185141	1
to Deterioration, Insect or Bird Damage, or Dama	39.194032	-121.146699	1
	39.190526	-120.809085	1
	39.214884	-120.848537	1
	39.184499	-120.813823	1
	39.243396	-121.198978	1
	39.276884	-120.707273	2b
	39.256369	-120.709402	1
	39.207613	-120.808948	1
	39.208311	-120.796082	1
	39.208511	-120.79316	1
	39.213129	-120.807862	1
	39.223743	-120.813276	1
	39.304877	-120.665486	2b
	39.670152	-120.667635	1
	39.469219	121.24437	2b
	39.314892	-120.637035	1
			1
	39.383654	-120.674508	1
	39.239892	-120.983418	1
	39.131162	-121.070102	1
	39.13839	-121.076729	1
	39.39201	-120.671593	1
	39.237557	-120.960539	1
	39.193039	-120.993467	1
	39.463537	-121.032631	1
	39.193039	-120.993467	1
JOB # A02SK9Z RELEASED TO THE FIELD 2/29/24	39.522175	-121.182022	2c
	39.182071	-120.93702	1
	39.164272	-120.936943	1
	39.157648	-120.941118	2b
	39.462261	-121.033501	2b
	39.257153	-121.235649	1
	39.105453	-121.062577	2a
	39.149731	-121.052917	2a

39.208752	-120.793991	2b
39.15966	-120.857735	2b
39.238571	-121.011803	2b
39.116732	-121.080871	2b
39.126171	-121.183739	2a
39.206451	-121.037758	2b
39.128857	-121.142235	2b
39.307828	-120.913188	2b
39.339169	-120.226906	2b
39.179745	-120.807886	1
39.123765	-121.17643	1
39.128612	-121.05894	1
39.142413	-121.034631	1
39.31598	-121.135895	1
39.207383	-121.043275	1
39.21996	-120.954759	1
39.21245	-120.927406	1
39.161988	-120.87802	1
39.180371	-120.98635	1
39.320892	-120.869344	1
39.195913	-121.053189	1
39.153985	-121.02531	1
39.153745	-121.023549	1
39.179981	-121.047983	1
39.350844	-120.242894	2

RSP_ORG	FIRE_TIER	POLE_TERM_MH_INFO	PLACEMENT	NEW_JOB_PURPOSE
TFS	3	100067669		GO95
TFS	2	100090531		GO95
CON	1	103886704		GO95
TFS	2	100083803		GO95
ENG	3	14099 dog	Aerial	GO95
CON	3		Aerial	GO95
CON	2	53	Aerial	GO95
CON	2	6	Aerial	GO95
CON	2	32647	Aerial	GO95
CON	2	007280	Aerial	GO95
CON	2	007105	Aerial	GO95
CON	2	009504	Aerial	GO95
CON	2	009922	Aerial	GO95
CON	2	007151	Aerial	GO95
CON	2	1051702H	Aerial	GO95
CON	2	009107	Aerial	GO95
CON	2	007251	Aerial	GO95
CON	2	009036	Aerial	GO95
CON	2	008652	Aerial	GO95
CON	2	53957	Aerial	GO95
TFS	2	SPAN	Aerial	GO95
CON	2	SPAN	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	SPAN	Aerial	GO95
CON	2	SPAN	Aerial	GO95
CON	2	007104	Aerial	GO95
CON	2	012158	Aerial	GO95
ENG	2	120761046	Aerial	GO95
ENG	2	24	Aerial	GO95
ENG	2	120782956	Aerial	GO95
TFS	2	7	Aerial	GO95
TFS	2	243	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	008655	Aerial	GO95
TFS	2	009979	Aerial	GO95
CON	2	13950931	Aerial	GO95
CON	2	53420183	Aerial	GO95
CON	2	10826959	Aerial	GO95
CON	2	03528907	Aerial	GO95
CON	2	NPT	Aerial	GO95
CON	2	88435883	Aerial	GO95

CON	2	51636986	Aerial	GO95
CON	2	176575	Aerial	GO95
CON	2	NPT	Aerial	GO95
CON	2	NPT	Aerial	GO95
CON	2	NPT	Aerial	GO95
CON	2	35813727	Aerial	GO95
CON	2	NPT	Aerial	GO95
CON	2	NPT	Aerial	GO95
CON	2	NPT	Aerial	GO95
CON	2	58576119	Aerial	GO95
CON	2	47	Aerial	GO95
CON	2	47	Aerial	GO95
CON	2	33223220	Aerial	GO95
CON	2	176589	Aerial	GO95
CON	2	22246	Aerial	GO95
CON	2	85102312	Aerial	GO95
CON	2	201338	Aerial	GO95
TFS	2	11	Aerial	GO95
CON	2	95066480	Aerial	GO95
CON	2	26340	Aerial	GO95
CON	2	6301	Aerial	GO95
TFS	2	36186179	Aerial	GO95
CON	2	161021	Aerial	GO95
CON	2	56b6	Aerial	GO95
CON	2	NPT	Aerial	GO95
CON	2	NPT	Aerial	GO95
CON	2	10826959	Aerial	GO95
CON	2	10826959	Aerial	GO95
CON	2	40046968	Aerial	GO95
CON	2	50898313	Aerial	GO95
TFS	2	24046650	Aerial	GO95
CON	2	176577	Aerial	GO95
TFS	2	58053975	Aerial	GO95
CON	2	55777189	Aerial	GO95
TFS	2	50900707	Aerial	GO95
CON	2	40046968	Aerial	GO95
CON	2	10544	Aerial	GO95
CON	2	NPT	Aerial	GO95
TFS	2	61309	Aerial	GO95
CON	2	63a	Aerial	GO95
CON	2	167911	Aerial	GO95
CON	2	66588487	Aerial	GO95
CON	2	158127	Aerial	GO95

CON	2	176579	Aerial	GO95
CON	2	56640728	Aerial	GO95
CON	2	17680939	Aerial	GO95
CON	2	24236150	Aerial	GO95
TFS	2	15631	Aerial	GO95
CON	2	90298922	Aerial	GO95
CON	2	180540	Aerial	GO95
CON	2	97252470	Aerial	GO95
CON	2	140179	Aerial	GO95
CON	2	87488390	Aerial	GO95
CON	2	140162	Aerial	GO95
CON	2	82010056	Aerial	GO95
CON	2	208563	Aerial	GO95
CON	2	Npt	Aerial	GO95
CON	2	Npt	Aerial	GO95
CON	2	161050	Aerial	GO95
CON	2	87299074	Aerial	GO95
CON	2	51378	Aerial	GO95
CON	2	45366966	Aerial	GO95
TFS	2	13670	Aerial	GO95
TFS	2	69531068	Aerial	GO95
TFS	2	158132	Aerial	GO95
TFS	2	176738	Aerial	GO95
TFS	2	68450817	Aerial	GO95
TFS	2	63916135	Aerial	GO95
TFS	2	11481	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	58146009	Aerial	GO95
TFS	2	155448	Aerial	GO95
TFS	2	32166286	Aerial	GO95
TFS	2	21343596	Aerial	GO95
TFS	2	208559	Aerial	GO95
TFS	2	180503	Aerial	GO95
TFS	2	02399141	Aerial	GO95
TFS	2	47347036	Aerial	GO95
TFS	2	26340	Aerial	GO95
TFS	2	12616175	Aerial	GO95
TFS	2	167940	Aerial	GO95
TFS	2	26108	Aerial	GO95
TFS	2	08735981	Aerial	GO95
TFS	2	62256147	Aerial	GO95
TFS	2	10579873	Aerial	GO95
TFS	2	10170	Aerial	GO95
CON	2	176721	Aerial	GO95

TFS	2	45976520	Aerial	GO95
TFS	2	16196219	Aerial	GO95
TFS	2	24046650	Aerial	GO95
TFS	2	78497696	Aerial	GO95
TFS	2	1570	Aerial	GO95
TFS	2	54325637	Aerial	GO95
TFS	2	63817518	Aerial	GO95
CON	2	155454	Aerial	GO95
TFS	2	161029	Aerial	GO95
TFS	2	180739	Aerial	GO95
TFS	2	6881480	Aerial	GO95
TFS	2	6881480	Aerial	GO95
TFS	2	14906	Aerial	GO95
TFS	2	50576001	Aerial	GO95
TFS	2	26663982	Aerial	GO95
TFS	2	72308266	Aerial	GO95
TFS	2	68768264	Aerial	GO95
TFS	2	72715740	Aerial	GO95
TFS	2	57038252	Aerial	GO95
TFS	2	41727067	Aerial	GO95
TFS	2	155471	Aerial	GO95
TFS	2	7890	Aerial	GO95
CON	2	25173620	Aerial	GO95
TFS	2	25173620	Aerial	GO95
TFS	2	20095960	Aerial	GO95
TFS	2	20095960	Aerial	GO95
TFS	2	33506527	Aerial	GO95
TFS	2	51959649	Aerial	GO95
TFS	2	60618292	Aerial	GO95
CON	2	93736587	Aerial	GO95
TFS	2	S112	Aerial	GO95
TFS	2	79239056	Aerial	GO95
TFS	2	02379288	Aerial	GO95
TFS	2	51966783	Aerial	GO95
TFS	2	97252470	Aerial	GO95
TFS	2	140181	Aerial	GO95
TFS	2	60725689	Aerial	GO95
TFS	2	140162	Aerial	GO95
TFS	2	90267413	Aerial	GO95
TFS	2	90267413	Aerial	GO95
TFS	2	68015935	Aerial	GO95
CON	2	201295	Aerial	GO95
TFS	2	208563	Aerial	GO95
TFS	2	158225	Aerial	GO95

TFS	2	44107139	Aerial	GO95
TFS	2	10049540	Aerial	GO95
CON	2	151390	Aerial	GO95
CON	2	76840907	Aerial	GO95
CON	2	52990403	Aerial	GO95
CON	2	236683	Aerial	GO95
CON	2	151398	Aerial	GO95
CON	2	85230725	Aerial	GO95
CON	2	39919748	Aerial	GO95
CON	2	67331122	Aerial	GO95
CON	2	10129	Aerial	GO95
CON	2	00245665	Aerial	GO95
CON	2	NPT	Aerial	GO95
CON	2	62400163	Aerial	GO95
CON	2	180534	Aerial	GO95
CON	2	J-62475	Aerial	GO95
CON	2	140140	Aerial	GO95
CON	2	NPT	Aerial	GO95
CON	2	3102608	Aerial	GO95
CON	2	52990403	Aerial	GO95
CON	2	12	Aerial	GO95
CON	2	139680	Aerial	GO95
TFS	2	158228	Aerial	GO95
CON	2	198675	Aerial	GO95
CON	2	139668	Aerial	GO95
CON	2	62658514	Aerial	GO95
CON	2	59458194	Aerial	GO95
CON	2	07360	Aerial	GO95
CON	2	75060	Aerial	GO95
CON	2	63192365	Aerial	GO95
CON	2	52206868	Aerial	GO95
CON	2	183262	Aerial	GO95
CON	2	161055	Aerial	GO95
CON	2	58407258	Aerial	GO95
CON	2	NPT	Aerial	GO95
CON	2	3	Aerial	GO95
CON	2	70922120	Aerial	GO95
TFS	2	NPT	Aerial	GO95
CON	2	58799337	Aerial	GO95

CON	2	73657573	Aerial	GO95
CON	2	15599	Aerial	GO95
CON	2	54838303	Aerial	GO95
CON	2	54979104	Aerial	GO95
CON	2	43313774	Aerial	GO95
CON	2	30	Aerial	GO95
CON	2	139665	Aerial	GO95
CON	2	10	Aerial	GO95
CON	2	189426	Aerial	GO95
CON	2	155456	Aerial	GO95
CON	2	61997791	Aerial	GO95
CON	2	64369294	Aerial	GO95
CON	2	180504	Aerial	GO95
CON	2	20	Aerial	GO95
CON	2	74597448	Aerial	GO95
CON	2	58968367	Aerial	GO95
TFS	2	25526806	Aerial	GO95
TFS	2	63505822	Aerial	GO95
TFS	2	66869277	Aerial	GO95
CON	2	69750933	Aerial	GO95
TFS	2	51307270	Aerial	GO95
TFS	2	49185999	Aerial	GO95
TFS	2	10139	Aerial	GO95
TFS	2	28186309	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	49116389	Aerial	GO95
TFS	2	65117040	Aerial	GO95
TFS	2	55375609	Aerial	GO95
TFS	2	65645735	Aerial	GO95
TFS	2	29317140	Aerial	GO95
TFS	2	34033715	Aerial	GO95
TFS	2	180534	Aerial	GO95
TFS	2	44046116	Aerial	GO95
TFS	2	64607226	Aerial	GO95
TFS	2	198675	Aerial	GO95
TFS	2	232264	Aerial	GO95
TFS	2	15775	Aerial	GO95
TFS	2	55303855	Aerial	GO95
TFS	2	15806	Aerial	GO95
TFS	2	65645735	Aerial	GO95
TFS	2	155462	Aerial	GO95
TFS	2	31146508	Aerial	GO95
TFS	2	158108	Aerial	GO95
TFS	2	183269	Aerial	GO95

TFS	2	49086639	Aerial	GO95
TFS	2	19947804	Aerial	GO95
TFS	2	77625889	Aerial	GO95
CON	2	05609620	Aerial	GO95
TFS	2	27	Aerial	GO95
TFS	2	201369	Aerial	GO95
TFS	2	15688	Aerial	GO95
TFS	2	31656461	Aerial	GO95
TFS	2	77290626	Aerial	GO95
TFS	2	57595866	Aerial	GO95
TFS	2	6071812	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	22123953	Aerial	GO95
TFS	2	248811	Aerial	GO95
TFS	2	52857832	Aerial	GO95
TFS	2	290840	Aerial	GO95
TFS	2	01566842	Aerial	GO95
TFS	2	34676070	Aerial	GO95
TFS	2	10696236	Aerial	GO95
TFS	2	50978164	Aerial	GO95
CON	2	49116389	Aerial	GO95
TFS	2	55076008	Aerial	GO95
TFS	2	57606234	Aerial	GO95
CON	2		Aerial	GO95
TFS	2			GO95
CON	2		Aerial	GO95
CON	2	51	Aerial	GO95
CON	2	008831	Aerial	GO95
CON	2	1	Aerial	GO95
CON	2	24	Aerial	GO95
TFS	2	SPAN	Aerial	GO95
TFS	2	SPAN	Aerial	GO95
CON	2	003206	Aerial	GO95
TFS	2	3	Aerial	GO95
TFS	2	SPAN	Aerial	GO95
CON	2	NPT	Aerial	GO95
CON	2	1501	Aerial	GO95
CON	2	1457	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	875	Aerial	GO95
TFS	2	10	Aerial	GO95
TFS	2	176	Aerial	GO95
TFS	2	23	Aerial	GO95
TFS	2	SPAN	Aerial	GO95

TFS	2	001099	Aerial	GO95
TFS	2	4	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	21	Aerial	GO95
ENG	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	SPAN	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2		Aerial	GO95
CON	2			GO95
CON	2	NPT	Aerial	GO95
CON	2	7	Aerial	GO95
CON	2	15362	Aerial	GO95
CON	2	NPT	Aerial	GO95
CON	2	6	Aerial	GO95
CON	2	13	Aerial	GO95
CON	2	120034930	Aerial	GO95
CON	2	SPAN	Aerial	GO95
TFS	2	178-5	Aerial	GO95
CON	2	13365	Aerial	GO95
CON	2	80557	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	80557	Aerial	GO95
TFS	2	SPAN	Aerial	GO95
TFS	2	SPAN	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	24	Aerial	GO95
TFS	2	39	Aerial	GO95
TFS	2	15	Aerial	GO95
TFS	2	8	Aerial	GO95
TFS	2	069424	Aerial	GO95
TFS	2	6	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	200111	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	SPAN	Aerial	GO95
TFS	2	NPT	Aerial	GO95
CON	2	358-1	Aerial	GO95

CON	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
CON	2	120008286	Aerial	GO95
CON	2	13258	Aerial	GO95
TFS	2	11448	Aerial	GO95
TFS	2	322	Aerial	GO95
CON	2	16837	Aerial	GO95
CON	2	7	Aerial	GO95
TFS	2	NPT	Aerial	GO95
CON	2	055339	Aerial	GO95
TFS	2	15339	Aerial	GO95
TFS	2	24B7	Aerial	GO95
TFS	2	052137	Aerial	GO95
TFS	2	052150	Aerial	GO95
TFS	2	055693	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	15938	Aerial	GO95
TFS	2	NPT	Aerial	GO95
ENG	2	120238754	Aerial	GO95
CON	2		Aerial	GO95
CON	3	NPT	Aerial	GO95
TFS	3	15473	Aerial	GO95
CON	3	10	Aerial	GO95
TFS	3	39	Aerial	GO95
TFS	3	16-3	Aerial	GO95
CON	3	19	Aerial	BPC
CON	3	NPT	Aerial	GO95
TFS	3	5	Aerial	GO95
CON	3	17	Aerial	GO95
TFS	3	937	Aerial	GO95
CON	3	8	Aerial	GO95
TFS	3	9	Aerial	GO95
CON	3	NPT	Aerial	GO95
TFS	3	35	Aerial	GO95
TFS	3	206	Aerial	GO95
TFS	3	2	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	411	Aerial	GO95
TFS	3	934	Aerial	GO95
TFS	3	16	Aerial	GO95
TFS	3	411	Aerial	GO95
TFS	3	25-5	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	933	Aerial	GO95

CON	3	NPT	Aerial	BPC
CON	3	120255112	Aerial	GO95
TFS	3	87	Aerial	GO95
CON	3	NPT	Aerial	GO95
TFS	3	995	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	981	Aerial	GO95
CON	3	NPT	Aerial	GO95
TFS	3	3	Aerial	GO95
TFS	3	NPT	Aerial	GO95
CON	3	15	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	1050392	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	1050387	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	5B2	Aerial	GO95
TFS	3	NPT	Aerial	GO95
CON	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	110340507	Aerial	GO95
TFS	3	4	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	15	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	998	Aerial	GO95
TFS	3	NPT	Aerial	GO95
CON	3	15519	Aerial	GO95
CON	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	897	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	5-May	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	44	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	120173835	Aerial	GO95
TFS	3	2	Aerial	GO95

TFS	3	3B3	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	15473	Aerial	GO95
TFS	3	120157162	Aerial	GO95
TFS	3	10	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	076292	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	854	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	15433	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	NPT	Aerial	GO95
TFS	3	31	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	12	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	50	Aerial	GO95
TFS	2		Aerial	GO95
CON	3	120782959	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	53	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	120763452	Aerial	GO95
CON	3	48	Aerial	GO95
CON	3	063196	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	36	Aerial	GO95

CON	3	NPT	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	110532461	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	14325	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	120238624	Aerial	GO95
ENG	3	NPT	Aerial	GO95
CON	3	120763452	Aerial	GO95
CON	3	12571B6	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	301	Aerial	GO95
TFS	3	120769527	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
CON	3	409	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	120238624	Aerial	GO95
TFS	3	120030223	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	4	Aerial	GO95
TFS	3	720	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	13255	Aerial	GO95
TFS	3	4	Aerial	GO95
TFS	3	12078742	Aerial	GO95
TFS	3	120182150	Aerial	GO95
CON	3	04646098	Aerial	GO95
CON	3	40480379	Aerial	GO95
CON	3	48489570	Aerial	GO95
CON	3	23329308	Aerial	GO95
TFS	3	61299930	Aerial	GO95
ENG	3	NPT	Aerial	GO95

TFS	3	82012105	Aerial	GO95
ENG	3	45185897	Aerial	GO95
TFS	3	65264749	Aerial	GO95
TFS	3	87304135	Aerial	GO95
TFS	3	78786017	Aerial	GO95
TFS	3	59615513	Aerial	GO95
TFS	3	24434406	Aerial	GO95
TFS	3	04514717	Aerial	GO95
TFS	3	54907508	Aerial	GO95
TFS	3	58945370	Aerial	GO95
TFS	3	03152897	Aerial	GO95
TFS	3	88289320	Aerial	GO95
TFS	3	47890505	Aerial	GO95
TFS	3	20701356	Aerial	GO95
TFS	3	96980109	Aerial	GO95
TFS	3	56594692	Aerial	GO95
TFS	3	71440178	Aerial	GO95
TFS	3	26641114	Aerial	GO95
TFS	3	71106204	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	49280505	Aerial	GO95
TFS	3	60694541	Aerial	GO95
TFS	3	04685593	Aerial	GO95
TFS	3	84294307	Aerial	GO95
TFS	3	05140379	Aerial	GO95
TFS	3	37349867	Aerial	GO95
TFS	3	29140496	Aerial	GO95
TFS	3	72784721	Aerial	GO95
TFS	3	10144707	Aerial	GO95
TFS	3	NPT	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	29	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	1076	Aerial	GO95
TFS	3	NPT	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	7	Aerial	GO95
ENG	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95

ENG	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	3	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	545	Aerial	GO95
TFS	3	120241801	Aerial	GO95
TFS	3	051665	Aerial	GO95
TFS	3	120153071	Aerial	GO95
TFS	3	123	Aerial	GO95
TFS	3	326	Aerial	GO95
TFS	3	049542	Aerial	GO95
TFS	3	13	Aerial	GO95
TFS	3	051947	Aerial	GO95
TFS	3	049541	Aerial	GO95
TFS	2		Aerial	GO95
CON	2	NPT	Aerial	GO95
TFS	2	291332	Aerial	GO95
TFS	2	291380	Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
CON	1			GO95
CON	2		Aerial	GO95
CON	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95

TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	3	2	Aerial	GO95
CON	3	Npt	Aerial	GO95
TFS	3	Tree	Aerial	GO95
TFS	3	Npt	Aerial	GO95
TFS	3	Npt	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	28	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT

CON	3	29	Aerial	GO95
TFS	3	Npt	Aerial	GO95
TFS	3	Npt	Aerial	GO95
TFS	3	NPT	Aerial	GO95

CON	3	NPT	Aerial	GO95
TFS	3	15649	Aerial	GO95
TFS	3	120764009	Aerial	GO95
TFS	3	22	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	120030241	Aerial	GO95
TFS	3	21	Aerial	GO95
TFS	3	Tree	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	12870	Aerial	GO95
CON	3	14495	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	53	Aerial	GO95
TFS	3	Npt	Aerial	GO95
TFS	3	110521581	Aerial	GO95
TFS	3	120767808	Aerial	GO95
TFS	3	12	Aerial	GO95
TFS	3	Tree	Aerial	GO95
TFS	3	4	Aerial	GO95
TFS	3	Npt	Aerial	GO95
TFS	3	374	Aerial	GO95
TFS	3	Tree	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	5	Aerial	GO95
TFS	3	Tree	Aerial	GO95
TFS	3	854	Aerial	GO95
TFS	3	16B6	Aerial	GO95
TFS	3	18B2	Aerial	GO95
TFS	3	2	Aerial	GO95
TFS	3	12808	Aerial	GO95
TFS	3	119	Aerial	GO95
TFS	3	8	Aerial	GO95

TFS	3	110478575	Aerial	GO95
TFS	3	1484	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	15831	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	120240366	Aerial	GO95
TFS	3	110525966	Aerial	GO95
TFS	3	986	Aerial	GO95
TFS	3	15	Aerial	GO95
TFS	3	10	Aerial	GO95
TFS	3	13390	Aerial	GO95
TFS	3	13325	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	13072	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	120181213	Aerial	GO95
TFS	3	120790858	Aerial	GO95
TFS	3	14012	Aerial	GO95
TFS	3	9	Aerial	GO95
TFS	3	191223	Aerial	GO95
TFS	3	110319681	Aerial	GO95
TFS	3	82	Aerial	GO95

CON	3	069195	Aerial	GO95
TFS	3	1	Aerial	GO95
TFS	3	3	Aerial	GO95
TFS	3	120851400	Aerial	GO95
TFS	3	A11110	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	069195	Aerial	GO95
TFS	3	120763457	Aerial	GO95
TFS	3	100	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	12442	Aerial	GO95
TFS	3	A11160	Aerial	GO95
TFS	3	2464	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	SM20863	Aerial	GO95
TFS	2	120934790	Aerial	GO95

TFS	3	Npt	Aerial	GO95
TFS	2	120871359	Aerial	GO95
TFS	3	30349871	Aerial	GO95
TFS	3	15229	Aerial	GO95
TFS	3	91754072	Aerial	GO95
TFS	3	12349	Aerial	GO95
TFS	3	08587626	Aerial	GO95
TFS	3	11383	Aerial	GO95
TFS	3	11100	Aerial	GO95
TFS	3	10144707	Aerial	GO95
TFS	3	64048290	Aerial	GO95
TFS	3	39120495	Aerial	GO95
TFS	3	04685593	Aerial	GO95
TFS	3	Npt	Aerial	GO95
TFS	3	99914605	Aerial	GO95
TFS	3	80234877	Aerial	GO95
TFS	3	87205079	Aerial	GO95
TFS	3	14020	Aerial	GO95
TFS	3	08659620	Aerial	GO95
TFS	3	88409152	Aerial	GO95
TFS	3	56594692	Aerial	GO95
TFS	3	57436712	Aerial	GO95
TFS	3	Npt	Aerial	GO95
TFS	3	Npt	Aerial	GO95
TFS	3	11677	Aerial	GO95
TFS	3	62272949	Aerial	GO95
TFS	3	12292	Aerial	GO95
TFS	3	96270228	Aerial	GO95
TFS	3	3855175	Aerial	GO95
TFS	3	87304135	Aerial	GO95
TFS	3	66644752	Aerial	GO95
TFS	3	11435	Aerial	GO95
TFS	3	24017387	Aerial	GO95
TFS	3	49064637	Aerial	GO95
TFS	3	308	Aerial	GO95
TFS	3	Npt	Aerial	GO95
TFS	3	73895140	Aerial	GO95
TFS	3	99754646	Aerial	GO95
TFS	3	4	Aerial	GO95
TFS	3	61008299	Aerial	GO95
TFS	3	1	Aerial	GO95
TFS	3	62634819	Aerial	GO95
TFS	3	13330	Aerial	GO95
TFS	3	14066	Aerial	GO95

TFS	3	26641114	Aerial	GO95
TFS	3	99628227	Aerial	GO95
TFS	3	95487016	Aerial	GO95
TFS	3	14096	Aerial	GO95
TFS	3	7	Aerial	GO95
TFS	3	11868	Aerial	GO95
TFS	3	13232	Aerial	GO95
TFS	3	14762	Aerial	GO95
TFS	3	36944700	Aerial	GO95
TFS	3	24434406	Aerial	GO95
TFS	3	1271	Aerial	GO95
TFS	3	68898193	Aerial	GO95
TFS	3	53470872	Aerial	GO95
TFS	3	14912	Aerial	GO95
TFS	3	94106549	Aerial	GO95
TFS	3	14114	Aerial	GO95
TFS	3	33043749	Aerial	GO95
TFS	3	33104335	Aerial	GO95
TFS	3	13231	Aerial	GO95
TFS	3	91223671	Aerial	GO95
TFS	3	15073	Aerial	GO95
TFS	3	47525319	Aerial	GO95
TFS	3	88881091	Aerial	GO95
TFS	3	32250951	Aerial	GO95
TFS	3	71440178	Aerial	GO95
TFS	3	59394685	Aerial	GO95
TFS	3	06176219	Aerial	GO95
TFS	3	50647998	Aerial	GO95
TFS	3	12032	Aerial	GO95
TFS	3	41186069	Aerial	GO95
TFS	3	12811	Aerial	GO95
TFS	3	77534701	Aerial	GO95
TFS	3	41275303	Aerial	GO95
TFS	3	12978	Aerial	GO95
TFS	3	12150	Aerial	GO95
TFS	3	29579810	Aerial	GO95
TFS	3	13908	Aerial	GO95
TFS	3	01966763	Aerial	GO95
TFS	3	74900795	Aerial	GO95
TFS	3	99186171	Aerial	GO95
TFS	3	37349867	Aerial	GO95
TFS	3	11598	Aerial	GO95
TFS	3	23073964	Aerial	GO95
TFS	3	11683	Aerial	GO95

TFS	3	14886	Aerial	GO95
TFS	3	63098915	Aerial	GO95
TFS	3	83252420	Aerial	GO95
CON	3	19	Aerial	GO95
CON	2	1	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	192998	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	192998	Aerial	GO95
TFS	3	110392742	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	183308	Aerial	GO95
TFS	3	120773386	Aerial	GO95
TFS	3	110460297	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
CON	3	NPT	Aerial	GO95
TFS	3	14016	Aerial	GO95
TFS	2	Npt	Aerial	GO95
TFS	2	31	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	Npt	Aerial	GO95
CON	3	NPT	Aerial	GO95

TFS	3	NPT	Aerial	GO95
CON	2	4	Aerial	GO95
TFS	2	Npt	Aerial	GO95
TFS	2	13298	Aerial	GO95
CON	3	NPT	Aerial	GO95
TFS	3	110521521	Aerial	GO95
TFS	2	Npt	Aerial	GO95
TFS	3	076404	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	3	Aerial	GO95
TFS	3	11028	Aerial	GO95
TFS	3	73	Aerial	GO95
TFS	3	120241378	Aerial	GO95
TFS	3	110525854	Aerial	GO95
TFS	2	4b	Aerial	GO95
TFS	3	120780704	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	14016	Aerial	GO95
TFS	3	12263	Aerial	GO95
TFS	2	2	Aerial	GO95
TFS	2	18334	Aerial	GO95
TFS	2	Npt	Aerial	GO95
TFS	3	120763469	Aerial	GO95
TFS	3	061751	Aerial	GO95
TFS	2	053669	Aerial	GO95
TFS	3	120768801	Aerial	GO95
TFS	2	66	Aerial	GO95
CON	3	13	Aerial	GO95
CON	3	65	Aerial	GO95
TFS	3	50	Aerial	GO95
TFS	3	49	Aerial	GO95
TFS	3	120804265	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	30	Aerial	GO95
TFS	3	45	Aerial	GO95
TFS	3	NPT	Aerial	GO95

CON	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	13159	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	33441	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	SM24705	Aerial	GO95
TFS	3	170	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	19672	Aerial	GO95
TFS	3	120182316	Aerial	GO95
TFS	3	120175631	Aerial	GO95
TFS	3	120175631	Aerial	GO95
CON	3	NPT	Aerial	GO95
CON	3	NPT	Aerial	GO95
ENG	3	8157	Aerial	GO95
TFS	2		Aerial	GO95
TFS	3	NPT	Aerial	GO95

TFS	3	6799	Aerial	GO95
TFS	3	120855002	Aerial	GO95
TFS	3	120811452	Aerial	GO95
TFS	3	120780986	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	120780717	Aerial	GO95
TFS	3	11762	Aerial	GO95
TFS	2	2	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	174	Aerial	GO95
TFS	3	15907	Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
CON	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
ENG	2	10172	Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
CON	1	13000		GO95
CON	1			GO95
CON	1	110525981		GO95
CON	1	3		GO95
CON	1	3n		GO95
CON	1			GO95
CON	1			GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
CON	1			GO95
TFS	1			GO95
TFS	2			GO95
TFS	2			GO95
TFS	2			GO95
TFS	2			GO95
TFS	2	009974	Aerial	GO95
TFS	2	009346	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95

TFS	2	NPT	Aerial	GO95
TFS	2	007447	Aerial	GO95
TFS	2	009984	Aerial	GO95
TFS	2	009991	Aerial	GO95
TFS	2	009038	Aerial	GO95
TFS	2	009910	Aerial	GO95
TFS	2	008534	Aerial	GO95
TFS	2	008526	Aerial	GO95
TFS	2	007522	Aerial	GO95
TFS	2	008504	Aerial	GO95
TFS	2	008656	Aerial	GO95
TFS	2	008807	Aerial	GO95
TFS	2	007103	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	008604	Aerial	GO95
TFS	2	008980	Aerial	GO95
TFS	2	007108	Aerial	GO95
TFS	2	007134	Aerial	GO95
TFS	2	008994	Aerial	GO95
TFS	2			GO95
TFS	2			GO95
TFS	1			GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	061381	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	069828	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95

TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	SM20870	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	19804	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
ENG	3	110321528	Aerial	GO95
TFS	3	112	Aerial	GO95
TFS	3	110525881	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	110498692	Aerial	GO95
TFS	2		Aerial	GO95
TFS	2	6	Aerial	GO95
ENG	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	120773411	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	14907	Aerial	GO95
TFS	3	118240	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
ENG	3	1	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	060607	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	060061	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	13619	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	2	Aerial	GO95
TFS	3	19224	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	257	Aerial	GO95
TFS	3	602	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	600	Aerial	GO95

TFS	3	611	Aerial	GO95
TFS	3	12612B3	Aerial	GO95
TFS	3	5	Aerial	GO95
TFS	3	120934600	Aerial	GO95
TFS	3	120934600	Aerial	GO95
TFS	3	NPT	Aerial	GO95
ENG	3	9	Aerial	GO95
ENG	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	120186641	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
ENG	3	NPT	Aerial	GO95
ENG	3	NPT	Aerial	GO95
TFS	3	120773570	Aerial	GO95
TFS	3	NPT	Aerial	GO95
ENG	3	15745	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	120803270	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2		Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	121073114	Aerial	GO95
TFS	3	120858890	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	228411	Aerial	GO95
TFS	3	118240	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	13560	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2		Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95

TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	120157737	Aerial	GO95
TFS	2	120238603	Aerial	GO95
TFS	2	120238758	Aerial	GO95
TFS	2	13639776	Aerial	GO95
TFS	2	06766371	Aerial	GO95
TFS	2	J-62259	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	47673596	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	29579810	Aerial	GO95
TFS	3	97098844	Aerial	GO95
TFS	3	92936101	Aerial	GO95
TFS	3	53986056	Aerial	GO95
TFS	3	05370570	Aerial	GO95
TFS	3	08559947	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	89569303	Aerial	GO95
TFS	2	08789150	Aerial	GO95
TFS	3	63587352	Aerial	GO95
TFS	2	248875	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	51959649	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	18890233	Aerial	GO95
TFS	2	11979727	Aerial	GO95
TFS	2	10149674	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	158147	Aerial	GO95
TFS	2	158146	Aerial	GO95
TFS	2	140185	Aerial	GO95
TFS	2	176730	Aerial	GO95
TFS	2	248873	Aerial	GO95
TFS	2	218342	Aerial	GO95
TFS	2	216397	Aerial	GO95
TFS	2	206098	Aerial	GO95
CON	2	18930924	Aerial	GO95
CON	2	31823155	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	64738282	Aerial	GO95
TFS	2	249306	Aerial	GO95
TFS	2	232264	Aerial	GO95
TFS	2	248811	Aerial	GO95

TFS	2	249373	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	45117509	Aerial	GO95
TFS	2	248861	Aerial	GO95
TFS	2	232363	Aerial	GO95
TFS	2	216386	Aerial	GO95
TFS	3	81829827	Aerial	GO95
TFS	3	83969484	Aerial	GO95
TFS	3	79808981	Aerial	GO95
TFS	2	135019	Aerial	GO95
TFS	2	248968	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	37080688	Aerial	GO95
TFS	3	13120495	Aerial	GO95
TFS	3	32250951	Aerial	GO95
TFS	3	26641114	Aerial	GO95
TFS	3	20701356	Aerial	GO95
TFS	3	18895307	Aerial	GO95
TFS	3	12166109	Aerial	GO95
TFS	3	60694541	Aerial	GO95
TFS	3	62834694	Aerial	GO95
TFS	3	91814337	Aerial	GO95
TFS	3	87304135	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	62256147	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	51615134	Aerial	GO95
TFS	3	24017387	Aerial	GO95
TFS	3	43491167	Aerial	GO95
TFS	3	96305611	Aerial	GO95
TFS	3	08815206	Aerial	GO95
TFS	3	96185526	Aerial	GO95
TFS	3	24176558	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	57436712	Aerial	GO95
TFS	3	07267122	Aerial	GO95
TFS	3	671154609	Aerial	GO95
TFS	3	55626056	Aerial	GO95
TFS	3	56455469	Aerial	GO95
TFS	3	86261183	Aerial	GO95
TFS	2	176631	Aerial	GO95
TFS	2	NPT	Aerial	GO95

TFS	2	NPT	Aerial	GO95
TFS	3	65618391	Aerial	GO95
TFS	3	73609738	Aerial	GO95
TFS	3	62272949	Aerial	GO95
TFS	3	61782765	Aerial	GO95
TFS	3	74900795	Aerial	GO95
TFS	3	01905688	Aerial	GO95
TFS	3	76337141	Aerial	GO95
TFS	3	73016459	Aerial	GO95
TFS	3	83606531	Aerial	GO95
TFS	3	54907508	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	63098915	Aerial	GO95
TFS	3	64048290	Aerial	GO95
TFS	3	68898193	Aerial	GO95
TFS	3	92007139	Aerial	GO95
TFS	3	74029797	Aerial	GO95
TFS	3	71440178	Aerial	GO95
TFS	3	80661199	Aerial	GO95
TFS	3	29140496	Aerial	GO95
TFS	3	21050746	Aerial	GO95
TFS	3	89752264	Aerial	GO95
TFS	2	19456191	Aerial	GO95
TFS	3	37349867	Aerial	GO95
TFS	3	48154729	Aerial	GO95
TFS	3	49064637	Aerial	GO95
TFS	3	52206864	Aerial	GO95
TFS	3	59723912	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	7884787	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	25526806	Aerial	GO95
TFS	3	01975972	Aerial	GO95
TFS	3	78786071	Aerial	GO95
TFS	3	54597144	Aerial	GO95
TFS	3	58594069	Aerial	GO95
TFS	3	62764024	Aerial	GO95
TFS	2	33116403	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	64800510	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95

TFS	3	96270228	Aerial	GO95
TFS	3	78334270	Aerial	GO95
TFS	3	66800443	Aerial	GO95
TFS	3	65390506	Aerial	GO95
TFS	3	54830887	Aerial	GO95
TFS	3	6446541	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	92216317	Aerial	GO95
TFS	3	93336400	Aerial	GO95
TFS	3	91730269	Aerial	GO95
TFS	3	91086133	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	44877839	Aerial	GO95
TFS	3	34868473	Aerial	GO95
TFS	3	54368622	Aerial	GO95
TFS	3	46737041	Aerial	GO95
TFS	3	42678308	Aerial	GO95
TFS	3	56198320	Aerial	GO95
TFS	3	77534701	Aerial	GO95
TFS	3	66644752	Aerial	GO95
TFS	3	59394685	Aerial	GO95
TFS	3	91495828	Aerial	GO95
TFS	3	66747956	Aerial	GO95
TFS	3	36944700	Aerial	GO95
TFS	3	43924820	Aerial	GO95
TFS	3	41186069	Aerial	GO95
TFS	3	08659620	Aerial	GO95
TFS	3	80742174	Aerial	GO95
TFS	3	94106549	Aerial	GO95
TFS	3	03275288	Aerial	GO95
TFS	3	39070853	Aerial	GO95
TFS	3	37790699	Aerial	GO95
TFS	3	38585175	Aerial	GO95
TFS	3	44254204	Aerial	GO95
TFS	3	01994477	Aerial	GO95
TFS	3	00344654	Aerial	GO95
TFS	3	54374707	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	76175879	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	291849	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	85515513	Aerial	GO95
TFS	3	77873434	Aerial	GO95

TFS	3	78253639	Aerial	GO95
TFS	3	83773395	Aerial	GO95
TFS	3	85483153	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	62634819	Aerial	GO95
TFS	3	62925394	Aerial	GO95
TFS	3	71814383	Aerial	GO95
TFS	2	46536129	Aerial	GO95
CON	2	36186179	Aerial	GO95
TFS	2	20916158	Aerial	GO95
TFS	3	58522357	Aerial	GO95
TFS	2	33258604	Aerial	GO95
TFS	2	33258604	Aerial	GO95
TFS	3	59615513	Aerial	GO95
TFS	2	NPT	Aerial	GO95
CON	3	72265840	Aerial	GO95
TFS	3	NPT	Aerial	GO95
CON	2	NPT	Aerial	GO95
TFS	3	36293762	Aerial	GO95
TFS	3	97154076	Aerial	GO95
TFS	3	33104335	Aerial	GO95
TFS	3	49634616	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	291382	Aerial	GO95
TFS	3	73895140	Aerial	GO95
CON	2	NPT	Aerial	GO95
CON	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
CON	2	121035	Aerial	GO95
CON	2	88186626	Aerial	GO95
TFS	3	54019784	Aerial	GO95
CON	3	NPT	Aerial	GO95
TFS	3	45878968	Aerial	GO95
TFS	3	52828691	Aerial	GO95
CON	2	269506	Aerial	GO95
TFS	3	05100619	Aerial	GO95
TFS	3	97050560	Aerial	GO95
TFS	3	05536355	Aerial	GO95
TFS	3	0196763	Aerial	GO95
TFS	3	98450516	Aerial	GO95
TFS	3	06176219	Aerial	GO95
CON	3	70544580	Aerial	GO95
TFS	2	121350	Aerial	GO95
TFS	2	121348	Aerial	GO95

TFS	2	NPT	Aerial	GO95
CON	2	11390820	Aerial	GO95
TFS	2	290840	Aerial	GO95
TFS	2	201375	Aerial	GO95
CON	2	176745	Aerial	GO95
TFS	2	244300	Aerial	GO95
CON	2	61287025	Aerial	GO95
TFS	3	02413569	Aerial	GO95
TFS	2	57606234	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	01272285	Aerial	GO95
CON	2	140139	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	58276885	Aerial	GO95
TFS	2	151409	Aerial	GO95
TFS	2	20535968	Aerial	GO95
TFS	2	66588487	Aerial	GO95
TFS	2	66538685	Aerial	GO95
CON	2	201295	Aerial	GO95
TFS	2	201294	Aerial	GO95
TFS	2	68768264	Aerial	GO95
TFS	2	72308266	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	60618292	Aerial	GO95
TFS	2	158105	Aerial	GO95
CON	2	244264	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	189343	Aerial	GO95
TFS	2	183266	Aerial	GO95
TFS	3	99914605	Aerial	GO95
CON	3	53314867	Aerial	GO95
TFS	2	72715740	Aerial	GO95
TFS	2	70475718	Aerial	GO95
TFS	2	08735981	Aerial	GO95
TFS	2	11556036	Aerial	GO95
TFS	2	12616175	Aerial	GO95
TFS	2	63916135	Aerial	GO95
TFS	2	10696236	Aerial	GO95
TFS	2	24006402	Aerial	GO95
TFS	3	80934608	Aerial	GO95
TFS	3	80934608	Aerial	GO95
CON	2	10770695	Aerial	GO95
CON	2	10350572	Aerial	GO95

TFS	2	10380412	Aerial	GO95
TFS	2	NPT	Aerial	GO95
CON	2	J76355	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
CON	2	NPT	Aerial	GO95
TFS	2	21343596	Aerial	GO95
TFS	2	26663982	Aerial	GO95
TFS	2	32403705	Aerial	GO95
TFS	2	NPT	Aerial	GO95
CON	2	167876	Aerial	GO95
TFS	2	180538	Aerial	GO95
CON	2	212371	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	79012554	Aerial	GO95
TFS	3	77922918	Aerial	GO95
CON	2	68390040	Aerial	GO95
TFS	2	290035	Aerial	GO95
TFS	2	115518	Aerial	GO95
TFS	3	83045798	Aerial	GO95
TFS	2	161170	Aerial	GO95
TFS	2	81249061	Aerial	GO95
TFS	2	79239056	Aerial	GO95
TFS	2	93360158	Aerial	GO95
TFS	2	77290626	Aerial	GO95
TFS	2	684508117	Aerial	GO95
TFS	3	55934215	Aerial	GO95
TFS	2	0093941	Aerial	GO95
CON	2	45013785	Aerial	GO95
CON	2	43313774	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
CON	2	55527334	Aerial	GO95
TFS	2	45976520	Aerial	GO95
TFS	2	45976520	Aerial	GO95
CON	2	167975	Aerial	GO95
TFS	2	161029	Aerial	GO95
TFS	2	180503	Aerial	GO95
TFS	3	61008299	Aerial	GO95
CON	2	158122	Aerial	GO95
TFS	2	158139	Aerial	GO95
CON	2	98016616	Aerial	GO95
TFS	2	NPT	Aerial	GO95

TFS	3	75057532	Aerial	GO95
TFS	2	57310544	Aerial	GO95
TFS	2	54908254	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	10049540	Aerial	GO95
TFS	2	68329148	Aerial	GO95
TFS	3	79027621	Aerial	GO95
CON	2	158123	Aerial	GO95
TFS	2	235714	Aerial	GO95
TFS	2	NPT	Aerial	GO95
CON	2	93736587	Aerial	GO95
TFS	3	57339785	Aerial	GO95
TFS	2	NPT	Aerial	GO95
CON	2	12927027	Aerial	GO95
CON	2	12956626	Aerial	GO95
TFS	2	15027272	Aerial	GO95
TFS	3	99628227	Aerial	GO95
TFS	3	86507323	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	155462	Aerial	GO95
TFS	3	95487016	Aerial	GO95
TFS	3	61208996	Aerial	GO95
TFS	3	60749220	Aerial	GO95
TFS	3	91328394	Aerial	GO95
TFS	3	8379085	Aerial	GO95
TFS	3	49280505	Aerial	GO95
TFS	3	53410446	Aerial	GO95
TFS	3	46030449	Aerial	GO95
TFS	2	96269468	Aerial	GO95
TFS	2	96249629	Aerial	GO95
TFS	2	88629156	Aerial	GO95
TFS	3	50383447	Aerial	GO95
TFS	3	72873864	Aerial	GO95
TFS	2	33506527	Aerial	GO95
TFS	2	33506528	Aerial	GO95
TFS	2	29317140	Aerial	GO95
TFS	2	41727067	Aerial	GO95
TFS	2	5078164	Aerial	GO95
TFS	2	8359114	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2		Aerial	GO95

TFS	3	19	Aerial	GO95
TFS	3	13	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	076670	Aerial	GO95
TFS	3	076670	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	120934798	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	007970	Aerial	GO95
TFS	2	007973	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	182386	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
ENG	3	120859678	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	120137926	Aerial	GO95
TFS	3	063047	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	120089431	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95

TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	080988	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	063051	Aerial	GO95
TFS	3	120859754	Aerial	GO95
TFS	3	063013	Aerial	GO95
TFS	3	063015	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	121057470	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	120558151	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	120558122	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	6	Aerial	GO95
TFS	3	152410	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	120855236	Aerial	GO95
TFS	3	063106	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	163409	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2		Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	080900	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	066074	Aerial	GO95
TFS	3	NPT	Aerial	GO95

TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
ENG	3	NPT	Aerial	GO95
ENG	3	NPT	Aerial	GO95
TFS	3	121205884	Aerial	GO95
ENG	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
ENG	3	NPT	Aerial	GO95
TFS	3	121206539	Aerial	GO95
ENG	3	121205931	Aerial	GO95
TFS	3	121206554	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	121206523	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	121298546	Aerial	GO95
TFS	3	120826576	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	120826593	Aerial	GO95
TFS	3	120565764	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	121206568	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	121205935	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	121298333	Aerial	GO95
ENG	3	NPT	Aerial	GO95
TFS	3	121206551	Aerial	GO95
ENG	3	NPT	Aerial	GO95
TFS	3	121205993	Aerial	GO95
TFS	3	121205867	Aerial	GO95
TFS	3	121215060	Aerial	GO95

TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	034578	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2		Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	120118593	Aerial	GO95
TFS	3	16481	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	16932	Aerial	GO95
TFS	2	16947	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	110362545	Aerial	GO95
TFS	3	120801034	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	720	Aerial	GO95
TFS	2	6147	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	18910	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	632	Aerial	GO95

TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	17141	Aerial	GO95
TFS	2	7273	Aerial	GO95
TFS	2	17005	Aerial	GO95
TFS	2	16846	Aerial	GO95
TFS	2	16816	Aerial	GO95
TFS	2	120767789	Aerial	GO95
TFS	2	11858	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	120934585	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	069417	Aerial	GO95
TFS	2	16784	Aerial	GO95
TFS	2	16725	Aerial	GO95
TFS	3	15462	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	110535290	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	16952	Aerial	GO95
TFS	2	16952	Aerial	GO95
TFS	2	67	Aerial	GO95
TFS	2	16851	Aerial	GO95
TFS	2	12	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	46	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	16741	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	13751	Aerial	GO95

TFS	2	NPT	Aerial	GO95
TFS	3	120036110	Aerial	GO95
TFS	2	17241	Aerial	GO95
TFS	2	191225	Aerial	GO95
TFS	2	17425	Aerial	GO95
TFS	2	17425	Aerial	GO95
TFS	2	17598	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	13509	Aerial	GO95
TFS	2	1760	Aerial	GO95
TFS	2	16320	Aerial	GO95
TFS	2	16243	Aerial	GO95
TFS	2	16194	Aerial	GO95
TFS	2	16194	Aerial	GO95
TFS	3	1465	Aerial	GO95
TFS	2	16399	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	8	Aerial	GO95
TFS	2	8B2	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	17457	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	18142	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95

TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	17060	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	17472	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	10639	Aerial	GO95
TFS	2	10396	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	055342	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	069363	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	16964	Aerial	GO95
TFS	2	16874	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	15437	Aerial	GO95
TFS	3	14132	Aerial	GO95
TFS	3	NPT	Aerial	GO95

TFS	3	LC80130	Aerial	GO95
TFS	3	110292507	Aerial	GO95
TFS	3	069490	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	11218	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	17475	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	17049	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	12877	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	12915	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	110319681	Aerial	GO95
TFS	3	069042	Aerial	GO95
TFS	2	18643	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	110478552	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	17060	Aerial	GO95
TFS	2	16927	Aerial	GO95
TFS	2	16647	Aerial	GO95
TFS	2	10B2	Aerial	GO95
TFS	2	16976	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	1021141	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	069045	Aerial	GO95
TFS	3	120871081	Aerial	GO95
TFS	3	120851393	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95

TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	6	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	052532	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	120030479	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	14098B8	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	069535	Aerial	GO95
TFS	2	16329	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	34219	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	120171207	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	120165673	Aerial	GO95
TFS	2	056491	Aerial	GO95
TFS	3	120763479	Aerial	GO95

TFS	3	13977	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	11404	Aerial	GO95
TFS	3	120561138	Aerial	GO95
TFS	3	120561138	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	110525778	Aerial	GO95
TFS	2	15106	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	16786	Aerial	GO95
TFS	3	120558025	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	120558063	Aerial	GO95
TFS	2	121016407	Aerial	GO95
TFS	2	058946	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	120868361	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	058931	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	LC2924	Aerial	GO95
TFS	3	15	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	110105248	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	1614	Aerial	GO95
TFS	3	NPT	Aerial	GO95

TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	110101739	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	121079166	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	056395	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	056402	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	110443085	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	120093622	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95

TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	053312	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	140	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	13100	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	200095	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	31566	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	052336	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	110432132	Aerial	GO95
TFS	2	110423000	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95

TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	110101651	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	LC25350	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	120972618	Aerial	GO95
TFS	2	120826246	Aerial	GO95
TFS	2	055083	Aerial	GO95
TFS	2	055083	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	16105	Aerial	GO95
TFS	2	6423	Aerial	GO95
TFS	2	15987	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	18395	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95

TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	052351	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	158537	Aerial	GO95
TFS	2	14555	Aerial	GO95
TFS	3	120561142	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	120768657	Aerial	GO95
TFS	3	120768657	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	14874	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	120561201	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	091019	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	10571	Aerial	GO95
TFS	2	40785	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	33817	Aerial	GO95
TFS	2		Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	250026	Aerial	GO95
TFS	2	138017	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95

TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	008832	Aerial	GO95
TFS	2	008830	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	003070	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	003162	Aerial	GO95
TFS	2	008848	Aerial	GO95
TFS	2	008844	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	008849	Aerial	GO95
TFS	2	004048	Aerial	GO95
TFS	2	003089	Aerial	GO95
TFS	2	001098	Aerial	GO95
TFS	2	003081	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95

TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	001075	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	160344	Aerial	GO95
TFS	2	66236	Aerial	GO95
TFS	2	155697	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	18589	Aerial	GO95
TFS	2	183062	Aerial	GO95
TFS	2	150577	Aerial	GO95
TFS	2	70890	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	050195	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	110506812	Aerial	GO95

TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	001229	Aerial	GO95
TFS	2	049850	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	1203160016	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	003075	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	120330100	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	120315972	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	145053	Aerial	GO95
TFS	2	150651	Aerial	GO95
TFS	2	186055	Aerial	GO95
TFS	2	006859	Aerial	GO95
TFS	2	006879	Aerial	GO95
TFS	2	006491	Aerial	GO95
TFS	2	006489	Aerial	GO95
TFS	2	006497	Aerial	GO95
TFS	2	C254R71	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	193563	Aerial	GO95
TFS	2	186063	Aerial	GO95
TFS	2	186176	Aerial	GO95
TFS	2	186179	Aerial	GO95
CON	2		Aerial	BPC
CON	2		Aerial	GO95

CON	2		Aerial	BPC
CON	2		Aerial	GO95
CON	2		Aerial	BPC
CON	2		Aerial	BPC
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
CON	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
CON	2		Aerial	BPC
TFS	2		Aerial	GO95
CON	2		Aerial	BPC
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
CON	2		Aerial	BPC
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
CON	2		Aerial	GO95
TFS	2		Aerial	GO95
CON	1	120181906		GO95
CON	1	36		BPC
TFS	2		Aerial	GO95
CON	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	3	365	Aerial	GO95
TFS	3	Npt	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	063067	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	3	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	8	Aerial	GO95
TFS	3	110498880	Aerial	GO95
TFS	3	NPT	Aerial	GO95

TFS	3	NPT	Aerial	GO95
TFS	3	120766541	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	120789427	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	120041231	Aerial	GO95
TFS	3	21-5	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3		Aerial	GO95
TFS	3	780	Aerial	GO95
TFS	3	120031945	Aerial	GO95
TFS	3	662	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	25	Aerial	GO95
TFS	3	28	Aerial	GO95
TFS	3	4	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	3	Aerial	GO95
TFS	3	6	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	24	Aerial	GO95
TFS	3	063153	Aerial	GO95
TFS	3	1	Aerial	GO95
TFS	3	1	Aerial	GO95
TFS	3	120183747	Aerial	GO95
TFS	3	13300	Aerial	GO95
TFS	3	2659B2	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	15649	Aerial	GO95
TFS	3	060674	Aerial	GO95
TFS	3	13951	Aerial	GO95
TFS	3	3	Aerial	GO95
TFS	3	1	Aerial	GO95
TFS	3	121030983	Aerial	GO95
TFS	3	1400	Aerial	GO95
TFS	3	120766527	Aerial	GO95
TFS	3	1	Aerial	GO95
TFS	3	120780968	Aerial	GO95

TFS	3	120764009	Aerial	GO95
TFS	3	NPT	Aerial	GO95
ENG	3	NPT	Aerial	GO95
ENG	3	120789427	Aerial	GO95
ENG	3	110323551	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	1051765	Aerial	GO95
TFS	3	110321529	Aerial	GO95
TFS	3	NPT	Aerial	GO95
ENG	3	npt	Aerial	GO95
TFS	3	46297497	Aerial	GO95
TFS	3	39204820	Aerial	GO95
TFS	3	57339785	Aerial	GO95
TFS	3	98864999	Aerial	GO95
TFS	3	76175879	Aerial	GO95
TFS	3	52828691	Aerial	GO95
TFS	3	64738282	Aerial	GO95
TFS	3	50670496	Aerial	GO95
TFS	3	6698701	Aerial	GO95
TFS	3	40734823	Aerial	GO95
TFS	3	66747956	Aerial	GO95
TFS	3	02183732	Aerial	GO95
TFS	3	08559947	Aerial	GO95
TFS	3	08559947	Aerial	GO95
TFS	3	89074627	Aerial	GO95
TFS	3	42678308	Aerial	GO95
TFS	3	43928422	Aerial	GO95
TFS	3	86507323	Aerial	GO95
TFS	3	86997181	Aerial	GO95
TFS	3	83510821	Aerial	GO95
TFS	3	17330941	Aerial	GO95
TFS	3	1	Aerial	GO95
TFS	3	121002598	Aerial	GO95
TFS	3	120362208	Aerial	GO95
TFS	3	42	Aerial	GO95
TFS	3	60805-78	Aerial	GO95
TFS	3	201	Aerial	GO95
TFS	3	498	Aerial	GO95
TFS	3	121019159	Aerial	GO95
TFS	3	120962134	Aerial	GO95
TFS	3	63	Aerial	GO95
TFS	3	npt	Aerial	GO95
TFS	3	npt	Aerial	GO95
TFS	2		Aerial	GO95

CON	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	365	Aerial	GO95
TFS	3	063067	Aerial	GO95
TFS	3	Npt	Aerial	GO95
ENG	2	P 17 Spenc	Aerial	GO95
ENG	2	8	Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2		Aerial	GO95
TFS	2	121298485		GO95
CON	2	120137926		GO95
CON	2	NPT		BPC
CON	2	NPT		GO95
TFS	2	120759725		GO95
CON	2	7		GO95
CON	2	121620473		GO95
CON	2	NPT		GO95
CON	3	75		BPC
TFS	3			GO95
CON	2	2		BPC
TFS	2	120034702		GO95
ENG	3	NPT	Aerial	GO95
CON	3	121699703		GO95
CON	2	20843		GO95
TFS	2	2479		GO95
TFS	3	36	Aerial	GO95
TFS	2	20796	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95

TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	180	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	NPT	Aerial	GO95
TFS	2	NPT	Aerial	GO95
TFS	3	21186	Aerial	GO95
TFS	3	13393	Aerial	GO95
CON	3	100009843		GO95
CON	2	103683053		GO95
CON	3	100014356		GO95
CON	3	100071498		GO95
CON	2		Aerial	GO95
CON	2	npt	Aerial	GO95
CON	2		Aerial	GO95
CON	2		Aerial	GO95
TFS	2		Aerial	GO95
CON	2		Aerial	GO95
CON	2		Aerial	GO95
CON	2		Aerial	GO95
CON	2		Aerial	GO95
CON	2		Aerial	GO95
CON	2		Aerial	GO95
CON	3	85068572	Aerial	GO95

TIX_CLOSEOUT_NARR

vc6131; drop down, reattached drop
;nh2812; PC-N; Tie in ground field completed by Contractor, riser and attachments completed

;sm4953; PC-N; Take down old drop from pole to trees

;ag2675;PC-N;Misc, needs trees cleared from cable, EK6957 to put digit in for removal

;rt9712;PC-N;Work completed
;sf8537;PC-Y;Rmvd dead tree off cable @P50- aka T50 HWY89;TN:5303544708

NH2812; WILLOW VALLEY RD SECTION THROW
;ek6957;PC-Y;Drop work;TN:2761304
;ek6957; PC-Y; Replace wet section; TN: 2761304
;sf8537;PC-Y;Removed abandoned asw,trimmed tree in span;TN:5309178926
;sf8537;PC-Y;Removed hazzard abandoned asw.;TN:5309178926

pg6512; Raised drop to correct go-95 height

cd5628; Per ticket request readjusted span to proper height

cd5628; Prer request, check level of drop as well as remove additional drop with an area.

cd5628; Per ticket raised up drop that was hanging low.

cd5628; Per ticket request raised up, low hanging wire

628; Per ticket, raised line to proper height, then per request of management, locate and rage equipment in gar

/ever, in initial connection at premises not able to be located higher, spoke to property owner, and asked not to

Aerial drop wires hanging from pole laying on the ground. Hazardous condition.
pg6512; pg6512; removed drop at pole,
JQ2645; REMOVE 2 DROPWIRES HANGING OFF POLE
DD6738; RESOLVE AERIAL DROP ISSUE
e. Pole transfer was done in the past. Relocated aerial pole mounted terminal. Cleaned up aerial drop wires anc
;dd6738; PC-Y; Remove single pair drop from aerial serving terminal; TN: Cbr
dd6738; dd6738; resolve no service affecting aerial drop issues
res hanging low at mid span in multiple locations. Removed 4ea. Single Pr aerial drop wires and cleaned up aer
;dd6738; PC-Y; Resolve aerial drop issues; TN: Cbr
dd6738; dd6738; resolve unused aerial drop issues
45; jh3145; Aerial drop wire hang from pole to the ground. Hazardous condition. Removed aerial drop wire from
DD6738; RESOLVE AERIAL DROP ISSUES
JQ2645; GEO LOCATION ADDR DOES NOT EXIST; NEITHER DOES POLE LEADS IN THE AREA
5; AERIAL DROP WIRES HANGING FROM POLE. REMOVED AERIAL DROP WIRE FROM POLE AND SERVING TERM
;dd6738; PC-Y; Aerial drop trouble resolved; TN: Cbr
;dd6738; PC-Y; Remove non service affecting aerial drops from serving terminal; TN: Cbr
DD6738; RESOLVE AERIAL DROP ISSUE
dd6738; dd6738; resolve non service affecting aerial drop issues
OP WIRE HANGING LOW FROM MID SPAN CLAMP. REMOVED AERIAL DROP WIRE FROM MID SPAN CLAMP AND
jh3145; jh3145; Aerial drop wire hanging on ground from pole. Removed aerial drop wire from pole.
Aerial drop wire hanging from pole laying on the ground.Hazardous condition. Removed aerial drop wire from p
dd6738; dd6738; resolve unused aerial drop issue at serving terminal
/ire hanging from mid span, connected at pole and terminal. Removed aerial drop wire from mid span and pole.
12; pg6512; removed cut drop and reconnected terminal to strand, made sure collars of terminal were correctl

dd6738; dd6738; resolve aerial drop issues from serving terminal
dd6738; dd6738; resolve aerial drop issues
jh3145; Aerial drop wire hanging down on ground from pole. Hazardous condition. Removed aerial drop wire fr
pg6512; pg6512; removed drop at pole, also raised drop to house on stone pine
;dd6738; PC-Y; Resolve unused aerial drop issue, remove aerial drop; TN: Cbr
jh3145; jh3145; Aerial drop wire hanging from pole. Remove aerial drop wire. GCAS down for 3 hours.
dd6738; dd6738; take down non service affecting aerial drops

;dd6738; PC-Y; Resolve aerial drop issues; TN: Cbr
FROM MID SPAN CLAMP. REMOVED AERIAL DROP WIRE FROM MID SPAN CLAMP, POLE, AND SERVING TERMI
jh3145; jh3145; Removed aerial drop wire hanging from mid span. Attach splice case to strand.
jh3145; jh3145; Aerial drop wire hanging low over driveway. Raised aerial drop wire for proper clearance.
;dd6738; PC-Y; Resolve aerial drop issues, remove drop from mid span and terminal; TN: Cbr
dd6738; dd6738; resolve unused aerial drop issues at serving terminal
pg6512; pg6512; removed drop hangin from pole, repaired splice with ends that were pulled out,
dd6738; dd6738; resolve aerial drop issues that are not being used
pg6512; pg6512; removed low hanging drop and corrected go 95 climbing splice violation on pole
;dd6738; PC-Y; Resolve multiple aerial drop issues; TN: Cbr
dd6738; dd6738; resolve unused aerial drop issue at serving terminal
;dd6738; PC-Y; Remove aerial drop from aerial serving terminal; TN: Cbr
;sm3126; PC-N; Removed dead asw
PG6512; REMOVED DISCONNECTED DROP FROM TREE

JQ2645; REMOVE DOWN DROPWIRE
pg6512; pg6512; removed broken cable at pole,
pg6512; pg6512; removed multiple drops on rio vista and ponderosa rd,
;dd6738; PC-Y; Resolve non used aerial drop issues at different locations; TN: Cbr
dd6738; dd6738; resolve aerial drop issues at serving terminal
dd6738; dd6738; resolve unused aerial drop issue at serving terminal

pg6512; pg6512; removed drop on pole and checked all go-95 codes
145; jh3145; Aerial drop wire hanging from pole. Removed aerial drop wire. Reattached buried drop wire with na
pg6512; pg6512; removed down cable near pole. Checked go95 codes at terminal,
;dd6738; PC-Y; Resolve aerial service drop issue; TN: Cbr
EMOVED DROP, ALSO ASSISTED MATT THALE ON A CABLE CUT REBUILD SPLICE OFF OF PROSSER DAM RD, AD
;sm3126; PC-N; Removed dead asw
Aerial drop wire hanging from pole, laying on the ground. Hazardous condition. Removed aerial drop wire from t
dd6738; dd6738; resolve aerial drop issues
pg6512; pg6512; attached cable to strand, raised drop to correct go-95 height,
jh3145; jh3145; Aerial drop wire hanging from midspan on rear cable lead. Removed aerial drop wire.
dd6738; dd6738; resolve unused aerial drop issues

6512; CHECKED ADDRESS FOR DOWNED CABLES OR OTHER GO 95 ISSUES, UNABLE TO FIND ANY ATT CORR
pg6512; pg6512; removed down drop at pole,

dd6738; dd6738; resolve unused aerial drop issue

145; Aerial drop wires hanging from mid span and laying on ground. Removed aerial drop wires from mid span a

, check hi adjustment, made the corrections. Noticed a couple additional mid span drops need to be cut down

cd5628; Per ticket, height adjustment, drove around to gab additional dead drops

6738; PC-Y; Resolve aeria drop issues, remove non used aerial drops from midspan and serving terminals; TN:

;dd6738; PC-Y; Remove unused non service affecting aerial drop from terminal; TN: Cbr

;sm3126; PC-N; Removed asw

jh3145; jh3145; Aerial drop wire hanging from mid span and attached to pole. Removed aerial drop wire.

on the ground. Hazardous condition. Needed bucket truck to remove aerial drop wire from pole. Technician ass

JQ2645; NO TELCO WIRES REMAIN ON POLE; CABLE CO WIRE STILL WRAPPED AROUND POLE

rop wire hanging from mid span cut hanging low. Removed aerial drop wire from mid span and prem. Person has

JQ2645; TREE BRANCH LAYING ON SPAN IS REM

;dd6738; PC-Y; Resolve aerial drop issues; TN: Cbr

pg6512; pg6512; removed low drop, checked terminal bonds, All tests ok

pg6512; pg6512; removed broken drop from pole and relished cable at terminal,

ıerial drop wires hanging from pole, laying on the ground. Hazardous condition. Removed aerial drop wire from p

3145; jh3145; Aerial drop wire hanging from pole on the ground. Removed aerial drop wire from pole and termin

DD6738; RESOLVE AERIAL DROP ISSUE

;sm3126; PC-N; Complete

pg6512; pg6512; removed drops at pole, checked go 95 codes at pole,

;dd6738; PC-Y; Resolve vegetation issue; TN: Cbr

M POLE ON THE GROUND. REMOVED AERIAL DROP WIRE FROM POLE . ASSISTED TECHNICIANS WITH SPLICIN

JQ2645; ALL DOWN DROPWIRES CLEAR

JQ2645; REMOVE AERIAL DR

JQ2645; REMOVE DOWN DROPWIRE

LTIPLE AERIAL DROP WIRES HANGING FROM POLE. REMOVED AERIAL DROP WIRES FROM POLE AND SERVINC

Aerial drop wire hanging from pole, laying on the ground. Hazardous condition. Removed aerial drop wire from p

dd6738; dd6738; resolve unused aerial drop issues

Aerial drop wires hanging from pole, laying on ground. Hazardous condition. Removed aerial drop wires from pc

dd6738; dd6738; remove tree limbs from on top of aeria cable

JQ2645; REF FOR TREE REMOVAL DIG 105042022

dd6738; dd6738; resolve aerial drop issue from aerial terminal
dd6738; dd6738; resolve aerial drop issues
DD6738; RESOLVE AERIAL DROP ISSUES

dd6738; dd6738; resolve aerial drop issues at aerial serving terminal
dd6738; dd6738; resolve aerial drop issue
;tl5296; PC-Y; All requested work complete
dd6738; dd6738; resolve aerial drop issues that are not being used
jh3145; jh3145; Aerial drop wire hanging from pole. Removed aerial drop wire from pole and terminal.
DD6738; RESOLVE AERIAL DROP ISSUES
dd6738; dd6738; resolve unused aerial drop issues at serving terminal
;dd6738; PC-Y; Resolve aerial drop issue; TN: Cbr
;tl5296; PC-Y; All work on ticket completed, also assist sm3126 on two tickets
JQ2645; UNPLOWED ROAD; NO ACCESS
;sm3126; PC-N; Task complete
pg6512; pg6512; down drop removed, terminal broken off strand, repaired,
; jh3145; Aerial drop wire hanging from pole on the ground. Hazardous condition. Removed aerial drop wire fror
PG6512; REMOVED LOW DROP TO HOUSES CHECKED GO 95 AT TERMINALS MARKED
l5; jh3145; Aerial drop wire hanging from pole due to pole transfer. Removed aerial drop wire from pole and terr
remove aerial drop wire hanging from pole laying on the ground. Hazardous condition. Removed aerial drop wir

al drop wire hanging from pole due to pole transfer. Removed aerial drop wire pole and terminal. Snow in the ar
dd6738; dd6738; resolve aerial drop issues not being used

;sc2675;PC-N;Rmvd tree from cable

;mm9751;PC-Y;Bpc 011602492,tree trimming
;mm9751;PC-N;Pg&e tree contractor,no trouble found,advised mg7218

/;ABWS 011600929. Needs outside contractor for tree removal. Tree pressing on cable pole starting to lean;TN:
: #011600284. Needs outside contractor for tree and vegetation management. See notes.P50 to P55 Hwy 70, cı

;sf8537; PC-Y; Rmvd abandoned asw; TN: 5309178926
;sf8537; PC-Y; Rmvd abandoned asw.; TN: 5309178926
;tl3147; PC-Y; Asst with fiber installs ; TN: 0000000000
;sf8537; PC-Y; Rmvd abandoned asw.; TN: 5309178926
;sf8537; PC-Y; No access,road closed at bridge.; TN: 5593976286
;sf8537; PC-Y; Rmvd abandoned asw.; TN: 5309178926

sf8537; Ntf,down guy on pole is TV COAX network.
;sf8537; PC-Y; Work complete; TN: 5309178926
;sf8537; PC-Y; Rmvd abandoned asw.; TN: 5309178926
;sf8537; PC-Y; No access,road closed; TN: 5593976286
sf8537; no access,road closed,worked P44 Alta,rmvd asw and securder term

;dm6529;PC-N;removed trees from cable
;dm6529;PC-N;Removed tree from cable
MM9751; RECONNECTED AERIAL DROP,18 FT HEI
MM9751; RECONNECTED AERIAL DROP,18FT CLEARANCE
537;PC-Y;Tree and vegetation clearance created for drop replacement,will open new ticket for drop;TN:530283

;mr1213;PC-N;PREFEILD CMOLT

95; PC-Y; Property owner to hire tree trimming co.,tree not damaging ATT cable,big mulberry overgrown; TN: 47
;md4156; PC-N; Resolved go95 condition at Mark it location
jm1295; jm1295; tree removed Allison ranch rd.and king street
qb6851; qb6851; all lines clear of tree limbs
;nh2812; PC-N; Job complete, locked gate at east side of property. Close per ek6957
;ek6957; PC-Y; Temp repair for road clearance. Notified line crew. Needs perm repair asap ; TN: 2761304
;md4156; PC-N; Cleared mark it drop go95
jm1295; jm1295; downed bypass corrected at Kubich 3way
vc6131; vc6131; drop hanging low, reattached drop highr
vc6131; vc6131; branches on drop,drop down,, trimmed branches, removed dead dop
;jm1295; PC-Y; Raised drop to prem,no access; TN: 4773022
;jm1295; PC-Y; Removed l.l.drop,no access to side of home; TN: 4773022
;jm1295; PC-Y; Removed drop to pole; TN: 4773022
dm820t; dm820t; raised low hanging drop by 4 and wrecked out cut drop at 1297 Nevada city hwy.
to city park 315 Colfax Ave GV, replace term at 315 colfax ave, mod 25 Pr, damage claim to be submitted, linec
rw5286; rw5286; rebuilt splice;
;md4156; PC-N; Removed low drop at mark it location
;md4156; PC-N; G095 cable issue resolved
812; PC-N; MEB, rmv aerial drop wrapped at base of pole 406 main st GV, move airpressure equipment onto ve

;ag2675;PC-Y;Misc, remove toppled tree branch off cable,

;rt9712;PC-N;Job complete
;ms7970;PC-N; Foliage cleared from specified pole.

;bl1527;PC-Y;Clear vegetation and trees from around pole.;TN:530

;om3842;PC-N;Adjusted drop to house. Moved line away from pge line. Work complete
erial drop clearance at 10681 Rambling Rd GV per UPS complaint, rmv drop per GO95 issue at 11281 Sunset W
;jm1295; PC-Y; Downed bypass reconnected,p4 bixler; TN: 4773022
;nh2812; PC-N; Go95 dwn drop aerial, rmv to clear go95 infrac. All work complete
NH2812; CUST CALL FOR MODEM ACCESS TO CHANGE SETTINGS, OLD OAK TRL GV.
vc6131; vc6131; cable hanging low, wrecked out cable, reattached cable
os, verify vacant and rmv to clear G095 issue. Check grnd field DONNA WY Penn Valley, contact contractor abo
QB6851; REATTACHED AND RAISED MULTIPLE DROPS

;jh2859;PC-Y;Bpc complete

;ac1532;PC-N;Remove trees from cable at 13317 la Porte rd
;cc2745;PC-N;Removed t we from cable

;cc2745;PC-Y;Cleared branch around cable

;ac1532;PC-N;Made dig request for tree removal

;cc2745;PC-Y;Removed limbs from cable

;cc2745;PC-Y;Removed tree from cable
;ac1532;PC-N;Remove trees from cable at 12177 la Porte rd
;cc2745;PC-Y;Needs tree removed dig # 011691962
;ac1532;PC-N;Remov tree from cable at 9256 la Porte rd
;ac1532;PC-N;Remove trees from cable at 13989 la Porte rd
;ac1532;PC-N;Remove tree from cable at 9256 la Porte rd
;ac1532;PC-N;Remove tree from cable at 18945 New York flat rd
;ac1532;PC-N;Clear tree from cable at 13989 la Porte rd
;cc2745;PC-Y;Removed trees from cable
;ac1532;PC-N;Remove tree from cable at p 2 old Knox rd
;ac1532;PC-N;Remove tree from cable at 9256 la Porte rd

;ac1532;PC-N;Remove trees from cable at 8742 la Porte rd

;ac1532;PC-N;Remove tree from cable at 9827 la Porte rd
;ac1532;PC-N;Remove tree from cable at 18644 New York flat rd
;cc2745;PC-Y;Tree needs removed from cable
;ac1532;PC-N;Remove tree from cable at 9692 la Porte rd

;cc2745;PC-Y;Trees removed from cable.
;ac1532;PC-N;Remove trees from cable at 17340 hummingbird

MD2797; CLEARED VEGETATION AROUND CABLE.
;ac1532; PC-N; Remove downed drop
dm258s; No access to the road.
dm258s; Issue has been resolved.

DM820T; TRIMMED TREES OFF CABLE
;db8381; PC-Y; Removed drop.; TN: 0000000000
qb6851; cables cleared of trees
DM820T; TRIMMED MULTIPLE OAK TREES FROM CABLE STRAND.
rh749c; Done Task is completed
HAS HAD THE TREE GROW AROUND IT AND IS TO BIG TO REMOVE. TRIED TO CREATE DIG TO HAVE TREE TRIMI
QB6851; GO95 TICKET COMPLETE TREE CLEAR
qb6851; low drops eliminate
GG8932; VEGETATION TREE LIMBS CLEARED OF TELCO FACS. ALL WORK COMP.
GG8932; TREE FOLIAGE RMVD FROM TELCO STRAND AND CABLE, ALL WORK COMPLETE.
;ac1532; PC-N; Remove downed drop
GG8932; OFFENDING BRANCHES TRIMMED AND REMOVED. ALL WORK COMPLETE.

ı2812; PC-N; Clear go95 sontag rd, section thrw 25 Pr 19 gauge Royal oaks Pl new term, no closure, transfer drc
;ac1532; PC-N; Rep def drop
sm4953; sm4953; trees laying on drop remove tree limbs
;ac1532; PC-N; Rep def drop
;db8381; PC-Y; Removed mid span drop that was laying on ground.; TN: 0000000000
;ac1532; PC-N; Remove trees from cable Binet rd
;cc2745; PC-N; Pick up service
;mm3647; PC-N; Temove abandoned drop
;ac1532; PC-N; Rep def drop 1459 little grass valley rd

;ac1532; PC-N; Rep def drop 31 jimmy ct

nh2812; aerial drop on grnd, clear go95 and will submit markit for cable work needed several spans from prim

sm4953; sm4953; trees laying on drop remove

b6851; qb6851; remove non conducting service drops on one pole and rescuerd buried drops down second pol

36851; ELIMINATE DROP NOT IN SERVICE IMPASSABLE ROADS DUE TO SNOW MAKE SEVERAL ROUTE CHANGE

sm4953; sm4953; remove old drop from cable and

;ac1532; PC-N; Rep low drop 9093 Nero rd

OD4318; DEF LINES. TOK.

sm4953; sm4953; abanded cable on Goodyears creek rd

;cc2745; PC-N; Removed drop s

sm4953; sm4953; low hanging drop from tree reattach and remove branch

qb6851; qb6851; routine ticket complete

;sm4953;PC-N;Remove old single pair drop

sm4953; sm4953; drop laying in field remove old drop

sm4953; sm4953; remove drop from a banded home

sf8537; no access,driveway not cleared from storm,will make new job for GO95-ASW.

;jm1295; PC-Y; Locate,facilities located ; TN: 4772022
lp848k; downed lines have been remo
20t; no issues at reported location. There are issues on other poles near by but not accessible without traffic co
;jm1295; PC-Y; Facilities located ; TN: 4773022
dm820t; secured riser cable to pole at reported location
;mr1213;PC-N;LOCATED 3 trees laying on cables,sent pics to local management

rd3541; rd3541; removed dead drop, cut in terminal
jm1295; jm1295; comp.corrected burried drop
;nh2812; PC-N; Rmv vacant aerial drop old Washington rd per go95
;gb1263; PC-Y; Complete, pole transfer
pc9347; pc9347; drop low remove
sm4953; sm4953; remove 3 old drops and empty splice old bird nest
nh2812; nh2812; rmv, vacant dwn drop in front of 712 S Auburn st GV. Job complete
nh2812; nh2812; rmv vacant aerial drop dwn to clear go95 hazard. All work complete
12; PC-N; Clear tree branches from lines, verify clear East and west of approx address, white cloud campgrounc
;gb1263; PC-Y; Remove all dead drops
rd3541; rd3541; removed dead drop
jh3986; jh3986; raised asw, nsa
we2989; we2989; all work is completed
;mm3647; PC-N; Pull up and reattach low drop.

dd6738; Resolve several bad plant aerial drop issues

dd6738; Resolve bad plant aerial drop issue.

pg6512; pg6512; removed broken drop at pole, checked go95 codes

;sm3126; PC-N; Removed 3 asw

DD6738; RESOLVE AERIAL DROP ISSUES

. DROP WIRE HANGING LOW FROM POLE ATTACHMENT. REMOVED AERIAL DROP WIRE FROM POLE AND SERV

;sm3126; PC-N; Removed 2 asw

;sm3126; PC-N; Removed asw

SERVING TERMINAL. ALSO, ASSISTED TECH WITH REMOVE SNOW FROM SUB BOX IN SERENE LAKES, 6218 ALI

. DROP WIRE HANGING FROM MID SPAN AND POLE. REMOVED AERIAL DROP WIRE FROM MID SPAN AND SERV

emoved down line, also advised manager tech stopped by downtown fire Dept ecause of a static phone service

PG6512; REMOVED MULTIPLE BROKEN DROPS ON STREET,

;sm3126; PC-N; Removed asw

dd6738; dd6738; resolve non service affecting aerial drop

PG6512; REMOVED DOWNED DROP, CLEANED UP TERMINAL ACROSS STRERT

;sm3126; PC-N; Removed abandoned asw

JQ2645; REMOVE DOWN

dd6738; dd6738; resolve unused aerial drop issues at serving terminal

DD6738; RESOLVE AERIAL DROP ISSUE

PG6512; REMOVED BROKEN DROP AT MIDSPAN

;sm3126; PC-N; Removed asw

JQ2645; REMOVE DOWN

JQ2645; REMOVE DOWN DROPWIRE

dd6738; dd6738; resolve non service effecting aerial drop issues

;dd6738; PC-Y; Resolve aerial drop issue; TN: Cbr

;jq2645; PC-N; Remove hazardous dropwire

;sm3126; PC-N; Removed 2 asw from pole

JQ2645; DROPS CLEARED FROM FOLIAGE

DD6738; RESOLVE AERIAL DROP ISSUE

12; PC-N; Assist buried drop trble isolation Harmony ridge rd Nevada city, cim bear canyon rd, low cable marina

;sc2675;PC-N;Readjusted drop for proper clearance

sc2675; Raised and reattached low drop

;jm3821; PC-N; Removed drop .. went to 12710 BlackBerry trail to assist tech with UVERSE service repair

JI2512; REMOVED DROP

e near 10261 Lake Spaulding.took meal break.PG&E tech drove up and let me in.no drops down or low aerial cal

;jm3821; PC-N; Removed drops

ook meal break on the way.at 39950Ca-20 found new joint pole had been placed and old drop still attached to te

;ja1893; PC-N; Removed obstructions remove drops down

;bk2151; PC-N; Removed has

;sf8537; PC-Y; Rmvd asw hazzard @ 144 willow.; TN: 5309178926

;sf8537; PC-Y; Rmvd asw hazzard eye sore.; TN: 5309178926

;sf8537; PC-Y; Rmvd hazzard asw; TN: 5309178926

;sf8537; PC-Y; Rmvd hazzard eye sore asw.; TN: 5309178926

;sf8537; PC-Y; Removed hazzard asw; TN: 5309178926

;sf8537; PC-Y; Rmvd hazzard asw,secured terminal cover.; TN: 5309178926

mm9751; mm9751; remove dead drop,rearrange drops

;sf8537; PC-Y; Removed hazzard asw, GO95 job; TN: 5309178926

;sf8537;PC-Y;Rural wires reattached to tree,down tree attachment broke,rpr;TN:5303544708

5; Mutiple aerial drop wires hanging from pole after pole transfer. Removed multiple aerial drop wires from pole

res hanging on the ground from the pole. Hazardous condition. Removed aerial drop wires hanging on the grour

AM8121; INSPECTED SITE, WORK WAS DONE UPON ARRIVAL.

;sf8537;PC-Y;Rprdrops;TN:5303544708

;sf8537;PC-Y;Rmvd hazzard drops along roadway,P6 e-o new st-hwy70. 80921 hwy70;TN:5306157196

537;PC-Y;Reattahed drop and rpr mast on premise,dtsni-cpe,5302830311 &5302830314,advised;TN:530283(

8537;PC-Y;Replaced drop to clearance pole,new drop and sni installed,retro mpoe 5302832000;TN:53028320

;sf8537;PC-Y;Rpld drp@742 mile high.;TN:5306157196

;sf8537;PC-Y;Drop hazzard cleared for hazzard tree removal.;TN:5309178926

;sf8537;PC-Y;Rpr drp an string by on Little Bear rd for DEG.;TN:5306157196

;jm3821; PC-N; Tree trimming

;sf8537;PC-Y;Vegetation control and fire safety@r.t. site complete.;TN:5306157196

;sf8537;PC-Y;Rpr asw and installed new asw for futer service order. 9 spans.;TN:5306157196

;sf8537;PC-Y;Brush control completed for vault access and r.t. Safety;TN:5306157196

;sf8537;PC-Y;Cleared R.T. Site and bbox fire fire safety and clearance.;TN:5306157196

;sf8537;PC-Y;Cleared vegetation for access and safety;TN:5306157196

7;PC-Y;Cleared brush and vegetation,air trouble repaired at RD2 portola,meeting blairsden w LL4958;TN:53061

Site brush cleared for work and fire safety. Meet with sierra county maintenance-advised buried cable runs in ar

;sf8537;PC-Y;Removed excess vegetation @r.t. Site 200 x lundy ln.;TN:5306157196

;sf8537;PC-Y;Removed tree off cable.submit new for lashing wire repair;TN:5306157196

;sf8537;PC-Y;Cleared vegetation around bbox and R.T. For work safety and fire safety;TN:5306157196

;sf8537;PC-Y;Cleared brush for fire safety and work safety,R.T. P139 hwy 70.;TN:5306157196

;sf8537;PC-Y;Removdabandoned asw from term to hnging midspan;TN:5306157196

;sf8537;PC-Y;Removed excessvegetation for fire safety and wrk safety;TN:5306157196
-Y;Hand thinned excess vegetation,to windy for weed wacker this afternoon.work area and fire safety P.M.;TN:5
;sf8537;PC-Y;Vegetation cleared for work and fire safety;TN:5306157196
8537;PC-Y;Removed excess vegetation surrounding r.t. Site and bbox,fire safety and work safety;TN:53061571
;sf8537;PC-Y;Dig pit for encap wrap, corner of whitehorn and buckbrush;TN:5309178926
;sf8537;PC-Y;Assessing burnt cable,Loyalton fire complex,buried cable assesment.;TN:5306157196
;sf8537;PC-Y;Replaced asw over Hwy70@P5;TN:5306157196
;sf8537;PC-Y;Asw replaced over hwy;TN:5306157196
;sf8537;PC-Y;Splice new terminal in cable and replace one section asw.Loyalton fire complex.;TN:530993429
;sf8537;PC-Y;Removed abandoned down drop.1990-2000 greenhorn rnch rd;TN:5306157196
;sf8537;PC-Y;Reattached asw@pole above pedestal.;TN:5306157196
;sf8537;PC-Y;Asw tangled in other utility service,rpr& reattached 8324630;TN:5306157196
;sf8537;PC-Y;Rpr asw,reattached and renmoved hazzard along hwy70.;TN:5309178926
SC2675; RMVD TREES FROM CABLE

SC2675; RMVD TREES FROM CABLE
js3172; js3172; remove several trees off cable
;tl3147; PC-Y; Remove branches, raise asw, pole replaced previously ; TN: 0000000000
;sm4953;PC-N;Remove old drop laying off cable
sm4953; sm4953; remove old drop from cable
nh2812; nh2812; brnchs cleared of line. Compkete
nh2812; nh2812; Go95 tree Trmng at this address, Clear from AT&T lines compket
growth acceptable, customer request concern over pge tree remvl at 15601 cleveland, meet with customer, en
nh2812; nh2812; submitted DG ticket, contract to clr large growth tree from AT&T aerial plant
a mile has heavy tree growth, advsd manager, will submit dig ticket for p30 moonshine rd Camptonville Ca, lar
ıo vegt. Requiring attention or rmvl 16834 state hwy 49, trmmd tree at 17548 statehwy 49 clearing climbing spa
;sm4953;PC-N;Power drop not phone close ticket
sm4953; sm4953; no trouble found test and looks good
;ac1532;PC-Y;Repair broken lashing wire at p 4 Hiatt ln
;ac1532;PC-N;Remove tree from cable at 8870 idlewood cir
;ac1532;PC-N;Made dig for Dudleys to remove large tree from cable at 18615 ny flat rd

SC2675; RMVD TREE FROM CABLE
;sc2675;PC-N;Rmvd trees from line/rprd dmg
;ek6957; PC-Y; A non issue; TN: 2761304

;nh2812;PC-N;Assist x country isolation foster rd GV, ladder hike in rfl prs to isolate x one side uverse.
;jm1295;PC-Y;Tree issues,also Weiss nursery 124779235,1305-150/140;TN:2727657
;ek6957;PC-Y;Sent tree trim to contract;TN:2761304
nh2812; nh2812; no hazrd or vegetation found requiring rmvl
_Y, overrde existing cable with new 25pr, several sections to allot new service requirements per forest service. N
;ek6957;PC-Y;Tree trimming;TN:2761304
;ek6957; PC-Y; Tree work already completed ; TN: 5302761304
;nh2812;PC-N;Field visit, created dg ticket to have tree trm done 104 village way
SM4953; LOW DROP TREES BEEN TRIMMED
Dig it made to have dead tree removed from cable hells half acre also placed case on squirrel chews and fix lash
Term replacement with extension, recent tree fall reported by GV fire, rebld 5??? slic with existing extensions 1
l;PC-Y;Branches growing into cable, terminal, and pole, removed branches from cable, terminal, pole;TN:5555

;vc6131;PC-Y;Branches growing into cable, trimmed branches away from cable;TN:5555555555
;di1638; PC-Y; Removed def dead drop; TN: 1
;bk2151; PC-N; Drop cleared, tree line clear
;np5869; PC-N; Trimming trees cable is now cleared,remove drop
a rd,long whindy mountain rd.inspected aerial cable run,no low hanging drops or cable found.dart ticket over a y
;md4156; PC-N; Removed aerial drop at. At marked location
PC9347; DROP HANG REMOVE DROP
;js6852; PC-Y; Removed tree limbs from cable and rehung low hanging drops
;md4156; PC-N; Removed drop at marked location
;md4156; PC-N; Removed drop at marked location
OD4318; DROPS REMOVED FROM TREES.
;ac1532; PC-N; Rep low drop
PC9347; LOW DROP RAISED SAFE NOW
;np5869; PC-N; Removed drop,raised cable line attached to metal strand,trimming trees cable is now cleared
;ac1532; PC-N; Rep low drop
;ac1532; PC-N; Rep low drop
;ac1532; PC-N; Rep low drop
-N; Nja,gas up,smart chatted in.At address of 10066 Smith rd found some tree limbs on aerial cable.handsawe
JM2792; DEAD DROPS RE
GG8932; AERIAL SERVICE WIRE REMOVED FROM POLE TERM. AWC. ASSIST RISER GUARD BELL RD. AWC.
;jm2792; PC-Y; Dead drop removed and others

;np5869; PC-N; Trimming trees cable is now cleared,removed drops
;jm3821; PC-N; Removed dead drops on pole
PC9347; DROP LOW REMOVE DROO
DM820T; WRECKED OUT DROPS.
'; Coiled down drop and attach to pole, snowing out, couldn???t drive truck to pole because of snow, had to use
;rw5286; PC-N; Removed drop;
ed 2 down drops at 1 location, coils up and secured a drop at 2nd location, trimmed a tree off the cable at 3rd lo
JM2792; ALL WORK COMPLETE
;jm2792; PC-Y; Loose drop down from terminal
town of Allegheny.found location and inspected aerial cable of any dead or hanging drops.already removed.hac
;jm3821; PC-N; Removed dead drop .. unable to safely remove mid span need bucket ..but not hazardous
;rw5286; PC-N; Removed dead drop;
MG1262; TREE TRIMMED AS MUCH AS POSSIBLE. CA NOT IN DANGER NOW, SUB TO GET TREE REMOVED.
;jm2792; PC-Y; Dead drops removed cleared
;sm1897; removed low hanging drop
s at 14608 DogBar rd in GV.inspected aerial cable run alongside rd,looks as though previous tech had already r
irst,gps trouble?at 12210 Valley View rd,inspected aerial cable for any drop issues.none found.the only drop go
JI2512; REMOVED DROPS ALONG DIRT ROAD
JI2512; REMOVED DEAD DROP
;js6852; PC-Y; Removed drops from poles and rehung low hanging drops
MM3647; REMOVE DEAD DROP.
MG1262; NO VEGATATION AT TICKET LOCATION, PREV REMOVED???

;ek6957;PC-Y;Will send to contract tree trimming . Multiple locations on street;TN:2761304
D OUT DOWNED DROP. HUNG NEW 50 PAIR SECTION IN ROUGH AND READY ON MYSTERY LANE HELPING LP8
M820T; WRECKED OUT DOWNED DROP AND GROUND WIRE NOT ATTACHED AT THE GROUND OR THE STRAN
MD4156; QUALITY ROUTINE COMPLETE
AG2675; REMOVED DROPS AND STREET, ALL WORK COMPLET
MM3647; REMOVE LOW HANGING ABANDONED DROP.
AG2675; REMOVED DEAD DROPS, ALL WORK COMPL
AG2675; CLEARED DEAD DROPS AND TREES FROM TERMINAL
LP848K; ROUTINE MAINTENANCE WORK
8932; MULT AERIAL SERVICE WIRE REMOVAL, RISER DROP SECURED TO POLE. ASSIST AG2675 ALTA SIERRA. A
QB6851; NON SERVICING DROPS ELIMINATED
C-N;Per inspector, tree needs trimming around cable. Made ABWS ticket for tree trimming. Will verify after job
;ek6957;PC-Y;Moved drop. Fixed geo 95 violation;TN:2761304
sm4953; sm4953; found limbs touching cable trim trees to clear
;sm4953;PC-N;Cable going through large trees nothing we can do private property
;sm4953;PC-Y;Remove tree branches off cable
sm4953; sm4953; tree trimming on pole for clear
sm4953; sm4953; reattach case hanging in the breeze

;jq2645;PC-N;Ref for dig for tree removal off cable @ mis-span, rear alley
sm4953; sm4953; wires hanging. From tree are not att drops they are old cable tv wires
ı3145; Aerial drop wire needs to be removed from pole. Removed aerial drop wire from pole and serving termina
;dd1636; repair cable and splice.
dd6738; Resolve aerial drop issue
p wire hanging from pole. Removed aerial drop from pole and serving terminal. Roads are covered in snow and i
dd6738; Resolve aerial drop issues
;dd1636; repaired splices found worke that need to be done.
dd6738; resolve aerial drop issue
pg6512; drops in Lahontan and martis camp, advised sup of work done
dd6738; resolve aerial drop issues
cd5628; cut down, drop at location, located additional drops and low hanging wires. Worked on lines
3145; Aerial drop wire needs to be removed from pole. Removed aerial drop wire from pole and serving termina
dd6738; resolve aerial drop issue
jh3145; Aerial drop wire hanging low from pole. Removed aerial drop wire from pole and serving terminal.
erial drop wires hanging down from pole. Hazardous condition. Removed multiple aerial drop wires from pole ar
ultiple aerial drop wires hang from pole. Hazardous condition. Removed aerial drop wires from pole and serving
jh3145; Removed aerial drop wire from serving terminal.
pg6512; removed downed drop, also pulled in multiple fiber drops
anging from mid span. Removed aerial drop wire from mid span and serving terminal. Hazardous conditions. Bli
drops hanging off of pole, still active services. Coming in from underground conduit. Pulled up re-tightened at t
wc8687; remvd unused low drop, raised working drop
dd6738; Resolve aerial drop issue
dd6738; resolve aerial drop issue
;pg2676; REM excess drop wire.
wc8687; remvd drop from snow
dd6738; Resolve aerial drop issues
dd6738; resolve aerial drop issues
Resolve bad plant condition
dd6738; resolve aerial drop issue
cd5628; cut drop, assisted tech with buried drops
dd6738; resolve aerial drop issues
pg6512; removed multiple drops and hardware from multiple poles on Baden,
dd6738; resolve aerial drop issue
dd6738; Resolve aerial drop issue
cd5628; per ticket, drop cut and removed. Remainder of drop buried, will return when snow melts.
dd6738; resolve aerial drop issues
undefined drop removed from span pole per ticket
WC8687; REMOVED LOOSE DROP
he pole on the ground. Hazardous condition. Removed aerial drop wire. Also, checked on damaged to cable on
dd6738; resolve aerial drop issues
drop wires hanging from pole and laying on the ground. Hazardous condition. Removed aerial drop wire from pol
d low hanging drop, two additional drops down nearby. Assisted with tightening up a cable company drop at the
g6512; rebuilt two terminals and bonded 25 pair and 600 pair cables on Davos, removed drops at ticket addres

rop teardowns, as well as repairing low, hanging drop further down. Assisted with cutting clear pair for another t
dd6738; resolve aerial drop issues
dd6738; resolve aerial drop issue
dd6738; Resolve aerial drop issues
nging drop per ticket request. Also noted additional tree damage to other lines. Advised owner of property to ha
dd6738; resolve aerial drop issues
pg6512; removed downed drops, rebuilt multiple terminals in soda springs, notified sup
dd6738; resolve aerial drop issues
dd6738; resolve aerial drop issues
dd6738; resolve aerial drop issues
dm141g; ran drops to houses
dd6738; Resolve aerial drop issues
dd6738; resolve aerial drop issue
dd6738; resolved aerial drop issues
dd6738; resolve aerial drop issue
;pg2676; Drop rem
cd5628; Removed and cut down multiple drops in area. Continue to higher level on street.
pg6512; Removed downed drops and repaired damaged splice case at 13360 Davos dr
;dd1636; prep new cable and ariel work remove pole mounted terminel. replace with arial terminel.
dd6738; resolve aerial drop issues
pg6512; removed downed drop, rebuilt splice case and terminal case on Davos dr, advised sup
dd6738; resolve aerial drop issue. Drop was other utility co drop
dd6738; Resolve aerial drop issue
dd6738; Resolve aerial drop issue
dd6738; resolve aerial drop issue
2; removed drop, removed snow off drops and cables on soda springs rd, needed snow cat to move snow, advis
dd6738; resolve aerial drop issues
;pg2676; Removed damaged drop. Dressed up drops on pole.
dd6738; rssolve aerial drop issues
jh3145; Aerial drop wire hanging low. Hazardous condition. Removed aerial drop wire.
dd6738; Resolve aerial drop issue
dd6738; resolve aerial drop issues
wc8687; remvd low hanging drop from midspan
dd6738; resolve aerial drop issues
dd6738; resolve aerial drop issues
/ire hanging from mid span on the ground. Hazardous condition. Removed aerial drop wire from mid span, pole
Resolve aerial drop issue
dd6738; resolve aerial drop issues
dd6738; resolve aerial dr
;econdary, drop off the road as well as install the case. Drove around, did not have the proper case for another t
rial drop wire hanging from mid span clamp and pole. Removed aerial drop wire from mid span clamp and servi
dd6738; Resolve aerial drop issues and assist techs with f1 cable trouble
cd5628; remove dead drops, found additional two hanging up telco Pole.
dd6738; resolve aerial drop issues

ıe to scope the neighborhood out, I believe I located the address, how to hike in between ski slope and slalom. S
cd5628; multiple drops down in the area, spent time cleaning up per GO 95 ticket plus additional drops
dd6738; resolve aerial drop issues

7/6/21 Notified of completion by SVA. NOTE: Resaggec
PC9347; VEGETATION STRAIN DEFLECTION AFFECTING POLE OR POLE ATTACHMENT REMOVE VEGETATION
DL1623; CLEAR GROWTH, OK TO CLOSE
;jm1295;PC-Y;Tree cleared,also ban 287641840-Emma,also dsl-0880864001-Kate;TN:6509130806
;ek6957;PC-Y;Rebuilt wet splice;TN:2761304
;sm4953;PC-Y;Rebuild splice at pole 6 American hill squirrel nest and chewed
;ek6957;PC-Y;No need for tree trimming ;TN:2761304

;nh2812;PC-N;Completed, assist extended wire run Wolf creek
;ek6957;PC-Y;Trees don???t need trimming;TN:2761304
;ek6957;PC-Y;No need for tree work;TN:5302761304
;ek6957;PC-Y;Normal trees near cable;TN:2761304
;ek6957;PC-Y;Sent to contract for tree removal;TN:2761304
;ek6957;PC-Y;Sent to contract for tree trimming;TN:2761304

7/19/21 Per SVA, Observed
;ek6957;PC-Y;No tree issues;TN:2761304
;ts3269;PC-N;Trimmed back trees and cleared from f2 cable strand and pole at P4 Northgate
ı2812;PC-N;Term replacement Buckeye circle penn valley, create dig ticket for tree trm lake Forrest dr penn val
QB6851; VEGETATION CLEARED FROM LINES
Trimmed tree branches to clear AT&T???s facilities cables/terminals, road blocks 2:30 to safety heavy traffic.;T

;ek6957;PC-Y;Worked hi cap with ms7970. No issue with trees;TN:2761304

mmed tree branches that were on/over AT&T facilities on penn valley rd, had to jump over a fence with a ladder.
;ms7970;PC-N;Refer to dig #013192421. Trees in span. Need trim.

MM3647; REMOVE ABANDONED DROP.
prep 2 manhole for work to be done tom made ticket for traffic control
gg8932; remove mult old drop wires awc. Assist ag2675 w co access and f2 repair buryard ln. Awc.
;jm1295; PC-Y; Facilities located; TN: 4773022
JI2512; BX9-DROP REMO
GG8932; ALL WORK COMPLETE.
;dm6529; PC-N; completed
MM3647; REMOVE DOWNED, ABANDONED DROP
;br5481; PC-Y; Rem drops at term, through trees; TN: 9999999999
pc9347; drop low remove drop
QB6851; ELIMINATE NON SERVICING DROPS INTERTWINED IN LANDSCAPING
qb6851; drops removed
MD4156; QUALITY ROUTINE COMPLETE AT MARKED LOCATION
MM3647; REMOVE LOW, DEAD DROP.
;rn2732; PC-N; Removed dead drops
VC6131; DROP DOWN, REMOVED DEAD DROP,
;dm6529; PC-N; work completed
ED CUT CABLE IN MANHOLE 214 IN PENN VALLEY. CABLE HAD BEN CUT AND NEEDED TO BE CAPPED TO PRE
MD4156; REMOVED ABANDONED AERIAL DROP FROM POLE AT MARKED LOCATION
PC9347; DROP LOW REMOVE DROP
MD4156; QUALITY ROUTINE COMPLETE AT MARKED LOCATION
md4156; quality routine ticket resolved at marked location
;jm1295; PC-Y; Working UVERS service on prem.; TN: 4773022
QB6851; DROPS ELIMINATED
7/19/21 Per SVC, Trimmed trees

;sm4953;PC-Y;Pole transfer needed tried to put in markit but can???t connect
12; large aerial bucket needed with 2 way traffic control to free AT&T lines from large tree branch, submitted di
;sm4953;PC-N;Tree trimming reattach drop
;ek6957;PC-Y;Sent to contract for tree trimming /removal;TN:2761304
sm4953; sm4953; remove tree limbs from drop ok now
;rd3541;PC-N;Complete
;ek6957; PC-Y; Tree work; TN: 5302761304

;sm4953;PC-N;Tree growing around pole markit to remove tree
;sm4953;PC-N;Place case over open sheath trees trimmed
;ek6957;PC-Y;Tree removal. Also replaced u guard;TN:2762304
;ek6957;PC-Y;Trees not an issue;TN:2761304
;sf8537;PC-Y;ASW cleared,P616 ellen,;TN:5309178926
;sf8537;PC-Y;Removed excess branches of strained cable, 278- 300 Bella vista;TN:5309178926
;sf8537;PC-Y;Removed excess branches on cable. P530 e spruce-P 480 e spruce.;TN:5309178926
;sf8537;PC-Y;Removed tree branch hazzard off cable;TN:5309178926
;sf8537;PC-Y;Removed excess trees,rmvd abandoner asw,rmvd tree guard on cable;TN:5309178926
;sf8537;PC-Y;Removed excessbranches on cable;TN:5309178926
;sf8537;PC-Y;Removed excess branches off cable;TN:5309178926
;sf8537;PC-Y;Trimmed tree, excess weight on cable.;TN:17752208431
PC-Y;Removed excessive strain on cable, 302 thru 350 Bella Vista dr, cleaned utility bed/lights/mirrors.;TN:530
;sf8537;PC-Y;Removed tree limbs on cable,pine and oak tree, cleaned debris in truck;TN:5309178926
SF8537; REMOVED EXCESS BRANCHES ON CABLE.
;sf8537;PC-Y;Removed tree hazards on cable;TN:5309178926
;sf8537;PC-Y;Removed excess branches on cable.;TN:5309178926
;sf8537;PC-Y;Removed excessive branches on cable,return to finish w chain saw;TN:5309178926
AVA-JA306P-DART ticket closed per the process.
;ek6957;PC-N;Removed tree on cable;TN:2761304
;ek6957;PC-Y;Not really an issue;TN:2761304
;qb6851;PC-N;Trees cleared from lines at 12600 Vicki dr
;sm4953;PC-N;Remove 13 tree branches from cable
PC9347; REDUCE VEGETATION AT POLE
PC9347; REMOVE VEGETATION NEAR POLE
;ek6957;PC-Y;Looks like the rest of the county;TN:2761304
;ek6957;PC-Y;Built on wrong turf;TN:2761304

;sf8537;PC-Y;Dig and rpr BSW trouble, 5302839005. Coworker assist with alternate job.;TN:5306157196
sf8537; NTF ATT, all on ground found was coaxial wire.

before dispatching.drove to location of 11100 Tyler Foote rd.inspected aerial cable run for old or low hanging d
at Camptonville co.drove to location at 10759 Ivey ln.found single vynl drop coiled up and still attached to term
JI2512; BX9-REMOVED UNUSED DROPS
MD4156; QUALITY ROUTINE WORK COMPLETED AT MARKED LOCATION
lp848k; down drop removed.
sf8537; rmvd asw hanging midspan.
sf8537; found correct location through pictures to be R439 second av. RMVD asw on fence.
MD4156; QUALITY ROUTINE COMPLETE AT MARKED LOCATION
lp848k; downed drops removed.
sf8537; rmvd abandoned asw on park property 1955 e claremont and P1985 e clarmont.
QB6851; REATTACHED AND RAISED TWO DROPS CROSSING LOW OVER TYLER FOOTE RD
;jm1295; PC-Y; Quality flow thru package; TN: 4773022
MD4156; REMOVED DROP AT MARKED LOCATION
;mm9751;PC-Y;Replaced nid,reconnected buried drop
;sf8537;PC-Y;Removed excess branches on cable,rmvd 2abandoner asw also.;TN:5309178926

;sf8537;PC-Y;Removed abandoned asw hanging midspan.;TN:5309178926
;sf8537;PC-Y;Removed abandoned asw handing midspan to to tree.;TN:5309178926
;sf8537;PC-Y;Isolated trouble for trench job to replace buried cable section.P42-43 Hwy 49;TN:7752208431
;sf8537;PC-Y;Removed branches tree strain on cable. TV coax still under strain. ATT clear;TN:5309178926
;ac1532; PC-N; Rep low drop

;sf8537;PC-Y;Pit and trench work completed, exposed cables buried.;TN:5309178026
;sf8537;PC-Y;Removed excessive weight-branches on cable, P30 greenhorn rnch.;TN:5309178926
;sf8537;PC-Y;Removed abandoned hanging asw.;TN:5309178926

;sf8537; PC-Y; Replaced multiple spans aerial service drp. Reloading drp for more tomorrow.; TN: 7752208431
PC-Y; Replaced 7 spans aerial wire, exhuated suppy on truck, need to stock more for tomorrow finish.; TN: 530

sf8537; referred to construction months ago reguarding trees on cable along Graeagle creek trail cable run.
; PC-Y; Forest closed for any chain saws,Fire safety-hazzard,GPS= Graeagle creek trl,wg2716 advised; TN: 7752
537; PC-Y; Forest closed to any woodcutting,fire safety/hazzard, GPS= Graeagle creek trail cable; TN: 7752208
'16-advised, Fire Safety exists,forest closed to chain saw.Graeagle creek trail cable 01x26-50 per GPS coordina
PC-Y; WG2716-advised.fire safety,forest closed to chainsaws. CA01x26-50, Graeage creek trail cable; TN: 530
sf8537; rmvd abandoned asw and secured term and cable
;sf8537; PC-Y; Rmvd abandoned asw.; TN: 5309178926
sf8537; rmvd abandoned asw
sf8537; Rmvd abandoned asw, and secured terminal

sf8537; rmvd abandoned asw,reattachd c wire., secured term cover
sf8537; looks like coax again, ntf ATT.
sf8537; rmvd abandoned asw
sf8537; lrmvd abandoned asw
sf8537; rmvd abandoned asw&bsw,new closure cover installed.
sf8537; rmvd abandoned asw,.
sf8537; rmvd abandoned asw and secured cable and term.
sf8537; coax in pic, no ATT issues.
sf8537; rmvd abandoned asw
sf8537; rmvd COAX 55 Klamath trl per picture,reattached BSW.
sf8537; found at P12 cedar ln, 58647 Cedar ln.
sf8537; rmvd abandoned asw.
;sf8537; PC-Y; Ntf,no ATT conflict.; TN: 5309178926
sf8537; rmvd abandoned asw.
sf8537; asw removed,abandoned
sf8537; rmvd abandoned asw to terminal, 2 spans.
;sf8537; PC-Y; Ntf ATT,suspect coaxx network.; TN: 5309178926
;sf8537; PC-Y; Found coaxial cable,advised other utility company,not ATT facilities.; TN: 5309178926
sf8537; Rpr hardware issue
;cc2745; PC-N; Cleared tree limbs
;ac1532; PC-N; Trees removed from p 1 to p 6 New York House rd
rh749c; Task is completed done
51; ATTEMP TO RAISE DROPS BUT DUE TO HEIGHT RESTRICTIONS FROM HEAVY MACHINERY HAD TO RAISE DI
sm4953; sm4953; remove old drop
QB6851; GO95 TICKET COMPLETED
QB6851; GO95 TICKET COMPLE
being written up to trim trees off cable, sweet land has 1 asw found multi spans no issues, pictures appear to b
QB6851; CLEAR FOLIAGE RAISE DROPS FOR CLEARANCE
;js2145; PC-N; All work completed
MM3647; RAISE LOW DROP.
QB6851; REMOVED NON SERVING DROP AND ATTACHMENTS CLEARED GO95 ISSUES
QB6851; LINES CLEARED OF TREES
QB6851; GO95 ISSUES CORRECTED
RW5286; REMOVED DROP;
JM2792; DROP HANGING FROM TERMINAL
DM820T; REMOVED VEGETATION FROM CLIMBING SPACE AT 26968 SWEET LAND.
AG2675; ALL WORK COMPLETED, REMOVED DROPS
RW5286; TRIMMED TREE LIMBS;
N; Drove to 18470 Oak Tree rd.inspected aerial cable alongside road.all limbs removed from pushing down on c
MM3647; REMOVE VEGETATION FROM POLE AND STRAND.
;bk2151; PC-N; Drop work cleared
;el8648; PC-N; Drove to location of 24590 Poplar Meadow on,found drop was cut down by previous tech?
;np5869; PC-N; Trimming trees cable is. Now cleared
;bk2151; PC-N; Drop removed

C-N; Drove from Sierracity to address of 28499 Sweetland rd in North San Juan.found old drop had already beer
sm4953; sm4953; pole in ravine nothing we can do to help it
;mm3647; PC-N; Place u guard over bsw on pole at address.
.ONG LANE CLOSURE, CUT TREE BRANCHES OFF CABLE TO RELIEVE STRAND.. PILE BRUSH ON SIDE OF HILL,
;ag2675; PC-N; Removed dead trees from cable
;jm1295; PC-Y; Multiple trees down from conservation camp to 5 mile house; TN: 4773022
OD4318; REPORTED TREE BRANCHES TO LOCAL

SM1897; VERIFIED TREE RMVD FROM POLE, ALL WORK COMPLETE
;mm3647; PC-N; Put u-guard over buried drops and route up pole.
sb6349; cable guard placed. Not service affecting
;qb6851; PC-N; Encroaching limbs removed
mm9751; mm9751; help move aerial drop
cb281c; wracked out drops and then pulled other dead drops used but test to test if they were dead
11/04/22 RWM PKG ID 922904
;ji2512; PC-Y; Bx9-advised construction with photos after removing what I was able to; TN: 5593976286
;ag2675; PC-N; Took pics and sent to management to get tree trimmers out
cb281c; pulled cut drop and other drops
md4156; power influence located and pge trouble ticket created
;mm3647; PC-N; Wrong address/no such address. Raise low drop at 165 burboun hill.
js2145; All work completed on this job
EH3437; BRANCHES CLEARED AROUND POLE AND TERM. SAFE NOW WORK COMPLETE
EH3437; BRANCHES CLEARED AROUND POLE, WORK COMPLETE
;qb6851; PC-N; Encroaching tree branches removed from pole
js2145; All work completed on this job. Also was on this job repairing t1spans ok per ac2913
js2145; all work is completed on this j
2145; had to place drop through trees at 17373 blue tent school rd, ok per ek6957, all work completed on this j
;ag2675; PC-N; Misc, trees around cable, pics and email sent to Eric to get tree trimmers out

;md4156; PC-N; Rfi noise isolation.
md2797; raised aerial drop through multiple tr
cb281c; cut drop in picture also removed one other dead drop
;md4156; PC-N; Rfi noise isolation complete
;md4156; PC-N; Rfi noise isolation
;md4156; PC-N; Rfi noise isolation
qb6851; resucured riser gaurd and labeled with dig warning sticker
;mm3647; PC-N; Raise low bypass.
js2145; all work is completed on this job.
md4156; Resolved go95 at marked location
js2145; all work is completed on this job.
;ag2675; PC-N; Misc, removed dead branches from pole
RW5286; MULTIPLE OPENS IN F1;
;jm3821; PC-N; Tree laying on cable ..unable to remove tree .. sent to local supervisor for line crew to remove
GG8932; TREE WORK, CUT AND REMOVE. AWC.

md2797; removed drop hanging down

ot AT&T cable it belongs to whoever the co-ax provider is in the area and lines are not lose just excess wrapped a

dm820t; no issues with riser cover at reported location

320t; no issues at reported location. Did RFI locates and office of the president escalation order while on this tic

;bk2151; PC-N; Tree line cleared

;md4156; PC-N; Rfi noise found at p26 n Bloomfield

;ag2675; PC-N; Misc, remove dead branches, also drop

ed to joint pole at address. Low drops already removed. No data/LTE service around Cascade Shores General St

pictures from sept 2021. No low hanging drops. Pole and cable appears to have been replaced. splice case next

;md4156; PC-N; Rfi noise isolation

GG8932; TREE ON LED RMVD. AWC.

11/04/22 RWM PKG ID 926429

;cg4741; PC-N; All work complete. Trees trimmed

AM8121; TREE HAVE BEEN REMOVED. REPLACED COVER ON TERMINAL. ALL WORK IS COMPLETE.

dm820t; cleared trees away from climbing space at reported lication

jo1454; all work completed no ccon

dm820t; New pole at reported location with no issues. Did RFI locates while dispatched on this ticket.

QUAILS NEST AND PLACED CLOSURE ON EXPOSED CABLE. NO NEED FOR CROSS ARM FOR DROP AS POWER

sb6349; located pole. Placed riser guard on drop

dm820t; found no issues at reported location

;mm3647; PC-N; Place u-guard over bsw on new pole.

md4156; md4156; cleared markit vegetation and foliage

js2145; all work is completed on this jo

mm3647; Reroute low drop to follow power.

;sf8537; PC-Y; Removed hazzard down asws.; TN: 5309178926

qb6851; Raise low hanging service drops

6851; riser cover secured to pole . Investage customer concern of low cables. Take photos and email to manage

qb6851; eliminate non conductive service drop

js2145; placed riser guard, all w

qb6851; eliminate discarded service drop

sb6349; all work com

js2145; Attached riser gaurd to pole, all work c

;mm3647; PC-N; Place riser guard over bsw.

violations cleared, risers attached, drops secured to pole. Comcast still has some GO95 violations on there, bu

rw1952; rw1952; dig for tree trimming inputted

dm820t; Isolated and reported to PG&E multiple locations of AC voltage trouble spots.

rw1952; rw1952; placed dig for tree trimming

;sf8537; PC-Y; Rpld asw, no access to mpoe.; TN: 5309178926

ww1427; ww1427; go95 cleared

qb6851; install riser cover service drops

rw1952; rw1952; dig requested to trim trees at 10981 Spenceville Rd, Penn Valley

;dm6529; PC-N; isolate power faults

;dc2631; PC-Y; Verified completed, nsa; TN: 5308675309

ft sections of grey conduit cover for exposed drops on joint pole 50 ft from address on ticket. Before and after pi

ıfered attached to new PG&E pole. Old pole with at&t plant and terminal is lashed bolted to new pole behind it.

;tl5296; PC-Y; All vegetation work complete

pg6512; Removed drop next to pole

dd6738; Resolve bad plant issues

dd6738; Resolve bad plant conditions. Other utilities

cd5628; Per ticket, cut down drop, tightened up neighbors drop

dd6738; Resolve bad plant issues

pg6512; Removed drop off pole

jh3145; Aerial drop wire hanging from pole. Removed aerial drop wire from pole and serving terminal.

rop wire hanging from pole. Laying in the snow. Hazardous condition. Removed aerial drop wire from pole and s

cd5628; Per ticket request cut down and removed remaining drop at lower end of telephone pole.

dd6738; Resolve bad plant issues

cd5628; Cleaned up blue hanging wires, one additional line left over from cable company

dd6738; Resolve bad plant issues

pg6512; Removed drop at pole

ıal, at location, walked entire building only saw a loose cable on pole showing from cable company. Assisted te

pg6512; Removed low drop, also assisted at sugar bowl with downed cable, advised sup Tim Lauder

dd6738; Resolve bad plant conditions

cd5628; Located loose hanging drop wire removed per ticket request

pg6512; Sent dig crew job details on fixing consuit

dd6738; Resolve bad plant issues

cd5628; Turn on case exposure has been repaired. No additional drops at low hanging depth.

dd6738; Resolve bad plant issue

dd6738; Resolve bad plant issues

dd6738; Resolve bad plant aerial drop conditions

pg6512; Removed downed drop at pole

pg6512; Sent work order to dig group

pg6512; Removed drop from strand

pg6512; Sent request to dig crew

dd6738; Resolve bad plant conditions

dd6738; Resolve bad plant conditions

r ticket, located, riser, cover damages. Dont have extension riser, but able to cover remainder of wire and tack c

ıcular request re-tiedown drop attached to lunchbox and BSW. Confirm DT back to property tied down wired no

pg6512; pg6512; Repaired down section of drop, heavy snow storm while wori

dd6738; Aerial drop issue resolved

jq2645; Found property & found pole; no g095 violation,

28; Located both drops off a dirt road, cut down and removed all the way back to lunchbox terminal per ticket re

ıoved low drop wire plus remaining spool left in dirt and pushes. Old phone line found 4 feet away, removed adc

jq2645; Raise low drop wire
dd6738; Unable to get to bad plant condition due to snow load
pg6512; Removed drop at pole
l wire from cable company laid out on the ground coiled up and removed from location. Customer on side to as
jq2645; Re-attached 3 low cables to poles
jq2645; Re-attach low cable to pole
pg6512; Road closed to Martis peak, will return to address and remove hazard
dd6738; Resolve aerial drop issues by removing drop from serving terminal not in service
dd6738; Resolve aerial drop issues. Non service effecting. Remove several drop from poles and serving termina
DD6738; RESOLVE AERIAL DROP ISSUE
pg6512; Sent work request to dig crew
pg6512; Removed drop at pole
dd6738; Bad plant issue resolved
dd6738; Other utility drop, Att buried drop in tact
dd6738; Resolve aerial drop issue
jq2645; Remove down drop wire
dd6738; Resolve aerial drop issues
jq2645; Remove down drop wire
; Per ticket request Cut down drop wrapped around telephone Paul able to remove all drop now that Snow has r
jq2645; Remove down drop wire
dd6738; Resolve aerial drop issues for bad plant conditions
dd6738; Resolve aerial drop bad plant condition
pg6512; Removed drop from pole
pg6512; Removed drops from pole
PG6512; REMOVED CABLE ON GROUND, ALSO REPAIRED DROP ON DONNER DR, ADVISED SUP
pg6512; Removed drop from pole
pg6512; Removed drop to mid span
dd6738; resolve aerial drop issues
pg6512; Removed drop at pole
pg6512; Removed drop at pole and mid span
dd6738; Resolve aerial drop bad plant conditions
2645; Remove down drop wire; note needs lid replaced over binding posts; no go95 violation, not service effecti
jq2645; Remove down drop wire
cd5628; Per ticket, located old drop cut down, removed excess old drops as well
pg6512; Removed drop at pole
pg6512; Removed drop at pole, repaired guard arm, bolt holding bracket broken,
cd5628; Per damage claim ticket, located, and removed dead drop, it was total of three drops.
145; NO VEGETATION TREE BRANCHES OBSTRUCTING ATT CABLE FACILITIES AT OR NEAR 13693 CRISTILLINA
dd6738; Resolve aerial drop issues
pg6512; Removed drop from pole
pg6512; Removed drop from pole
DD6738; RESOLVE TREE BRANCHES LEANING ON AERIAL CABLE
pg6512; Removed low drop from pole
pg6512; Removed drop handing from pole

5; DETERMINED THAT ALL AERIAL DROPWIRES ARE SUFFICIENTLY SAFE LEGALLY SEPARATED FROM POWER I
cket request cut down loose hanging drop however picture showed next to house drop was hanging on opposite
Aerial drop wire hanging from pole. Laying on the ground. Hazardous condition. Removed aerial service wire fro
jq2645; Remove down drop wire
jq2645; Remove down drop wire
jh3145; Aerial drop wire hanging from pole. Removed aerial drop wire from pole.
jq2645; Remove down drop wire
dd6738; Resolve aerial drop bad plant conditions
dd6738; Resolve aerial drop bad plant issues
cd5628; Located low hanging drop, cut down and tightened up additional drop from customers property
pg6512; Removed drop at midspan and pole
pg6512; Removed drop at pole
dd6738; Resolve bad plant aerial drop issue
dd6738; Resolve bad plant aerial drop issue
wire hanging from the pole. Laying on the ground. Hazardous condition. Removed aerial drop wire from pole ar
op, however, another cable line is hanging there looks like it goes to a customers property and just needs a new
ltiple aerial drop wires need to be removed from clearance pole. Laying on the ground. Removed multiple aerial
jh3145; Aerial drop wire hanging from pole. Removed aerial drop wire from pole and serving terminal.
m pole. Laying on the ground. Hazardous condition. Removed aerial drop wire from pole and serving terminal. V
dd6738; Resolve aerial drop bad plant issues
pg6512; Removed drop at pole
pg6512; Removed drops at pole
rial drop wire hanging from pole under the snow. Removed aerial drop wire from pole and pulled out from under
ed low hanging drop, leftover wire on the Ground. Also able to tighten up additional customers line that was low
ocated, and removed drop wrapped around telephone pole, prior to arrival noticed phone line down from anoth
cd5628; Per ticket, removed drop wrapped around pole
pg6512; Removed drop at pole,
dd6738; Resolve aerial drop bad plant issues
6512; MARKED AREA WITH BRANCHES ON TREE, SEND DIG TICKET TO HAVE BRANCHES REMOVED OFF CABL
Per ticket request cut down drops wrapped around pole additional line hanging low tied back to proper high adj
jh3145; Aerial drop wire hanging from pole. Removed aerial drop wire from pole.
dd6738; Resolve bad plant issues
jh3145; Aerial drop wire hanging from the pole. Removed aerial drop wire from pole.
dd6738; Resolve bad plant issues
pg6512; Removed drop at pole
dd6738; Resolve aerial drop bad plant issues
dd6738; Resolve aerial drop bad plant issues
dd6738; Resolve bad plant issues
dd6738; Resolve bad plant issue
N GROUND DUE TO ICE AND SNOW, REMOVED CABLE GOING TO HOMES, ALSO WORKED ON CABLE AT 1500
dd6738; Resolve bad plant issue
cd5628; Per ticket request, raised to drop up above required height. Removed tree, limb affecting height.
ial drop wires hanging from tree, laying on the ground. Hazardous condition. Removed multiple aerial drop wire
dd6738; Resolve bad plant aerial drop issue

dd6738; Resolve bad plant aerial drop issues

wire hanging from the pole. Laying in the snowbank. Hazardous condition. Removed aerial drop wire from pole a

5; Aerial drop wire hanging from pole. Laying in the snow. Removed aerial drop wire from pole and the serving te

jh3145; Aerial drop wire hanging from the pole Removed aerial drop wire from the pole and serving terminal.

dd6738; Resolve aerial drop bad plant issues

w hanging, drop in snow, able to cut down and remove not that deep and snow. Noticed damaged open case, ab

down drop Hanging from telephone pole noticed additional mid span drop Hanging loose, cut down and remov

jh3145; Aerial drop wire hanging from the pole. Removed aerial drop wire from the pole.

jh3145; Aerial drop wire hanging from the pole. Removed aerial drop wire from pole and serving terminal.

dd6738; Resolve bad plant aerial drop issues

cd5628; Per routine ticket, cut down low hanging drop. Located additional drop in Bush close by.

wire hanging from the pole. Laying on the ground. Hazardous condition. Removed aerial drop wire from pole ar

628; Per ticket request, cut down remainder of drop additional coil wrapped around base of telephone pole rem

dd6738; Resolve aerial drop bad plant conditions

dd6738; Resolve bad plant aerial drop issues

cut down low hanging drop, secondary line hanging low from customers property reattached to telephone pole

dd6738; Resolve aerial drop bad plant issues

cd5628; Per ticket request located low having drop, cut down

dd6738; Resolve non service aerial drop hanging from pole

dd6738; Resolve aerial drop issues

dd6738; Resolve aerial drop issue from prem. Other part of drop already removed

jq2645; Re-attach riser drop wire to pole

jh3145; Aerial drop wire hanging from pole. Removed aerial drop wire from pole and serving terminal.

cd5628; Per ticket, isolated, and located low hanging drop. Closed up terminal case next to it.

ticket request cut down and removed all drop, assisted with raising up an additional telephone line from anoth

cd5628; Per per ticket request cut down drop removed coiled drop from ground

dd6738; Resolve bad plant aerial drop issues

dd6738; Resolve bad plant aerial drop issues

dd6738; Resolve aerial drop issues

dd6738; Resolve aerial drop issues

dd6738; Resolve bad plant buried drop service wire

dd6738; Resolve aerial drop bad plant conditions

pg6512; Tech will remove drop, pulled off job to hazardous condition on Alder dr, Truckee, per sup

dd6738; Resolve bad plant aerial drop issue

628; Her ticket request is to cut down all existing drops. Found additional drop wrapped around tree off side of r

t request cut down additional drops like previous ticket located loose cable and re-tied down or tightened addit

cket request cut down drop God as low as I could in between the snow and telephone pole To remove additiona

ont of customers house also removed from tree to secondary tree all the way back to customers premises, all v

dd6738; resolve bad plant issues

dd6738; Resolve bad plant issues

cd5628; Cable loose at pole near on-ramp re tach down

pg6512; Sent request to dig crew

UP VEGETATION TREES CAUSING ISSUES WITH POLE. DIDNT OBSERVE ANY TREE BRANCHES OBSTRUCTING

LEARANCE POLE AT 12880 PINE FOREST RD. OBSTRUCTING AERIAL SERVICE WIRE AND PUD POWER SERVICE

dd6738; Resolve bad plant issue

: Abel to raise up, drop another foot and a half almost 2 feet, still a little close to power. Able to cut down anothe

dd6738; resolve bad plant issues

pg6512; Removed drop off tree

628; Particular request increased high adjustment as well as located to additional drops from mid spans cut d

cd5628; Cut down loose drops, patrolled area, and found additional wires low and still needing to be cut down.

dd6738; Resolve bad plant issue

dd6738; resolve bad plant issue

dd6738; Resolve bad plant issues

dd6738; Resolve bad plant aerial drop issues

dd6738; Resolve bad plant issues

dd6738; Resolve bad plant issues

dd6738; resolve bad plant issues

cd5628; Per ticket, stated, case was damaged and open, looks like two new cases of already been replaced

dd6738; Resolve bad plant issue, other utility

owever remaining drop still buried underneath 8 to 10 feet of snow. Dug out as much as I can rest frozen and gr

op wire hanging from pole. Laying on the ground. Hazardous condition. Removed aerial drop wire from pole and

rial drop wire hanging from midspan. Laying on the ground. Hazardous condition. Removed aerial drop wire fro

jh3145; Aerial drop wire hanging from the pole. Removed aerial drop wire hanging from the pole.

dd6738; Resolve aerial drop bad plant conditions

dd6738; Resolve bad plant issues

location of drop wire. Cut one down. Secondary line was cable. Companies line left up for now. Went to go wor

cd5628; Per ticket request fixed bad plant condition. Case closed and rebuilt.

ıl drop wire hanging from pole. Removed aerial drop wire. Pulled up 2 6pr aerial drop wires with drop puller betw

jq2645; Remove down drop wire

h3145; Aerial drop wire hanging in trees from the pole. Removed aerial drop wire from pole and serving termina

cd5628; Assisted with CO help for another technician isolating F1 pair for Business. Was assigned ticket.

POLE was cable company. Still attached to property buried in snow utilize the remainder of time on ticket to get

pg6512; Removed drop from pole

jh3145; Aerial drop wire hanging from pole. Removed aerial drop wire.

cd5628; Ticket request, the drop was removed, and I reattached secondary drop to make it tighter and cleaner

pg6512; Removed drop at pole

cd5628; Per ticket, cut drops hanging from ground.

;cd5628; PC-Y; Standard routine ticket. Cut down low hanging drop. Per request; TN: 1234567890

pg6512; Removed limbs off cable

628; Per ticket request cut down loose hanging drop also noticed a low hanging drop and tightened back up at p
pg6512; Removed drop off pole

dd6738; Resolve bad plant issue

pg6512; Removed low drop and lashed cable to pole
jq2645; Remove down drop wire
PG6512; DOWN DROPS REMOVED ON SNOW FLOWER CAT AND PARTS OF SILVER FIR,
DD6738; RESOLVE AERIAL DROP ISSUE
l5; Aerial drop wire hanging from pole laying on the ground. Removed aerial drop wire from pole and serving terr

pg6512; Removed drop from pole
pg6512; Removed drop from pole
pg6512; Removed drop from pole, also closed case at 14830 glenshire dr
PG6512; CLEANED UP DROPS ON GROUND, REBUILT TERMINAL AT POLE ONE POLE SOUTH OF ADDRSZZ
pg6512; Sent order to dig crew
dd6738; Resolve bad plant issues

dd6738; Resolve bad plant kssue
pg6512; Removed drop off pole
pg6512; Removed drop off pole
removed drop from pole
jh3145; Aerial drop wire hanging low. Removed aerial drop wire.
dd6738; Resolve bad plant issues

pg6512; Removed drop off pole
pg6512; Sent job to dig crew to place cover
pg6512; Sent job to dig crew
pg6512; Removed drop off pole

ɔ wire hanging from pole. Laying on the snowbank Hazardous condition. Removed aerial drop wire from pole an
area however, there was not major cable, only a little bit that was needed to be cut down and removed drove up
dd6738; Resolve aerial drop issues
dd6738; Resolve aerial drop issues
pg6512; Removed drop on ground, construction has rehung cable, all go95 violations fixed
pg6512; Removed drop at pole
pg6512; Removed drop at pole
l drop wire hanging from pole. Laying in the snow. Hazardous condition. Removed aerial drop from pole and ser
pg6512; Removed drop off strand at pole
pg6512; Removed go 95 violations

pg6512; Removed hanging drop.
pg6512; Removed drop off tree near house

cd5628; Check for drops per ticket request returned back to base to transfer vehicle back over
dd6738; resolve bad plant issues
pg6512; Down guy issues, sent to construction

dd6738; resolve aerial drop issues
dd6738; resolve bad plant issue
al request. Looks like tree was already cut down prior to arrival assisted premise technician to help finish fiber a
JQ2645; DIG TICKET FOR TREE LIMB REMO

dd6738; Resolve aerial drop issues

t bad plant condition, isolated trouble and repaired per ticket. Request was given to additional POTS tickets wer
dd6738; Resolve bad plant issue, other utility
dd6738; Resolve bad plant issue

pg6512; Removed drop at pole
h3145; Aerial drop wire hanging from pole on ground. Hazardous condition. Removed aerial drop wire from pole
jh3145; Aerial service wire hanging from pole. Service wire is CATV.
pg6512; Removed drop at pole
628; Per ticket, forgot to close out at the end of day day assist with fiber, drop poles and cut down old copper li
cd5628; Per ticket request, removed half drop and dug out remaining drop on ground
dd6738; Resolve bad plant issues
dd6738; Resolve bad plant issues
dd6738; Resolve bad plant issues
dd6738; Resolve aerial drop bad plant condition
;cd5628; PC-Y; Cut down, drop per request, return to Garage to transfer vehicles; TN: 1234567890

dd6738; resolve aerial drop issues
request isolated drop cut down remaining from telephone pole. Walk neighborhood just to make sure no additi

pg6512; Removed drop off strand
pg6512; Removed cable off strand

dd6738; Resolve bad plant issue
dd6738; Resolve bad plant issues
ormed them that if I cut the drop, they could be charged from the cable company, however, they have a ticket cı

pg6512; Removed drop and closed up terminal

PG6512; REBUILT SPLICE, REMOVED BROKEN DROP,

jh3145; Aerial drop wire hanging low on ground. Removed aerial service wire from the ground.
cd5628; Cut down old drops and tied up cable
jh3145; Unable to locate address on Deerfield Drive. No pole address on RWM CIMI ticket.
cd5628; Per ticket request cut down drop tied around tree.
cd5628; Three loose drops hanging off of tree able to reach over and cut them off for safety
jh3145; Aerial drop wire hanging from pole. Removed aerial drop wire.
ket request cut down drop, also lifted up cable company drop as courtesy returned back to base to clean out an
cd5628; Per bad plant condition cut down one drop tightened up secondary drop
jh3145; Aerial drop wire hanging from pole. Removed aerial drop wire pole.
jh3145; Aerial drop wire hanging from pole. Removed aerial service wire.

dd6738; Resolve bad plant issues
pg6512; Removed drop from pole

jq2645; Remove down drop wire
dd6738; Resolve bad plant issues

;dd6738; PC-Y; Resolve aerial drop issue, proper distance between secondary and att drop; TN: Cbr
dd6738; Resolve bad plant issues
28; Per ticket request raised up customers drop another 1.5 feet. Drop is close to power but about 5 to 7 inches
cd5628; Repair services, cut down, unused drop raised up secondary drop
pg6512; Sent request to dig crew
jh3145; Aerial drop wire hanging from pole. Removed aerial drop wire from pole and serving terminal.
pg6512; Sent repair request to dig crew
pg6512; Fixed drop and send work request to dig crew
dd6738; Resolve bad plant issue
pg6512; Removed drop off pole
dd6738; Resolve aerial drop bad plant issues
et request located, and removed drop from telephone pole all the way down to the base and cut down cable con
cd5628; Removed 2 drops from pole
cd5628; Per ticket request isolated, cut down, drop also raised up an additional drop
cd5628; Remove drop per ticket request
jh3145; Aerial drop wire hanging from midspan. Removed aerial drop wire.
ut down, drop, secondary drop hanging low is a buried drop, so I cleaned it up against the telephone pole in cas
dd6738; Resolve bad plant issue
pg6512; Removed,drop from pole
dd6738; Resolve bad plant issue
pg6512; Removed drop at pole
pg6512; Removed drop from pole
pg6512; Removed cable wrapped around pole
;sm3126; PC-N; Cleared task
pg6512; sent broken conduit to dig crew, all other repaired made at pole
sf8537; sf8537; removed dead tree off cable.ccon advised

QB6851; ELIMINATE NON SERVICING DROPS SECURE PMT LID . REATTACHED DROP TO HOUSE
KS6734; REMOVED DEAD DROPS,
MD4156; REMOVED DOWN DROP AT DESIGNATED LOCATION
MD4156; REMOVED ATT WIRE ATREPORTED LOCARTIOM
QB6851; CHOP NON SERVING LINES FROM POLE
QB6851; ELIMINATE NON SERVICING DROPS AND ELEVATE EXISTING LOW DROPS
512; PC-Y; Bx9-trimmed several trees along lead and topped tree to prevent risk of falling on cable; TN: 5594487
QB6851; LOW DROPS ELIMINATED
QB6851; ELIMINATED LOW HANGING DROP
QB6851; CHOP MULTIPLE TREES LAYING ON CABLE IN REMOTE LOCATION
;cg4741; PC-N; Inspect and clear limbs off plant. Trees downed by storm
GG8932; ALL WORP COMPLETE.
QB6851; FOLIAGE CLEARED FROM LINES
QB6851; FOLIAGE CLEARED FROM LINES
QB6851; GO95 CLEARANCES CLEARED
QB6851; ELIMINATE NON SERVING DROP AND RAISE OTHER DROPS
3; FOUND 2 LOW CABLES. 1 AT 17 AND ONE AT 16 CENTER OF ROAD. EMAILED ROBERT ACHTER INFO AND PH
sf8537; installd and cable strapped to pole,secured f1 f2 splice case.
sf8537; sf8537; rmvd excessive strain on cable,terr
;sf8537; PC-Y; Removed excessive strain on cable; TN: 5309178926
QB6851; VEGETATION CLEAR FOR GO95
;gs6496; PC-N; pole swap and tree trimmed around lines
;js6852; PC-Y; Removed tree limbs from cable and rehung low hanging drops
rx3937; cleared troub
sc2675; removed downed abandoned drop and submitted bpc ticket
sc2675; removed downed abandoned drop and submitted 2 more bpc tic
sc2675; removed downed abandoned dr
;ra4618; PC-N; Vegetation removed from Lines
;ra4618; PC-N; Vegetation removed from lines
RA4618; VEGETATION REMOVED FROM LINES

KS8192; TREE HAS ALREADY BEEN REMOVED NEEDED TO CLEAR BRUSH AWAY ONLY ORDER IS COMPLETE
sc2675; removed encroaching vegetation from cable
sc2675; raised low drop
HP4528; TREE BRANCHS RMVD
sc2675; removed vegetation and downed abandoned drop
HP4528; RELASH FIBER TO STRAND DAMAGED BY TREE
sc2675; retrmd downed drop
sc2675; removed downed drop
sc2675; secured aerial service wire riser to pol
sc2675; removed downed abandoned drop
sc2675; removed downed abandoned drop and submitted bpc ticket
MD4156; GO95 QUALITY ROUTINE COMPLETE
sc2675; removed drop and did 25 pr section throw

sc2675; removed downed abandoned drops
;ra4618; PC-N; Tree foliage removed not affecting cable
sc2675; removed downed abandoned drops
cn2921; removed aerial drop hanging from pole.
sc2675; removed abandoned downed drop
tl3147; Remove asw from pole all clear
;gs6496; PC-N; Removed all drops broken on and around poles E & C
sc2675; removed downed drops
sc2675; reattached bsw to pole and fixed riser guard also submitted 2 more bpcs
sc2675; removed 4 downed drop
tl3147; Remove asw from pole to house
GS6496; ALL DRIVE HOOKS IN PLACE
tl3147; removed single pr asw abandoned from pole to house
;gs6496; PC-N; Trimmed branches around cable accessibility issues trees not on cable
MG1262; NO VEGATATION IN CLIMB SPACE
js3172; bad address no cable at the add
sc2675; removed downed abandoned d
KS8192; REMOVED VEGETATION FROM LINE AND A PARTIAL TREE BRANCH ORDER IS COMPLETE
;aw2727; PC-Y; ALL WORK COMPLETED, TRIM TREES; TN: 0000000
; PC-Y; 677 Sacramento raised saw???s, gps per ticket jay street, cable has been replaced, clrd tckt ; TN: 3606
KS8192; TREES AND BUSHES ALREADY REMOVED, ORDER IS COMPLETE
;aw2727; PC-Y; ALLWORK COMPLETED; TN: 0000000
cn2921; service wire is in a conduit.
js3172; place hardware on pole
cn2921; removed downed aerial drop.
sc2675; riser cover repaired
KS6734; PERFORMED TREE TRIMMING.
js3172; put in mark it
cn2921; placed drop cover over bsw and attached to pole.
sc2675; removed downed abandoned drop and submitted 2 bpc tickets
cn2921; placed cover over bsw, attached to pole.
pm8616; placed oversized guard on drop next to unguarded ground from power
pm8616; drop guard not needed, bump pole, drop secured to pole, locked gateded property, ok hv2377
sg1898; removed aerial drop.
sg1898; removed aerial drop.
COULD NOT LOCATE LOWER CABLE IN THE WOODS. WENT UP AND DOWN ROAD AT THE TROUBLE REPORT L
;kl2356; PC-N; Tree down / cable down removed hazard/ raised cable
ds4637; rehab work com
wa6713; SECURED BURIED DROP TO POLE, CANNOT PLEASE GUARD. TO MUCH OTHER STUFF IN THE WAY.
md2797; cleaned up & removed dead aerial drops
cn2921; protective riser cover placed on pole in question.
cn2921; drop on ground removed.
cn2921; Covered buried drop portion with plastic wrap.
RK7932; NO TROUBLE AT REPORTED POLE , DEF TERMINAL IN T ZONE , DID 50PR MINI SECTION THROW

RK7932; REPORTED AREA IS RAIL ROAD COMMUNICATION LINE NOT ATT LINE
;av1412; PC-Y; All clear no issues found at that location
MG1262; NO VEGATAION IN CLIMB AREA

;db8381; PC-Y; Drop already removed.; TN: 0000000000

;ac1532; PC-N; Removed trees from cable
;ac1532; PC-N; Removed trees from cable
;ac1532; PC-N; Remove tree from cable
;ac1532; PC-N; Removed tree from cable
rh749c; Done with task job completed
;ac1532; PC-N; Remove tree from cable
;ac1532; PC-N; Remove downed drop

;ac1532; PC-N; Remove tree from cable

;cc2745; PC-N; Trees been removed
;ac1532; PC-N; Remove tree from cable
ac1532; Removed defective drop
;ac1532; PC-N; Remove tree from cable
rh749c; not a drop, power also there
;db8381; PC-Y; Removed drop on ground.; TN: 0000000000
;ac1532; PC-N; Remove tree from cable
;ac1532; PC-N; Remove tree from cable
;ac1532; PC-N; Remove tree from cable
;ac1532; PC-N; Remove tree from cable
;ac1532; PC-N; Remove tree from cable
;cc2745; PC-N; Trees been removed
;cc2745; PC-N; Removed trees limbs
;ac1532; PC-N; Remove def drop
rh749c; Completed task job completed
;cc2745; PC-N; Tree removed
;ac1532; PC-N; Made drop over 6 feet from primary
;cc2745; PC-N; Tree been removed
;db8381; PC-Y; Removed service drop; TN: 0000000000
;ac1532; PC-N; Remove tree from cable
;ac1532; PC-N; Remove downed drop

;ac1532; PC-N; Remove tree from cable

;db8381; PC-Y; Removed service drop.; TN: 0000000000
;db8381; PC-Y; Removed drop.; TN: 0000000000
;ac1532; PC-N; Remove downed drop

;ac1532; PC-N; Remove downed drop
;ac1532; PC-N; Remove tree from cable
;ac1532; PC-N; Remove tree from cable
381; PC-Y; Put in dig for tree removal on spand between p31 to p32 French town rd.dig #21601870; TN: 000000
;ac1532; PC-N; Remove tree from cable
;db8381; PC-Y; Removed service drop on ground; TN: 0000000000
;ac1532; PC-N; Remove tree from cable
;ac1532; PC-N; Remove downed drop
dm258s; Cleared drop hanging from the pole
sf8537; sf8537; reattached drop Pole. 5308324143 & 5308324141.
md2797; removed dead aerial drops
lp848k; pg&e ground wire not telco lines.
lp848k; line is a buried service line that goes to prem. Does not need to be removed.
md4156; resolved drop issue at marked location
;mm3647; PC-N; Cables that need u guard are comcast.
;mm3647; PC-N; Place u guard over att wire. Comcast still exposed.
md2797; rehung low hanging drop through trees
45; PC-N; Waited for cr3845 for safety meeting,helped Am8121 on low drop, ok per cr3845, removed trees off c
js2145; all work is completed on this job.
qb6851; eliminate unused service drop and hardware
742; drove to street address gps coordinates. Drop removed from pole 11754. Not a hazard anymore. Pics tak
md2797; raised low hanging drop
SM1897; VEGETATION CLEARED
ROWN TREE BRANCHES LAYING ON OUR FACILITIES CABLE, TERMINALS AND DROP, ROAD BLOCKS 55 MINUT
FR1292; TRIMMED SOME TREE BRANCHES THAT WERE ON TOP OF OUR FACILITIES.
;ja1893; PC-N; Issue may have been prev resolved no trouble located
qb6851; riser secured to pole
lp848k; hanging line has been removed.
lp848k; downed line has been removed.
;jj6768; PC-Y; Job complete pole is marked for replacement by power company
qb6851; eradicated unused service drops .
dm820t; Installed riser guard over drops and secured loose buried drops to pole
dm820t; Secured drops to pole and installed riser guard
dm820t; secured u guard and buried drops
dm820t; secured, loose drops and wrecked out down drop hanging from the span
dm820t; no issues at reported location. Entered Markit ticket for bad, exposed section of cable.
lp848k; downed low hanging line has been removed.
dm820t; wrecked out downed drop at reported location
FR1292; REMOVED CLEARED FACILITIES CABLE DROPS AND TERMINAL BY TRIMMING TREE BRANCHES.
lp848k; Downed lines have been removed.
;jj6768; PC-N; Locate GO95 address pole marked by power company to replace job compete
lp848k; downed lines h
lp848k; downed lines have been removed.
;mm3647; PC-N; Remove limbs on cable

;jm1295; PC-Y; Facilities located ; TN: 4773022
md2797; removed downed drop through trees
qb6851; riser cover secured over cables
qb6851; installed new riser gaurd over service drop
qb6851; tree foliage cleared from telco lines
qb6851; installed new rise cover over multiple drops
qb6851; remove loose bent riser cover and install a new one
lp848k; new riser cover placed.
pc9347; loose cover riser reattach riser cover
dm820t; wrecked out downed drop at reported location
dm820t; wrecked out cut drop on clearance pole at reported loc
dm820t; Wrecked out downed drop at reported location.
rw5286; removed dead drop, repaired serving terminal;
lp848k; removed multiple downed lines.
;mm3647; PC-N; Place u guard over buried service wire
pc9347; drop low remove multi drops clean up around term dead drops
jm1295; completed buried splice on lower colfax
dm820t; removed slack and secured drops to pole .
dm820t; secured drops to pole at reported locat
lp848k; riser cover on pole
sb6349; cleared drop.
qb6851; secured riser cover and reattached service drops with drive rings . Removed unused service drops .
;mm3647; PC-N; Remove multiple broken drops leftover from snow storm winter 2023.
qb6851; telco lines cll
js2145; all work is completed on this job
md2797; replaced u-guard that was damaged.
dm820t; removed down bypass laying in bushes.
lp848k; downed line has been removed.
lp848k; downed line has been removed.
lp848k; low hanging line has been resolved.
lp848k; Riser cover placed.
;jm1295; PC-Y; Wrong address,16931 Oscar,corrected issue; TN: 4773022
;mm3647; PC-Y; Remove limbs for drop clearance.
dm820t; secured drops under existing risers
rd springs Rd needing guard replace or fixed? No missing or damaged guard in area?removed dead drop hangin
;dc2631; PC-Y; Safety issue verified complete ; TN: 5308675309
lp848k; downed lines have been removed.
lp848k; downed lines have been removed.
;dc2631; PC-Y; Safety issue resolution complete ; TN: 5308675309
;bk2151; PC-N; Tree line clear
lp848k; riser cover placed
qb6851; reroute and s3cur3 drops to pole . Intalss ugaurd around service drops
;dc2631; PC-Y; Go95 verified complete ; TN: 5308675309
;rw5286; PC-N; Fastened drop to pole;

lp848k; low hanging line issue has been resolved.
lp848k; riser cover placed
C-Y; Trim tree limbs from AT&T cable near pole at 17241 Virginia Way. Haul off half of the downed limbs ; TN: 55
:ated pole at 10552 Bragg ave.inspected pole,see no drop or obstruction in the way of safely climbing pole to ge
dm820t; secured buried drop to pole, it had slack and was loose but not abandoned.
;jj6768; PC-Y; Ran all drops out of climbing space job complete
dm820t; wrecked out downed drios
qb6851; installed riser cover over service drops
;ji2512; PC-Y; Bx9-trees removed after storm ; TN: 5594487061
;rw5286; PC-N; Removed dead drop;
md2797; rearranged drops going down pole & cleared vege
lp848k; cleared vegetation pushing down on line
md2797; trimmed trees around cable
md2797; Cleared vegetation from above cables
;am2764; PC-N; Vegetation Cleared
lp848k; placed new riser guard.
ess on ticket is Cross-box & RT. Customer at address said they had sycamore tree removed over a year ago whe
ess, pole is at 4 ways crossing, old pole removed, work done durning snowstorms of 22-23. No drop, no sni, pol
md4156; resolved drop issue at marked location
;jm1295; PC-Y; Corrected picture issues; TN: 4773022
;rw5286; PC-N; Repaired drop issue;
lp848k; removed downed lines
sb6349; dead drop removed
pc9347; Loose riser cover reattach hardware
pc9347; loose riser cover reattach riser cover
;dc2631; PC-Y; GO95 issue verified with land owner complete ; TN: 5308675309
rb2427; cable lifted up off the ground
;jm1295; PC-Y; Locate completed ; TN: 4773022
sb6349; drop removed
ml1973; obstructions cleared
lp848k; downed lines have been removed.
md4156; placed riser at marked location
;ja1893; PC-N; Removed dead drops, advise sub needs to reenforce c pole,
;mm3647; PC-N; Reattach aerial drops to pole and place u guard over bsw on pole.
lp848k; downed lines have been rem
lp848k; low hanging line has been resolved.
qb6851; qb6851; routine ticket completed
qb6851; qb6851; routine ticket compl
qb6851; qb6851; resucured and realigned service drop atta
JI2512; BX9-TREE TRIMMING DONE BY TREE CREWS GOING THROUGH NEI
;jj6768; PC-Y; Drop is as low as I can get it and maintain clearance job complete
dm820t; installed u guard to cover buried drop coming down pole at reported location
;ja1893; PC-N; Dropwork,slightly lower. Good perimeters
dm820t; no hanging cable at reported location. Lash was broken near by so I secured cable back to strand

md2797; removed dead aerial drops
;rw5286; PC-N; Raised low drop;
;rw5286; PC-N; Reattached 25pr terminal to pole;
md2797; trimmed trees around cable
VC6131; VEGETATION AND DEAD DROP ON GROUND, REMOVED VEGETATION AND DEAD DROP
qb6851; remove non servicing drops from terminal
js2145; placed riser, reattached drops, all w
r foliage at bottom of hill where maps pinged. Address didn???t quite match sub says end of road, says Att out
dm820t; installed u guard over drops on pole per reported trouble ticket
lp848k; downed lines have been removed.
lp848k; downed lines have been removed.
lp848k; downed lines have been removed.
lp848k; downed lines have been removed.
qb6851; eliminate low hang8ng drop
dm820t; ran new cat5 hr and placed new jack at 10776 lone heron ct.
js2145; all work is completed on job
;jm1295; PC-Y; Facilities located,also tree trimming 13375 Lola rica; TN: 4773022
rw5286; removed multiple drops; rebuilt terminal;
md2797; Removed dead aerial drops
rw5286; drop issue, resolved;
qb6851; decommissioned multiple non conductive service drops
pc9347; Place new 8fl drop iss
jm1295; comp assist T1 colfax hwy
sb6349; Drop removed.
rx3937; drop,wol 3 poles worth to rattle snake road
rx3937; removed 3 aerial drops and all drops and sni from abandoned trailer
;we5739; PC-N; Removed long drop.
md2797; removed downed aerial drop
md2797; removed downed aerial drops
;jj6768; PC-Y; Job complete address was wrong though
md4156; resolve drop issue at marked location
jo1454; All work completed no ccon
pc9347; drop low remove old drop
;rp6278; PC-Y; Riser cover completed; TN: 530
;ja1893; PC-N; Cut and remove tres from lines raising and providing clearance
2675; UNABLE TO REACH POLE, GATE, REMOVED DOWN DROPS ON OTHER POLES, NO TROUBLE SEEN AT OC
;rp6278; PC-Y; Riser cover is completed and place drop rings on pole.; TN: 530
;jm1295; PC-Y; Facilities located ; TN: 4773022
;kl2356; PC-N; Def drop / rr drop / test ok w cx
kl2356; def drop   remove drop   hazard Cl
md2797; removed downed aerial drops
md2797; removed downed aerial drops
;ji2512; PC-Y; Trees already topped by pg&e; TN: 5594487061
md4156; drop issue resolved at marked location

;bk2151; PC-N; Tree line clear
qb6851; elimated unused service drop
sb6349; removed dead drop from 3 pole spans thru heavy foilage
;jm1295; PC-Y; Facilities located ; TN: 4773022
bandon shack house, between 2 curves in road. Boom up in bucket at upper location to look down cable path,
lp848k; line has been raised back up.
md2797; rehung low hanging drops through trees
;mm3647; PC-N; Rem broken drop at clearance pole.
this address from AT&T,the service for this address is fed underground. There are two aerial drops from Comcas
N; Removed dead drop,raised two other drops,trimmed trees off lines. Travel to Hotel and back, personal emerg
md2797; removed downed aerial dr
qb6851; eliminate multiple service drops
dm820t; pulled up slack out of buried drop and secured drop and guard back onto pole
dm820t; secured all lines on pole.
dm820t; removed multiple downed drops at reported location
dm820t; trouble reported is a PG&E ground line with no riser. No AT&T issue at this lication
qb6851; bpc ticket comp,eyed drops removed
dm820t; installed riser to cover buried drop at reported location.
;ji2512; PC-Y; Bx9-cleared climbing area ; TN: 5594487061
lp848k; riser cover on pole.
lp848k; No riser cover on pole. Removed downed lines from pole.
pictures isn???t a drop, it???s the tail of support strand for Comcast services feeding away from pole. Pulled st
lp848k; removed downed lines from pole.
;dc2631; PC-Y; Safety issue resolved complete ; TN: 5308675309
dm820t; secured loose drops to pole and wrecked out downed drops.
md4156; resolved p3028 at marked location
md2797; removed dead drops
lp848k; riser guard placed
md4156;
md4156; removed down drop at marked location
rw5286; removed dead drop;
rw5286; aligned drop to pole;
;jm1295; PC-Y; Facilities located ; TN: 4773022
dm820t; secured drops to pole at reported location
dm820t; secured multiple drops to pole
dm820t; secured lose hanging drops to pole
ml1973; deviation cleared
lp848k; downed drops have been re
dm820t; wrecked out multiple drops and a 6 pair can that had been left on the ground next to the pole.
lp848k; down drops have been removed.
qb6851; eliminate low hanging service drops
qb6851; resecured riser gaurd and re dressed wire up the pol
; Created dig ticket for tree cutting, entire climbing space and aerial facility access blocked by tree and branche
o pole location and remove 5 pair messenger drop from terminal and strand. Place waste in back of bucket truc

;jm1295; PC-Y; Facilities located ; TN: 4773022
1893; PC-N; Possible 18524? Needs 2nd power raised to maintain clearance over driveway, reterm can and bs
md2797; rehung riser cover on pole
md2797; removed dead drops
md2797; raised low hanging aerial dr
Remove drop not service affecting
Cable tv low advise cu
;js2145; PC-N; All work completed
lp848k; Low hanging lines ha
md2797; Trimmed tree branches off of cable
AM8121; INSPECTED SITE. WORK WAS ALREADY COMPLETE UPON ARRIVAL.
Raise low drop down driveway.
vc6131; drop down, removed dead drop
vc6131; drop down, removed dead drop
jo1454; all work completed no ccon
;bk2151; PC-N; All facilities/cable ok
;jm1295; PC-Y; Facilities located ; TN: 4773022
AG2675; TREE TRIMMERS TRIMMING AROUND POLE AS I ARRIVED
eattached multiple splice boxs and installed riser dairy over exposed service drops and eliminated un used serv
;rw5286; PC-N; Removed drop spans;
qb6851; Resecured riser cover
qb6851; Eliminate non conductive service drop
qb6851; Attached riser cover to pole covering service drop
;am2764; PC-N; Vegetation Cleared
lp848k; downed lines hav
;mm3647; PC-Y; Remove broken drop that was wrapped around pole
pc9347; drop low remove safe
pc9347; Riser cover loose reattach riser cover
md4156; removed drop at marked location
;rw5286; PC-N; Placed riser over buried drop at pole;
;rw5286; PC-N; Removed drop;
md4156; low drop issue resolved at marked location
;rw5286; PC-N; Aligned drop with pole;
;mm3647; PC-N; Gate locked to property. Removed 3 broken drops along the road.
md2797; replaced u-guard to protect cabl
qb6851; eliminate non conductive service drops
;jm1295; PC-Y; Facilities located ; TN: 4773022
;bk2151; PC-N; Facilities good
lp848k; Riser guard up
;jr8198; PC-N; Package completed
rw5286; removed dead drop;
qb6851; go95 ticket comple
lp848k; lines have b
lp848k; downed lines have been removed.

;mm3647; PC-N; Remove broken drop from pole and house.
dm820t; wrecked out
dm820t; wrecked out downed drop and removed shoes from midspan cable.
;rw5286; PC-N; Aligned drops with riser;
qb6851; rehab ticket completed
;bk2151; PC-N; Facilities good
qb6851; Resecured serice drop and riser cover to pole
qb6851; phone cables secured to pole other lines are cable company lines
qb6851; resecured riser cover and other attachments to pole
pc9347; loose riser cover reconnect riser cover clean up area
pc9347; drop low not in service remove drop
pc9347; missing riser cover place riser cover
;rw5286; PC-N; Drops aligned to pole;
;mm3647; PC-N; Rem abandoned/broken drop from pole and trees.
;ja1893; PC-N; Clear tees from cable, relash, hazard gone
;mm3647; PC-N; Rem down drop from demolished house.
dm820t; wrecked out 2 drops. No issues at reported location that would require riser cover
dm820t; placed riser guards over buried drop
qb6851; attached no riser cover to pole over service drop wire
qb6851; bpc ticket closec
qb6851; installed riser cover
qb6851; installed riser cover over service drop
AG2675; REMOVED DEAD DROPS, AT 13422 S PONDEROSA AT POLE,
SM1897; CLEARED DROP FROM CLIMBING SPACE
pc9347; drop low no service remove drop
dm820t; wrecked out multiple drips
lp848k; waited for tree crew to finish work. Removed hanging lines.
js2145; removed drop from ground, all work c
md4156; go95 issue resolved at marked location
;we5739; PC-N; Removed two low drops,and remounted terminal.all work completed.
qb6851; eliminate multiple service drops and reroute existing lines at terminal
qb6851; eliminate multiple unused servic3 drops
lp848k; downed lines have been removed.
md4156; drop issue resolved at marked location
lp848k; riser cover placed back on pole.
qb6851; place u gaurd over service drop on pole .
;mm3647; PC-N; Place u guard over bsw.
to 14909 Kelsey ln.checked the only pole that feeds customer at address mentioned.already has cross arm pla
;el8648; PC-N; Drove to location at 19164 Wolf Creek rd didn???t find any low drop or cable.
;mm3647; PC-N; Remove dead, broken drop wrapped around pole.
md4156; drop removed at marked location
qb6851; resecured riser gaurd
qb6851; riser cover secured to pole
;mm3647; PC-N; Rem broken drop hanging from pole.

vc6131; drop down, reattached drop

noved from house and left hanging off of support pole. Boom up new top of pole & reattach coils of drop wire for

pc9347; riser cover loose reconnect clean up around area

qb6851; Drop wires secured on private pole

qb6851; Installed riser cover over cable in pictures.

pc9347; riser cover loose repair

OD4318; DROP REMOVED. TOK

pc9347; drop low no service remove drop

vc6131;

we5739; trimmed trees back off cable lines at pole 19 near 11220 Bitney Springs Rd,no drop to remove?

vc6131; drop down, removed dead drop

md4156; ed drop issue at marked location

sb6349; all work compl

mm3647; reattach can to pole and raise drop over driveway.

qb6851; go95 ticket comp

;mm3647; PC-N; Put down drop back up

qb6851; routine ticket closed

qb6851; remove service drop thru multi0le trees

and placed riser guard, also helped sb6349 at 17973 Wallis dr test and isolate trouble, recover pair and replace

vc6131; missing riser, installed riser, also dead drop, removed dead drop

;bk2151; PC-N; Tree line clear

vc6131; missing riser, installed riser

pc9347; riser cover loose fix clean up around srea

Remove low dead drops

s,checked facilities,no drops to prim to remove,buried drop to this address.no other drops in area low or needin

md2797; Rehung downed aerial drop

pc9347; riser cover loose reconnect riser cover clean up arae

vc6131; drop down, removed dead drop

vc6131; drop down, removed dead drop

md4156; riser placed , secured loose drive rings on pole, loose wire next to Att b drop is comcast.

pc9347; drop low raise drop clean up space

md4156; resolved low drop issue at marked location

jo1454; all work comp

647; remove broken drop still attached to pole. Also low drops (working) attached to a trailer. Definite go95 viola

;ja1893; PC-N; Remove branches, remand drop to guard arm

AM8121; INSPECTED SITE. NO HAZARD FOUND.

rw5286; placed riser at pole for buried drop;

;ja1893; PC-N; Removed branches place slicks

vc6131; drop down, also needed riser, installed riser, reattached drop

rw5286; tightened drop to pole, no room for riser;

vc6131; missing riser, installed riser

js2145; had to help deg recover pairs to lop co, then went to this job, all work is c

vc6131; missing riser, placed riser

vc6131; drop down, removed dead deop

ging drops. Joint Support pole between 13421 & 13423 replaced during last winters storms. Checked all 5 hous

qb6851; resecured riser cover

qb6851; eliminate multiple service drops

qb6851; remove and disconnect obsolete service drops

qb6851; remove unused ugaurd and service drop

js2145; reattached drop placed riser, all w

;di1638; PC-Y; Follow 1st a, on new arm; TN: 1

Brewer and found clearance pole on private property.called fellow tech and he says we don???t put cross arms

js2145; all work is complete on this Jo

js2145; all work completed on this job and removed drop from neighbors house

;bk2151; PC-N; Tree line clear

jo1454; removed hazardous conditions on pole near busy road highwY

jo1454; removed hazardous conditions and drops, raised low drops and lashed cable

jo1454; removed abandoned drops, readied low drops, re-lashed cable strand, no ccon

;ja1893; PC-N; Remove limbs rpl bags w slicks

tion is not accessible as it is in fenced area on private property and is on a clearance pole not a normal utility po

rw5286; raised low drop; service restored;

rw5286; removed dead drop;

;ja1893; PC-N; Remove branches, place slicks,

s lose, hanging off pole or hanging from terminals, reterminated drops, placed guides all the way up the pole fas

qb6851; eliminate hanging no conductive service drops and resecured terminal to strand .

ww1427; ww1427; go95 cleared

qb6851; install riser guard over telco drop on clearance pole deep into property.

vc6131; drop down, removed dead drop

;we5739; PC-N; Removed old dead drops,and cleaned up terminal.all work completed.

;mm3647; PC-N; Guard placed over buried service wire on pole.

lp848k; down line has been removed.

lp848k; down lines have been removed

lp848k; down line has been temove

dm820t; wrecked out multiple

;mm3647; PC-Y; Raise low drop by adding mid span attachment.

dm820t; wrecked out down, drop by hay

;mm3647; PC-N; Remove down drop. There is more behind locked gate.

;am2764; PC-N; Vegetation Cleared

le indicated by ticket and remove drop. Took before and after pictures. Cleanup location. Local Fiber also on st

vc6131; drop down, removed dead drop

;js2145; PC-N; All work completed

;mm3647; PC-N; Low drop with no service. Drop was defective and sub wanted it removed.

vc6131; installed u guard on pole

to address, pole is first on left part way up driveway, no more down drop, new drop already placed. took pics, ac

sm4953; sm4953; t small tree limbs not hazardous

;jm1295; PC-Y; Facilities located ; TN: 4773022

vc6131; drops down, removed dead drops

qb6851; reroute resecure drops and riser gaurd. Marked with dig sticker

js2145; all work completed on this job.
js2145; job is completed.
jm1295; completed big package
jm1295; package completed
ɔ had broken loose from house and was low across street. Reattached drop to the house and raise to acceptabl
;jm1295; PC-Y; Facilities located ; TN: 4773022
;jm1295; PC-Y; Corrected drop,repaired BAN 136837515 hwy 20; TN: 4773022
pc9347; riser cover loose reconnect clean up around area
pc9347; riser cover loose drop exposed reattach riser cover
pc9347; drop low remove drop clean up around area
;bk2151; PC-N; Facilities good
vc6131; drop down, removed dead drop
Drop down, removed dead drop
;bk2151; PC-N; Facilities/cable ok
vc6131; drop down, removed dead drop
ml1973; rep fixtures
vc6131; drop down, removed dead drop
vc6131; Two down drops, removed dead drops
ww1427; ww1427; go95 cleared
jo1454; FVD indicated energized drop pole discharged and removed drops
jo1454; all work completed no ccon
m820t; went to remove downed drops at reported location but there is a new pole in place with no downed drop
dm820t; removed downed drop from reported address
dm820t; wrecked out multiple drio
rw5286; recovered pr 104; service restored;
js2145; all work completed on this jo
;we5739; PC-N; Placed cable guard over buried drop wire running up pole,all work completed.
vc6131; Drop down, removed dead drop
mm3647; reattach 6 pr can to pole.
Raise low drop. Order riser covers.
mm3647; remove broken drop.
;mm3647; PC-N; Remove broken drop from house and pole.
pc9347; riser cover loose drop clean up area reattach riser cover
pc9347; riser cover clean up area reattach riser cover
md4156; Issue resolved at marked location, u-guard placed on pole
;rw5286; PC-N; Removed dead drop;
;rw5286; PC-N; Removed dead drop;
we5739; placed pole guard over buried drop coming up pole,all work completed.
md2797; low aerial drop
js2145; all work is completed on this job
js2145; all work completed on job
vc6131; drops down, reattached drops,
;jm1295; PC-Y; Corrected BAN#136837515,nev.city,also 5304770830 grass valley; TN: 4773022
pc9347; our drop above 8 cable tv service drops low below 8

;mm3647; PC-N; Raise low drop over road.
;mm3647; PC-N; Raise low drop and remove broken/dead drops.
vc6131; drop and cable low, removed dead drop and cable
pc9347; remove drop wire clean up dead drops at pole
vc6131; dead drop, removed dead drop
;rw5286; PC-N; Removed dead drop;
;jm1295; PC-Y; Facilities located; TN: 4773022
vc6131; drop down, removed dead drop
vc6131; drop down, removed dead drop
md4156; qr ticket issue resolved at marked locatiom
lp848k; routine maintenance ticket
ɔt found, no GO95 violations noted in area, guard arms are placed by construction line crew not maintenance sp
qb6851; drop eliminate
cg4741; removed hazardous drops
ag2675; all work comple
md4156; quality routine complete at marked location
gg8932; place plastic riser guard over buried service drop. Awc. Assist cg4741 cold stream rd.
pc9347; missing cable guard place guard safe
vc6131; go95 routine ticket, placed guard on riser
qb6851; rerouted drops on pole and install u gaurd
gg8932; all low lines have been removed. No others found. Input fiddle creek bpc x2.
pc9347; cable guard missing place cable guard
qb6851; secured service drop to clearance pole on private property
cg4741; roamed drop 3 poles down from location. No access to 15050. Removed drop 19078 Bitney spr
ag2675; all work compl
qb6851; elimated vacated servic3 drops
qb6851; routine ticket completed
cg4741; all work complete. Manager Eric Koppes
gg8932; all work complete per local sup Eric.
address search for pole address locate pole and install gaurd over drops . Major atlas issues affecting dispatch
mm3647; remove dead, broken drop from pole and across property.
;jm1295; PC-Y; Facilities located; TN: 4773022
SF8537; REMOVED HAZZARD ASW POLE
Bsw riser guard installed
sf8537; Rmvd abandoned asw and secured treminal.
;sf8537; PC-Y; Rmvd abandoned asw.; TN: 5309178926
sf8537; Secured bsw,no riser guard required
sf8537; Ntf,ATT network no iisues per picture.
sf8537; Non ATT issue, ground wire for power monitoring un guarded.
sf8537; Bsw secured,no riser guard required
sf8537; NTF ATT,rmvd coax hazzard.
sf8537; Secured bsw,no guard required
sf8537; Bsw secured, no riser guard required
sf8537; Bsw secure,no riser guard required

sf8537; Secured bsw,no riser guard required,ring run up po
sf8537; Secured bsw in guard, ring run up riser good
sf8537; coax cable tv wire, NOT att issue.
sf8537; riser guard installed
;sf8537; PC-Y; Removed on other repair job,ntf. This was a tv coax wire hazzard. Non ATT.; TN: 5309178926
;sf8537; PC-Y; NTF ATT, coax tv wire unguarded on riser.; TN: 5309178926
sf8537; riser guard installed
sf8537; Bsw riser guard and drive rings.
sf8537; Secured bsw, hazzard cleared
sf8537; ntf not a hazzard due to location.
sf8537; Installed riser guard and ring run up pole.
7; NEED TO CHK MAINTENANCE CONTRACTOR ABOUT WORKING IN THE CALTRANS RIGHTOF WAY FOR TREE \
sf8537; rmvd abandoned asw hazzard.
sf8537; installed bsw riser guard.
sf8537; NTF ATT, coax with other company.
sf8537; P14, bsw secured,no guard required
sf8537; Secured bsw,no guard required.
sf8537; Bsw secured,no riser guard required
sf8537; Secured bsw,no riser guard required,P5 at 5685 casey jones per pics.
sf8537; Secured bsw,ring run and secured cable.P12 5875 casey jones per pics.
sf8537; Secured bsw,no riser guard required
sf8537; Rmvd abandoned asw, secured terminal
sf8537; noATT issue,coax cable is not in a riser guard.
sf8537; riser guard installed over bsw
sf8537; bsw riser guard installed,ring run up pole
sf8537; P23, secured bsw,no guard required.
;sf8537; PC-Y; Bsw riser gurd installed; TN: 5309178926
sf8537; Secured bsw,no riser required.
sf8537; P29, secured bsw,noguard required
;sf8537; PC-Y; Riser guard bsw installd; TN: 5309178926
sf8537; riser guard installed bsw
;sf8537; PC-Y; Riser bsw and rmvd abandoned asw; TN: 5309178926
;sf8537; PC-Y; Rmvd abandoned asw.; TN: 5309178926
sf8537; NTF ATT,coax issue is other company.
;sf8537; PC-Y; Bsw riser installed; TN: 5309178926
sf8537; riser guard and ring run complete
sf8537; bsw riser guard installd
sf8537; asw hazzard removed
sf8537; Secured bsw conduit,
sf8537; secured bsw riser and drive rings.
;sf8537; PC-Y; Ntf ATT, coax tv wire exposed.; TN: 5309178926
;sf8537; PC-Y; Bsw secured,no riser guard required.; TN: 5309178926
;sf8537; PC-Y; Ntf,bsw secured, no riser guard required.; TN: 5309178926
sf8537; Secured bsw, coax hang- non ATT issue.

sf8537; POWER service drop,local LIBERTY POWER texh advised,NTF ATT.
sf8537; Riser guard installed
sf8537; Ring run reattahed bsw,tv coax hanging
sf8537; NTF ATT, exposed ground wire is power company
'; PC-Y; Refered tree on cable to construction dept. P1 to P2 going uphill to radio hill, fiber- cable lead; TN: 5309
sf8537; rmvd asw hazzard
sf8537; Secured bsw,no riser guard requred. P 12 Delleker dr per gpsand pics
;sf8537; PC-Y; Riser guard installed.; TN: 5309178926
;sf8537; PC-Y; Bsw ring run good,no riser cover required.; TN: 5309178926
;sf8537; PC-Y; NTF ATT,conduits exposed?, no ATT services in conduits, only COAX tv wire.; TN: 5309178926
;sf8537; PC-Y; Previously done, asw remaoved.; TN: 5309178926
sf8537; Rmvd abandoned asw, secured term.
sf8537; bsw hazzard rmvd
sf8537; rmvd asw hazzard
sf8537; rmvd all ATT asw issues on Clarence ln.
sf8537; already did this one prior to dispatch.
;sf8537; PC-Y; Riser guard installed@ 319 s mill creek,per pics; TN: 5309178926
sf8537; secured bsw riser guard,COAX non ATT has no guard. Rmvd abandoned asw P162 s mill crk also.
;sf8537; PC-Y; Rmvd hazzard asw.; TN: 5309178926
;sf8537; PC-Y; NTF ATT NETWORK,COAX cable tv issue.; TN: 5309178926
sf8537; bsw riser guard placed and drive rung up pole.
sf8537; rmvd asw hazzard.
sf8537; Previously done on other custome repair.
sf8537; NTF ATT network,old TV coax network wire on ground.
sf8537; found 954 Lk Davis rd,P7 Kandy ln.bsw riser guard installed.
sf8537; asw previously removed when doing other near by.
sf8537; Non ATT issue,COAX tv network,other company.
sf8537; rmvd asw hazzard
sf8537; guard installed grounding wire
sf8537; installed bsw riser cover guard for ATT. Coax is not ATT.
sf8537; ntf due to location,not a public hazzard.
sf8537; ntf, existing conduits ok.
sf8537; Rmvd haazrd coax-non att
sf8537; Rmvd abandoned asw,rpr guard& bsw
sf8537; Exposed conduits buried
sf8537; riser guard installed.
sf8537; rmvd asw hazzards,installed bsw riser guard
sf8537; rmvd abandoned asw hazzard
;sf8537; PC-Y; Replaced riser guard.; TN: 5309178926
;sf8537; PC-Y; Rpr riser guard; TN: 5309178926
;sf8537; PC-Y; Bsw riser guard installed; TN: 5309178926
;sf8537; PC-Y; Rmvd abandoned bsw; TN: 5309178926
;sf8537; PC-Y; Riser guard installed.; TN: 5309178926
;sf8537; PC-Y; Rmvd,COAX hazzrd,non ATT issue.; TN: 5309178926

;sf8537; PC-Y; Rmvd asw hazzrd; TN: 5309178926

sf8537; rmvd abandoned asw.

sf8537; rmvd abandoned asw, expose grounf wire is not ATT network

sf8537; secured all on pole and rmvd asw across street hanging off pole.

sf8537; previously done prior to dispatch.

;sf8537; PC-Y; Buried cable near 86 S Linden,ntf; TN: 5309178926

sf8537; reattached asw hanging for rear unit.

sf8537; ring run asw up pole,secured conduit

sf8537; installed bsw riser guard, ground wire is power company

sf8537; secure bsw ATT network.

SF8537; NEED TO CHK MAINTENANCE CONTRACTOR TO TRIM VEGETATION ON CALTRANS RIGHT OF WAY.

SF8537; NEED TREE SERVICE ON CALTRANS RIGHT OF WAY, WILL CHECK WITH MAINTENANCE CONTRACTOR

sf8537; rmvd anandoned asw hazzard.

sf8537; installed bsw riser guard

sf8537; Ntf ATT, coax tv wire issue

sf8537; Ntf ATT,,ntf,ntf,ntf

sf8537; NTF ATT, coax riser hanging

sf8537; Installed bsw riser guard

sf8537; NTF ATT, coax wire other company.

sf8537; rmvd hazzard

sf8537; rmvd hazzard P2088 e main per pics.

sf8537; riser guards installd

sf8537; rmvd asw hazzard

sf8537; secured ATT riser guard, coax cable is not ATT

;sf8537; PC-Y; Rmvd bsw hazzard and secured asw.; TN: 5309178926

sf8537; rmvd coax once again

sf8537; reattahd bsw riser to term.

e down road, had to park truck. Based on Geo location there is already a case in place. However, case was popı

jh3145; Unable to locate Sheep Camp Rd in Chilcoot-Vinton Doyle area.

access one drop. Close by customers property, however, unable to access secondary drop further out due to w

3145; Unable to locate area where aerial drop is hanging from pole. New poles transferred due to fire in Doyle ar

ain highway one side had too much mud potential issue getting truck stuck, would be about a 4 mile hike from t

5; Aerial drop wire hanging from pole. Laying on the ground. Hazardous condition. Removed aerial drop wire fror

sf8537; rmvd coax,contractor seems not to know what is what.

sf8537; rmvd coax ?.

SF8537; SECURED ASW ON POLE.

SF8537; SECURED ASW,

SF8537; SECURED ASW P7B6

SF8537; HARDWARE ATTACHED,SECURED ASW.

DL4872; FACILITY MAIN

NAASW12313 CRESCENTASW IS CUST OWNED AT REPORTED ADDRESSREPLACED ASW ON ROAD AT NEIGHB

SF8537; RPLD TEMP ASW W NEW SPAN,DTCPE

SF8537; PLACED NEW ASW,DTSNI

;js2145; PC-N; All work completed

SF8537; REHAB ASW AND TERMINAL, AND SPLICE

rw5286; removed old drops; raised low drops;

SF8537; REMOVED BRANCHES OFF CABLE, REPLACED ASW 58 WILLOW WY- 5302830200.

SF8537; REMOVED HANGND ASW AND SECURED TERMINALS, P572 522 500 BELL LN

;js6852; PC-Y; Removed tree limbs from cable and rehung low hanging drops

QB6851; CABLE NO LONGER SAGGING TO THE GROUND

SF8537; WORKED DT5308367301-C.O. JMPRBLRSCA01. LOCATE N SCOTT RDHWY70.

SF8537; REATTACHED RURAL WIRE AT CEDAR TREE.

SF8537; REPLACED DEF ASW, 5302839673

N AND REMOVE FALLEN PINE TREE LAYING ON STRAND AND CABLE. HAZ COND BAD PLANT CONDITION TRBL

JS3172; MADE DIG TO CLEAR TREE FROM CABLE

GG8932; HEAVY TREE REMOVAL FROM CABLE AND STRAND, ALL WORK COMPLETE.

N MID SPAN. AWC. BROKEN LASHING WIRE HANGING CABLE ALSO REPAIRED MAIN STREET. ATLAS DISPATCH

sc2675; Removed downed abandoned drop

VC6131; VEGETATION ON LINES, TRIMMED VEGETATION

PC9347; TRIM FOLIAGE AROUND POLE AND CABLE

PC9347; TRIM FOLIAGE AROUND POLE AND CABLE

PC9347; TRIM FOLIAGE AROUND CABLE AND POLE

VC6131; VEGETATION ON LINES, TRIMMED VEGETATION ON LINES

AG2675; CLEARED TREES AND LIMBS FROM CABLE, ALL WORK COMPLETED
PC9347; TRIM FOLIAGE AROUND POLE AND CABLE
;cg4741; PC-N; All work complete. Assist ji2512 with street crossing
CG4741; ALL WORK COMPLETE. REMOVED TREES
GG8932; ALL WORK COMPLETE.
MO1513; POLE HAS BEEN REPLACED, TRIMMED REMAINING BRANCHES OFF OF CABLE.
;jm1295; PC-Y; Facilities located; TN: 4773022
;jm1295; PC-Y; Facilities located; TN: 4773022
PC9347; TRIM FOLIAGE AROUND CABLE AND POLE
GG8932; TREE VINE TRIMMING AND REMOVAL LAVA ROCK NOT SLOW POKE. AWC.
GG8932; ALL WORK COMPLETE.
JS2145; TREES CLEARED, ALL WORK COMPLETED ,,,,,,,
MD4156; FOLIAGE CLEARED AT MARKED LOCATION.
SB6349; ALL WORK COMPLETED.
OD4318; ALL TOK. NOW
CG4741; TRIMMED TREES
QB6851; CLIMBING SPACE CLEARED
T; CLEARED AWAY TREE FROM CLIMBING SPACE AND BIG LIMBS PUSHING DOWN ON CABLE. REMOVED CUT I
MD4156; VEGETATION CLEARED AT MARKED LOCATION
VC6131; VEGETATION ON LINES, TRIMMED VEGETATION
VC6131; VEGETATION ON LINES, TRIMMED VEGETA
MD4156; VEGETATION REMOVED AT MARKED LOCATIOM
;rw5286; PC-N; Trees on line between p15 and p16 American Hill Rd; created Dig it request for tree trimming;
MO1513; POLE HAS BEEN REPLACED. TRIMMED REMAINING TREE BRANCHES OFF OF STRAND AND CABLE.
LP848K; TRIMMED TREE FROM CABLE
;jm1295; PC-Y; Drove to auburn to retrieve chainsaw,truck locked in maintenance bay; TN: 5304773022
CG4741; TRIMMED LIMBS OFF STRAND. HIGH LEVEL TRAFFIC WARNING SY
MD4156; QUALITY ROUTINE CLEARED
;rw5286; PC-N; Trees not service effecting;
GG8932; TREE VINE TRIMMING REMOVAL FROM CABLE AND STRAND BRUNSWICK RD.
MM3647; REM FOLIAGE FROM CABLE
ER. PRIVATE PROPERTY ACCESS. FULL POLE STRAND CABLE INSPECTION, NO DEFLECTION, NO HAZARD OBSI
932; TREE BRANCH REMOVAL FROM CABLE AND STRAND COMPLETE. ONLY BRANCHES LEANING ON PLANT. A
MM3647; REM FOLIAGE FROM CABLE POLE.
JM2792; REMOVED TREE BRANCHES OFF CABLE THAT WERE SAFE TO REM
;mm3647; PC-N; Trim limbs fr9m cable near address.
ANCHES LAYING ON STRAND AND CABLE. MOVED SEVERAL BELOW TELCO PLANT. TREE ALREADY BUTCHERE
;jm1295; PC-Y; Completed/pressure wrap.burried facilities Zion street; TN: 5304773022
JM2792; REMOVED VEGETATION THAT WAS ON CABLE, MOVED AS MUCH AS POSSIBLE SAFE
GG8932; TREE LIMB REMOVAL FROM CABLE AND STRAND. AWC.
;jm1295; PC-Y; Completed plant condition; TN: 4773022
;mm3647; PC-N; REM branches from around pole and strand.
MD4156; VEGETATION CLEARED AT MARKED LOCATION
VC6131; VEGETATION, CLEARED VEGETATION

PC9347; TRIM FOLIAGE AROUND POLE AND CABLE
AG2675; CLEARED TREES OFF CABLE ALL WORK COMPLETED

BPC #1008137

rw5286; Removed drop; no other faults isolated;
PC9347; TRIM FOILAGE AROUND POLE AND CABLE
PC9347; TRIM FOLIAGE AROUND POLE AND CABLE
G8932; TREE BRANCH REMOVAL IN FRONT OF CO, ALL BRANCHES REMOVED FROM CABLE AND STRAND. AW

pg6512; Vegetation cleared from cables
jh3145; Aerial drop wire hang from the pole. Removed aerial drop wire from the pole.
dd6738; Resolve bad plant aerial drop issues
dd6738; Resolve aerial drop issues at serving terminal
dd6738; Resolve bad plant aerial drop issues
pg6512; Removed drop at pole, rebuilt terminal
pg6512; Removed drop from pole
pg6512; Removed drop from pole
pg6512; Removed drops at pole
jh3145; Aerial drop wire hanging from the pole. Removed aerial drop wire from pole and serving terminal.
pg6512; Removed drops at pole
dd6738; Resolve aerial drop issues at serving terminal
dd6738; Resolve bad plant aerial drop issue
dd6738; Resolve bad plant aerial drop issues
dd6738; Resolve aerial drop issues at serving terminal
dd6738; Resolve bad plant aerial drop issues
dd6738; Resolve bad plant aerial drop issues
/ire hanging from the pole. Laying on the ground. Hazardous condition. Removed aerial drop wire from the pole
jh3145; Aerial drop wire hanging from pole. Removed aerial drop wire from the pole.
DD6738; RESOLVE AERIAL,DROP ISSUES
jh3145; Aerial drop wire hanging from the pole. Removed aerial drop wire from pole and serving terminal.
sf8537; Rmvd asw hazzard on previous occasion
tm3217; Work completed,., ,,.
sf8537; Asw hazard ends, secured terminal and cable
sf8537; Pics are P242 Oddie wy,rmvd hazzard
;dd043u; assisted tech with splicing ect
sf8537; Ntf,previously did on other occasion
sf8537; Rmvd coax hazzardP496 Alder ct,NTF ATT.
sf8537; Rmvd hazzard asw two poles Cate.
sf8537; All ATT network cleaned and cleared.
sf8537; Rprriser guard and ring run bsw to term.
db8381; Removed service drop from pole.
db8381; Removed service drop.
:D ASW SECURED TERM AND CABLES-355 LAWRENCE. ALSO REPEATER 6- C.O.TESTING ON KEDDIE CABLE PI

sf8537; rerouted and changed asw for dead tree removal.

stomer has not opened trench for BEW replacement. Property owner has damaged bsw multiple times, needs n

sf8537; Removed down asw today while leaving Loyalton.

sf8537; Rmvd hazz asw P226 bucks lk rd, rmvd48545 hwy 70, rettached low asw P2138 e main st.

sc2675; rmvd tree from cable

sc2675; rmvd tree from cable

sc2675; rmvd tree from cab

sc2675; removed tree from ca

cn2921; removed two aerial drops hanging from serv terms, replaced one term that was damaged from trees.

cn2921; removed abandon aerial drop from strand and gathered up the rest.

cn2921; removed abandon aerial drop from strand and gathered the rest from base of tree.

ed 2 low hanging drops through trees from terminal and pulled them both back up over the top of the trees and

sc2675; removed tree from cable

js3172; Drop work, on ground

sc2675; removed 3 downed abandoned drop

sc2675; Removed downed dr

sc2675; removed downed drop and submitted 3 more bpcs

sc2675; removed 3 downed drops and submitted bpc

sc2675; removed 3 downed drop

sc2675; Removed tree from cable

sf8537; c wire repaired w construction assist,new sni installed,advised

;db8381; PC-Y; Cut tree off of service drop.; TN: 0000000000

vc6131; drop down, removed dead drop

vc6131; drop down, removed dead drop

mm3647; raise low bypass and raise low drop

;mm3647; PC-N; Clear tree from cable.

qb6851; Removed tree from lines .

dm820t; Wrecked out downed drop.

;rw5286; PC-N; Placed drop behind riser;

qb6851; bpc ticket completed

sc2675; Trees removed from cable
sc2675; Removed tree limbs from cable
qb6851; removed tree from cable
;rw5286; PC-N; Removed branch on cable;
;rw5286; PC-N; Raised low drop; service good to mpoe;
lp848k; Removed vegetation pulling down on line. Placed tree trimming ticket to have larger limbs removed.
;mm3647; PC-N; Submit dig 21512802 for tree removal from cable.
;mm3647; PC-N; 2 trees on cable. Need tree service to remove. Made dig request for tree service.
wc8687; all cable issues resolved last winter from snow load, removed remaining tail on house

PER CM RA961

sc2675; Tree removed from cable

FLD_COMP_NOTE	FLD_FORCE_TECH
Updating Actual Minutes on CIMI_RWM_00348606_01	VC6131
All Wire/Work Jobs have Completed, Package now in Complete status.	NH2812
complete with job A01AMRJ	
All Wire/Work Jobs have Completed, Package now in Complete status.	SM4953
Package Manually Completed by dm2165.	
job complete as of 8/28	
all work complete and hazard cleared per TW5962	
Package Manually Completed by tn5252.	
Package Manually Completed by tn5252.	
all work complete VC1691	
all work complete VC1691	
CATV in violation	
Package Manually Completed by tn5252.	
all work complete VC1691	
Package Manually Completed by tn5252.	
Package Manually Completed by tn5252.	
Package Manually Completed by tn5252.	
Package Manually Completed by tn5252.	
all work complete VC1691	
work complete	
All Wire/Work Jobs have Completed, Package now in Complete status.	AG2675
Package Manually Completed by tn5252.	
All Wire/Work Jobs have Completed, Package now in Complete status.	RT9712
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
all work complete and hazard cleared per TW5962	
all work complete vc1691	
all work complete vc1691	
Package Manually Completed by gh304f.	
this job is complete , job number A01MLSK intent PG180390HM	
COMPLETED JOB A01L7VY INTENT PG180381HM	
All Wire/Work Jobs have Completed, Package now in Complete status.	NH2812
All Wire/Work Jobs have Completed, Package now in Complete status.	EK6957
All Wire/Work Jobs have Completed, Package now in Complete status.	EK6957
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
all work comp./ placed guy guard	
all work comp./ cleared CATV drop	
a.w.c. re sag and relash	
all work comp./ raise attachment	
re-lash 70'	
RAISED 2 CABLES 3' ON POLE AND REPLACED 2 DOWN GUYS	

Package Manually Completed by sr5695.	
Package Manually Completed by sr5695.	
all work comp./ place guy guard	
Package Manually Completed by sr5695.	
Package Manually Completed by sr5695.	
Package Manually Completed by sr5695.	
all work comp./ removed down guy	
Package Manually Completed by sr5695.	
Package Manually Completed by sr5695.	
Package Manually Completed by sr5695.	
Package Manually Completed by sr5695.	
all work comp. / replaced down guy	
Package Manually Completed by sr5695.	
Package Manually Completed by sr5695.	
ALL WORK COMP./ RE-LASH SPAN	
all work comp./ rem. cut drop wire	
all work comp./ replaced 2 down guys	
Updating Actual Minutes on CIMI_RWM_00471864_01	PG6512
all work comp./ place guy guard	
all work complete/ place down guy	
all work comp./ placed guy guard	
Updating Actual Minutes on CIMI_RWM_00471869_01	CD5628
Package Manually Completed by sr5695.	
Package Manually Completed by sr5695.	
all work comp./ place guy guard	
all work comp./ re-lash section	
all work complete / place guy guard	
no trouble found	
Package Manually Completed by sr5695.	
all work comp./ transfer attachment	
Updating Actual Minutes on CIMI_RWM_00471883_01	CD5628
Package Manually Completed by sr5695.	
Updating Actual Minutes on CIMI_RWM_00471885_01	CD5628
all work comp./ raise attachment	
Updating Actual Minutes on CIMI_RWM_00471890_01	CD5628
Package Manually Completed by sr5695.	
all work comp.	
Package Manually Completed by sr5695.	
Updating Actual Minutes on CIMI_RWM_00471902_01	CD5628
no trouble found	
Package Manually Completed by sr5695.	
al work compl./ placed guy guard	
all work comp./ place guy guard	

all work comp./ tension down guy	
Package Manually Completed by sr5695.	
all work complete / place guy guard	
all work comp./ replaced term.	
Updating Actual Minutes on CIMI_RWM_00471915_01	CD5628
Package Manually Completed by sr5695.	
Package Manually Completed by sr5695.	
Package Manually Completed by sr5695.	
all work comp./ re-tension down guy	
Package Manually Completed by sr5695.	
all work comp./ re-lash cable	
all work comp./ secured air pipe	
all work comp./ place guy guard	
Package Manually Completed by sr5695.	
All work comp./ Placed guy guard	
Package Manually Completed by sr5695.	
all work comp./ re-lash cable	
Package Manually Completed by sr5695.	
Package Manually Completed by sr5695.	
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145
All Wire/Work Jobs have Completed, Package now in Complete status.	PG6512
All Wire/Work Jobs have Completed, Package now in Complete status.	JQ2645
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	JQ2645
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145
All Wire/Work Jobs have Completed, Package now in Complete status.	PG6512
Package Manually Completed by sr5695.	

All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145
All Wire/Work Jobs have Completed, Package now in Complete status.	PG6512
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
Package Manually Completed by am2868.	
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	PG6512
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	PG6512
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	SM3126
All Wire/Work Jobs have Completed, Package now in Complete status.	PG6512
Package Manually Completed by sr5695.	
All Wire/Work Jobs have Completed, Package now in Complete status.	JQ2645
All Wire/Work Jobs have Completed, Package now in Complete status.	PG6512
All Wire/Work Jobs have Completed, Package now in Complete status.	PG6512
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
Package Manually Completed by ca8161.	
All Wire/Work Jobs have Completed, Package now in Complete status.	PG6512
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145
All Wire/Work Jobs have Completed, Package now in Complete status.	PG6512
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	PG6512
All Wire/Work Jobs have Completed, Package now in Complete status.	SM3126
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	PG6512
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
Package Manually Completed by sr5695.	
All Wire/Work Jobs have Completed, Package now in Complete status.	PG6512
All Wire/Work Jobs have Completed, Package now in Complete status.	PG6512

All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145
all work comp./ tension down guys	
Package Manually Completed by sr5695.	
re sag and re lash	
Package Manually Completed by sr5695.	
Package Manually Completed by sr5695.	
Package Manually Completed by sr5695.	
Package Manually Completed by sr5695.	
Package Manually Completed by sr5695.	
Package Manually Completed by sr5695.	
Raise attachment and re-sag Telcoo and CATV	
Re-sag 2 cables at dead end pole	
Package Manually Completed by sr5695.	
Package Manually Completed by sr5695.	
all work comp./ re-lash cable	
Package Manually Completed by sr5695.	
Package Manually Completed by sr5695.	
all work comp./ placed guy guard	
all work comp./ cable has been undergrounded	
all work comp./ re-lash cable	
all work comp./ placed down guy	
Package Manually Completed by sr5695.	
Updating Actual Minutes on CIMI_RWM_00472664_01	CD5628
all work comp. /replaced down guy	
Package Manually Completed by sr5695.	
Package Manually Completed by sr5695.	
Package Manually Completed by sr5695.	
Package Manually Completed by sr5695.	
all work complete / place guy guard	
Package Manually Completed by sr5695.	
Package Manually Completed by sr5695.	
Package Manually Completed by sr5695.	
all work comp./ re-tension 2 down guys	
all work comp./ replaced term.	
Package Manually Completed by sr5695.	
all work comp. /replaced down guy	
Package Manually Completed by sr5695.	
Updating Actual Minutes on CIMI_RWM_00472797_01	CD5628
Package Manually Completed by sr5695.	

Package Manually Completed by sr5695.	
all work comp./ raised cable, placed guy guard	
Package Manually Completed by sr5695.	
Package Manually Completed by sr5695.	
all work complete, replaced terminal	
all work comp./ place guy guard	
all work comp./ placed guy guard	
all work comp./ placed guy guard	
Package Manually Completed by sr5695.	
all work comp./ re-lash cable	
Package Manually Completed by sr5695.	
all work complete, replaced terminal	
Package Manually Completed by sr5695.	
all work complete, replaced terminal	
Package Manually Completed by sr5695.	
all work complete, replaced terminal	
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	SM3126
CATV Slacked	
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145
All Wire/Work Jobs have Completed, Package now in Complete status.	JQ2645
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145
All Wire/Work Jobs have Completed, Package now in Complete status.	JQ2645
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	PG6512
All Wire/Work Jobs have Completed, Package now in Complete status.	PG6512
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	SM3126
All Wire/Work Jobs have Completed, Package now in Complete status.	PG6512
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145
All Wire/Work Jobs have Completed, Package now in Complete status.	JQ2645
All Wire/Work Jobs have Completed, Package now in Complete status.	JQ2645
All Wire/Work Jobs have Completed, Package now in Complete status.	JQ2645
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	JQ2645

All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
Package Manually Completed by sr5695.	
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	TL5296
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	TL5296
All Wire/Work Jobs have Completed, Package now in Complete status.	JQ2645
All Wire/Work Jobs have Completed, Package now in Complete status.	SM3126
All Wire/Work Jobs have Completed, Package now in Complete status.	PG6512
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145
All Wire/Work Jobs have Completed, Package now in Complete status.	PG6512
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145
Package Manually Completed by sr5695.	
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
Hazard cleared by tech MM9751	
All Wire/Work Jobs have Completed, Package now in Complete status.	SC2675
hazard cleard gm2576 & jg29x	
Package Manually Completed by dn2494.	
Package Manually Completed by tn5252.	
Package Manually Completed by tn5252.	
all work complete and hazard cleared per TW5962	
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
all work complete VC1691	
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
not telco	
prior to inspection	
prior to inspection	
Updating Actual Minutes on CIMI_RWM_00488894_01	SF8537
Updating Actual Minutes on CIMI_RWM_00488896_01	SF8537
Updating Actual Minutes on CIMI_RWM_00488906_01	TL3147
Updating Actual Minutes on CIMI_RWM_00489028_01	SF8537
Updating Actual Minutes on CIMI_RWM_00489033_01	SF8537
Updating Actual Minutes on CIMI_RWM_00489059_01	SF8537

Updating Actual Minutes on CIMI_RWM_00489103_01	SF8537
Updating Actual Minutes on CIMI_RWM_00489113_01	SF8537
Updating Actual Minutes on CIMI_RWM_00489143_01	SF8537
Updating Actual Minutes on CIMI_RWM_00489146_01	SF8537
Updating Actual Minutes on CIMI_RWM_00489303_01	SF8537
Package Manually Completed by dm2165.	
Updating Actual Minutes on CIMI_RWM_00489312_01	DM6529
All Wire/Work Jobs have Completed, Package now in Complete status.	DM6529
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
all work complete and hazard cleared per TW5962	
Package Manually Completed by tn5252.	
all work complete and hazard cleared per TW5962	
all work complete and hazard cleared per TW5962	
cleared raised ok	
Package Manually Completed by bc683a.	
Package Manually Completed by bc683a.	
replace broken dg with insulated dg	
go95 fixed on cable replacement	
All Wire/Work Jobs have Completed, Package now in Complete status.	MR1213
Package Manually Completed by jd1746.	
cleared raised ok	
Updating Actual Minutes on CIMI_RWM_00493885_01	JM1295
All Wire/Work Jobs have Completed, Package now in Complete status.	MD4156
All Wire/Work Jobs have Completed, Package now in Complete status.	JM1295
All Wire/Work Jobs have Completed, Package now in Complete status.	QB6851
All Wire/Work Jobs have Completed, Package now in Complete status.	NH2812
All Wire/Work Jobs have Completed, Package now in Complete status.	EK6957
All Wire/Work Jobs have Completed, Package now in Complete status.	MD4156
All Wire/Work Jobs have Completed, Package now in Complete status.	JM1295
All Wire/Work Jobs have Completed, Package now in Complete status.	VC6131
All Wire/Work Jobs have Completed, Package now in Complete status.	VC6131
All Wire/Work Jobs have Completed, Package now in Complete status.	JM1295
All Wire/Work Jobs have Completed, Package now in Complete status.	JM1295
All Wire/Work Jobs have Completed, Package now in Complete status.	JM1295
All Wire/Work Jobs have Completed, Package now in Complete status.	DM820T
All Wire/Work Jobs have Completed, Package now in Complete status.	NH2812
All Wire/Work Jobs have Completed, Package now in Complete status.	RW5286
All Wire/Work Jobs have Completed, Package now in Complete status.	MD4156
All Wire/Work Jobs have Completed, Package now in Complete status.	MD4156
All Wire/Work Jobs have Completed, Package now in Complete status.	NH2812
Package Manually Completed by tn5252.	

Package Manually Completed by bc683a.	
All Wire/Work Jobs have Completed, Package now in Complete status.	AG2675
All work completed.	
cleared raised ok	
All Wire/Work Jobs have Completed, Package now in Complete status.	RT9712
All Wire/Work Jobs have Completed, Package now in Complete status.	MS7970
Package Manually Completed by jd1746.	
Package Manually Completed by jd1746.	
All Wire/Work Jobs have Completed, Package now in Complete status.	BL1527
Package Manually Completed by bc683a.	
All Wire/Work Jobs have Completed, Package now in Complete status.	OM3842
All Wire/Work Jobs have Completed, Package now in Complete status.	NH2812
All Wire/Work Jobs have Completed, Package now in Complete status.	JM1295
All Wire/Work Jobs have Completed, Package now in Complete status.	NH2812
All Wire/Work Jobs have Completed, Package now in Complete status.	NH2812
All Wire/Work Jobs have Completed, Package now in Complete status.	VC6131
All Wire/Work Jobs have Completed, Package now in Complete status.	NH2812
All Wire/Work Jobs have Completed, Package now in Complete status.	QB6851
Design Record Updated by gh304f.	
Complete by Auburn Linecrew. No project	
Package Manually Completed by sm5367.	
All Wire/Work Jobs have Completed, Package now in Complete status.	JH2859
Package Manually Completed by gt7416.	
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
All Wire/Work Jobs have Completed, Package now in Complete status.	CC2745
Updating Actual Minutes on CIMI_CJD17460924C01	
Package Manually Completed by gt7416.	
All Wire/Work Jobs have Completed, Package now in Complete status.	CC2745
placed/ raised lower DG and or guard arm	
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
all work complete and hazard cleared per TW5962	
All Wire/Work Jobs have Completed, Package now in Complete status.	CC2745
Package Manually Completed by gt7416.	
All Wire/Work Jobs have Completed, Package now in Complete status.	CC2745
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
All Wire/Work Jobs have Completed, Package now in Complete status.	CC2745
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
All Wire/Work Jobs have Completed, Package now in Complete status.	CC2745
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532

Updating Actual Minutes on CIMI_CJD17460922C01	
All work complete.	
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
Package Manually Completed by gt7416.	
BPC Job has Dispatched, Package now in In Progress status.	AC1532
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
All Wire/Work Jobs have Completed, Package now in Complete status.	CC2745
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
placed guard on dg with queens post	
All Wire/Work Jobs have Completed, Package now in Complete status.	CC2745
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
Package Manually Completed by gt7416.	
Package Manually Completed by gt7416.	
Package Manually Completed by gt7416.	
placed/ raised lower DG and or guard arm	
complete 7/13/2020	
All Wire/Work Jobs have Completed, Package now in Complete status.	MD2797
Updating Actual Minutes on CIMI_RWM_00504674_01	AC1532
Updating Actual Minutes on CIMI_RWM_00504754_01	DM258S
Updating Actual Minutes on CIMI_RWM_00504755_01	DM258S
Package Manually Completed by ct9141.	
All Wire/Work Jobs have Completed, Package now in Complete status.	DM820T
Updating Actual Minutes on CIMI_RWM_00504842_01	DB8381
Updating Actual Minutes on CIMI_RWM_00504893_01	QB6851
All Wire/Work Jobs have Completed, Package now in Complete status.	DM820T
Updating Actual Minutes on CIMI_RWM_00505016_01	RH749C
All Wire/Work Jobs have Completed, Package now in Complete status.	DM820T
All Wire/Work Jobs have Completed, Package now in Complete status.	QB6851
Updating Actual Minutes on CIMI_RWM_00505038_01	QB6851
All Wire/Work Jobs have Completed, Package now in Complete status.	GG8932
All Wire/Work Jobs have Completed, Package now in Complete status.	GG8932
Updating Actual Minutes on CIMI_RWM_00505104_01	AC1532
All Wire/Work Jobs have Completed, Package now in Complete status.	GG8932
Work complete by 46L. Hazard cleared.	
Package Manually Completed by dm2165.	
All Wire/Work Jobs have Completed, Package now in Complete status.	NH2812
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
All Wire/Work Jobs have Completed, Package now in Complete status.	SM4953
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
All Wire/Work Jobs have Completed, Package now in Complete status.	DB8381
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
All Wire/Work Jobs have Completed, Package now in Complete status.	CC2745
All Wire/Work Jobs have Completed, Package now in Complete status.	MM3647
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532

All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
All Wire/Work Jobs have Completed, Package now in Complete status.	NH2812
All Wire/Work Jobs have Completed, Package now in Complete status.	SM4953
All Wire/Work Jobs have Completed, Package now in Complete status.	QB6851
All Wire/Work Jobs have Completed, Package now in Complete status.	QB6851
All Wire/Work Jobs have Completed, Package now in Complete status.	SM4953
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
All Wire/Work Jobs have Completed, Package now in Complete status.	OD4318
All Wire/Work Jobs have Completed, Package now in Complete status.	SM4953
All Wire/Work Jobs have Completed, Package now in Complete status.	CC2745
All Wire/Work Jobs have Completed, Package now in Complete status.	SM4953
All Wire/Work Jobs have Completed, Package now in Complete status.	QB6851
all work complete and hazard cleared per TW5962	
Package Manually Completed by tn5252.	
All Wire/Work Jobs have Completed, Package now in Complete status.	SM4953
Package Manually Completed by gt7416.	
all work complete and hazard cleared per TW5962	
all work complete and hazard cleared per TW5962	
All Wire/Work Jobs have Completed, Package now in Complete status.	SM4953
All Wire/Work Jobs have Completed, Package now in Complete status.	SM4953
Updating Actual Minutes on CIMI_RWM_00507147_01	SF8537
Package Manually Completed by tn5252.	
all work complete and hazard cleared per TW5962	
all work complete and hazard cleared per TW5962	
Package Manually Completed by tn5252.	
all work complete and hazard cleared per TW5962	
all work complete and hazard cleared per TW5962	
all work complete and hazard cleared per TW5962	
Package Manually Completed by tn5252.	
All work complete.	
all work complete and hazard cleared per TW5962	
all work complete and hazard cleared per TW5962	
Package Manually Completed by tn5252.	
Package Manually Completed by tn5252.	
Package Manually Completed by tn5252.	
Package Manually Completed by tn5252.	
all work complete and hazard cleared per TW5962	
all work complete and hazard cleared per TW5962	
all work complete and hazard cleared per TW5962	
Package Manually Completed by tn5252.	
all work complete and hazard cleared per TW5962	
all work complete and hazard cleared per TW5962	
Package Manually Completed by tn5252.	
ALL WORK COMPLETE.	

all work complete and hazard cleared per TW5962	
all work complete and hazard cleared per TW5962	
Package Manually Completed by tn5252.	
all work complete and hazard cleared per TW5962	
all work complete and hazard cleared per TW5962	
all work complete and hazard cleared per TW5962	
all work complete and hazard cleared per TW5962	
Package Manually Completed by tn5252.	
all work complete and hazard cleared per TW5962	
Package Manually Completed by rx2347.	
all work complete and hazard cleared per TW5962	
Package Manually Completed by tn5252.	
Package Manually Completed by gt7416.	
Package Manually Completed by hl1436.	
Package Manually Completed by tn5252.	
Package Manually Completed by tn5252.	
Updating Actual Minutes on CIMI_RWM_00509025_01	JM1295
Updating Actual Minutes on CIMI_RWM_00509218_01	LP848K
Updating Actual Minutes on CIMI_RWM_00509260_01	DM820T
Updating Actual Minutes on CIMI_RWM_00509318_01	JM1295
Updating Actual Minutes on CIMI_RWM_00509364_01	DM820T
All Wire/Work Jobs have Completed, Package now in Complete status.	MR1213
Work complete by 46L. Hazard cleared.	
All Wire/Work Jobs have Completed, Package now in Complete status.	RD3541
All Wire/Work Jobs have Completed, Package now in Complete status.	JM1295
All Wire/Work Jobs have Completed, Package now in Complete status.	NH2812
All Wire/Work Jobs have Completed, Package now in Complete status.	GB1263
All Wire/Work Jobs have Completed, Package now in Complete status.	PC9347
All Wire/Work Jobs have Completed, Package now in Complete status.	SM4953
All Wire/Work Jobs have Completed, Package now in Complete status.	NH2812
All Wire/Work Jobs have Completed, Package now in Complete status.	NH2812
All Wire/Work Jobs have Completed, Package now in Complete status.	NH2812
All Wire/Work Jobs have Completed, Package now in Complete status.	GB1263
All Wire/Work Jobs have Completed, Package now in Complete status.	RD3541
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3986
All Wire/Work Jobs have Completed, Package now in Complete status.	WE2989
All Wire/Work Jobs have Completed, Package now in Complete status.	MM3647
De-lash and re-lash 2 separate spans, re-sag strand, re-place down guy	
Package Manually Completed by sr5695.	
DE-LASH AND RE-LASH 150'	
All work is complete.	
Updating Actual Minutes on CIMI_RWM_00509657_01	DD6738
Package Manually Completed by md7181.	

Updating Actual Minutes on CIMI_RWM_00509683_01	DD6738
All work is complete.	
All Wire/Work Jobs have Completed, Package now in Complete status.	PG6512
All Wire/Work Jobs have Completed, Package now in Complete status.	SM3126
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145
All Wire/Work Jobs have Completed, Package now in Complete status.	SM3126
All Wire/Work Jobs have Completed, Package now in Complete status.	SM3126
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145
All Wire/Work Jobs have Completed, Package now in Complete status.	PG6512
All Wire/Work Jobs have Completed, Package now in Complete status.	PG6512
All Wire/Work Jobs have Completed, Package now in Complete status.	SM3126
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	PG6512
All Wire/Work Jobs have Completed, Package now in Complete status.	SM3126
All Wire/Work Jobs have Completed, Package now in Complete status.	JQ2645
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	PG6512
All Wire/Work Jobs have Completed, Package now in Complete status.	SM3126
All Wire/Work Jobs have Completed, Package now in Complete status.	JQ2645
All Wire/Work Jobs have Completed, Package now in Complete status.	JQ2645
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	JQ2645
All Wire/Work Jobs have Completed, Package now in Complete status.	SM3126
All Wire/Work Jobs have Completed, Package now in Complete status.	JQ2645
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	NH2812
all work complete and hazard cleared per TW5962	
Package Manually Completed by tn5252.	
all work complete and hazard cleared per TW5962	
Package Manually Completed by tn5252.	
raised lower, guard arm	
All Wire/Work Jobs have Completed, Package now in Complete status.	SC2675
cleared raised ok	
cleared raised ok	
cleared raised ok	
Package Manually Completed by bc683a.	
Package Manually Completed by gt7416.	
Package Manually Completed by rp2967.	
Updating Actual Minutes on CIMI_RWM_00511066_01	SC2675

Package Manually Completed by jp2396.	
All Wire/Work Jobs have Completed, Package now in Complete status.	JM3821
All Wire/Work Jobs have Completed, Package now in Complete status.	JI2512
All Wire/Work Jobs have Completed, Package now in Complete status.	EL8648
All Wire/Work Jobs have Completed, Package now in Complete status.	JM3821
All Wire/Work Jobs have Completed, Package now in Complete status.	EL8648
All Wire/Work Jobs have Completed, Package now in Complete status.	JA1893
All Wire/Work Jobs have Completed, Package now in Complete status.	BK2151
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
power secondary loose and in telco space	
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145
All Wire/Work Jobs have Completed, Package now in Complete status.	AM8121
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
all work has been completed and hazard cleared per TW5962 04/30/20	
Package Manually Completed by tn5252.	
TREE HAS BEEN REMOVED AND HAZARD HAS BEEN CLEARED	
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	JM3821
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537

All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
update	SF8537
update	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SC2675
Package Manually Completed by rp2967.	
All Wire/Work Jobs have Completed, Package now in Complete status.	SC2675
All Wire/Work Jobs have Completed, Package now in Complete status.	JS3172
All Wire/Work Jobs have Completed, Package now in Complete status.	TL3147
All Wire/Work Jobs have Completed, Package now in Complete status.	SM4953
All Wire/Work Jobs have Completed, Package now in Complete status.	SM4953
All Wire/Work Jobs have Completed, Package now in Complete status.	NH2812
All Wire/Work Jobs have Completed, Package now in Complete status.	NH2812
All Wire/Work Jobs have Completed, Package now in Complete status.	NH2812
All Wire/Work Jobs have Completed, Package now in Complete status.	NH2812
All Wire/Work Jobs have Completed, Package now in Complete status.	NH2812
All Wire/Work Jobs have Completed, Package now in Complete status.	NH2812
All Wire/Work Jobs have Completed, Package now in Complete status.	SM4953
All Wire/Work Jobs have Completed, Package now in Complete status.	SM4953
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532

7/19/21 Notified of completion by SVA. RP2967.

Package Manually Completed by rp2967.

Package Manually Completed by rp2967.

Notified of completion by SVA.

Notified of completion by SVA.	
All Wire/Work Jobs have Completed, Package now in Complete status.	SC2675
All Wire/Work Jobs have Completed, Package now in Complete status.	SC2675
All Wire/Work Jobs have Completed, Package now in Complete status.	EK6957
Package Manually Completed by rp2967.	
All Wire/Work Jobs have Completed, Package now in Complete status.	NH2812
All Wire/Work Jobs have Completed, Package now in Complete status.	JM1295
All Wire/Work Jobs have Completed, Package now in Complete status.	EK6957
All Wire/Work Jobs have Completed, Package now in Complete status.	NH2812
All Wire/Work Jobs have Completed, Package now in Complete status.	NH2812
All Wire/Work Jobs have Completed, Package now in Complete status.	EK6957
All Wire/Work Jobs have Completed, Package now in Complete status.	EK6957
All Wire/Work Jobs have Completed, Package now in Complete status.	NH2812
All Wire/Work Jobs have Completed, Package now in Complete status.	SM4953
All Wire/Work Jobs have Completed, Package now in Complete status.	SM4953
All Wire/Work Jobs have Completed, Package now in Complete status.	NH2812
All Wire/Work Jobs have Completed, Package now in Complete status.	VC6131
6/28/21 Notified of completion by SVA. RP2967.	
All Wire/Work Jobs have Completed, Package now in Complete status.	VC6131
All Wire/Work Jobs have Completed, Package now in Complete status.	DI1638
All Wire/Work Jobs have Completed, Package now in Complete status.	BK2151
All Wire/Work Jobs have Completed, Package now in Complete status.	NP5869
All Wire/Work Jobs have Completed, Package now in Complete status.	EL8648
All Wire/Work Jobs have Completed, Package now in Complete status.	MD4156
All Wire/Work Jobs have Completed, Package now in Complete status.	PC9347
All Wire/Work Jobs have Completed, Package now in Complete status.	JS6852
All Wire/Work Jobs have Completed, Package now in Complete status.	MD4156
All Wire/Work Jobs have Completed, Package now in Complete status.	MD4156
All Wire/Work Jobs have Completed, Package now in Complete status.	OD4318
Updating Actual Minutes on CIMI_RWM_00782633_01	AC1532
All Wire/Work Jobs have Completed, Package now in Complete status.	PC9347
All Wire/Work Jobs have Completed, Package now in Complete status.	NP5869
Updating Actual Minutes on CIMI_RWM_00782637_01	AC1532
Updating Actual Minutes on CIMI_RWM_00782638_01	AC1532
Updating Actual Minutes on CIMI_RWM_00782639_01	AC1532
All Wire/Work Jobs have Completed, Package now in Complete status.	EL8648
All Wire/Work Jobs have Completed, Package now in Complete status.	JM2792
Updating Actual Minutes on CIMI_RWM_00782642_01	GG8932
All Wire/Work Jobs have Completed, Package now in Complete status.	JM2792

All Wire/Work Jobs have Completed, Package now in Complete status.	NP5869
All Wire/Work Jobs have Completed, Package now in Complete status.	JM3821
Updating Actual Minutes on CIMI_RWM_00782648_01	PC9347
Updating Actual Minutes on CIMI_RWM_00782651_01	DM820T
All Wire/Work Jobs have Completed, Package now in Complete status.	DI1638
Updating Actual Minutes on CIMI_RWM_00782655_01	RW5286
All Wire/Work Jobs have Completed, Package now in Complete status.	DI1638
All Wire/Work Jobs have Completed, Package now in Complete status.	JM2792
All Wire/Work Jobs have Completed, Package now in Complete status.	JM2792
All Wire/Work Jobs have Completed, Package now in Complete status.	EL8648
All Wire/Work Jobs have Completed, Package now in Complete status.	JM3821
Updating Actual Minutes on CIMI_RWM_00782661_01	RW5286
All Wire/Work Jobs have Completed, Package now in Complete status.	MG1262
All Wire/Work Jobs have Completed, Package now in Complete status.	JM2792
All Wire/Work Jobs have Completed, Package now in Complete status.	SM1897
All Wire/Work Jobs have Completed, Package now in Complete status.	EL8648
All Wire/Work Jobs have Completed, Package now in Complete status.	EL8648
All Wire/Work Jobs have Completed, Package now in Complete status.	JI2512
All Wire/Work Jobs have Completed, Package now in Complete status.	JI2512
All Wire/Work Jobs have Completed, Package now in Complete status.	JS6852
All Wire/Work Jobs have Completed, Package now in Complete status.	MM3647
All Wire/Work Jobs have Completed, Package now in Complete status.	MG1262

Package Manually Completed by rp2967.

All Wire/Work Jobs have Completed, Package now in Complete status.	EK6957
Updating Actual Minutes on CIMI_RWM_00783242_01	DM820T
Updating Actual Minutes on CIMI_RWM_00783243_01	DM820T
Updating Actual Minutes on CIMI_RWM_00783244_01	MD4156
Updating Actual Minutes on CIMI_RWM_00783246_01	AG2675
Updating Actual Minutes on CIMI_RWM_00783247_01	MM3647
All Wire/Work Jobs have Completed, Package now in Complete status.	AG2675
All Wire/Work Jobs have Completed, Package now in Complete status.	AG2675
Updating Actual Minutes on CIMI_RWM_00783257_01	LP848K
Updating Actual Minutes on CIMI_RWM_00783259_01	GG8932
Updating Actual Minutes on CIMI_RWM_00783264_01	QB6851
All Wire/Work Jobs have Completed, Package now in Complete status.	TL5296
All Wire/Work Jobs have Completed, Package now in Complete status.	EK6957
All Wire/Work Jobs have Completed, Package now in Complete status.	SM4953
All Wire/Work Jobs have Completed, Package now in Complete status.	SM4953
All Wire/Work Jobs have Completed, Package now in Complete status.	SM4953
All Wire/Work Jobs have Completed, Package now in Complete status.	SM4953
All Wire/Work Jobs have Completed, Package now in Complete status.	SM4953

All Wire/Work Jobs have Completed, Package now in Complete status.	JQ2645
All Wire/Work Jobs have Completed, Package now in Complete status.	SM4953
Updating Actual Minutes on CIMI_RWM_00783742_01	JH3145
Updating Actual Minutes on CIMI_RWM_00783743_01	DD1636
Updating Actual Minutes on CIMI_RWM_00783744_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783745_01	JH3145
Updating Actual Minutes on CIMI_RWM_00783746_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783747_01	DD1636
Updating Actual Minutes on CIMI_RWM_00783748_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783749_01	PG6512
Updating Actual Minutes on CIMI_RWM_00783750_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783751_01	CD5628
Updating Actual Minutes on CIMI_RWM_00783752_01	JH3145
Updating Actual Minutes on CIMI_RWM_00783753_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783754_01	JH3145
Updating Actual Minutes on CIMI_RWM_00783756_01	JH3145
Updating Actual Minutes on CIMI_RWM_00783757_01	JH3145
Updating Actual Minutes on CIMI_RWM_00783767_01	JH3145
Updating Actual Minutes on CIMI_RWM_00783768_01	PG6512
Updating Actual Minutes on CIMI_RWM_00783769_01	JH3145
Updating Actual Minutes on CIMI_RWM_00783771_01	CD5628
Updating Actual Minutes on CIMI_RWM_00783772_01	WC8687
Updating Actual Minutes on CIMI_RWM_00783773_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783774_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783775_01	PG2676
Updating Actual Minutes on CIMI_RWM_00783776_01	WC8687
Updating Actual Minutes on CIMI_RWM_00783777_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783778_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783779_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783780_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783781_01	CD5628
Updating Actual Minutes on CIMI_RWM_00783782_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783783_01	PG6512
Updating Actual Minutes on CIMI_RWM_00783784_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783785_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783786_01	CD5628
Updating Actual Minutes on CIMI_RWM_00783787_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783788_01	CD5628
Updating Actual Minutes on CIMI_RWM_00783789_01	WC8687
Updating Actual Minutes on CIMI_RWM_00783790_01	JH3145
Updating Actual Minutes on CIMI_RWM_00783791_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783795_01	JH3145
Updating Actual Minutes on CIMI_RWM_00783796_01	CD5628
Updating Actual Minutes on CIMI_RWM_00783797_01	PG6512

Updating Actual Minutes on CIMI_RWM_00783798_01	CD5628
Updating Actual Minutes on CIMI_RWM_00783799_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783800_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783801_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783803_01	CD5628
Updating Actual Minutes on CIMI_RWM_00783804_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783805_01	PG6512
Updating Actual Minutes on CIMI_RWM_00783806_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783807_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783808_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783809_01	DM141G
Updating Actual Minutes on CIMI_RWM_00783820_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783821_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783822_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783823_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783824_01	PG2676
Updating Actual Minutes on CIMI_RWM_00783826_01	CD5628
Updating Actual Minutes on CIMI_RWM_00783827_01	PG6512
Updating Actual Minutes on CIMI_RWM_00783828_01	DD1636
Updating Actual Minutes on CIMI_RWM_00783829_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783846_01	PG6512
Updating Actual Minutes on CIMI_RWM_00783847_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783848_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783849_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783850_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783851_01	PG6512
Updating Actual Minutes on CIMI_RWM_00783852_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783853_01	PG2676
Updating Actual Minutes on CIMI_RWM_00783854_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783859_01	JH3145
Updating Actual Minutes on CIMI_RWM_00783860_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783861_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783864_01	WC8687
Updating Actual Minutes on CIMI_RWM_00783865_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783866_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783872_01	JH3145
Updating Actual Minutes on CIMI_RWM_00783873_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783874_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783875_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783876_01	CD5628
Updating Actual Minutes on CIMI_RWM_00783877_01	JH3145
Updating Actual Minutes on CIMI_RWM_00783878_01	DD6738
Updating Actual Minutes on CIMI_RWM_00783879_01	CD5628
Updating Actual Minutes on CIMI_RWM_00783880_01	DD6738

Updating Actual Minutes on CIMI_RWM_00783887_01	CD5628
Updating Actual Minutes on CIMI_RWM_00783888_01	CD5628
Updating Actual Minutes on CIMI_RWM_00783889_01	DD6738

7/12/21 Notified of completion by SVA. RP2967.

ɪ cable but an innerset pole will need to be placed for ground clearance. I have forwarded this to the Const Mgr fo

All Wire/Work Jobs have Completed, Package now in Complete status.	PC9347
All Wire/Work Jobs have Completed, Package now in Complete status.	DL1623
All Wire/Work Jobs have Completed, Package now in Complete status.	JM1295
All Wire/Work Jobs have Completed, Package now in Complete status.	EK6957
All Wire/Work Jobs have Completed, Package now in Complete status.	SM4953
All Wire/Work Jobs have Completed, Package now in Complete status.	EK6957

6/28/21 Notified of completion by SVA. RP2967.

7/19/21 Notified of completion by SVA. RP2967.

All Wire/Work Jobs have Completed, Package now in Complete status.	NH2812
All Wire/Work Jobs have Completed, Package now in Complete status.	EK6957
All Wire/Work Jobs have Completed, Package now in Complete status.	EK6957
All Wire/Work Jobs have Completed, Package now in Complete status.	EK6957
All Wire/Work Jobs have Completed, Package now in Complete status.	EK6957
All Wire/Work Jobs have Completed, Package now in Complete status.	EK6957

many infractions along this cable lead (tree attachments with trees down), corrected specified location.

All Wire/Work Jobs have Completed, Package now in Complete status.	EK6957
All Wire/Work Jobs have Completed, Package now in Complete status.	TS3269
All Wire/Work Jobs have Completed, Package now in Complete status.	NH2812
All Wire/Work Jobs have Completed, Package now in Complete status.	QB6851
All Wire/Work Jobs have Completed, Package now in Complete status.	FR1292

7/6/21 Notified of completion by SVA. RP2967.

All Wire/Work Jobs have Completed, Package now in Complete status. EK6957

Package Manually Completed by rp2967.

All Wire/Work Jobs have Completed, Package now in Complete status. FR1292

All Wire/Work Jobs have Completed, Package now in Complete status. MS7970

Package Manually Completed by rp2967.

Updating Actual Minutes on CIMI_RWM_00785275_01 MM3647

Updating Actual Minutes on CIMI_RWM_00785284_01 DM820T

Updating Actual Minutes on CIMI_RWM_00785285_01 GG8932

Updating Actual Minutes on CIMI_RWM_00785286_01 JM1295

Updating Actual Minutes on CIMI_RWM_00785287_01 JI2512

Updating Actual Minutes on CIMI_RWM_00785288_01 GG8932

Updating Actual Minutes on CIMI_RWM_00785290_01 DM6529

Updating Actual Minutes on CIMI_RWM_00785291_01 MM3647

Updating Actual Minutes on CIMI_RWM_00785292_01 BR5481

Updating Actual Minutes on CIMI_RWM_00785293_01 PC9347

Updating Actual Minutes on CIMI_RWM_00785294_01 QB6851

Updating Actual Minutes on CIMI_RWM_00785296_01 QB6851

Updating Actual Minutes on CIMI_RWM_00785298_01 MD4156

Updating Actual Minutes on CIMI_RWM_00785299_01 MM3647

Updating Actual Minutes on CIMI_RWM_00785300_01 RN2732

Updating Actual Minutes on CIMI_RWM_00785301_01 VC6131

Updating Actual Minutes on CIMI_RWM_00785306_01 DM6529

Updating Actual Minutes on CIMI_RWM_00785310_01 DM820T

Updating Actual Minutes on CIMI_RWM_00785312_01 MD4156

Updating Actual Minutes on CIMI_RWM_00785313_01 PC9347

Updating Actual Minutes on CIMI_RWM_00785314_01 MD4156

Updating Actual Minutes on CIMI_RWM_00785318_01 MD4156

Updating Actual Minutes on CIMI_RWM_00785324_01 JM1295

Updating Actual Minutes on CIMI_RWM_00785332_01 QB6851

on both sides of pole to clear cable. There is a corner pull on pole, pole push brace needed to straighten pole.

7/6/21 Notified of completion by SVA. RP2967.

All Wire/Work Jobs have Completed, Package now in Complete status. SM4953

All Wire/Work Jobs have Completed, Package now in Complete status. NH2812

All Wire/Work Jobs have Completed, Package now in Complete status. SM4953

All Wire/Work Jobs have Completed, Package now in Complete status. EK6957

All Wire/Work Jobs have Completed, Package now in Complete status. SM4953

All Wire/Work Jobs have Completed, Package now in Complete status. RD3541

All Wire/Work Jobs have Completed, Package now in Complete status. EK6957

7/6/21 Notified of completion by SVA. RP2967.

All Wire/Work Jobs have Completed, Package now in Complete status.	SM4953
All Wire/Work Jobs have Completed, Package now in Complete status.	SM4953
All Wire/Work Jobs have Completed, Package now in Complete status.	EK6957
All Wire/Work Jobs have Completed, Package now in Complete status.	EK6957
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	RK7932
All Wire/Work Jobs have Completed, Package now in Complete status.	EK6957
All Wire/Work Jobs have Completed, Package now in Complete status.	EK6957
All Wire/Work Jobs have Completed, Package now in Complete status.	QB6851
All Wire/Work Jobs have Completed, Package now in Complete status.	SM4953
All Wire/Work Jobs have Completed, Package now in Complete status.	PC9347
All Wire/Work Jobs have Completed, Package now in Complete status.	PC9347
All Wire/Work Jobs have Completed, Package now in Complete status.	EK6957
All Wire/Work Jobs have Completed, Package now in Complete status.	EK6957

7/12/21 Notified of completion by SVA. RP2967.

7/12/21 Notified of completion by SVA. RP2967.

Package Manually Completed by hl1436.

All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
Updating Actual Minutes on CIMI_RWM_00786635_01	SF8537

All Wire/Work Jobs have Completed, Package now in Complete status.	EL8648
All Wire/Work Jobs have Completed, Package now in Complete status.	EL8648
Updating Actual Minutes on CIMI_RWM_00786671_01	JI2512
Updating Actual Minutes on CIMI_RWM_00786672_01	MD4156
Updating Actual Minutes on CIMI_RWM_00786677_01	LP848K
Updating Actual Minutes on CIMI_RWM_00786681_01	SF8537
Updating Actual Minutes on CIMI_RWM_00786682_01	SF8537
Updating Actual Minutes on CIMI_RWM_00786683_01	MD4156
Updating Actual Minutes on CIMI_RWM_00786684_01	LP848K
Updating Actual Minutes on CIMI_RWM_00786692_01	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	QB6851
Updating Actual Minutes on CIMI_RWM_00786710_01	JM1295
Updating Actual Minutes on CIMI_RWM_00786711_01	MD4156
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
Package Manually Completed by tn5252.	
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
Updating Actual Minutes on CIMI_RWM_00819648_01	AC1532
APPROVED A01Z3MA PER P740 COMP 7-3-21	
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
all work complete and hazard has been cleared	
all work is complete and hazard cleared	
all waork is complete and hazard cleared per RA9619	
Package Manually Completed by tn5252.	
Package Manually Completed by tn5252.	
all work complete and hazard cleared per RA9619	
Package Manually Completed by te7361.	
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
Package Manually Completed by tn5252.	
Updating Actual Minutes on CIMI_RWM_00872128_01	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
Updating Actual Minutes on CIMI_RWM_00911241_01	SF8537
Updating Actual Minutes on CIMI_RWM_00911242_01	SF8537
Updating Actual Minutes on CIMI_RWM_00911243_01	SF8537
Updating Actual Minutes on CIMI_RWM_00911244_01	SF8537

Updating Actual Minutes on CIMI_RWM_00911245_01	SF8537
Updating Actual Minutes on CIMI_RWM_00911246_01	SF8537
Updating Actual Minutes on CIMI_RWM_00911247_01	SF8537
Updating Actual Minutes on CIMI_RWM_00911248_01	SF8537
Updating Actual Minutes on CIMI_RWM_00911249_01	SF8537
Updating Actual Minutes on CIMI_RWM_00911250_01	SF8537
Updating Actual Minutes on CIMI_RWM_00911251_01	SF8537
Updating Actual Minutes on CIMI_RWM_00911252_01	SF8537
Updating Actual Minutes on CIMI_RWM_00911253_01	SF8537
Updating Actual Minutes on CIMI_RWM_00911254_01	SF8537
Updating Actual Minutes on CIMI_RWM_00911267_01	SF8537
Updating Actual Minutes on CIMI_RWM_00911268_01	SF8537
Updating Actual Minutes on CIMI_RWM_00911269_01	SF8537
Updating Actual Minutes on CIMI_RWM_00911270_01	SF8537
Updating Actual Minutes on CIMI_RWM_00911271_01	SF8537
Updating Actual Minutes on CIMI_RWM_00911272_01	SF8537
Updating Actual Minutes on CIMI_RWM_00911382_01	SF8537
Updating Actual Minutes on CIMI_RWM_00911383_01	SF8537
Updating Actual Minutes on CIMI_RWM_00911388_01	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	CC2745
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
Updating Actual Minutes on CIMI_RWM_00917508_01	RH749C
All Wire/Work Jobs have Completed, Package now in Complete status.	QB6851
All Wire/Work Jobs have Completed, Package now in Complete status.	SM4953
All Wire/Work Jobs have Completed, Package now in Complete status.	QB6851
All Wire/Work Jobs have Completed, Package now in Complete status.	QB6851
Updating Actual Minutes on CIMI_RWM_00919546_01	TL3147
All Wire/Work Jobs have Completed, Package now in Complete status.	QB6851
All Wire/Work Jobs have Completed, Package now in Complete status.	JS2145
All Wire/Work Jobs have Completed, Package now in Complete status.	MM3647
All Wire/Work Jobs have Completed, Package now in Complete status.	QB6851
All Wire/Work Jobs have Completed, Package now in Complete status.	QB6851
All Wire/Work Jobs have Completed, Package now in Complete status.	QB6851
All Wire/Work Jobs have Completed, Package now in Complete status.	RW5286
All Wire/Work Jobs have Completed, Package now in Complete status.	JM2792
All Wire/Work Jobs have Completed, Package now in Complete status.	DM820T
All Wire/Work Jobs have Completed, Package now in Complete status.	AG2675
All Wire/Work Jobs have Completed, Package now in Complete status.	RW5286
All Wire/Work Jobs have Completed, Package now in Complete status.	EL8648
All Wire/Work Jobs have Completed, Package now in Complete status.	MM3647
All Wire/Work Jobs have Completed, Package now in Complete status.	BK2151
All Wire/Work Jobs have Completed, Package now in Complete status.	EL8648
All Wire/Work Jobs have Completed, Package now in Complete status.	NP5869
All Wire/Work Jobs have Completed, Package now in Complete status.	BK2151

All Wire/Work Jobs have Completed, Package now in Complete status.	EL8648
All Wire/Work Jobs have Completed, Package now in Complete status.	SM4953
Updating Actual Minutes on CIMI_RWM_00922739_01	MM3647
All Wire/Work Jobs have Completed, Package now in Complete status.	DI1638
All Wire/Work Jobs have Completed, Package now in Complete status.	AG2675
All Wire/Work Jobs have Completed, Package now in Complete status.	JM1295
All Wire/Work Jobs have Completed, Package now in Complete status.	OD4318
Package Manually Completed by hl1436.	
All Wire/Work Jobs have Completed, Package now in Complete status.	SM1897
Updating Actual Minutes on CIMI_RWM_00922842_01	MM3647
Updating Actual Minutes on CIMI_RWM_00922864_01	SB6349
All Wire/Work Jobs have Completed, Package now in Complete status.	QB6851
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
Updating Actual Minutes on CIMI_RWM_00922886_01	CB281C

l closed and a new RWM PKD ID, 1184769, has been referred to PG&E. This is a joint point. PG&E to inspect

All Wire/Work Jobs have Completed, Package now in Complete status.	JI2512
All Wire/Work Jobs have Completed, Package now in Complete status.	AG2675
Updating Actual Minutes on CIMI_RWM_00924682_01	CB281C
Updating Actual Minutes on CIMI_RWM_00924691_01	MD4156
Updating Actual Minutes on CIMI_RWM_00924805_01	MM3647
Updating Actual Minutes on CIMI_RWM_00924816_01	JS2145
All Wire/Work Jobs have Completed, Package now in Complete status.	EH3437
All Wire/Work Jobs have Completed, Package now in Complete status.	EH3437
All Wire/Work Jobs have Completed, Package now in Complete status.	QB6851
Updating Actual Minutes on CIMI_RWM_00924962_01	JS2145
Updating Actual Minutes on CIMI_RWM_00924968_01	JS2145
Updating Actual Minutes on CIMI_RWM_00924971_01	JS2145
All Wire/Work Jobs have Completed, Package now in Complete status.	AG2675
Package Manually Completed by hl1436.	
Updating Actual Minutes on CIMI_RWM_00925059_01	MD4156
Updating Actual Minutes on CIMI_RWM_00925065_01	MD2797
Updating Actual Minutes on CIMI_RWM_00925223_01	CB281C
Updating Actual Minutes on CIMI_RWM_00925260_01	MD4156
Updating Actual Minutes on CIMI_RWM_00925261_01	MD4156
Updating Actual Minutes on CIMI_RWM_00925262_01	MD4156
Updating Actual Minutes on CIMI_RWM_00925269_01	QB6851
Updating Actual Minutes on CIMI_RWM_00925286_01	MM3647
Updating Actual Minutes on CIMI_RWM_00925360_01	JS2145
Updating Actual Minutes on CIMI_RWM_00925390_01	MD4156
Updating Actual Minutes on CIMI_RWM_00925394_01	JS2145
All Wire/Work Jobs have Completed, Package now in Complete status.	AG2675
All Wire/Work Jobs have Completed, Package now in Complete status.	RW5286
All Wire/Work Jobs have Completed, Package now in Complete status.	JM3821
All Wire/Work Jobs have Completed, Package now in Complete status.	GG8932

Updating Actual Minutes on CIMI_RWM_00925426_01	MD2797
Updating Actual Minutes on CIMI_RWM_00925713_01	DM820T
Updating Actual Minutes on CIMI_RWM_00925890_01	DM820T
Updating Actual Minutes on CIMI_RWM_00925894_01	DM820T
All Wire/Work Jobs have Completed, Package now in Complete status.	BK2151
Updating Actual Minutes on CIMI_RWM_00925904_01	MD4156
This Package was completed from OSPCM/JAM! Moving to Complete.	
Design Record Updated by jt379t.	
All Wire/Work Jobs have Completed, Package now in Complete status.	AG2675
Updating Actual Minutes on CIMI_RWM_00926090_01	RC5742
Updating Actual Minutes on CIMI_RWM_00926091_01	RC5742
Updating Actual Minutes on CIMI_RWM_00926098_01	MD4156
All Wire/Work Jobs have Completed, Package now in Complete status.	GG8932
) closed and a new RWM PKD ID, 1184868, has been referred to PG&E. This is a joint point. PG&E to inspect	
This Package was completed from OSPCM/JAM! Moving to Complete.	
All Wire/Work Jobs have Completed, Package now in Complete status.	CG4741
All Wire/Work Jobs have Completed, Package now in Complete status.	AM8121
Package Manually Completed by hl1436.	
Updating Actual Minutes on CIMI_RWM_00926839_01	DM820T
Updating Actual Minutes on CIMI_RWM_00926840_01	JO1454
Updating Actual Minutes on CIMI_RWM_00926846_01	DM820T
All Wire/Work Jobs have Completed, Package now in Complete status.	DM820T
Updating Actual Minutes on CIMI_RWM_00927686_01	SB6349
Updating Actual Minutes on CIMI_RWM_00927856_01	DM820T
Updating Actual Minutes on CIMI_RWM_00927857_01	MM3647
All Wire/Work Jobs have Completed, Package now in Complete status.	MD4156
Updating Actual Minutes on CIMI_RWM_00927865_01	JS2145
Updating Actual Minutes on CIMI_RWM_00927878_01	MM3647
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
Updating Actual Minutes on CIMI_RWM_00928039_01	QB6851
Updating Actual Minutes on CIMI_RWM_00928041_01	QB6851
Updating Actual Minutes on CIMI_RWM_00928046_01	QB6851
Updating Actual Minutes on CIMI_RWM_00928053_01	JS2145
Updating Actual Minutes on CIMI_RWM_00928059_01	QB6851
Updating Actual Minutes on CIMI_RWM_00928239_01	SB6349
Updating Actual Minutes on CIMI_RWM_00928241_01	JS2145
Updating Actual Minutes on CIMI_RWM_00937990_01	MM3647
Updating Actual Minutes on CIMI_RWM_00938016_01	VC6131
All Wire/Work Jobs have Completed, Package now in Complete status.	RW1952
Updating Actual Minutes on CIMI_RWM_00938026_01	DM820T
All Wire/Work Jobs have Completed, Package now in Complete status.	RW1952
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	WW1427
Updating Actual Minutes on CIMI_RWM_00938224_01	QB6851

All Wire/Work Jobs have Completed, Package now in Complete status.	RW1952
Updating Actual Minutes on CIMI_RWM_00938258_01	DM6529
All Wire/Work Jobs have Completed, Package now in Complete status.	DC2631
Updating Actual Minutes on CIMI_RWM_00940950_01	RC5742
Updating Actual Minutes on CIMI_RWM_00940951_01	RC5742
All Wire/Work Jobs have Completed, Package now in Complete status.	TL5296
Updating Actual Minutes on CIMI_RWM_00945862_01	PG6512
Updating Actual Minutes on CIMI_RWM_00945863_01	DD6738
Updating Actual Minutes on CIMI_RWM_00945864_01	DD6738
Updating Actual Minutes on CIMI_RWM_00945865_01	CD5628
Updating Actual Minutes on CIMI_RWM_00945866_01	DD6738
Updating Actual Minutes on CIMI_RWM_00945867_01	PG6512
Updating Actual Minutes on CIMI_RWM_00945873_01	JH3145
Updating Actual Minutes on CIMI_RWM_00945874_01	JH3145
Updating Actual Minutes on CIMI_RWM_00945875_01	CD5628
Updating Actual Minutes on CIMI_RWM_00945876_01	DD6738
Updating Actual Minutes on CIMI_RWM_00945877_01	CD5628
Updating Actual Minutes on CIMI_RWM_00945880_01	DD6738
Updating Actual Minutes on CIMI_RWM_00945899_01	PG6512
Updating Actual Minutes on CIMI_RWM_00945900_01	CD5628
Updating Actual Minutes on CIMI_RWM_00945901_01	PG6512
Updating Actual Minutes on CIMI_RWM_00945902_01	DD6738
Updating Actual Minutes on CIMI_RWM_00945903_01	CD5628
Updating Actual Minutes on CIMI_RWM_00945933_01	PG6512
Updating Actual Minutes on CIMI_RWM_00945934_01	DD6738
Updating Actual Minutes on CIMI_RWM_00945935_01	CD5628
Updating Actual Minutes on CIMI_RWM_00945936_01	DD6738
Updating Actual Minutes on CIMI_RWM_00945937_01	DD6738
Updating Actual Minutes on CIMI_RWM_00945938_01	DD6738
Updating Actual Minutes on CIMI_RWM_00945939_01	PG6512
Updating Actual Minutes on CIMI_RWM_00945940_01	PG6512
Updating Actual Minutes on CIMI_RWM_00945941_01	PG6512
Updating Actual Minutes on CIMI_RWM_00945942_01	PG6512
Updating Actual Minutes on CIMI_RWM_00945944_01	DD6738
Updating Actual Minutes on CIMI_RWM_00945945_01	DD6738
Updating Actual Minutes on CIMI_RWM_00945946_01	CD5628
Updating Actual Minutes on CIMI_RWM_00945947_01	CD5628
Package Manually Completed by ca8161.	
Package Manually Completed by ca8161.	
All Wire/Work Jobs have Completed, Package now in Complete status.	PG6512
Updating Actual Minutes on CIMI_RWM_00947007_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947012_01	JQ2645
Updating Actual Minutes on CIMI_RWM_00947014_01	CD5628
Updating Actual Minutes on CIMI_RWM_00947015_01	CD5628

Updating Actual Minutes on CIMI_RWM_00947020_01	JQ2645
Updating Actual Minutes on CIMI_RWM_00947022_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947024_01	PG6512
Updating Actual Minutes on CIMI_RWM_00947031_01	CD5628
Updating Actual Minutes on CIMI_RWM_00947035_01	JQ2645
Updating Actual Minutes on CIMI_RWM_00947036_01	JQ2645
Updating Actual Minutes on CIMI_RWM_00947040_01	PG6512
Updating Actual Minutes on CIMI_RWM_00947048_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947056_01	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
Updating Actual Minutes on CIMI_RWM_00947071_01	PG6512
Updating Actual Minutes on CIMI_RWM_00947072_01	PG6512
Updating Actual Minutes on CIMI_RWM_00947077_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947086_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947087_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947092_01	JQ2645
Updating Actual Minutes on CIMI_RWM_00947097_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947102_01	JQ2645
Updating Actual Minutes on CIMI_RWM_00947111_01	CD5628
Updating Actual Minutes on CIMI_RWM_00947113_01	JQ2645
Updating Actual Minutes on CIMI_RWM_00947119_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947120_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947126_01	PG6512
Updating Actual Minutes on CIMI_RWM_00947137_01	PG6512
All Wire/Work Jobs have Completed, Package now in Complete status.	PG6512
Updating Actual Minutes on CIMI_RWM_00947143_01	PG6512
Updating Actual Minutes on CIMI_RWM_00947154_01	PG6512
Updating Actual Minutes on CIMI_RWM_00947161_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947204_01	PG6512
Updating Actual Minutes on CIMI_RWM_00947206_01	PG6512
Updating Actual Minutes on CIMI_RWM_00947210_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947215_01	JQ2645
Updating Actual Minutes on CIMI_RWM_00947218_01	JQ2645
Updating Actual Minutes on CIMI_RWM_00947219_01	CD5628
Updating Actual Minutes on CIMI_RWM_00947252_01	PG6512
Updating Actual Minutes on CIMI_RWM_00947254_01	PG6512
Updating Actual Minutes on CIMI_RWM_00947256_01	CD5628
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145
Updating Actual Minutes on CIMI_RWM_00947271_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947274_01	PG6512
Updating Actual Minutes on CIMI_RWM_00947279_01	PG6512
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
Updating Actual Minutes on CIMI_RWM_00947286_01	PG6512
Updating Actual Minutes on CIMI_RWM_00947287_01	PG6512

All Wire/Work Jobs have Completed, Package now in Complete status.	JQ2645
Updating Actual Minutes on CIMI_RWM_00947302_01	CD5628
Updating Actual Minutes on CIMI_RWM_00947310_01	JH3145
Updating Actual Minutes on CIMI_RWM_00947318_01	JQ2645
Updating Actual Minutes on CIMI_RWM_00947319_01	JQ2645
Updating Actual Minutes on CIMI_RWM_00947361_01	JH3145
Updating Actual Minutes on CIMI_RWM_00947365_01	JQ2645
Updating Actual Minutes on CIMI_RWM_00947372_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947374_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947375_01	CD5628
Updating Actual Minutes on CIMI_RWM_00947378_01	PG6512
Updating Actual Minutes on CIMI_RWM_00947379_01	PG6512
Updating Actual Minutes on CIMI_RWM_00947381_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947382_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947383_01	JH3145
Updating Actual Minutes on CIMI_RWM_00947385_01	CD5628
Updating Actual Minutes on CIMI_RWM_00947428_01	JH3145
Updating Actual Minutes on CIMI_RWM_00947429_01	JH3145
Updating Actual Minutes on CIMI_RWM_00947437_01	JH3145
Updating Actual Minutes on CIMI_RWM_00947447_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947457_01	PG6512
Updating Actual Minutes on CIMI_RWM_00947474_01	PG6512
Updating Actual Minutes on CIMI_RWM_00947480_01	JH3145
Updating Actual Minutes on CIMI_RWM_00947483_01	CD5628
Updating Actual Minutes on CIMI_RWM_00947493_01	CD5628
Updating Actual Minutes on CIMI_RWM_00947494_01	CD5628
Updating Actual Minutes on CIMI_RWM_00947513_01	PG6512
Updating Actual Minutes on CIMI_RWM_00947514_01	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	PG6512
Updating Actual Minutes on CIMI_RWM_00947525_01	CD5628
Updating Actual Minutes on CIMI_RWM_00947526_01	JH3145
Updating Actual Minutes on CIMI_RWM_00947527_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947532_01	JH3145
Updating Actual Minutes on CIMI_RWM_00947534_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947538_01	PG6512
Updating Actual Minutes on CIMI_RWM_00947543_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947545_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947548_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947551_01	DD6738
All Wire/Work Jobs have Completed, Package now in Complete status.	PG6512
Updating Actual Minutes on CIMI_RWM_00947553_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947555_01	CD5628
Updating Actual Minutes on CIMI_RWM_00947556_01	JH3145
Updating Actual Minutes on CIMI_RWM_00947575_01	DD6738

Updating Actual Minutes on CIMI_RWM_00947581_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947583_01	JH3145
Updating Actual Minutes on CIMI_RWM_00947586_01	JH3145
Updating Actual Minutes on CIMI_RWM_00947592_01	JH3145
Updating Actual Minutes on CIMI_RWM_00947596_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947644_01	CD5628
Updating Actual Minutes on CIMI_RWM_00947645_01	CD5628
Updating Actual Minutes on CIMI_RWM_00947668_01	JH3145
Updating Actual Minutes on CIMI_RWM_00947669_01	JH3145
Updating Actual Minutes on CIMI_RWM_00947673_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947708_01	CD5628
Updating Actual Minutes on CIMI_RWM_00947718_01	JH3145
Updating Actual Minutes on CIMI_RWM_00947726_01	CD5628
Updating Actual Minutes on CIMI_RWM_00947727_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947732_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947741_01	CD5628
Updating Actual Minutes on CIMI_RWM_00947743_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947747_01	CD5628
Updating Actual Minutes on CIMI_RWM_00947749_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947750_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947751_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947758_01	JQ2645
Updating Actual Minutes on CIMI_RWM_00947761_01	JH3145
Updating Actual Minutes on CIMI_RWM_00947766_01	CD5628
Updating Actual Minutes on CIMI_RWM_00947771_01	CD5628
Updating Actual Minutes on CIMI_RWM_00947782_01	CD5628
Updating Actual Minutes on CIMI_RWM_00947790_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947796_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947802_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947810_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947824_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947828_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947830_01	PG6512
Updating Actual Minutes on CIMI_RWM_00947832_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947853_01	CD5628
Updating Actual Minutes on CIMI_RWM_00947862_01	CD5628
Updating Actual Minutes on CIMI_RWM_00947867_01	CD5628
Updating Actual Minutes on CIMI_RWM_00947882_01	CD5628
Updating Actual Minutes on CIMI_RWM_00947891_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947892_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947897_01	CD5628
Updating Actual Minutes on CIMI_RWM_00947898_01	PG6512
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145

Updating Actual Minutes on CIMI_RWM_00947910_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947916_01	CD5628
Updating Actual Minutes on CIMI_RWM_00947917_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947918_01	PG6512
Updating Actual Minutes on CIMI_RWM_00947921_01	CD5628
Updating Actual Minutes on CIMI_RWM_00947922_01	CD5628
Updating Actual Minutes on CIMI_RWM_00947923_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947926_01	DD6738
Package Manually Completed by ca8161.	
Updating Actual Minutes on CIMI_RWM_00947935_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947936_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947939_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947940_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947944_01	DD6738
Updating Actual Minutes on CIMI_RWM_00947952_01	CD5628
all work comp./ placed guard arm	
Updating Actual Minutes on CIMI_RWM_00947976_01	DD6738
Package Manually Completed by ca8161.	
Updating Actual Minutes on CIMI_RWM_00947994_01	CD5628
Updating Actual Minutes on CIMI_RWM_00947995_01	JH3145
Updating Actual Minutes on CIMI_RWM_00947997_01	JH3145
Updating Actual Minutes on CIMI_RWM_00948001_01	JH3145
Updating Actual Minutes on CIMI_RWM_00948007_01	DD6738
Updating Actual Minutes on CIMI_RWM_00948020_01	DD6738
Updating Actual Minutes on CIMI_RWM_00948026_01	CD5628
Package Manually Completed by ca8161.	
ADSS fiber, arm not required	
Updating Actual Minutes on CIMI_RWM_00948034_01	CD5628
Need taller pole to maintain proper roadway clearance	
Pole to short, power built in to our spacing	
Updating Actual Minutes on CIMI_RWM_00948048_01	JH3145
Pole too short to acquire proper spacing	
Updating Actual Minutes on CIMI_RWM_00948052_01	JQ2645
Updating Actual Minutes on CIMI_RWM_00948054_01	JH3145
Arm placed	
Updating Actual Minutes on CIMI_RWM_00948063_01	CD5628
Updating Actual Minutes on CIMI_RWM_00948077_01	CD5628
Updating Actual Minutes on CIMI_RWM_00948078_01	PG6512
Updating Actual Minutes on CIMI_RWM_00948081_01	JH3145
Updating Actual Minutes on CIMI_RWM_00948082_01	CD5628
Updating Actual Minutes on CIMI_RWM_00948090_01	PG6512
All work complete, guard arm placed	
Updating Actual Minutes on CIMI_RWM_00948107_01	CD5628
Updating Actual Minutes on CIMI_RWM_00948109_01	CD5628

Updating Actual Minutes on CIMI_RWM_00948111_01	PG6512
work complete	
Updating Actual Minutes on CIMI_RWM_00948114_01	CD5628
Updating Actual Minutes on CIMI_RWM_00948115_01	PG6512
Package Manually Completed by ca8161.	
Updating Actual Minutes on CIMI_RWM_00948118_01	DD6738
Arm placed	
Updating Actual Minutes on CIMI_RWM_00948120_01	PG6512
Updating Actual Minutes on CIMI_RWM_00948121_01	JQ2645
All Wire/Work Jobs have Completed, Package now in Complete status.	PG6512
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
Updating Actual Minutes on CIMI_RWM_00948129_01	JH3145
Package Manually Completed by ca8161.	
Updating Actual Minutes on CIMI_RWM_00948138_01	PG6512
Updating Actual Minutes on CIMI_RWM_00948139_01	PG6512
Updating Actual Minutes on CIMI_RWM_00948141_01	PG6512
All Wire/Work Jobs have Completed, Package now in Complete status.	PG6512
Updating Actual Minutes on CIMI_RWM_00948146_01	PG6512
Updating Actual Minutes on CIMI_RWM_00948147_01	DD6738
arm placed	
Updating Actual Minutes on CIMI_RWM_00948149_01	DD6738
Updating Actual Minutes on CIMI_RWM_00948151_01	PG6512
Updating Actual Minutes on CIMI_RWM_00948153_01	PG6512
Updating Actual Minutes on CIMI_RWM_00948155_01	PG6512
Updating Actual Minutes on CIMI_RWM_00948157_01	JH3145
Updating Actual Minutes on CIMI_RWM_00948160_01	DD6738
Low drop wire removed.	
Updating Actual Minutes on CIMI_RWM_00948165_01	PG6512
Updating Actual Minutes on CIMI_RWM_00948180_01	PG6512
Updating Actual Minutes on CIMI_RWM_00948183_01	PG6512
Updating Actual Minutes on CIMI_RWM_00948187_01	PG6512
Package Manually Completed by ca8161.	
Updating Actual Minutes on CIMI_RWM_00948195_01	JH3145
Updating Actual Minutes on CIMI_RWM_00948196_01	CD5628
Updating Actual Minutes on CIMI_RWM_00948197_01	DD6738
Updating Actual Minutes on CIMI_RWM_00948198_01	DD6738
Updating Actual Minutes on CIMI_RWM_00948199_01	PG6512
Updating Actual Minutes on CIMI_RWM_00948200_01	PG6512
Updating Actual Minutes on CIMI_RWM_00948201_01	PG6512
Updating Actual Minutes on CIMI_RWM_00948202_01	JH3145
Updating Actual Minutes on CIMI_RWM_00948203_01	PG6512
Updating Actual Minutes on CIMI_RWM_00948204_01	PG6512
Package Manually Completed by ca8161.	
Work complete	

Updating Actual Minutes on CIMI_RWM_00948218_01	PG6512
Updating Actual Minutes on CIMI_RWM_00948221_01	PG6512
No trouble found	
Updating Actual Minutes on CIMI_RWM_00948224_01	CD5628
Updating Actual Minutes on CIMI_RWM_00948225_01	DD6738
Updating Actual Minutes on CIMI_RWM_00948226_01	PG6512
Pole too short	
Updating Actual Minutes on CIMI_RWM_00948229_01	DD6738
Updating Actual Minutes on CIMI_RWM_00948230_01	DD6738
Updating Actual Minutes on CIMI_RWM_00948232_01	CD5628
All Wire/Work Jobs have Completed, Package now in Complete status.	JQ2645
done	
Updating Actual Minutes on CIMI_RWM_00948237_01	DD6738
Moved cables down and placed arm at 48"	
Updating Actual Minutes on CIMI_RWM_00948241_01	CD5628
Updating Actual Minutes on CIMI_RWM_00948242_01	DD6738
Updating Actual Minutes on CIMI_RWM_00948244_01	DD6738
Per ca8161 06/06/22 not AT&T	
Updating Actual Minutes on CIMI_RWM_00948258_01	PG6512
Updating Actual Minutes on CIMI_RWM_00948267_01	JH3145
Updating Actual Minutes on CIMI_RWM_00948268_01	JH3145
Updating Actual Minutes on CIMI_RWM_00948271_01	PG6512
Updating Actual Minutes on CIMI_RWM_00948291_01	CD5628
Updating Actual Minutes on CIMI_RWM_00948293_01	CD5628
Updating Actual Minutes on CIMI_RWM_00948298_01	DD6738
Updating Actual Minutes on CIMI_RWM_00948300_01	DD6738
Updating Actual Minutes on CIMI_RWM_00948301_01	DD6738
Updating Actual Minutes on CIMI_RWM_00948303_01	DD6738
Updating Actual Minutes on CIMI_RWM_00948305_01	CD5628
Guard arm placed, drops spaced. power is built down in our zone	
Package Manually Completed by ca8161.	
Updating Actual Minutes on CIMI_RWM_00948310_01	DD6738
Updating Actual Minutes on CIMI_RWM_00948320_01	CD5628
Needs a taller pole for us to be correct	
Updating Actual Minutes on CIMI_RWM_00948324_01	PG6512
Updating Actual Minutes on CIMI_RWM_00948325_01	PG6512
Package Manually Completed by ca8161.	
Updating Actual Minutes on CIMI_RWM_00948327_01	DD6738
Updating Actual Minutes on CIMI_RWM_00948330_01	DD6738
Updating Actual Minutes on CIMI_RWM_00948333_01	CD5628
Package Manually Completed by ca8161.	
Updating Actual Minutes on CIMI_RWM_00948337_01	PG6512
Pole to short, power built in to our spacing	
All Wire/Work Jobs have Completed, Package now in Complete status.	PG6512

Updating Actual Minutes on CIMI_RWM_00948354_01	JH3145
Updating Actual Minutes on CIMI_RWM_00948358_01	CD5628
Updating Actual Minutes on CIMI_RWM_00948364_01	JH3145
Updating Actual Minutes on CIMI_RWM_00948368_01	CD5628
Updating Actual Minutes on CIMI_RWM_00948369_01	CD5628
Updating Actual Minutes on CIMI_RWM_00948372_01	JH3145
Updating Actual Minutes on CIMI_RWM_00948374_01	CD5628
Updating Actual Minutes on CIMI_RWM_00948377_01	CD5628
Updating Actual Minutes on CIMI_RWM_00948378_01	JH3145
Updating Actual Minutes on CIMI_RWM_00948385_01	JH3145
Arm placed at 48"	
Updating Actual Minutes on CIMI_RWM_00948394_01	DD6738
Updating Actual Minutes on CIMI_RWM_00948397_01	PG6512
Package Manually Completed by ca8161.	
Updating Actual Minutes on CIMI_RWM_00948403_01	JQ2645
Updating Actual Minutes on CIMI_RWM_00948416_01	DD6738
Referred to power for taller pole	
Package Manually Completed by ca8161.	
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
Updating Actual Minutes on CIMI_RWM_00948423_01	DD6738
Updating Actual Minutes on CIMI_RWM_00948432_01	CD5628
Updating Actual Minutes on CIMI_RWM_00948437_01	CD5628
Updating Actual Minutes on CIMI_RWM_00948439_01	PG6512
Updating Actual Minutes on CIMI_RWM_00948453_01	JH3145
Updating Actual Minutes on CIMI_RWM_00948462_01	PG6512
Updating Actual Minutes on CIMI_RWM_00948463_01	PG6512
Updating Actual Minutes on CIMI_RWM_00948483_01	DD6738
Updating Actual Minutes on CIMI_RWM_00948503_01	PG6512
Updating Actual Minutes on CIMI_RWM_00948515_01	DD6738
Updating Actual Minutes on CIMI_RWM_00948516_01	CD5628
Updating Actual Minutes on CIMI_RWM_00948517_01	CD5628
Updating Actual Minutes on CIMI_RWM_00948530_01	CD5628
Updating Actual Minutes on CIMI_RWM_00948535_01	CD5628
Updating Actual Minutes on CIMI_RWM_00948536_01	JH3145
Updating Actual Minutes on CIMI_RWM_00948548_01	CD5628
Updating Actual Minutes on CIMI_RWM_00948553_01	DD6738
Updating Actual Minutes on CIMI_RWM_00948557_01	PG6512
Updating Actual Minutes on CIMI_RWM_00948558_01	DD6738
Updating Actual Minutes on CIMI_RWM_00948562_01	PG6512
Updating Actual Minutes on CIMI_RWM_00948563_01	PG6512
Updating Actual Minutes on CIMI_RWM_00948573_01	PG6512
All Wire/Work Jobs have Completed, Package now in Complete status.	SM3126
Updating Actual Minutes on CIMI_RWM_00948590_01	PG6512
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537

All Wire/Work Jobs have Completed, Package now in Complete status.	QB6851
All Wire/Work Jobs have Completed, Package now in Complete status.	KS6734
All Wire/Work Jobs have Completed, Package now in Complete status.	MD4156
All Wire/Work Jobs have Completed, Package now in Complete status.	MD4156
All Wire/Work Jobs have Completed, Package now in Complete status.	QB6851
All Wire/Work Jobs have Completed, Package now in Complete status.	QB6851
All Wire/Work Jobs have Completed, Package now in Complete status.	JI2512
All Wire/Work Jobs have Completed, Package now in Complete status.	QB6851
All Wire/Work Jobs have Completed, Package now in Complete status.	QB6851
Updating Actual Minutes on CIMI_RWM_00955302_01	QB6851
All Wire/Work Jobs have Completed, Package now in Complete status.	CG4741
All Wire/Work Jobs have Completed, Package now in Complete status.	GG8932
All Wire/Work Jobs have Completed, Package now in Complete status.	QB6851
All Wire/Work Jobs have Completed, Package now in Complete status.	QB6851
All Wire/Work Jobs have Completed, Package now in Complete status.	QB6851
All Wire/Work Jobs have Completed, Package now in Complete status.	QB6851
All Wire/Work Jobs have Completed, Package now in Complete status.	RH5983
Updating Actual Minutes on CIMI_RWM_00956118_01	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	QB6851
All Wire/Work Jobs have Completed, Package now in Complete status.	GS6496
All Wire/Work Jobs have Completed, Package now in Complete status.	JS6852
Updating Actual Minutes on CIMI_RWM_00962094_01	RX3937
Updating Actual Minutes on CIMI_RWM_00962095_01	SC2675
Updating Actual Minutes on CIMI_RWM_00962109_01	SC2675
Updating Actual Minutes on CIMI_RWM_00962127_01	SC2675
All Wire/Work Jobs have Completed, Package now in Complete status.	RA4618
All Wire/Work Jobs have Completed, Package now in Complete status.	RA4618
All Wire/Work Jobs have Completed, Package now in Complete status.	RA4618
Package Manually Completed by jp2396.	
All Wire/Work Jobs have Completed, Package now in Complete status.	KS8192
Updating Actual Minutes on CIMI_RWM_00962177_01	SC2675
Updating Actual Minutes on CIMI_RWM_00962190_01	SC2675
All Wire/Work Jobs have Completed, Package now in Complete status.	HP4528
Updating Actual Minutes on CIMI_RWM_00962206_01	SC2675
All Wire/Work Jobs have Completed, Package now in Complete status.	HP4528
Updating Actual Minutes on CIMI_RWM_00962214_01	SC2675
Updating Actual Minutes on CIMI_RWM_00962240_01	SC2675
Updating Actual Minutes on CIMI_RWM_00962241_01	SC2675
Updating Actual Minutes on CIMI_RWM_00962242_01	SC2675
Updating Actual Minutes on CIMI_RWM_00962247_01	SC2675
All Wire/Work Jobs have Completed, Package now in Complete status.	MD4156
Updating Actual Minutes on CIMI_RWM_00962282_01	SC2675

Updating Actual Minutes on CIMI_RWM_00962283_01	SC2675
All Wire/Work Jobs have Completed, Package now in Complete status.	RA4618
Updating Actual Minutes on CIMI_RWM_00962297_01	SC2675
Updating Actual Minutes on CIMI_RWM_00962305_01	CN2921
Updating Actual Minutes on CIMI_RWM_00962329_01	SC2675
Updating Actual Minutes on CIMI_RWM_00962333_01	TL3147
All Wire/Work Jobs have Completed, Package now in Complete status.	GS6496
Updating Actual Minutes on CIMI_RWM_00962342_01	SC2675
Updating Actual Minutes on CIMI_RWM_00962362_01	SC2675
Updating Actual Minutes on CIMI_RWM_00962366_01	SC2675
Updating Actual Minutes on CIMI_RWM_00962367_01	TL3147
All Wire/Work Jobs have Completed, Package now in Complete status.	GS6496
Updating Actual Minutes on CIMI_RWM_00962370_01	TL3147
All Wire/Work Jobs have Completed, Package now in Complete status.	GS6496
All Wire/Work Jobs have Completed, Package now in Complete status.	MG1262
Updating Actual Minutes on CIMI_RWM_00962381_01	JS3172
Updating Actual Minutes on CIMI_RWM_00962390_01	SC2675
All Wire/Work Jobs have Completed, Package now in Complete status.	KS8192
All Wire/Work Jobs have Completed, Package now in Complete status.	AW2727
Updating Actual Minutes on CIMI_RWM_00962395_01	TL3147
All Wire/Work Jobs have Completed, Package now in Complete status.	KS8192
All Wire/Work Jobs have Completed, Package now in Complete status.	AW2727
Updating Actual Minutes on CIMI_RWM_00962413_01	CN2921
Updating Actual Minutes on CIMI_RWM_00962416_01	JS3172
Updating Actual Minutes on CIMI_RWM_00962428_01	CN2921
Updating Actual Minutes on CIMI_RWM_00962430_01	SC2675
All Wire/Work Jobs have Completed, Package now in Complete status.	KS6734
Updating Actual Minutes on CIMI_RWM_00962444_01	JS3172
Updating Actual Minutes on CIMI_RWM_00962450_01	CN2921
Updating Actual Minutes on CIMI_RWM_00962451_01	SC2675
Updating Actual Minutes on CIMI_RWM_00962455_01	CN2921
Updating Actual Minutes on CIMI_RWM_00962456_01	PM8616
Updating Actual Minutes on CIMI_RWM_00962463_01	PM8616
Updating Actual Minutes on CIMI_RWM_00962468_01	SG1898
Updating Actual Minutes on CIMI_RWM_00962483_01	SG1898
Updating Actual Minutes on CIMI_RWM_00962485_01	WA6713
Updating Actual Minutes on CIMI_RWM_00962486_01	KL2356
Updating Actual Minutes on CIMI_RWM_00962488_01	DS4637
Updating Actual Minutes on CIMI_RWM_00962496_01	WA6713
Updating Actual Minutes on CIMI_RWM_00962497_01	MD2797
Updating Actual Minutes on CIMI_RWM_00962498_01	CN2921
Updating Actual Minutes on CIMI_RWM_00962499_01	CN2921
Updating Actual Minutes on CIMI_RWM_00962502_01	CN2921
All Wire/Work Jobs have Completed, Package now in Complete status.	RK7932

All Wire/Work Jobs have Completed, Package now in Complete status.	RK7932
All Wire/Work Jobs have Completed, Package now in Complete status.	AV1412
All Wire/Work Jobs have Completed, Package now in Complete status.	MG1262
This Package was completed from OSPCM/JAM! Moving to Complete.	
This Package was completed from OSPCM/JAM! Moving to Complete.	
Updating Actual Minutes on CIMI_RWM_00970190_01	DB8381
This Package was completed from OSPCM/JAM! Moving to Complete.	
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
Updating Actual Minutes on CIMI_RWM_00970219_01	RH749C
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
Updating Actual Minutes on CIMI_RWM_00970234_01	AC1532
This Package was completed from OSPCM/JAM! Moving to Complete.	
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
This Package was completed from OSPCM/JAM! Moving to Complete.	
All Wire/Work Jobs have Completed, Package now in Complete status.	CC2745
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
Updating Actual Minutes on CIMI_RWM_00970258_01	AC1532
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
Updating Actual Minutes on CIMI_RWM_00970266_01	RH749C
Updating Actual Minutes on CIMI_RWM_00970269_01	DB8381
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
All Wire/Work Jobs have Completed, Package now in Complete status.	CC2745
All Wire/Work Jobs have Completed, Package now in Complete status.	CC2745
Updating Actual Minutes on CIMI_RWM_00970296_01	AC1532
Updating Actual Minutes on CIMI_RWM_00970299_01	RH749C
All Wire/Work Jobs have Completed, Package now in Complete status.	CC2745
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
All Wire/Work Jobs have Completed, Package now in Complete status.	CC2745
Updating Actual Minutes on CIMI_RWM_00970377_01	DB8381
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
Updating Actual Minutes on CIMI_RWM_00970381_01	AC1532
This Package was completed from OSPCM/JAM! Moving to Complete.	
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
This Package was completed from OSPCM/JAM! Moving to Complete.	
Updating Actual Minutes on CIMI_RWM_00970396_01	DB8381
Updating Actual Minutes on CIMI_RWM_00970397_01	DB8381
Updating Actual Minutes on CIMI_RWM_00970400_01	AC1532

Updating Actual Minutes on CIMI_RWM_00970406_01	AC1532
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
Updating Actual Minutes on CIMI_RWM_00970424_01	DB8381
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
Updating Actual Minutes on CIMI_RWM_00970430_01	DB8381
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
Updating Actual Minutes on CIMI_RWM_00970442_01	AC1532
Updating Actual Minutes on CIMI_RWM_00970443_01	DM258S
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
Updating Actual Minutes on CIMI_RWM_00986067_01	MD2797
Updating Actual Minutes on CIMI_RWM_00986072_01	LP848K
Updating Actual Minutes on CIMI_RWM_00986073_01	LP848K
Updating Actual Minutes on CIMI_RWM_00986077_01	MD4156
Updating Actual Minutes on CIMI_RWM_00986081_01	MM3647
Updating Actual Minutes on CIMI_RWM_00986082_01	MM3647
Updating Actual Minutes on CIMI_RWM_00986087_01	MD2797
All Wire/Work Jobs have Completed, Package now in Complete status.	JS2145
Updating Actual Minutes on CIMI_RWM_00986106_01	JS2145
Updating Actual Minutes on CIMI_RWM_00986109_01	QB6851
Updating Actual Minutes on CIMI_RWM_00986121_01	RC5742
Updating Actual Minutes on CIMI_RWM_00986122_01	MD2797
All Wire/Work Jobs have Completed, Package now in Complete status.	SM1897
All Wire/Work Jobs have Completed, Package now in Complete status.	FR1292
All Wire/Work Jobs have Completed, Package now in Complete status.	FR1292
All Wire/Work Jobs have Completed, Package now in Complete status.	JA1893
Updating Actual Minutes on CIMI_RWM_00986130_01	QB6851
Updating Actual Minutes on CIMI_RWM_00986142_01	LP848K
Updating Actual Minutes on CIMI_RWM_00986150_01	LP848K
All Wire/Work Jobs have Completed, Package now in Complete status.	JJ6768
Updating Actual Minutes on CIMI_RWM_00986173_01	QB6851
Updating Actual Minutes on CIMI_RWM_00986185_01	DM820T
Updating Actual Minutes on CIMI_RWM_00986186_01	DM820T
Updating Actual Minutes on CIMI_RWM_00986199_01	DM820T
Updating Actual Minutes on CIMI_RWM_00986201_01	DM820T
Updating Actual Minutes on CIMI_RWM_00986205_01	DM820T
Updating Actual Minutes on CIMI_RWM_00986208_01	LP848K
Updating Actual Minutes on CIMI_RWM_00986209_01	DM820T
All Wire/Work Jobs have Completed, Package now in Complete status.	FR1292
Updating Actual Minutes on CIMI_RWM_00986217_01	LP848K
All Wire/Work Jobs have Completed, Package now in Complete status.	JJ6768
Updating Actual Minutes on CIMI_RWM_00986220_01	LP848K
Updating Actual Minutes on CIMI_RWM_00986221_01	LP848K
Updating Actual Minutes on CIMI_RWM_00986224_01	MM3647

Updating Actual Minutes on CIMI_RWM_00986225_01	JM1295
Updating Actual Minutes on CIMI_RWM_00986227_01	MD2797
Updating Actual Minutes on CIMI_RWM_00986234_01	QB6851
Updating Actual Minutes on CIMI_RWM_00986235_01	QB6851
Updating Actual Minutes on CIMI_RWM_00986236_01	QB6851
Updating Actual Minutes on CIMI_RWM_00986237_01	QB6851
Updating Actual Minutes on CIMI_RWM_00986238_01	QB6851
Updating Actual Minutes on CIMI_RWM_00986242_01	LP848K
Updating Actual Minutes on CIMI_RWM_00986246_01	PC9347
Updating Actual Minutes on CIMI_RWM_00986271_01	DM820T
Updating Actual Minutes on CIMI_RWM_00986272_01	DM820T
Updating Actual Minutes on CIMI_RWM_00986274_01	DM820T
Updating Actual Minutes on CIMI_RWM_00986285_01	RW5286
Updating Actual Minutes on CIMI_RWM_00986287_01	LP848K
Updating Actual Minutes on CIMI_RWM_00986293_01	MM3647
Updating Actual Minutes on CIMI_RWM_00986294_01	PC9347
Updating Actual Minutes on CIMI_RWM_00986295_01	JM1295
Updating Actual Minutes on CIMI_RWM_00986299_01	DM820T
Updating Actual Minutes on CIMI_RWM_00986300_01	DM820T
Updating Actual Minutes on CIMI_RWM_00986309_01	LP848K
Updating Actual Minutes on CIMI_RWM_00986313_01	SB6349
Updating Actual Minutes on CIMI_RWM_00986315_01	QB6851
Updating Actual Minutes on CIMI_RWM_00986318_01	MM3647
Updating Actual Minutes on CIMI_RWM_00986330_01	QB6851
Updating Actual Minutes on CIMI_RWM_00986344_01	JS2145
Updating Actual Minutes on CIMI_RWM_00986345_01	MD2797
Updating Actual Minutes on CIMI_RWM_00986347_01	DM820T
Updating Actual Minutes on CIMI_RWM_00986348_01	LP848K
Updating Actual Minutes on CIMI_RWM_00986349_01	LP848K
Updating Actual Minutes on CIMI_RWM_00986353_01	LP848K
Updating Actual Minutes on CIMI_RWM_00986358_01	LP848K
Updating Actual Minutes on CIMI_RWM_00986363_01	JM1295
Updating Actual Minutes on CIMI_RWM_00986366_01	MM3647
Updating Actual Minutes on CIMI_RWM_00986369_01	DM820T
Updating Actual Minutes on CIMI_RWM_00986379_01	WE5739
All Wire/Work Jobs have Completed, Package now in Complete status.	DC2631
Updating Actual Minutes on CIMI_RWM_00986381_01	LP848K
Updating Actual Minutes on CIMI_RWM_00986383_01	LP848K
All Wire/Work Jobs have Completed, Package now in Complete status.	DC2631
All Wire/Work Jobs have Completed, Package now in Complete status.	BK2151
Updating Actual Minutes on CIMI_RWM_00986396_01	LP848K
Updating Actual Minutes on CIMI_RWM_00986401_01	QB6851
All Wire/Work Jobs have Completed, Package now in Complete status.	DC2631
Updating Actual Minutes on CIMI_RWM_00986421_01	RW5286

Updating Actual Minutes on CIMI_RWM_00986425_01	LP848K
Updating Actual Minutes on CIMI_RWM_00986428_01	LP848K
Updating Actual Minutes on CIMI_RWM_00986441_01	RC5742
All Wire/Work Jobs have Completed, Package now in Complete status.	EL8648
Updating Actual Minutes on CIMI_RWM_00986473_01	DM820T
All Wire/Work Jobs have Completed, Package now in Complete status.	JJ6768
Updating Actual Minutes on CIMI_RWM_00986478_01	DM820T
Updating Actual Minutes on CIMI_RWM_00986479_01	QB6851
All Wire/Work Jobs have Completed, Package now in Complete status.	JI2512
Updating Actual Minutes on CIMI_RWM_00986486_01	RW5286
Updating Actual Minutes on CIMI_RWM_00986498_01	MD2797
Updating Actual Minutes on CIMI_RWM_00986500_01	LP848K
Updating Actual Minutes on CIMI_RWM_00986501_01	MD2797
Updating Actual Minutes on CIMI_RWM_00986502_01	MD2797
All Wire/Work Jobs have Completed, Package now in Complete status.	AM2764
Updating Actual Minutes on CIMI_RWM_00986505_01	LP848K
Updating Actual Minutes on CIMI_RWM_00986527_01	RC5742
Updating Actual Minutes on CIMI_RWM_00986540_01	RC5742
Updating Actual Minutes on CIMI_RWM_00986548_01	MD4156
Updating Actual Minutes on CIMI_RWM_00986550_01	JM1295
Updating Actual Minutes on CIMI_RWM_00986557_01	RW5286
Updating Actual Minutes on CIMI_RWM_00986559_01	LP848K
Updating Actual Minutes on CIMI_RWM_00986563_01	SB6349
Updating Actual Minutes on CIMI_RWM_00986571_01	PC9347
Updating Actual Minutes on CIMI_RWM_00986572_01	PC9347
All Wire/Work Jobs have Completed, Package now in Complete status.	DC2631
Updating Actual Minutes on CIMI_RWM_00986596_01	RB2427
Updating Actual Minutes on CIMI_RWM_00986598_01	JM1295
Updating Actual Minutes on CIMI_RWM_00986607_01	SB6349
Updating Actual Minutes on CIMI_RWM_00986609_01	ML1973
Updating Actual Minutes on CIMI_RWM_00986619_01	LP848K
Updating Actual Minutes on CIMI_RWM_00986621_01	MD4156
All Wire/Work Jobs have Completed, Package now in Complete status.	JA1893
Updating Actual Minutes on CIMI_RWM_00986642_01	MM3647
Updating Actual Minutes on CIMI_RWM_00986647_01	LP848K
Updating Actual Minutes on CIMI_RWM_00986661_01	LP848K
All Wire/Work Jobs have Completed, Package now in Complete status.	QB6851
All Wire/Work Jobs have Completed, Package now in Complete status.	QB6851
All Wire/Work Jobs have Completed, Package now in Complete status.	QB6851
All Wire/Work Jobs have Completed, Package now in Complete status.	JI2512
All Wire/Work Jobs have Completed, Package now in Complete status.	JJ6768
Updating Actual Minutes on CIMI_RWM_00986690_01	DM820T
All Wire/Work Jobs have Completed, Package now in Complete status.	JA1893
Updating Actual Minutes on CIMI_RWM_00986694_01	DM820T

Updating Actual Minutes on CIMI_RWM_00986696_01	MD2797
Updating Actual Minutes on CIMI_RWM_00986707_01	RW5286
Updating Actual Minutes on CIMI_RWM_00986710_01	RW5286
Updating Actual Minutes on CIMI_RWM_00986731_01	MD2797
All Wire/Work Jobs have Completed, Package now in Complete status.	VC6131
Updating Actual Minutes on CIMI_RWM_00986742_01	QB6851
Updating Actual Minutes on CIMI_RWM_00986744_01	JS2145
All Wire/Work Jobs have Completed, Package now in Complete status.	JA1893
Updating Actual Minutes on CIMI_RWM_00986750_01	DM820T
Updating Actual Minutes on CIMI_RWM_00986753_01	LP848K
Updating Actual Minutes on CIMI_RWM_00986754_01	LP848K
Updating Actual Minutes on CIMI_RWM_00986755_01	LP848K
Updating Actual Minutes on CIMI_RWM_00986756_01	LP848K
Updating Actual Minutes on CIMI_RWM_00986757_01	QB6851
Updating Actual Minutes on CIMI_RWM_00986769_01	DM820T
Updating Actual Minutes on CIMI_RWM_00986771_01	JS2145
Updating Actual Minutes on CIMI_RWM_00986772_01	JM1295
Updating Actual Minutes on CIMI_RWM_00986773_01	RW5286
Updating Actual Minutes on CIMI_RWM_00986785_01	MD2797
Updating Actual Minutes on CIMI_RWM_00986788_01	RW5286
Updating Actual Minutes on CIMI_RWM_00986790_01	QB6851
Updating Actual Minutes on CIMI_RWM_00986793_H01	PC9347
Updating Actual Minutes on CIMI_RWM_00986798_01	JM1295
Updating Actual Minutes on CIMI_RWM_00986812_01	SB6349
Updating Actual Minutes on CIMI_RWM_00986815_01	RX3937
Updating Actual Minutes on CIMI_RWM_00986817_01	RX3937
Updating Actual Minutes on CIMI_RWM_00986824_01	WE5739
Updating Actual Minutes on CIMI_RWM_00986826_01	MD2797
Updating Actual Minutes on CIMI_RWM_00986827_01	MD2797
All Wire/Work Jobs have Completed, Package now in Complete status.	JJ6768
Updating Actual Minutes on CIMI_RWM_00986834_01	MD4156
Updating Actual Minutes on CIMI_RWM_00986841_01	JO1454
Updating Actual Minutes on CIMI_RWM_00986843_01	PC9347
Updating Actual Minutes on CIMI_RWM_00986850_01	RP6278
All Wire/Work Jobs have Completed, Package now in Complete status.	JA1893
All Wire/Work Jobs have Completed, Package now in Complete status.	AG2675
Updating Actual Minutes on CIMI_RWM_00986855_01	RP6278
Updating Actual Minutes on CIMI_RWM_00986857_01	JM1295
Updating Actual Minutes on CIMI_RWM_00986868_01	KL2356
Updating Actual Minutes on CIMI_RWM_00986871_01	KL2356
Updating Actual Minutes on CIMI_RWM_00986877_01	MD2797
Updating Actual Minutes on CIMI_RWM_00986878_01	MD2797
All Wire/Work Jobs have Completed, Package now in Complete status.	JI2512
Updating Actual Minutes on CIMI_RWM_00986887_01	MD4156

All Wire/Work Jobs have Completed, Package now in Complete status.	BK2151
Updating Actual Minutes on CIMI_RWM_00986893_01	QB6851
Updating Actual Minutes on CIMI_RWM_00986899_01	SB6349
Updating Actual Minutes on CIMI_RWM_00986902_01	JM1295
Updating Actual Minutes on CIMI_RWM_00986903_01	RC5742
Updating Actual Minutes on CIMI_RWM_00986912_01	LP848K
Updating Actual Minutes on CIMI_RWM_00986922_01	MD2797
Updating Actual Minutes on CIMI_RWM_00986924_01	MM3647
Updating Actual Minutes on CIMI_RWM_00986925_01	WE5739
Updating Actual Minutes on CIMI_RWM_00986929_01	WE5739
Updating Actual Minutes on CIMI_RWM_00986930_01	MD2797
Updating Actual Minutes on CIMI_RWM_00986932_01	QB6851
Updating Actual Minutes on CIMI_RWM_00986937_01	DM820T
Updating Actual Minutes on CIMI_RWM_00986940_01	DM820T
Updating Actual Minutes on CIMI_RWM_00986942_01	DM820T
Updating Actual Minutes on CIMI_RWM_00986943_01	DM820T
Updating Actual Minutes on CIMI_RWM_00986944_01	QB6851
Updating Actual Minutes on CIMI_RWM_00986946_01	DM820T
All Wire/Work Jobs have Completed, Package now in Complete status.	JI2512
Updating Actual Minutes on CIMI_RWM_00986952_01	LP848K
Updating Actual Minutes on CIMI_RWM_00986953_01	LP848K
Updating Actual Minutes on CIMI_RWM_00986954_01	RC5742
Updating Actual Minutes on CIMI_RWM_00986962_01	LP848K
All Wire/Work Jobs have Completed, Package now in Complete status.	DC2631
Updating Actual Minutes on CIMI_RWM_00986988_01	DM820T
Updating Actual Minutes on CIMI_RWM_00986993_01	MD4156
Updating Actual Minutes on CIMI_RWM_00986995_01	MD2797
Updating Actual Minutes on CIMI_RWM_00987001_01	LP848K
Updating Actual Minutes on CIMI_RWM_00987003_01	MD4156
Updating Actual Minutes on CIMI_RWM_00987004_01	MD4156
Updating Actual Minutes on CIMI_RWM_00987005_01	RW5286
Updating Actual Minutes on CIMI_RWM_00987006_01	RW5286
Updating Actual Minutes on CIMI_RWM_00987010_01	JM1295
Updating Actual Minutes on CIMI_RWM_00987012_01	DM820T
Updating Actual Minutes on CIMI_RWM_00987013_01	DM820T
Updating Actual Minutes on CIMI_RWM_00987014_01	DM820T
Updating Actual Minutes on CIMI_RWM_00987016_01	ML1973
Updating Actual Minutes on CIMI_RWM_00987017_01	LP848K
Updating Actual Minutes on CIMI_RWM_00987018_01	DM820T
Updating Actual Minutes on CIMI_RWM_00987019_01	LP848K
Updating Actual Minutes on CIMI_RWM_00987023_01	QB6851
Updating Actual Minutes on CIMI_RWM_00987027_01	QB6851
All Wire/Work Jobs have Completed, Package now in Complete status.	MD4156
Updating Actual Minutes on CIMI_RWM_00987040_01	RC5742

Updating Actual Minutes on CIMI_RWM_00987048_01	JM1295
All Wire/Work Jobs have Completed, Package now in Complete status.	JA1893
Updating Actual Minutes on CIMI_RWM_00987050_01	MD2797
Updating Actual Minutes on CIMI_RWM_00987053_01	MD2797
Updating Actual Minutes on CIMI_RWM_00987063_01	MD2797
Updating Actual Minutes on CIMI_RWM_00987181_01	PC9347
Updating Actual Minutes on CIMI_RWM_00987182_01	PC9347
All Wire/Work Jobs have Completed, Package now in Complete status.	JS2145
Updating Actual Minutes on CIMI_RWM_00987189_01	LP848K
Updating Actual Minutes on CIMI_RWM_00987192_01	MD2797
All Wire/Work Jobs have Completed, Package now in Complete status.	AM8121
Updating Actual Minutes on CIMI_RWM_00987245_01	MM3647
Updating Actual Minutes on CIMI_RWM_00987281_01	VC6131
Updating Actual Minutes on CIMI_RWM_00987289_01	VC6131
Updating Actual Minutes on CIMI_RWM_00987293_01	JO1454
All Wire/Work Jobs have Completed, Package now in Complete status.	BK2151
Updating Actual Minutes on CIMI_RWM_00987303_01	JM1295
All Wire/Work Jobs have Completed, Package now in Complete status.	AG2675
Updating Actual Minutes on CIMI_RWM_00987306_01	QB6851
Updating Actual Minutes on CIMI_RWM_00987310_01	RW5286
Updating Actual Minutes on CIMI_RWM_00987312_01	QB6851
Updating Actual Minutes on CIMI_RWM_00987316_01	QB6851
Updating Actual Minutes on CIMI_RWM_00987321_01	QB6851
All Wire/Work Jobs have Completed, Package now in Complete status.	AM2764
Updating Actual Minutes on CIMI_RWM_00987363_01	LP848K
Updating Actual Minutes on CIMI_RWM_00987365_01	MM3647
Updating Actual Minutes on CIMI_RWM_00987366_01	PC9347
Updating Actual Minutes on CIMI_RWM_00987377_01	PC9347
Updating Actual Minutes on CIMI_RWM_00987382_01	MD4156
Updating Actual Minutes on CIMI_RWM_00987384_01	RW5286
Updating Actual Minutes on CIMI_RWM_00987385_01	RW5286
Updating Actual Minutes on CIMI_RWM_00987386_01	MD4156
Updating Actual Minutes on CIMI_RWM_00987389_01	RW5286
Updating Actual Minutes on CIMI_RWM_00987397_01	MM3647
Updating Actual Minutes on CIMI_RWM_00987401_01	MD2797
Updating Actual Minutes on CIMI_RWM_00987405_01	QB6851
Updating Actual Minutes on CIMI_RWM_00987409_01	JM1295
All Wire/Work Jobs have Completed, Package now in Complete status.	BK2151
Updating Actual Minutes on CIMI_RWM_00987413_01	LP848K
All Wire/Work Jobs have Completed, Package now in Complete status.	JR8198
Updating Actual Minutes on CIMI_RWM_00987440_01	RW5286
Updating Actual Minutes on CIMI_RWM_00987441_01	QB6851
Updating Actual Minutes on CIMI_RWM_00987442_01	LP848K
Updating Actual Minutes on CIMI_RWM_00987458_01	LP848K

Updating Actual Minutes on CIMI_RWM_00987474_01	MM3647
Updating Actual Minutes on CIMI_RWM_00987491_01	DM820T
Updating Actual Minutes on CIMI_RWM_00987493_01	DM820T
Updating Actual Minutes on CIMI_RWM_00987495_01	RW5286
Updating Actual Minutes on CIMI_RWM_00987497_01	QB6851
All Wire/Work Jobs have Completed, Package now in Complete status.	BK2151
Updating Actual Minutes on CIMI_RWM_00987503_01	QB6851
Updating Actual Minutes on CIMI_RWM_00987505_01	QB6851
Updating Actual Minutes on CIMI_RWM_00987506_01	QB6851
Updating Actual Minutes on CIMI_RWM_00987509_01	PC9347
Updating Actual Minutes on CIMI_RWM_00987516_01	PC9347
Updating Actual Minutes on CIMI_RWM_00987524_01	PC9347
Updating Actual Minutes on CIMI_RWM_00987526_01	RW5286
Updating Actual Minutes on CIMI_RWM_00987533_01	MM3647
All Wire/Work Jobs have Completed, Package now in Complete status.	JA1893
Updating Actual Minutes on CIMI_RWM_00987546_01	MM3647
Updating Actual Minutes on CIMI_RWM_00987549_01	DM820T
Updating Actual Minutes on CIMI_RWM_00987563_01	DM820T
Updating Actual Minutes on CIMI_RWM_00987564_01	QB6851
Updating Actual Minutes on CIMI_RWM_00987566_01	QB6851
Updating Actual Minutes on CIMI_RWM_00987567_01	QB6851
Updating Actual Minutes on CIMI_RWM_00987568_01	QB6851
All Wire/Work Jobs have Completed, Package now in Complete status.	AG2675
All Wire/Work Jobs have Completed, Package now in Complete status.	SM1897
Updating Actual Minutes on CIMI_RWM_00987571_01	PC9347
Updating Actual Minutes on CIMI_RWM_00987572_01	DM820T
Updating Actual Minutes on CIMI_RWM_00987588_01	LP848K
Updating Actual Minutes on CIMI_RWM_00987591_01	JS2145
Updating Actual Minutes on CIMI_RWM_00987596_01	MD4156
Updating Actual Minutes on CIMI_RWM_00987597_01	WE5739
Updating Actual Minutes on CIMI_RWM_00987598_01	QB6851
Updating Actual Minutes on CIMI_RWM_00987600_01	QB6851
Updating Actual Minutes on CIMI_RWM_00987605_01	LP848K
Updating Actual Minutes on CIMI_RWM_00987606_01	MD4156
Updating Actual Minutes on CIMI_RWM_00987624_01	LP848K
Updating Actual Minutes on CIMI_RWM_00987625_01	QB6851
Updating Actual Minutes on CIMI_RWM_00987627_01	MM3647
All Wire/Work Jobs have Completed, Package now in Complete status.	EL8648
All Wire/Work Jobs have Completed, Package now in Complete status.	EL8648
Updating Actual Minutes on CIMI_RWM_00987631_01	MM3647
Updating Actual Minutes on CIMI_RWM_00987636_01	MD4156
Updating Actual Minutes on CIMI_RWM_00987638_01	QB6851
Updating Actual Minutes on CIMI_RWM_00987641_01	QB6851
Updating Actual Minutes on CIMI_RWM_00987642_01	MM3647

Updating Actual Minutes on CIMI_RWM_00987644_01	VC6131
Updating Actual Minutes on CIMI_RWM_00987650_01	RC5742
Updating Actual Minutes on CIMI_RWM_00987651_01	PC9347
Updating Actual Minutes on CIMI_RWM_00987655_01	QB6851
Updating Actual Minutes on CIMI_RWM_00987656_01	QB6851
Updating Actual Minutes on CIMI_RWM_00987661_01	PC9347
All Wire/Work Jobs have Completed, Package now in Complete status.	OD4318
Updating Actual Minutes on CIMI_RWM_00987672_01	PC9347
Updating Actual Minutes on CIMI_RWM_00987682_01	VC6131
Updating Actual Minutes on CIMI_RWM_00987684_01	WE5739
Updating Actual Minutes on CIMI_RWM_00987686_01	VC6131
Updating Actual Minutes on CIMI_RWM_00987688_01	MD4156
Updating Actual Minutes on CIMI_RWM_00987690_01	SB6349
Updating Actual Minutes on CIMI_RWM_00987695_01	MM3647
Updating Actual Minutes on CIMI_RWM_00987696_01	QB6851
Updating Actual Minutes on CIMI_RWM_00987697_01	MM3647
Updating Actual Minutes on CIMI_RWM_00987700_01	QB6851
Updating Actual Minutes on CIMI_RWM_00987701_01	QB6851
Updating Actual Minutes on CIMI_RWM_00987711_01	JS2145
Updating Actual Minutes on CIMI_RWM_00987712_01	VC6131
All Wire/Work Jobs have Completed, Package now in Complete status.	BK2151
Updating Actual Minutes on CIMI_RWM_00987726_01	VC6131
Updating Actual Minutes on CIMI_RWM_00987727_01	PC9347
Updating Actual Minutes on CIMI_RWM_00987742_01	PC9347
Updating Actual Minutes on CIMI_RWM_00987750_01	WE5739
Updating Actual Minutes on CIMI_RWM_00987751_01	MD2797
Updating Actual Minutes on CIMI_RWM_00987753_01	PC9347
Updating Actual Minutes on CIMI_RWM_00987754_01	VC6131
Updating Actual Minutes on CIMI_RWM_00987756_01	VC6131
Updating Actual Minutes on CIMI_RWM_00987758_01	MD4156
Updating Actual Minutes on CIMI_RWM_00987759_01	PC9347
Updating Actual Minutes on CIMI_RWM_00987760_01	MD4156
Updating Actual Minutes on CIMI_RWM_00987761_01	JO1454
Updating Actual Minutes on CIMI_RWM_00987762_01	MM3647
All Wire/Work Jobs have Completed, Package now in Complete status.	JA1893
All Wire/Work Jobs have Completed, Package now in Complete status.	AM8121
Updating Actual Minutes on CIMI_RWM_00987781_01	RW5286
All Wire/Work Jobs have Completed, Package now in Complete status.	JA1893
Updating Actual Minutes on CIMI_RWM_00987783_01	VC6131
Updating Actual Minutes on CIMI_RWM_00987784_01	RW5286
Updating Actual Minutes on CIMI_RWM_00987787_01	VC6131
Updating Actual Minutes on CIMI_RWM_00987789_01	JS2145
Updating Actual Minutes on CIMI_RWM_00987800_01	VC6131
Updating Actual Minutes on CIMI_RWM_00987801_01	VC6131

Updating Actual Minutes on CIMI_RWM_00987802_01	RC5742
Updating Actual Minutes on CIMI_RWM_00987815_01	QB6851
Updating Actual Minutes on CIMI_RWM_00987820_01	QB6851
Updating Actual Minutes on CIMI_RWM_00987826_01	QB6851
Updating Actual Minutes on CIMI_RWM_00987829_01	QB6851
Updating Actual Minutes on CIMI_RWM_00987830_01	JS2145
All Wire/Work Jobs have Completed, Package now in Complete status.	DI1638
All Wire/Work Jobs have Completed, Package now in Complete status.	EL8648
Updating Actual Minutes on CIMI_RWM_00987838_01	JS2145
Updating Actual Minutes on CIMI_RWM_00987843_01	JS2145
All Wire/Work Jobs have Completed, Package now in Complete status.	BK2151
Updating Actual Minutes on CIMI_RWM_00987845_01	JO1454
Updating Actual Minutes on CIMI_RWM_00987846_01	JO1454
Updating Actual Minutes on CIMI_RWM_00987848_01	JO1454
All Wire/Work Jobs have Completed, Package now in Complete status.	JA1893
Updating Actual Minutes on CIMI_RWM_00987851_01	DM820T
Updating Actual Minutes on CIMI_RWM_00987853_01	RW5286
Updating Actual Minutes on CIMI_RWM_00987856_01	RW5286
All Wire/Work Jobs have Completed, Package now in Complete status.	JA1893
All Wire/Work Jobs have Completed, Package now in Complete status.	CC6897
Updating Actual Minutes on CIMI_RWM_00987871_01	QB6851
All Wire/Work Jobs have Completed, Package now in Complete status.	WW1427
Updating Actual Minutes on CIMI_RWM_00987879_01	QB6851
Updating Actual Minutes on CIMI_RWM_00987880_01	VC6131
Updating Actual Minutes on CIMI_RWM_00987881_01	WE5739
Updating Actual Minutes on CIMI_RWM_00987884_01	MM3647
Updating Actual Minutes on CIMI_RWM_00987889_01	LP848K
Updating Actual Minutes on CIMI_RWM_00987893_01	LP848K
Updating Actual Minutes on CIMI_RWM_00987894_01	LP848K
Updating Actual Minutes on CIMI_RWM_00987897_01	DM820T
Updating Actual Minutes on CIMI_RWM_00987906_01	MM3647
Updating Actual Minutes on CIMI_RWM_00987907_01	DM820T
Updating Actual Minutes on CIMI_RWM_00987912_01	MM3647
All Wire/Work Jobs have Completed, Package now in Complete status.	AM2764
Updating Actual Minutes on CIMI_RWM_00987917_01	RC5742
Updating Actual Minutes on CIMI_RWM_00987923_01	VC6131
All Wire/Work Jobs have Completed, Package now in Complete status.	JS2145
Updating Actual Minutes on CIMI_RWM_00987929_01	MM3647
Updating Actual Minutes on CIMI_RWM_00987931_01	VC6131
Updating Actual Minutes on CIMI_RWM_00987933_01	RC5742
All Wire/Work Jobs have Completed, Package now in Complete status.	SM4953
Updating Actual Minutes on CIMI_RWM_00987935_01	JM1295
Updating Actual Minutes on CIMI_RWM_00987937_01	VC6131
Updating Actual Minutes on CIMI_RWM_00987946_01	QB6851

Updating Actual Minutes on CIMI_RWM_00987948_01	JS2145
Updating Actual Minutes on CIMI_RWM_00987950_01	JS2145
Updating Actual Minutes on CIMI_RWM_00987952_01	JM1295
Updating Actual Minutes on CIMI_RWM_00987953_01	JM1295
Updating Actual Minutes on CIMI_RWM_00987956_01	DM820T
Updating Actual Minutes on CIMI_RWM_00987957_01	JM1295
Updating Actual Minutes on CIMI_RWM_00987959_01	JM1295
Updating Actual Minutes on CIMI_RWM_00987964_01	PC9347
Updating Actual Minutes on CIMI_RWM_00987965_01	PC9347
Updating Actual Minutes on CIMI_RWM_00987967_01	PC9347
All Wire/Work Jobs have Completed, Package now in Complete status.	BK2151
Updating Actual Minutes on CIMI_RWM_00987974_01	VC6131
Updating Actual Minutes on CIMI_RWM_00987977_01	VC6131
All Wire/Work Jobs have Completed, Package now in Complete status.	BK2151
Updating Actual Minutes on CIMI_RWM_00987979_01	VC6131
Updating Actual Minutes on CIMI_RWM_00987990_01	ML1973
Updating Actual Minutes on CIMI_RWM_00987997_01	VC6131
Updating Actual Minutes on CIMI_RWM_00988004_01	VC6131
All Wire/Work Jobs have Completed, Package now in Complete status.	WW1427
Updating Actual Minutes on CIMI_RWM_00988012_01	JO1454
Updating Actual Minutes on CIMI_RWM_00988013_01	JO1454
Updating Actual Minutes on CIMI_RWM_00988014_01	DM820T
Updating Actual Minutes on CIMI_RWM_00988017_01	DM820T
Updating Actual Minutes on CIMI_RWM_00988018_01	DM820T
Updating Actual Minutes on CIMI_RWM_00988019_01	RW5286
Updating Actual Minutes on CIMI_RWM_00988020_01	JS2145
Updating Actual Minutes on CIMI_RWM_00988021_01	WE5739
Updating Actual Minutes on CIMI_RWM_00988038_01	VC6131
Updating Actual Minutes on CIMI_RWM_00988039_01	MM3647
Updating Actual Minutes on CIMI_RWM_00988040_01	MM3647
Updating Actual Minutes on CIMI_RWM_00988042_01	MM3647
Updating Actual Minutes on CIMI_RWM_00988047_01	MM3647
Updating Actual Minutes on CIMI_RWM_00988049_01	PC9347
Updating Actual Minutes on CIMI_RWM_00988051_01	PC9347
Updating Actual Minutes on CIMI_RWM_00988052_01	MD4156
Updating Actual Minutes on CIMI_RWM_00988053_01	RW5286
Updating Actual Minutes on CIMI_RWM_00988054_01	RW5286
Updating Actual Minutes on CIMI_RWM_00988055_01	WE5739
Updating Actual Minutes on CIMI_RWM_00988058_01	MD2797
Updating Actual Minutes on CIMI_RWM_00988059_01	JS2145
Updating Actual Minutes on CIMI_RWM_00988061_01	JS2145
Updating Actual Minutes on CIMI_RWM_00988063_01	VC6131
Updating Actual Minutes on CIMI_RWM_00988070_01	JM1295
Updating Actual Minutes on CIMI_RWM_00988073_01	PC9347

Updating Actual Minutes on CIMI_RWM_00988077_01	MM3647
Updating Actual Minutes on CIMI_RWM_00988078_01	MM3647
Updating Actual Minutes on CIMI_RWM_00988081_01	VC6131
Updating Actual Minutes on CIMI_RWM_00988085_01	PC9347
Updating Actual Minutes on CIMI_RWM_00988087_01	VC6131
Updating Actual Minutes on CIMI_RWM_00988088_01	RW5286
Updating Actual Minutes on CIMI_RWM_00988090_01	JM1295
Updating Actual Minutes on CIMI_RWM_00988091_01	VC6131
Updating Actual Minutes on CIMI_RWM_00988092_01	VC6131
Updating Actual Minutes on CIMI_RWM_00988125_01	MD4156
Updating Actual Minutes on CIMI_RWM_00988128_01	LP848K
All Wire/Work Jobs have Completed, Package now in Complete status.	JO1454
Updating Actual Minutes on CIMI_RWM_00988138_01	QB6851
Updating Actual Minutes on CIMI_RWM_00988140_01	CG4741
Updating Actual Minutes on CIMI_RWM_00988141_01	AG2675
Updating Actual Minutes on CIMI_RWM_00988142_01	MD4156
Updating Actual Minutes on CIMI_RWM_00988149_01	GG8932
Updating Actual Minutes on CIMI_RWM_00988154_01	PC9347
Updating Actual Minutes on CIMI_RWM_00988156_01	VC6131
Updating Actual Minutes on CIMI_RWM_00988161_01	QB6851
Updating Actual Minutes on CIMI_RWM_00988164_01	GG8932
Updating Actual Minutes on CIMI_RWM_00988177_01	PC9347
Updating Actual Minutes on CIMI_RWM_00988183_01	QB6851
Updating Actual Minutes on CIMI_RWM_00988184_01	CG4741
Updating Actual Minutes on CIMI_RWM_00988187_01	AG2675
Updating Actual Minutes on CIMI_RWM_00988192_01	QB6851
Updating Actual Minutes on CIMI_RWM_00988199_01	QB6851
Updating Actual Minutes on CIMI_RWM_00988203_01	CG4741
Updating Actual Minutes on CIMI_RWM_00988204_01	GG8932
Updating Actual Minutes on CIMI_RWM_00988207_01	QB6851
Updating Actual Minutes on CIMI_RWM_00988208_01	MM3647
Updating Actual Minutes on CIMI_RWM_00988218_01	JM1295
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
Updating Actual Minutes on CIMI_RWM_00997623_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997629_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997634_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997640_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997642_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997645_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997647_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997648_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997649_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997650_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997652_01	SF8537

Updating Actual Minutes on CIMI_RWM_00997653_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997655_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997663_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997665_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997668_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997669_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997672_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997675_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997684_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997685_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997688_01	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
Updating Actual Minutes on CIMI_RWM_00997694_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997696_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997733_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997747_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997748_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997768_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997769_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997770_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997772_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997774_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997777_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997779_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997796_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997798_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997799_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997800_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997801_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997802_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997803_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997804_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997805_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997807_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997808_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997809_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997813_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997816_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997817_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997819_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997821_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997823_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997824_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997825_01	SF8537

Updating Actual Minutes on CIMI_RWM_00997827_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997828_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997879_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997883_01	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
Updating Actual Minutes on CIMI_RWM_00997890_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997917_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997920_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997921_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997922_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997927_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997928_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997930_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997933_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997958_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997965_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997966_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997967_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997968_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997969_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997970_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997971_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997975_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997980_01	SF8537
Updating Actual Minutes on CIMI_RWM_00997985_01	SF8537
Updating Actual Minutes on CIMI_RWM_00998010_01	SF8537
Updating Actual Minutes on CIMI_RWM_00998019_01	SF8537
Updating Actual Minutes on CIMI_RWM_00998020_01	SF8537
Updating Actual Minutes on CIMI_RWM_00998021_01	SF8537
Updating Actual Minutes on CIMI_RWM_00998022_01	SF8537
Updating Actual Minutes on CIMI_RWM_00998024_01	SF8537
Updating Actual Minutes on CIMI_RWM_00998025_01	SF8537
Updating Actual Minutes on CIMI_RWM_00998027_01	SF8537
Updating Actual Minutes on CIMI_RWM_00998028_01	SF8537
Updating Actual Minutes on CIMI_RWM_00998029_01	SF8537
Updating Actual Minutes on CIMI_RWM_00998043_01	SF8537
Updating Actual Minutes on CIMI_RWM_00998044_01	SF8537
Updating Actual Minutes on CIMI_RWM_00998045_01	SF8537
Updating Actual Minutes on CIMI_RWM_00998046_01	SF8537
Updating Actual Minutes on CIMI_RWM_00998047_01	SF8537
Updating Actual Minutes on CIMI_RWM_00998048_01	SF8537
Updating Actual Minutes on CIMI_RWM_00998049_01	SF8537
Updating Actual Minutes on CIMI_RWM_00998050_01	SF8537
Updating Actual Minutes on CIMI_RWM_00998053_01	SF8537

Updating Actual Minutes on CIMI_RWM_00998054_01	SF8537
Updating Actual Minutes on CIMI_RWM_00998078_01	SF8537
Updating Actual Minutes on CIMI_RWM_00998079_01	SF8537
Updating Actual Minutes on CIMI_RWM_00998080_01	SF8537
Updating Actual Minutes on CIMI_RWM_00998085_01	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
Updating Actual Minutes on CIMI_RWM_00998113_01	SF8537
Updating Actual Minutes on CIMI_RWM_00998114_01	SF8537
Updating Actual Minutes on CIMI_RWM_00998120_01	SF8537
Updating Actual Minutes on CIMI_RWM_00998121_01	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
Updating Actual Minutes on CIMI_RWM_00998176_01	SF8537
Updating Actual Minutes on CIMI_RWM_00998178_01	SF8537
Updating Actual Minutes on CIMI_RWM_00998241_01	SF8537
Updating Actual Minutes on CIMI_RWM_00998243_01	SF8537
Updating Actual Minutes on CIMI_RWM_00998244_01	SF8537
Updating Actual Minutes on CIMI_RWM_00998248_01	SF8537
Updating Actual Minutes on CIMI_RWM_00998250_01	SF8537
Updating Actual Minutes on CIMI_RWM_00998251_01	SF8537
Updating Actual Minutes on CIMI_RWM_00998252_01	SF8537
Updating Actual Minutes on CIMI_RWM_00998254_01	SF8537
Updating Actual Minutes on CIMI_RWM_00998255_01	SF8537
Updating Actual Minutes on CIMI_RWM_00998257_01	SF8537
Updating Actual Minutes on CIMI_RWM_01002219_01	SF8537
Updating Actual Minutes on CIMI_RWM_01002229_01	SF8537
Updating Actual Minutes on CIMI_RWM_01002247_01	SF8537
Updating Actual Minutes on CIMI_RWM_01002257_01	CD5628
Updating Actual Minutes on CIMI_RWM_01002258_01	JH3145
Updating Actual Minutes on CIMI_RWM_01002264_01	CD5628
Updating Actual Minutes on CIMI_RWM_01002265_01	JH3145
Updating Actual Minutes on CIMI_RWM_01002268_01	CD5628
Updating Actual Minutes on CIMI_RWM_01002269_01	JH3145
Updating Actual Minutes on CIMI_RWM_01002279_01	SF8537
Updating Actual Minutes on CIMI_RWM_01002287_01	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537

Updating Actual Minutes on CIMI_CMK168S0126C01

04/07/22 Hazard cleared per RA9619

Updating Actual Minutes on CIMI_CSD488C0127C01

04/07/22 Hazard cleared per RA9619

Updating Actual Minutes on CIMI_CDJ96230120C01

Updating Actual Minutes on CIMI_CBG36140212C01

All Wire/Work Jobs have Completed, Package now in Complete status.	DL4872
All Wire/Work Jobs have Completed, Package now in Complete status.	JM1827

Package Manually Completed by te7361.

All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537

Updating Actual Minutes on CIMI_CRC13430212C01

All Wire/Work Jobs have Completed, Package now in Complete status.	JS2145

Updating Actual Minutes on CIMI_CIR28670212C01

All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537

Updating Actual Minutes on CIMI_RWM_01048485_01 RW5286

All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537

Updating Actual Minutes on CIMI_CAC23710127C01

All Wire/Work Jobs have Completed, Package now in Complete status.	JS6852
All Wire/Work Jobs have Completed, Package now in Complete status.	QB6851

Package Manually Completed by te7361.

All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537

Package Manually Completed by te7361.

Updating Actual Minutes on CIMI_CRC13430418C01

All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537

Package Manually Completed by sr5695.

All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	GG8932
All Wire/Work Jobs have Completed, Package now in Complete status.	JS3172
All Wire/Work Jobs have Completed, Package now in Complete status.	GG8932
All Wire/Work Jobs have Completed, Package now in Complete status.	GG8932

Updating Actual Minutes on CIMI_RWM_01116057_01 SC2675

All Wire/Work Jobs have Completed, Package now in Complete status.	VC6131
All Wire/Work Jobs have Completed, Package now in Complete status.	PC9347
All Wire/Work Jobs have Completed, Package now in Complete status.	PC9347
All Wire/Work Jobs have Completed, Package now in Complete status.	PC9347
All Wire/Work Jobs have Completed, Package now in Complete status.	VC6131

All Wire/Work Jobs have Completed, Package now in Complete status.	AG2675
All Wire/Work Jobs have Completed, Package now in Complete status.	PC9347
All Wire/Work Jobs have Completed, Package now in Complete status.	CG4741
All Wire/Work Jobs have Completed, Package now in Complete status.	CG4741
All Wire/Work Jobs have Completed, Package now in Complete status.	GG8932
All Wire/Work Jobs have Completed, Package now in Complete status.	MO1513
All Wire/Work Jobs have Completed, Package now in Complete status.	JM1295
All Wire/Work Jobs have Completed, Package now in Complete status.	JM1295
All Wire/Work Jobs have Completed, Package now in Complete status.	PC9347
All Wire/Work Jobs have Completed, Package now in Complete status.	GG8932
All Wire/Work Jobs have Completed, Package now in Complete status.	GG8932
All Wire/Work Jobs have Completed, Package now in Complete status.	JS2145
All Wire/Work Jobs have Completed, Package now in Complete status.	MD4156
All Wire/Work Jobs have Completed, Package now in Complete status.	SB6349
All Wire/Work Jobs have Completed, Package now in Complete status.	OD4318
All Wire/Work Jobs have Completed, Package now in Complete status.	CG4741
All Wire/Work Jobs have Completed, Package now in Complete status.	QB6851
All Wire/Work Jobs have Completed, Package now in Complete status.	DM820T
All Wire/Work Jobs have Completed, Package now in Complete status.	MD4156
All Wire/Work Jobs have Completed, Package now in Complete status.	VC6131
All Wire/Work Jobs have Completed, Package now in Complete status.	VC6131
All Wire/Work Jobs have Completed, Package now in Complete status.	MD4156
All Wire/Work Jobs have Completed, Package now in Complete status.	RW5286
All Wire/Work Jobs have Completed, Package now in Complete status.	MO1513
All Wire/Work Jobs have Completed, Package now in Complete status.	LP848K
All Wire/Work Jobs have Completed, Package now in Complete status.	JM1295
All Wire/Work Jobs have Completed, Package now in Complete status.	CG4741
All Wire/Work Jobs have Completed, Package now in Complete status.	MD4156
All Wire/Work Jobs have Completed, Package now in Complete status.	RW5286
All Wire/Work Jobs have Completed, Package now in Complete status.	GG8932
All Wire/Work Jobs have Completed, Package now in Complete status.	MM3647
All Wire/Work Jobs have Completed, Package now in Complete status.	GG8932
All Wire/Work Jobs have Completed, Package now in Complete status.	GG8932
All Wire/Work Jobs have Completed, Package now in Complete status.	MM3647
All Wire/Work Jobs have Completed, Package now in Complete status.	JM2792
All Wire/Work Jobs have Completed, Package now in Complete status.	MM3647
All Wire/Work Jobs have Completed, Package now in Complete status.	GG8932
All Wire/Work Jobs have Completed, Package now in Complete status.	JM1295
All Wire/Work Jobs have Completed, Package now in Complete status.	JM2792
All Wire/Work Jobs have Completed, Package now in Complete status.	GG8932
All Wire/Work Jobs have Completed, Package now in Complete status.	JM1295
All Wire/Work Jobs have Completed, Package now in Complete status.	MM3647
All Wire/Work Jobs have Completed, Package now in Complete status.	MD4156
All Wire/Work Jobs have Completed, Package now in Complete status.	VC6131

All Wire/Work Jobs have Completed, Package now in Complete status.	PC9347
All Wire/Work Jobs have Completed, Package now in Complete status.	AG2675
Design Record Updated by jt379t.	
Package Manually Completed by hl1436.	
781 CREATED FOR REPORTED ISSUE ON THIS RWM PACKAGE, PHOTOS INCLUDED IN BPC.	
Updating Actual Minutes on CIMI_RWM_01116839_01	RW5286
All Wire/Work Jobs have Completed, Package now in Complete status.	PC9347
All Wire/Work Jobs have Completed, Package now in Complete status.	PC9347
All Wire/Work Jobs have Completed, Package now in Complete status.	GG8932
User ra9619 added to Notifications for this package.	
Updating Actual Minutes on CIMI_RWM_01131136_01	PG6512
Updating Actual Minutes on CIMI_RWM_01131157_01	JH3145
Updating Actual Minutes on CIMI_RWM_01131170_01	DD6738
Updating Actual Minutes on CIMI_RWM_01131173_01	DD6738
Updating Actual Minutes on CIMI_RWM_01131176_01	DD6738
Updating Actual Minutes on CIMI_RWM_01131183_01	PG6512
Updating Actual Minutes on CIMI_RWM_01131245_01	PG6512
Updating Actual Minutes on CIMI_RWM_01131248_01	PG6512
Updating Actual Minutes on CIMI_RWM_01131251_01	PG6512
Updating Actual Minutes on CIMI_RWM_01131268_01	JH3145
Updating Actual Minutes on CIMI_RWM_01131282_01	PG6512
Updating Actual Minutes on CIMI_RWM_01131330_01	DD6738
Updating Actual Minutes on CIMI_RWM_01131358_01	DD6738
Updating Actual Minutes on CIMI_RWM_01131359_01	DD6738
Updating Actual Minutes on CIMI_RWM_01131375_01	DD6738
Updating Actual Minutes on CIMI_RWM_01131396_01	DD6738
Updating Actual Minutes on CIMI_RWM_01131398_01	DD6738
Updating Actual Minutes on CIMI_RWM_01131415_01	JH3145
Updating Actual Minutes on CIMI_RWM_01131417_01	JH3145
All Wire/Work Jobs have Completed, Package now in Complete status.	DD6738
Updating Actual Minutes on CIMI_RWM_01131422_01	JH3145
Updating Actual Minutes on CIMI_RWM_01131723_01	SF8537
Updating Actual Minutes on CIMI_RWM_01131724_01	TM3217
Updating Actual Minutes on CIMI_RWM_01131730_01	SF8537
Updating Actual Minutes on CIMI_RWM_01131731_01	SF8537
Updating Actual Minutes on CIMI_RWM_01131733_01	DD043U
Updating Actual Minutes on CIMI_RWM_01131748_01	SF8537
Updating Actual Minutes on CIMI_RWM_01131754_01	SF8537
Updating Actual Minutes on CIMI_RWM_01131768_01	SF8537
Updating Actual Minutes on CIMI_RWM_01131769_01	SF8537
Updating Actual Minutes on CIMI_RWM_01131771_01	SF8537
Updating Actual Minutes on CIMI_RWM_01139638_01	DB8381
Updating Actual Minutes on CIMI_RWM_01139677_01	DB8381
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537

10/25/22 Cleared per RA9619	
Updating Actual Minutes on CIMI_RWM_01175821_01	SF8537
Updating Actual Minutes on CIMI_RWM_01184083_01	SF8537
Updating Actual Minutes on CIMI_RWM_01185700_01	SF8537
Updating Actual Minutes on CIMI_RWM_01192981_01	SF8537
Updating Actual Minutes on CIMI_RWM_01198039_01	SC2675
Updating Actual Minutes on CIMI_RWM_01198053_01	SC2675
Updating Actual Minutes on CIMI_RWM_01198063_01	SC2675
Updating Actual Minutes on CIMI_RWM_01198086_01	SC2675
Hazard cleared per Sup RA9619	
Package Manually Completed by te7361.	
Updating Actual Minutes on CIMI_RWM_01230505_01	CN2921
Updating Actual Minutes on CIMI_RWM_01230506_01	CN2921
Updating Actual Minutes on CIMI_RWM_01230507_01	CN2921
Updating Actual Minutes on CIMI_RWM_01312497_01	DM820T
Updating Actual Minutes on CIMI_RWM_01338077_01	SC2675
Updating Actual Minutes on CIMI_RWM_01339076_01	JS3172
Updating Actual Minutes on CIMI_RWM_01339112_01	SC2675
Updating Actual Minutes on CIMI_RWM_01340357_01	SC2675
Updating Actual Minutes on CIMI_RWM_01340358_01	SC2675
Updating Actual Minutes on CIMI_RWM_01340887_01	SC2675
Updating Actual Minutes on CIMI_RWM_01340888_01	SC2675
Updating Actual Minutes on CIMI_RWM_01341214_01	SC2675
Updating Actual Minutes on CIMI_RWM_01346767_01	SF8537
Updating Actual Minutes on CIMI_RWM_01350849_01	DB8381
HAZARD RESOLVED BY TECH WO8419 ON 11/03/2023. THANK YOU	
Updating Actual Minutes on CIMI_CWO84191019C01	
HAZARD RESOLVED BY TECH WO8419 ON 11/03/2023. THANK YOU	
Updating Actual Minutes on CIMI_RWM_01352329_01	VC6131
HAZARD RESOLVED BY TECH DS2341 ON 11/07/2023. THANK YOU	
Package Manually Completed by ds5682.	
HAZARD RESOLVED BY TECH WO8419 ON 11/03/2023. THANK YOU	
Updating Actual Minutes on CIMI_CSC89521102C01	
Updating Actual Minutes on CIMI_RWM_01353660_01	VC6131
HAZARD RESOLVED BY TECH MK168S ON 11/08/2023. THANK YOU	
Updating Actual Minutes on CIMI_RWM_01355535_01	MM3647
Package Manually Completed by sm5367.	
HAZARD RESOLVED BY TECH MK168S ON 11/08/2023. THANK YOU	
Package Manually Completed by ds5682.	
Updating Actual Minutes on CIMI_RWM_01356845_01	MM3647
Updating Actual Minutes on CIMI_RWM_01360976_01	QB6851
Updating Actual Minutes on CIMI_RWM_01361290_01	DM820T
Updating Actual Minutes on CIMI_RWM_01375653_01	RW5286
Updating Actual Minutes on CIMI_RWM_01375656_01	QB6851

Updating Actual Minutes on CIMI_RWM_01375659_01	SC2675
Updating Actual Minutes on CIMI_RWM_01375665_01	SC2675
Updating Actual Minutes on CIMI_RWM_01375681_01	QB6851
Updating Actual Minutes on CIMI_RWM_01375686_01	RW5286
Updating Actual Minutes on CIMI_RWM_01376323_01	RW5286
Updating Actual Minutes on CIMI_RWM_01376329_01	LP848K
Updating Actual Minutes on CIMI_RWM_01376338_01	MM3647
Updating Actual Minutes on CIMI_RWM_01378363_01	MM3647
Updating Actual Minutes on CIMI_RWM_01378992_01	WC8687

Completed 3/29 per manager

Completed 3/29

Package Manually Completed by km1231.

Package Manually Completed by km1231.

.9, THIS HAZARD WAS RESOLVED BY THE AUBURN LINE CREW ON 04/08/2024. THANK YOU

Package Manually Completed by ds5682.

Package Manually Completed by ds5682.

Package Manually Completed by ds5682.

Updating Actual Minutes on CIMI_RWM_01455732_01	SC2675

Package Manually Completed by ds5682.

Package Manually Completed by ds5682.

Package Manually Completed by ds5682.

Package Manually Completed by ds5682.

Package Manually Completed by ds5682.

Package Manually Completed by ds5682.

Package Manually Completed by jg856r.

ır this area. rp2967.

PACKAGE_ID	STATE	GEO	WC_ID	CLLI	WC_NAME
444913	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
445392	CA	NVN_CA_SACR_QUINCY_A	530506	SRVLCA11	SIERRAVILLE
457898	CA	NVN_CA_SACR_GRASS_VALLEY_A	530535	GRVYCA12	LAKE WILDWOOD
458532	CA	NVN_CA_SACR_QUINCY_A	530433	BLRSCA12	BLAIRSDEN
460382	CA	NVN_CA_SACR_QUINCY_A	530433	BLRSCA12	BLAIRSDEN
460383	CA	NVN_CA_SACR_QUINCY_A	530433	BLRSCA12	BLAIRSDEN
460630	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
466814	CA	NVN_CA_SACR_QUINCY_A	530433	BLRSCA12	BLAIRSDEN
466815	CA	NVN_CA_SACR_QUINCY_A	530433	BLRSCA12	BLAIRSDEN
468903	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
471377	CA	NVN_CA_SACR_QUINCY_A	530433	BLRSCA12	BLAIRSDEN
471380	CA	NVN_CA_SACR_QUINCY_A	530433	BLRSCA12	BLAIRSDEN
471382	CA	NVN_CA_SACR_QUINCY_A	530471	LLTNCA11	LOYALTON
471383	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
474187	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
474190	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
474554	CA	NVN_CA_SACR_QUINCY_A	530506	SRVLCA11	SIERRAVILLE
474583	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
476379	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
487109	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
487113	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
487116	CA	NVN_CA_SACR_QUINCY_A	530433	BLRSCA12	BLAIRSDEN
488533	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
488611	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
488622	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
489921	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
493116	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY

495041	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
496997	CA	NVN_CA_SACR_QUINCY_A	530433	BLRSCA12	BLAIRSDEN
497105	CA	NVN_CA_SACR_QUINCY_A	530433	BLRSCA12	BLAIRSDEN
497121	CA	NVN_CA_SACR_QUINCY_A	530433	BLRSCA12	BLAIRSDEN
503131	CA	NVN_CA_SACR_QUINCY_A	530433	BLRSCA12	BLAIRSDEN
503157	CA	NVN_CA_SACR_QUINCY_A	530433	BLRSCA12	BLAIRSDEN
503200	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
503221	CA	NVN_CA_SACR_QUINCY_A	530433	BLRSCA12	BLAIRSDEN
504519	CA	NVN_CA_SACR_GRASS_VALLEY_A	530459	GRVYCA01	GRASS VALLEY
507543	CA	NVN_CA_SACR_QUINCY_A	530433	BLRSCA12	BLAIRSDEN
507581	CA	NVN_CA_SACR_QUINCY_A	530433	BLRSCA12	BLAIRSDEN
507646	CA	NVN_CA_SACR_QUINCY_A	530433	BLRSCA12	BLAIRSDEN
507659	CA	NVN_CA_SACR_QUINCY_A	530433	BLRSCA12	BLAIRSDEN
507720	CA	NVN_CA_SACR_QUINCY_A	530433	BLRSCA12	BLAIRSDEN
507763	CA	NVN_CA_SACR_QUINCY_A	530433	BLRSCA12	BLAIRSDEN
510338	CA	NVN_CA_SACR_QUINCY_A	530433	BLRSCA12	BLAIRSDEN
510339	CA	NVN_CA_SACR_QUINCY_A	530433	BLRSCA12	BLAIRSDEN
524658	CA	NVN_CA_SACR_GRASS_VALLEY_A	530459	GRVYCA01	GRASS VALLEY
526873	CA	NVN_CA_SACR_GRASS_VALLEY_A	530459	GRVYCA01	GRASS VALLEY
532316	CA	NVN_CA_SACR_GRASS_VALLEY_A	530475	NVCYCA11	NEVADA CITY
532574	CA	NVN_CA_SACR_GRASS_VALLEY_A	530475	NVCYCA11	NEVADA CITY
542803	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
542804	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
544068	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
544070	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
549432	CA	NVN_CA_SACR_GRASS_VALLEY_A	530459	GRVYCA01	GRASS VALLEY
565667	CA	NVN_CA_CHCO_CHALLENGE_MWF_A	530437	CHLNCA11	CHALLENGE
568593	CA	NVN_CA_CHCO_CHALLENGE_MWF_A	530437	CHLNCA11	CHALLENGE
572382	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
596050	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
599486	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
612685	CA	NVN_CA_SACR_GRASS_VALLEY_A	530459	GRVYCA01	GRASS VALLEY
615756	CA	NVN_CA_SACR_QUINCY_A	530506	SRVLCA11	SIERRAVILLE
615758	CA	NVN_CA_SACR_QUINCY_A	530506	SRVLCA11	SIERRAVILLE
621860	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
621861	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
622401	CA	NVN_CA_CHCO_CHALLENGE_MWF_A	530437	CHLNCA11	CHALLENGE

622402	CA	NVN_CA_CHCO_CHALLENGE_MWF_A	530437	CHLNCA11	CHALLENGE
649504	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
652182	CA	NVN_CA_SACR_QUINCY_A	530492	PTOLCA01	PORTOLA
652183	CA	NVN_CA_SACR_QUINCY_A	530492	PTOLCA01	PORTOLA
669804	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
670205	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
670206	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
671531	CA	NVN_CA_SACR_GRASS_VALLEY_A	530459	GRVYCA01	GRASS VALLEY
675755	CA	NVN_CA_SACR_QUINCY_A	530433	BLRSCA12	BLAIRSDEN
677607	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
678522	CA	NVN_CA_SACR_QUINCY_A	530433	BLRSCA12	BLAIRSDEN
679210	CA	NVN_CA_SACR_N_TAHOE_A	530515	TRUCCA11	TRUCKEE
681583	CA	NVN_CA_SACR_QUINCY_A	530492	PTOLCA01	PORTOLA
682928	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
687638	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
687641	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
687642	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
687643	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
687645	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
696852	CA	NVN_CA_SACR_QUINCY_A	530492	PTOLCA01	PORTOLA
703688	CA	NVN_CA_SACR_GRASS_VALLEY_A	530475	NVCYCA11	NEVADA CITY
707173	CA	NVN_CA_SACR_N_TAHOE_A	530515	TRUCCA11	TRUCKEE
707192	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
707743	CA	NVN_CA_SACR_QUINCY_A	530433	BLRSCA12	BLAIRSDEN
707768	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
707769	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
707871	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
707872	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
707876	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
709843	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
710388	CA	NVN_CA_SACR_N_TAHOE_A	530515	TRUCCA11	TRUCKEE
710389	CA	NVN_CA_SACR_N_TAHOE_A	530515	TRUCCA11	TRUCKEE

711319	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
712531	CA	NVN_CA_SACR_QUINCY_A	530492	PTOLCA01	PORTOLA
713055	CA	NVN_CA_SACR_N_TAHOE_A	530515	TRUCCA11	TRUCKEE
713083	CA	NVN_CA_SACR_N_TAHOE_A	530515	TRUCCA11	TRUCKEE
717739	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
717740	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
730525	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
730767	CA	NVN_CA_SACR_GRASS_VALLEY_A	530459	GRVYCA01	GRASS VALLEY
737018	CA	NVN_CA_SACR_GRASS_VALLEY_A	530475	NVCYCA11	NEVADA CITY
737095	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
739634	CA	NVN_CA_SACR_QUINCY_A	530492	PTOLCA01	PORTOLA
752854	CA	NVN_CA_SACR_GRASS_VLY_MWF_A	530480	NSJNCA11	NORTH SAN JUAN
762233	CA	NVN_CA_SACR_GRASS_VLY_MWF_A	530436	CMPVCA11	CAMPTONVILLE
764445	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
804650	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
804651	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
805982	CA	NVN_CA_SACR_GRASS_VLY_MWF_A	530436	CMPVCA11	CAMPTONVILLE
809628	CA	NVN_CA_SACR_QUINCY_A	530471	LLTNCA11	LOYALTON
819074	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
830252	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
834244	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
838874	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
847587	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
850971	CA	NVN_CA_CHCO_CHALLENGE_MWF_A	530437	CHLNCA11	CHALLENGE
852438	CA	NVN_CA_SACR_QUINCY_A	530471	LLTNCA11	LOYALTON
853916	CA	NVN_CA_SACR_QUINCY_A	530506	SRVLCA11	SIERRAVILLE
853917	CA	NVN_CA_SACR_QUINCY_A	530506	SRVLCA11	SIERRAVILLE
855971	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
857123	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
859272	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
859475	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
869466	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
869467	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY

870804	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
896499	CA	NVN_CA_SACR_QUINCY_A	530433	BLRSCA12	BLAIRSDEN
910392	CA	NVN_CA_SACR_QUINCY_A	530433	BLRSCA12	BLAIRSDEN
914295	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
916266	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
916733	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
916734	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
916735	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
916736	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
916737	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
916738	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
917557	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
919302	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
919356	CA	NVN_CA_SACR_QUINCY_A	530471	LLTNCA11	LOYALTON
921003	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
921210	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
922584	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
923965	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
923966	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
926227	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
938821	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
938822	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
940068	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
940069	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
961751	CA	NVN_CA_SACR_N_TAHOE_A	530515	TRUCCA11	TRUCKEE
966228	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
989587	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
1025907	CA	NVN_CA_SACR_N_TAHOE_A	530515	TRUCCA11	TRUCKEE
1032652	CA	NVN_CA_SACR_GRASS_VALLEY_A	530459	GRVYCA01	GRASS VALLEY
1040875	CA	NVN_CA_SACR_GRASS_VALLEY_A	530459	GRVYCA01	GRASS VALLEY
1041635	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
1043720	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY

1048290	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
1048325	CA	NVN_CA_SACR_QUINCY_A	530471	LLTNCA11	LOYALTON
1060619	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
1073525	CA	NVN_CA_SACR_N_TAHOE_A	530515	TRUCCA11	TRUCKEE
1073618	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
1073957	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
1075019	CA	NVN_CA_SACR_QUINCY_A	530471	LLTNCA11	LOYALTON
1097827	CA	NVN_CA_SACR_GRASS_VALLEY_A	530459	GRVYCA01	GRASS VALLEY
1144889	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
1145380	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
1163765	CA	NVN_CA_SACR_QUINCY_A	530471	LLTNCA11	LOYALTON
1163770	CA	NVN_CA_SACR_QUINCY_A	530492	PTOLCA01	PORTOLA
1176976	CA	NVN_CA_SACR_GRASS_VLY_MWF_A	530436	CMPVCA11	CAMPTONVILLE
1177417	CA	NVN_CA_SACR_GRASS_VLY_MWF_A	530436	CMPVCA11	CAMPTONVILLE
1191857	CA	NVN_CA_SACR_GRASS_VLY_MWF_A	530480	NSJNCA11	NORTH SAN JUAN
1213445	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
1221602	CA	NVN_CA_SACR_QUINCY_A	530492	PTOLCA01	PORTOLA
1249473	CA	NVN_CA_SACR_QUINCY_A	530433	BLRSCA12	BLAIRSDEN
1249501	CA	NVN_CA_SACR_QUINCY_A	530433	BLRSCA12	BLAIRSDEN
1250198	CA	NVN_CA_SACR_QUINCY_A	530433	BLRSCA12	BLAIRSDEN
1255715	CA	NVN_CA_SACR_QUINCY_A	530471	LLTNCA11	LOYALTON
1260360	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
1260409	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
1263927	CA	NVN_CA_SACR_GRASS_VALLEY_A	530475	NVCYCA11	NEVADA CITY
1264288	CA	NVN_CA_SACR_QUINCY_A	530492	PTOLCA01	PORTOLA
1268274	CA	NVN_CA_SACR_GRASS_VLY_MWF_A	530480	NSJNCA11	NORTH SAN JUAN
1275152	CA	NVN_CA_SACR_QUINCY_A	530433	BLRSCA12	BLAIRSDEN
1278824	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
1278829	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
1278833	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
1283787	CA	NVN_CA_SACR_QUINCY_A	530471	LLTNCA11	LOYALTON
1288967	CA	NVN_CA_CHCO_CHALLENGE_MWF_A	530437	CHLNCA11	CHALLENGE
1292404	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
1292405	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
1292408	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
1310923	CA	NVN_CA_SACR_QUINCY_A	530506	SRVLCA11	SIERRAVILLE
1317255	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY

1335365	CA	NVN_CA_CHCO_CHALLENGE_MWF_A	530437	CHLNCA11	CHALLENGE
1356919	CA	NVN_CA_SACR_QUINCY_A	530492	PTOLCA01	PORTOLA
1360775	CA	NVN_CA_CHCO_CHALLENGE_MWF_A	530437	CHLNCA11	CHALLENGE
1366644	CA	NVN_CA_CHCO_CHALLENGE_MWF_A	530437	CHLNCA11	CHALLENGE
1367429	CA	NVN_CA_SACR_N_TAHOE_A	530515	TRUCCA11	TRUCKEE
1369243	CA	NVN_CA_CHCO_CHALLENGE_MWF_A	530437	CHLNCA11	CHALLENGE
1369245	CA	NVN_CA_CHCO_CHALLENGE_MWF_A	530437	CHLNCA11	CHALLENGE
1370861	CA	NVN_CA_CHCO_CHALLENGE_MWF_A	530437	CHLNCA11	CHALLENGE
1393280	CA	NVN_CA_CHCO_CHALLENGE_MWF_A	530437	CHLNCA11	CHALLENGE
1452072	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
1452074	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
1452075	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
1452076	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
1452077	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY
1471228	CA	NVN_CA_SACR_QUINCY_A	530433	BLRSCA12	BLAIRSDEN
1471266	CA	NVN_CA_SACR_QUINCY_A	530506	SRVLCA11	SIERRAVILLE
1488494	CA	NVN_CA_SACR_QUINCY_A	530433	BLRSCA12	BLAIRSDEN
1507311	CA	NVN_CA_SACR_QUINCY_A	530493	QNCYCA12	QUINCY

CREATE_DATE	DUE_DATE	CLOSED_DATE	CREATED_UUID	FORCE_TECH	PACKAGE_STATUS	BPC_OWNER
7/13/2019	7/12/2020	8/2/2019	MM9751	MM9751	Complete	TFS
7/17/2019	7/16/2020	8/6/2019	SF8537	SF8537	Complete	TFS
8/21/2019	8/20/2020	8/21/2019	RX2347		Complete	ENG
8/23/2019	8/22/2020	8/26/2019	SF8537	SF8537	Complete	TFS
8/29/2019	8/28/2020	9/4/2019	SF8537	SF8537	Complete	TFS
8/29/2019	8/28/2020	9/10/2019	SF8537	SF8537	Complete	TFS
8/30/2019	8/29/2020	9/11/2019	MM9751	MM9751	Complete	TFS
9/10/2019	9/9/2020	9/12/2019	SF8537	SF8537	Complete	TFS
9/10/2019	9/9/2020	9/11/2019	SF8537	SF8537	Complete	TFS
9/12/2019	9/11/2020	9/16/2019	MM9751	MM9751	Complete	TFS
9/19/2019	9/18/2020	10/3/2019	SF8537	SF8537	Complete	TFS
9/19/2019	9/18/2020	10/16/2019	SF8537	SF8537	Complete	TFS
9/19/2019	9/18/2020	1/9/2020	SF8537	SF8537	Complete	TFS
9/19/2019	9/18/2020	10/21/2019	SF8537	SF8537	Complete	TFS
9/24/2019	9/23/2020	10/9/2019	SF8537	MM9751	Complete	TFS
9/24/2019	9/23/2020	10/3/2019	MM9751	MM9751	Complete	TFS
9/26/2019	9/25/2020	10/15/2019	SF8537	SF8537	Complete	TFS
9/26/2019	9/25/2020	10/3/2019	MM9751	MM9751	Complete	TFS
10/1/2019	9/30/2020	12/5/2019	SF8537	JC4378	Complete	TFS
10/17/2019	10/16/2020	12/6/2019	SF8537	SF8537	Complete	TFS
10/17/2019	10/16/2020	12/5/2019	SF8537	SF8537	Complete	TFS
10/17/2019	10/16/2020	1/16/2020	SF8537	SF8537	Complete	TFS
10/19/2019	10/18/2020	10/23/2019	MM9751	JC4378	Complete	TFS
10/19/2019	10/18/2020	11/5/2019	MM9751	MM9751	Complete	TFS
10/19/2019	10/18/2020	12/3/2019	MM9751	MM9751	Complete	TFS
10/22/2019	10/21/2020	12/3/2019	SF8537	SF8537	Complete	TFS
10/26/2019	10/25/2020	10/28/2019	JC4378	JC4378	Complete	TFS

10/29/2019	10/28/2020	12/2/2019	JC4378	JC4378	Complete	TFS
11/1/2019	10/31/2020	11/6/2019	JC4378	JC4378	Complete	TFS
11/1/2019	10/31/2020	11/5/2019	JC4378	JC4378	Complete	TFS
11/1/2019	10/31/2020	11/1/2019	JC4378	MM9751	Complete	TFS
11/8/2019	11/7/2020	11/13/2019	JC4378	MM9751	Complete	TFS
11/8/2019	11/7/2020	11/14/2019	JC4378	JC4378	Complete	TFS
11/8/2019	11/7/2020	11/11/2019	MM9751	MM9751	Complete	TFS
11/8/2019	11/7/2020	11/8/2019	JC4378	JC4378	Complete	TFS
11/9/2019	11/8/2020	11/25/2019	RX2347	EK6957	Complete	TFS
11/14/2019	11/13/2020	12/23/2019	MM9751	JC4378	Complete	TFS
11/14/2019	11/13/2020	1/7/2020	JC4378	SF8537	Complete	TFS
11/14/2019	11/13/2020	12/9/2019	MM9751	JC4378	Complete	TFS
11/14/2019	11/13/2020	11/25/2019	JC4378	MM9751	Complete	TFS
11/14/2019	11/13/2020	12/2/2019	JC4378	JC4378	Complete	TFS
11/14/2019	11/13/2020	11/18/2019	MM9751	MM9751	Complete	TFS
11/19/2019	11/18/2020	11/26/2019	MM9751	JC4378	Complete	TFS
11/19/2019	11/18/2020	11/25/2019	MM9751	MM9751	Complete	TFS
12/11/2019	12/10/2020	1/7/2020	VC6131	MS7970	Complete	TFS
12/13/2019	12/12/2020	4/30/2020	VC6131	MP8321	Complete	TFS
12/19/2019	12/18/2020	1/24/2020	RX2347	RD3541	Complete	TFS
12/19/2019	12/18/2020	1/24/2020	RX2347	TV1972	Complete	TFS
1/8/2020	1/7/2021	1/27/2020	MM9751	MM9751	Complete	TFS
1/8/2020	1/7/2021	1/23/2020	MM9751	MM9751	Complete	TFS
1/11/2020	1/10/2021	1/27/2020	MM9751	MM9751	Complete	TFS
1/11/2020	1/10/2021	1/31/2020	MM9751	MM9751	Complete	TFS
1/23/2020	1/22/2021	1/25/2020	AB2847	FR1292	Complete	TFS
2/8/2020	2/7/2021	3/14/2020	AC1532	AC1532	Complete	TFS
2/13/2020	2/12/2021	2/18/2020	AC1532	AC1532	Complete	TFS
2/20/2020	2/19/2021	2/21/2020	SF8537	SF8537	Complete	TFS
4/1/2020	4/1/2021	4/23/2020	SF8537	SF8537	Complete	TFS
4/9/2020	4/9/2021	4/9/2020	SF8537	MM9751	Complete	TFS
4/16/2020	4/16/2021	9/7/2020	RX2347	CO1631	Complete	TFS
4/21/2020	4/21/2021	4/21/2020	MM9751	MM9751	Complete	TFS
4/21/2020	4/21/2021	4/21/2020	MM9751	MM9751	Complete	TFS
4/29/2020	4/29/2021	5/14/2020	SF8537	SF8537	Complete	TFS
4/29/2020	4/29/2021	7/9/2020	SF8537	SF8537	Complete	TFS
4/29/2020	4/29/2021	6/8/2020	AC1532	AC1532	Complete	TFS

4/29/2020	4/29/2021	6/16/2020	AC1532	AC1532	Complete	TFS
6/3/2020	6/3/2021	6/4/2020	MM9751	MM9751	Complete	TFS
6/10/2020	6/10/2021	6/10/2020	SF8537	SF8537	Complete	TFS
6/10/2020	6/10/2021	6/23/2020	SF8537	SF8537	Complete	TFS
7/15/2020	7/15/2021	7/21/2020	SF8537	SF8537	Complete	TFS
7/16/2020	7/16/2021	8/17/2020	MM9751	MM9751	Complete	TFS
7/16/2020	7/16/2021	8/20/2020	MM9751	MM9751	Complete	TFS
7/18/2020	7/18/2021	3/14/2021	MS7970	MS7970	Complete	TFS
7/22/2020	7/22/2021	7/28/2020	SF8537	SF8537	Complete	TFS
7/28/2020	7/28/2021	7/29/2020	MM9751	MM9751	Complete	TFS
7/30/2020	7/30/2021	9/14/2020	SF8537	SF8537	Complete	TFS
8/1/2020	8/1/2021	8/11/2020	MT3451	JH3145	Complete	TFS
8/7/2020	8/7/2021	8/7/2020	SF8537	SF8537	Complete	TFS
8/12/2020	8/12/2021	8/12/2020	MM9751	MM9751	Complete	TFS
8/27/2020	8/27/2021	9/16/2020	MM9751	SF8537	Complete	TFS
8/27/2020	8/27/2021	9/10/2020	MM9751	SF8537	Complete	TFS
8/27/2020	8/27/2021	9/11/2020	MM9751	SF8537	Complete	TFS
8/27/2020	8/27/2021	9/1/2020	MM9751	MM9751	Complete	TFS
8/27/2020	8/27/2021	8/27/2020	MM9751	MM9751	Complete	TFS
9/17/2020	9/17/2021	9/18/2020	SF8537	SF8537	Complete	TFS
10/2/2020	10/2/2021	10/27/2020	GG8932	NH2812	Complete	TFS
10/13/2020	10/13/2021	10/13/2020	TL5296	TL5296	Complete	TFS
10/13/2020	10/13/2021	10/21/2020	SF8537	SF8537	Complete	TFS
10/14/2020	10/14/2021	10/27/2020	SF8537	SF8537	Complete	TFS
10/14/2020	10/14/2021	10/19/2020	MM9751	MM9751	Complete	TFS
10/14/2020	10/14/2021	10/20/2020	MM9751	MM9751	Complete	TFS
10/14/2020	10/14/2021	10/21/2020	MM9751	MM9751	Complete	TFS
10/14/2020	10/14/2021	10/29/2020	MM9751	MM9751	Complete	TFS
10/14/2020	10/14/2021	11/6/2020	MM9751	MM9751	Complete	TFS
10/20/2020	10/20/2021	11/5/2020	MM9751	MM9751	Complete	TFS
10/21/2020	10/21/2021	1/8/2021	PG6512	PG6512	Complete	TFS
10/21/2020	10/21/2021	10/30/2020	PG6512	PG6512	Complete	TFS

10/23/2020	10/23/2021	10/28/2020	MM9751	SF8537	Complete	TFS
10/28/2020	10/28/2021	10/28/2020	SF8537	SF8537	Complete	TFS
10/29/2020	10/29/2021	11/9/2020	PG6512	PG6512	Complete	TFS
10/29/2020	10/29/2021	10/29/2020	PG6512	PG6512	Complete	TFS
11/3/2020	11/3/2021	11/10/2020	MM9751	MM9751	Complete	TFS
11/3/2020	11/3/2021	11/6/2020	MM9751	MM9751	Complete	TFS
11/17/2020	11/17/2021	11/20/2020	MM9751	MM9751	Complete	TFS
11/18/2020	11/18/2021	12/6/2020	PC9347	JI2512	Complete	TFS
12/4/2020	12/4/2021	3/14/2021	RD3541	QB6851	Complete	TFS
12/4/2020	12/4/2021	12/10/2020	SF8537	SF8537	Complete	TFS
12/11/2020	12/11/2021	12/29/2020	SF8537	SF8537	Complete	TFS
1/2/2021	1/2/2022	3/8/2021	SM4953	SM4953	Complete	TFS
1/22/2021	1/22/2022	2/23/2021	MS7970	SM4953	Complete	TFS
1/26/2021	1/26/2022	1/26/2021	MM9751	MM9751	Complete	TFS
3/27/2021	3/27/2022	3/30/2021	MM9751	MM9751	Complete	TFS
3/27/2021	3/27/2022	3/29/2021	MM9751	MM9751	Complete	TFS
3/31/2021	3/31/2022	4/2/2021	SM4953	DM820T	Complete	TFS
4/2/2021	4/2/2022	4/14/2021	SF8537	SF8537	Complete	TFS
4/28/2021	4/28/2022	5/12/2021	MM9751	MM9751	Complete	TFS
5/14/2021	5/14/2022	5/17/2021	MM9751	MM9751	Complete	TFS
5/21/2021	5/21/2022	5/24/2021	MM9751	MM9751	Complete	TFS
5/26/2021	5/26/2022	5/27/2021	MM9751	MM9751	Complete	TFS
6/2/2021	6/2/2022	6/4/2021	MM9751	MM9751	Complete	TFS
6/7/2021	6/7/2022	8/29/2022	AC1532	AC1532	Complete	TFS
6/9/2021	6/9/2022	6/14/2021	SF8537	SF8537	Complete	TFS
6/14/2021	6/14/2022	8/20/2021	MM9751	MM9751	Complete	TFS
6/14/2021	6/14/2022	6/17/2021	MM9751	MM9751	Complete	TFS
6/17/2021	6/17/2022	6/29/2021	MM9751	MM9751	Complete	TFS
6/22/2021	6/22/2022	7/28/2021	MM9751	SF8537	Complete	TFS
6/29/2021	6/29/2022	6/30/2021	MM9751	MM9751	Complete	TFS
6/30/2021	6/30/2022	7/6/2021	MM9751	MM9751	Complete	TFS
7/13/2021	7/13/2022	7/30/2021	MM9751	SF8537	Complete	TFS
7/13/2021	7/13/2022	7/14/2021	MM9751	MM9751	Complete	TFS

7/15/2021	7/15/2022	8/2/2021	MM9751	MM9751	Complete	TFS
8/27/2021	8/27/2022	8/27/2021	MM9751	MM9751	Complete	TFS
9/8/2021	9/8/2022	9/13/2021	MM9751	MM9751	Complete	TFS
9/15/2021	9/15/2022	9/16/2021	MM9751	MM9751	Complete	TFS
9/16/2021	9/16/2022	9/16/2021	SF8537	SF8537	Complete	TFS
9/17/2021	9/17/2022	9/23/2021	MM9751	MM9751	Complete	TFS
9/17/2021	9/17/2022	9/20/2021	MM9751	MM9751	Complete	TFS
9/17/2021	9/17/2022	9/24/2021	SF8537	SF8537	Complete	TFS
9/17/2021	9/17/2022	9/30/2021	SF8537	SF8537	Complete	TFS
9/17/2021	9/17/2022	9/20/2021	SF8537	SF8537	Complete	TFS
9/17/2021	9/17/2022	9/17/2021	MM9751	MM9751	Complete	TFS
9/20/2021	9/20/2022	9/22/2021	MM9751	MM9751	Complete	TFS
9/23/2021	9/23/2022	10/14/2021	MM9751	MM9751	Complete	TFS
9/23/2021	9/23/2022	9/24/2021	MM9751	SF8537	Complete	TFS
9/28/2021	9/28/2022	9/28/2021	SF8537	SF8537	Complete	TFS
9/28/2021	9/28/2022	9/29/2021	MM9751	MM9751	Complete	TFS
9/30/2021	9/30/2022	9/30/2021	SF8537	SF8537	Complete	TFS
10/5/2021	10/5/2022	10/14/2021	SF8537	SF8537	Complete	TFS
10/5/2021	10/5/2022	11/22/2021	SF8537	MM9751	Complete	TFS
10/5/2021	10/5/2022	10/14/2021	MM9751	MM9751	Complete	TFS
10/14/2021	10/14/2022	10/18/2021	MM9751	MM9751	Complete	TFS
10/14/2021	10/14/2022	10/20/2021	MM9751	MM9751	Complete	TFS
10/19/2021	10/19/2022	11/10/2021	MM9751	MM9751	Complete	TFS
10/19/2021	10/19/2022	10/19/2021	MM9751	SF8537	Complete	TFS
11/17/2021	11/17/2022	3/14/2022	JQ2645	JQ2645	Complete	TFS
11/22/2021	11/22/2022	12/1/2021	MM9751	SF8537	Complete	TFS
12/10/2021	12/10/2022	2/23/2022	SF8537	SF8537	Complete	TFS
1/19/2022	1/19/2023	11/3/2022	CC808U	JH3145	Complete	TFS
1/30/2022	2/2/2022	2/3/2022	JM1827	DO1823	Complete	TFS
2/10/2022	2/10/2023	3/18/2022	MH2676	BK2151	Complete	TFS
2/12/2022	2/12/2023	2/16/2022	SF8537	SF8537	Complete	TFS
2/17/2022	2/17/2023	2/24/2022	SF8537	SF8537	Complete	TFS

3/1/2022	3/1/2023	3/2/2022	SF8537	SF8537	Complete	TFS
3/1/2022	3/1/2023	3/25/2022	SF8537	SF8537	Complete	TFS
3/15/2022	3/15/2023	4/12/2022	SF8537	SF8537	Complete	TFS
3/23/2022	3/23/2023	4/18/2022	PG6512	PG6512	Complete	TFS
3/23/2022	3/23/2023	7/28/2022	SF8537	SF8537	Complete	TFS
3/24/2022	3/24/2023	7/22/2022	SF8537	SF8537	Complete	TFS
3/25/2022	3/25/2023	3/28/2022	DD6738	SF8537	Complete	TFS
4/14/2022	4/14/2023	10/29/2022	DM820T	QB6851	Complete	TFS
7/29/2022	7/29/2023	2/10/2023	SF8537	SF8537	Complete	TFS
8/1/2022	8/1/2023	8/10/2022	SF8537	SF8537	Complete	TFS
9/14/2022	9/14/2023	11/4/2022	SF8537	SF8537	Complete	TFS
9/14/2022	9/14/2023	9/15/2022	SF8537	SF8537	Complete	TFS
10/17/2022	10/17/2023	10/22/2022	PC9347	JM1295	Complete	TFS
10/18/2022	10/18/2023	11/13/2022	CG4741	QB6851	Complete	TFS
11/28/2022	11/28/2023	11/29/2022	PC9347	PC9347	Complete	TFS
1/19/2023	1/19/2024	1/27/2023	SF8537	SF8537	Complete	TFS
2/8/2023	2/8/2024	4/17/2023	SF8537	SF8537	Complete	TFS
3/29/2023	3/28/2024	4/27/2023	SF8537	SF8537	Complete	TFS
3/29/2023	3/28/2024	4/27/2023	SF8537	SF8537	Complete	TFS
3/30/2023	3/29/2024	2/6/2024	SF8537	SF8537	Complete	TFS
4/5/2023	4/4/2024	5/2/2023	SF8537	SF8537	Complete	TFS
4/12/2023	4/11/2024	8/11/2023	SF8537	SF8537	Complete	TFS
4/12/2023	4/11/2024	4/14/2023	SF8537	SF8537	Complete	TFS
4/17/2023	4/16/2024	8/26/2023	WP3262	VC6131	Complete	TFS
4/17/2023	4/16/2024	12/4/2023	SF8537	SF8537	Complete	TFS
4/24/2023	4/23/2024	8/26/2023	PC9347	QB6851	Complete	TFS
5/2/2023	5/1/2024	5/11/2023	SF8537	SF8537	Complete	TFS
5/9/2023	5/8/2024	5/18/2023	SF8537	SF8537	Complete	TFS
5/9/2023	5/8/2024	5/25/2023	SF8537	SF8537	Complete	TFS
5/9/2023	5/8/2024	5/25/2023	SF8537	CC2745	Complete	TFS
5/16/2023	5/15/2024	6/2/2023	SF8537	SF8537	Complete	TFS
5/26/2023	5/25/2024	10/20/2023	AC1532	AC1532	Complete	TFS
6/2/2023	6/1/2024	6/7/2023	SF8537	SF8537	Complete	TFS
6/2/2023	6/1/2024	7/27/2023	SF8537	SF8537	Complete	TFS
6/2/2023	6/1/2024	7/25/2023	SF8537	SF8537	Complete	TFS
7/7/2023	7/6/2024	8/4/2023	SF8537	SF8537	Complete	TFS
7/19/2023	7/18/2024	7/20/2023	SF8537	SF8537	Complete	TFS

8/11/2023	8/10/2024	10/20/2023	AC1532	AC1532	Complete	TFS
9/27/2023	9/26/2024	12/13/2023	SF8537	SF8537	Complete	TFS
10/4/2023	10/3/2024	10/13/2023	AC1532	AC1532	Complete	TFS
10/13/2023	10/12/2024	12/6/2023	AC1532	AC1532	Complete	TFS
10/16/2023	10/15/2024	11/1/2023	BH9763	DD6738	Complete	TFS
10/20/2023	10/19/2024	12/15/2023	AC1532	AC1532	Complete	TFS
10/20/2023	10/19/2024	10/25/2023	AC1532	AC1532	Complete	TFS
10/25/2023	10/24/2024	10/26/2023	AC1532	AC1532	Complete	TFS
12/8/2023	12/7/2024	2/29/2024	AC1532	AC1532	Complete	TFS
4/3/2024	4/3/2025	5/3/2024	SF8537	SF8537	Complete	TFS
4/3/2024	4/3/2025	5/9/2024	SF8537	SF8537	Complete	TFS
4/3/2024	4/3/2025	4/22/2024	SF8537	SF8537	Complete	TFS
4/3/2024	4/3/2025	4/10/2024	SF8537	SF8537	Complete	TFS
4/3/2024	4/3/2025	4/25/2024	SF8537	SF8537	Complete	TFS
5/9/2024	5/9/2025	5/15/2024	SF8537	SF8537	Complete	TFS
5/9/2024	5/9/2025	5/13/2024	SF8537	SF8537	Complete	TFS
6/4/2024	6/4/2025	6/26/2024	SF8537	SF8537	Complete	TFS
6/20/2024	6/20/2025	7/22/2024	SF8537	SF8537	Complete	TFS

TOWN	ADDRESS	TROUBLE_LOCATION	SERVICE_PRIORITY
Quincy	159 Lawrence St	Terminal Address	Service Affecting - POTS
Sierraville	114 E Willow St	Terminal Address	Service Affecting - POTS
Rough And Ready	16400-16430 Rough And Ready Hw	Street Address	Non-Service Affecting
Portola	69253-69317 Mohawk Rd	Terminal Address	Service Affecting - POTS
Portola	69901-69985 Betterton Creek Rd	Terminal Address	Service Affecting - POTS
Portola	69201 Mohawk Rd	Front of Address	Service Affecting - POTS
Quincy	113 N Mill Creek Rd	Side of Address	Service Affecting - POTS
Portola	68701 Mohawk Rd	Terminal Address	Service Affecting - POTS
Portola	69857 Mohawk Rd	Terminal Address	Service Affecting - POTS
Quincy	86 N Mill Creek Rd	Terminal Address	Service Affecting - POTS
Portola	69667 Mule Deer Rd	Front of Address	Service Affecting - POTS
Portola	69537-69645 Mohawk Rd	Street Address	Service Affecting - POTS
Beckwourth	88451 CA-70	Street Address	Service Affecting - POTS
Belden	6212 Hwy 70	Street Address	Service Affecting - POTS
Blairsden Graeagle	2868-2932 La Porte Rd	Side of Address	Service Affecting - POTS
Quincy	870 Bresciani Cir	Pole Address	Non-Service Affecting
Sierraville	418-426 Old Truckee Rd	Street Address	Service Affecting - POTS
Blairsden Graeagle	2981-2999 La Porte Rd	Street Address	Service Affecting - POTS
Quincy	12552-12754 Bucks Lake Rd	Street Address	Service Affecting - POTS
Meadow Valley	RPTR15 Big Creek rd	Terminal Address	Service Affecting - POTS
Quincy	RPTR16 Big Creek Rd	Terminal Address	Service Affecting - POTS
Blairsden Graeagle	23 Mohawk Hwy 40A Rd	Terminal Address	Service Affecting - POTS
Quincy	43374-43392 Blackhawk Creek Rd	Terminal Address	Service Affecting - POTS
Belden	4255-4299 Feather River Hwy	Pole Address	Service Affecting - POTS
Quincy	197 Lawrence St	Terminal Address	Service Affecting - POTS
Belden	6214 Hwy 70	Street Address	Service Affecting - POTS
Quincy	1760 E Main St	Street Address	Service Affecting - POTS

Quincy	158-280 Danny Ct	Terminal Address	Service Affecting - POTS
Portola	71326 CA-70	Terminal Address	Service Affecting - POTS
Portola	71326 CA-70	Front of Address	Service Affecting - POTS
Portola	71326 CA-70	Street Address	Service Affecting - POTS
Portola	71239 CA-70	Street Address	Service Affecting - POTS
Portola	71326 CA-70	Terminal Address	Service Affecting - POTS
Quincy	25 Main St	Street Address	Service Affecting - POTS
Portola	124 Clareville Rd	Terminal Address	Service Affecting - POTS
Grass Valley	815 S Auburn St	Front of Address	Non-Service Affecting
Portola	133 Clairville Cir	Terminal Address	Service Affecting - POTS
Portola	56 Somewhere Rd	Street Address	Service Affecting - POTS
Portola	168 Clareville Rd	Terminal Address	Service Affecting - POTS
Portola	217-261 Clareville Rd	Terminal Address	Service Affecting - POTS
Portola	301 Clareville Rd	Terminal Address	Service Affecting - POTS
Portola	71326 CA-70	Terminal Address	Service Affecting - POTS
Quincy	25 Main St	Street Address	Service Affecting - POTS
Portola	190-220 Kitten Cir	Street Address	Service Affecting - POTS
Nevada City	15461 Banner Lava Cap Rd	Front of Address	Non-Service Affecting
Grass Valley	14406 Penn Rd	Terminal Address	Service Affecting - POTS
Nevada City	17107 Old Mill Rd	Street Address	Service Affecting - POTS
Nevada City	19365-19399 Tyler Foote Crossi	Street Address	Service Affecting - POTS
Quincy	26 Circle Dr	Street Address	Service Affecting - POTS
Quincy	32 Circle Dr	Street Address	Service Affecting - POTS
Quincy	106 Circle Dr	Street Address	Service Affecting - POTS
Quincy	116 Circle Dr	Street Address	Service Affecting - POTS
Grass Valley	10137 Daisy King Dr	Front of Address	Service Affecting - POTS
Clipper Mills	12038-12098 La Porte Rd	Pole Address	Service Affecting - POTS
Brownsville	10050 La Porte Rd	Pole Address	Service Affecting - POTS
Quincy	200-248 N Mill Creek Rd	Pole Address	Service Affecting - POTS
Quincy	39967 state hwy 70	Street Address	Service Affecting - POTS
Quincy	41247 Wests Ranch Rd	Street Address	Service Affecting - POTS
Grass Valley	129 Neal St	Street Address	Non-Service Affecting
Calpine	1-35 Main St	Terminal Address	Service Affecting - POTS
Calpine	1-35 Main St	Terminal Address	Service Affecting - POTS
Quincy	895 E Main St	Pole Address	Service Affecting - POTS
Quincy	1355 E Main St	Pole Address	Service Affecting - POTS
Brownsville	17335-17369 Indiana Ranch Rd	Terminal Address	Service Affecting - POTS

Brownsville	17335-17369 Indiana Ranch Rd	Terminal Address	Service Affecting - POTS
Quincy	860 Grizzly Loop	Street Address	Service Affecting - POTS
Beckwourth	ped 11	Pole Address	Service Affecting - POTS
Portola	5046 Grizzly Rd	Pole Address	Service Affecting - POTS
Quincy	179 Lawrence St	Street Address	Service Affecting - POTS
Quincy	14227-14255 Feather River Hwy	Street Address	Service Affecting - POTS
Belden	14227-14255 Feather River Hwy	Street Address	Service Affecting - POTS
Grass Valley	13393 Grass Valley Ave	Manhole Address	Service Affecting - POTS
Blairsden Graeagle	1 Pine Cone Ct	Terminal Address	Service Affecting - POTS
Quincy	197 Main St	Terminal Address	Service Affecting - POTS
Blairsden Graeagle	72 Sequoia Cir	Street Address	Service Affecting - POTS

Truckee	P 10 Truckee Weight Station	Terminal Address	Service Affecting - POTS
Portola	79282-79316 Valley View Dr	Terminal Address	Service Affecting - POTS
Quincy	52 Wildwood Ct	Street Address	Service Affecting - POTS
Blairsden Graeagle	4439-4599 La Porte Rd	Pole Address	Service Affecting - POTS
Blairsden Graeagle	4353-4437 La Porte Rd	Pole Address	Service Affecting - POTS
Blairsden Graeagle	3959-4289 La Porte Rd	Pole Address	Service Affecting - POTS
Blairsden Graeagle	3901-3957 La Porte Rd	Pole Address	Service Affecting - POTS
Quincy	150 N Mill Creek Rd	Pole Address	Service Affecting - POTS
Portola	7735 Whitethorn Trail	Street Address	Service Affecting - POTS
Nevada City	17801 Cooper Rd	Street Address	Service Affecting - POTS
Truckee	14156 Russel Valley Rd.	Terminal Address	Service Affecting - POTS
Quincy	2500-2516 La Porte Rd	Pole Address	Service Affecting - POTS
Blairsden Graeagle	23 Mohawk Hwy 40A Rd	Street Address	Service Affecting - POTS
Quincy	210 Carol Ln E	Terminal Address	Service Affecting - POTS
Quincy	250 Carol Ln E	Street Address	Service Affecting - POTS
Quincy	290 Carol Ln E	Terminal Address	Service Affecting - POTS
Quincy	362 Carol Ln E	Terminal Address	Service Affecting - POTS
Quincy	476 Carol Ln E	Terminal Address	Service Affecting - POTS
Quincy	6278-6298 Feather River Hwy	Pole Address	Service Affecting - POTS
Truckee	11070 Brockway Rd	Behind Address	Non-Service Affecting
Truckee	11070 Brockway Rd	Behind Address	Non-Service Affecting

Quincy	93 Lindan Ave	Terminal Address	Service Affecting - POTS
Portola	7398 Marilyn Way	Terminal Address	Service Affecting - POTS
Truckee	10948 Brockway Rd	Behind Address	Non-Service Affecting
Truckee	11070 Brockway Rd	Behind Address	Non-Service Affecting
Quincy	400 Carol Ln E	Terminal Address	Service Affecting - POTS
Quincy	590 Carol Ln E	Terminal Address	Service Affecting - POTS
Quincy	1988 Chandler Rd	Terminal Address	Service Affecting - POTS
Nevada City	14394 Banner Mountain Lookout	Terminal Address	Service Affecting - POTS
Nevada City	15300-15308 Lewis Rd	Front of Address	Service Affecting - POTS
Meadow Valley	3400 bucks lake rd	Pole Address	Service Affecting - POTS
Portola	500-598 Ridgewood Dr	Terminal Address	Service Affecting - POTS
Nevada City	10000-10038 Tyler Foote Crossi	Terminal Address	Service Affecting - POTS
Camptonville	17649 CA-49	Behind Address	Service Affecting - POTS
Quincy	55 Main St	Street Address	Non-Service Affecting
Quincy	25 Main St	Street Address	Non-Service Affecting
Quincy	25 Main St	Street Address	Non-Service Affecting
Camptonville	14669 Old Camptvil Rd	Outside Terminal Address	Service Affecting - POTS
Vinton	94248 CA-70	Terminal Address	Service Affecting - POTS
Quincy	6232-6276 Feather River Hwy	Pole Address	Service Affecting - POTS
Belden	14257-14283 Feather River Hwy	Pole Address	Service Affecting - POTS
Quincy	200 Railway Ave	Pole Address	Service Affecting - POTS
Quincy	9934-10110 Bucks Lake Rd	Street Address	Service Affecting - POTS
Quincy	10111 Bucks Lake Rd	Pole Address	Service Affecting - POTS
Oroville	18594-18624 New York Flat Rd	Street Address	Service Affecting - POTS
Beckwourth	7411 roberti ranch	Pole Address	Service Affecting - POTS
Calpine	46201-46303 CA-49	Pole Address	Service Affecting - POTS
Calpine	22500-22798 CA-89	Pole Address	Service Affecting - POTS
Meadow Valley	8507 Bucks Lake Rd	Pole Address	Service Affecting - POTS
Quincy	150 N Mill Creek Rd	Terminal Address	Service Affecting - POTS
Quincy	2200-2498 La Porte Rd	Terminal Address	Service Affecting - POTS
Quincy	2670 La Porte Rd	Terminal Address	Service Affecting - POTS
Quincy	760 La Porte Rd	Pole Address	Service Affecting - POTS
Quincy	834 La Porte Rd	Terminal Address	Service Affecting - POTS

Quincy	760 La Porte Rd	Pole Address	Service Affecting - POTS
Blairsden Graeagle	481-699 Graeagle Johnsville Rd	Terminal Address	Service Affecting - POTS
Blairsden Graeagle	217-295 Graeagle Johnsville Rd	Street Address	Service Affecting - POTS
Quincy	6000-6230 Feather River Hwy	Pole Address	Service Affecting - POTS
Quincy	ped2-3	Pole Address	Service Affecting - POTS
Quincy	130 Twain Store Rd	Pole Address	Service Affecting - POTS
Quincy	134-298 Twain Store Rd	Pole Address	Service Affecting - POTS
Belden	15177-15319 Feather River Hwy	Pole Address	Service Affecting - POTS
Belden	14587-14739 Feather River Hwy	Pole Address	Service Affecting - POTS
Belden	14291-14323 Feather River Hwy	Pole Address	Service Affecting - POTS
Quincy	134-298 Twain Store Rd	Pole Address	Service Affecting - POTS
Quincy	8175-8199 Butterfly Valley Twa	Pole Address	Service Affecting - POTS
Quincy	8175-8199 Butterfly Valley Twa	Pole Address	Service Affecting - POTS
Loyalton	200 Taylor Ave	Street Address	Non-Service Affecting
Belden	15177-15319 Feather River Hwy	Pole Address	Service Affecting - POTS
Quincy	41796 CA-70	Pole Address	Service Affecting - POTS
Belden	14285-14289 Feather River Hwy	Pole Address	Service Affecting - POTS
Belden	14101-14225 Feather River Hwy	Pole Address	Service Affecting - POTS
Belden	14421-14463 Feather River Hwy	Pole Address	Service Affecting - POTS
Quincy	41796 CA-70	Pole Address	Service Affecting - POTS
Quincy	8175-8199 Butterfly Valley Twa	Pole Address	Service Affecting - POTS
Quincy	200-268 County Hospital Rd	Pole Address	Service Affecting - POTS
Quincy	41796 CA-70	Pole Address	Service Affecting - POTS
Quincy	8175-8199 Butterfly Valley Twa	Pole Address	Service Affecting - POTS
Truckee	11070 Brockway Rd	Behind Address	Service Affecting - POTS
Quincy	14421-14463 Feather River Hwy	Street Address	Service Affecting - POTS
Quincy	39877 CA-70	Terminal Address	Service Affecting - POTS
Truckee	10342 Cold Stream Rd	Terminal Address	Service Affecting - POTS
Grass Valley	14800 Greenhorn Access Rd	Front of Address	Hazardous Condition
Grass Valley	63 Candy Ln	Behind Address	Service Affecting - POTS
Quincy	1862-1984 La Porte Rd	Street Address	Service Affecting - POTS
Quincy	185 Clough St	Terminal Address	Service Affecting - POTS

Quincy	Pole.20 Howeells rd	Pole Address	Service Affecting - POTS
Beckwourth	1600-1616 Harrison Ranch Rd	Street Address	Service Affecting - POTS
Quincy	2023-2079 Greenhorn Ranch Rd.	Street Address	Service Affecting - POTS
Truckee	10040 Estates Dr	Terminal Address	Non-Service Affecting
Quincy	RPTR1 snake lake rd	Terminal Address	Service Affecting - POTS
Quincy	200-268 County Hospital Rd	Terminal Address	Service Affecting - POTS
Loyalton	606 CA-49	Front of Address	Non-Service Affecting
Grass Valley	29-49 Rockwood Dr	Terminal Address	Service Affecting - POTS
Quincy	248-298 Fairground Rd	Street Address	Service Affecting - POTS
Quincy	3730 Chandler Rd	Street Address	Service Affecting - POTS
Loyalton	109 Hill St	Terminal Address	Service Affecting - POTS
Portola	6930-6972 Altis Trail	Terminal Address	Service Affecting - POTS
Camptonville	3 ped pendola rd ext	Front of Address	Service Affecting - POTS
Camptonville	weeds point rd	Front of Address	Service Affecting - POTS
Nevada City	18545-18873 Sages Rd	Front of Address	Non-Service Affecting
Belden	9538-9556 Feather River Hwy	Pole Address	Service Affecting - POTS
Portola	72205 CA-70	Terminal Address	Service Affecting - POTS
Blairsden Graeagle	1201 Smith Creek Rd	Street Address	Service Affecting - POTS
Portola	69840 Chipmunk Rd	Terminal Address	Service Affecting - POTS
Portola	71709-71799 CA-70	Street Address	Service Affecting - POTS
Beckwourth	1634-1694 Harrison Ranch Rd	Terminal Address	Service Affecting - POTS
Quincy	10111 Bucks Lake Rd	Pole Address	Service Affecting - POTS
Quincy	1770 E Main St	Terminal Address	Service Affecting - POTS
Nevada City	14486 N Bloomfield Rd	Pole Address	Service Affecting - POTS
Portola	72129 CA-70	Street Address	Service Affecting - POTS
Nevada City	13344 Poplar Meadow Ln	Street Address	Non-Service Affecting
Portola	71326 CA-70	Street Address	Service Affecting - POTS
Belden	9538-9556 Feather River Hwy	Street Address	Service Affecting - POTS
Belden	9558-9580 Feather River Hwy	Terminal Address	Service Affecting - POTS
Belden	9558-9580 Feather River Hwy	Street Address	Service Affecting - POTS
Chilcoot-Vinton	49 Main St	Street Address	Service Affecting - POTS
Quincy	1841 Aristocracy Dr	Pole Address	Service Affecting - POTS
Quincy	1250 La Porte Rd	Street Address	Service Affecting - POTS
Quincy	1294 Quincy-La Porte Rd	Street Address	Service Affecting - POTS
Quincy	1048-1196 Quincy-La Porte Rd	Street Address	Service Affecting - POTS
Calpine	132-142 CA-49	Pole Address	Service Affecting - POTS
Quincy	1360 Grizzly Loop	Terminal Address	Service Affecting - POTS

Blairsden Graeagle	2678-2848 Little Grass Valley	Pole Address	Service Affecting - POTS
Beckwourth	83101-83151 CA-70	Street Address	Service Affecting - POTS
Brownsville	8700-8798 Greenwell Ln	Pole Address	Service Affecting - POTS
Strawberry Valley	583-599 Little Grass Valley Rd	Street Address	Service Affecting - POTS
Truckee	12047 Donner Pass Rd	Street Address	Non-Service Affecting
Strawberry Valley	2850-2998 Little Grass Valley	Street Address	Service Affecting - POTS
Strawberry Valley	2040-2344 Little Grass Valley	Street Address	Service Affecting - POTS
Strawberry Valley	1800-1806 Little Grass Valley	Pole Address	Service Affecting - POTS
Challenge	10695 Forbestown Rd	Street Address	Service Affecting - POTS
Meadow Valley	664 Silver Creek Rd	Street Address	Service Affecting - POTS
Quincy	26116-26142 Feather River Hwy	Street Address	Service Affecting - POTS
Quincy	26116-26142 Feather River Hwy	Street Address	Service Affecting - POTS
Quincy	26144-26198 Feather River Hwy	Street Address	Service Affecting - POTS
Quincy	26110 Feather River Hwy	Street Address	Service Affecting - POTS
Blairsden Graeagle	Ped5 Johnsville rd	Terminal Address	Service Affecting - POTS
Calpine	132-142 CA-49	Street Address	Service Affecting - POTS
Sierra City	7000 gold lake forest hwy	Pole Address	Service Affecting - POTS
Quincy	51840-51860 CA-70	Street Address	Service Affecting - POTS

CATEGORY	TYPE_OF_TROUBLE
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Poles/Hardware	Deteriorated Pole
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Damaged Cable Section
Terminal	SAI/XBOX Repair-Wire
Cable (Copper)	Defective Cable Section
Cable (Copper)	Defective Cable Section
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Defective Cable Section
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Damaged Cable Section
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal

Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Manhole/Handhole	HAND HOLE LID BROKEN/DEF
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal

Manhole/Handhole	HAND HOLE LID BROKEN/DEF

Cable (Copper)	Def/Damaged Splice/Terminal
Manhole/Handhole	HAND HOLE LID BROKEN/DEF
Manhole/Handhole	HAND HOLE LID BROKEN/DEF
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal

Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal

Cable (Copper)	Def/Damaged Splice/Terminal

Cable (Copper)	Damaged Cable Section
Cable (Copper)	Def/Damaged Splice/Terminal
Manhole/Handhole	HAND HOLE LID BROKEN/DEF
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal

Cable (Copper)	Def/Damaged Splice/Terminal

Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal

Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal

Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Defective Cable Section
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Terminal	SAI/XBOX Repair-Wire
Cable (Copper)	Damaged Cable Section
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def/Damaged Splice/Terminal
Cable (Copper)	Def or Damaged Terminal
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Terminal
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Terminal	SAI/XBOX Repair-Wire
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice

Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Terminal
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Terminal
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Terminal
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Fiber	F2 - Fiber Connectorized / Fiber Serving Termina
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice

Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Manhole/Handhole	Handhole / Manhole Lid Broken or Def
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Terminal
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Terminal
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Defective Cable Section
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Terminal
Cable (Copper)	Def or Damaged Terminal
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice

Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Fiber	Handhole / Manhole Lid Broken or Def
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Terminal
Cable (Copper)	Def or Damaged Terminal
Cable (Copper)	Def or Damaged Terminal
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice
Cable (Copper)	Def or Damaged Splice

DESCRIPTION
MARKIT Resplice wet cable splice,replace waffle case,600 Pr
MARKIT Resplice f2 cable and install new 6 pedestal, CA0106x176-200
MARKIT Damaged pole due to car pole. Need traffic control.
MARKIT Section throw dfective splice,CA5310 x1-100. Office carrier cable.
MARKIT Replace def pedestal, CA0316x226-250, @ 69903 betterton rd
MARKIT Section throw def cable, CA5310 x1-100, dig requested and materials ordered.
MARKIT Remount 25 Pr 1.1 to wall,laying on ground,address 150 n mill creek ,right rear wall,unit H
MARKIT CA5310 x1-100 cable trouble isolation. Office carrier cable dig job, trench conduit under Rd3/ Chipmunk rd. C
MARKIT CA5310 x1-100. Office carrier cabledig/ splice job.
MARKIT Remount 1.1 25 Pr terminal
MARKIT Open existing case and test to isolate trouble on CA5310- toll cable
MARKIT Open existing splice to isolate trouble on Ca5310 toll cable
MARKIT Replace temp section cable, CA0211x401-425, Harrison Ranch rd.
MARKIT Request 2 dig pits,encapsulate and bury two defective temp wraps @culvert, 1000 north of hwy 70 bridge@ T
MARKIT Assist county with locate and conduit work@ culvert.cable got dug up needs section throw and new conduit b
MARKIT Remove all dead drops
MARKIT Cable exposed on shoulder county rd. CA0102x 76-100
MARKIT Place 60 ft buried 50 Pr cable,resplice,place 2-10 inch pedi
MARKIT Section throw defective splice and install pedestals.carrier cable bucks lakr r.t.
MARKIT Open splice for RPTR15 Big Crrek rd,wet, need rehab and case work.
MARKIT Open RPTR16 splice,wet, rehab cable,case work
MARKIT CA03x651-675. Remove cable splice off tree. And install pedestal over conduit. Resplice and bury two ft of F1
MARKIT Replace defective ped,resplice
MARKIT Replace defective ped cad 6,Resplice
MARKIT Replace defective cad 12 ped,resplice cable
MARKIT Dig small pit to access defective splice. Encap and bury splice, carrier pairs for TobinR.T. Site trouble, cable e
MARKIT Need ped replaced, damaged

MARKIT Splice case needs repair
MARKIT Damaged ped needs repair
MARKIT Splice corroded needs replacement
MARKIT Damaged splice needs repair
MARKIT Damaged ped needs repair
MARKIT Damaged splice needs repair
MARKIT Replace defective ped
MARKIT Damaged ped needs repair
MARKIT Broken sub box lid
MARKIT Resplice cable,replace ped
MARKIT Damaged ped needs repair
MARKIT Resplice cable,replace terminal
MARKIT Damaged terminal needs replacement
MARKIT Damaged ped needs repair
MARKIT Resplice cable,replace ped
MARKIT Resplice defective splice,replace cad 6 terminal
MARKIT Resplice cable,repair terminal

MARKIT Buried box 15435 banner lava cap rd. Cover ripped off probably by snow plow. Cover replaced, but partly bust

MARKIT Serving terminal falling apart no cover, cable getting wet. replace cover and splice group 1.
MARKIT Need 1 bollard placed to secure generator. Needs eyelet, hole,etc. to place chain through to lock and secure
MARKIT Need 1 bollard placed with a way of securing a chain to it. (Ring,eyelet,etc.) to secure and lock a portable gen
MARKIT Resplice defective wet splices
MARKIT Resplice defective wet splices
MARKIT Resplice defective cable wet
MARKIT Resplice defective wet splice replace closure

MARKIT Box needs to be removed and pit dug dipper to get slack and section throw cable
MARKIT Trees fell on cable and drops. There is one broken drop going x street to pool and another going towards CO. A
MARKIT Resplice 400pr loaf splice and place new 12" case has a 7" case now and it is too small

MARKIT New new closure,rehab pairs. Blow air into buried f2 cable to dry wet span.

MARKIT ABWS-012052288. Trench for section throw cable damage. CA5315, Keddie Toll cable
MARKIT Buried cable damage, Bpc for trench job and section throw, CA5315 X1-50
MARKIT Need racking placed on the side walls of the tunnel.
MARKIT Replace defective cad 12 ped
MARKIT Replace defective cad 12 ped

MARKIT P 887 e main st, drops and air pressure lines hanging from pole, CA0111x201-300. Needs site work and air ch

MARKIT CA0111x1-200, needs air chack in MH13 e main st
MARKIT Need to do 12 foot section throw on 50 pair buried cable at terminal 17345 Indiana ranch rd

MARKIT Need to do 12 foot section throw on 50 pair buried cable at terminal 17345 Indiana ranch rd
MARKIT Replace smashed cad 12 ped
MARKIT Place new pedestal and stake,CA0209 x176-200

MARKIT Identify cable trouble,at LP4, RPTR5 grizzley rd
MARKIT Isolate and repair cable trouble. CA 0307x726-750.suspect wet in sub box splice.
MARKIT Defective buried splice,rebuild splice replace closure
MARKIT Defective buried splice,rebuild splice replace closure
MARKIT Need slack pulled from riser pole, rebuild splice, put in accessible ped.
MARKIT Bond cables after section throw.CA0309x1-50
MARKIT Resplice wet cable replace closure
MARKIT Bsw splice trouble,@AFL next to power splice.Between #72 &#82 sequoia cir.

MARKIT Wet 25 pair splice located at old Truckee weight station. Splice locates 430 from pole.

MARKIT Ped 79284 need splice reworked,corroded module.
MARKIT Resplice cable
MARKIT Resplice defective burned splice replace terminal
MARKIT Resplice cable replace terminal

MARKIT Resplice burned cable replace terminal
MARKIT Resplice burned cable replace terminal
MARKIT Resplice cable replace ped
MARKIT Pedestal post rotted, found laying on side,needs replacement pedestal. CA0210x376-400
MARKIT Damaged cad12 buried splice, possible vehicle damage. Roadside hazard, exposed 200 pair cable.

MARKIT Splice needs rebuild and new bmt needs placed. Collars need rebuild.
MARKIT Dig to install new pesetal,exposed cable

MARKIT Remove splice on tree and place new pedestal over conduit opening at base of tree.
MARKIT Resplice cable place ped
MARKIT Resplice cable replace ped
MARKIT Resplice cable replace ped
MARKIT Resplice cable replace ped
MARKIT Resplice cable replace ped
MARKIT Cable trouble isolation

MARKIT Need new buried case and terminal, dig dirt out of box, resplice drops into terminal and bond cable and bsw

MARKIT Need new buried case and terminal, dig dirt out of box, resplice drops into terminal and bond cable and bsw

MARKIT Resplice cable
MARKIT Ped 8060 craig ln, lake davis. Splice needs rehab, CA0210 x301-325

MARKIT Splice case needs to be replaced with sealed case. Cable is exposed to elements.

MARKIT Need buried case placed and terminal cut in
MARKIT Resplice cable replace ped
MARKIT Resplice cable replace ped
MARKIT Resplice defective splice replace defective ped

MARKIT Corroded at sheet opening/raise cable/sheet cable for good copper/resplice cable/replace ped
MARKIT Replace riser cable at corner of Lewis and Dow, 50 pair 24 gauge,

MARKIT Ped needs splice rehab @P160 Bucks lake rd.
MARKIT Remove bridge tap,and resplice
MARKIT Box hit by car needs new box
MARKIT Hit section by gate 107 ft up snowline from riser pole. Also hard case needs replaced on riser with 51A. Pour a
MARKIT Remove dead jumpers in main frame
MARKIT Remove dead jumpers main frame
MARKIT Remove dead jumpers main frame

MARKIT Rain soaked ped needs rebuilding

MARKIT Bob Kelley 7757379330, wants lburiedmcable located to Ped 20 frenchman lk trlr prk cable. Customer wishe

MARKIT Need to isolate trouble in buried span
MARKIT Span trouble isolation for Hi Caps

MARKIT Replace buried splice closure,replace aerial closure
MARKIT Span trouble isolation
MARKIT Cable trouble isolation and repair
MARKIT Place 6 inch ped over exposed buried splice at 18558 New York Flat rd
MARKIT Ped 3 dyson ln@tramsion lines,replice def pairs and install new pedestal. Old ped rusted and on side.
MARKIT Needs splice work needs new closure
MARKIT Span trouble isolation
MARKIT Span trouble isolation

MARKIT 10x golden eagle bbox weeds need to be cut down around bbox and rt
MARKIT Span trouble isolation
MARKIT Trouble isolation in span

MARKIT BBox 760 la porte rd,span trouble isolation
MARKIT Resplice defective splice

MARKIT Resplice wet splices 0801x1-200,replace closure B case sub box
MARKIT Resplice cable ped 573 grey eagle
MARKIT Replace broken 2 peds

MARKIT Span trouble isolation hi cap

MARKIT Recover pedestal damaged from Dixie fire, remove old materials left after rehab work
MARKIT Resplice temp wire by carrier cable

MARKIT Place temp wire by carrier cable rt Resplice

MARKIT Rehab splice and secure cable,chk bonding
MARKIT Rehab splice at Repeater5 hwy 70,
MARKIT Bpc job for ABWS dig.recover cable issue and section throw or rpr trouble.
MARKIT Carrier cable TLines damaged place wire by

MARKIT Isolating span trouble Dixie fire
MARKIT Span trouble isolation
MARKIT Replace broken ped,Resplice cable

MARKIT Rehab splice at RPTR2 Hwy 70
MARKIT Locate span trouble in carrier cable and repair
MARKIT Rehab splice,test facilities for trouble isolation
MARKIT Rehab splices in side by side pedestals, trouble isolation.
MARKIT Trouble isolation on cable,rehab pedestals near mile marker 9.0. Two on risers over crek and two side by side
MARKIT Pole 24 golden eagle,span trouble isolation HI CAPS
MARKIT Isolation span trouble T lines
MARKIT Isolation span trouble T lines
MARKIT Span trouble isolation T1 lines,10x golden eagle
MARKIT Span trouble isolation T1 lines
MARKIT Buried splice needs to cased w/ bmt
MARKIT trouble isolation on cable rehab pedestals near mile marker 9.0 two on risers over creek and two side by side
MARKIT Ped3-6 Hwy 70. Needs pedestal hardware replaced and pair rehab work.03

MARKIT Fiber hanging out of term need to replace

MARKIT Pedestal is uprooted and laying on the ground, from recent pole replacement from severe storm
MARKIT Found wet soaked open encap with bad modules needs to be respliced, a new A case has been placed
MARKIT Rehab splice,corroded modules @1860 LaPorte rd

MARKIT Ped 180 clough, need splice rehab,corroded.

MARKIT Access cable is for engineering, replace pedestal
MARKIT Encap ,wrap, and bury splice.
MARKIT Isolate buried splice trouble, Greenhorn Ranch

MARKIT Buried splice missing cover. Cable exposed to elements

MARKIT Isolate cable trouble on T1 circuit for Twain Post Office
MARKIT Isolate cable trouble fron fiber MUX to RPTR1, Snake Lake rd
MARKIT Broken concrete lid at SB54 corner of 2nd and main
MARKIT Needs 100 pair buried cable dug up and respliced. All insulation on wiring is crumbling off and creating shorts
MARKIT Splice at 12pedestal eeds new ped and pair rhab
MARKIT Rehab section throw splice.0401
MARKIT Bsw issue @109 Hill, needs dig
MARKIT Cable splice trouble, 6840 Altis trl

MARKIT Broken ped/rehab splice/replace ped
MARKIT Splice in some pedestal needs sheath back and respliced
MARKIT Ped corroded needs splice and new ped

MARKIT RPTR4 hwy 70, resplice cable,tempt
MARKIT Ped 1:hwy 70,splice needs rehab,corroded
MARKIT Pedestal and splice work
MARKIT Ped and splice work0316x201-225
MARKIT Ped splice needs rehab
MARKIT Pedestal and splice work
MARKIT SPG15, system 2 span3 trouble-sht
MARKIT Test PG05 spans from co to rt
MARKIT Def riser cable feeding rt from 4 way splice
MARKIT Ped@72129 need replice work
MARKIT Broken ped/replace ped/rehab splice/
MARKIT Ped1 Kitty Kat trl,need splice rehab and reinfo4cment post installd

MARKIT Temp strnby needs removal and cable spliced back into pedestal.
MARKIT Reha cable splice and dig it new Repeater post in and new pedestal
MARKIT Section throw bad splice,encap wrap and bury with. Dig it
MARKIT Rehab splice and replace def pedestal
MARKIT Rehab def 25 pair splice at p 1 aristocracy per

MARKIT Pull new cable and prep for section throw
MARKIT Tone and splice assistance, XXBL-51
MARKIT Tone and splice assistance, XXBL 51
MARKIT Splice missing pedestal cover, needs new pedestal and splice rehab.
MARKIT Pedestal on crnr big creek rd and grizzley loop needs replacement and spice work

MARKIT Rehab def 50 pair splice in ped
MARKIT Place two pedestals after cut cable section throw.
MARKIT Replace damaged ped and replace 25 pair riser cable 25 feet at p 16b8 Willow Glen rd at the intersection of G
MARKIT Replace damaged ped and resplice 75 pair cable

MARKIT Spring lid only has one latch bolt and is seized so can not be tightened! Lid is in the sidewalk and has been lef
MARKIT Replace damaged ped at 2325 Little Grass Valley rd
MARKIT Replace damaged ped at 1950 Little Grass Valley rd
MARKIT Repair def ped p 13 Little Grass Valley
MARKIT Replace defective ped at 10693 Forbestown rd

MARKIT Locate bsw fault,rod existing conduit, pull new bsw to sni. Ccon Davidson, 5302839032.
MARKIT Sheath and resplice BHBH-75
MARKIT Sheath and resplice BHBH-75
MARKIT Sheath and resplice BHBH-75
MARKIT Sheath and resplice BHBH-75

MARKIT Cable got power burnt, needs splicing and bonding. BHBH-25

MARKIT Pedestal missing cover,needs new.
MARKIT Need pedestal installed,a nd splice completely rehabed, 01x26-50

MARKIT South side of RxR tracks,cable needs bonding and trash pick up, after section throw.

LATITUDE	LONGITUDE	RSP_ORG	POLE_TERM_MH_INFO	PLACEMENT
39.943096	-120.992055	TFS	129 main s	Buried
39.577328	-120.368441	TFS	PED2-5	Buried
39.211031	-121.161748	ENG	rough read	
39.774807	-120.579261	TFS	splice 6-5	Buried
39.786722	-120.581499	TFS	69903 bett	Buried
39.774431	-120.580196	TFS	69201	Buried
39.937651	-120.904904	TFS	150 N mill	Buried
39.775292	-120.587581	TFS	RPTR 3	Buried
39.778316	-120.569738	TFS	RPTR4	Buried
39.936762	-120.904748	TFS	111	Buried
39.777692	-120.57531	TFS	spl 6-2.5	Buried
39.777483	-120.575834	TFS	spl 6-2.5	Buried
39.816944	-120.234759	TFS	INV spl	Buried
39.938406	-121.313536	TFS	spl 1	Buried
39.893645	-120.862618	TFS	2932	Buried
39.942515	-120.922405	TFS	875	
39.565332	-120.36386	TFS	420	Buried
39.889923	-120.864073	TFS	2981	Buried
39.89865	-121.120434	TFS	11-Apr	Buried
39.907736	-121.092787	TFS	RPTR15	Buried
39.900993	-121.105202	TFS	RPTR16	Buried
39.784895	-120.631893	TFS	23 1.1	Buried
39.993251	-120.991584	TFS	ped 65	Buried
39.918893	-121.321709	TFS	ped61B6	Buried
39.937588	-120.942527	TFS	sb341	Buried
39.938386	-121.313712	TFS	spl 2	Buried
39.934209	-120.907262	TFS	1770	Buried

39.93881	-120.905516	TFS	Sb 319		Buried
39.785185	-120.542951	TFS	so 10		Buried
39.786464	-120.543191	TFS		71326	Buried
39.786726	-120.544117	TFS	Sb 56		Buried
39.787339	-120.543939	TFS		71239	Buried
39.78683	-120.542983	TFS	Sb 57		Buried
39.938334	-120.93837	TFS		5000	Buried
39.786631	-120.541155	TFS	ped 168		Buried
39.200954	-121.058642	TFS	sb		
39.787	-120.540324	TFS	ped133		Buried
39.788673	-120.542079	TFS		71345	Buried
39.78577	-120.54105	TFS	p168		Buried
39.785324	-120.539953	TFS	ped 282		Buried
39.78544	-120.538883	TFS	ped 301		Buried
39.787501	-120.542966	TFS		71350	Buried
39.938461	-120.938498	TFS	200-298		Buried
39.783566	-120.544024	TFS	190-220		Buried
39.25209	-120.944556	TFS	15435 bann		
39.159029	-121.046165	TFS		14406	
39.381675	-120.993412	TFS		17121	
39.386718	-120.976345	TFS		19399	
39.936079	-120.940185	TFS	sb4		Buried
39.936439	-120.940136	TFS	sb3		Buried
39.936191	-120.938803	TFS	sb 1		Buried
39.93656	-120.939158	TFS	SB2		Buried
39.153673	-121.063158	TFS		10137	Buried
39.531629	-121.164285	TFS	p197 lapor		
39.485255	-121.227207	TFS	p 1015 la		
39.93916	-120.904956	TFS	SB312		Combo
39.960462	-120.952056	TFS	ped1		Buried
39.958726	-120.953716	TFS	splice1		Buried
39.217084	-121.063073	TFS		7	
39.668328	-120.436827	TFS	p65 main		Buried
39.668087	-120.436967	TFS	65 main		Buried
39.93506	-120.921908	TFS	P 887		Buried
39.934786	-120.91486	TFS	MH13		Buried
39.466092	-121.22183	TFS	17345India		Buried

39.466092	-121.22183	TFS	17345India		Buried
39.865697	-121.156955	TFS	ped860		Buried
39.762555	-120.352471	TFS	ped11		Buried
39.83798	-120.423864	TFS	LP4A		Buried
39.937685	-120.941992	TFS	sb1		Combo
39.947927	-121.304136	TFS	repeater 8		Combo
39.947987	-121.305084	TFS	repeater 8		Underground
39.218055	-121.01232	TFS	SB 126		Buried
39.793103	-120.650695	TFS	ped 1		Buried
39.936718	-120.942389	TFS	sb197		Buried
39.787519	-120.647991	TFS	afl		Buried
39.324211	-120.218886	TFS	P10		Buried
39.826923	-120.411029	TFS		79284	Buried
39.939126	-120.957965	TFS		52	Buried
39.874322	-120.863635	TFS	opp5511		Buried
39.877088	-120.864525	TFS		23	Buried
39.879585	-120.865338	TFS		23	Buried
39.882158	-120.868056	TFS		20	Buried
39.937391	-120.904578	TFS		8-Jul	Buried
39.87835	-120.47185	TFS	crnr ped		Buried
39.298147	-120.957363	TFS		17860	Buried
39.442417	-120.141437	TFS	Sb 126		Buried
39.91664	-120.85634	TFS	ped20		Buried
39.784793	-120.631894	TFS		23	Buried
39.95189	-120.887856	TFS	210 carol		Buried
39.951465	-120.888466	TFS	250 carol		Buried
39.951123	-120.889007	TFS	290 carol		Buried
39.950435	-120.890209	TFS		363	Buried
39.950574	-120.891869	TFS	476 carol		Buried
39.935773	-121.315618	TFS	p43		Buried
39.323622	-120.168087	TFS	so 18		Buried
39.323622	-120.168087	TFS	so 18		Buried

39.939735	-120.939449	TFS	93 lindan		Buried
39.871557	-120.471735	TFS		8060	Buried
39.32356	-120.168651	TFS	sb 23		Buried
39.323636	-120.16802	TFS	sb 18		Buried
39.950413	-120.891053	TFS	ped 438		Buried
39.951847	-120.89333	TFS	ped590		Buried
39.956567	-120.888715	TFS	ped1-17		Buried
39.245242	-120.95866	TFS		14508	Buried
39.273406	-121.003366	TFS	Lewis-Dow		Combo
39.946984	-121.046847	TFS	160 bk lk		Buried
39.800759	-120.473722	TFS	600 ridgew		Buried
39.328761	-121.11111	TFS	p75 Tyler		Combo
39.487007	-121.040822	TFS		1	Buried
39.937829	-120.938623	TFS	P25 main		Underground
39.938156	-120.938464	TFS	25 main		Underground
39.93829	-120.938363	TFS	25 main		Underground
39.442456	-121.073288	TFS	ped14		Buried
39.797156	-120.138208	TFS	ped20		Buried
39.934045	-121.315749	TFS	P43		Buried
39.950024	-121.302758	TFS	P31		Buried
39.939239	-120.946292	TFS	P200		Combo
39.916803	-121.101634	TFS	P51		Buried
39.918227	-121.103291	TFS	P51		Combo
39.491706	-121.276699	TFS	18558nyfla		Buried
39.762499	-120.225932	TFS	ped3		Buried
39.62787	-120.445627	TFS	P16		Combo
39.66294	-120.432889	TFS		2700	Combo
39.922684	-121.076622	TFS	P235		Combo
39.937568	-120.904453	TFS	10x golden		Underground
39.9184	-120.859178	TFS		2434	Buried
39.91559	-120.855139	TFS		2434	Buried
39.923897	-120.882716	TFS	760 laport		Buried
39.923438	-120.882068	TFS	Ped 1		Buried

39.9239	-120.882761	TFS	760 laport		Buried
39.774744	-120.627696	TFS	ped 573		Buried
39.772955	-120.625077	TFS	ped 15		Buried
39.933345	-121.315663	TFS	P43		Combo
40.007783	-121.230334	TFS	P11		Buried
40.019196	-121.07069	TFS	P13		Underground
40.019042	-121.070885	TFS	P13		Underground
39.995437	-121.27494	TFS	RPTR2		Buried
39.963927	-121.276171	TFS	RPTR5		Buried
39.951363	-121.301546	TFS	MMrkr 8.46		Buried
40.018829	-121.070739	TFS	P13		Underground
40.017105	-121.048385	TFS	P13		Underground
40.017682	-121.045078	TFS	P13		Underground
39.675178	-120.246691	TFS	ped 0.1		Buried
39.995763	-121.274679	TFS	RPTR2		Buried
39.952268	-120.959901	TFS	10x golden		Underground
39.950358	-121.301868	TFS	MM Ped 8.3		Buried
39.939779	-121.309676	TFS	MM ped 7.6		Buried
39.956641	-121.29332	TFS	MM ped 9.0		Buried
39.952408	-120.95992	TFS	24 golden		Buried
40.017869	-121.043614	TFS	P13		Buried
39.951601	-120.960352	TFS	P10x		Buried
39.952644	-120.96013	TFS	10x golden		Buried
40.018316	-121.043371	TFS	P13 Twain		Buried
39.322647	-120.16883	TFS	SP 79-9		Buried
39.956264	-121.292952	TFS	Ped 9.0		Buried
39.971372	-120.938348	TFS	ped 3-6		Buried
39.321598	-120.227456	TFS		12930	Underground
39.172684	-120.961761	TFS		14800	Buried
39.21308	-121.080427	TFS	63 Candy		Buried
39.920471	-120.865695	TFS	@1860		Buried
39.930101	-120.892674	TFS	ped180		Buried

40.009406	-121.228598	TFS	P20		Buried
39.80977	-120.234809	TFS	ped 1		Buried
39.903593	-120.750779	TFS		2116	Buried
39.327451	-120.168912	TFS		10040	Underground
39.982764	-120.998938	TFS	RPTR1		Buried
39.951474	-120.960377	TFS	MUX1		Buried
39.675685	-120.241791	TFS	SB54		
39.228017	-121.054888	TFS	41rockwood		Buried
39.937948	-120.914946	TFS	ped1		Buried
39.968017	-120.913312	TFS	P1		Buried
39.673797	-120.249976	TFS	R109		Buried
39.873906	-120.487113	TFS		6840	Buried
39.492316	-121.043455	TFS	ped3		Buried
39.488712	-121.044062	TFS	ped2		Buried
39.381927	-121.059216	TFS		10	Buried
39.984458	-121.282458	TFS	RPTR4		Buried
39.794724	-120.529485	TFS	ped 1		Buried
39.761756	-120.650332	TFS		1201	Buried
39.781318	-120.578764	TFS	ped6		Buried
39.791876	-120.534844	TFS	ped71799		Buried
39.820541	-120.234713	TFS	ped5		Buried
39.917766	-121.103142	TFS	P51		Buried
39.934144	-120.905931	TFS	CEV1		Buried
39.307892	-120.974768	TFS		118	Underground
39.79442	-120.530074	TFS	ped2		Buried
39.371628	-121.081469	TFS	ped		Buried
39.786064	-120.54585	TFS	ped1		Buried
39.984477	-121.282485	TFS	RPTR 4		Buried
39.991852	-121.280825	TFS	RPTR 3		Buried
39.992323	-121.2804	TFS	RPTR3		Buried
39.794614	-120.143107	TFS		93945	Buried
39.684129	-120.983743	TFS	p1		Buried
39.922532	-120.876846	TFS		1250	Buried
39.922549	-120.876323	TFS		1294	Buried
39.922486	-120.877427	TFS		1196	Buried
39.617509	-120.431246	TFS	ped2		Buried
39.865015	-121.149259	TFS	last 1 ped		Buried

39.709829	-120.994881	TFS	p27		Buried
39.817322	-120.342798	TFS	ped 2		Buried
39.449463	-121.283638	TFS	p16b8		Buried
39.709099	-120.972841	TFS		791	Buried
39.325231	-120.222587	TFS	SB 12047		
39.712637	-120.993885	TFS		2325	Buried
39.710264	-120.987241	TFS		1950	Buried
39.713542	-120.982074	TFS	p12		Buried
39.516931	-121.217258	TFS		10693	Buried
39.941944	-121.067972	TFS	P2 B3		Buried
40.014363	-121.088386	TFS	Ped4 Hwy70		Buried
40.0142	-121.089459	TFS	Ped2 Hwy70		Buried
40.014926	-121.087343	TFS	Ped4 Hwy70		Buried
40.01434	-121.090442	TFS	Ped1 Hwy70		Buried
39.777686	-120.659778	TFS	Ped 5 + 6		Buried
39.616998	-120.429891	TFS	Ped 132		Buried
39.683618	-120.656714	TFS	Ped1		Buried
39.9043	-120.794526	TFS	Ped1&2		Buried

TIX_CLOSEOUT_NARR

mm9751; Rehab f2 cable

sf8537; Respliced CA0106x176-200. Ped 2-5 e willow ;114 e willow. New pedestal installd

sf8537; Respliced cables at location,isolated CA5310 cable trouble to chipmunk rd,need another dig;trench job with conduit placement. Also respliced CA0319 100 pr ;200 pr at location-wet wrap.

sf8537; Replaced pedestal and rpr cable. Emergency locate ; crnr hwy49;89 sattley.
sf8537; Assisted dig crew to excavate and locate correct cable for section throw,conduit to be placed, cable on order.
mm9751; Remounted 1.1

sf8537; Isolated wet splice, need to section throw and place conduit,CA5310 x1-100
sf8537; Assisted dig crew placing conduit for cable trouble,CA5310; chipmunk rd ; mohawk vista dr. Waiting on cable order now.
mm9751; Remount 1.1 to wall
sf8537; Assisted construction on cable cut over,section throw;RPTR4 hwy 70 to Tobin. Assitedcoworker with cut over section throw on La Porte rd.
sf8537; Test assist in BLRSCA01 w CS2948, submit BPC markit app work, started First Aid training,asscist co worker;148 E Sierra, finished First Aid training.
sf8537; Rpr PED 5 E-O P 138 hwy 70, rmvd down drops ; 92200; 92013, 93899 hwy 70. Unable to perform section throw with BPC cable issue on job.
sf8537; BPC complete,encap wrap, needs one more for other end of trouble. Then input for dig to bury encap wraps.
mm9751; Resplice cable,place peds
mm9751; Resplice cable,placed new terminal

sf8537; Assist county road crew excavated and bury exposed cable.CA0102x76-100. Sheath work. Removed abandoned drop along hwy89 ;P3 s-o henry dotta rd.
mm9751; Placed cable respliced,place 2 peds
jc4378; Rpr ped

sf8537; No access repeater. Road closed. Checked water levels on Quincy C.O. Dryers.
sf8537; No access to repeater at this time road closed for season,will make new job in spring.
sf8537; Safety concern, large trees in area,extreme high winds today. Did other, rebuild compressor and training.
jc4378; Rpr ped
mm9751; Respliced cable,replaced ped
mm9751; Resplice cable,repair terminal
sf8537; Encap splices ready for ABWS dig to bury splice;culvert.
jc4378; Rpr ped case

jc4378; Rpr term
jc4378; Rpr term
jc4378; Rpr term
mm9751; Trouble isolation,cut f2 cable,located and marked
mm9751; Resplice cable replace terminal
jc4378; Rpr terminal
mm9751; Resplice cable,replace closure
jc4378; Rpr splice
;ek6957;PC-Y;Turned in box for replacement;TN:2761304
jc4378; Rpr ped
sf8537; Rehab work cmplete,prefield new service at 2080 Hwy 89,advsied
jc4378; Rpr splice
mm9751; Resplice cable,replace terminal
jc4378; Rpr splice
mm9751; Resplice cable replace terminal
jc4378; Rpr splice
mm9751; Respliced cable replaced terminal
ms7970; Refer dig it ;011811499 to replace brkn splice box banner lava cap rd;opalite.
Viewed in person.

mp8321; Pieced out 1 group,replaced serv term and extended case at 14406 penn ln
rd3541; Ticket made for construction
tv1972; Bpc, was completed, a pole was placed near box.
mm9751; Rprd defective splices
mm9751; Respliced cable splices rebuilt closure
mm9751; Respliced defective splices
mm9751; Rprd f2 cable splices
fr1292; Marked terminal and submitted dig up to have more space for section throw, i did
rehabbed;cleaned f2 ca 2005 101-200,.
ac1532; Removed all trees from cable and replaced broken drop
ac1532; Rep def case with new 9; case at p 1015 la Porte rd

sf8537; Wet buried span, applied compressor air to case in attempts to dry defective pairs.
sf8537; Section throw complet,ca5310x1-50,, temp cable removed and site clean
up.Keddie toll cable.
mm9751; Respliced cable,replaced terminal
;co1631;PC-N;Issue dig for broken lid, catch up on trng
mm9751; Repaired broken ped
mm9751; Repaired defective ped
sf8537; Rmvd abandoned drops, identifying air pressure structure at bbox to manhole or
side wlak box,creating new bpc job
sf8537; Air pressure readings good per PWEB site,monitored,cleaned truck cab at office,and
ordered material w supervisor.
ac1532; Rehab def buried splice

ac1532; Section throw complete at 17345 Indiana ranch rd
mm9751; Replaced cad 12 ped
sf8537; New pedestal placed with back post.
sf8537; Isolated trouble to ped4456 grizzley rd,multiple cable isssues found. Will create new for next location.
WET SPLICE LOCATED UNDER PED 11179 LAWRENCE.
SPLICED BURIED SPLICE,SECTION THROW BURIED TO PED SPLICED
RESPLICED BURIED SPLICE,PLACED PED
MS7970; REBUILD 50PR AERIAL CABLE, NEW TERM.
CABLE BONDING COMPLETED AFTER SECTION THROW.
RESPLICE CABLE,REPLACE BURIED CLOSURE
sf8537; Located and resplice bsw;8fl, raised

25PR SPLICE WET AND CORRODED IN BURIED SPLICE CASE. RINGBACK CABLE A FOOT ON EACH END TO EXPOSE GOOD COPPER CONDUCTORS. ARMOR PLATE HARD TO REMOVE.RESPLICE 25PR AND PIECE OUT. INSTALL NEW BURIED SPLICE CASE AND BOND CABLE. REBUILD COLLARS ON CABLE AND SEAL CASE. TORQUED BOLTS. FLASH CASE. NO LEAKS. ASSISTED TECH WITH JDSU METER AT CENTRAL OFFICE.
RPRCABLE PEDESTAL,ADVISED CUSTOMER BSW IN LOCATION,NEEDS TRENCH. FINISHED WEED WACKING AT R.T. SITE.
RESPLICE DEFECTIVE CABLE SPLICE
sf8537; New pedestal installed and pairs rehabed, CA0801x1-50
;SF8537;REBUILT SLPICE CA 0801 X 1-50

sf8537; Respliced and replaced multiple burn cable locations,replaced pedestal.
FIRE AREA,CABLE TROUBLE ISOLATI
CABLE TROUBLE ISOLAT
sf8537; Encap wrap complete and splice buried,
PEDESTAL REPLACEMENT, STAKE AND REGROUPED REBOND

tl5296; Complete splice rebuild, new case, new bmt, trbl corrected further down lead.
sf8537; Replaced pedestal with new-busted post.rehab pairs.

REMOVED SPLICE OFF TREE,AND INSTALLED PEDESTAL,RESPLICED F1 CABLE PAIRS.
mm9751; Respliced cable placed pedestal
mm9751; Respliced cable placed ped
mm9751; Respliced cable replaced ped
CABLE TROUBLE ISOLATION
CABLE TROUBLE ISOLAT
CABLE TROUBLE ISOLATION ...

PG6512; REBUILT 25 PAIR CABLE SPLICE, PLACED BMT, REMOVED BT ON DATA SERVICES PLACED AERIAL SLIC AT BBOX, BONDED CABLES, REMOVED CORROSION AT SB NEXT TO BBOX, TECH STILL NEEDS TO BUILD CASE AND PLACE TERMINAL,

RESPLICED CABLE IN PEDESTAL AT BIKE PATH AND ON LEVEE.
BSW ISSUE, PULLED NEW FROM PEDESTAL TO SPLICE BOX. PED7299 MARILYN.
CLOSED UP OPEN SPLICE CASE, REMOVED CORRODED CABLE, BONDED SHEATHING, ALL TESTS OK
ABLE TO PUT TOGETHER BMT, AND SPLICE IN BSW INTO BMT, SPLICE CASE STILL NEEDS TO BE BUILT AND SEALED
CABLE TROUBLE ISOLATION ...
CABLE TROUBLE ISOLATION
RESPLICE F2 CABLE REPLACE PED
WORKED ON ONLY PED THAT I COULD LOCATE BUT ADDRESS WAS DIFFERENT THAN TICKET
QB6851; RISER CABLE RESPLICED WITH NEW CASE
RESPLICE 03X1-100 151-175 276-300. NEEDS FURTHER REHAB TO COMPLETE. CREATED NEW JOB FOR FINISH.
SF8537; REMOVED B.T., CA0207X551-600 PED 601 RIDGEWOOD.
SM4953; RESKIN BOX COMPL
SM4953; PLACE PEDESTAL THAT WAS NEVER PLACED FROM OLD SECTION THROW
MM9751; REMOVE DEAD JUMPERS MAIN FRAME
MM9751; REMOVE DEAD JUMPERS MAIN FR
MM9751; RECONNECTED AERIAL DROP
DM820T; REHABBED 100 PAIR CABLE. CUT OUT DAMAGED SECTION AND PIECED OUT ALL 100 PAIRS. INSTALLED NEW PED.
SF8537; ,ADVISED MR KELLY 7757379330,CABLE LOCATED, SUB NEEDS TO EVALUATE CABLE AND DISCUSS WITH ENGINEERING A REARANGEMNET OPTION
MM9751; ISOLATED CABLE TROUBLE,MARKED AND LOCATED,200 FT BURIED 25 PR BURIED CABLE REPLACEMENT TO ORDER,PLACE DIG TICKET
MM9751; SPAN TROUBLE ISLOLATION
MM9751; DAMAGE CLAIM MM975120210524164417,REPLACED DAMAGED CABLE RESPLICED PLACED CLOSURES,NOTIFIED CONTRACTOR OSMOS JEREMY,ADVISED SUPERVISER WG2716
MM9751; CABLE TROUBLE IS
MM9751; ISOLATED SPAN TR
;ac1532; PC-N; Rehab def splice
SF8537; SPLICE WORK COMPLETE AND NEW PEDESTAL INSTALLD.
mm9751; mm9751; Resplice cable replace clo
MM9751; ISOLATED TROUBLE
MM9751; LOCATED DEFECTIVE SPLICE,RESPLICE SPLICE RESTORED SERVICE

sf8537; sf8537; cleared brush around 2 sub boxs,bbox,power meter, and fiber R.T.mux.
MM9751; ISOLATING SPAN TROUBLE
MM9751; SPAN TROUBLE ISOLA
sf8537; sf8537; splicing complete,ready for new case.Found with 51B3 closure open,pairs corroded.
mm9751; mm9751; isolated trouble sub box splice,wet

mm9751; mm9751; Resplice cable replace closure
mm9751; mm9751; Resplice cable
mm9751; mm9751; replaced 2 peds

mm9751; mm9751; isolated span trouble Dixie fire restoration,cal Tran damaged cable place guard rail fence,dig and claim supervisor notified wg2716

sf8537; sf8537; removed hazzard s left from previous digs with Dixie fire. USA paint for dig scheduled at mile marker 8.46, guard rail post in cable. Caltrans advised.
mm9751; mm9751; isolated cable trouble,placed wire by,restored hi caps to rt

mm9751; mm9751; isolated span trouble placed 25 Pr cable wire by hi caps special circuit
sf8537; sf8537; rpld asw to clearance pole,pedestal rehab, 5 ldial tones restored from Dixie fire damage. Work loc.= 32984 Hwy 70 x Hwy 89..
sf8537; sf8537; rehab RPTR5 &RPTR7 splices Hwy 70 to Tobin
sf8537; sf8537; section throw guard rail issue,claim submitting on 9-22-2021.
mm9751; mm9751; Dixie fire ,located damaged span,placed wire by

mm9751; mm9751; Dixie fire,isolated span trouble,placed wire by restored service to RT
mm9751; mm9751; isolated trouble in span
sf8537; sf8537; new ped installedsplice ok,did locate on wendril av.

sf8537; sf8537; rehab splice at RPTR2 and RPTR5 Hwy 70. Lots of traffic controls Hwy 70.
mm9751; mm9751; span trouble isolation
sf8537; sf8537; rehab splice at mile mrkr 8.3 Hwy70.
sf8537; sf8537; assisted in F1cable testing for trouble isolation.
mm9751; mm9751; isolated trouble sections in buried cable spans
mm9751; mm9751; span trouble is
mm9751; mm9751; isolated cable trouble Resplice cable at ped near repeater1
mm9751; mm9751; span trouble is
mm9751; mm9751; span trouble isolated
sf8537; sf8537; temp cable placed by construction, R.T. sites in service.
JQ2645; PLACE NEW CASE BMT
sf8537; sf8537; section throw completed,cable splice rehabed.
SF8537; REHAB SPLICE AND REPLACEPEDESTAL HARDWARE,
jh3145; Had to locate terminal under snow. Found that fiber connector had been repaired previously from construction technician.

DO1823; OLD CAD 8 WAS UNEARTHED WHEN POLE FELL DURING STORM, NEED NEW CAD 8 OR 12 PLACED, USA MARKED AND OLD PED COVERED AND SECURED, ABWS 14305001,
BK2151; NTF ON ATT FACILITIES OR CABLE OR TERMINAL,,,DRY SUB BOX,
SF8537; CA0801X1-50 REHAB.PED 1862 1724 RESPLICED.
SF8537; RESPLICED PED PAIRS,,SUPERVISOR MEETING AND TEMP DROP ON LA PORTE RD4080

SF8537; ASSESSED CABLE ISSUE ON HOWELLS RD, 13 JOINT POLES MISSING AND CABLE MISSING., CA0306X101-150
SF8537; SPLICE FROM OLD PEDESTAL, ENCAPPED WRAP AND BURIED
SF8537; RPR BSW CABLE ISSUE, LEFT FROM RETIRED COWORKER.
PG6512; REBUILT SPLICE CASE, OLD RE-ENTERABLE DEFECTIVE, TECH FOUND CORROSION IN SPLICE, CLEANED SPLICE AND SEALED CASE,

SF8537; KEDDIE CABLE WORK,MOVED SLOT 1 TO SLOT 21, AND SLOT 3 TO SLOT 22 RPTR6.
SF8537; ISOLATING CARRIER SPAN TROUBLE KEDDIE CABLE.
SF8537; PICTURES AND ABWS 014480060 SUBMITTED
qb6851; stealth back cable to fresh copper and consolidate works to a count
sf8537; cables bonded and splice organized,new ped installed w dig crew.
SF8537; SECTION THROW COMPLETE, ENCAP WRAPS COMPLETE. 0401X26-50
sf8537; conduit rodded and newbsw placed and buried,dtcpe,5309934148
SF8537; BSW PULLED AND CABLE SPLICE FIXED. CA0210X51-75.
jm1295; comp,couldnt find address on ticket,straighten 2 random pens on pen doll,transit to 26th street ticket taken away
qb6851; sheath back for fresh cable
pc9347; corroded splice resplice cable bond cable
sf8537; no access location,worked another job,(new terminalP13 Rush Creek.- new pole set).
sf8537; repliced cable,burntmodules.
sf8537; rprbsw,bonded,and rpr pedestals.
sf8537; new ped and post,repliced terminal.
sf8537; Rehab postponed until spring summer.
sf8537; rehab splices and installed new pedestals.
sf8537; system2 CONKLIN,SPAN THREE SHORT CLEARED,IN SERVICE.
sf8537;
Missing riser, installed riser
sf8537; Repliced cables, 0401x 1-50.
qb6851; rehab ticket completed
sf8537; uprighted pedestal and installed reinforcement post.
sf8537; rmvd string by,spliced repaeter tail,needs backfill RPTR4, new pedestal installed at RPTR3, new slot spliced in at RPTR7.
sf8537; section throw and repeater post and pedestal digs complete.
;cc2745; PC-N; Section throw on 25 pr ca. encapsulated splices
sf8537; new pedestal set,needs return for bonding and gravel.
;ac1532; PC-N; Rebuild def splice
sf8537; claim submitted,new conduit placed and cable pulled,temp rpr rmvd,need further bbox to cut tone assistance and encap wraps to bury.
sf8537; encap splice,ready to bury after section throw,dig set for 8-1.
sf8537; encap wrap ready for dig crew to bury.
sf8537; new pedestal set and support post.
sf8537; rpld pedestal and rpr splice.

;ac1532; PC-N; Rehab def splice
sf8537; Pedestals installed after section throw in culvert ditch.
;ac1532; PC-N; Rep def ped and Rep def riser cable
;ac1532; PC-N; Rep def ped

dd6738; repaired sub box lid. Loosened seized bolt and repaired locking mechanism for lid
;ac1532; PC-N; Rep def ped
;ac1532; PC-N; Replace def ped
;ac1532; PC-N; Rep damaged ped
ac1532; Replace def pedestal

sf8537; Rodded conduit,found trouble,pulled new bsw in, 5302839032, R. Davidson
sf8537; Respliced BKBH-75,carrier and f2 groups
sf8537; Repliced BHBH-75,carrier pairs and f2.
sf8537; Rehab splice and lowered closure.
sf8537; Rehab completed,also worked on 5302835301 and 5302831236

sf8537; New ped5 placed,splice work and bonding completePED4 &5 Johnsville rd.
sf8537; Recovered pedestal lid, found in ditch along Hwy49 89. Worked Sierraville c o and rd1 dryers.
sf8537; New pedestal placed and splice rehabed
sf8537; Bonded cables and cleaned up mess from past section throw. Also fire monitoring and work truck reloacted to Blairsden C.O.

FLD_COMP_NOTE	FLD_FORCE_TECH
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status. Package Manually Completed by jb2436.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status. All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537 MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status. All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537 MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status. All Wire/Work Jobs have Completed, Package now in Complete status. All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537 MM9751 MM9751
All Wire/Work Jobs have Completed, Package now in Complete status. All Wire/Work Jobs have Completed, Package now in Complete status. All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537 MM9751 JC4378
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status. All Wire/Work Jobs have Completed, Package now in Complete status. All Wire/Work Jobs have Completed, Package now in Complete status. All Wire/Work Jobs have Completed, Package now in Complete status. All Wire/Work Jobs have Completed, Package now in Complete status. All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537 JC4378 MM9751 MM9751 SF8537 JC4378

All Wire/Work Jobs have Completed, Package now in Complete status.	JC4378
All Wire/Work Jobs have Completed, Package now in Complete status.	JC4378
All Wire/Work Jobs have Completed, Package now in Complete status.	JC4378
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	JC4378
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	JC4378
All Wire/Work Jobs have Completed, Package now in Complete status.	EK6957
All Wire/Work Jobs have Completed, Package now in Complete status.	JC4378
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	JC4378
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	JC4378
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	JC4378
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	MS7970
All Wire/Work Jobs have Completed, Package now in Complete status.	MP8321
All Wire/Work Jobs have Completed, Package now in Complete status.	RD3541
All Wire/Work Jobs have Completed, Package now in Complete status.	TV1972
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	FR1292
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	CO1631
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532

All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	MS7970
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	JH3145
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	NH2812
All Wire/Work Jobs have Completed, Package now in Complete status.	TL5296
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
This package has been identified as being in a Fiber Overlay area.	PG6512
This package has been identified as being in a Fiber Overlay area.	PG6512

All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	PG6512
All Wire/Work Jobs have Completed, Package now in Complete status.	PG6512
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	JI2512
All Wire/Work Jobs have Completed, Package now in Complete status.	QB6851
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SM4953
All Wire/Work Jobs have Completed, Package now in Complete status.	SM4953
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	DM820T
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	AC1532
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751

All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	MM9751
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	JQ2645
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
Updating Actual Minutes on CIMI_RWM_01025907_01	JH3145
All Wire/Work Jobs have Completed, Package now in Complete status.	DO1823
All Wire/Work Jobs have Completed, Package now in Complete status.	BK2151
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537

All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	PG6512
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
Updating Actual Minutes on CIMI_RWM_01097827_01	QB6851
Updating Actual Minutes on CIMI_RWM_01144889_01	SF8537
All Wire/Work Jobs have Completed, Package now in Complete status.	SF8537
Updating Actual Minutes on CIMI_RWM_01163765_01	SF8537
Updating Actual Minutes on CIMI_RWM_01163770_01	SF8537
Updating Actual Minutes on CIMI_RWM_01176976_01	JM1295
Updating Actual Minutes on CIMI_RWM_01177417_01	QB6851
Updating Actual Minutes on CIMI_RWM_01191857_01	PC9347
Updating Actual Minutes on CIMI_RWM_01213445_01	SF8537
Updating Actual Minutes on CIMI_RWM_01221602_01	SF8537
Updating Actual Minutes on CIMI_RWM_01249473_01	SF8537
Updating Actual Minutes on CIMI_RWM_01249501_01	SF8537
Updating Actual Minutes on CIMI_RWM_01250198_01	SF8537
Updating Actual Minutes on CIMI_RWM_01255715_01	SF8537
Updating Actual Minutes on CIMI_RWM_01260360_01	SF8537
Updating Actual Minutes on CIMI_RWM_01260409_01	SF8537
Updating Actual Minutes on CIMI_RWM_01263927_01	VC6131
Updating Actual Minutes on CIMI_RWM_01264288_01	SF8537
Updating Actual Minutes on CIMI_RWM_01268274_01	QB6851
Updating Actual Minutes on CIMI_RWM_01275152_01	SF8537
Updating Actual Minutes on CIMI_RWM_01278824_01	SF8537
Updating Actual Minutes on CIMI_RWM_01278829_01	SF8537
Updating Actual Minutes on CIMI_RWM_01278833_01	CC2745
Updating Actual Minutes on CIMI_RWM_01283787_01	SF8537
Updating Actual Minutes on CIMI_RWM_01288967_01	AC1532
Updating Actual Minutes on CIMI_RWM_01292404_01	SF8537
Updating Actual Minutes on CIMI_RWM_01292405_01	SF8537
Updating Actual Minutes on CIMI_RWM_01292408_01	SF8537
Updating Actual Minutes on CIMI_RWM_01310923_01	SF8537
Updating Actual Minutes on CIMI_RWM_01317255_01	SF8537

Updating Actual Minutes on CIMI_RWM_01335365_01	AC1532
Updating Actual Minutes on CIMI_RWM_01356919_01	SF8537
Updating Actual Minutes on CIMI_RWM_01360775_01	AC1532
Updating Actual Minutes on CIMI_RWM_01366644_01	AC1532
Updating Actual Minutes on CIMI_RWM_01367429_01	DD6738
Updating Actual Minutes on CIMI_RWM_01369243_01	AC1532
Updating Actual Minutes on CIMI_RWM_01369245_01	AC1532
Updating Actual Minutes on CIMI_RWM_01370861_01	AC1532
Updating Actual Minutes on CIMI_RWM_01393280_01	AC1532
Updating Actual Minutes on CIMI_RWM_01452072_01	SF8537
Updating Actual Minutes on CIMI_RWM_01452074_01	SF8537
Updating Actual Minutes on CIMI_RWM_01452075_01	SF8537
Updating Actual Minutes on CIMI_RWM_01452076_01	SF8537
Updating Actual Minutes on CIMI_RWM_01452077_01	SF8537
Updating Actual Minutes on CIMI_RWM_01471228_01	SF8537
Updating Actual Minutes on CIMI_RWM_01471266_01	SF8537
Updating Actual Minutes on CIMI_RWM_01488494_01	SF8537
Updating Actual Minutes on CIMI_RWM_01507311_01	SF8537