SCN RESOLUTION & PHOTO

July 21, 2014

Version No: 3.2

Pole Number (Old Pole and New Pole, If Available)	Latitude/Longitude or Address	Noticing Company	Date Completed	Completed By
484440E	34.11289128-118.1688171	CC	2/22/2024	PWC

What is the issue/correction required?

Too Low at Midspan
Clearance at Midspan

Were corrections made per Crown Castle's request? **Yes** ☑ **No** ☐ (If 'No' please provide a detailed response below)

TV LOW AT MIDSPAN

Description of work performed.

ATTACHED CC @ 20'4" & 20'9", REMOVED TEMP DG, PLACED NEW DG, PLACED GG, RAISED OHG TO 21'9"

Before Photo #1	After Photo #1

SCN RESOLUTION & PHOTO

July 21, 2014

Version No: 3.2

Before Photo #2 (If Necessary)	After Photo #2 (If Necessary)

Before Photo #3 (If Necessary)	After Photo #3 (If Necessary)