

December 19, 2017

201712729

PUBLIC UTILITIES COMMISSION  
STATE OF CALIFORNIA  
ATTN: SAFETY AND ENFORCEMENT DIVISION  
320 W FOURTH STREET SUITE 500  
LOS ANGELES CA 90013

Re: Date of Incident: December 2, 2017  
Location of Incident: 750 Clyde River Place, Oxnard, CA

Ladies and Gentlemen:

In accordance with the reporting requirements set forth in Resolution E-4184, this letter supplements the notice Southern California Edison Company (SCE) provided to the Commission via the web-based reporting system on Saturday, December 2, 2017, at 5:59 p.m., regarding the above-referenced incident. SCE is required to submit this information pursuant to Commission instructions, resolutions and the Public Utilities Code, and submits this report under Public Utilities Code Section 315.

On December 2, 2017, at approximately 1:39 p.m., the Maulhardt 16 kV circuit out of Gonzalez Substation locked-out. Upon notice of the circuit lock-out, SCE personnel responded to 750 Clyde River Place, Oxnard, where they discovered a damaged underground primary cable consisting of 1/0 Aluminum Jacketed Cable (JCN). Witnesses on scene informed SCE personnel that employees of Baja Construction, working for and at the direction of McCarthy Companies on a carport construction project, had dug into and exposed the subject underground cable with an auger. The Baja Construction crew subsequently reported the incident to employees of Light & Power, Inc., an electrical contractor working on the project.

A short time later, ██████████, a foreman employed by Light & Power, Inc., approached the incident scene and began to examine the subject cable. He then used a hand-held cable cutter and cut into the exposed primary cable causing an electrical flash. Following the incident, ██████████ co-workers transported him to ██████████ in ██████████. After an examination at ██████████, ██████████ was transported by ambulance to the ██████████ for further treatment.

The SCE facilities involved in the incident consisted of a 1/0 Aluminum Jacketed Cable (JCN) underground primary cable. The involved facilities were part of the Maulhardt 16 kV circuit out of Gonzalez Substation.

It does not appear McCarthy Companies or Baja Construction contacted USA DigAlert prior to the excavation work. No USA markings were present at the incident location at the time of the occurrence. UtiliQuest is currently conducting an investigation into this incident.

The repairs to SCE facilities consisted of splicing in a new section of 1/0 Aluminum Jacketed Cable (JCN). At this time, the complete cost of repairs to SCE facilities has not been tabulated. SCE is unaware of any other property damage or injuries beyond which is reported in this letter.

Sincerely,

A solid black rectangular redaction box covering the signature area.

February 06, 2018

201712729

PUBLIC UTILITIES COMMISSION  
STATE OF CALIFORNIA  
ATTN: SAFETY AND ENFORCEMENT DIVISION  
320 W FOURTH STREET SUITE 500  
LOS ANGELES CA 90013

Re: Date of Incident: December 2, 2017  
Location of Incident: 750 Clyde River Place, Oxnard, CA

Ladies and Gentlemen:

In a letter dated December 19, 2017, SCE provided a follow up account as required by Commission instructions, resolutions and Public Utilities Code Section 315. Subsequent to this submission, SCE has been informed of a change in material fact concerning this incident and provides the following update.

In the December 19, 2017 letter, SCE reported the following:

*It does not appear McCarthy Companies or Baja Construction contacted USA DigAlert prior to the excavation work. No USA markings were present at the incident location at the time of the occurrence.*

SCE was recently advised by Digalert of an error in their research regarding the existence of a Digalert ticket for the subject location. According to Digalert, Baja Construction did notify Digalert of the excavation activity prior to the event. A copy of the correspondence and ticket supplied by Digalert to SCE is attached to this letter.

Notwithstanding this correction, no readily visible marks were observed by SCE after the incident occurred. Whether the marks were obscured by the "spoil" from the excavation itself, other construction activity at the site or other reason(s) is under review.

Sincerely,

[REDACTED]  
[REDACTED]

[REDACTED]

---

**From:** [REDACTED]  
**Sent:** Monday, January 29, 2018 8:19 AM  
**To:** [REDACTED]  
**Subject:** (External):Re: 750 Clyde River Pl  
**Attachments:** a173121598.pdf

[REDACTED]

On 12/4/2017, you sent a request to search our records from 5/1/2017 through 12/2/2017, for the address of 750 Clyde River Pl in Oxnard. Although DigAlert tickets were provided to you, DigAlert converted its archive database on 11/1/2017 which has led to some errors.

I am in the process of redoing request with a search date on or after 11/1/2017 and have found the attached DigAlert ticket A173121598 was not included in your results but was an active ticket for your time frame and location.

This ticket has already been submitted to the PUC.

I apologize for any inconvenience.

[REDACTED]  
Safety Director  
[REDACTED]  
[REDACTED]

MBRCOD 00000 USAS 11/08/17 16:28:28 A173121598-00A NORM NEW POLY

Ticket : A173121598 Date: 11/08/17 Time: 16:20 Oper: ADW Chan: 100  
Old Tkt: A173121598 Date: 11/08/17 Time: 16:20 Oper: ADW Revision: 00A

Company: BAJA CONSTRUCTION Caller: [REDACTED]  
Co Addr: 233 FOSTER ST  
City&St: MARTINEZ, CA Zip: 94553  
Phone: [REDACTED] Ext: [REDACTED] Call back: 7AM-5PM  
Formn: [REDACTED] Phone: [REDACTED]  
Email: [REDACTED]

State: CA County: VENTURA Place: OXNARD  
Delineated: Y  
Delineated Method: WHITEPAINT  
Address: 750 Street: CLYDE RIVER PL  
X/ST 1 : N VENTURA RD  
MPM 1: MPM 2:  
Locat: PARKING LOTS AT ADDRESS, WHICH IS RIVER PARK SENIOR LIVING APARTMENT  
: COMPLEX LOC ON S/COR/OF INTER/OF CLYDE RIVER PL & N VENTURA RD

Excav Enters Into St/Sidewalk: N

Grids:  
Lat/Long : 34.245800/-119.182105 34.243060/-119.178285  
: 34.243025/-119.184095 34.240285/-119.180276  
Caller GPS:

Boring: Y Explosives: N Vacuum: N  
Re-Mark: N

Work : INSTALL FOOTINGS FOR CARPORT  
Wkend: N Night: N  
Work date: 11/13/17 Time: 17:01 Hrs notc: 121 Work hrs: 020 Priority: 2  
Instruct : MARK BY Permit: NOT AVAILABLE  
Done for : MCCARTHY COMPANY

Tkt Exp: 12/06/17

Mbrs : ATDSOUTH OWDDIST OXN02 OXN03 SCG4UR USCE39 UTWCNW39  
UVZSTABAR VEN46DIST

IN-HOUSE CMMTS: TKT TIME: 07:30--[ADW 11/08/2017 16:28:28 192.168.4.137]

MBRCOD 00000 USAS 12/04/17 09:51:46 A173121598-01A NORM UPDT POLY

Ticket : A173121598 Date: 12/04/17 Time: 09:51 Oper: JRB Chan: 200  
Old Tkt: A173121598 Date: 11/08/17 Time: 16:20 Oper: ADW Revision: 01A

Company: BAJA CONSTRUCTION Caller: [REDACTED]  
Co Addr: 233 FOSTER ST  
City&St: MARTINEZ, CA Zip: 94553  
Phone: [REDACTED] Ext: [REDACTED] Call back: 7AM-5PM  
Formn: [REDACTED] Phone: [REDACTED]  
Email: [REDACTED]

State: CA County: VENTURA Place: OXNARD  
Delineated: Y  
Delineated Method: WHITEPAINT  
Address: 750 Street: CLYDE RIVER PL  
X/ST 1 : N VENTURA RD  
MPM 1: MPM 2:  
Locat: PARKING LOTS AT ADDRESS, WHICH IS RIVER PARK SENIOR LIVING APARTMENT  
: COMPLEX LOC ON S/COR/OF INTER/OF CLYDE RIVER PL & N VENTURA RD

Excav Enters Into St/Sidewalk: N

Grids:  
Lat/Long : 34.245799/-119.182105 34.243060/-119.178285  
: 34.243025/-119.184094 34.240285/-119.180274  
Caller GPS:

Boring: Y Explosives: N Vacuum: N  
Re-Mark: N

Work : INSTALL FOOTINGS FOR CARPORT  
Wkend: N Night: N  
Work date: 12/04/17 Time: 09:51 Hrs notc: 000 Work hrs: 000 Priority: 2  
Instruct : WORK CONTINUING Permit: NOT AVAILABLE  
Done for : MCCARTHY COMPANY

Tkt Exp: 01/01/18

COMMENTS

\*\*RESEND\*\*UPDATE ONLY-WORK CONT PER [REDACTED] [JRB 12/04/2017 09:51:38 AM]

Mbrs : ATTD SOUTH OWDDIST OXN02 OXN03 SCG4UR USCE39 UTWCNW39  
UVZSTABAR VEN46DIST

IN-HOUSE CMMTS: TKT TIME: 07:30--[ADW 11/08/2017 16:28:28 192.168.4.137]  
TKT TIME: 00:08--[JRB 12/04/2017 09:51:46 192.168.4.37]

MBRCOD 00000 USAS 12/04/17 10:45:45 A173121598-02A RUSH DMEX POLY

Ticket : A173121598 Date: 12/04/17 Time: 10:42 Oper: LAC Chan: 100  
Old Tkt: A173121598 Date: 11/08/17 Time: 16:20 Oper: ADW Revision: 02A

Company: BAJA CONSTRUCTION Caller: [REDACTED]  
Co Addr: 233 FOSTER ST  
City&St: MARTINEZ, CA Zip: 94553  
Phone: [REDACTED] Ext: [REDACTED] Call back: 7AM-5PM  
Formn: [REDACTED] Phone: [REDACTED]  
Email: [REDACTED]

State: CA County: VENTURA Place: OXNARD  
Delineated: Y  
Delineated Method: WHITEPAINT  
Address: 750 Street: CLYDE RIVER PL  
X/ST 1 : N VENTURA RD  
MPM 1: MPM 2:  
Locat: PARKING LOTS AT ADDRESS, WHICH IS RIVER PARK SENIOR LIVING APARTMENT  
: COMPLEX LOC ON S/COR/OF INTER/OF CLYDE RIVER PL & N VENTURA RD

Excav Enters Into St/Sidewalk: N

Grids:  
Lat/Long : 34.245799/-119.182105 34.243060/-119.178285  
: 34.243025/-119.184094 34.240285/-119.180274  
Caller GPS:

Boring: Y Explosives: N Vacuum: N  
Re-Mark: N

Work : INSTALL FOOTINGS FOR CARPORT  
Wkend: N Night: N  
Work date: 12/04/17 Time: 10:42 Hrs notc: 000 Work hrs: 000 Priority: 0  
Instruct : EXPOSED/UNCOVERED Permit: NOT AVAILABLE  
Done for : MCCARTHY COMPANY

Tkt Exp: 01/01/18

#### COMMENTS

\*\*RESEND\*\*UPDATE ONLY-WORK CONT PER [REDACTED]-[JRB 12/04/2017 09:51:38 AM]  
\*\*RESEND\*\*CALLER ADVISES OF AN EXPOSED LINE FROM TELEPHONE, STREET LIGHTS,  
TRAFFIC LIGHTS, ELECTRIC, CABLE TV, CITY, FIBER - CALLER REPORTING EXPOSED CABLE  
IN PARKING LOT OF ADDRESS\*\*CREW ONSITE\*\* PER [REDACTED]-[LAC 12/04/2017  
10:42:54 AM]

Mbrs : ATTD SOUTH OWDDIST OXN02 OXN03 SCG4UR USCE39 UTWCNW39  
UVZSTABAR VEN46DIST

IN-HOUSE CMMTS: TKT TIME: 07:30--[ADW 11/08/2017 16:28:28 192.168.4.137]  
TKT TIME: 00:08--[JRB 12/04/2017 09:51:46 192.168.4.37]  
TKT TIME: 02:51--[LAC 12/04/2017 10:45:45 192.168.4.141]