

March 15, 2023

Mr. Terence Eng Program Manager Gas Safety and Reliability Branch Safety and Enforcement Division California Public Utilities Commission 505 Van Ness Avenue San Francisco, CA 94102-3298

SUBJECT: General Order (G.O.) 112-F Inspection of Southwest Gas Company's Operation and Maintenance Procedures and Emergency Response Program Updates

Dear Mr. Eng,

Southwest Gas Corporation (Southwest Gas or Company) respectfully submits the attached response to the Summary of Inspection Findings of SED's General Order 112-F inspection of the Company's Operations and Maintenance Procedures and Emergency Response Program updates, which was conducted between January 23 and January 27, 2023.

Southwest Gas appreciates Staff's consideration of this matter. Please do not hesitate to contact me if there are any questions or concerns.

Sincerely,

Jerome T. Schmitz, P.E. Vice President, Engineering Staff

cc:

Kevin Lang Valerie Ontiveroz Dennis Lee, CPUC Victor Muller, CPUC Jason R. McMillan, CPUC Matthewson Epuna, CPUC Claudia Almengor, CPUC



GO 112-F Inspection of Southwest Gas Company's O&M Procedures and ER Program Updates Page 2 of 3

# **Post-Inspection Written Findings**

Date of Transmittal: 02/06/2023

Dates of Inspection: 1/23/2023-1/27/2023

**Operator: SOUTHWEST GAS CORP** 

Operator ID: 18536 (primary)

Assets (Unit IDs) with results in this report: Main Office (Specialized Inspections) (88373)

System Type: GD

Inspection Name: 2023 Southwest Gas (SWG) O&M/ER Updates (Distribution)

Lead Inspector: Victor Muller

Operator Representative: Laurie Brown

## **Unsatisfactory Results**

### No Preliminary Findings.

### Concerns

#### A. <u>Maintenance and Operations : ROW Markers, Patrols, Leakage Survey and</u> <u>Monitoring (MO.RW)</u>

Question Title, ID Distribution Leakage Surveys, MO.RW.DISTLEAKAGE.P (also presented in: PD.RW)
Question 10. Does the process require distribution system leakage surveys to be conducted?
References 192.723(a) (192.723(b))
Assets Covered Main Office (Specialized Inspections) (88373 (30))

Issue Summary California General Order (GO) 112F, subpart 143.2(c)(1) states, "Each Operator must reevaluate Grade 3 leaks during the next scheduled survey, or within fifteen months of the reporting date, whichever occurs first. Thereafter, the leak must be



GO 112-F Inspection of Southwest Gas Company's O&M Procedures and ER Program Updates Page 3 of 3

reevaluated every calendar year, not to exceed 15 months until the leak is repaired, regraded or no longer results in a reading."

Section 1.6.5 of SWG's Office of Pipeline Safety (OPS) - Leak Survey Procedure provides SWG's standards for follow-up on aboveground Grade 3 leaks stating, "Class 3 leaks must be repaired within 12 months, not to exceed 15 months, from the date of discovery".

SWG has no reevaluation procedures for aboveground Grade 3 leaks. Therefore, SWG's procedures should require the repair of any aboveground Grade 3 leaks before a reevaluation would be required by GO-112F. A survey could be scheduled or may be required by Title 49 CFR Part 192 to be completed, prior to 15 months after the discovery of an aboveground Grade 3 leak. SED recommends that SWG revise section 1.6.5 of SWG's OPS - Leak Survey Procedure to ensure that a reevaluation required by GO 112F, subpart 143.2(c)(1) is not missed.

Southwest Gas Response:

Southwest Gas acknowledges SED's recommendation and is currently reviewing the Leak Survey Procedure, Section 1.6.5, for revision to include a reevaluation requirement to ensure compliance with GO 112F. A revision to the procedure will be included in the third quarter Operations Manual release in September 2023.