

From: USRB
Sent: Tuesday, October 31, 2017 3:10 PM
To: SED-Gas Section-South; SED-Gas Section-North; TerKeurst, Charlotte; Palmer, Leslie L.; SED-Electric Safety and Reliability Branch - North; SED-Electric Safety and Reliability Branch - South
Subject: FW: Electric Safety Incident Reported- PG&E Incident No: 171031-8606

From: webmaster@cpuc.ca.gov
Sent: Tuesday, October 31, 2017 3:09:36 PM (UTC-08:00) Pacific Time (US & Canada)
To: USRB
Cc: meae@pge.com
Subject: Electric Safety Incident Reported- PG&E Incident No: 171031-8606

The Following information regarding this incident has been reported:

Reporting Date: 10/31/2017 3:05:09 PM
Incident Date: 10/8/2017 @ 10:00 p.m.
Reported By: Meredith Allen, Sr. Director
Utility Name: PG&E
Phone Number: (415)973-2868
Email Address: meae@pge.com

Incident Location: near Fused Cutout 15877 Glen Ellen, Sonoma

Reasons For Reporting:

- Fatalities? No (Utility: , Others:)
- Names of Fatalities:
- Injuries? (Utility: , Others:)
- Names of Injured:
- Damage? Yes (Utility: , Others:)
- Interruption? (Total Customers: , Total Hours:)
- Operator Judgement? No
- Media Coverage? No

Cause of Incident: Other (Other Cause:)

Agencies on Scene:

Facilities Affected:

- Utilities Facilities: Dunbar 1101
- Voltage (KV): 12
- Customer's Facilities:

DigIn Information:

- Excavator Name:
- Contact:
- Phone: (____)____ - _____

Incident Recovery:

- On Scene Date & Time: @ 00:00 a.m.
- Service Restored: @ 00:00 a.m.

Summary: On October 18, 2017, near Glen Ellen, Sonoma County, PG&E identified downed primary conductors near Fused Cutout 15877 on the Dunbar 1101 12 kV Circuit. PG&E's meteorology department determined that there were wind gusts in the area up to 58 m.p.h. prior to the event. PG&E notified CalFire, and CalFire has investigated and released the site on October 19, 2017. CalFire did not request any PG&E assets. PG&E subsequently collected the downed conductors on October 20, 2017. This information is preliminary and PG&E is fully cooperating with CalFire.