

Kyo, Richard

From: USRB
Sent: Thursday, May 15, 2014 6:15 AM
To: SED-Gas Section-South; SED-Gas Section-North; SED-Electric & Communication-South; SED-Electric & Communication-North; Beck, Valerie
Subject: FW: Electric Safety Incident Reported - Incident No: 140515-6274

From: webmaster@cpuc.ca.gov
Sent: Thursday, May 15, 2014 6:14:53 AM (UTC-08:00) Pacific Time (US & Canada)
To: USRB
Cc: paul.pimentel@sce.com
Subject: Electric Safety Incident Reported - Incident No: 140515-6274

The Following information regarding this incident has been reported:

Reporting Date: 5/15/2014 6:07:54 AM
Incident Date: 5/15/2014 @ 3:14 a.m.
Reported By: Paul C. Pimentel, Investigations Manager
Utility Name: Southern California Edison Company
Phone Number: 626-695-4705
Email Address: paul.pimentel@sce.com

Incident Location: 6439 Danby Whittier, Los Angeles County

Reasons For Reporting:

- Fatalities? Yes (Utility: 0, Others: 1)
- Names of Fatalities: Unknown
- Injuries? No (Utility: 0, Others: 0)
- Names of Injured:
- Damage? No (Utility: 0, Others: 0)
- Interruption? No (Total Customers: 0, Total Hours: 0)
- Operator Judgement? No
- Media Coverage? No

Cause of Incident: Unknown (Other Cause:)

DigIn Information (if applicable):

- Excavator Name:
- Contact:
- Phone:

Agencies on Scene:

Facilities Affected:

- Utility's Facilities: Bronco
- Voltage (KV): 12 kV
- Customer's Facility:

Incident Recovery:

- On Scene Date & Time: @ 00:00 a.m.
- Service Restored (Date & Time): @ 00:00 a.m.

Summary: Preliminary information indicates an unidentified male individual sustained fatal injuries after contacting a downed primary conductor at the subject location. The investigation into the incident is ongoing.