

Jose Moran Senior Advisor

December 12, 2023 202310743

VIA EMAIL ONLY

PUBLIC UTILITIES COMMISSION STATE OF CALIFORNIA ATTN: JASDEEP LALLY – WILDFIRE SAFETY ENFORCEMENT BRANCH 505 VAN NESS AVENUE SAN FRANCISCO CA 94102-3298

Re: Date of Incident: Location of Incident:

November 9, 2023 Landon Drive, Jurupa Valley, California

Dear Jasdeep Lally:

In accordance with the reporting requirements set forth in Resolution E-4184, this letter supplements the notice Southern California Edison Company (SCE) provided to the Commission via the web-based emergency reporting system on Thursday, November 9, 2023, at 2:29 p.m. regarding the above-referenced incident. SCE is required to submit this information pursuant to Commission instructions, resolutions and the Public Utilities Code, and submits this report under Public Utilities Code Section 315.

On November 9, 2023, at 5:53 a.m., the Riverside County Fire Department (RCFD), notified SCE of a downed pole and wire associated with a brush fire in the Jurupa Valley area. SCE personnel responded to the scene and observed Pole No. 1714303E had been vandalized and exhibited damage as if it had been intentionally cut down. Two No. 4 solid copper overhead primary conductors supported by Pole No. 1714303E were also downed. Our personnel also observed what appeared to be a blade-like object near the base of Pole No. 1714303E. The Landon Fire burned approximately 36 acres of open field before it was extinguished by fire personnel.

Pole No. 1714303E supported overhead electrical facilities on the Bellgrave 12 kV Circuit out of Bain Substation. Although there was no circuit relay activity, our personnel determined two fuses operated at Pole No. 4826125E which is upstream from the damaged pole location.

Repairs to the involved SCE facilities consisted of replacing Pole No. 1714303E and approximately 400-feet of No. 4 solid copper primary overhead conductors were replaced with 1/0 ACSR overhead primary conductors, three 30-amp SMU fuses were replaced at Pole No. 4826125E, and an H-Frame structure consisting of Pole Nos. 2446885E and 2346884E in the burn area that sustained fire damage was replaced.

Public Utilities Commission December 12, 2023 Page 2 of 2

SCE is unaware of any additional property damage or injuries as a result of this incident.

Sincerely,

Jose Moran