JACKIE SPEIER

211 CANNON HOUSE OFFICE BUILDING WASHINGTON, DC 20515-0512 (202) 225-3531 FAX: (202) 226-4183 400 S. EL CAMINO REAL, SUITE 410 SAN MATEO, CA 94402 (650) 342-0300 FAX: (650) 375-8270 WWW.SPEER.HOUSE.GOV

Congress of the United States House of Representatives Washington, DC 20515-0512

COMMITTEE ON FINANCIAL SERVICES

SUBCOMMITTEES: CAPITAL MARKETS, INSURANCE AND GOVERNMENT SPONSORED ENTERPRISES FINANCIAL INSTITUTIONS AND CONSUME CREDIT OVERSIGHT AND INVESTIGATIONS

COMMITTEE ON OVERSIGHT AND GOVERNMENT REFORM

> SUBCOMMITTEE: GOVERNMENT MANAGEMENT AND ORGANIZATION PROCUREMENT

SELECT COMMITTEE ON ENERGY INDEPENDENCE AND GLOBAL WARMING

April 1, 2011

Mr. Paul Clanon, Executive Director California Public Utilities Commission 505 Van Ness San Francisco, CA 94102-3298

APR 04 2011

EXECUTIVE DIRECTOR'S OFFICE

Re: Proposals for Natural Gas Transmission Line Safety

Dear Mr. Clanon:

I appreciate the fact that the CPUC is holding a public hearing on adopting "New Safety and Reliability Regulations for Natural Gas Transmission and Distribution Pipelines and Related Ratemaking Mechanisms" in San Bruno. The residents here had their lives inalterably changed on September 9, 2010 by the rupture of an aging gas pipeline operated by PG&E. Their concerns are my concerns and to that extent, I offer the following proposals to improve consumer safety in the delivery of natural gas by any and all operators subject to regulation by the CPUC:

- Require that operators disclose the location of transmission pipelines to any and all first
 responders. Such disclosure shall be in person to insure the information is received and
 understood. Additionally, the operator and the first responders shall exchange and
 maintain emergency contact information and emergency response plans to be used in case
 of a natural gas leak and/or fire. Operators should make annual contact with first
 responders to insure that all exchanged information is current.
- Require that operators disclose to customers the fact that they reside or work within 2,000
 feet of a natural gas transmission line. Require that this notice be done annually and
 include contact information for reporting suspected gas leaks.
- Require the CPUC to establish a statewide database of pipelines removed from service. This database shall contain the following information provided by the operator: the reason for the removal; the condition of the pipe, including the condition of welds, its age, and the name of the manufacturer. The CPUC shall use the database to identify any emerging trends such as excessive corrosion or stress fractures specific to a manufacturer.
- Require installation of automatic, or remote control shut-off valves every five miles in lines that are in high consequence areas, or that run along an earthquake fault.

JACKIE SPEIER 12TH DISTRICT, CALIFORNIA

211 CANNON HOUSE OFFICE BUILDING WASHINGTON, DC 20515-0512 (202) 225-3531 FAX: (202) 226-4183 400 S. EL CAMINO REAL, SUITE 410 SAN MATEO, CA 94402 (650) 342-0300 FAX: (650) 375-8270 WWW, SPEIER, HOUSE, GOV

Congress of the United States House of Representatives Washington, DC 20515-0512

SUBCOMMITTEES: CAPITAL MARKETS, INSURANCE AND GOVERNMENT SPONSORED ENTERPRISES FRANCIAL INSTITUTIONS AND CONSUMER CREDIT OVERSIGHT AND INVESTIGATIONS

COMMITTEE ON OVERSIGHT AND GOVERNMENT REFORM

> SUBCOMMITTEE: GOVERNMENT MANAGEMENT AND ORGANIZATION PROCUREMENT

- Require the CPUC to audit the integrity management plans of all operators every two years. Audit exceptions that are deemed critical shall be responded to within 24 hours place and while all other exceptions must be responded to within 30 days.
- Make it clear that an operator may not maintain historical MOAPs by intentional spiking
 of pressure to or beyond the MOAP level.
- If an operator does not have documentation that a pipeline segment has been pressure tested, then one of the following must occur: reduce pressure 20%; hydro-test; or replace.
- · Establish a rule for the duration of pressure test.
- Define the "most conservative value" to be assigned to any segment of pipeline that does not have a record of being pressure tested.
- An operator shall report to the CPUC any increase over MOAP within 24 hours.
- Require every operator to provide a replacement plan for any pipeline installed prior 1961 in a high consequence area. Each plan shall contain a timeframe for replacement beginning with the highest risk pipeline and descending to the lowest risk pipeline. The plan shall contain an estimated cost of replacement.
- Require that all pipe sold by Consolidated Western be inspected and tested, or replaced.
- Promulgate a rule for how the age of a pipeline shall be considered a risk factor and how the inability to utilize internal inspection equipment increases risk as a pipe ages.
- Increase CPUC's funding to provide for more inspectors.

All the best,

Jackie Speier Member of Congress