

From: USRB
Sent: Saturday, August 01, 2015 1:12 PM
To: SED-Gas Section-South; SED-Gas Section-North; SED-Electric & Communication-South; SED-Electric & Communication-North; Beck, Valerie; TerKeurst, Charlotte
Subject: FW: Electric Safety Incident Reported - Incident No: 150801-7888
Categories: Incidents

From: webmaster@cpuc.ca.gov
Sent: Saturday, August 01, 2015 1:11:58 PM (UTC-08:00) Pacific Time (US & Canada)
To: USRB
Cc: [REDACTED]
Subject: Electric Safety Incident Reported - Incident No: 150801-7888

The Following information regarding this incident has been reported:

Reporting Date: 8/1/2015 12:55:18 PM
Incident Date: 8/1/2015 @ 9:36 a.m.
Reported By: [REDACTED]
Utility Name: Southern California Edison Company
Phone Number: [REDACTED]
Email Address: [REDACTED]

Incident Location: Near Desert Knoll/Valley Vista Twenty-Nine Palms, San Bernardino County

Reasons For Reporting:

- Fatalities? No (Utility: 0, Others: 0)
- Names of Fatalities:
- Injuries? Yes (Utility: 0, Others: 2)
- Names of Injured: Unknown
- Damage? No (Utility: 0, Others: 0)
- Interruption? No (Total Customers: 0, Total Hours: 0)
- Operator Judgement? No
- Media Coverage? No

Cause of Incident: Unknown (Other Cause:)

DigIn Information (if applicable):

- Excavator Name:
- Contact:
- Phone:

Agencies on Scene:

Facilities Affected:

- Utility's Facilities: North Adobe
- Voltage (KV): 12 kV
- Customer's Facility:

Incident Recovery:

- On Scene Date & Time: @ 00:00 a.m.
- Service Restored (Date & Time): @ 00:00 a.m.

Summary: SCE submits this report as the subject incident may involve a fatality or personal injury rising to the level of in-patient hospitalization. Preliminary information indicates two unidentified male individuals were riding motorcycles and contacted overhead electrical facilities and sustained injuries. It was reported that one of the subjects was airlifted from the scene to [REDACTED] and the other was transported from the site [REDACTED]. At this time the nature and extent of the injuries are unknown. Our information indicates the North Adobe 12 kV circuit out of Twenty-Nine Palms Substation relayed and locked-out beyond RAR 0256 at 9:36 a.m. The investigation into the incident is on-going.