

From: USRB
Sent: Monday, October 16, 2017 10:02 PM
To: SED-Gas Section-South; SED-Gas Section-North; TerKeurst, Charlotte; Palmer, Leslie L.; SED-Electric Safety and Reliability Branch - North; SED-Electric Safety and Reliability Branch - South
Subject: FW: Electric Safety Incident Reported- PG&E Incident No: 171016-8576

From: webmaster@cpuc.ca.gov
Sent: Monday, October 16, 2017 10:01:53 PM (UTC-08:00) Pacific Time (US & Canada)
To: USRB
Cc: ldttd@pge.com
Subject: Electric Safety Incident Reported- PG&E Incident No: 171016-8576

The Following information regarding this incident has been reported:

Reporting Date: 10/16/2017 9:59:54 PM
Incident Date: 10/9/2017 @ 1:00 a.m.
Reported By: Laxmi Terala, Compliance Specialist, Expert
Utility Name: PG&E
Phone Number: (925)768-6603
Email Address: ldttd@pge.com

Incident Location: 1210 Nuns Canyon Road Glenn Ellen, Sonoma

Reasons For Reporting:

- Fatalities? No (Utility: , Others:)
- Names of Fatalities:
- Injuries? (Utility: , Others:)
- Names of Injured:
- Damage? Yes (Utility: , Others:)
- Interruption? (Total Customers: , Total Hours:)
- Operator Judgement? No
- Media Coverage? No

Cause of Incident: Other (Other Cause:)

Agencies on Scene:

Facilities Affected:

- Utilities Facilities:
- Voltage (KV):
- Customer's Facilities:

DigIn Information:

- Excavator Name:
- Contact:
- Phone: (____)____-____

Incident Recovery:

- On Scene Date & Time: @ 00:00 a.m.
- Service Restored: @ 00:00 a.m.

Summary: This afternoon near Glen Ellen in Sonoma County, PG&E identified a tree whose top broke and fell on an open wire secondary service to 1210 Nuns Canyon Road. The alder tree was rooted approximately 30 feet from the overhead secondary distribution conductors. PG&E's meteorology department determined that there were wind gusts in the area up to 58 m.p.h. prior to the event. CalFire has taken possession of the secondary conductors. This information is preliminary and PG&E is fully cooperating with Cal Fire.