

Source: Aspen 2015 and SCE 2014

0 0.25 0.5 Miles

Existing Substation
Impact Corridor
Survey Area

Vegetation Community/Land Cover Type

Agriculture
Diegan Coastal Sage Scrub
Disturbed / Ruderal Habitat
Disturbed Wetland
Mulefat Scrub
Non-native Grassland
Nonnative Woodland/Ornamental
Open Water
Southern Willow Scrub
Urban / Developed

Figure C.5-1a
Map A
Vegetation and Cover Types