



5020 Chesebro Road, Suite 200, Agoura Hills, CA 91301-2285 Tel. 818-597-3407, Fax 818-597-8001, www.aspeneg.com

PROJECT MEMORANDUM PG&E WINDSOR SUBSTATION PROJECT

To: Eric Chiang, Project Manager, CPUC
From: Vida Strong, Aspen Project Manager
Date: November 2, 2017
Subject: Monitoring Report #38 – October 23, 2017 to October 29, 2017

This report provides a summary of the construction and compliance activities associated with the PG&E Windsor Substation Project which includes the construction of the Windsor Substation, as well as 12 kV distribution line underbuild and reconductoring work (see Exhibit A).

A summary of the Notices to Proceed (NTPs) for construction and Minor Project Change (MPC) activities are provided in Tables 1 and 2, respectively (below).

CPUC Environmental Monitor (EM): Jody Fessler was on site October 27.

Windsor Substation Site

NTP #1 was issued on June 15, 2016 for the Windsor Substation component of the Project, located at 10789 Old Redwood Highway in the Town of Windsor. NTP #1 included conditions that had to be satisfied prior to the start of construction. PG&E was allowed to start vegetation clearing and tree trimming prior to receiving their grading permit from the Town of Windsor. PG&E received the grading and building permits from the Town of Windsor on November 14, 2016, and minimal construction activities started thereafter. During the 2016/2017 rainy season, heavy rains and saturated conditions precluded construction activities at the Windsor Substation site for the majority of the season. Construction activities started back up in April 2017.

Summary of Activity:

Crews worked at the Windsor Substation site Monday through Sunday to make up for the time they were not able to work due to the wildfires earlier in the month.

Conduit trenches for the distribution line were excavated, conduit installed to pull boxes, and the trenches backfilled on the northern side of the switchgear building (see Figure 1).

Deliveries of base rock and sand occurred for the build-up of the substation pad to grade and for around the SPCC pond.

Crews poured concrete for the SPCC pond and continued to backfill and compact engineered fill around the pond (see Figures 2 and 3).

The transformer and some of the dead-end structures were painted green (see Figure 4).

At the time of the CPUC EM's site visit on October 27, crews were excavating conduit trenches on the north side of the switchgear building, and backfilling and compacting engineered fill around the SPCC pond.

Environmental Compliance:

 PG&E's Environmental Inspector (EI), conducted an inspection and monitoring on October 23. Approximately 120-foot section of the western perimeter silt fence was moved 1 to 3 feet towards the wetland to facilitate equipment access along the SPCC pond's western wall and was monitored by the PG&E EI. No impacts to wetlands occurred. Ongoing surveys for special-status species were performed. No special-status species were observed.

2. The CPUC EM noted that the site was neat and clean. Silt fencing was installed around the wetland areas on the west and south sides of the substation site, and was in good working condition. Environmentally Sensitive Area fencing was also installed around oak trees for protection. Soil piles that were not active were covered with plastic and surrounded by fiber rolls. Drainage inlets were protected with fiber rolls and gravel bags. Watering of the site for dust control was observed. Traffic control signs were setup along Old Redwood Highway near the substation entrance and exit. The site was in compliance with mitigation measures, Applicant Proposed Measures, and other permit requirements.

12 kV Distribution Line Underbuild and Reconductoring Work

NTP #2 for the 12 kV distribution line underbuild and reconductoring work was issued by CPUC on March 30, 2017. Work along Old Redwood Highway began July 5, 2017. Work along the Fulton No. 1 line began on September 12, 2017.

Summary of Activity:

No work occurred along Old Redwood Highway or the Fulton No. 1 line during the subject weeks.

Environmental Compliance:

- 1. The PG&E EI did not conduct an inspection along Old Redwood Highway or the Fulton No. 1 line during the subject week since no construction activities were occurring.
- 2. The CPUC EM did not conduct monitoring along Old Redwood Highway or the Fulton No. 1 line during the subject week since no construction activities were occurring.

Notices to Proceed (NTPs)

Table 1 summarizes the Notices to Proceed (NTPs) for the Windsor Substation Project.

NTP #	Date Requested	Date Issued	Phase	Description
NTP #1	5/17/16	6/15/16	Windsor	Windsor Substation component of the
			Substation	Project.
NTP #2	2/17/17	3/30/17	Reconductoring & 12 kV Line Underbuild	Rebuild a segment of the Fulton No. 1 power line to hold a new double-circuit 12 kilovolt (kV) distribution line underbuild, and reconductoring an existing distribution line along Old Redwood Highway.

Table 1 Notice to Proceeds (NTPs) (Updated 11/02/17)


Minor Project Changes (MPCs)

Table 2 summarizes the Minor Project Changes (MPCs) submitted for the Windsor Substation Project.

Table 2 Minor Project Changes (MPCs) (Updated 11/02/17)

MPC #	Date Requested	Date Issued	Phase	Description
MPC #1	5/17/16	6/15/16	Windsor Substation	Design change to Spill Prevention Control and Countermeasure (SPCC) retention pond and stormwater flow. MPC #1 was incorporated into NTP #1.
MPC #2	5/17/16	6/15/16	Windsor Substation	Use of water truck or driwater pods instead of irrigation system for landscaping. MPC #2 was incorporated into NTP #1.
MPC #3	5/17/16	6/15/16	Windsor Substation	Replacement of culverts in existing roadways entering substation site and Herb Lane. MPC #3 incorporated into NTP #1.
MPC #4	8/11/16	8/19/16	Windsor Substation	Revision of the Conceptual Landscape Plan based on final design and engineering.
MPC #5	2/17/17	3/30/17	Reconductoring & 12 kV Line Underbuild	Use of crane staged on SMART tracks to replace certain poles along the Fulton No. 1 Power Line submitted with NTP Request #2.
MPC #6	2/17/17	3/30/17	Reconductoring & 12 kV Line Underbuild	Final design and engineering revision to the tubular steel pole (TSP) west of the substation submitted with NTP Request #2.
MPC #7	2/1717	3/30/17	Reconductoring & 12 kV Line Underbuild	Changes to tree trimming and removal due to construction method changes (crane use on SMART tracks) submitted with NTP Request #2.
MPC #8	2/17/17	3/30/17	Reconductoring & 12 kV Line Underbuild	Additional pull and tension site located on Railroad Avenue between Poles a32 and a33 submitted with NTP Request #2.
MPC #9	6/05/17	6/22/17	Reconductoring & 12 kV Line Underbuild	Reconfiguration of distribution line crossing of Old Redwood Highway and pole changes.
MPC #10 Revised	8/15/17	9/12/17	Additional Staging Area	Additional temporary staging area at southeast corner of Windsor River Road and Windsor Road in Windsor.

EXHIBIT A – CONSTRUCTION STATUS



PROJECT PHOTOS



Figure 1 – Conduit trenching on north side of switchgear building – view west, October 27, 2017.



Figure 2 – Backfilling and compacting around SPCC pond – view south, October 27, 2017.



Figure 3 – Equipment moving backfill to west side of SPCC pond – view northwest, October 27, 2017.



Figure 4 – Transformer painted green – view south, October 27, 2017.