

PUBLIC UTILITIES COMMISSION

505 VAN NESS AVENUE
SAN FRANCISCO, CA 94102-3298



December 2, 2013

Melvin Stark
Manager, Maintenance & Inspection
Southern California Edison (SCE)
3 Innovation Way
Pomona, CA 91768

EA2013-012

SUBJECT: Audit of SCE's Fullerton District

Dear Mr. Stark:

On behalf of the Electric Safety and Reliability Branch of the California Public Utilities Commission, Zelalem Ewnetu and Derek Fong of my staff conducted an audit of SCE's Fullerton District from October 7, 2013 to October 11, 2013. The audit included a review of SCE's records and field inspections of SCE's facilities.

During the audit, my staff identified violations of one or more General Orders. A copy of the audit summary itemizing the violations is enclosed. By January 10, 2014 please advise me of all corrective measures taken by SCE to remedy and prevent such violations.

If you have any questions, you can contact Zelalem Ewnetu at (213) 576-7042 or ze1@cpuc.ca.gov.

Sincerely,

A handwritten signature in dark ink, appearing to read "Raymond G. Fugere".

Raymond G. Fugere, P.E.
Program & Project Supervisor
Electric and Communication Facility Safety Section
Safety and Enforcement Division

Enclosure: Audit Summary

Cc: Elizaveta Malashenko, Deputy Director, Safety and Enforcement Division
Fadi Daye, P.E., Senior Utilities Engineer Supervisor, CPUC – LA

AUDIT SUMMARY

The following violations were not documented and/or addressed by SCE during its last detailed inspection as required by General Order 165:

1.	Location:	Pole Number 1267211E
	Previous SCE Visit Details:	08/08/2013
	Date of CPUC Inspection:	10/08/13
Explanation of Violation(s):		
<p><u>Conductor Clearance</u></p> <p style="text-align: center;"><i>GO 95, Table 2, Case 18-C, requires utilities to maintain three inch separation between supply guy wires and communication wires.</i></p> <p>Communication service drop and a guy wire were touching.</p>		

2.	Location:	Pole Number 874982
	Previous SCE Visit Details:	03/06/13
	Date of CPUC Inspection:	10/08/13
Explanation of Violation(s):		
<p><u>Conductor Clearance</u></p> <p style="text-align: center;"><i>GO 95, Table 2, Case 18-C, requires utilities to maintain three inch separation between supply guy wires and communication wires.</i></p> <p>Communication service drop and a guy wire were touching.</p>		