Loc	RWM Pkg#	Pole	Issue Description (PUC Eng)	Address	City	Lat	long	Completed	Closure/ Notification Date
76	<b>11299638</b>	2084496E	ground moulding on each of the following poles was damaged:	137 N Joy St	Corona	33.88051	-117.559387	х	7/25/2023
71	11299637	11256J	ground moulding on each of the following poles was damaged:	2825 5th St	Fontana (Riverside)	33.9802742	-117.3623581	х	7/25/2023
43	11299634	4757445E	there was a damaged lashing wire,	17962 Merrill Ave	Fontana	34.092286	-117.412835	х	7/25/2023
100	11299633	706624H	there was a damaged lashing wire.	1308 Sixth St.	Norco	33.938549	-117.5500565	х	7/25/2023
25	11299629	32252J	Pole Transfer	1588 Monroe St	Riverside	33.8951378	-117.4044113	x	7/31/2023
93	1299640	1065048E	an AT&T communication conductor was touching a CATV conductor	1307 Detroit St	Norco	33.942131	-117.550152	x	7/25/2023
98	1299639	290516E	The lowest pole step on pole 290516E was located at a height of less than eight feet.	4081 Valley View Ave	Norco	33.94037	-117.549777	x	7/25/2023
53	1299636	x	Pole in front of Merrill and Locust Ave: there was a damaged lashing wire.	18101 Merrill Ave	Fontana	34.09232975	-117.4096682	x	7/25/2023
47	1299635		Pole in front of Buckeye Dr and Merrill Ave: there was a damaged lashing wire.	8898 Buckeye Dr	Fontana	34.09226638	-117.4111941	x	7/25/2023
65	1299632	11272	there was a damaged lashing wire. Replacement pole 4441622E	2910 Pleasant St	Fontana	33.96958692	-117.3702615	х	7/25/2023
54	1299631		there was a damaged lashing wire.	8860 Locust Ave	Fontana	34.092346	-117.409512	х	7/25/2023
103	1299628	809907H	Down Guy Wire and Lashing wire	3976 Valley View	Norco	33.93911358	-117.5498729	Х	7/25/2023
80	1299627	2084493E	there was a broken down guy wire.	180 Joy St	Corona	33.880846	-117.560332	x	7/25/2023
4	1299626	4420929E	the location where the down guy wire was attached to the guy anchor was buried.	3753 Placentia Ln	Riverside (Colton)	34.019236	-117.359757	х	7/25/2023
9	1299625	4845486E	the location where the down guy wire was attached to the guy anchor was buried.	3719 Placentia Ln	Riverside	34.01854	-117.357647	х	7/25/2023
61	1299624	320252E	unauthorized mailbox attached.	14832 Valley Blvd	Fontana	34.07034	-117.481501	X	7/25/2023
2	1299623	1196667E	there was a damaged pole step	3779 Placentia Ln	Riverside	34.019235	-117.361071	x	7/25/2023
101	1299622		there was a damaged pole step.	3910 Valley View Ave and 3976 Valley View	Norco			х	7/25/2023
42	1296524		poles have permanently abandoned AT&T's service drop that were not removed	17934 Merrill Ave	Fontana	34.092284	-117.413287	х	6/13/2023
9	1296522	4845486E	have permanently abandoned AT&T's service drop that were not removed	3719 Placentia Pn	Riverside	34.01854	-117.357647	х	7/14/2023
10	1296517	J36122	poles have permanently abandoned AT&T's service drop that were not removed	PLACENTIA LN N/S 1686' E/O N MAIN ST 3698 Placentia Ln	Riverside	34.01862262	-117.3576548	x	7/14/2023

21	1296516	24397J	poles have permanently abandoned AT&T's service drop that were not removed	4820 Monroe St	Riverside	33.9445419	-117.4444427	х	7/14/2023
91	1296515	4020918F	poles have permanently abandoned AT&T's service drop that were not removed	1353 Detroit St	Norco	33.94213	-117.550827	x	7/6/2023
103	1296431		there was a damaged terminal box	3976 Valley View	Norco	33.93911358	-117.5498729	X	7/6/2023
89	1296379	Pedestal	Cover Was Broken	coro rano, rien	Mandeville Way	00.00011000	11110100120	X	7/6/2023
51	1296378	Pedestal 18088	Cover not Secured(missing lock)	18088 Merrill Ave	Fontana	34.0923119	-117.409942	Х	7/7/2023
77	1292327	435537H	there was a damaged lashing wire.	299 Pearl St	Corona	33.880958	-117.559317	х	7/25/2023
6	1292326	4672778E	ground moulding is damaged:	3698 W Center St	Riverside	34.018896	-117.358325	х	7/31/2023
55	1292191		a CATV lashing wire was touching an AT&T communications conductor.	18088 Merrill Ave	Fontana	34.0923119	-117.409942	х	Tpn sent
97	1292190		a CATV service drop was wrapped around an AT&T communications conductor.	4111 Valley View Ave	Norco	33.940822	-117.549779	x	Tpn sent
66	1292189	779780	a CATV service drop was touching an AT&T conductor.	2916 Pleasant St	Riverside	33.9695892	-117.370163	Х	Tpn sent
69	Unable to locate	3491	Pole Transfer	5th and Park area	Fontana				
70	Unable to locate	2957	Pole Transfer	5th and Park area	Fontana				
?	Unable to locate	J37246	poles have permanently abandoned AT&T's service drop that were not removed	?	?				
62	Unable to locate		AT&T service drop was touching a CATV conductor		Fontana				
52	Unable to locate	4923490E	Pole Transfer		Fontana				