



Sandra Aguilar  
Team Lead -Compliance  
Kearny Maintenance & Operations  
San Diego Gas & Electric  
Saguila2@SDGE.com

October 22, 2025

VIA E-MAIL

Mr. Fadi Daye, P.E.  
Program and Project Supervisor  
Electric Safety and Reliability Branch  
Safety and Enforcement Division  
California Public Utilities Commission  
505 Van Ness Avenue  
San Francisco, CA 94102-3298

**Subject: SDG&E Response to CPUC Orange County Substation Audit**

Dear Mr. Daye:

A substation audit of San Diego Gas & Electric's (SDG&E) Orange County District was conducted by the Electric Safety and Reliability Branch of the California Public Utilities Commission (CPUC) staff Calvin Choi on August 25, 2025 to August 26, 2025. A letter was sent to SDG&E on September 24, 2025, identifying the findings by your staff. The table below identifies the findings your staff captured during their record and field inspection. SDG&E has addressed the finding identified.

CPUC Comment	SDGE Comment
<b>San Clemente:</b> One cooling fan on the Bank 10 transformer did not start.	The cooling fan has been repaired and tested successfully.

If you have questions regarding these comments, please do not hesitate to contact me at (619)-751-5256 or at [saguila2@sdge.com](mailto:saguila2@sdge.com).

Sincerely,  
Sandra Aguilar  
Team Lead - Substation & Transmission Compliance