

California Public Utilities Commission Gas Safety and Reliability Branch (GSRB) 2024 Highlights

1st rank (tied)

GSRB received a perfect score on Pipeline Safety Trust's State Pipeline Safety Website Transparency Review

GSRB believes in making its inspection reports easily accessible and available to the public



50%

Year-over-year reduction in DOT-reportable gas incidents

GSRB thoroughly investigates gas pipeline incidents to determine operator compliance with regulations, and ensure measures are taken to prevent recurrence

99 (out of 100)

PHMSA State Program Evaluation Score

PHMSA performs an annual evaluation to measure state program performance



2735

Inspection-Person Days conducted

GSRB performs field inspections across California to ensure pipeline systems are designed, constructed, operated, and maintained according to safety standards

