



Source: Proponents Environmental Assessment

Figure D.3-23A: Existing Condition
 Cypress Canyon Park Drive midway between Cypress Terrace Place and Candy Rose Way. View faces northwest. View shows existing 230 kV and 138 kV transmission lines rising above residences located along south side of ROW.



Source: Proponents Environmental Assessment

Figure D.3-23B: Photo Simulation
 Simulation of Proposed Project from Cypress Canyon Park Drive midway between Cypress Terrace Place and Candy Rose Way in Miramar Ranch North